Title List of Documents Made Publicly Available

September 1-30, 1980

Office of Administration U.S. Nuclear Regulatory Commission



Title List of Documents Made Publicly Available

September 1-30, 1980

Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, D.C. 20555



CONTENTS

Preface
Arrangement of Items by Docket Number i
Alphabetic Arrangement of Docket 50 Items by Facility Name xvi
Docketed Items
Low Level Radwaste Disposal Sites – Docket 27
Domestic Licensing of Source Material – Docket 40
Domestic Licensing of Production and Utilization Facilities - Docket 50
Domestic Licensing of Special Nuclear Material - Docket 70 30-
Packaging of Radioactive Material for Transport and Transportation of
Radioactive Material Under Certain Conditions - Docket 71 31
Nondocketed Items
10CFR — Commission Meeting Records
ACRS – Advisory Committee on Reactor Safeguards
COMMISSION – NRC Commissioners
CONTRACT - NRC Contracts and Modifications
DISCLOSURE - Financial Disclosure Information
FOIA - Freedom of Information Act Requests and Releases
GEN TECH IS — Generic Technical Issues
I&E — Inspection and Enforcement
MISC - Public Document Room Miscellaneous
NUREG - NUREG Reports and Related Correspondence
ORG - Correspondence with Other Organizations
PR — Proposed Rule
PRM - Petition for Rulemaking
PROJ - Projects - Predocket Licensing
PT21 - Noncompliance Reports and Related Correspondence 350
QA999 — Quality Assurance Inspections
REGGD - Regulatory Guides
RES – Research and Technical Assistance Reports
REVIEW GRP – NRC Research Review Groups
RM Rulemakings
SECY — Position Papers Before the Commission
STATE PROG — State Programs
TOPREP - Vendor Reports and Related Correspondence
WASTE MGT - Nuclear Waste Management
XPORTLIC - Export and Import Licenses
Personal Author Index
Corporate Source Index
Report Number Index
Cross Reference of Enclosures to Principal Documents
Appendix A - Definitions of Docket 50 Categories
Appendix B — Definitions of Nondocketed Categories 45

PREFACE

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS

The listings within dockets are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence

Y

- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences, LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence
- W. Decommissioning stage documents and correspondence

Appendix A sets forth those categories and described the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report

The principal elements of the entries in the list are:


①

P Operating license stage documents & correspondence



7904170015 Forwards info on TMLJM Hendrie 790410 testimony, preliminary chronology of NRC actions, description of events & generic consideration of incident.

REHM, T.A. Office of the Executive Director for Operations.



- 1 NRC/PDR Document category (see Appendix A).
- 2. NRC Accession Number
- 3. Description of information contained in the document
- 4. Personal author. An asterisk in this position indicates that there is no personal author
- 5. Corporate, agency or nonindividual source
- 6 Date of document described
- 7 Pages in document
- 8. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5

NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories and their symbols are:

10CFR — Commission Meeting Records
ACRS — Advisory Committee on Reactor Safeguards
COMMISSION — NRC Commissioners
CONTRACT — NRC Contracts and Modifications
DISCLOSURE — Financial Disclosure Information
FOIA — Freedom of Information Act Requests and Releases

GEN TECH IS — Generic Technical Issues

I&E — Inspection and Enforcement

MISC — Public Document Room Miscellaneous

NUREG — NUREG Reports and Related Correspondence

ORG — Correspondence with other organizations

PR - Proposed Rule

PRM — Petition for Rulemaking

PROJ — Projects-Predocket Licensing

PT9 — Public Records

PT21 — Noncompliance Reports and Related Correspondence

QA999 — Quality Assurance Inspections

REGGD — Regulatory Guides

RES — Research and Technical Assistance Reports

REVIEW GRP - NRC Research Review Groups

RM - Rulemakings

SECY — Position Papers Before the Commission

STATE PROG — State Programs

TOPREP — Vendor Reports and Related Correspondence

WASTE MGT — Nuclear Waste Management

XPORTLIC — Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:


NUREG - NUREG Reports and Related Correspondence



7901060007 NUREG/CR-0161

(4) The Progress Report 780101-780331 Identifies parameters which affect normal shock & vibration environs.

FIELDS, S.R., MECH, S.J. Hanford Engineering Development Laboratory.



- Nondocketed category
- 2. NRC Accession Number
- 3. NRC Report Number
- 4. Title and description of information contained in the document
- 5. Personal author(s). An asterisk in this position indicates that there is no personal author
- 6. Corporate, agency or other nonindividual source
- 7. Contract or financial (FIN) number (if any). If the document has a secondary report number it will appear following this entry.
- 8. Date of document described
- 9. Pages in document

10. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" or "Available at NTIS." See NOTES on this page for information on ordering publications.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the charge-card number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: 8¢ per page for standard size paper; 11¢ per page for oversized paper (drawings); 25¢ per microfiche for 24x diazo duplicates. A minimum charge of \$2.00 plus postage is charged for mail orders.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Potomac Research, Inc.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Doci	ket	Name	Page
27-010	Beatty, NV	1		40-8502	Irigaray Mine, Wyoming Mining Corp.	6
27-039	Sheffield, IL, Nuclear Engineering Co.	1		40-8568	Dept. of the Air Force	6
27-047	Barnwell, SC, Chem-Nuclear Systems, Inc.	1	1	40-8584	Union 76 Minerals Exploration Co.	6
27-048	Richland, WA, Nuclear Engineering Co.	1		40-8663	Nuclear Dynamics, Inc.	6
40-0299	Union Carbide Corp.	2		40-8681	Energy Fuels Nuclear, Inc.	6
40-0672	Nuclear Metals, Inc.	2		40-8692	Cotter Corp.	7
40-0791	United Technologies, Inc	2		40-8693	Ogle Petroleum, Inc.	7
40-1162	Western Nuclear, Inc.	2		40-8697	Rocky Mountain Energy Co.	7
40-1341	Edgemont Uranium Mine, TVA, and	2		40-8698	Plateau Resources, Ltd.	7
	Mines Development, Inc.	3		40-8721	Rocky Mountain Energy Co.	7
40-2061	West Chicago Facility, Kerr-McGee Corp.			40-8724	Chemtron Corp.	7
40-2259	Pathfinder Mines Corp.	3		40-8743	Conoco	7
40-2940	NL Industries, Inc.	3		40-8745	Ogle Petroleum	7
40-3392	Allied Chemical Corp.	4		40-8768	Kerr-McGee Nuclear Corp.	8
40-3453	Atlas Minerals	4		50-3	Indian Point Station, Unit 1	8
40-4348	Dept, of Commerce	4		50-5	Pennsylvania State Univ. Research Reactor	9
40-4492	Federal American Partners (Mining)	4		50-10	Dresden Nuclear Power Station, Unit 1	10
40-4826	Northwestern Univ.	4		50-20	Massachusetts Institute of Technology	11
40-6659	Petrotomics Co., Getty Oil Co.	4			Research Reactor	
40-8027	Kerr-McGee Corp.	5		50-22	Westinghouse Tost Reactor	11
40-8084	Lisbon Mine, Rio Algom Corp.	5		50-27	Washington State Univ. Research Reactor	12
40-8092	NASA	5		50-29	Yankee-Rowe Nuclear Power Station	12
40-8102	Exxon Minerals Co. USA, Exxon Corp.	5		50-30	Plum Brook Research Reactor Facility	13
40-8113	Univ. of Utah	5		50-47	Army Materials Research Reactor	13
40-8180	Univ. of Oklahoma	5		5 0-54	Union Carbide Research Reactor	13
40-8348	In Situ Uranium Leaching Project	5		50-57	State Univ. of New York Research Reactor	13
40-8380	Rocky Mountain Energy Co.	5		50-59	Texas A&M Univ. Research Reactor	13
40-8452	Bear Creek Uranium Co.	5		50-70	General Electric Test Reactor	13

Docket	Name	Page	Docket	Name	Page
50-77	Catholic Univ. of America Research Reactor	14	50-213	Haddam Neck Plant	24
50-83	Univ. of Florida Training Reactor	14	50-219	Oyster Creek Nuclear Power Plant	26
50-87	Westinghouse Critical Experiment	14	50-220	Nine Mile Point Nuclear Station, Unit 1	28
50-97	Cornell Univ. Zero Power Reactor	14	50-222	Columbia Research Reactor	30
50-99	Babcock & Wilcox Test Reactor	14	50-223	Univ. of Lowell Research Reactor	30
50-112	Univ. of Oklahoma Research Reactor	14	50-224	Univ. of California Research Reactor	30
50-123	Univ. of Missouri Research Reactor	14	50-225	RPI Critical Experiment	30
50-124	Virginia Polytechnic Institute Training	14	50-227	TRIGA Thermionic Prototype Reactor	30
50.100	Reactor		50-237	Dresden Nuclear Power Station, Unit 2	30
50-128	Texas A&M Univ. Research Reactor	14	50-243	Oregon State Univ. Research Reactor	33
50-131	Omaha Veterans Administration Hospital Research Reactor	15	50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	33
50-133	Humboldt Bay Power Plant, Unit 3	15	50-245	Millstone Nuclear Power Station, Unit 1	35
50-134	Worcester Polytechnic Institute Research Reactor	15	50-247	Indian Point Station, Unit 2	37
50-139	Univ. of Washington Research Reactor	16	50-249	Dresden Nuclear Power Station, Unit 3	39
50-142	UCLA Training Reactor	16	50-250	Turkey Point Plant, Unit 3	41
50-147	Rockwell International Corp. Critical	16	50-251	Turkey Point Plant, Unit 4	43
	Facility		50-254	Quad-Cities Station, Unit 1	45
50-152	Florida West Coast Nuclear Group, Inc.	16	50-255	Palisades Nuclear Plant	47
50-155	Big Rock Point Nuclear Plant	16	50-259	Browns Ferry Nuclear Power Station, Unit 1	50
50-156	Univ. of Wisconsin Research Reactor	19	50-260	Browns Ferry Nuclear Power Station, Unit 2	53
50-157	Cornell Univ. Research Reactor	19	50-261	H.B. Robinson Plant, Unit 2	55
50-166	Univ. of Maryland Research Reactor	19	50-263	Monticello Nuclear Generating Plant	56
50-170	National Naval Medical Center	19	50-265	Quad-Cities Station, Unit 2	58
50-171	Peach Bottom Atomic Power Station, Unit 1	19	50-266	Point Beach Nuclear Plant, Unit 1	60
50-182	Purdue Univ. Research Reactor	20	50-267	Fort St. Vrain Nuclear Generating Station	62
50-184	National Bureau of Standards Reactor	20	50-268	Midwest Fuel Recovery Plant	64
50-185	Plum Brook Reactor - Mock-up	20	50-269	Oconce Nuclear Station, Unit 1	64
50-186	Univ. of Missouri Research Reactor	20	50-270	Oconce Nuclear Station, Unit 2	66
50-193	Rhode Island & Providence Plantations AEC	20	50-271	Vermont Yankee Nuclear Power Station	68
50-199	Manhattan College Research Reactor	20	50-272	Salem Nuclear Generating Station, Unit 1	70
50-201	West Valley Reprocessing Plant	20	50-273	Beznau Nuclear Station, Unit 1, Switzerland	72
50-206	San Onofre Nuclear Station, Unit 1	22	50-274	U.S. Geological Survey Research Reactor	72
50-208	Columbia Univ. Research Reactor	24	50-275	Diablo Canyon Nuclear Power Plant, Unit 1	72

Docket	Name	Page	Docket	Name	Page
50-277	Peach Bottom Atomic Power Station, Unit 2	74	50-326	Univ. of California at Irvine Research Reactor	153
50-278	Peach Bottom Atomic Power Station, Unit 3	76	50-327	Sequoyah Nuclear Plant, Unit 1	153
50-280	Surry Power Station, Unit 1	79	50-328	Sequoyah Nuclear Plant, Unit 2	157
50-281	Surry Power Station, Unit 2	81	50-329	Midland Plant, Unit 1	160
50-282	Prairie Island Nuclear Station, Unit 1	84	50-330	Midland Plant, Unit 2	162
50-285	Fort Calhoun Station, Unit 1	86	50-331	Duane Arnold Energy Center	164
50-286	Indian Point Station, Unit 3	87	50-332	Barnwell Reprocessing Plant	166
50-287	Oconee Nuclear Station, Unit 3	90	50-333	James A. Fitzpatrick Nuclear Power Plant	166
50-289	Three Mile Island Nuclear Station, Unit 1	91	50-334	Beaver Valley Power Station, Unit 1	169
50-293	Pilgrim Nuclear Power Station, Unit 1	99	50-335	St. Lucie Plant, Unit 1	171
50-295	Zion Nuclear Power Station, Unit 1	103	50-336	Millstone Nuclear Power Station, Unit 2	173
50-296	Browns Ferry Nuclear Power Station, Unit 3	106	50-338	North Anna Power Station, Unit 1	174
50-297	North Carolina State Univ. PULSTAR Reactor	108	50-339	North Anna Power Station, Unit 2	177
50-298	Cooper Nuclear Station	108	50-340	Seabrook Nuclear Station, Unit 1	179
50-301	Point Beach Nuclear Plant, Unit 2	110	50-341	Enrico Fermi Atomic Power Plant, Unit 2	179
50-302	Crystal River Nuclear Plant, Unit 3	112	50-344	Trojan Nuclear Plant	180
50-304	Zion Nuclear Power Station, Unit 2	114	50-346	Davis-Besse Nuclear Power Station, Unit i	182
50-305	Kewaunee Nuclear Power Plant	116	50-348	Joseph M. Pariey Nuclear Plant, Unit 1	184
50-306	Prairie Island Nuclear Station, Unit 2	117	50-352	Limerick Generating Station, Unit 1	187
50-309	Maine Yankee Atomic Power Plant	119	50-353	Limerick Generating Station, Unit 2	188
50-311	Salem Nuclear Generating Station, Unit 2	121	50-354	Hope Creek Nuclear Station, Unit 1	189
50-312	Rancho Seco Nuclear Generating Station	124	50-355	Hope Creek Nuclear Station, Unit 2	190
50-313	Arkansas Nuclear One, Unit 1	126	50-356	Univ. of lilinois LOPRA Research Reactor	191
50-315	Donald C. Cook Nuclear Power Plant, Unit 1	128	50-358	William II. Zimmer Nuclear Station, Unit 1	191
50-316	Donald C. Cook Nuclear Power Plant, Unit 2	130	50-361	San Onofre Nuclear Station, Unit 2	192
50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	131	50-362	San Onofre Nuclear Station, Unit 3	195
50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	133	50-363	Forked River Nuclear Station, Unit 1	197
50-320	Three Mile Island Nuclear Station, Unit 2	135	50-364	Joseph M. Farley Nuclear Plant, Unit 2	197
50-321	Edwin I. Hatch Nuclear Plant, Unit 1	143	50-366	Edwin I. Hatch Nuclear Plant, Unit 2	199
50-322	Shoreham Nuclear Power Station	145	50-367	Bailly Generating Station	202
50-323	Diablo Canyon Nuclear Power Plant, Unit 2	146	50-368	Arkansas Nuclear One, Unit 2	204
50-324	Brunswick Steam Electric Plant, Unit 2	148	50-369	William B. McGuire Nuclear Station, Unit 1	207
50-325	Brunswick Steam Electric Plant, Unit 1	150	50-370	William B. McGuire Nuclear Station, Unit 2	209

Docket	Name	Page	Docket	Name	Page
50-37	3 LaSalle County Station, Unit 1	211	50-440	Perry Nuclear Power Plant, Unit 1	246
50-374	4 LaSalle County Station, Unit 2	213	50-441	Perry Nuclear Power Plant, Unit 2	248
50-376	North Coast Nuclear Plant, Puerto Rico	214	50-443	Seabrook Nuclear Station, Unit 1	250
50-378	B Caorso Nuclear Station, Italy	215	50-444	Seabrook Nuclear Station, Unit 2	251
50-382	Waterford Generating Station, Unit 3	215	50-445	Comanche Peak Steam Electric Station,	251
50-387	Susquehanna Steam Electric Station, Unit 1	216		Unit 1	
50-388	Susquehanna Steam Electric Station, Unit 2	218	50-446	Comanche Peak Steam Electric Station, Unit 2	255
50-389	St. Lucie Plant, Unit 2	219	50-452	Greenwood Energy Center, Unit 2	250
50-390	Watts Bar Nuclear Plant, Unit 1	221	50-453	Greenwood Energy Center, Unit 3	259
50-391	Watts Bar Nuclear Plant, Unit 2	222	50-454	Byron Station, Unit 1	259
50-395	Virgil C. Summer Nuclear Station, Unit 1	224	50-455	Byron Station, Unit 2	259
50-397	WPPSS Nuclear Project, Unit 2	226	50-456	Braidwood Station, Unit 1	260
50-400	Shearon Harris Nuclear Power Plant, Unit 1	228	50-457	Braidwood Station, Unit 2	261
50-401	Shearon Harris Nuclear Power Plant, Unit 2	229	50-458	River Bend Station, Unit 1	262
50-402	Shearon Harris Nuclear Power Plant, Unit 3	230	50-459	River Bend Station, Unit 2	263
50-403	Shearon Harris Nuclear Power Plant, Unit 4	231	50-460	WPPSS Nuclear Project, Unit 1	264
50-404	North Anna Power Station, Unit 3	231	50-461	Clinton Power Statlon, Unit 1	265
50-405	North Anna Power Station, Unit 4	232	50-462	Clinton Power Station, Unit 2	266
50-409	La Crosse Bolling Water Reactor	232	50-466	Allens Creek Nuclear Station, Unit 1	268
50-410	Nine Mile Point Nuclear Station, Unit 2	234	50-467	Allens Creek Nuclear Station, Unit 2	269
50-412	Beaver Valley Power Station, Unit 2	235	50-471	Pilgrim Nuclear Power Station, Unit 2	271
50-413	Catawba Nuclear Station, Unit 1	235	50-472		271
50-414	Catawba Nuclear Station, Unit 2	236	STN-50-482	Pilgrim Nuclear Power Station, Unit 3 Wolf Creek Generating Station	271
50-416	Grand Gulf Nuclear Station, Unit 1	237	STN-50-483	Calloway Plant, Unit 1	271
50-417	Grand Gulf Nuclear Station, Unit 2	240	STN-50-485		272
50-423	Millstone Nuclear Power Station, Unit 3	242	STN-50-486	Sterling Power Project, Nuclear, Unit 1 Calloway Plant, Unit 2	273
50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	242	STN-50-488		273
50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	243	STN-50-489	Perkins Nuclear Station, Unit 1	274
50-431	Genkai, Unit 1, Japan	243		Perkins Nuclear Station, Unit 2	275
50-433	Univ. of California at Santa Barbara Research Reactor	243	STN-50-490	Perkins Nuclear Station, Unit 3	276
STN-50-437	Floating Nuclear Plant	0.43	STN-50-491	Cherokee Nuclear Station, Unit 1	276
50-438	Bellefonte Nuclear Plant, Unit 1	243	STN-50-492	Cherokee Nuclear Station, Unit 2	277
50-439		244	STN-50-493	Cherokee Nuclear Station, Unit 3	277
20 105	Bellefonte Nuclear Plant, Unit 2	245	STN-50-498	South Texas Project, Unit 1	277

Docket	Name	Page	Docket	Name	Page
STN-50-499	South Texas Project, Unit 2	280	STN-50-567	Yellow Creek Nuclear Plant, Unit 2	302
50-500	Davis-Besse Nuclear Power Station, Unit 2	283	STN-50-574	Bagnac Nuclear Power Project, Philippines	303
50-501	Davis-Besse Nuclear Power Station, Unit 3	283	50-582	Sundesert, Unit 1	303
STN-50-502	Haven Nuclear Plant, Unit 1	283	50-583	Sundesert, Unit 2	303
STN-50-508	WPPSS Nuclear Project, Unit 3	283	STN-50-592	Palo Verde Nuclear Station, Unit 4	303
STN-50-509	WPPSS Nuclear Project, Unit 5	284	STN-50-593	Palo Verde Nuclear Station, Unit 5	303
50-510	Blue Hills Station, Unit 1	284	50-599	Carroll Facility I	304
50-511	Blue Hills Station, Unit 2	284	50-600	Carroll Facility II	304
50-513	WPPSS Nuclear Project, Unit 4	284	70-0008	Battelle Columbus Laboratories	304
50-514	Pebble Springs Nuclear Plant, Unit 1	285	70-0025	Rockwell International Corp.	304
50-515	Pebble Springs Nuclear Plant, Unit 2	285	70-0027	Babcock & Wilcox Co.	304
STN-50-516	Jamesport Nuclear Statlon, Unit 1	285	70-0033	Texas Instruments, Inc.	304
STN-50-517	Jamesport Nuclear Station, Unit 2	286	70-0036	Combustion Engineering, Inc.	305
STN-50-518	Hartsville Nuclear Plant, Unit 1	286	70-0135	Babcock & Wilcox Co.	305
STN-50-519	Hartsville Nuclear Plant, Unit 2	287	70-0143	Nuclear Fuel Services, Inc.	306
STN-50-520	Hartsville Nuclear Plant, Unit 3	288	70-0258	Univ. of Illinols at Urbana-Champaign	307
STN-50-521	Hartsville Nuclear Plant, Unit 4	290	70-0312	Univ. of Massachusettes	307
STN-50-522	Skaglt Nuclear Power Project, Unit 1	291	70-0343	Rutgers the State University of New Jersey	307
STN-50-523	Skagit Nuclear Power Project, Unit 2	291	70-0349	Northwestern Univ. at Evanston-Chicago	307
STN-50-528	Palo Verde Nuclear Station, Unit 1	291	70-0364	Parks Township Site, Babcock & Wilcox Co.	307
STN-50-529	Palo Verde Nuclear Station, Unit 2	292	70-0371	United Nuclear Corp.	308
STN-50-530	Palo Verde Nuclear Station, Unit 3	294	70-0398	Dept. of Commerce	308
50-536	Gosgen, Switzerland	295	70-0575	Lebanon Vailey College	308
50-537	Clinch River Breeder Reactor	296	70-0600	Scattle Univ,	308
STN-50-546	Marble Hill Nuclear Station, Unit 1	296	70-0687	Union Carbide Corp.	308
STN-50-547	Marble Hill Nuclear Station, Unit 2	297	70-0710	Merrimack College	308
STN-50-553	Phipps Bend Nuclear Plant, Unit 1	299	70-0734	General Atomic Co.	309
STN-50-554	Phipps Bend Nuclear Plant, Unit 2	300	70-0754	Vallecitos Nuclear Center	309
STN-50-556	Black Fox Station, Unit 1	301		General Electric Co.	
STN-50-557	Black Fox Station, Unit 2	301	70-0820	United Nuclear Corp.	309
50-559	Maanshan Nuclear Station, Unit 2, Taiwan	301	70-0824	Babcock & Wilcox Co.	310
50-564	Nuclear Fuels Recovery and Recycle Center	301	70-0925	Cimatron Facility, Kerr-McGee Corp.	310
STN-50-566	Yellow Creek Nuclear Plant, Unit 1	302	70-0959	Nuclear Fuel Services, Inc.	310

Docket	Name	Page	Docket	Name	Page
70-0984	Pacific Northwest Laboratory	310	70-2322	Edlow International Co.	315
70-1007	General Electric Co.	310	70-2375	Pacific Gas & Electric Co.	315
70-1097	General Electric Co.	310	70-2478	Transnuclear, Inc.	315
70-1100	Combustion Engineering, Inc.	311	70-2479	Transnuclear, Inc.	316
70-1113	General Electric Co.	311	70-2520	West Virginia Univ. Medical Center, Morgantown, WV	316
70-1120	Westinghouse Electric Co.	311	70-2554	Valley Hospital, Ridgewood, NJ	316
70-1143	Westinghouse Electric Corp.	311	70-2560	Oklahoma Osteopathic Hospital, Tulsa, OK	316
70-1151	Westinghouse Electric Corp.	311	70-2599	Berrien General Hospital, Berrien Center, MI	
70-1167	Northwestern Oklahoma State Univ.	312		• • • • • • • • • • • • • • • • • • • •	316
70-1193	Cimarron Facility, Kerr-McGee Corp.	312	70-2609	Commonwealth Edison Co.	316
70-1201	UF-6 Conversion Facility,	312	70-2621	Riverside Hospital, Newport News, VA	316
	Babcock & Wilcox Co.		70-2623	McGuire Spent Fuel Pool, Duke Power Co.	316
70-1220	General Electric Co.	312	70-2705	St. Francis Medical Center Hospital, Lynwood, CA	316
70-1257	Mixed Oxide Fabrication Plant, Exxon Nuclear Co., Inc.	312	70-2786	General Electric Co.	316
70-1308	Morris Operations, General Electric Co.	313	70-2883	Hanna Mining Co.	316
70-1309	Morris Operations, Sources & Standards, General Electric Co.	314	70-2885	Commonwealth Edison	317
70-1327	UF-6 Conversion Facility, Allied-General	314	70-2892	Auxilio Mutuo Hospital	317
10 1327	Nuclear Services Corp.	311	70-2908	Veterans Administration Hospital, San Diego, CA	317
70-1349	Hospital Pavia	314	70-2909	Westinghouse Electric Corp. Power Systems	317
70-1377	Hanna Mining Co.	314	70-2910	Tennessee Valley Authority	317
70-1397	St. Mary's Hospital, Richmond, VA	314		, , , , , , , , , , , , , , , , , , ,	
70-1401	Veterans Administration Hospital, Dallas, TX	314	70-2913	Tennessee Valley Authority	317
70-1417	Greater Southeast Community Hospital,	314	70-2914	Hanna Mining Co.	317
70.1422	Washington, DC		70-2932	Texns Utilities Generating Co.	317
70-1432	Recycle Fuels Plant, Westinghouse Electric Corp.	314	71-0002	Chem-Nuclear Systems, Inc.	317
70-1470	Veterans Administration Hospital,	315	71-0017	Rhode Island Atomic Energy Commission	317
	Los Angeles, CA		71-0018	Nuclear Assurance Corp.	317
70-1729	Fuel Recovery & Storage Station, Allied- General Nuclear Services Corp.	315	71-0035	Rockwell International	317
70-1738	Pacific Gas & Electric Co.	315	71-0082	Kerr-McGee Nuclear Corp.	317
70-1739	Tri-State Motor Transit Co.	315	71-0108	Univ. of Missouri	317
70-1821	Plutonium Production Facility, Allied-	315	71-0109	Union Carbide Corp.	318
	General Nuclear Services Corp.		71-0112	Dept. of the Navy	318
70-2192	Pittston Co., Coal Group	315	71-0138	Battelle Columbus Laboratories	318
70-2313	Nuclear Fuel Services	315	71-0192	Nuclear Packaging, Inc.	318

Docket	Name	Page	Docket	Name	Page
71-0198	Nuclear Fuel Services, Inc	318	71-9018	Model BU-6, General Electric Co.	320
71-0244	NL Industries, Inc.	318	71-9019	Model. BU-7, General Electric Co.	320
71-0370	Amersham Corp.	318	71-9022	Model CE-250-2, Combustion Engineering	320
71-0382	Dept. of the Interior, Geological Survey	318	a. 000a	Co., Inc	***
71-0385	Dept. of the Navy, Naval Nuclear Power	318	71-9027	Model 741, Technical Operations, Inc.	320
71.0004	Unit Port, Hueneme, CA		71-9032	Model 650, Technical Operations, Inc.	320
71-0394	Nuclear Sources & Services, Inc.	318	71-9033	Model: 660 & 660E, Technical Operations, Inc.	320
71-0395	Dept. of the Navy, Naval Facilities Engineering Command	318	71-9034	Model: TRIGA-1, General Atomic Co.	320
71-0396	Atcor Washington, Inc.	318	71-9035	Model: 680, Technical Operations, Inc.	320
71-4888	Model: Sentinel -25A, B, C, C3, D, E, F, Teledyne Energy Systems	318	71-9036	Model: C-1, Source Production Equipment Co.	320
71-4986	Model: RA-2, Exxon Nuclear Co., Inc.	318	71-9037	Model: TRIGA-2, General Atomic Co.	320
71-5088	Model: D34710-1, U.S. Nuclear, Inc	318	71-9039	Model: 715, Technical Operations, Inc.	320
71-5442	Model: LA-36, Babcock & Wilcox Co.	318	71-9044	Model: GE-1600, General Electric Co.	320
71-5450	Model: RCC-1, -2, -3, Westinghouse Electric Corp.	319	71-9049	Model: GE-500, General Electric Co.	320
71-5740	Model: ORNL-TRU-CF, Shipping Container,	319	71-9074	Model: AP-100, Anefco, Inc.	321
	Dept. of Energy		71-9080	Model: HN-600, Hittman Nuclear &	321
71-5862	Model. Sentinel-100F, Teledyne Energy Systems	319	71.0001	Development Corp.	221
71-5926	Model: 100, General Electric Co.	319	71-9081	Model: CNSI-1600, Chem-Nuclear Systems, Inc.	321
71-5942	Model: GE-700, General Electric Co.	319	71-9094	Model: CNSI-14-195-H, Chem-Nuclear	321
71-5957	Model: BMI-1, Dept. of Energy	319		Systems, Inc.	
71-5971	Model: GE-200, General Electric Co.	319	71-9096	Model: CNSI-21-300, Chem-Nuclear Systems, Inc.	321
71-5980			71-9097	Model: CNSI-14-195L, Chem-Nuclear	321
71-5998	Model: GE-600, General Electric Co.	319		Systems, Inc.	721
	Model: GE-400, General Electric Co.	319	71-9108	Model: AL-33-90, Atcor, Inc.	321
71-6058	Model: B3-I, Nuclear Engineering Co.	319	71-9111	Model: CN6-80A, Chem-Nuclear	321
71-6144	Model: 6144, Nuclear Engineering Co.	319		Systems, Inc.	
71-6357	Model: NNFD-10, Babcock & Wilcox Co.	319	71-9113	Model: 7-100, Chem-Nuclear Systems, Inc.	321
71-6400	Model: Super Tiger, Westinghouse Electric Corp.	319	71-9116	Model: CN6-80B, Nuclear Packaging,	321
71-6458	Model: BU-5, General Electric Co.	319	71-3110	Inc.	121
71-6581	Model: 51032-1 & 1A, Exxon Nuclear Co., Inc.	319	71-9136	Model: GE-9136, General Electric Co.	321
71-6717	Model: 6717 B	320	71-9508	Model: DOT SPEC 6M, Dept. of Energy	321
71-9001	Model: 1F-300, General Electric Co.	320	71-9853	Model: ORNL - BNL - NBS, Unirradiated Fuel Container,	321
71-9009	Model: FL 10-1, General Electric Co.	320		Dept. of Energy	

	0		
	,		
			1
			,
			1
			5.4.7

ALPHABETIC ARRANGEMENT OF DOCKET 50 ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Allens Creek Nuclear Station, Unit 1	50-466	269	Brunswick Steam Electric Plant, Unit 1	50-325	150
Allens Creek Nuclear Station, Unit 2	50-467	271	Brunswick Steam Electric Plant, Unit 2	50-324	148
Arkansas Nuclear One, Unit 1	50-313	126	Byron Station, Unit 1	50-454	259
Arkansas Nuclear Onc, Unit 2	50-368	204	Byron Station, Unit 2	50-455	260
Army Materials Research Reactor	50-47	13	Calloway Plant, Unit 1	STN-50-483	272
Duane Arnold Energy Center	50-331	164	Calloway Plant, Unit 2	STN-50-486	273
Babcock & Wilcox Co. Test Reactor	50-99	14	Calvert Cliffs Nuclear Power Plant,	50-317	131
Bagnac Nuclear Power Project, Philippines	STN-50-574	303	Unit 1	50.010	100
Bailly Generating Station	50-367	202	Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	133
Barnwell Reprocessing Plant	50-332	166	Caorso Nuclear Station, Italy	50-378	215
Beaver Valley Power Station, Unit 1	50-334	169	Carroll Facility 1	50-599	303
Beaver Valley Power Station, Unit 2	50-412	235	Carrolt Facility II	50-600	304
Bellefonte Nuclear Plant, Unit 1	50-438	244	Catawba Nuclear Station, Unit 1	50-413	235
Bellefonte Nuclear Plant, Unit 2	50-439	245	Catawba Nuclear Station, Unit 2	50-414	236
Beznau Nuclear Station, Unit 1, Switzerland	50-273	72	Catholic Univ. of America Research	50-77	14
Big Rock Point Nuclear Power Plant	50-155	16	Reactor	gm) 1 60 104	05.5
Black Fox Station, Unit 1	STN-50-556	301	Cherokee Nuclear Station, Unit 1	STN-50-491	276
Black Fox Station, Unit 2	STN-50-557	301	Cherokee Nuclear Station, Unit 2	STN-50-492	277
Blue Hills Station, Unit 1	STN-50-510	284	Cherokee Nuclear Station, Unit 3	STN-50-493	277
Blue Hills Station, Unit 2	50-511	284	Clinch River Breeder Reactor	50-537	296
Braidwood Station, Unit 1	50-456	261	Clinton Power Station, Unit 1	50-461	266
Braidwood Station, Unit 2	50-457	262	Clinton Power Station, Unit 2	50-462	268
Browns Ferry Nuclear Power Station, Unit 1	50-259	50	Columbia Research Reactor Columbia Univ. Research Reactor	50-222 50-208	30 24
Browns Ferry Nuclear Power Station, Unit 2	50-260	53	Comanche Peak Steam Electric Station, Unit 1	50-445	251
Browns Ferry Nuclear Power Station, Unit 3	50-296	106	Comanche Peak Steam Electric Station, Unit 2	50-446	255

Name	Docket	Page	Name	Docket	Page
Donald C. Cook Nuclear Power Plant,	50-315	128	Grand Gulf Nuclear Station, Unit 1	50-416	237
Unit 1			Grand Gulf Nuclear Station, Unit 2	50-417	240
Donald C. Cook Nuclear Power Plant, Unit 2	50-316	130	Greenwood Energy Center, Unit 2	50-452	259
Cooper Nuclear Station	50-298	108	Greenwood Energy Center, Unit 3	50-453	259
Cornell Univ. Research Reactor	50-157	19	Haddam Neck Plant	50-213	24
Cornell Univ. Zero Power Reactor	50-97	14	Shearon Harris Nuclear Power Plant, Unit 1	50-400	228
Crystal River Nuclear Plant, Unit 3	50-302	112	Shearon Harris Nuclear Power Plant,	50-401	229
Davis-Besse Nuclear Power Station, Unit 1	50-346	182	Unit 2		
Davis-Besse Nuclear Power Station,	50-500	283	Shearon Harris Nuclear Power Plant, Unit 3	50-402	230
Unit 2			Shearon Harris Nuclear Power Plant,	50-403	231
Davis-Besse Nuclear Power Station, Unit 3	50-501	283	Unit 4	OTN EA E10	286
Diablo Canyon Nuclear Power Plant,	50-275	72	Hartsville Nuclear Plant, Unit 1	STN-50-518	
Unit 1			Hartsville Nuclear Plant, Unit 2	STN-50-519	287
Diablo Canyon Nuclear Power Plant, Unit 2	50-323	146	Hartsville Nuclear Plant, Unit 3	STN-50-520	288
Dresden Nuclear Power Station, Unit 1	50-10	10	Hartsville Nuclear Plant, Unit 4	STN-50-521	290
Dresden Nuclear Power Station, Unit 2	50-237	30	Edwin I. Hatch Nuclear Plant, Unit 1	50-321	143
Dresden Nuclear Power Station, Unit 3	50-249	39	Edwin I, Hatch Nuclear Plant, Unit 2	50-366	199
Joseph M, Farley Nuclear Plant, Unit 1	50-348	184	Haven Nuclear Plant, Unit 1	STN-50-502	283
Joseph M. Farley Nuclear Plant, Unit 2	50-364	197	Hope Creek Nuclear Station, Unit 1	50-354	189
			Hope Creek Nuclear Station, Unit 2	50-355	190
Enrico Fermi Atomic Power Plant, Unit 2	50-341	179	Humboldt Bay Power Plant, Unit 3	50-133	15
James A. Fitzpatrick Nuclear Power Plant	50-333	166	Indian Point Station, Unit 1	50-3	8
Floating Nuclear Plant	STN-50-437	243	Indian Point Station, Unit 2	50-247	37
		16	Indian Point Station, Unit 3	50-286	87
Florida West Coast Nuclear Group, Inc.	50-152		Jamesport Nuclear Station, Unit 1	STN-50-516	285
Forked River Nuclear Station, Unit 1	50-363	197	Jamesport Nuclear Station, Unit 2	STN-50-517	286
Fort Calhoun Station, Unit 1	50-285	86	Kewaunee Nuclear Power Plant	50-305	116
Fort St. Vrain Nuclear Generating Station	50-267	62	La Crosse Boiling Water Reactor	50-409	232
General Electric Test Reactor	50-70	13	LaSalle County Station, Unit 1	50-373	211
Genkai, Unit 1, Japan	50-431	243	LaSalle County Station, Unit 2	50-374	213
Robert Emmet Ginna Nuclear Plant,	50-244	33	Limerick Generating Station, Unit 1	50-352	187
Unit 1	30-244	33	Limerick Generating Station, Unit 2	50-353	188
Gosgen, Switzerland	50-536	295	Maanshan Nuclear Station, Unit 2, Taiwan	50-559	301

Name	Docket	Page	Name	Docket	Page
Maine Yankee Atomic Power Plant	50-309	119	Omaha Veterans Administration Hospital Research Reactor	50-131	15
Manhattan College Research Reactor	50-199	20	Oregon State Univ. Research Reactor	50-243	33
Marble Hill Nuclear Station, Unit 1	STN-50-546	296		50-243	26
Marble Hill Nuclear Station, Unit 2	STN-50-547	297	Oyster Creek Nuclear Power Plant		
Massachusetts Institute of Technology	50-20	11	Palisades Nuclear Plant	50-255	47
Research Reactor			Palo Verde Nuclear Station, Unit 1	STN-50-528	291
William B. McGuire Nuclear Station, Unit 1	50-369	207	Palo Verde Nuclear Station, Unit 2	STN-50-529	292
William B. McGuire Nuclear Station,	50-370	209	Palo Verde Nuclear Station, Unit 3	STN-50-530	294
Unit 2			Palo Verde Nuclear Station, Unit 4	STN-50-592	303
Midland Plant, Unit 1	50-329	160	Palo Verde Nuclear Station, Unit 5	STN-50-593	303
Midland Plant, Unit 2	50-330	162	Peach Bottom Atomic Power Station, Unit 1	50-171	19
Midwest Fuel Recovery Plant	50-268	64	Peach Bottom Atomic Power Station,	50-277	74
Millstone Nuclear Power Station Unit 1	50-245	35	Unit 2		
Millstone Nuclear Power Station, Unit 2	50-336	173	Peach Bottom Atomic Power Station, Unit 3	50-278	76
Milistone Nuclear Power Station,	50-423	242	Pebble Springs Nuclear Plant, Unit 1	50-514	285
Unit 3	00 (23		Pebble Springs Nuclear Plant, Unit 2	50-515	285
Monticello Nuclear Generating Plant	50-263	56	Pennsylvania State Univ. Research Reactor	50-5	9
National Bureau of Standards Reactor	50-184	20	Perkins Nuclear Station, Unit 1	STN-50-488	274
National Naval Medical Center	50-170	19	Perkins Nuclear Station, Unit 2	STN-50-489	275
Nine Mile Point Nuclear Station, Unit 1	50-220	28	Perkins Nuclear Station, Unit 3	STN-50-490	276
Nine Mile Point Nuclear Station,	50-410	234	Perry Nuclear Power Plant, Unit 1	50-440	246
Unit 2			Perry Nuclear Power Plant, Unit 2	50-441	248
North Anna Power Station, Unit 1	50-338	174	Phipps Bend Nuclear Plant, Unit 1	STN-50-553	299
North Anna Power Station, Unit 2	50-339	177	Phipps Bend Nuclear Plant, Unit 2	STN-50-554	300
North Anna Power Station, Unit 3	50-404	231	Pilgrim Nuclear Power Station, Unit 1	50-293	99
North Anna Power Station, Unit 4	50-405	232	Pilgrim Nuclear Power Station, Unit 2	50-471	271
North Carolina State Univ. PULSTAR Reactor	50-297	108	Pilgrim Nuclear Power Station, Unit 3	50-472	271
North Coast Nuclear Plant, Puerto Rico	50-376	214	Plum Brook Reactor - Mock-up	50-185	20
Nuclear Fuels Recovery and Recycle Center	50-564	301	Plum Brook Research Reactor Facility	50-30	13
Oconec Nuclear Station, Unit 1	50-269	64	Point Beach Nuclear Plant, Unit 1	50-266	60
Oconce Nuclear Station, Unit 2	50-270	66	Point Beach Nuclear Plant, Unit 2	50-301	110
Oconee Nuclear Station, Unit 3	50-287	90	Prairie Island Nuclear Station, Unit 1	50-282	84

Name	Docket	Page	Name	Docket	Page
Prairie Island Nuclear Station, Unit 2	50-306	117	Virgil C. Summer Nuclear Station, Unit 1	50-395	224
Purdue Univ. Research Reactor	50-182	20		50-582	303
Quad-Cities Station, Unit 1	50-254	45	Sundesert, Unit 1 Sundesert, Unit 2	50-583	303
Quad-Cities Station, Unit 2	50-265	58	Surry Power Station, Unit 1	50-280	303 79
Rancho Seco Nuclear Generating	50-312	124		50-281	81
Station	50.102	20	Surry Power Station, Unit 2 Susquehanna Steam Electric Station,	50-281	216
Rhode Island & Providence Plantations AEC	50-193	20	Unit 1	30-307	210
River Bend Station, Unit 1	50-458	263	Susquehanna Steam Electric Station, Unit 2	50-388	218
River Bend Station, Unit 2	50-459	264	Texas A&M Univ. Research Reactor	50-59	13
H. B. Robinson Plant, Unit 2	50-261	55	Texas A&M Univ. Research Reactor	50-128	14
Rockwell International Corp. Critical Facility	50-147	16	Three Mile Island Nuclear Station, Unit 1	50-289	91
RPI Critical Experiment	50-225	30	Three Mile Island Nuclear Station, Unit 2	50-320	135
Salem Nuclear Generating Station,	50-272	70	TRIGA Thermionic Prototype Reactor		30
Unit 1	50-212	70		50-227	180
Salem Nuclear Generating Station, Unit 2	50-311	121	Trojan Nuclear Plant Turkey Point Plant, Unit 3	50-344 50-250	41
San Onofre Nuclear Station, Unit 1	50-206	22	Turkey Point Plant, Unit 4	50-251	43
San Onofre Nuclear Station, Unit 2	50-361	192	UCLA Training Reactor	50-231	16
San Onofre Nuclear Station, Unit 3	50-362	195	Union Carbide Research Reactor		13
Seabrook Nuclear Station, Unit 1	50-340	179	Univ. of California at Irvine Research Reactor	50-54	153
Seabrook Nuclear Station, Unit 1	50-443	250	Univ. of California at Santa Barbara Research	50-326	243
Seabrook Nuclear Station, Unit 2	50-444	251	Reactor	50-433	243
		153	Univ. of California Research Reactor	50-224	30
Sequoyah Nuclear Plant, Unit 1	50-327	157	Univ. of Florida Training Reactor	50-83	14
Sequoyah Nuclear Plant, Unit 2	50-328	145	Univ. of Illinois LOPRA Research Reactor	50-356	191
Shoreham Nuclear Power Station	50-322	291	Univ. of Lowell Research Reactor	50-223	30
Skagit Nuclear Power Project, Unit 1 Skagit Nuclear Power Project, Unit 2	STN-50-522		Univ. of Maryland Research Reactor	50-166	19
South Texas Project, Unit 2	STN-50-523	291 277	Univ. of Missouri Research Reactor	50-123	14
• /	STN-50-498		Univ. of Missouri Research Reactor	50-186	20
South Texas Project, Unit 2	STN-50-499	280	Univ. of Oklahoma Research Reactor	50-112	14
State Univ. of New York Research Reactor	50-57	13	Univ. of Washington Research Reactor	50-139	16
Sterling Power Project, Nuclear, Unit 1	STN-50-485	273	Univ. of Wisconsin Research Reactor	50-156	19
St. Lucie Plant, Unit 1	50-335	171	U. S. Geological Survey Research Reactor	50-274	72
St. Lucle Plant, Unit 2	50-389	219	Vermont Yankee Nuclear Power Station	50-271	68

Name	Docket	Page	Name	Docket	Page
Virginia Polytechnic Institute Training Reactor	50-124	14	WPPSS Nuclear Project, Unit 1	50-460	265
			WPPSS Nuclear Project, Unit 2	50-397	226
Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	242			
Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	243	WPPSS Nuclear Project, Unit 3	STN-50-508	283
Washington State Univ. Research Reactor	50-27	12	WPPSS Nuclear Project, Unit 4	50-513	284
Waterford Generating Station, Unit 3	50-382	215	WPPSS Nuclear Project, Unit 5	STN-50-509	284
Watts Bar Nuclear Plant, Unit 1	50-390	221	Yankee-Rowe Nuclear Power Station	50-29	12
Watts Bar Nuclear Plant, Unit 2	50-391	222	fankee-Rowe Ruclear Fower Station	30-29	12
Westinghouse Critical Experiment	50-87	14	Yellow Creek Nuclear Plant, Unit 1	STN-50-566	302
Westinghouse Test Reactor	50-22	11	Yellow Creek Nuclear Plant, Unit 2	STN-50-567	302
West Valley Reprocessing Plant	50-201	20	William H. Zimmer Nuclear Station, Unit 1	50-358	191
Wolf Creek Generating Station	STN-50-482	271	Zion Nuclear Power Station, Unit 1	50-295	103
Worcester Polytechnic Institute Research Reactor	50-134	15	Zion Nuclear Power Station, Unit 2	50-304	114

			1

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-010 BEATTY, NV

8009110578 Notice of nonroutine event involving Agreement State or agreement matl 80-30 State of NV reported three incidents of low level radwaste shipments which did not conform w/ regulatory requirements Meeting scheduled for 800910-11 XERR.8 U , LUBENAU, L. O Office of State Programs, Director 80/09/005 in

DOCKET 27-039 SHEFFIELD, IL . NUCLEAR ENGINEERING CO

- 8009040055 Forwards Waste Packaging Insp Rept 15000039/80-10 on 80070B No noncompliance noted 810HR.J P Region 2, Atlanta, Fuei Facility & Materials Safety Branch 80/07/16 2pp
- --8009040068 Waste Packaging insp Rept 15000037/80-10 on 800708 No noncompilance noted Major areas inspected compilance w/DOT > NRC regulations POTTER:J P. BROWN:R A Region 2. Atlanta. Fuel Facility & Materials Safety Branch 80/07/15 4pp
- B009110099 Forwards Waste Packaging Insp Rept 15000039/80-12 on 800617-20 No noncompliance noted STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Bafety Branch 80/07/29 2pp
- --8009110208 Waste Packaging Insp Rept 15000039/80-12 on 800617-20 No noncompliance noted Major areas inspected shipping paper requirements, radiation lovels & removable contamination, DDT & NRC requirements for external package features MACARTHUR, T C , POTTER, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/07/28 5pp
- 8009090331 Petition for review of ASLAB 800812 decision affirming ASLB order which dismissed application for expansion Aileges error in decision that ASLB action did not constitute major federal action Certificate of Svc encl
 CANNON.J M , WANAT.S W Nuclear Engineering Co , Inc , (subs of Teledyne, Inc) GANNON,J M Mid-America Legal Foundation 80/09/02 12pp
- 8009220179 Advises that Geo-Ctrs.Inc will visit site on 800908-12 to collect independent info using subsurface pulsed radar detection equipment SMITH.R D Low Level Waste Licensing Branch 80/09/03 ip
- B007230055 Advises that Oeo-Ctrs.luc will visit sits on 800708-12 to collect independent info using subsurface pulsed radar detection equipment
 SMITH.R D Low Level Waste Licensing Branch 80/07/03 ip
- B009090400 Order granting extension until 800917 for Commission to elect whether to review ALAB-606 re low level radwaste disposal site HOYLE.J C Office of the Sucretary of the Commission 80/09/05
- 8009120409 Order re 8000928 prehearing conference, determining issues in controversy re possession of SNM & unilateral termination of license Discovery requests to be made by 801010, objections by 801020, responses by 801101 motions by 801115 GOODHOPE, A C Atomic Safety and Licensing Board Panel 80/09/09 3pp
- 8009250002 Motion for clarification of ASLB 800909 prehearing conference order which determined issues to be litigated dwestions relationship between unilateral termination, appropriate termination & possession W/Certificate of Svc LESSY.R P Antitrust Division 80/09/23 7pp

- 8007300017 Order granting extension until 801006 for Commission to consider petition for review CHILK-S J Office of the Secretary of the Commission 80/09/24 to
- DOCKET 27-047 BARNWELL, SC . CHEM-NUCLEAR SYSTEMS
- 8007100067 Provides SC Bureau of Radiological Health w/signed copy of statement of cooperation to establish basis for preparation of joint environ assessment SMITHER D. Low Level Waste Licensing Branch 80/06/30 lp
- ~~8009100072 Forwards signed copy of statement of cooperation to establish basis for preparation of joint environ assessment. Btatement of work is acceptable BHEALY.H O South Carolina, Btate of, 80/05/27 ip
- --B009100076 Statement of cooperation between State of BC (Agreement State) & NRC to establish basis for preparation of joint environ assessment for low level wasts disposal operation SHEALY, H O South Carolina, State of SHITH, R D Low Level Wasts Licensing Branch 80/06/19 2pp
- DOCKET 27-048 RICHLAND, WA , NUCLEAR ENGINEERING CO
- 8007110650 PNO-V-80-061 on 800728. State of MA banned Radiac Research Corp from use of disposal site at Richland, MA Action is based on noncompliance identified by state & NRC inspectors THONAS. R. D. Region 5. Ban Francisco, Office of the Director 80/07/28.
- 8009290123 Forwards Waste Packaging Insp Rept 15000046/80-65 on 800527-30 % notice of violation DAVIS.A D Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/08/18 2pp
- --8007290126 Notice of violation from insp on 800527-30

 * Region 3, Chicago, Office of the Director 80/07/23 in
- --B009290131 Waste Packaging Insp Rept 15000046/80-65 on 800527-30 Noncompliance noted failure to meet strong, tight package requirement contained in DOT regulation LOVENDALE,P C. THUMAS,R D. Region 3. Chicago, Office of the Director BOOK, H E Region 3. Chicago, Fuel Facility & Materials Bafety Branch 80/07/23 2pp
- 8009120125 Forwards closure plan for Hanford commercial low level waste disposal facility Intent is to continue to operate facility until leass termination or facility capacity is reached, whichever comes first
 DE POIX.V P Nuclear Engineering Co . Inc., (subs. of Teledyne, inc.) 80/08/20 3pp
- --8009i20i37 "Closure Plan Hanford Commercial Low Level Waste Disposal Facility, Hanford Reservation, WA " ★ Law Engineering Testing Co 80/05/28 10pp
- ---B009120144 Informs of staff position on status of License 16-17204-01 re continued disposal of SNM at Richland, HA low level radwasts disposal site Requests preliminary site closure design plan
 MARTIN, J B Division of Haste Management 80/07/31 3pp
- --8009120156 Responds to 791219 itr re 1968 license renewal application NRC denied application Rejects proposed License 16-19204-01. No basis for NRC jurisdiction exists re author activities at Hanford.

 NEEL.J N Nuclear Engineering Co . Inc . (subs of Teledyne, Inc) 80/02/04 App

- 8009300312 Ack receipt of 800822 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-344/80-17 800K-M E Region 5, Ban Francisco, Fuel Facility & Materials Safety Branch 80/09/12 1p
- --8009300314 Responds to NRC 800806 ltr re violations noted in 3E insp Rept 50-344/B0-17 Corrective actions procedure implemented requiring checklist be used during insp of drums prior to shipment to verify proper labeling GDDDNIN.C Portland General Electric Co 80/08/22 3pp
- --B0093003:8 Forwards IE Insp Rept 50-344/80-17 on B005:9 & notice of violation BD0X.H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch B0/08/06 2pp
- --8009300319 Notice of violation from Insp on 800419.

 # Region 5, Sap Francisco, Office of the Director 80/09/05
 2pp
- --8009300324 IE lnsp Rept 50-344/80-17 on 800619 Noncompliance noted failure to mark two drums "Redicactive-LSA" & one container appeared to fail requirement of strong tight package FONO.T. MENSLAWSKI.F.A. Region 5. San Francisco. Office of the Director BOOK.H E. Region 5. San Francisco. Fuel Facility & Materials Safety Branch. 80/08/05. 7pp

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0299 UNION CARBIDE CORP

- BD09020478 Forwards NUREO-0702. "FES re Operation of Gas Hills U Project," & FR notice of availabilities SCARNNO.R A Uranium Recovery Licensing Branch BD/08/20 ip
- --8009020504 "FES Re Operation of Oas Hills U Project "
 # Division of Waste Management NUREC-0702 80/07/31 252pp
- 8008130375 Forwards "A-9 Pit.Leaky Aquifer Tasts " Test indicated hydrologic communication through mudstons unit which separates upper & lower wand river formations WONG.Y Union Carbide Corp 80/08/05 ip
- --8008130378 "A-7 Pit,Leafy Aquifer Tests " Three oversize drawings encl RICE:T . HOFFMAN.O L. Hydro-Engineering 80/08/05 41pp
- 800916D549 Farwards rept for QC testing of evaporation pends includes work performed 800717-30 HONG, T Union Carbide Corp 80/08/07 45pp
- 8009240721 Forwards IE Insp Rept 40-D299/80-01 on 800522-29 No noncompliance noted. BROWN, Q D Region 4. Dalias, Fuel Facility & Materials Safety Branch 80/08/16 2pp
- --8009240729 IE Insp Rept 40-0279/80-01 No noncompliance noted Major areas inspected. U mill operations, radiation protection program, facilities & equipment, training, environ monitoring & internal review HUSTAIN, M. J. Region 4, Dallas, Office of the Director GROUN, C. Z. Office of State Programs, Director BROUN, O.D. Region 4, Dallas, Fuel Facility & Materials Bafety Branch 80/08/13 Spp
- 800909039D Feruards FES on Qas Hills U project H/o enci. Linehan, J J Uranium Recovery Licensing Branch 80/08/18 is
- 800911077D Forwards final rept, "Eas't Cas Hills, NY, U Millsite Evaluation " * Barr Engineering Co 80/08/25 ip
- '109170373 Responds to BD0215 & 0609 ltrs commenting on DEB Addresses specific concerns re wildlife & vegetation, wildlife & cattle roosere pathways & monitoring wells CARANG.R A Uranium Recovery Licensing Branch. 80/08/27 Bpp
 - 109170376 Submits comments re-wildlife & vegetation & cattle & wildlife exposure pathways for consideration in connection wifinal Eig.

 DANIELSON.L.J National Wildlife Federation 80/02/15 720

- 8009120390 Forwards Miller Testing Co results in response to NRC request for Lab pinhola test conducted on clay sample taken from liner math used for evaporation pends Sample results show intermediate dispersivity

 WONG.T Union Carbide Corp 80/09/08 2pp
- 8009300281 Notifacation of contract execution "Union Carbide East Gas Hills.WY U Mill Site," awarded to Barr Engineering Co HAIRSTON.G Technical Assistance Contracts Branch FIN B-6941-0 80/09/09 is
- ~-8009300284 Contract "Union Carbide East Gas Hills.WY U Hill Site "
 awarded to Barr Engineering Co
 BARR,D I/ Barr Engineering Co DOUGHERTY.D J Fechnical
 Assistance Contracts Branch FIN 8-6941-0 80/09/09 3pp

DOCKET 40-0672 NUCLEAR METALS. INC

8009120585 States understanding per 800804 telcon confirming 800801 commitments on upgrading low level waste packages prior to shipment for burial NRC must be informed within 24-h if specified actions are not in accordance w/actual plans GRIER.8 H Region 1, Philadelphia, Office of the Director 80/98/07 ip

DOCKET 40-0791 UNITED TECHNOLOGIES, INC.

8009300537 Responds to IE Bulletin 80-22, "Failures of Hestinghouse Type N-2 Spring Return to Neutral Control Switches " No Automation Industries source assemblies owned or operated MANITYMERCKI.P United Technologies Corp. Pratt & Whitney Aircraft Group 50/09/24 ip

DOCKET 40-1162 WESTERN NUCLEAR. INC

- 8009240041 Forwards tailings dam insp rept for 800728-0803 BDQDEN.0 Western Nuclear, Inc. (subs. of Phelps Dodge Corp.) BO/08/05 4pp
- H009180193 Forwards IE Insp Rept 40-1162/80-01 on 800714-15 No noncompliance noted BROWN.8 D Region 4, Dallas, Fuel Facility & Materials Safety Branch 80/08/08 2pp
- ~-8009180203 IE Insp Rept 40~1162/80~01 on 800714~15 No noncompliance noted Major areas inspected training, facilities & equipment, internal exposure control environ monitoring, fire protection & waste mpt BROWN.0 D Region 4. Dallas, Fuel Facility & Materials Safety Branch WILBORN.L., SHOPENN,N M Region 4. Dallas, Office of the Director 80/08/04 App
- 8009180419 Forwards Belit Rock mill tailings dam inse rept for 800804-10 BOODEN, C Western Nuclear, Inc (subs of Phelps Dodge Corp) 80/08/11, 4pp
- 8009150550 Forwards Split Rock mill tailings dam insp rept for 800811-17
 BD00BN.0 Hestern Nuclear, Inc. (subs. of Phelps Dodge Corp.)
 B000BN.0 4pp
- 8009020420 Responds to inquiry made during 800813 meeting in Denver re Commission authority to deal m/license violations Cites relevant acts Congress has increased agency authority to impose civil forfeitures REIS.E.U Hearing Branch 3. 80/08/28 ip
- 8007300141 Forwards trailings dam insp rept for 800825-31 BOGDEN, 0 Western Nuclear, Inc. (subs of Phelps Dodge Corp.) 80/09/03 ip
- 8009120407 Order directing WY Outdoor Council to file suppl to 800629 amended petition to intervene w/specified contentions.by 801010 Applicant & NRC responses shall be filed by 801031 after which prehearing conference will be scheduled WOLFE, 8 J Atomic Safety and Licensing Board Panel 80/09/09 2pp
- DOCKET 40-1341 EDGEMONT URANIUM MINE. TVA & MINES DEVELOPMENT, INC
- 800722003B Forwards "Semiannual Effluent Release Rept Number 10, Jan-June 1980" & errata sheet MILLS,L M Tennessee Valley Authority 80/08/13 1p

- --8009220041 "Semiannual Effluent Release Rept Number 10. Jan-June 1980" * Tennessee Valley Authority RH-80-4-ED2 80/07/31 8pp
- 8009120562 Responds to 800721 request for DEB re Edgement U mill decommissioning Statement being prepared Recipient being placed on distribution list TRAGER: E A Uranium Recovery Licensing Branch 80/08/27 lp
- --8009120565 Requests DES re decommissioning of Edgement U mill LEMBKE, B Affiliation Unknown 80/07/21 ip
- 8009300277 Responds to NRC 800828 request by forwarding procedures for on-sole. A responds to NRC GODOZA request by forwarding procing in-site permeability packer testing performed during geotechnical study Info required for review of preliminary geotechnical study rept MILLG.L M Tennessee Valley Authority 80/09/03 ip
- --B009300280 "In-Site Permeability Packer Testing
 * Yennessee Valley Authority 80/09/03 4pp

DOCKET 40-2061 WEST CHICAGO FACILITY, KERR-MCGEE CORP

- 8007040087 Forwards rept of special survey performed 791127.800110 & 17 & ANL bioassay measurements on individuals who have been occupants of facility bidg KEPPLER.J G Region 3. Chicago. Office of the Director 80/07/17
- --8009040099 Requests that W-1 bldg at 185 West Mashington Street.West Chicago. IL. be removed from iicense Bidg has been surveyed for radiation & is within decontamination guidelines Radiological survey enci
 CRAIO. L. Kerr-McGee Chemicai Corp (subs of Kerr-McGee Corp) CRAIO, L L Ke 74/06/13 7pp
- --8009040104 Advises NRC that gamma-ray spectrometric analysis wes performed on three samples from West Chicago to qualitatively determine which nuclides were present GOLCHERTIN W Argonne National Laboratory 79/12/21 ip
- --8009040109 "Ouidelines for Decontamination of Facilities & Equipment Prior to Release for Unrestricted Use or Termination of Licenses for Byproduct, Source or SNM" 4 Atomic Energy Commission 73/12/31 25pp
- 8009050358 Advises of restrictions & objections re proposed plan of Kerr-McOge Chemicai Co to install incingrator for purpose of reducing voi of therium contaminated mat1 disposed of by RENNELB. A. E. illinois, State of 80/07/29 3pp
- 8009260021 Objects to proposed onsite burial of nuclear matis on behaif of City of West Chicago RENNELS.A E illinois, State of 80/08/05 ip
- 80073002iB Forwards comments on Kerr-McGee Chemical Corp revised plan for decommissioning & stabilizing facilities Environ sampling program for Kress Creek is not adequate to identify possible deleterious effects from plan implementation MCGUIRE.J Environmental Protection Agency 80/08/11 i3pp
- 8009140132 Ack receipt of 800729 comments on Kerr-McGee application for amend of license, authorizing incineration of thorium wastes at West Chicago site Info required for Commission approval CROW, W.T. Uranium Fuel Licensing Branch 60/08/12 2pp
- 80091901iB Forwards 800715 survey of bldg at 185 West Washington Avenue:West Chicago, IL. on 791127, 800110, 17 & 0513 DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch, 80/08/20 ip
- --8009190121 IE special survey of bidg at 185 West Washington Avenue.West Chicago. IL on 791127.800110.17 & 0513 Major areas of contamination ctr sewer spipe.drain pipes, duct in microfilm developing room, two areas of attic floor & others NICHOLSONN A. SHATTERLY.L. W. Region 3, Chicago. Office of the Director DAVIS.A.B. Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/07/15 10pp.
- --- 8009190123 "Radiological Survey for Kerr McGer Facility, W-1 Bidg, West Chicago, IL GUTHEN, M Eberline Instrument Corp 74/09/06

- 8009180440 Responds to 800807 request for matls referred to in 800715 memo to file re-criteria related to waste disposal & site decommissioning Uranium Fuel Licensing Branch 80/09/03 2pp
- -8009180447 Forwards "Fuel Processing & Fabrication Branch Interim Land Cleanup Criteria for Decommissioning V Hill Sites " ROUSE:L C Fuel Process & Fab Branch (Pre 790727) 78/05/24
- --8009180449 "Fuel Processing & Fabrication Branch Interim Land Cleanup Criteria for Decommissioning U Mill Sites " * Advanced Fuel & Spent Fuel Licensing Branch 78/05/24 24pp
- --8009180453 "Ouidelines for Decontamination of Facilities & Equipment Prior to Release for Unrestricted Use or Termination of Licenses for Byproducti Source or SNM" Division of Fuel Cycle & Material Safety 76/11/30 Spp

DOCKET 40-2259 PATHFINDER MINES CORP

- 8009170099 Advises that License SUA-172 is amended by revision of Condition 39 authorizing transfer of tailings samples for environ research purposes BCARAND, R A Uranium Recovery Licensing Branch 60/06/26 10
- 8009180027 Forwards IE insp Rept 40-2259/80-02 on 80072i No NOTIONAL FORWARDS IE INSPIRENT NOTIONAL ON GOOVER NO BROWN 0 D Region 4. Dailas, Fuel Facility & Materials Safety Branch 80/08/08 ip
- --8009180033 IE Insp Rept 40-2299/80-02 on 800721 No noncompliance noted Major areas inspected const activities in progress insp & testing records re ilcense conditions & SER requirements BROKN.0 Region 4. Delias: Fuel Facility & Materiais Safety Branch OALLAGHER, E. J. Region 3. Chicago, Office of the Director 80/08/11 13pp
- B009260045 Notifies of delay in completion of Tailings Dam 4 Excavation required to properly prepare foundation has increased over that estimated by design engineers Requests meeting during whit of 800825 NUGENT.E L Pathfinder Kines Corp 80/08/13 2pp
- 80090305i0 Notifies that 10% piacement of embankment fill on Tailings Dam 4 will be completed on approx 800918.per License SUA-672 Requests info re insp plans NUGENT.E L Pathfinder Mines Corp 80/08/28 lp
- 8009ii0402 Forwards "Semiannual Effluent Monitoring Rept. Jan-June 1980 NUGENTAE L Pathfinder Mines Corp 80/08/29 1p
- --8009i10404 "Semiannual Effluent Monitoring Rept. Jan-June 1980 "
 # Pathfinder Mines Corp 80/08/29 9pp
- --8009110407 "General Land Use Within 5 Mile Distance of Lucky McMill "
 * Pathfinder Mines Corp 80/08/27 lp
- 8009160349 Responds to Point 2(a) of summary of conclusions & commitments per 800912 teicon & 0825 meeting Total vol of liquid stored upstream, effective 800829, summarized NUGENT, E.L. Pathfinder Mines Corp 80/09/12 lp
- 8007170373 Notifies that Chen & Associates will complete design review ro tailings Dam 4 by 801015 Data will be forwarded following NUGENT, E L. Pathfinder Mines Corp 80/09/15 1p

DOCKET 40-2940 NL INDUSTRIES, INC.

- 8009:20132 Forwards NL Nuclear route w/revised guidance NUREG-056; reflecting latest amend to interim rule for physical protection of irradiated reactor fuel in transit Requirements must be implemented by 800703 W/o encls MCCORKLE.O W Physical Security Development Branch 80/07/07 80/07/07 10
- 8007120201 Ack receipt of 800707 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 40-2940/79-01 KINNEKAN,J D Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/07/31 jp

- --B009120220 Responds to NRC 791204 ltr re violations noted in IE Insp Rept 40-2940/79-01 Corrective actions smear test performed on mfg parts & personnel instructed on how to perform smear VUMBACO, F J ML Industries. Inc 80/07/09 200
- --B009120222 Discusses IE Insp Rept 40-2940/79-01 on 791108-09 & forwards notice of violation MCCLINTOCK.R O Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/12/04 2pp
- --8009120223 Notice of violation from insp on 791108-09 Noncompliance noted smear surveys not routinely performed to assure plating free of radioactive contaminants * Region 1, Philadelphia, Office of the Director 79/12/04 ip

DOCKET 40-3392 ALLIED CHEMICAL CORP

- 8009150165 IE Insp Rept 40-3392/80-01 on 800617-19 No noncompliance noted Major areas inspected facility changes & mods, audits, safety committees, training, internal exposure control & transportation activities fisher, N L. Region 3, Chicago, Fuel Facility & Materials Safety Branch PECK, C C. Region 3, Chicago, Office of the Director 30/07/24 Spp
- 8009300241 Resterates request for surrent NRC or agreement state license to receive contaminated 55-gallon U ore concentrate empty drums Also expresses interest in visiting facility AJ Cipolla 800701 ltr enc1 CIPOLLA,A J Allied Chemicai Corp 80/09/19 2pp

DOCKET 40-3459 ATLAS MINERALS

- 8009110739 Responds to NRC 800717 itr re violations at mill Corrective actions sample meter will be placed upon NRC location designation
 SWANBY.G T Atlas Kinerals 80/08/07 lp
- 8009080472 Act receipt of 800807 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 40-3453/80-D2 BRCHNLO D Region 4. Dallas. Fuel Facility & Haterials Safety Branch 80/08/20 1p
- --8009080480 Responds to NRC 800717 ltr re violations noted in IE Insp Rept 40-3453/80-02 Corrective actions will be completed following further instructions from NRC re location of ampler "ANBY, G F Atlas Minerals 80/08/07 ip
 -)80475 Forwards 1E Inse Rept 40-3453/80-02 on 800623-24 & notice of liation NN.9, D Region 4, Dallas, Fuel Facility & Materials Safety Inch 80/07/17 2pp
 - 380482 Notice of violation from insp on 800623-24 Region 4. Dallas, Office of the Director 80/07 80/07/15 10
 - 7080487 IE Insp Rept 40-3453/80-02 on 800623-24 Noncompliance noted onthly background sampling for Rn-222 not performed & regstation foliage not analyzed for Ra-226 SRUNN-9 D Region 4, Dallas, Fuel Facility & Materials Safety Branch WILBURN. 1 CAIN, C L Region 4, Dallas, Office of the Director 80/07/15 6pp
 - 70143 Informs requested monthly repts on river samples for Th-230 226 concentrations were mailed 800324 Provides location se ambient air monitoring stations 0 T Atlas Minerals, 80/08/22 ip

0-4348' COMMERCE, DEPT OF

293 Discusses IE Insp Repts 40-4348/80-01,30-03918/80-01,894/80-01,30-03919/80-01 & 30-11675/80-01 on 800619-20 scampliance noted Major areas inspected selected is & procedures,measurements & observations talk,J D Region i, Philadelphia, Fuel Facility & Materials | Branch 80/06/ii 2pp

- DOCKET 40-4492 FEDERAL AMERICAN PARTNERS (MINING)
- 8009110266 Forwards responses to 800522 & 0703 interrogatories, responses to questions arising from 800707 meeting & RAD data sheets Responses to Questions 34 & 35 of 800703 interrogatories are omitted, due to incomplete info PIERSON, O & Federal American Partners 80/08/27 210pp
- BOO9020193 Advises that organization is on distribution list to receivs Federal-American Partners' DES when completed & all EIS issued by Uranium Recovery Licensing Branch per 800723 request Ratl Hildlife Federation 800723 ltr encl LINEHAN.J J Uranium Recovery Licensing Branch 80/08/ii ip
- --8009020200 Requests addition of name to distribution list to receive DES on Federal-American Partners' U mill & info restatus of relicensing & expansion project DAMTELSON.L J Colorado State Univ 80/07/23 2pp
- 8009190779 Forwards "Preliminary Process Water Balance for Expanded Mill Operation," Figure 3 3-2 in environ rept revised 800800 ADAMS, D.P. Kaiser Engineers 80/08/12 2pp
- 8009170234 Forwards data sheets of principle parameters for radiological assessment PIERSON O W Federal American Partners 80/08/14 10pp
- 8009100133 Summary of BOO717 meeting w/Federal-American Partners. ORNL & consultants in Silver Spring MO re status of DES & outstanding requests for addl info & outstanding environ OlLLEN,D M Uranium Recovery Licensing Branch 80/08/20 lipp
- 8009:00654 Forwards water quality & air sampling data for 800:01-0701 Drawing encl ANDRUS.N J . LANE.J R Federal American Partners 80/08/28 1:3pp.
- --8009100657 "Environ Monitoring Stations" * Federal American Partners 80/08/27 80/08/27 1p

DOCKET 40-4826 NORTHWESTERN UNIV

- 8009110827 Requests amend to Licenses 12-00382-03,12-00382-05, 12-00094-06,SUD-556 & BNK-330 to reflect encl membership of radiation safety committee MILLER.D R Northwestern Univ 80/06/25 2pp
- -BOD9|1083| Notifies that amend to Licenses 12-00382-03,12-00382-05, 12-00094-04,SUD-556 & BNM-330 is fee exempt CQOPER.J. Region 3. Chicago, Office of the Director 80/04/30
- --8009ii0835 Notifies that amend to Licenses i2-00382-03.12-00382-09. 12-00094-06.5UD-556 & SNM-330 is fee exempt MILLER.W D License Fee Management Branch 80/07/18 ip

DOCKET 40-6659 PETROTOMICS CO , GETTY OIL

- 8009100069 Forwards data on whole body counts for 780201,0618,790305 & 0730 PFAFF:S Getty Dil Co , Petrotomics Co Div 80/06/02 8pp
- 8009100188 Forwards IE Insp Rept 40-6659/80-02 on 800515-16 & 0603 & notice of violation SEYFRIT.K.V Region 4. Dallas, Office of the Director 80/06/18,
- --8009100191 Notice of violation from insp on 800515-16 & 0603 * Region 4. Dallas. Office of the Director 80/06/18 2
- --BO09100199 IE Insp Rept 40-659/80-02 on B00515-16 & 0603 Noncompliance noted failure to obtain NRC approval prior to transferring tailings & failure to sample for rador in mill CAIN.C L. Region 4- Dallas, Office of the Director BROWN, O PRegion 4- Dallas, Fuel Facility & Materials Safety Branch 80/06/18 Spp
- ---8009100205 Ack receipt of 800710 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept A0-6659/80-02 Add1 info re use of half mask respirators required BRCWN.9 D Region 4, Dallas, Fuel Facility & Materials Safety Branch 80/07/28 ip

- --8009100212 Responds to NRC 860618 itr re violations noted in IE Insp Rept 40-659/80-02 Corrective actions application for amend submitted to allow transfer of tailings to research facilities
 PFAFF, B J Getty Oil Co . Petrotomics Co Div 80/07/10 2pp
- --8009100217 Ack receipt of 800710 & 0808 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 40-659/80-02 SEYFRIT.K V Region 4, Dallas. Office of the Director 80/08/21
- --8009100222 Responds to NRC 800728 ltr re violation re half mask respirators noted in IE lnsp Rept 40-6659/80-02 Personnel instructed & areas posted where half mask respirators will not suffice H/o encl documentation
 PFAFF.8 J Oetty Gil Co . Petrotomics Co Div 80/08/08 1
- 8008080187 Forwards Hydro-Engineering rapt, "Geglogic & Monitor Well Info for Petrobomics Tailings Reservoir Area " Rept contains Info for Petrotomics Tailings Reservoir Area " Rept of info for Petrotomics Tailings Reservoir Area " Rept of info requested in Section 258 i of Amend 7 to License SUA-551 PFAFF.8 J Cetty Dii Co , Petrotomics Co Div 80/07/30 1p
- ---8008080193 "Geologic & Monitor Well Info for Petrotomics Tailings Reservoir Area " Dversized drawing encl PLAYTON, S J Hydro-Engineering 80/07/31 10pp
- DOCKET 40-8027 KERR-MCGEE CORP
- 8009300656 Application for amend of License SUB-1010.authorizing controlled release of hay grown on land fartilized byraffinate Justification for amend encl SHELLEY, M J Kerr-McGes Nuclear Corp 80/08/15 7pp

DOCKET 40-8084 LISSON MINE, RIO ALGOM CORP

- 8009120603 "Rept of Ceotechnical Evaluation to Support Request for 5-Ft Dam Raise-Upper Tailings Pond Embankment Sys, Lisbon Vailey Cogrations Dames & Moore 80/08/22 60pp
- 8009100936 Discusses Region 4 enforcement action as result of recent insp Requests participation w/region in mgt meeting planned w/Rio Algom officials SCARAND.R A Uranium Recovery Licensing Brench. 80/08/25 ip
- BOO9300520 Discusses Dames & Moore "Rept of Geotechnical Evaluation to Support Request for 5-ft Dam Raise " Urges early approval for commencement of const LAWTON.M D Rio Algom. Ltd 80/08/27 2pp

DOCKET 40-B092 NASA

- 8009300180 Forwards IE Bulletin 79-i9, "Packaging of Low Level Radwaste for Transport & Burial " Response required SEYFRIT,K V Region 4, Dallas, Office of the Director 79/08/10
- --8009300185 Responds to IE Bulletin 79-19, "Packaging of Low Level Radwaste for Transport & Burlai " Radwaste transferred to contractor JOHNSTON, R. B. National Agronautics & Space Admin 79/09/18 2pp
- DOCKET 40-BIO2 EXXON MINERALS CO USA, EXXON CORP
- 8009100288 Forwards hydrologic review of Exxon Minerals tailings disposel site at Highland Mine & Mill site Land Quality Div favors below grade disposal at Exxon site to minimize environ degradation for future tailings ACKERMAN. H C Hyoming. State of 80/07/29 26pp.
- B009020123 Summary of 800630,0701 & 02 site visits by WY Dept of DAYOCALES GOMERY OF GUOGIO, OF A US SITE VISITS BY A USED BY Environ Quality, HY Mineral Co & Exxon to MY Mineral Irigaray Site, Exxon Highland Site & Rocky Mountain Energy Bear Creek to observe water quality monitoring program VANDELL, T D Uranjum Recovery Licensing Branch 80/08/11 App

DOCKET 40-8113 UTAH, UNIV OF

- 6009130364 Act receipt of 800731 ltr informing NRC of steps taken to correct violations noted in 1E lnsp Repts 30-05219/80-02 & 30-14452/80-02 XINNEMANJ D Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 60/08/11 ip
- --8009150373 Responds to NRC 800703 ltr re violations noted in IE Insp Repts 30-05219/80-02 & 30-14452/80-02 Corrective actions monthly & annual check list sys instituted & steps taken to document complete & proper evaluation procedures SCHULTZ.D F Teledyne Isotopes 80/07/31 2pp
- --8009150380 Discusses 1E Insp Repts 30-05219/80-02 & 30-14452/80-02 on 800614 & forwards notice of violation KINNEMAN, J D Region 1, Philadelphia, Fuel Facility & Hatarials Safety Branch 80/07/03 2pp
- --80091503B7 Notice of violation from insp on 800614 Noncompliance noted failure to adequately evaluate 80032B release to semage sys from holdup tank & failure to test sealed sourcos for leakage or contamination since 790820 w Region 1, Philadeiphia, Office of the Director 80/07/03 lp

DOCKET 40-8180 OKLAHOMA, UNIV OF

- 8009260390 Forwards IE Bulletin 79-19, "Packaging of Low Level Radwaste for Transport & Burial " Response required SEYFRIT,X V Region 4. Dallas, Office of the Director 79/08/10
- --8009280408 Responds to IE Bulletin. "Packaging of Low Level Radwaste for Transport & Burial " One shipment of radwaste made since 1978 JAMES, J Dklahoma, Univ of 79/10/16 2pp
- DOCKET 40-834B IN SITU URANIUM LEACHING PROJECT
- 8009190767 Submits costs incurred & manpower expended for review of EADIE, 0 0 Uranium Recovery Licensing Dranch 80/09/02 ip

DOCKET 40-8380 ROCKY MOUNTAIN EKERGY CO

- 8009240133 Forwards revised Table 1 to "Effluent Monitoring Rept. Jan-June 1980." re Pattern 111 water quality NEUMANN, M R Rocky Mountain Energy Co 80/08/12 2pp
- --8009260159 "Effluent Monitoring Rept, Jan-June 1980," revised Table I re Pattern III water quality + Rocky Mountain Energy Co 80/08/12 5pp
- 8009260024 Forwards 800714 & 0805 assay results re Pattern III monitor wells No significant change in water quality since last rept Elavated vanadium levels will be corrected w/increased pumping rate NEUMANI, H R Rocky Mountain Energy Co GO/08/14
- 8009170237 Revises Table I from 800812 ltr Correct sulfate mean value in Monitor Well M-40 is 1,225 mg/liter Also, range for vanadium in Well M-41 reversed Correct low value is 0.05 mg/liter & correct high value is 0.7 mg/liter NEUMARN, M R Rocky Mountain Energy Co 80/08/15 ip

DOCKET 40-8452 DEAR CREEK URANIUM CO

- 8007020123 Summary of 800630,0701 & 02 site visits by MY Dept of Environ Quality, MY Mineral Co & Exson to MY Mineral Irigaray Site.Exxon Highland Site & Rocky Hountain Energy Bear Creek to observe water quality moniforing program VANDELL, T D Uranium Recovery Licensing Branch 80/08/11 6pp
- 8009180072 Forwards IE Insp Rept 40-8452/80-01 on 800716-17 & notice of violation BRONN 0 D Region 4, Dallas, Fuel Facility & Materials Safety Branch BO/OB/13 2pp
- 80/08/12

- --8009180081 tE tasp Rept 40-8452/80-01 on 800716-17 Noncompliance noted failure to minimize dusting of tailings & to implement means to obtain quarterly gross beta measurements BROWN.0 D Region 4. Dallas. Fuel Facility & Materials Safety Branch SHOPENN.N M . WILBORN.L Region 4. Dallas. Office of the Director 80/08/12 8pp
- 8009180336 Authorizes travel costs & prof svcs for R Hilliams trip to Silver Spring MD re meeting w/MRC & licensee to discuss below grade tailings disposal plan SCARAND, R A. Uranium Recovery Licensing Branch 80/08/20 Ip
- 8009030462 Forwards semiannual environ monitoring rept for period ending 800630 8LUSSON.J N Bear Creek Uranium Co 80/08/29 ip
- --B009030465 Semiannual anviron monitoring rept for period ending 800630 • Bear Creek Uranium Co. 80/08/29 10pp
- DOCKET 40-8502 IRIGARAY MINE, WYDMING MINING CORP
- 8009100471 Forwards revised 790508 rept on Irigaray mine excursion potential Changes reflect recent experiences

 DAVIS-D Hydrology Associates, Inc. 79/06/14 14pp
- 8008110036 Forwards 800710 % 14 itrs to State of WY re leak in Evaporation Pend C & excursion status of Monitor Well 9M-22 Leakage ninor Excursion status caused by sulfate ion MICHERS D L Wignamy Hineral Corp 80/07/14 7pp
- --9008(10038 "Location of 9½-22 & Surrounding RS & Trend Wells "

 # Wyoning Mineral Corp 80/07/11 lp
- 8008120614 Forwards 800710 shallow monitor zone status rept & 800714 ltr re Shallow Monitor Well 95M-14 Shallow zone data inducates that overall valves are responding to control/ cleanup program Well 95M-14 is off excursion status WICHERS.D L. Hyoming Hineral Corp. 80/07/23 20pp
- --8008120620 "Location of Shallow Zone, Unit 1 Sand & Hater Yable, Monitor Wells. Units 4 & 5 Shallow Zone Control Program " # Wyoming Mineral Corp 80/06/24 1p
- --8008120626 "Location of Shallow Zone, Unit 1 Band & Water Table. Monitor Wolls. Units 4 & 5 Shallow Zone Control Program "

 # Wyoming Mineral Corp 80/06/24 1p
- --8008120630 "Location of Shallow Zone.Unit 1 Sand & Water Table.Monitor Wells.Units 4 & 5 Shallow Zone Control Program " + Wyoming Mineral Corp 80/06/24 1p
- --8008120631 "Location of Shallow Zone, Unit I Band & Water Table, Monitor Walls, Units 4 & 5 Shallow Zone Control Program " " Wyoming Mineral Corp 80/06/24 lp
- BOO9170240 Submits rept per Condition 31 for License SUA-1341 Monitor Well 9K-22 is off excursion status Due to sudden increase in sulfate, conductivity & alkalinity & subsequent return to normal source & cause investigations are continuing WICHERS, D. L. Wyoming Mineral Corp. 80/08/01 2pp
- 8009020490 Orders cessation of pumping in all shallow zone wells by 800823 Neekly sampling program will be initiated to determine status of shallow zone excursions in monitor wells \$M-4.5M-9.5M-12 & 5M-14 MORROW.D Wyoming. State of 80/08/08 lp
- 8009020123 Summary of 800630,0701 & 02 site visits by HY Dept of Environ Quality, HY Mineral Co & Erron to HY Mineral Irigaray Sites Erron Highland Site & Rocky Mountain Energy Bear Greek to observe water quality monitoring program VANDELL, T D Granium Recovery Licensing Branch 80/09/11 App
- BOD9150023 Confirms 600Bil notification re BOOBO7 chloride values in Bhallow Unit 1 Band Well 6SM-4 Forwards table showing Initial value 2 most recent sample analysis for BBM Wells 1-5 Downward trand observed in all wells TIEFEL.E W Wyoming Mineral Corp BO/08/12 3pp
- 1009150530 Summarizes 800730 meetings w/E Tiepel & C Chien & NRC & response to data submittal re NRC questions on hydrology rept Urgs high quality & correct analysis in future hydrologic studies Awalts RW Davis data re leakage SCARANO.R & Uranium Recovery Licensing Branch 80/09/03 5pp

- 8009300191 Forwards requested Electric Logs LI-18,LP-17,LP-28,LP-43, KI-138 & KP-53 H/o encis MICHERS,D L Wyoming Mineral Corp 80/09/03 1p
- DOCKET 40-8568 AIR FORCE, DEPT OF
- 8009020533 IE Insp Findings & Licensee Ack on 800711 of License SUB-1282 Insp findings no noncompliance noted * Region 2, Atlanta, Office of the Director 80/07/11 ip
- DOCKET 40-8584 UNION 76 MINERALS EXPLORATION CO
- 8009110850 Forwards Table 2. "Estimate of Cost of First Yr of Reclamation." from application for permit to mine ACOSTA:A P Union 76 Minerals Exploration Co 80/07/28 App
- 8009180089 Forwards 1E Insp Rept 40-8984/80-01 on 800722 No noncompliance noted DROWN 0 D Region 4, Dailas, Fuel Facility & Materials Safety Branch 80/08/08 lp
- --8099180093 IE Insp Rept 40-8584/80-01 on 800722 No noncompliance noted Major areas inspected insp 2 testing records re license conditions & SER requirements BRONN, O Region 4, Dallas, Fuel Facility & Materials Safety Branck QALLAGHER, E J Region 3, Chicago, Office of the Director 80/08/04 23pp
- 8009150476 Ack receipt of 800724 ltr re QC program for urine specimens Request classified as requiring minor amend to License SUA-1350 Minor safety & environ amend fee required MEISS.D License Fee Management Branch 80/08/21 ip
- 8009030470 Forwards fee for minor safety amend review re unine analysis GC program ACOBTA-A P Minerals Exploration Co (subs of Union Dil Co of California) 80708/25 ip
- DOCKET 40-8663 NUCLEAR DYNAMICS. INC
- 6009260363 Forwards IE Builetin 79-19, "Packaging of Low Level Radwasts for Transport & Burial " Response required SEYFRIT.K V. Region 4, Dailas, Office of the Director 79/08/10,
- --8009260475 Responds to 1E Bulletin 79-19. "Packaging of Low Level Radwaste for Transport & Burial " No radwaste generated STOICK.A F Nucor Gorp 79/10/23 2pp
- DOCKET 40-8691 ENERGY FUELS NUCLEAR, INC.
- 8009300409 Forwards "Annual Rept Meteorological & Air Quality 16 Observations.White Mesa U Project Near Blanding.UT, June 1979-1980, " inadvertently omitted from semiannual effluent rept submitted by D Roberts on 800829 BAKER.C.E Energy Fuels Nuclear. Inc 80/09/25 ip
- --8007300414 "Annual Rept Meterological & Air Quality Observations, White MESA U Project Near Blanding, UT, June 1979-1980."
 + Steams-Roger, Inc. 80/07/31. 216pp
- 8009180034 Notifies of Amend 3 to License SUA-1358, revising Conditions 11 & 38 to authorize addition of second crusher unit & to clarify environ monitoring program Other conditions remain unchanged Refs CE Baker 800414 request & 800507 telcon SCARAND, R A Uranium Recovery Licensing Branch 80/06/04. 2pp
- 8009140845 Requests investigation to determine if Energy Fuels Nuclear, Inc is implementing conditions of license re avoidance, minimizing 8 mitigating adverse effects of project on White Mesa Archeological District WALL, L. 8. Advisory Council on Historic Preservation 80/07/25
- B009170139 Forwards determination of eligibility for inclusion in Natl Register of White Mesa Archaeological District District is eligible for inclusion SMULL.6 D Interior.Dept of 80/08/11 3pp

ŧ

8009170127 Forwards documentation of insp of Cell 2 PVC liner installation & test results on underdrain inplace densities performed by D'Appolonia Consulting Engineers ROBERTS: H R Energy Fuels Nuclear; Inc 80/08/12. 3pp 8009300237 Submits rept in accordance w/Condition 39 of License SUA-1358 Survey of land use within 5 miles of facility indicates that use of area has not changed Changing of ownership has occurred but land is still agricultural ROBERTS.D Energy Fuels Nuclear. Inc. 80/08/20 lp

8009100666 Forwards rept of measured concentration of principal radionuclides released to unrestricted area for Jan-June 1980
ROBERTS, D Energy Fuels Nuclear, Inc. 80/08/29 2pp

DOCKET 40-8692 COTTER CORP

8009170423 Forwards recent correspondence w/Cotter Corp & Dept of Environ Quality re Charlis Area U Mine reclamation efforts Unable to iocate 800626 ltr from Cotter Corp MQUNEY. O Wyoming. State of 80/07/25 7pp

8009i60651 Notifies of Amend 1 to License SUA-i370 authorizing reactivation of thin layer leach pilot plant facility to conduct second test in which approx 25 tons per day crushed U ore will be processed for 60 days over 45-day period SCARANQ R A Uranium Recovery Licensing Branch 80/07/3i 3pp

8009190781 SePety/environ evaluation of Cotter Corp 800626 request for amend to License SUA-1370 authorizing second pilot plant scale test Recommends approval subj to Indicated provisions ROTHFLEISCH.J., MILLER, H.J. Uranium Recovery Licensing Branch 80/004189 498

8009i50597 Responds to 800728 telcon re addl info on License Conditions 2i & 22 of RML i370 & Amend 1 Radiological safety & environ sampling data collected in i979 & description of pilot plant facilities enci SMITH.T C Cotter Corp 80/08/25 i3pp

DOCKET 40-8693 DOLE PETROLEUM, INC

8009030455 Submits quarterly rept for May-Jui 1780 re U mining operation under Licenso 8UA-1336 Operational summary, flow rates & monitoring data encl SAUNDERGO A CATCHPOLE, O J Ogle Petroleum, inc 80/08/22 68pp

DOCKET 40-8697 ROCKY MOUNTAIN ENERGY CO

8009080453 Bubmits quarterly rept for Apr-June 1980 for Reno Creek in situ test facility SPIELE8.P Rocky Mountain Energy Co 80/07/31 Spp

DOCKET 40-8498 PLATEAU RESOURCES, LTD

8009260027 Submits efficient monitoring rept for Jan-June 1980 800TT.A D Piateau Resources, Ltd 80/08/22 ip

DOCKET 40-8721 ROCKY MOUNTAIN ENERGY CO

BOOB110042 Forwards "Alternative Analysis of Process Waste Disposai Options:" as preliminary version of matl which will be included in revised environ rept NEUMANN.M R Rocky Mountain Energy Co BO/07/14 Spp

--8008110046 "Alternative Analysis of Process Waste Disposal Options " Bayen oversize drawings encl * Rocky Mountain Energy Co. 80/07/16 17pp

DUCKET 40-8724 CHEMTRON CORP

8007300112 Notifies that plant operations do not involve use of depieted U Responsibliity for removal of depleted U at dump site should be placed on Chematron Corp License 8018-852 ZELLNER, R J McGean Chemical Co , Inc 80/08/21 2pp

DOCKET 40-8743 CONOCO

800709019B Submits key ref document listing in support of Sand Rock
Mill application
GUIGLEY, T. W. CONDCO, Inc. (Continential Oil Co.) 80/07/30 3pp

8007130198 Requests archeological/paleontological clearance for Sand Rock Mill Project.Section 1.741N.R75M & Forwards "Results of Archaeological & Paleontological Survoys for Sand Rock Mili Project.Southern Campbell County.UW Related 1tr encl QUIGLEY.T W Conoco Coal Development Co 80/08/14 5pp

--8009150164 "Results of Archaeological & Paleontological Surveys for Sand Rock Mill Project Southern Campbell County, MY " GRANT,M , CARPENTER,K , LENNON,T J Hestern Cultural Resource Management in. , 80/07/15 Sopp

B009i60020 Forwards Band Rock mill project application & environ rept. for immediate review Deficiencies required addl info & evaluation of proposed actions must be identified Proposes discussion of schedule & scape of work on 800826 My encis MILLER, H & Uranium Recovery Licensing Branch 80/08/19 lp

8009150117 Advises of review completion of 800731 application for source math license w/supporting environ rept Documents acceptable for detailed review Scoping meeting scheduled on 801016 in Casper, MY Principal contact. W Hamill SCARRAND, R A Uranium Recovery Licensing Branch 80/08/29 4pp

---8009150123 Notice of availability of environ rept 2 announcement of 801016 scoping meeting in Casper, WY re application for source matl license to construct 8 operate Sand Rock Mill project NRC DES will be available on 810301 SCARANO, R A Uranium Rocavery Licensing Branch 80/08/27 2pp

DOCKET 40-8745 DOLE PETROLEUM

8009020592 Comments on DES, Section 4 5 i re project No site specific air quality data obtained Time duration for expected atmospheric concentrations should be specified Internal memo encl RAFFELSON, C N Wyoming, State of 80/07/21 3pp

BO09050362 Forwards drawing of initial survey locations for in-plant radiological monitoring program CATCHPOLE:0 J Ogie Petroleum. Inc 80/07/28 2pp

BOO9030258 Comments on draft EiS inclusion of provision addressing need for human svc programs for inhabitants of vicinity recommended MASIER.W Health & Human Services, Dept. of, 80/07/29 2pp

8009i60546 Forwards comments from various state agencies on DES for consideration & use in proparing final analysis HARTMAN.D Wyoming, State of 80/07/29 23pp

8009170134 Discusses NRC DES on Ogle Petroieum proposed commercial in situ U mine Recommends NRC environ statement be modified to include groundwater restoration plan ACKERMAN,W C Wyoning, State of 80/08/04 2pp

8009170i30 Discusses review of draft EiS for Bison Basin V in situ mining project Project will have little effect on radionuclides in environ STROUSE, N B HHS. Dept of, US Public Health Bervice 90/09/05

8009130592 Forwards latest proposal to DEG for well integrity tosting Will forward revised pages to DEG application W/o encis CATCHPOLE.G J Ogie Petroleum. Inc. 80/08/06 lp

800902050B Comments on DES re Daie Petroleum, înc Bison Basin In-Silv U Project NRC should recognize that U operations cause (solated, cumulative M/or synergistic environ impacts EAST.D J Myoming Outdoor Gouncil 80/08/07 7pp

8009150355 Informs that Water Quality Div has no objections to approving Ogle Petroleum, Inc application to operate Bison Basin Project
MANCINI.A J Wyoming, State of 80/08/07 lp

8007020170 Forwards comment latters re Bison Basin Project DES Requesta appropriate reply to questions & comments Responses should be provided in sufficient detail to permit direct inclusion in FES Responses should be mailed before 800827 W/o encis ROTHFLEISCH. J Uranium Recovery Licensing Branch 80/08/11 2pp

8009300202 Forwards requested Geophysical Logs OP-83, OP-86, OP-87, OP 60. OP-89, BBX-146, BDX-187 & CBX-147 & "Introduction to Well Log Analysis," for data interpretation 170 encl. SCATCHPOLE, O J Ggle Petrolsum, Inc. 80/08/12 ip

- 900702051B Forwards MY Dutdoor Council 900807 ltr.WC Ackerman 800804 memo & NC Raffelson 800721 memo re Bison Basin Project DES M/o encls ROTHFLEISCH.J E Uranium Recovery Licensing Branch 80/08/13 &p
- 8009170144 Forwards review comments on DES re Ogle Patroleum Bison Basin Project Recommends dual cell design for waste pond sys for alternate holding area in event of leakage in primary cell
- WILLIAMS.R L Environmental Protection Agency 80/08/18 8pp
- B007030476 Notifies that response to Natl Wildlife Federation comments cannot be forwarded by 800822, due to large number of comments received Comments will be forwarded as soon as possible CATCHPOLE.O J Ogie Petroleum, Inc. 80/08/20 ip
- 8009150209 Forwards State of MY Game & Fish Dept 800821 itr commenting on DES Requests reply to comments re additional field work fencing of access road & proposed reclemation practices ROTHFLEISCH, J Uranium Recovery Licensing Branch 80/08/28 lp
- ---8009150212 Comments on DES Recommends further field work to evaluate project impact on wildlife Requests documentation to support reclamation claims 8 assurances access road will not be fenced
 DEXTER.W D Wyoming, State of 80/08/21 2p
- 8009030385 Forwards approved MY Dept of Environ Quality mine permit application CATCHPOLE. 0 J Ogle Petroleum, Inc 80/08/29 14pp
- 80071603B3 Forwards responses to Natl Hildlife Federation 800718 comments re environ impact of project. General comments deal w/antelope migration properational monitoring downward migration & "no action" alternative CATCHPOLE, O J Ogle Petrojeum. Inc. 80/09/03 25pp
- 8009160462 Forwards responses to WY Outdoor Council 800807 comments re commercial source mail license application Responses were not provided for comments dealing U/NRC policy issues or which referred to sections of DES CATCHPOLE.O J Ogie Petroleum. Inc 80/09/03 10pp
- 3007160386 Forwards responses to EPA draft comments re commercial source matl license application Responses were not provided for comments dealing w/NRC policy issues or sections of DES CATCHPOLE.G J Ogle Petroleum. Inc 80/07/04 App
- 8009140331 Advises that no response is planned to FS Lisella 800721 ltm CATCHPOLE,O J Ogle Petroleum, Inc. 80/09/05 ip.
- -8009(6033) Advises that proposed project will not have any significant impact on endangered species in response to DDI 800723 ltr CATCHPOLE, G J Ogle Petroleum, Inc. 80/09/05 ip
- ~-8009160334 Advises that no response is planned to W Master 800729 ltr CATCHPOLE.O J Ogle Petroleum, Inc. 80/09/05 ip
 - 109(60326 Responds to LE Allen 800717 mans to D Hartman Permits for evaporation ponds have been applied for & no const will begin until permits are received Nater supply for nonprocess activities comes from well permitted by state engineer CATCHPOLE.6 J Ogie Petroleum, Inc. 80/09/05 2pp
 - O9100315 Advises that no reponse is planned to HY Dept of Health & Social Svc 800623 memo except that number of anticipated employees is approx 30 Cursory perusal of DES resulted in one misconceptions
 17CHPDLE.G J Ogle Petroleum. Inc 80/09/05 1p
 - 160348 Responds to Dept of Commerce 800731 ltr.including RB Rollins 3722 memo to UM Woods No geodetic control survey monuments within project area No plans to relocate monuments in inection william Basin project TCHPDLE: 6 U Ogle Petroleym, Inc. 80/09/03 19
 - 160350 Responds to NA Lockstet 800803 comments re wellfield & nitaring Pumping wells for sampling more frequently than a period tends to produce excursions since two casing a must be pumped each time well is sampled CHPCLE.9 J Ogie Patroleum. Inc. 80/09/05 2pp

- --8009160354 Advises that no response is planned to WC Ackerman 800864 memo to RE Sundin since comments are more in form of comparisons rather than questions CATCHPOLES of Ogle Petroleum. Inc. 80/09/05 lp
- --B009160356 Advises that no response is planned to CN Raffelson 800724 memo to RE Sundin except to state that CP mentioned in last paragraph 1s being pursued 6ATCHPDLE.G J Ogle Petroleum, Inc. 80/09/05 ip
- 8009190389 Submits changes to DES Related documentation encl GATCHPOLE Q J Ogle Petroleum, Inc. 80/09/15 Spp
- 8009190392 Forwards addl data re surface water quality in vicinity of facility, in response to NRC 791204 itr CATCHPOLE.G J Ogle Petroleum, Inc. 80/09/15 3pp
- 8007220332 Submits responses to rinal EPA comments Preferred oxidizar utilized for Bison Basin Project is oxygen Hydrogen peroxide will be used as backup oxidizer Some pipeline will be buried & some portione will be on surface CATCHPOLE, O.J. Ogle Petroleum, Inc. 80/09/16 3pp
- 8009300457 Forwards map showing all exploration holes drilled & plugged w/bentonite & cement in response to 800908 ltr re commercial source mati license application Response to Item 6 transmitted on 800915 CATCMPOLE.Q J Ogle Petroleum, Inc. 80/09/22 3pp
- DOCKET 40-8748 KERR-MCKEE NUCLEAR CORP
- 8009150575 Forwards 800806 ltr not received by NRC re establishing baseling groundwater quality values
 FREEMAN, H. D. Kerr-McGee Nuclear Corp. 80/08/21 1p
- --8009150577 Responds to 800701 ltr re establishing baseline groundwater quality values Min of three samples to be taken from each monitor well w/samples analyzed for excursion parameters FREEMAN. M D Kerr-McGee Corp. 80/08/06 ip
- 8009100473 Confirms 800820 beloon w/G France & advises of status of licensing review in-depth review of application to begin mid-Oct
 MILLER/H J Uranium Recovery Licensing Branch 80/08/25 ip

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-3 INDIAN POINT STATION, UNIT 1

- F Security, medical, emergency & fire protection plans
- 8009230167 Requests that all personnel be reminded of purpose of emergency notification sys 3 health physics network Sys installed for govt use during emergency ORIER. B H Region i. Philadelphia. Office of the Director 80/08/22 3pp
- G Adjudicatory correspondence
- 8009120394 Order granting extension until 800926 for Commission to review ALAB-436 & relevant portions of ALAB-361 CHILK, S.J. Office of the Secretary of the Commission 80/09/10 lp.
- 8009300320 Order granting extension until 801024 for Commission to review ALAB-436 t ALAB-561, CHILK S J Office of the Secretary of the Commission 80/09/26
- H General correspondence
- 8009180448 Responds to 800319 ltr requesting public debate re issues appropriate to evacuation of large population ctrs near plants
 DENION, H R Office of Nuclear Reactor Regulation, Director 80/04/21 3pp

- --8009180462 Requests public debate re issues appropriate to evacuation of large population ctrs near piants Expresses confidence in attempts by Commissioners to represent public concerns EMDRY.K Affiliation Unknown 80/03/19 ip
- 8009040404 Forwards petition reflecting deep concern re safety of facility
 CINGUEMANI.D K . CINGUEMANI.F L Affiliation Unknown 80/08/28
- 8009110218 Forwards response to 800728 itr requesting assistance in answering constituent questions re nuclear power & effects of radiation DIRCKS.W J Office of the Executive Director for Operations DIRCKS.W J 0 80/08/28 4pp
- P Operating license stage documents & correspondence
- 8009300i69 "Rept of Zion/indian Point Study Voi 2." informal rept STEVENSON.H 9 Los Alamos Scientific Laboratory FIN A-70i5 NUREG/CR-14i1 V2 80/04/30 i65pp Available at NTiS
- 8009020297 Submits interim criteria for shift staffing to all OL & CP iicensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D C Division of Licensing 80/07/3i
- 8007080080 Forwards draft NUREC-0676. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREC-0696 encl M/o NUREG EISENHUT, D & Division of Licensing 80/08/01 i19pp
- 8009230052 Informs that exemption from fee re licensing action associated v/TM1-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D O Division of Licensing 80/08/07 60pp
- 8009190794 Forwards revised Westinghouse STS 3 9 8 2,3 9 10 & Bases 3/4 9 8 & 3/4 9 10 to require 23 ft of water over top of reactor pressure vessei flange during movement of fuel assemblies or control rods Written response required NOVAK.T M Assistant Director for Operating Reactors 80/08/i5
- --8009190817 Revised Westinghouse STB 3 9 8 2,3 9 10 % Bases 3/4 9 8 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods # Assistant Director for Operating Reactors 80/06/23 21pp
- B0090903B3 Forwards "Rept on Evaluation of Thermal Piume Studies of indian Point Nuclear Generating Etation " Objectives of thermal plume program have been fuifilied Rept available in Central Files only ZARAKAS,P Consolidated Edison Co of New York B0/08/29 ip
- 8009120502 "Rept of Zion/Indian Point Study," Vol i MURFIN.W B Bandia Laboratories FIN A-1218 NUREQ/CR-1410 VI 80/08/31 400pp.
- 8009250266 Forwards current training course outlines re heat transfer, fluid flow & thermodynamics, in response to NRC 800328 ltr ZARAKAS,P Consolidated Edison Co of New York 80/07/i7 30pp
- G Inspection reports, IE Sulietins & correspondence
- BOOTO90242 Responds to IE Builetin 80-14 Unit 2 has no specified transmitters installed Unit 1 shut down since 741031 & in dafueled condition ZARAKABJP Consolidated Edison Co of New York 80/07/30 2pp
- 8009120187 Responds to IE Dulletin 79-03A re langitudinal wald defects purizuia/ Responds to IE Bulletin 79-03A re longitudinal weld in 8A-312 or A-312 Type 300 stainless steel piping Unit 1 is in defueled condition Unit 2 piping satisfies criteria re allowable stress ZARAKAS.P Consolidated Edison Co of New York. 80/08/06 Consolidated Edison Co of New York. 80/08/06 2pp
- 8009030073 Forwards Revision i to IE Bulletin 80-i9, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER.8 H Region i, Philadelphia, Office of the Director 80/08/15 ip

- 8009180339 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GRIER.B H Region 1. Phriadeiphia. Office of the Director 80/08/22 1p
- 8009120171 Forwards IE Info Notice 80-31. "Maioperation of Oculd-Brown Boveri 480 Voit Type K-600S & K-DON 6QOS Circuit Breakers " No written response required GRIER B H Region 1. Philadelphia, Office of the Director 80/08/27 lp
- 8009090423 Responds to 1E Bulietin 80-15, "Possible Loss of Emergency Notification Sys W/Loss of Offsite Power" Insp revealed loss of emergency notification sys on 800602 due to poor motor generator brush contact ZARAKAS.P Consolidated Edison Co of New York 80/09/02 2pp
- 8009230778 Forwards IE Circular 80-21, "Regulation of Refueling Crews " No written response required ORIER.B M Region 1. Philadelphia. Office of the Director BO/09/10 is
- B009240304 Forwards iE info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls "No written response required GRIER.D H Region 1. Philadelphia, Office of the Director B0/09/12 Ip
- R Periodic operating reports & related correspondence
- 8009030382 Forwards "Effluent & Waste Disposal Semiannual Rept. Jan-June ZARAKAS,P Consolidated Edison Co of New York 80/08/29
- --8009030386 "Effluent & Waste Disposal Semiannual Rept, Jan-June 1980 "

 Consolidated Edison Co of New York 80/08/29 43pp
- 8009230432 Forwards daily record of fash collections for Aug 1980, including daily species breakdown & total weight Unit 2 & 3 circulators were run for entire month Unit 1 circulators were run on 800808,10,13,17,19,21,23,30 & 31 ZARAKAS,P Consolidated Edison Co of New York 80/09/15 ip
- ---8009230433 Daily record of fish collections from intake screens for Aug 1980 « Consolidated Edison Co of New York BO/09/15 5pp
- 8009240452 Forwards quarterly rept on "Stismic Manitoring Network In Vicinity of Indian Point NY, Consolidated Edison Project. Mar-May 1980 " ZARAKAS.P Consolidated Edison Co of New York 80/09/15 lp
- --8009240455 "Seismic Monitoring Network in Vicinity of indian Point.NY. Consolidated Edison Project.Mar-Hay 1980 " * Noodward-Clyde Consultants. inc 80/08/15 44pp
- S Reportable occurrences. LERs & related correspondence
- 8005i40025 PNS-1-80-003 on 80032i, local telephone company received bomb threat re facility from unidentified male cailer Search was conducted but no bomb was found Threat was repeated on 80032i but no bomb was found was Ragion i. Philadelphia. Office of the Director 80/03/24 ip
- 8009030410 RO on 800804.circulating water sys discharge temp exceeded Tech Specs limit Caused by high ambient river temps, high discharge temps & broken circulating water pump Demand load & discharge temp reduced ZARAKAB,P Consolidated Edison Co of New York 80/08/28 2pp
- DOCKET 50-5 PENNSYLVANIA STATE UNIV RESEARCH REACTOR F Security, medical, emergency & fire protection plans
- 8007030601 Forwards replacement for Table of Contents submitted w/physical security plan on 800731 Table of Contents withheld (ref iOCFR2 790)
 LEVINE.8 H Pennsylvania State Univ 80/08/27 ip
- H General correspondence
- 8007100470 Comments on RM 50~5 public should be advised of advantages & disadvantages of implementing Pu recycle NRG should not have terminated efforts on GESMO fuels DECHER.U Affiliation Unknown 80/09/03 ip

- Q inspection reports. IE Bulletins & correspondence
- 8009240231 Forwards IE Info Notice 80-32. "Clarification of Certain Requirements for Exclusive-Use Bhipments of Radioactive Matis " No written response required GRIER.8 H Region 1. Philadelphia, Office of the Director 80/09/12 ip
- DOCKET 30-10 DRESDEN MUCLEAR POWER STATION, UNIT I F Security, medical, emergency & fire protection plans
- ECOP23028B Requests that all personnel be reminded of surpoxe of emergency notification sys & health physics network Sys installed for govt use during emergency KEPPLER.J O Region 3. Chicago. Office of the Director 60/08/22
- 8009100378 Forwards review of util generating station emergency plan & draft litr requesting additions & commitments from util PAOAND.F 9 Emergency Preparedness Licensing Branch 80/08/28,
- 8009120453 Notifies that Comm Ed does not wish to participate in proposed study re review of people-related problems in nuclear safeguards Responses would be misleading, reflecting inexperience & short-term problems

 ABEL J S Commonwealth Edison Co 80/09/02 jp
- P Operating license stage documents & correspondence
- 7910110018 Notification of 790918 meeting w/util in Dethesda.MD to discuss impact of free standing l(quid requirements for solls wasts
 LD.R Environmental Evaluation Branch (Fre 791030) 79/09/17 200
- 6006300604 Ltr to all BWR licensess forwarding "For Comment" edition of NUREO-0619. "BWR Feedwater Nozzie & Control Rod Drive Return Line Nozzie Cracking " Comments will be evaluated by NRC prior to final implementation N/o enci
- O9110554 Suppls NRC 800707 request for proposed Tech Specs changes re scram discharge vol vent & drain valves, & reactor protection sys & control rad block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT, D. Q Division of Licensing 80/07/22 22pp
- J09020297 Bubmits interim criteria for shift staffing to all GL & CP licensees & applicants.per NRC 800807 ltr Discusses administrative provisions for emergency & overtime work Development & inplementation to be reviewed within 90 days EISENHUT.D Q Division of Licensing. 80/07/31 7pp
- 8009080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed Implementation schedule for meeting criteria of NUREO-0696 encl 4/o NUREO EISENRUT, D O Division of Licensing 80/08/01 119pp
- B009230032 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISEMHUT, D O Division of Licensing 80/08/07, 60pp
- 8009020496 Forwards evaluation of util response to NRC 800223 request for info re primary coolant sys pressure isolation valves. Two specific Event 5 valve configurations do not exist at factities.

 CRUTCHFIELD,D. Operating Reactors Branch 5 80/09/12 3pp
- --8009020463 "Primary Coolant Sys Pressure Scolation Valves," technical evaluation rept NGELL-P R's BTILHELL.7 C Franklin Institute/Franklin Research Center NRC-03-79-118 80/07/21 4pp
- --8009020467 "Primary Coolant Sys Pressure Isolation Valves." technical availation rept NOELL, P N . STILHELL, T C Franklin Institute/Franklin Research Center NRC-03-79-118 80/07/21, 5pp
- -8009020470 *Primary Coolant Sys Pressure Isolation Valves, " technical evaluation rept NCELL.P.N. STILHELL.T C Franklin Institute/Franklin Research Center NRC-03-79-118 80/07/21 4pp

- --8009020473 "Primary Coolant Sys Pressure Isolation Valves," technical evaluation rept NUELL.P N , STILWELL.T C Franklin Institute/Franklin Research Center NRC-03-79-118 80/07/21 4pp
- --8009020474 "Primary Coolant Sys Pressure Isolation Valves," technical evaluation rept NOELL.P N. STILNELL.T C Frankiin Institute/Prenklin Research Center NRC-03-79-118 80/07/21 4pp
- 8009180428 Forwards evaluation of SEP Topic XV-20, "Radiological Consequences of Fuel Damaging Accidents (Inside & Outside Containment) " Buggested mods incorporated into evaluation CRUICHFIELD D Operating Reactors Branch 5 80/09/12 App
- 8009150401 Confirms 800811 discussion re arranging 800821 meeting w/util in Chicago.IL re facility cooling lake dike seepage & remedial action to be taken
 KEPPLER.J G Region 3. Chicago. Office of the Director 80/08/15
- 8009110746 Natification of 800916 meeting w/BEP owners group to discuss NRC initial review & recommondations for site-specific ground response spectra & owners group program plans for seismic functional qualification of Class IE equipment LEVIN, H A Division of Engineering 80/08/26 1p
- E009120404 Forwards Attachments 1-5 to util 600630 ltr re facility electric distribution sys voltage adequacy Ltr inadvertently transmitted w/o attachments

 JANGCEK.R F Commonwealth Edison Co 80/08/28 6pp
- 8009110250 Requires submittal of ATMS emergency operating procedure for NRC review Generic analysis should confirm ATMS mitigation capability described in Vol 3 of NUREO-0460 Commission will determine required mods & implementation schedules
 TEDESCO.R L Assistant Director for Licensing 80/08/29 3pp
- 8007240555 Forwards final critique of 800619 SEP exercise Critique discusses problem areas identified during exercise & presents corrective actions Wo critique DELGEOROE, L. O. Commonwealth Edison Co. 80/08/29 ip
- 8009110376 Comments on NRC 800612 evaluation re 8EP Topic V-S.RCPB Leakage Detaction Info provided re air sampling sys.leak detaction sys & reactor drain tank instrumentation.Plant is in compliance w/Reg Guide 1.45 JANECEK.R F Commonwealth Edison Co 80/09/02 2pp
- E007270143 Notification of B00726 meeting w/utils & Kerr-McGee Chemical Corp in Bethesda.MD to discuss review & recommendations for site specific ground response spectra & program plans for seismic functional qualification of Class IE equipment ALLIEON, D P Systamatic Evaluation Program Branch 80/09/08 3pp
- 5009240022 Notification of second rescheduling until 801003 for meeting w/SEP owners group & KMC. Inc to discuss NRC initial review of sito-specific ground response spectra & util program for seismic fountional qualification of Class IE equipment ALLISON.D P Systematic Evaluation Program Branch 80/09/10 Spp
- 8009290335 Responds to DO Eisenhut 800804 ltr re seismic plan Complete spismic evaluation program will be provided to NRC for seview & approval before restarting unit JANFCEKIR F Commonwealth Edison Co 80/09/11 ip
- 8009220293 Forwards analysis of 30 & 60-day corresion test results retest pracedures for NS-1 solidified waste
 JANECEK.R F. Commonwealth Edizon Co 80/09/12 4pp
- 8007290334 Responds to 800701 ltr to DL Peoples re SEP Topic 8-3 B.dc power sys bus voltage monitoring & annunciation
 Typographical error noted in Section 5. Ref 2 which should be Reg Quide 1 47 not 1 74
 JANECEK,R J Commonwealth Edison Co 80/09/17 1p
- 8009230463 Forwards proposed Tech Sper changes re implementation of TMI Lessons Learned. Category A requirements, in response to NRC 800702 request Dresden Unit 1 Tech Spec changes will be submitted 90 days prior to scheduled startup JANECEK,R F Commonwealth Edison Co 80/09/18 3pp
- --8007230466 Proposed Tech Spec changes re implementation of TMI-2 Lessons Learned Category A items * Commonwealth Edison Co 80/09/10 29pp

- 8009250292 Requests addl 60-90 days for review to determine whether as-built facilities differ from basis in NRC assessment Addl time would allow for reproduction, distribution & review mathods to function properly

 JANCEEK, R F Commonwealth Edison Co 80/09/19 ip
- Q Inspection reports. IE Bullatins & correspondence
- 8009100143 Forwards IE Insp Repts 80-010/80-12.50-237/80-12 & 50-249/80-16 on 800609-0703 No noncompliance noted HEI8HMAN.R F Region 3, Chicago. Reactor Operations Nuclear Support Branch 80/07/23 2pp
- --8009100148 IE insp Repts 50-010/80-12,50-237/80-12 & 50-249/80-16 on 800609-0703 No noncompliance noted Major areas inspected operational safety verification & monthly maint & surveillance observations SPE88ARD,R L , BARKER,J L , TONQUE,T H Region 3, Chicago, Office of the Director 80/07/23 4pp
- 8009020109 Responds to IE Bulletin 79-03A. "Longitudinal Held Defects in ASME SA-312, Type 304 Stainless Steel Pipe " SA-312 pipe not present in operating plants Final confirmation from suppliers anticipated by 800915 re const plant piping sys NAUGHTON, W F Commonwealth Edison Co 80/08/07. 2pp
- 8009030231 Forwards Revision i to iE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER.J O Region 3. Chicago, Office of the Director 80/08. Region 3. Chicago, Office of the Director 80/09/15
- 8009260395 Forwards IE Insp Repts 50-010/80-13.50-237/80-14 & 50-249/80-18 on 800707-0801 & notice of violation HEI8HMAN.R F Region 3. Chicago. Reactor Operations Nuclear Support Branch 80/08/18 2pp
- --8009240399 Notice of violation from insp on 800707-080i
 Region 3, Chicago, Office of the Director 80/08/ 80/08/18 1p
- --B009260404 IE insp Repts 50-010/B0-13.50-237/B0-14 & 50-249/B0-18 on 800707-0801 Noncompliance noted failure of licensed operators to keep themselves cognizant of design changes BARKER, J.L. STREETER, J.F. SPESSARD, Rt. Region 3, Chicago, Office of the Director 80/08/18 lipp
- 8009150495 Forwards iE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE BMR Facilities " No specific action or response requested KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/20
- 8009120060 Forwards Suppl 3 to IE Builetin 80-17, "Failure of Control Rods to Insert During Scram at BWR" Written response required
- KEPPLER, J O Region 3, Chicago, Office of the Director 80/08/22
- 8009180551 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluatione for Changes to Radwaste Treatment Sys " No written response required
 KEPPLER.J O Region 3, Chicago, Office of the Director. 80/08/22
- 8009230094 Forwards IE Info Nutice 80-31. "Maloperation of Qould-Brown Bover1 480 Voit Type K-6008 & K-DON 6008 Circuit Breakers " No written response required KEPPLER.J O. Region 3. Chicago. Office of the Director 80/08/28
- 8009120117 Advises that Suppl 3 to 1E Bulletin 80-17. "Failure of Control Rods to Insert During Scram at GWR." was sent to listed utils on 800822 PAPPAB.H Region 3, Chicago, Office of the Director 80/08/29
- 80091704il Forwards response to IE Bulletin 80-15 re possible loss of emergency notification sys w/loss of offsite power Review revealed inoperability of Dresden sys Investigation being conducted Operating Order 26-80 changed.

 JANACEK.R F Commonwealth Edison Co 80/08/29, 4pp.
- 8009180466 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Identified relays are not used in facility. No action required Twenty-four manhours expended on review RAUSCH.T J Commonwealth Edison Co 80/08/29. 1p

- 8009230478 Forwards Revision 1 to 1E Bulletin 79-26, "Boron Loss From BUR Control Blades" Written response required KEPPLER.J O Region 3. Chicago. Office of the Director 80/08/29
- 80092A0109 Forwards response to 1E Bulletin BO-17. Suppl 3. "Failure of 76 of 183 Control Rods to Fully Insert During Scram at BWR "
 Procedure at Dresden 2 & 3 changed to require immediate manual scram when air pressure reaches 60 psi RAUSCH.T J Commonwealth Edison Co 80/09/02 4pp
- 8009240133 Forwards IE Circular 80-21. "Regulation of Refueling Crews 'No written response required
 KEPPLER, J G Region 3. Chicago. Office of the Director 80/09/10
- 8009300200 Forwards response to IE Bulletin 80-20 No Westinghouse Type W-2 control switches are used in safety-related sys at Dresden Guad Cities & LaSalle County Responses for Zion & Byron are encl RAUSCH.F.J. Commonwealth Edison Co
- R Periodic operating reports & related correspondence
- 8009030456 Forwards semiannual rept of radioactive effluent discharges 5 solid radwaste for Jan-June 1980 800TT.D J Commonwealth Edison Co 80/08/20 1p
- --8007030467 Bemiannual rept of radioactive effluent discharges & solid radwaste, for Jan-June 1980 Communumealth Edison Co 80/08/20 15pp
- 8009230713 Forwards monthly operating repts for Aug 1980 SCOTT.D J Commonwealth Edison Co 80/09/12 1p
- --8009230720 Monthly operating repts for Aug 1980 CIESZKIEWICZ,8 Commonwealth Edison Co 80/09/03 15pp
- V Operator Examinations
- B0093002B7 Forwards preliminary topical outlines of proposed modules on thermal hydraulics & core damage mitigation to be included in revised reactor operator training program per 800328 request NAUGHTON, W F Commonwealth Edison Co 80/09/15 7pp
- DOCKET 50-20 MASSACHUBETTS INST OF TECH RES REACTOR F Security, medical, emergency & fire protection plans
- 8009080198 Forwards rewrite & revision of physical security plan Plan withheld (ref 10CFR2 790) CLARK.L Massachusetts Institute of Technology 80/09/28 1p
- Q Inspection reports, IE Bulletins & correspondence
- 8009240227 Forwards IE info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matts "No written response required GRIER, B H Region i, Philadelphia, Office of the Director, 80/09/12 ip
- R Periodic operating reports & related correspondence
- 8009030565 Forwards "Mit Research Reactor Annual Rept, Jul 1979-June CLARK, L. Massachusetts Institute of Technology 80/08/27 ip
- --8009030569 "MIT Research Reactor Annual Rept.Jul 1979-June 1980 " * Massachusetts Institute of Technology 80/08/26 27pp
- DOCKET 50-22 WESTINGHOUSE TEST REACTOR
- O Inspection reports, IE Bulletins & correspondence
- 8009240252 Forwards IE Info Notice 60-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matis " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/09/12 ip
- 8009250257 Forwards annual insp rept of retired Westinghouse Test Reactor for 1780
 DIPIAZZA.R.P Westinghouse Electric Corp BO/09/19

- DOCKET 50-27 WASHINGTON STATE UNIV RESEARCH REACTOR
 P Operating license stage documents & correspondence
- G009150191 Forwards request for add1 info needed for Structural Engineering Branch to determine appropriateness of allowing operation of facility for next 20 yrs TEDESCO.R L Assistant Director for Licensing 80/09/05 2pp
- 8009300391 Informs that response to 800905 ltr is an progress re design procedure of reactor fuel storage pools Appropriate info being obtained from Campbell Engineers in Spotane, HA WILSDN. U.S. Washington State Univ. 80/09/23 1p
- R Periodic operating reports & related correspondence
- 8009030528 Forwards annual rept of operation for Jul 1979-June 1980 WILSOM N E Washington State Univ 80/08/25 Ip
- --8009030530 "Annual Rept on Operation of Washington State Univ TRIGA Reactor Jul 1979-June 1980 " HAMLEY,S C Washington State Univ 80/08/25 9pp
- DOCKET 50-29 YANKEE-ROHE NUCLEAR POWER STATION

 F Security, medical, emergency & fire protection plans
- G009230200 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency GRIER, B H Region 1, Philadelphia, Office of the Director G0/08/22 Jpp
- O Adjudicatory correspondence
- 8009300551 Forwards order for license mod.requiring supporting info to support environ qualification of safety-related electrical equipment Info should be submitted by 801101 CRUTCHFIELD.D Operating Reactors Branch 5 80/08/29 2pp
- --8009300553 Order for mod of license, requiring supporting info re environ qualification of safety-related electric) equipment EISENHUF.D & Division of Licensing 80/08/29 6pp
- P Operating license stage documents & correspondence
- 8009090030 Discusses void formation in vessel head during 80061f natural circulation cooldown event Requests opinion repotential for voiding phenomenon in util designed NSSS CHECK.P S Assistant Director for Plant Systems 80/07/28 2pp
- 8009020297 Submits interim criteria for shift staffing to all UL & CP licensess & applicants, per NRC 800007 ltr Discusses administrative provisions for amergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D O Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREO-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/o NUREO EISENHUT.D @ Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregated Requested submittal should Include preposed class of amend EISENNUT, D G Division of Licensing 80/08/07 60pp
- 8009050497 Informs that NRC evaluation confirmed that two specific Event 5 valve configurations discussed in NRC 800223 ltm, do not exist at facility NRC activities re valve configurations finalized for facility Technical evaluation rept encl CRUTCHFIELD, D Operating Reactors Branch 5 80/08/12 3pp
- --8007050501 "Primary Coolant Sys Pressure Isolation Valves, Yankee Rows Unit 1," technical evaluation rept NGELL.P N. STILKELL.T C Franklin Institute/Franklin Research Center NRC-03-79-118 80/07/21 4pp
- 8009190794 Forwards revised Westinghouse STS 3 9 8 2.3 9 10 % Bases 3/4 9 8 % 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Whitten response required, NOVAK.T M Assistant Director for Operating Reactors 80/08/15

A

- --8009190817 Revised Westinghouse STS 3 7 8 2,3 9 10 & Bases 3/4 9 8 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods

 **Assistant Director for Operating Reactors 80/06/23 21ng
- 8009120284 Forwards request for info re adequacy of station electric distribution sys voltages Requests response within 75 days of itr receipt GRUTCHFIELD. D Operating Reactors Branch 5 80/08/20 4pp
- 8007020021 Requests deferment of encl listed surveillance testing until rescheduled refueling outage in Spring 1981 Performance of testing during current cold shutdown conditions would significantly increase personnel exposure
 HEIDER, L. H. Yankee Atomic Electric Go. 80/08/26. 2pp
- 8009110746 Notification of 8009t6 meeting w/8EP owners group to discuss NRC initial review & recommendations for site-specific ground response spectra & owners group program plans for seismic functional qualification of Class IE equipment LEVIN, H A Division of Engineering 80/08/26 ip
- 8009030651 Forwards proprietary version of Westinghouse rept
 "Preliminary Metallurgical Analysis of Generator End Number
 One Disc From Yankee Rowe Nuclear Plant " Rept withheld
 (ref 10CFR2 790)
 KAY.J A Yankee Atomic Electric Co 80/08/29 1p
- 8009100542 Forwards info supplementing 800827 ltr re turbino disc failure analysis Discs 1 & 2 on both generators & governor ends have been romoved No detectable cracking exists in remaining discs Info withheld (ref 10CFR2 790) KAYJJA Yankee Atomic Electric Co 80/09/05 7pp
- 8009290149 Notification of 800926 meeting w/utils & Kerr-McGse Chemical Corp in Bethasda.MD to discuss review & recommendations for sits specific ground response spectra & program plans for seismic functional qualification of Class IE aquipment ALLISON.D P Systematic Evaluation Program Branch 80/09/08 3pp
- B009260022 Notification of second rescheduling until 801003 for meeting w/SEP owners group & KMC, Inc to discuss NRC initial raview of site-specific ground response spectra & util program for sejamic functional qualification of Class IE equipment ALLISON, D P Systematic Evaluation Program Branch 80/09/10 3pp
- E009180383 Responds to NRC 800804 request for info re seismic evaluation & plant upgrade program includes info re reactor support mods, steam generator supports, probabilistic risk assessment & seismic analysis KAY, J A Yankee Atomic Electric Co 80/09/12 2pp
- O Inspection reports, IE Bulletins & correspondence
- 8009080526 Responds to IE Hulletin 79-03A Steam welded A312 pips not used in facility Review of piping spec has determined use is permitted; however in all cases pipe wall thickness is based on use of 85% of code allowable
 MOODY, D E Yanker Atomic Electric Co 80/07/22 ip
- 8009080522 Responds to IE Bulletin 80-16 Rosemount Model 1151 & 1152 pressure transmitters would not be exposed to imput pressures that could result in anomalous signals during normal operation, anticipated transients or accidents MODDY, D E Yankee Atomic Electric Co 60/07/29 2pp
- 8007030063 Forwards Revision I to IE Bulletin 80-19, "Fallures of Mercury-Metted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER B H Region 1, Philadelphia, Office of the Director 80/08/15 ip
- 8009180057 Forwards IE Circular 80-18, "10CFR50 59 Bafety Evaluations for Changes to Radwaste Treatment Sys." No written response required ORIGE, B H Region 1, Philadelphia, Office of the Director 80/08/22 ip
- 8009:20214 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DDN 6008 Circuit Breakers " No written response required. ORIER, B H Region 1. Philadelphia, Office of the Director 80/08/27 19
- 8009240050 Forwards IE Circular 80-21. "Regulation of Refueling Craws " No written response required GRIER, D. H Region i, Philadelphia, Office of the Director 80/09/10 ip

23038 Forwards IE info Notice 80-32, "Clarification of Certain of French Programme of Radioactive Using No written response required to 1 # B H Region 1, Philadelphia, Office of the Director 100-712 ip

iodic operating reports & related correspondence

180831 Forwards "Effluent & Waste Disposal Semiannual Rept, Jan-June

9 1 00355 "Effivent & Waste Disposai Semiannual Rept. Jan-June 1980 "Yankee Atomic Electric Co 80/08/29 11pp

120289 Forwards monthly operating rept for Aug 1980

09160303 Monthly operating rept for Aug 1980 BEER6.F C Yankee Atomic Electric Co 80/09/ii 5pp

eportable occurrences, LERs & related correspondence

1 1 329 Forwards LER 80-016/99L-0 TIO+H A Yankee Atomic Electric Co 80/09/09 ip

OP110334 LER 80-016/99L-0 on 800731, during shutdown conditions & while performing fire protection sys mods, cable tray house sprinkler sys taten out of syc for B-h Cause due to sys mods to improve sys 8ys changed, tested & returned to syc to BRAWBRIDDE, B L Yankee Atomic Electric Co. 80/08/29 1p

ET 90-30 PLUM BROOK RESEARCH REACTOR FACILITY

020431 Seeks NRC response to 800317 request for issuance of smantling order & termination of Licenses TR-3 & R-93 and ing for project was included in FYBI budget Lack of NRC smantling orders prevents contracting of work NEDICT, D E National Aeronautics & Space Admin 80/08/25 2pp

ET 50-47 ARMY MATERIALS RESEARCH REACTOR

240277 Forwards IE Info Notice 80-32, "Clarification of Certain Quirements for Exclusive-Use Shipments of Radioactive & 1 s " No written response required IER. B H Region i, Philadelphia, Office of the Director /07/12 ip

ET 50-54 UNION CARDIDE RESEARCH REACTOR

🗖 J wdicatory correspondence

O 4 0250 Petition to participate as interested state NY State Energy is vested w/authority to coordinate regulatory programs fecting atomic energy activities Petition is not request hearing Certificate of 80 energy activities Ferming Certificate of 80 energy activities Petition is not request hearing Certificate of 80 energy activities Petition is not request hearing Certificate of 80 energy activities Petition is not request.

1 7 Oi60 Response stating no objection to NY State Energy Ofc 800827 tition to participate as interested state in proposed OL same wall proceeding Certificate of Buy enci
CHMANN-R O Rulemaking & Enforcement Division 80/09/15 2pp

Pection reports, IE Bulletins & correspondence

1 OO066 Ack receipt of 800727 itr informing NRC of add1 steps & on to correct violations noted in IE insp rept. & one of civil penalty

ELLO, V Office of Inspection & Enforcement, Office of the soctor 80/08/21, 1p

24 0268 Forwards IE Info Notice 80-32, "Clarification of Certain Statements for Exclusive-Use Shipments of Radioactive Lis" No written response required IER.BH Region 1, Philadelphia, Office of the Director 707/12 1p

DOCKET 50-57 STATE UNIV OF NEW YORK RESEARCH REACTOR

F Security, medical: emergency & fire protection plans

8009i6033B Forwards PULSTAR Reactor Requalification Program estimated decommissioning costs financial rept & security plan for protection of SNM of low strategic significance Security plan withheld (ref 100FR2 790)
HENRY

I Financial information

8009160338 Forwards PULSTAR Reactor Requalification Program, estimated decommissioning costs, financial rept % security plan for protection of SNM of low strategic significance Security plan withheld (raf 10CFR2 790)

HERRY,L 0 New York, State Univ of, Suffalo 80/09/11 8pp

--8009160340 "PULSTAR Reactor (R-77) Requalification Program for Licensed Reactor Operators & Licensed Senior Reactor Operators:" Revision 5 ORLOSKY,P M , WiCKHORST,P M New York, State Univ of Buffalo 75/03/12 6pp

P Operating license stage documents & correspondence

8009040376 Informs NRC of current status of application for renewal of License R-77 Nazard summary rept, operator requalification program 2 physical security plan have been completed New Tech Epecs are nearing completion HENRY, L O New York, State Univ of, Duffalo 80/08/29 2pp

G Inspection reports, IE Bulletins & correspondence

B009240238 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required ORIER, B H Region I, Philadelphia, Office of the Director 80/09/12 ip

V Operator Examinations

BO09160339 forwards PULSTAR Reactor Requalification Program estimated decommissioning costs financial rept & security plan for protection of SNM of low strategic significance Security plan withheld (ref 100FR2 790)

MEMRY,L G New York, State Univ of, Buffalo 60/09/11 8pp

--8009160340 "PULSTAR Reactor (R-77) Requalification Program for Licensed Reactor Operators & Licensed Senior Reactor Operators," Revision 5 URLOSKY,P M , WICKHORST,P M New York, State Univ of Buffalo 75/03/12 6pp

DOCKET 50-59 TEXAS ALM UNIV RESEARCH REACTOR

R Periodic operating reports & related correspondence

8009030568 Forwards "Annual Operations Rept of TX A&M Univ AQN-201M Training Reactor, June 1977-Nay 1980" COCHRAN.R 0 Texas A & M Univ 80/08/27. 1p

~-8009030572 "Annual Operations Rept of TX A&K Univ AGN-201 Training Reactor, June 1979 - May 1980 " ZGLICZYKSKI, J Texas A & M Univ 80/08/27 9pp

DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

O Advisory Committee on Reactor Bafeguards reports & correspondence

8009150236 Forwards comments re seismic design considerations for GETR Inadequate info re reactor site precludes comments or suggestions for alternative considerations TRIFUNAC.H D California, Univ of, Los Angeles 80/06/23 2pp

8009150242 Submits comments on 800616-17 meeting on GETR Requests copy of EDAC 117-253-01, Revision i Probabilistic effects of presentation of combining vibratory motion u/uplift ware unclear

* White, M P Consulting Engineer 80/07/11 ip

- P Operating license stage documents & correspondence
- 8009050489 Summary of 800730 meeting u/OE in Bethesda. MD re ongoing structural evaluation of GETR Issuance of SER addressaing GETR sys & structural enalysis & tandslide evaluation expected by nid-Oct
 NELSON.C C Operating Reactors Branch 3 80/08/12 16pp
- 8007030639 Forwards revised table of total CC levels in facility waters during normal operation.including jodine isotope activities eccluded in 800806 ftr Also forwards calculations which include indina isotopes & revised organ doses
 DARMITZEL.R W General Electric Co 20/08/28 4pp
- 8009040255 Forwards "GETR Landstide Stability Analysis "
 DARMITZEL.R W General Electric Co 80/08/29 2pp
- --8007040256 "GETR Landslide Stability Analysis "
 4 Earth Sciences Associates 80/08/31 93pp
- 8009180474 Forwards "GETR Response to Add1 Info Request re Sessmic Scram Sys." concerning Item 2 of RW Danitrel 800814 submittal to D3 Essenbut Affirmation enci DARNITZEL.R W General Electric Co 80/09/16 2pp
- --8007180477 "CETR Response to Add1 Info Request re Seismic Scram Sys " # Engineering Decision Analysis Company. Inc EDAC 117-258 03 80/09/15 25pp
- 8009250245 Forwards response to NRC ltr.received on 800919, requesting add1 info re fuel elements & fueled capsules No fuel or equipment capsule failure occured due to design seismic events

 DARKITZEL.R W General Electric Co 80/09/23 App
- DOCKET 90-77 CATHOLIC UNIV OF AMERICA RESEARCH REACTOR

 O Inspection reports. IE Bulietins & correspondence
- 8009240215 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matis." No written response required GRIER, B M Region 1. Philadelphia, Office of the Director 80/09/12 1p
- DOCKET 50-83 UNIV OF FLORIDA TRAINING REACTOR

 P Operating license stage documents & correspondence
- 8009160399 Responds to 800807 ltr re addl licensing documentation SAR in final stages or assembly & will be submitted by 801031 Discusses SAR status
 BIAZ,N J Florida, Univ of Gainesville 80/07/10 220
- DOCKET 30-87 RESTINGHOUSE CRITICAL EXPERIMENT

 O Inspection reports, IE Bulletins & correspondence
- 8009100085 Forwards IE Insp Rept 50-087/80-05 on 800627 No noncompliance noted DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/07/23 2pp
- --B007100091 IE Ensp Rept 50-087/80-05 on 800627 No noncompliance noted Major areas inspected qualifications, audits & radiation procedures FISHER, W L Region 3. Chicago, Fuel Facility & Materials Safety Branch HEUTER, L J Region 3. Chicago, Office of the Director 80/07/18 6pp
- DOCKET 50-97 CORNELL UNIV ZERO POWER REACTOR
- F Security, medical, emergency & fire protection plans
- 8009230643 Matl in support of application to renew & amend License R-80 "Financial Rept.1978-1979." "Final Bafaguards Rept. Bupp 1." proposed Amend 8 to Tech Spec & license & proposed sarrgency plan enci CODAE, W D Cornell Univ 80/09/15 19pp

- P Operating license stage documents & correspondence
- B009230643 Matl in support of application to renew & amend License R-BO "Financial Rept. 1978-1979;" "Final Safeguards Rept. Supp I." proposed Amend 8 to Tech Spec & license & proposed emergency plan encl COUME, M D Cornell Univ 80/09/15 19pp
- --8009230668 Proposed emergency plan for Licenses R-80 & R-89 * Cornell Univ 80/09/01 16pp
- Q Inspection reports, 1E Bulletina & correspondence
- 8009240221 Forwards 1E info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Hatls " No written responso required GRIER.8 H Region i, Philadelphia. Office of the Director 80/09/12 ip
- DOCKET 50-99 BASCOCK & WILCOX TEST REACTOR

 P Operating license stage documents & correspondence
- 8007030443 Forwards Tech Specs incorporating changes proposed by 790501-02 lers & submitted in connection #/780303 request for renewal of License R-47 OLSEN.A F Babcock & Wilcox Co 80/08/29 ip
- --8009030446 Tech Specs incorporating changes proposed by 790501-02 1\$19 b submitted in connection w/780303 request for renewal of License R-47 * Babcock & Wilcox Co 79/05/31 44pp
- DOCKET 50-112 UNIV OF OKLAHOMA RESEARCH REACTOR
- R Periodic operating reports & related correspondence
- BO09100577 Annual operating rept for Jul 1979-June 1980 JAMES. J Oklahoma. Univ of BO/09/02 2pp
- 8009260432 Submits annual rept for Jul 1979-June 1980 JAMES.J Oklahoma. Univ of 80/09/02 2pp.
- DOCKET 50-123 UNIV OF MISSOURI RESEARCH REACTOR
 P Operating license stage documents & correspondence
- 8009090399 Forwards revised Tech Bpecs completing submittal for Univ of MO.Rolla reactor relicensing ELLIOTT.A E Missouri, Univ of, Rolla 80/09/03 ip
- --8009090403 Revised Tech Specs for Univ of MO.Rolla Reactor * Missouri, Univ of Rolla 80/09/03 25pp
- DOCKET 50-124 VIRGINIA POLYTECH INST TRAINING REACTOR

 P Operating license stage documents & correspondence
- 8009300457 Application for amend of License R-62, changing Tech Spece to permit tests of one i3-plate element w/o exceeding k limit Safety analysis encl
 PARKINSON. TF Virginia Tech 80/09/17 4pp
- DOCKET 90-126 TEXAS ALM UNIV RESEARCH REACTOR
- R Periodic operating reports & related correspondence
- 8009030350 Forwards revised App 111 to "Sixteenth Progress Rept of TX ASM Univ Nuclear Science Ctr." 1979 consisting of summaries of health physics support effluent releass environ survey program radiation & contamination control program FELTZ.D E Texas A & M Univ 80/08/28 ip
- --8009030393 Revised App III to "Bixteenth Progress Rept of TX A&M Univ Nuclear Science Ctr." 1979 consisting of summaries of health physics support, offuent releases, environ survey program, radiation & contamination control program * Texas A & M Univ BO/08/28 29pp

DOCKET 50-131 OMAMA VET ADMIN HOSP RESEARCH REACTOR
F Security, medical, emergency & fire protection plans

8009160434 Requests revisions b add1 info re physical security plan for protection of SNM of low strategic significance Description of insp procedures & revised plan pages required by 800930 MILLER, J R Standardization & Special Projects Branch 80/08/26

8009260280 Forwards Revision 2 to physical security plan Revision withheld (ref 10CFR2 790) TURCOTTE, R L Vet Admin Hosp Omaha, NE 80/09/15 lp

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3

F Security, medical, emergency & fire protection plans

8009030337 Notifies of 800819.22 & 30 regional workshops re development of guidance for acceptable method for coping w/emergencies at facility Requests that representative be sent Subj areas to be discussed include function of facilities & location EMGELKEN,R H Region 5, San Francisco, Office of the Director 80/08/12 2pp

P Operating license stage documents & correspondence

B009110554 Suppis NRC B00707 request for proposed Tech Specs changes re scram discharge vol vent & drain valves, & reactor protection sys & control rod block limit switch surveillance requirements Class III licenses fee to be submitted w/change EIBENHUT.D Q Division of Licensing 80/07/22 22pp

8009020297 Submits interim criteria for shift staffing to all QL & CP licensess & applicants.per NRC 800507 itr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D Q Division of Licensing 80/07/31 7pp

8007080080 Forwards draft NUREC-0896, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days, Proposed implementation schedule for meeting criteria of NUREG-0676 encl W/o NUREQ EISENHUT, D O Division of Licensing 80/08/01 ii9pp

8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EiSENHUT, D O Division of Licensing 80/08/07 60pp

8009190637 Forwards IB Alterman trip rept re field & trench observations in vicinity of plant JACKEDN,R E Geosciences Branch 80/09/12 ip

--8009190639 Forwards trip rept re field & trench observations in vicinity of plant New Fault was found 700 ft from plant ALTERMAN, I B Geosciences Branch 80/09/10 20pp

G Inspection reports. IE Bulletins & correspondence

8009080082 Forwards response to lE Bulletin 80-14, "Degradation of BHR Scram Discharge Vol Capability " Record review showed no instances of bent float assemblies or water hammer damage Required surveillance procedures performed regularly CRANE,P A Pacific Gas & Electric Co 80/07/28 3pp

8009240299 Forwards IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange," No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director BO/08/07 lp

8007030288 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Marcury-Wetted Matrix Relays in Reactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E " Written response required ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/08/15 1p

8007270309 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolent Pump Studs " No written response required ENCELKEN,R H Region 5, San Francisco, Office of the Director 80/08/18. 4pp 8009120029 Forwards Suppl 3 to IE Bulletin 80-17. "Failure of Control Rods to Insert During Scram at BMR" No written response required ENDELKEN, R H Region 5. San Francisco. Office of the Director 80/08/22 1p

8009160181 Forwards IE Circular 80-18, "10CFR50 59 Bafety Evaluations for Changes to Radwaste Treatment Sys " No written response required ENGELKEN, R H Region 5, San Francisco. Office of the Director

8009120458 Forwards 1E Info Notice 80-31. "Maloperation of Gould-Brown Bover: 480 Volt Type K-600S & K-DON 6008 Circuit Breakers "
No written response required ENGELKEIAR H Region 5, San Francisco. Defice of the Director 80/08/27 1p

8009180130 Forwards Revision i to IE Bulletin 79-26, "Boron Loss From BMR Control Blades " Hritten response required ENGELKEN, R H Region 5. San Francisco. Office of the Director 80/08/27 lp

R Periodic operating reports & related correspondence

8009080333 Forwards "Radioactive Effluent Release & Waste Disposal Semiannual Rept. Jan-June 1980" & Environ Radiation Study Repts 75 & 76 CRANE, P A Pacific Oas & Electric Co 80/09/04 1p

--8009080334 "Radioactive Effluent Release & Waste Disposal Semiannual Rept. Jan-June 1980 " * Pacific Gas & Electric Co 80/09/04 15pp

--8009080335 Rept 75, "Environ Radiation Study in Vicinity of Humboldt Bay Power Plant: Eureka: CA: Quarter Ending 791231." CAYOT.R F. BROWNRIOG.D L. LORENZ.R W Pacific Oas & Electric Co 80/05/09 19pp

--8009080336 Rept 74. "Environ Radiation Study in Vicinity of Humboldt Bay Power Plant, Eureka, CA. Quarter Ending 800331 " CAYOT, R F . BROWNRIOO, D L . LURENZ, R W Pacific Gas & Electric Co 80/07/10 199p

8009120447 Forwards monthly operating rept for Aug 1980 WEEKS, E D Pacific Gas & Electric Co 80/09/08 2pp

--800912045i Monthly operating rept for Aug 1980
BAUN, P W Pacific Gas & Electric Co 80/09/04 3pp

8007230551 Forwards supplemental info for effluent & waste disposal semiannual rept for 1978, in response to NRC 800825 ltr Supplemental info available in Central Files only CRANE, P. A. Pacific Gas & Electric Co. 807/09/15 lp

S Reportable occurrences, LERs & related correspondence

8009120349 Forwards LER 80-004/03L-0 CRANE, P A Pacific Oas & Electric Co 80/09/08 ip

---8009120419 LER 80-004/03L-O on 800807, screen wash pump motor in adjacent fossil unit overheated 2 breaker would not trip Caused by breaker wear & inattention to preventive maint Screen wash pump breakers to be replaced GETTY. 8 Q Pacific Gas & Electric Co 80/09/06 ip

V Operator Examinations

8007050321 Forwards "Licensed Operator & Senior Operator Training Programs," Administrative Procedure 8-155, in response to NRC 800328 Itr Emergency operating procedures also revised to incorporate pertinent recommendations CRANE, P A Pacific Oas & Electric Co 80/08/20 ip

--8009050324 "Licensed Operator & Senior Operator Training Programs."
Administrative Procedure B-135
Pacific Gas & Electric Co 80/08/20 9pp

DOCKET 50-134 NORCESTER POLYTECH 1NST RESEARCH REACTOR

F Security, medical, smergency & fire protection plans

8009020019 Forwards physical security plan Plan withheld (ref 10CFR2 790) MILBUR.L C Morcester Polytechnic Inst 80/04/12 1p

- Q Inspection reports, IE Bulletins & correspondence
- 8009240250 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls" No written response required ORIER.B H Region is Philadelphia, Office of the Director 80/09/12 ip

DOCKET 50-139 UNIV OF HASHINGTON RESEARCH REACTOR
F Security, medical, emergency & fire protection plans

8009040240 Submits security plan Pian withheld (ref 100FR2 790) VALENTE, F A Seattle Univ 80/08/27 3pp

COCKET 50-142 UCLA TRAINING REACTOR

O Adjudicatory correspondence

BOD7040203 Supplemental contentions to 800322 petition to intervene Alleget omission of essential info by applicant resevere reactor damage L lack of spare parts Supporting documentation & Certificate of Syc encil HSRSCN.D Committee to Bridge the Oap 80/08/25 140pp

B009170192 Provides background info re Director's decision under iOCFR2 206 denying Committee to Bridge the Oap patition to shutdown research reactor NRC did not exempt univ from code requirements 870 encl decision TEDESCO.R L Assistant Director for Licensing. 80/09/29 3pp

B009040292 Forwards documents he early licensing & operation to be used in present application for OL renewal Licensee physical security plan withheld (ref 10CFR2 790) Same documents sent to all parties except applicant W/o encis GRAY.J R Hearing Branch i 80/09/02 ip

8009230016 Response in opposition to Committee to Bridge The Oap supplemental Petition to intervens Discusses irrelevancy & late of merits of contentions & expresses desire to explain & etaborate conterns at prehearing conference HDODB.Q R , HELMICK.C . REIDHAAR.D L California, Univ of, Berkeley 80/09/09 20pp

~~8009230018 "UCLA Reactor is Safe" Exhibit B Fifteen of 22 pages * California, Univ of, Berkeley 80/01/03 18pp

--B009230021 Certifies tyc of response to Committee to Bridge The Cap supplemental petition to intervene.on 800907 CDSTALUPEGYY California, Univ of, Berkeley 80/09/07 2pp

8009240466 Forwards list of primary areas of contention & corrected typographical errors contained in "Committee to Bridge Gap Supplemental Contentions to Petition for Leave to Intervene" Requests that J Bay be maintained on svc list HIRSCH.D Committee to Bridge the Gap 80/09/15 Spp

8009180469 Statement in support of Committee to Bridge The Cap admission as intervenor due to submittal of one good contention Individual positions re Contentions i - 23 listed Certificate of Svc enci LAVERTY. J H Hearing Branch 1 80/09/16 37pp

8009230747 Forwards NRC response to Committee to Bridge The Cap contentions re application for Dicense renewal W/o enci LAVERTY. J. H. Hearing Branch 1 80/09/18 1p

P Operating license stage documents & correspondence

8009160321 Forwards info re facility location, restricted areas, emission monitoring, sampling sys & seismic test, in response to NRC 800731 ltr "Atmospheric Dispersion of Ar-41 from UCLA Nuclear Reactor" encl HEOST, W F California, Univ of, Los Angeles 80/09/05 30pp

--8009160322 "Atmospheric Dispersion of Ar-41 from UCLA Nuclear Reactor "
RUBIN.M F California, Univ of, Los Angeles 76/12/31 64pp

DOCKET 50-147 ROCKWELL INTL CORP CRITICAL FACILITY

G Inspection reports, IE Bulletins & correspondence

8009240407 Forwards IE Insp Rept 50-147/80-01 on 800603-04 & 11 No noncompliance noted 800K.H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 80/07/11 2pp

--8009240533 IE Insp Rept 50-147/80-01 on 800603-04 & 11 No noncompliant noted Major areas inspected meter & smear surveys of facility, review of records of radiation surveys instruments & techniques
CURTIS.J R , WENBLAWSKI.F Region 9, San Francisco, Office of the Director BOOK, H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 80/07/11 6pp

DOCKET 50-152 FLORIDA WEST COAST NUCLEAR GROUP INC

G Inspection reports, IE Buildtins & correspondence

8009230387 Forwards IE Circular 80-20, "Changes in Safe-Siab Tank Dimensions " No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/08/21

DOCKET 50-155 BIO ROCK POINT NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

8009230295 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for got use during emergency KEPPLER. J G Region 3. Chicago. Office of the Director 80/09/22 3nn

G Adjudicatory correspondence

8009040262 Forwards documents re aircraft crash risks & military low level training routes in response to 800724 ltr NRC applied acceptance criteria of std review plan re case of 852 bomber crash into facility MOCRE, J E Hearing Branch 2 80/08/29 2pp

--8009040269 Bubmits updated analysis of risks associated w/accident involving aircraft on low level training route Probability of crash in three nautical mile square enclosing plant is less than one in one hundred million per yr NICHOLS, D.L. Air Force, Dept of 80/01/19 7pp

---8009040274 Advises that Air Force training route is being adjusted so that centerline of route will pass 12 miles west of plant at closest point DDD filight info re military training routes encl KANFOR.F Accident Analysis Branch 80/02/11 App

6009110802 Motion for withdrawal of appearance as counsel due to financial burden intervenor intends to remain as party w/o counsel despite unfair imbalance of power JORDAN.W S , SHELDON.K P , WEISS, E R Christa-Haria 60/09/05

8009ii0365 Forwards motion for withdrawal of appearance as counsel in spent fuel pool expansion proceeding Clients cannot afford lawyer NRC should realize impact of imbalance of resources on ability of public to trust NRC decision in case W/o encl JGRDAN.W 8 Sheldon: Harmon & Weiss. 80/09/08 1p

8009150339 Forwards util response to Interrogatory 3-5, including Tech Specs, procedures & requested documents Requests that Page 41 of response to Interrogatory 3-6, submitted 800822, be corrected to documents indicated Related correspondence OALLO, J Isham, Lincoln & Beale 80/09/10 2pp

--B009150344 Util response to Interragatory 3-5 propounded by Christa-Maria, et al Certificate of Svc.affidavits, Tech Specs, procedures & related correspondence encl GALLO, J Consumers Power Co QALLO, J, Isham, Lincoln & Beale B0/09/09 550pp

800916043B Forwards AGLB 800912 memorandum & order & AGLAB 800912 order Requests brief amicus be filled on 801020 or 1124 depending on council position Motion for deadline extensions may be filled if necessary W/o encis
BISHOP, C J Atomic Bafety and Licensing Appeal Panel 80/09/12

- 8009160525 Notice of assignment of ASLAB in spent fuel pool expansion proceeding AS Rosenthal Chairman JH Buck & TS Moore, members BISHOP, C J Atomic Bafety and Licensing Appeal Panel 80/09/12
- BO09170175 Memorandum & order directing NRC to prepare E18 per NEPA re add1 operation arising from spent fuel pool expansion Intervenor O'Neili Contention B admitted but will not be subjit of discovery prior to BES Refers rulings to ASLAB GROSSMAN.H., PARIS, O.H., EHON, F.J. Atomic Safety and Licensing Board Panel BO/09/12 19pp
- 8009220185 Forwards notices of appearance by J Gallo,PP Steptoe & P Thornton on behalf of GPC Certificate of Svc encl OALLO,J Isham, Lincoln & Beale 80/09/17 1p
- --B009220216 Notice of appearance on behalf of CPC GALLD, J Consumers Power Co 80/09/17 1p
- ---8009220217 Notice of appearance on behalf of CPC 8TEPTOE.P.P. Consumers Power Co. 80/09/17
- ---8009320218 Notice of appearance on behalf of CPC THORNTON,P Consumers Power Co 80/09/17 3pp
- 8009230030 Order substituting Page 15 of ABLB 800912 memorandum & order on NEPA raylew re spent fuel pool expansion GROSSMAN, H Atomic Safety and Licensing Board Panei 80/09/iB 1p
- ---8009230033 Substitute Page 15 of ASLB 800912 memorandum & order on NEPA review re-spent fuel pool expansion # Atomic Safety and Licensing Board Panel 80/09/12 1p
- 8009260650 Informs of temporary withdrawal from proceedings re facility installation of storage racks for spent fuel Withdrawal caused by harassment & consequent mental stress * Christa-Maria 80/09/23 200
- 8009300033 Forwards memorandum of 800923 conference call between ASLS & parties except J O'Neill respent fuel pool expansion proceeding GROSBMAN. H Atomic Safety and Licensing Board Panel 80/09/24 ip
- --8009300036 Memorandum of 800923 conference call between parties except
 J O'Neill re spent fuel pool expansion proceeding Addresses
 Christa-Maria temporary withdrawal-assistance to intervenors
 & further scheduling re safety issues
 GROSSMAN,H Atomic Safety and Licensing Board Panel 80/09/24
- J Insurance & indemnity information
- 8007230443 Forwards Endorsement 82 to NELIA Policy NF-117 IRELAND. J H Consumers Power Co 80/09/16 4pp
- P Operating license stage documents & correspondence
- 8009110554 Supple NRC BOD707 request for proposed Tech Specs changes re scram discharge vol vent & drain valves. & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT.D O Division of Licensing 80/07/22 22pp
- 8009020297 Bubmits interim criteria for shift staffing to all DL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for amergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D 0 Division of Licensing 80/07/31 7pp
- 8007080080 Forwards draft NUREQ-0696, "Functional Criteria for Emergency Response Facilities," Communts requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl W/o NUREO EISENHUT.D O Division of Licensing 80/08/08 119pp
- 8009020340 Bummary of 800728 meeting w/util in Charlevoix County.MI re licensee proposed risk assessment of facility Mod to surveillance testing of diesel generator proposed by NRC was also discussed PAVLSON.U A Operating Reactors Branch 5 80/08/06 4pp
- --8007020343 "Procedure to Determine Extent of Core Damage (For 0% to 100% Core Meltdown) Consumers Power Co 80/06/10 App

- 8007230052 Informs that exemption from fee re licensing action associated w/THI-2 Lessons Learned is unjustified Previ determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D C Division of Licensing 80/08/07 60pp
- 8007050500 Forwards Amend 33 to License DPR-6.safety evaluation & notice of issuence & availability
 PAULSON.N A Operating Reactors Branch 5 80/08/11 2pp
- --8009050504 Amend 33 to License DPR-6, changing surveillance requirements for verifying operability of power operated valves in containment spray sys PAULSON.W A Operating Reactors Branch 5 80/09/11 5pp
- --8009050509 Notice of issuance & availability of Amend 33 to License DPR-6
 PAULSOILU A Operating Reactors Branch 5 80/08/11 2pp
- B009040088 Confirms that two specific Event 5 valve configurations do not exist at facility Review efforts on other configurations continuing CRUICHFIELD.D Operating Reactors Branch 5 80/08/12 3pp
- --8009040103 "Primary Coolant Sys Pressure Isolation Valves, Big Rock Point: "technical evaluation rept NDELLP N, STILMELLT C Franklin Institute/Franklin Research Centor NRC-03-79-118 80/07/21 4pp
- 8009110744 Notification of 800914 meeting w/SEP owners group to discuss NRC initial review b recommendations for site-specific ground response spectra b owners group program plans f seismic functional qualification of Class IE equipment LEVIN.H A Division of Engineering 80/08/26 ip
- 8009150042 Notification of 800908-lt meetings at plant sites w/utils to discuss environ qualification of electrical equipment PAULBON.W A Operating Reactors Branch 5 80/08/27 2pp
- B009100374 Forwards corrected tables to util 791203 response to HRC request for addl info on proposed Tech Spec changes to radiological effluents
 HGFFMAN.D P Consumers Power Co 80/08/28 3pp
- B009030490 Responds to NRC 800808 ltr on generic concerns re adequaty of station electric distribution sys voltages Dffsite power sys & onsite distribution sys are sufficiently capable to automatically start & operate all required safety loads HOFFMAN.D P Consumers Power Co 80/08/29 11pp
- 8007040423 Natifies of procedural problem in complying w/NRC 800023 memorandum & order re electrical equipment qualification Emergency radiation assessment sys cannot invoke IEEE 323-1774 Best components consistent w/order will be used HOFFMAN. D P Consumers Power Co 80/09/02 3pp
- B007100973 Discusses proposed increase in emergency diesel generator start time acceptance criteria per 800225 Tech Bpoc change request Approval will provide increase in power autput & allow time use for reporting \$ failure rate determination HOFFMAN,D P Consumers Power Co 80/09/02 2pp
- 8009100521 Forwards design descriptions of containment pressure & water level instrumentation mods.in response to NRC 790913 ltr specifying requirements for plant mods resulting from TMI Lessons Learned Identification of NRC concerns requested HOFFMAN.D P Consumers Power Co 80/09/05 41pp
- 8009290143 Notification of 800926 meeting w/utils & Kerr-McGee Chemical Corp in Bethesda.MD to discuss review % recommendations for site specific ground response spectra & program plans for seismic functional qualification of Class IE equipment ALLISON.D P Systematic Evaluation Program Branch 80/09/08 3pp
- BOO9240022 Notification of second rescheduling until B01003 for meeting w/BEP owners group & KMC, Inc to discuss NRC initial review of site-specific ground response spectra & util program for setswic functional qualification of Class IE equipment ALLISON.D P Systematic Evaluation Program Branch B0/09/10 Tpp
- BOO7250278 Forwards corrected Tech Spec Page 7.Section 3 9 1(d) & Page 143.Section ii 4 3 45 to replace errors identified during review grior to implementation of Amend 33 to License DPR-6 HOFFMAN,D P Consumers Power Co

- --8009250279 Corrected Tech Spec Page 7. Section 3 5 1(d) & Page 143-Section 11 4 3 4E Consumers Power Co 80/09/12 2pp
- 8009300231 Forwards "Sys Design & Functional Description of Gig Rock Point Plant Steam Drum/Reactor Vessel Level Instrument Mod." FD-CPM-002.Revision 1 Addi layel instrumentation deferred pending completion of overall risk assessment HOFFMAN.D P Consumers Power Co 80/09/18 2pp
- ~~8009300235 "Sys Design & Functional Description of Big Rock Point Plant Steam Drum/Reactor Vessel Level Instrument Mod." Revision i → Energy Incorporated FD-CPW-092 Rt 80/09/09 12pp
- @ Inspection reports: IE Builetins & correspondence
- 8009040540 Forwards IE Bulletin 80-07. Suppl 1. "BWR Jet Pump Assembly Fallure " Response required KEPPLER, J G Region 3. Chicago: Dffice of the Director 80/05/14
- 8009120506 Forwards IE Insp Rept 50-155/80-08 on 800611-26 No noncompiiance noted DAVIS.A B Region 3. Chicago. Fuel Facility & Materials Safety Branch BO/OB/Ol Zpp
- --8007120509 IE Insp Rept 50-155/80-08 on 800411-24 No noncompliance noted Major areas inspected results of previous sample collection ESSIG.T H , JANUSKA.A Q Region 3. Chicago. Office of the Director 80/09/01 4pp
- 8009030229 Forwards Revision 1 to IE Bulietin 80-19. "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Fower Plants Designed by C-E " Written required KEPPLER, J O Region 3. Chicago, Office of the Director 80/08/15
- 8009i50494 Forwards JE Info Notice 80-30. "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain 6E BMR Facilities " No specific action or response requested KEPPLER.J G Region 3. Chicago. Office of the Director 80/08/20
- 8009120035 Forwards Suppl 3 to IE Bulletin 80-17. "Failure of Control Rods to Insert During Scram at EWR" Written response required KEPPLER. J G Region 3. Chicago. Office of the Director 80/08/22
- 8009170415 Forwards IE Circular 80-18, "ICCFRSO 59 Bafety Evaluations for Changes to Radwaste Treatment Sys " No written response KEPPLER, J O Region 3, Chicago, Office of the Director 80/08/22
- 8009110817 Ack receipt of 800718 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-155/80-04
 KEPPLER, J Q Region 3, Chicago, Office of the Director 80/08/26
- --8009110920 Forwards response to NRC 800613 ltr re violations noted in IE Insp Rept 50-195/80-04 Corrective actions high radiation areas securely locked technical personnel training improved & noble gas monitoring increased HOFFMAN. D P Consumers Power Co 80/07/18 Gpp
- 6009180102 Responds to IE Bulietsn BO-19 re failures of mercury-wetted matrix relays in reactor protective sys Identified relays are not used in facility Receipt of bulietin Revision 1 does not change response HOFFMAN, D P Consumers Power Co 80/08/28 ip
- 8009230093 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover(480 Volt Type K-6005 & K-DON 6005 Circuit Breakers " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/28
- 8009230489 Forwards Revision 1 to IE Bulletin 79-26. "Boron Loss From NEEPPLER. J G Region 3. Chicago. Office of the Director 80/08/29

- 8009260125 Forwards response to IE Builetin 80~17. Suppl 3. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR "Facility scram discharge sys meets requirements w/o add1 mods or surveillance HOFFMAN, D P Consumers Power Co 80/09/02 3pp
- 8009260146 Forwards response to IE Bulletin 80-15. "Possible Loss of Emergency Notification Sys (ENS) w/Loss of Offsite Power"
 Util expediting correction of health physics line power source w/MI Bell Telephone Co
 HOFFMAN.D P Consumers Power Co 80/09/02 4pp
- 8009240096 Forwards IE Circular 80-21. "Regulation of Refueling Craws " No written response required
 KEPPLER, J O Region 3, Chicago, Office of the Director 80/07/10
- R Periodic operating reports & related correspondence
- 8009030544 Forwards "Semiannual Radioective Effluent Release Rept," Jan-June 1980 HOFFMAN, D P Consumers Power Co 80/08/27 1p
- --8009030547 "Semiannual Radioactive Effluent Release Rept," Jan-June * Consumers Power Co 80/08/27 12pp
- 8 Reportable occurrences, LERs & related correspondence
- 8009020070 Ferwards LER 80-021/03L-0
- 8009020077 LER 80-021/03L-0 on 800729 following intermittent automatic ATABOUTY LER BUMDZI/USL-U on BOD/27.following intermitest circuit alarms.sensor channel D of reactor depressurizing sys was removed from svc to vent level transmitter LT31B3 Caused by minor calibr shift a Consumers Power Co 80/08/25 ip
- 8007020266 Forwards LER 80-023/01T-0 HOFFMAN, D P Consumers Power Co 80/08/26 1p
- -8009020271 LER-80-023/01T-0 on 800A12 review of reactor containment design for steam line breaks in primary sys indicated that containment atmosphere temp can acceed temp criteria previously used Operating instructions revised & Consumers Power Co. 80/08/26 20pp
- 8007090458 Forwards LER 8D-022/031-0, HOFFMAN, D. P. Consumers Power Co. B0/09/05
- --8009070474 LER 80-022/03L-0 on 800607, during monthly specific gravity checks, cells 38.39 \$ 56 of reactor depressurizing battery for channel C had low readings Cause not known Ceil units 13 \$ 19 replaced Channel C restored on 800813 \$ Consumers Power Co 80/09/05 ip
- 8009170098 Forwards LERs 80-024/03L-0,80-025/03L-0,80-026/03L-0 & 80-027/03L-0 HUFFMAN, D.P. Consumers Power Co. 80/09/12 19
- -8009190101 LER 80-024/03L-0 on 800814.after periodic automatic test circuit alarms, reactor depressurizing sys sensor channel D was removed from svc to vent reactor water level transmitter LT3183 Caused by minor calibr shift in transmitter 4 Consumers Power Co 80/09/12 ip
- --8009190105 LER 80-025/03L-0 on 800819, after periodic automatic test circuit alarms, reactor depressurizing sys sensor channel D was removed from syc to vent reactor water level transmitter LT3183 Caused by minor calibr shift in transmitter * Consumers Power Co 80/09/12 1p
- --8007190124 IER 80-026/03L-0 on 800820, after periodic automatic test circuit nlarms, reactor depressurizing sys sensor channel D was removed from syc to vent reactor water level transmitter LT3183 Gaused by minor callbr shift in transmitter 4 Gansumers Power Co 60/09/12 Ip
- --G009190129 LER 80-027/03L-0 on 800814, after periodicautomatic test circuit alarms, reactor depressurizing sys sensor channel D was removed from svc to vent reactor water level transmitter LT3183 Caused by minor calibr shift in transmitter * Consumers Power Co 80/09/12 ip

DOCKET 50-156 UNIV OF WISCONSIN RESEARCH REACTOR

🖴 Reportabio occurrences. LERs & related correspondence

© CO9040397 Advises of noncompliance w/10CFR95 3 from 800627-0818 Util submitted renewal application for License SDP-3278 on 800424.but license expired before NRC final action Appropriate personnel notified that license was invalid CASHWELL.R J Hisconsin. Univ of Madison 80/08/26 1p

DICKET 50-157 CORNELL UNIV RESEARCH REACTOR

F. Security, medical, emergency & fire protection pians

EDO09230643 Matt in support of application to renew & amend License R-80 "Financial Rept. 1978-1979." "Final Safeguards Rept. Supp 1." proposed Amend & to Tech Spec & license & proposed emergency plan enc!
COCKE, D Corneli Univ 80/09/15 19pp

I Financial information

○OO9230643 Matl in support of application to renew & amend License R-BO "Financial Rept. 1978-1979." "Final Safeguards Rept. Bupp 1." proposed Amend 8 to Tech Spec & license & proposed emergency plan encl COUKE, W D Corneli Univ BO/09/15 19pp

W Utility Final Bafety Analysis Report (FSAR) & amends

E3OO9230643 Matl in support of application to renew & amend License R-80 "Financial Rept.1978-1979." "Final Safeguards Rept. Supp 1." proposed Amend 8 to Tech Spec & license & proposed emergency plan enci COCKE,W D Corneil Univ 80/09/15 19pp

P Operating license stage documents & correspondence

SO09230643 Mati in support of application to renew & amend License R-BO "Financial Rept.1978-1979," "Final Bafeguards Rept. Supp 1." proposed Amend B to Tech Opec & license & proposed emergency plan enci COUXE, W D Cornell Univ BO/09/15 19pp

Q Inspection reports: IE Bulletins & correspondence

BO09240221 Forwards IE Info Notice 80-32. "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required ORIER,B H Region 1. Philadelphia, Office of the Director 80/09/12 ip

COCKET 50-166 UNIV OF MARYLAND RESEARCH REACTOR

P. Operating license stage documents & correspondence

BO09080474 Forwards FR notice of proposed renewal of license, in response 800523 application Existing license will not be deemed expired until present application determined MILLER, J R Standardization & Special Projects Branch 80/08/ii 2pp

---8009080478 Notice of proposed renewal of license extending expiration date until 200629 Request for hearing & petitions to intervene may be filed subj to regulations

MILLERUUR Standardization & Special Projects Branch 40/08/11
400

Q Inspection reports, i& Bulletins & correspondence

8009240247 Forwards 1E info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matis " No written response required GRIER.B H Region 1. Philadelphia. Office of the Director BO

V Operator Examinations

8009110317 Advises that licensee June 1980 requalification program is Unacceptable w/o encl documentation re presently approved program COLLINS.P F Operator Licensing Branch 80/09/02 1p

DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER

F Security, medical, emergency > fire protection plans

800929016B Forwards emergency plan
TYLER/P E Defense, Dept of, Defense intelligence Agency E0/09/26
10

--8009290171 Emergency pian for TRIGA reactur ANDERSON,F Dames & Moore 60/09/03 37pp

P Operating license stage documents & correspondence

8007030450 Forwards proposed Amend i7 to Tech Specs, specifying safety limits & limiting conditions, surveillance requirements, destyn features & administrative requirements Replaces previous document in doctot file TYLER, P E Defenso Dept of, Defense Nuclear Agency 80/09/01 ip

--8009030452 Proposed Amend 17 to Tech Specs, specifying safety limits & itmiting conditions, surveillance requirements, design features & administrative requirements

4 Defense, Dept of, Defense Nuclear Agency 80/08/27 60pp

8009290359 Forwards EIA data for renewal of License R-84 TYLER.P E Defense.Dept of, Defense Nuclear Agency 80/09/26

Q Inspection reports, 1E Bulietins & correspondence

8009240275 Forwards IE Info Notice 80-32, "Clarification of Cartain Requirements for Exclusive-Use Shipments of Radioactive Matls "No written response required GRIER, B H Region i, Philadelphia, Office of the Director 80/09/12 ip

V Operator Examinations

8009190i95 Forwards proposed "Reactor Operator Requalification Program" for review per NUREO-0094

TYLER.P E Defense.Dept of, Defense Nuclear Agency 80/09/17 ip

--8009170179 Proposed "Reactor Operator Requalification Program" + Defense,Dept of, Defense Nuclear Agency 80/09/17 22pp

DOCKET 50-171 PEACH BOTTOM ATOMIC POWER STATION, UNIT 1

E NRC Safety Evaluation Report (SER), suppls & correspondence

8009020053 Forwards draft comments on SER Items 3 2 3(1)-(4),3 2 9, 3 2 13-15 & 3,2 4 from fire protection review Finai Item 3 1 8(2) will be sent shortly HALL,R E Brookhaven National Laboratory 80/08/21 5pp

F Security, medical, emergency & fire protection plans

B009250274 Requests permission to record conversations on dedicated telephone connection installed between facilities & NRC Bethesda ND headquarters COUNEY.H J Philadelphia Electric Co 80/04/18 ip

- 8009070364 Forwards amended fire protection review, Item 3 (i re Area & cable spreading room fire detection sys HALL.R E Argonne National Laboratory 80/07/15 2pp
- 8009090362 Forwards comments on tire protection review Items 3 2 3(1), (2), (3), (4), 3 2 9, 3 2 13, 3 2 14, 3 2 15 & 3 2 4 re fire detection sys & ventilation ducts Final Item 3 1 8(2) comments uill be sent shortly HALL, R E Brookhaven National Laboratory 80/08/21 App
- 8009230189 Requests that all personnel be reminded of purpose of emergency notification sys t health physics network Sys installed for goot use during emergency ORIER.8 H Region 1. Philadelphia, Office of the Director 80/08/22 3pp
- 8009070424 Forwards info on Itam 3 2 8(i) & (2) re fire barrier penetration seals for fire protection review HALL,R E Brookhaven National Laboratory #80/08/26 2pp
- R Periodic operating reports & related correspondence
- 8009020245 Forwards "Peach Buttom Atomic Power Station Thermal Mapping Rept 80-3 for 800715,23 & 31 * WILLSEY, W D Philadelphia Electric Co 80/08/24 1p
- --8009020246 "Peach Bottom Atomic Power Station Thermal Mapping Rept 80-3 for 800715,23 & 31 " + Philadelphia Electric Co 80/08/26 App
- COCKET 50-182 PURDUE UNIV RESEARCH REACTOR
- P Operating lucense stage documents & correspondence
- 8009100650 Forwards Amend 4 to License R-87 MILLERJ R Standardization & Special Projects Branch 80/09/28 3pp
 - 8009100653 Amend 4 to License R-87, revising physical security plan MILLER-J R Standardization & Special Projects Beanch 80/08/28 2pp
- ICKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR
 Security, medical, emergency & fire protection plans
- 8009100504 Submits security info Info withheld (ref (OCFR2 790) CARTER.R S Commerce, Dept of, National Bureau of Standards 80/09/04 1p
- G Inspection reports, fE Bulletins & correspondence
- 8009240278 Forwards IE info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 30/09/12 ip
 - 19240281 Forwards 1E Info Notice 80-32, "Clarification of Certain lequirements for Exclusive-Use Shipments of Radioactive latis " Ko written response required RIER. B H Region I. Philadelphia, Office of the Director '0/09/12 19
 - KET 50-185 PLUM BROOK REACTOR MOCK-UP
 - 9020431 Seeks NRC response to 800317 request for issuance of ismantiing order & termination of Licenses TR-3 & R-93 unding for project was included in Fy81 budget Lack of NRC ismantiing orders prevents contracting of work INEDICT.D E National Aeronautics & Space Admin 80/08/25 2pp
 - .ET 50~186 UNIV OF MICBOURI REGEARCH REACTOR
 - 10586 Discusses deviation from Foch Specs 3 6, requiring samples to test hole to hold rigidly in place during reactor, action Review of importance of visual verification of pie loadings conducted w/entire operating staff IBBEN, J C , BRUGGER, R M Missouri, Univ of, Columbia 60/09/18

- R Periodic operating reports & related correspondence
- 8009030212 Forwards "Annual Rept.June 1979 June 1980" & "Std Operating Procedures " Repts available in Central Files only KCKIBFH, J C Missouri, Univ of, Columbia 80/08/27 ip
- S Reportable occurrences. LERs & related correspondence
- 8009040406 RO on 800803, entire holding tank failed to meet primary lech Specs Caused by inadvertent entry of approx 400 gallons of water failing to meet primary specs Holdup tank drained & water meeting primary specs returned to tank MCKIBBEN.J C., BRUGGER.R M. Missouri. Univ. of. Columbia 80/08/29
- B00904041B RO on B00829, primary inlat isolation valve 507B failure to shut when securing primary sys following shutdown Caused by separation of lower seat from metal insert in Schrader valve tensequent blockage of schaust port KCKIBBEN, J.C., BRUGGER, R.M. Missouri, Univ. of, Columbia 80/08/29 4an
- --8009040419 RO on 750620, investigation of Schrader 9725 series threeway colenoid valve indicated valve could fail if lower scal separated from metal insert & prevent air from being exhausted Mfg confirmed problem through testing JULIAN.C A. ALGER.D M Missouri, Univ of, Columbia 75/06/20 6pp
- DOCKET 50-193 RHODE IBLAND & PROVIDENCE PLANTATIONS AEC
- @ Inspection reports, IE Bulletins & correspondence
- 8009240271 Forwards IE info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matis " No written response required ORIER, B if Region 1, Philadelphia, Office of the Director 80/09/12 io
- DOCKET 50-179 MANHATTAN COLLEGE RESEARCH REACTOR

 G Inspection reports, IE Bulletins & correspondence
- 8009240225 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Chipments of Radioactive Matls " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/09/12 1p
- DOCKET 50-201 WEST VALLEY REPROCESSING PLANT
- F Security, medical, emergency & fire protection plans
- 8009230215 Requests that all personnel be reminded of purpose of emergency motification sys & health physics network Sys installed for govt use during emergency GRIER. B H Region i. Philadelphia, Office of the Director 80/08/22 3pp
- G Adjudicatory correspondence
- 800908046B Urges strong support & cooperation to implement insp & evaluation program re condition of high level liquid waste storage sys
 DIRCKS, U J Office of Nuclear Material Safety & Safeguards
 80/06/26. 4pp
- 8009170366 Comments on rulemaking 50-5 re mixed oxide fuel DESMO & other recycle-related licensing proceedings should continue Positive affirmative action to approve licenses recommended KiRK, W F William F Kirk 80/08/28 4pp
- 8009160224 Requests OEBMO re fuels be completed Info is needed for future decisions re reprocessing of spent nuclear fuel VILLEMY. G R Affiliation Unknown 80/09/08 ip
- 8007160420 Comments on rulemaking 50-5 GESMO proceedings should be reposed to provide early procedural framework for subsequent licenting RicHARDS,R II General Electric Co 80/09/09 2pp
- 800930J514 Expresses concern to reopening of DESMO & other related licensing proceedings for reprocessing sites FEIQ.D Affiliation Unknown 80/09/13 lp

- 8009220226 Comments on rulemaking 50-5 GESMO proceedings should be respensed Technical economic & safety issues must be addressed in order for decisions to be mado re use of mixedweitzberg. A Affiliation Unknown 80/09/15
- 8009260641 Urges resumption of GESMO hearings BOLON, A E Affiliation Unknown 80/09/16
- --8009260646 Opposes respening of GESMO hearings BURRELL.A Affiliation Unknown 80/09/13
- --8009260652 Urges reopening OESMO & recycle-related proceedings & consideration of expanding scope to include recycle of LWR fuel in breeder reacturs
 MCCORMACK.M House of Rep 80/09/22 2pp
- 8009300525 Forwards comments in response to Commission 800807 order reterminated GESMO proceedings Reopening would be inimical to natl security & defense & at odds w/nonproliferation objectives BIALIK,E I New York, State of 80/09/23 7pp
- 8009300540 Comments on reopening of OESMO proceedings Add1 use of nuclear generated electricity should be pacad to preserve significant quantities of hydrocarbon reserves for use as raw mals in future chemical mfg BURRIS.L American Institute of Chemicai Engineers 80/09/23 2pp
- 8009300549 Request extension of time for comment on Commission 800807 order to reopening OESMO proceeding HDLDEN, B Ailied General Nuclear Services 80/09/23 1p
- 8009300561 Supports reopening of CESMO & other recycling license proceedings
 PRICE, J E Affiliation Unknown 80/09/23 ip
- H Ceneral correspondence
- 8009100470 Comments on RM 50-9 public should be advised of advantages & disadvantages of implementing Pu recycle NRC should not have terminated efforts on GEBMO fuels

 DECHER.U Affiliation Unknown 80/09/03 ip
- P Operating license stage documents & correspondence
- 8009120545 Forwards 800710 ltr on behalf of NY State Energy R&D Authority re Western NY Nuclear Svc Ctr GitLEN, PH Beries Buttel: Kass & Case 80/07/10, ip
- --8007120547 Resconds to NRC 800605 ltr re Western NV Nuclear Svc Ctr OUTIZED TRANSPORCE OF NAC GOOGRAFIE TO MISSETT AN NUCLEAR RECOgnizes requirements of provisional OL are independent of various contractual provisions & obligations that exist between NFS & NY State R&D authority

 LARDCCA.J L New York, State of 80/07/10 3pp
- 8007100202 Bummary of 800717 meeting w/NFS & NY Energy Research & Davelopment Authority in West Valley, NY re facility issues associated w/work by contractor, Rockwell Hanford Operations
 TINO,W W Advanced Fuel & Spent Fuel Licensing Branch 80/07/22
- Q Inspection reports, IE Bulletins & correspondence
- 8007110684 Forwards JL Larocca 800710 itr re matters invoiving Western NY Nuclear Svc Ctr on behalf of NY State Energy R&D Authority OITLEN,P H Derle, Butsei, Kass & Case BO/07/10 ip
- --8009110692 Responds to NRC 800626 ltr re program for insp & evaluation of facilities for storage of high level liquid redwaste Advised piant that failure to repair pan-leak constitutes default of obligations under general agreement LAROCCA, J L New York, State of 80/07/10 2pp
- 8009250356 Ack receipt of 800701 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-201/80-04 Ltr withheld (ref 10CFR2 790)
 MARTIN.W.O Region I, Philadelphia, Safeguards Branch 80/08/05
- --8009250339 Forwards nonproprietary version of IE Insp Rept 50-201/80-04 on 800519-21 Notice of violation withheld (ref 10GFR2 790) MARTINAN O Region 1. Philadelphia. Safeguards Branch 60/06/17

- ~-8009250363 Nonproprietary version or IE Insp Rept 50-201/80-04 on 800519-21 Noncompliance noted failure of contract security guard to sign in when on duty Details withheld (ref 100FR2 790) 10CFR2 790)
 DEVLIN J W Region 1. Philadelphia, Safeguards Branch
 MCDEGNM.L M Region 1. Philadelphia, Office of the Director Íр
- 8009230412 Forwards IE Circular 80-20. "Changes in Bafe-Slab Tank Dimensions " No written response required GRIER, B H Region I. Philadelphia. Office of the Director 80/08/21 4pp
- R Periodic operating reports & related correspondence
- 8009120601 Forwards SPDES discharge monitoring rept for May 1980 DUCKKORTH, J P Nuclear Fuel Services, inc. (subs. of Getty Gil Co.) íρ 80/06/05
- --8009120604 SPDE8 discharge monitoring rept for May 1980 DUCKWORTH, J.P. Nuclear Fuel Services. Inc. (subs. of Getty Oil Co.) 80/06/26 Spp
- 8009170378 Forwards "Fifty-third Quarterly Environ Manutaring Rept. DUCKMORTH J P Nuclear Fuel Services, Inc., West Valley Reprocessing Plant 80/07/18 ip
- -- 8007170392 "Fifty-third Quarterly Environ Monitoring Rept. Apr-June Nuclear Fuel Services, Inc , West Valley Reprocessing Plant
- 8009ii0648 Forwards SPDES discharge monitoring rept. Jul 1980 DUCKKORTH-J P Nuclear Fuel Services, Inc. (subs. of Getty Gil Co.) 80/08/04 ip
- --8009i10652 SPDES discharge monitoring rept.Jul 1980 * Nuclear Fuol Services. Inc. (subs. of Getty Gil Co.) 80/08/04
- U Congressional/Executive Correspondence
- 8009150020 Responds to Subcommittee on Nuclear Regulation 780906 ltr re Sonator Stafford request for hearing to discuss 1972 momo re pressure suppressing containments: UCS criticisms re ATMS safety problems & Mest Valloy insp problems HENORIE, J M Commission 80/08/18 2pp
- ---8009150094 Discusses actions being taken as result of anonymous ltr refacility inspirent will be available to public & will refanonymous ltr O'REILLY. J P Atomic Energy Commission, Directorate of Regulatory Operations 72/09/20 ip
- --8009180098 Discusses actions taken in response to anonymous allegation re facility leakages Rept should include ref to ltr & allegations which AEC investigated Recommends establishment of iocal PDR Routing slips onci ENDELKEN-R H Atomic Energy Commission, Directorate of Regulatory Operations 72/09/21 App
- -8009150107 Discusses unannounced insp of facility, investigating outsouter miscusses unannounced than or ractice, investigating allegations re leakage accidents from stacks & pending lawsuit on overexposure No substance to allegation on stack leakage No overexposure to radiation indicated ENGELKEN, R II Abomic Energy Commission, Directorate of Regulatory Operations 72/10/04 ip
- --B009150112 Summarizes /20919-29 followup insp results Three violations do not constitute hazard Inquiry made into allegations in 720903 its Licensee will be reinspected on Priority I basis EPSTEIILE Atomic Energy Commission, Directorate of Regulatory Operations 73/01/05 ip
- --B009150118 Forwards Insp Rept S0-201/72-03 Person referred to in anonympus ltr was H Baadeok Info re overe;posure of const workers was relayed to State of NY on 720721 11/0 encl rept NELSON, P R Atomic Energy Commission, Directorate of Regulatory Operations 73/01/05 ip
- ---8009150121 Forwards notice of violation cited in IE Insp Rept 50-201772-03 on 720919-23 & 26-29 NLLSON.P R Atomic Energy Commission. Directorate of Regulatory Operations 73/01/03 2pp
- --8009150127 Notice of violation from 1919 on 720919-23 & 26-29

 * Abomic Energy Commission, Directorate of Regulatory Operations 73/01/05

- --8009130132 Act receipt of AEC 730105 itr relitems of noncompliance cited in Insp Rept 50-201/72-03 on 720919-23 & 26-29 Corrective actions aperators were reprinanced for actions & proper methods for solution transvers were reviewed DUCKMORTH, J. P. Nuclear Fuel Services, Inc., West Valley Reprocessing Plant 73/01/26 2pp
- --8009130133 Act receipt of 730126 itr informing AEC of actions taken to correct items of noncompliance noted in Insp Rept 50-201/72-03 Corrective actions us11 be verified during next insp NELSON PR Atomic Energy Commission. Directorate of Regulatory Operations 73/03/30 3pp
- --8009190139 Ack receipt of Insp Rept 50-201/72-03 No objection lodged to publication in PDR MILLER R N Nuclear Fuel Services, Inc (subs of Getty Dil Co) 73/04/05 1p

9080409 Submits summary of Dingell subcommittee markup session on lest Valley waste solidification bill.HR 6865 Bill as mended passed by subcommittee LARK.A T Advanced Fuel & Spent Fuel Licensing Branch 80/09/22

JCKET 50-206 SAN GNOFRE NUCLEAR STATION, UNIT 1 Security, medical, emergency & fire protection plans

8009030358 Notifies of 800819,22 & 30 regional workshops re development of guidance for acceptable method for coping w/emergencies at facility Requests that representative be sent Subj areas to be discussed include function of facilities & location EXIOELERIA H Region 5. San Francisco, Office of the Director 80/08/12 2pp

09230342 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for goot use during emergency ENDELKEN, R H Region 5. San Francisco. Office of the Director 80/08/22 3pp

09030387 Forwards revised safeguards contingency plan per NRC 791211 & 800324 requests Plan withheld (ref 100FR2 790) BASKILLK P Southern California Edison Co 80/08/28 2pp

)9050286 Forwards Revision 1 to security force training & qualification plan Plan withheld (ref 100FR2 790) BASKHLK P Southern California Edison Co 80707/03 1p

Adjudicatory correspondence

)09300253 Forwards order for mod of license, requiring info to support environ qualification of safety-related electrical equipment Briefings were held w/all interested licenses during wt of 800717 CRUTCHFIELD, D Operating Reactors Sranch 5 80/08/29 2pp

-8009360258 Order for mod of License DPR~13, requiring info to support environ qualification of safety-related electrical equipment EISENHUT, D O Division of Licensing 80/08/29 App

Ceneral correspondence

009050359 Urges NRC not to issue low power fuel loading license for Unit 2 Unit 2 LITELN.K Affiliation Unknown 80/08/28 ip

NOOPLICETE Opposes low level testing & licenting of facility, since no evacuation plan possible MARTINEI, PR Affiliation Uninown 80/08/29 lp

3009120444 Opposes licensing of facility for low level testing due to undue risks posed to health & safety of public & environ RROWN, P Affiliation Unknown 80/08/29 ip

3009050350 Expresses apposition to nuclear energy & licensing of Unit 2 COHEN.P Affilsation Unknown 80/09/03 is

8009110430 Opposes granting low power loading license to avoid evacuation plan requirements
PULIDG, M Affiliation Unknown 80/09/03 ip

- P Operating license stage documents & correspondence
- 8009120505 Notification of contract execution, Mod 5 to "Simulation of Earthquake Ground Motions for San Gnofre" Contractor K Aki MCNULTY. A Administrative Contracts Granch FIN 8-6531 80/04/01
- --8007120514 Mod 5.extending period of performance & adding addl funds to "Simulation of Ground Motions for San Onofre " AKI.K Massachusetts Institute of Technology PERLMAN.J Administrative Contracts Branch FIN B-6531 80/04/01 ip
- 8009090880 Advises that list of 60 addl heavily populated areas have been included in encl revised guidance document, NUREQ-0861, per NRC amend interim rule for physical protection of irradiated reactor fuel in transitie
- B009020297 Submits interim criteria for shift staffing to all GL & CP licensees & applicants,per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT,D O Division of Licensing 80/07/31 7pp
- 8007080080 Forwards draft NUREO-0676. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0676 enci W/o KUREO EISENHUT.D G Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D Q Division of Licensing 80/08/07 60pp
- 800910000B Notification of cancellation of 800B26 meeting w/util in Bethesda,MD to discuss requirements for change over from safety injection to recirculation mode operation NOWICKI.S J. Operating Reactors Branch S. 80/08/11 2pp
- 8009190794 Forwards revised Westinghouse STS 3 9 8 2,3 9 10 & Bases 3/4 9 8 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required NOVAK.T M Assistant Director for Operating Reactors 80/08/15
- --8009190817 Revised Westinghouse STS 3 9 8 2:3 9 10 & Bases 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods ** Assistant Director for Operating Reactors ** 80/06/23 21pp
- 8009020063 Forwards response to NRC 800523 itr requesting response to FSAR Questions 361 65 re comparative analysis of results of site-specific earthquake program & empirical evaluations for facility

 BASKIN, K P Southern California Edison Co 80/08/21, 15pp
- 8009020082 Forwards repts referenced in 800428 submittal re seismic adequacy of plant per 800711 telcon request BASKIN, K.P. Southern California Edison Co. 80/08/21 2pp
- ~-8007020085 "Reduction in Free Field Ground Motion Due to Presence of Etructures," submitted to Southern CA Edison Co * TERA Corp 80/08/31 17pp
- ~-B009020091 "Experimental Investigations~Correlation W/Analysis" presented at 770711-15 proceedings of Natl Science Faundation workshop, Univ of CA: Berkeley SHEPNERD, R. UENNINGS, P. C. California Institute of Technology 77/07/11 20pp
- ~-8009020096 "Seasmic Performance of Piping in Past Earthquakes." submitted for presentation & publication at 800913-17 Speciality Conference on Cavil Engineering & Nuclear Fower in Knoyville.TH CLOUD.R.L. Rubert L. Cloud Associates, Inc. 80/09/15 29pp
- --8009020100 "On Instrumental vs Effective Acceleration & Design Coefficients," presented at 790822-24 proceedings of Second UB Natl Conference on Earthquake Engineering, Stanford Univ.CA BLUME. A John A Blume & Associates, Engineers (subs URS Corp 1 74/08/22 15pp

- 8009110746 Notification of 800916 meeting w/SEP numers group to discuss NRC initial review & recommendations for site-specific ground response spectra & owners group program plans for seismic functional qualification of Class IP equipment LEVIN.H A Division of Engineering 80/08/26 1p
- 8009120547 Notification of 800903 meeting w/utii in Bethesda.MD to discuss util submittal for steam generator repairs NOWICKi.S J Operating Reactors Branch 5 80/08/26 2pp
- 8009030634 Forwards application for Amend 92 to License DPR-13, consisting of Proposed Changes 97.98 & 99 to Tech Specs License amend fee enci DIETCH, R Southern California Edison Co 80/08/27 2pp
- --8009030637 Application for Amend 92 to License DPR-13 consisting of Proposed Changes 97.98 & 99 to Tech Specs Cartificate of Svc encl DIETCH.R Southern California Edison Co 80/08/27 Spp
- --8009030644 Proposed Changes 97.98 & 99 to Tech Spec 3 7 re auxiliary electrical supply. Tech Spec 3 3 re safety injection & containment spray sys & Tech Specs 5 0 & 6 0 re administrative controls

 * Southern California Edison Co 80/09/27 12pp
- 8009:004:7 Summary of 800724 meeting w/applicants to discuss analysis of Imperial Valley parthquake of Oct 1979
 ROOD.H Licensing Branch 3 80/08/27 iopp
- 8009150420 Notification of contract execution "Folinwon to Simulation of Earthquake Ground Motions for San Gnofra Nuclear Oenerating Station," awarded to E Luco LITTLE, M Administrative Contracts Branch FIN 8-6898-0 80/08/27
- ---8009130424 Contract "Followen to Simulation of Earthquate Oround Motions for San Onofre Nuclear Generating Station." awarded to E'Luco
 LUCG, J E Luco, J E PERLMAN, J Administrative Contracts Branch
 FIN 3-6898-0 80/08/27 5pp
- 8009240052 Notification of contract execution "Foilowon to Bimulation of Earthquake Ground Motions for Ban Quofre Nuclear Ornerating Station " Contractor R Hermann LITLE, K Administrative Contracts Branch FJN 8-6898-0 80/08/28 tp.
- ~-8009240057 Contract "Followen to Simulation of Earthquake Ground Motions for San Onofre Nuclear Ownerating Station." awarded to R Hermann HERMANN, R St Louis Univ PERLMAN, J Administrative Contracts Branca FIN 8-6898-0 80/08/28 5pp
- 8007080343 Responds to NRC 800728 itr requesting util provide plan concerning evaluation of cable trays Criteria for re-evaluation will be determined based upon cable tray test program results Action plan enci BASKIN,K P Southern California Edison Co 80/08/29 3pp
- 8007070463 Forwards add; info on effects of non-Category A equipment failure requested at 800804-05 meeting w/NRC & LLL BASKIN, K P Southern California Edison Co 80/08/27 App
- HOO919036 Forwards "Steam Cenerator Repair Rept "
 BASKIN, K P Bouthern Cairfornia Edison Co 80/08/29 3pp
- --8009190365 Errata to "Steam Cenerator Repair Rept." nonproprietary version 4 Westinghouse Electric Corp SE-EP-58(80) ERR 80/08/29 ip
- --8009190374 Forwards "Steam Generator Repair Rept." proprietary & nonproprietary versions Application & affidavit for utbhhoiding encl ANDERSON.T M Wastinghouse Electric Corp 80/09/il. 10pp
- --8009190378 "Steam Generator Repair Rept," nonproprietary version AKIN.R C , ROSENTHAL.H P. Westinghouse Electric Corp SE-SP-38(80) 80/09/30 380pp
- 8009090552 Advises that responses to NRC 800723 request for add1 info re steam generator & reactor coolant pump supports should be available for submittal by 800919 BASKIN,K P Southern California Edison Co 80/09/02 ip

- 8009160230 Forwards Page 24 of "Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station. Unit 1. Suppl II " Page 24 was inadvertently omitted from rept submitted on 800808 BASKIN.K P Southern California Edison Co 80/09/05 1p
- --8009160231 Page 24 of "Simulation of Carthquake Ground Motions for San Onofre Nuclear Generating Station.Unit 1.Suppi 11 " Page 24 was inadvertently omitted from rept submitted on 600808 4 Del Har Technical Associates 80/07/05 ip
- 8009170238 Confirms understanding based on 800905 discussions during mpt meeting at util ofcs.re actions to be taken for corrections of observed weaknesses in radiation protection program NRC should be notified if understanding incorrect ENGELKEN.R H Region 5. San Francisco, Difice of the Director 80709705 2pp
- 8007080322 Forwards additinfo restructural topics in response to NRC 790816 itr Design wind velocity of 100 miles/h was used for containment sphere BAEKIN-K P Southern Cailfornia Edison Co 80/09/08 15pp
- --8007080326 "Addendum 2 to Guelity/Safety-Related Civil Structural Const Spec for Sphere Encl Project for Southern CA Edison Co SDNOS-1 " Bill of matl for storage tanks dtd 640526 & related matl encl # Bechtel Power Corp
- 8009290143 Notification of 800926 meeting w/utils & Kerr-McGee Chemical Corp in Bethesda, MD to discuss review % recommendations for site specific ground response spectra & program plans for seismic functional qualification of Class IE equipment ALLISON, D.P. Bystematic Evaluation Program Branch 80/09/08 3pp
- 8009260022 Notification of second reschaduling until 801003 for meeting w/SEP numers group & KMC. Inc to discuss //RC initial review of site-specific ground response spectra & util program for selsmic functional qualification of Class IE equipment ALLISON, D.P. Systematic Evaluation Program Branch 80/09/10 3pp
- 8009190402 Responds to NRC 800815 request to review facility Tech Specs to ensure that 23 ft of water is over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Facility is in compliance DASKIN.K P Southern California Edison Co 80/09/11 1p
- BOO9170336 Notifies that actions required in NRC 800702 ltr re license amend application concerning implementation of TMI Lessons Learned requirements cannot be accomplished by 800912 License amend application will be submitted by 810916 BASKIN.K P Southern California Edison Co 80/09/12 1p
- 8009290348 Responds to 800703 itr requesting additinfore differences in Unit I design from SEP assessments Description of safety injection sys should be clarified in terms of alternate method in event of preferred path fallure BASKIN.K P Southern California Edison Co 80/09/22 2pp
- 8009300377 Forwards response to 800723 request for add1 info re steam gamerator & reactor coolant pump supports
 AASKIN, F Southern California Edison Co 80/09/23 5pp
- 8009300362 Bubmits current status of structural evaluations & summary of program for evaluation of piping & equipment Detailed evaluations of plant structures are scheduled for completion in June 1981

 BASKIN K P Southern California Edison Co 80/09/24 3pp
- BOO930044B Ack receipt of 800B29 request for additinfore failure of salt water cooling sys Input from several engineers & operating entities required to complete request Response will be submitted B0100B BASKIN.K P. Southern California Educon Co. 80/09/24 1p
- G Inspection reports, IE Bulletins & correspondence
- BO09090B11 Reschedules response to Item 2 of IE Bulletin 80-04, "Analysis of PWR Main Stream Line Break w/Continued Feedwater Addition " Response will be forwarded by BO0801, pending MSLB cone response reanalysis OTTO80N, H L Southern California Edison Co 80/07/16 2pp.
- 8007:70207 Forwards response to 1E Builetin 80-11. "Masonry Wall Design " Describes masonry walls at facility that are in proximity to or have attachments from safety-related piping equipment UTTOSON, H L Southern California Edison Co 60/07/17 6pp

- 8009150011 Responds to Item 2 of IE Bulletin 80-04 re analysis of reactivity increases due to main steam line break inside or outside containment Pravious response validated OTTOSON, H. L. Southern California Edison Co. 80/08/04 2pp
- 8009160630 Responds to IE Bulletsn 79-13 Revision 2, "Cracking in Feeduster Sys Piping " Radiograph exam performed on all feedwater nozzle to reducer b reducer to pipe welds w/no deficiencies noted OTTOSCH.H L Southern California Edison Co 80/08/07 3pp
- 80092A0297 Forwards JE Info Notice 80-29, "Broken Studs on Terry Turbine Steam inlet Flange" No written response required ENGELKEN,R H Region 5, San Francisco. Office of the Director 80/09/07 1p
- 6009020448 Summary of 600710 meeting w/util in Bethesda.MD re results of steam generator insps & corrective actions
 NDWICKLS J Operating Reactors Branch 2 60/08/08 48pp
- 8009030283 Forwards Revision I to IE Bulletin 80-19, "Faitures of Morcury-Hetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Fower Plants Designed by C-E " Written response required ENGELKEN.R H. Region S. Ban Francisco. Office of the Director 80/08/15 io
- 8009160521 Responds to IE Bulletin 80-19. "Failures of Mercury-Wetted Matris Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E "Mercury-wetted relays not used in Factive reactor protective sys OTTOSON.H L Southern California Edison Co 80/08/19 1p
- 8009290457 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pong Studs " ENGELKEN,R H Region 5, San Francisco, Office of the Director SO/08/18 4pp
- 8009160184 Forwards IE Circular 80-18. "IOCFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys ' No written response togusted ENGLINER, R H Region 5, San Francisco, Office of the Director
- 6009120463 Forwards iE info Notice 80-31. "Maloperation of Gould-Brown Boveri 430 Volt Type K-6003 & K-DON 6005 Circuit Breakers" No written response required EMGELXEN, R H. Region 5. San Francisco, Office of the Director 80/08/27 1p
- R Periodic operating reports & related correspondence
- 8009030533 Forwards "San Chofre Nuclear Generating Station Semiannual Operating Rept," for Jan~June 1980 OTTOSON:H L Southern California Edison Co 80/08/27 1p
- --8007030535 "San Onofre Nuclear Generating Station Semiannual Operating Rept." for Jak-June 1980 # Southern California Edison Co # San Diego Cas & Electric Co 80/08/27 7pp
- 8009090265 Forwards monthly operating rept for Aug 1980 EURRAN, J H Southern California Edison Co 80/09/04, 19
- --8009090269 Monthly operating rept for Aug 1980 uQY.J M Southern California Edison Co 80/09/04 5pp
- S Reportable occurrences. LERs & related correspondence
- 8009020078 Forwards LER 80-031/03L-0 OTTOSON, H L Southern California Edison Co 80/08/21 3pp
- --BD09020083 LER BD-031/03L-0 on 800728 during routine equipment rotation, south saltwater cooling pump discharge valve failed to open automatically Caused by installation of solenoid valve operator w/wrong size spring Valve replaced CURRAN.J M Southern California Edison Co 80/08/19 ip
- 8009180139 PMO-V-80-067 on 800902, licensee reported that workers involved in steam generator head entries may have radiation exposures in excess of 3 rem per quarter Largest exposure is 7 rem Caused by monitoring chast instead of head YUMAS, 0. WENSLAKSKIF Region 5, San Francisco, Office of the Director 80/09/02 29p
- 009260509 Forwards LER 80-033/01T-0 HAYNES.J 6 Southern California Edison Co 80/09/16 3pp

- --8009260513 tER 80-033/017-0 on 800902, actuation of safety injection block switch followed by loss of offsite power indicated sequencer test box would not perform as designed Caused by design deficiency Redesign is underway CURRAN, J M Southern California Edison Co 80/09/16 3pp
- 8007300615 PND-V-80-067 advertisement in Southern CA newspaper offering \$100.00 per day for work involving exposure to radiation has attracted media attention Region 5 is closely monitoring steam generator repairs YUHAS, GP, WENSLAWSKI, F Region 5, San Francisco, Office of the Director 80/07/16 ip
- DOCKET 50-208 COLUMBIA UNIV RESEARCH REACTOR

 G Inspection reports, IE Bulletins & correspondence
- 8009340218 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No critten response required CRIER, B.H. Region 1, Philadelphia, Office of the Director 80/09/12 ip
- BOCKET 50-213 HADDAM NECK PLANT

 F Security, medical, tmergency & fire protection plans
- 8009230169 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency ORIER, BH Region I, Philadelphia, Office of the Director 80/08/22.
- P Operating license stage documents & correspondence
- 800902027 Bubmits interim criteria for shift staffing to all OL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D O Division of Licensing 80/07/31 7pp
- B0090B00B0 Forwards draft NUREQ-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREQ EISENHUT, D Q Division of Licensing 80/08/01 119pp
- 8009120709 Forwards agenda of 800821 meeting at util ofcs to discuss assessment of regulatory performance GRIER. B H Region 1. Philadelphia. Office of the Director 80/08/04 2pp
- 8007230092 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D 0 Division of Licensing 80/08/07 60pp
- 8009190794 Forwards revised Westinghouse 8TS 3 7 8 2,3 9 10 & Bases 3/4 9 8 & 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required NDVAK.T M Assistant Director for Operating Reactors 80/08/15 ip
- ~~8007170B17 Revised Westinghouse STS 3 9 8 2,3 9,10 & Bases 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vescel flange during movement of fuel assemblies or control roots

 4 Assistant Director for Operating Reactors 80/06/23 21pp
- 9009100454 Advises that mgt meeting w/NRC in Berlin,CT has been rescheduled for 800911 Agenda encl ORIER B H Region 1. Philadelphia, Office of the Director 30/08/20 2pp
- 800702023: Forwards add: info to Questions 2.3 & 4 re adequacy of station electric distribution sys voltages per Crutchfield 800701 itr Response to Question 1 will be submitted by 801126 GONSIL.N 0. FEE.W F Connecticut Yankee Atomic Power Co 80/08/21 7pp
- 8009110746 Natification of 800916 meeting w/SEP owners group to discuss NRC initial review & recommendations for site-specific ground response spectra & owners group program plans for seismic functional qualification of Class IE equipment LEVIN.H A Division of Engineering 80/08/26 19

DOCKETED ITEMS

- 8009030532 Advises that NRC 800728 request for SEP licensees to 009000532 Advises that NRC 800728 request for SEP licensees to specifically address issue of seismic support criteria for internally attached components of safety-related electrical equipment not feasible approach COUNSIL.H G , FEE.H F Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/08/27 2pp
- 8009030641 Discusses implementation status of automatic initiation auxiliary feedwater Control-grade scheme is installed & will be made operable after NRC review & approval Final safety-grade design will be forwarded Class IV amend fee encl COUNSIL.W G Connecticut Yankee Atomic Power Co 80/08/27 App
- --8009030646 Proposed revisions to Tech Spec 3 8 for operation of turbine cycle Revisions specify conditions of turbine cycle equipment necessary to insure capability to remove decay heat from reactor core

 * Connecticut Yankee Atomic Power Co 80/08/27 6pp
- B00903037B Advises that util will not meet deadline for implementation of NUREC-057B requirements re emergency procedures & retraining for accidents & translents NRC feedback needed COUNSIL.H G Connecticut Yankee Atomic Power Co COUNSIL.W G Nertheast Nuclear Energy Co (subs of Northeast Utilities) 80/08/28 2pp
- B009120257 Responds to NRC B0070B ltr re SEP Topics III-10 A,V-II A,V-IV-4,VI-7 C 1 & VIII-3 B Concurs w/NRC conclusions.except for Topic VIII 3 B Control room contains battery fuse open alarm in addition to alarms noted in NRC assessment COUNBIL.N 0 . FEE,W F Connecticut Yantee Atomic Power Co B0/09/04 2pp
- 8009270143 Notification of 800924 meeting w/utils & Kerr-McGee Chemical Corp in Bethesda-MD to discuss review & recommendations for site specific ground response spectra & program plans for seismic functional qualification of Class IE equipment ALLISON, D P Systematic Evaluation Program Branch 80/09/08 3pp
- 8009260022 Notification of second rescheduling until 801003 for meeting w/SEP owners group & KMC.Inc to discuss NRC initial review of site-specific ground response spectra & util program for seismlc functional qualification of Class IE equipment ALLISON, D P Systematic Evaluation Program Branch 80/09/10 3pp
- 8009180357 Forwards implementation status of Category B TMI-2 Lessons Learned requirements for each facility Schedules specifically identify items where requirement cannot be met or schedule is not feasible COUNSIL, W O Connecticut Yankee Atomic Power Co COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/09/15 43pp
- 8009230621 Submits addl info re seismic re-evaluation program Significant progress has been achieved Modeling of structures is approx 75% complete & RCS is approx 70% complete COUNSIL,W O , FEE,W F Connecticut Yankee Atomic Power Co 80/09/15 Spp
- E009290331 Application for amend to Licenses DPR-61, DPR-21 & DPR-65, incorporating revisions to Tech Specs for RCS per TKI-related requirements Fee enci COUNSIL, W G CO
- --B009290354 Proposed revisions to Tech Specs 3 3 for RC8 operational commonent Connecticut Yankes Atomic Pawer Co 80/09/30 5pp
- --8009290358 Proposed revisions to Tech Bpecs 3 11 for containment * Connecticut Yankee Atomic Power Co 80/09/30 6pp
- --8009290362 Proposed revisions to Tech Specs 6 3 for administrative controls of facility staff qualifications
 4 Connecticut Yankee Atomic Power Co 80/09/30 3pp
- --8009290367 Proposed revisions to Tech Specs 6 0 for administrative Connecticut Yankee Atomic Power Co 78/12/08 4pp
- --8009290372 Proposed revisions to Tech Specs 3/4 4 3 for limiting condition for operation of RCS relief sys
 * Connecticut Yankse Atomic Power Co 78/12/08 3pp
- --8009290377 Proposed revisions to Tech Spect 3/4 4-3a re limiting conditions for operation of RCS relief valves-operating # Connecticut Yankee Atomic Power Co 80/09/30 ip

- --8009290381 Proposed levisions to Tech Specs 3/4 4 4 for limiting conditions for operation of RCS prossurizer * Connecticut Yankon Atomic Power Co G0/09/30 2pp
- -- 8007270384 Proposed revisions to Tech Specs 3/4 4 5 for RCS steam generators
 * Connecticut Yankee Atomic Power Co 80/09/30
- --8009290387 Proposed revisions to Tach Specs 6 0 for administrative Connecticut Yankee Atomic Power Co 80/09/30 3pp
- 8009260478 Forwards util petition for declaratory ruling re Power Facility Evaluation Council jurisdiction over proposed spent resin storage facility Action on petition withheld, pending investigation of issue of superseding federal authority PONO,0 D Connecticut, State of 80/09/17 8pp
- Q Inspection reports, 1E Bulletins & correspondence
- 8009120247 Responds to IE Sulletin 80-16 No Resempont 1151 or 1152 pressure transmitters w/Codes A or D installed or planned to be installed in safety or nonsafety-rolated application GOUNSIL.U G Connecticut Yanker Atomic Power Co GO/07/3 80/07/30
- 8009110474 Responds to IE Bulletin 79-13 & forwards summary rept of insp of feedwater sys piping No unacceptable piping components identified CDUNSIL:H O Connecticut Yankee Atomic Power Co 80/08/01 Spp Connecticut Yantee Atomic Power Co 80/00/01 5pp
- 8009030113 Forwards Revision 1 to IE Builetin 80-19, "Failures of Mercury-Metted Matrix Relays in Reactor Protective 8ye of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER, B H Region I. Philadelphia. Office of the Director 80/08/15 Ip
- 8009020015 Forwards results of May 1980 steam generator tube insp GRAVES,R H Connecticut Yantee Atomic Power Co 80/08/22 1a
- 8009180003 Forwards IE Circular 80-18, "10CFRSO 59 Safety Evaluations for Changes to Radwaste Treatment Bys " No written response required GRIER.B II Region 1, Philadelphia, Office of the Director 80/08/22 1p
- 8009120174 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover: 480 Volt Type K-6008 & K-DDN 6008 Circuit Breakers" No written response required GRIER, B H Region I. Philadelphia, Office of the Director 80/08/27 1p
- 8009230779 Forwards IE Circular 80-21, "Regulation of Refueling Crews "
 No written response required
 GRIER,B H Region i, Philadelphia, Office of the Director
 80/09/10 ip
- 8009240308 Forwards JE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Bhipments of Radioactive Matls " No written response required ORIER, B Nt Region I, Philadelphia, Office of the Director 80/09/12 ip
- R Periodic operating reports & related correspondence
- 8009040380 "Bemiannual Radioactive Effluent & Waste Disposal Rept," Jan-June 1980
 - * Connecticut Yankee Atomic Power Co 80/06/30 55րթ
- 8009:80175 Forwards monthly operating rept for Aug 1980 GRAVES.R H Connecticut Yankee Atomic Power Co 80/4 80/07/10 1p
- ---8009180180 Monthly operating rept for Aug 1780 * Connecticut Yankee Atomic Power Co 80/09/10

- DOCKET 50-214 OVSTER CREEK NUCLEAR POWER PLANT F Security, medical, emergency & fire protection plans
- 8009230174 Requests that all parsonnel be reminded of purpose of emergency notification sys & health physics notwork Bys installed for govt use during emergency GRIER, B H Region 1. Philadelphia, Office of the Director 80/08/22 Spp

G Adjudicatory correspondence

- 8009300265 Forwards order for mod of license, requiring info to support environ qualification of safaty-related electrical equipment Briefings were held u/all interested licensees during whof 800717 CRUICHFIELD.D Operating Reactors Branch 5 80/08/29 Rep
- --8009300269 Order for mod of license requiring info to support environ qualification of safety-related electrical equipment EISENHUT. D O Division of Licensing 80/09/29 App
- 8009190299 Responds to FOIA request for 15 documents listed in bibliography of MUREO-0629. "Rept of Siting Policy Task Force" Documents 6-8 t 13 are available in PDR Forwards remaining documents FELION, J M Division of Rules and Records 60/09/04 1p
- --8009190587 Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants for determination of site acceptability & adequacy of engineered safety features.

 MINDOUE, R B Office of Standards Development, Director SECY-79-362 79/06/04 7pp
- --8009190630 Requests that encl. "Differences in Procedures for Estimating Atmospheric Dispersion Conditions at Inland & Coastal Sites," be sent to apprepriate Boards SCINTO, JF Hearings Division 79/04/04 [App
- 8007090395 Memorandum & order.ALAB-612.remanding ASLB 800222 order for further proceeding per ALAB-611 Relationship between significant unresolved generic safety issue & reactor operation under scruting must be resolved RISMOP.C J. Atomic Safety and Licensing Appeal Panel 80/09/05 5pp
- 8007110807 Memorandum & order advising NRC to file add1 into by 801031 re unresolved generic safety issues, per ASLB 800705 order which remanded proceeding LAZO.R N Atomic Safety and Licensing Board Panel 80/07/07 2pp

H General correspondence

- 8009020187 Responds to 800623 ltr re RE Cunningham comments on cracks detected in core spray sys spargers Sparger strengthened during Fall 1978 outage Interia measures for nouly found cracks acceptable IE Bulletin 80-13 describes requirements DIRCHS.II J Office of the Executive Director for Operations 80/08/07 2pg
- 8009020191 Requests consideration of encl RE Cunningham 1tr commenting on cracks in core spray sys sparger BRADLEY, B Genate 80/06/23 3pp

Operating license stage documents & correspondence

- 10116018 Notification of 750918 meeting w/wtil in Betheida MD to discuss impact of free standing liquid requirements for solid daste LDR Environmental Evaluation Branch (Pre 791030) 79/09/87 2pp
- JO9090879 Advises that list of 60 addl heavily populated areas have been included in encl revised guidance document.NUREG-0561, per NRC amend rule for physical protection of irradiated reactor fuel in transit.effective 800703 H/O encl MCCORKLE.O W Physical Security Licensing Branch 80/07/07 ip
- 8009110554 Suppls NRC 800707 request for proposed Tech Specs changes re scram discharge vol vent & drain valves, & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT.D 0 Davision of Licensing 80/07/82 22pp

- 8009020297 Submits interim criteria for shift staffing to all OL & CP licenses & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENMUT.D G Division of Licensing 80/07/31 7pp
- 8007080080 Forwards draft NUREG-0.696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0.676 enc? N/O NUREO EISENHUT, D & Division of Licensing 80/08/01 119pp
- 8009230052 Informs that eramption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D & Division of Licensing 80/08/07 60pp
- 8007150506 Forwards request for add1 info from licensee, based upon review of facility inservice testing program Requests meeting w/util on 800783-24
 8DSYMKUR J Mechanical Engineering Branch 80/08/20 12pp
- BO09240593 Forwards *Mark 1 Containment Long-Term Program GER, Resolution of Generic Technical Activity A-7," NUREG-0461 W/o encl CRUTCHFIELD,D Operating Reactors Branch 4 80/08/20 2pp
- 8009150031 Advises that 800807 Change Request 91 to form new mgt organization is considered to have safety significance & requires Class III amend fee Requests that add1 sum be remitted to NRC DIGOS,R K License Fee Management Branch 80/08/22 1p
- 8009110746 Notification of 800916 meeting w/SEP owners group to discuss NRC instal review & recommondations for site-specific ground response spectra & owners group program plans for seismic functional qualification of Class IE equipment LEVIN.H A Division of Engineering 80/08/26 ip
- 8009020360 Notifies that 800825 Tech Spec Change Request 91 days not after basic responsibility of util refacility operation Figure 6.2 i clted as ref to proposed mgt reorganization FINFROCK. I R Jersey Control Power & Light Co. 80/08/27 ip
- 8009150046 Notification of 800907 meeting w/util in Bethesda.MD to discuss pipe breaks outside containment PAULSON.W A Operating Reactors Branch 5 80/09/02 2pp
- 8009290143 Notification of 800926 meeting w/utils & Kerr-McGee Chemical Corp in Bethesda. MD to discuss review & recommendations for site specific ground response spectra & program plans for seismic functional qualification of Class IE equipment ALLISON. D P Systematic Evaluation Program Branch 80/09/08 3pp
- 8009240022 Notification of second rescheduling until 801003 for merting w/SEP owners group & KMC. Inc to discuss NRC initial review of site-specific ground response spectra & util program for solamic functional qualification of Class IE equipment ALLISON.D P Systematic Evaluation Program Branch 80/09/10 Spp
- 8009190421 Forwards info re turbine disk intergrity, in response to NRC 800611 ltr Table re nominal water chemistry of condensate turbines encl FINPROCK, I R Jersey Central Power & Light Co 80/09/15 13pp
- 8009220283 Forwards addl Class 3 amend fee, in response to NRC 800807 FINFROCK, I R Jersey Central Power & Light Co 80/09/15 2pp
- 8009290365 Requests changes to App A of License DPR-(6 Sections 1 0, 3 5, 4 5 & 6 0 to Tech Specs will be revised & Sections 3 13 & 4 13 will be added in response to NRC 800702 itr re NUREO-0578 Category A items Certificate of Svc encl FINFROCK. I R Jersey Central Power & Light Co 80/09/23 4pp
- --8009290369 Tech Spec changes for Sections 1 0.3 5.4 5 & 6 3 & addl Sections 3 13 & 4 13 to App A of License DPR-16 Clarifying shift technical advisor program # Jersey Central Power & Light Co 80/09/23 13pp
- 8009300261 Responds to NRC 800905 ltr re TMI-2 Lessons Learned requirements Requests that Implementation date of some items be extended Altermative schedules & justification for two ltems enci
 FINHROCK, I R Jersey Central Power & Light Co 80/09/26 4pp

- E009300270 Ack receipt of 800827 ltr re environ qualification of safety-related electrical equipment Util is currently reviewing electrical & mechanical equipment qualifications & will submit supporting info no later than 801101 FINFROCK.IR Jersey Central Power & Light Co 80/07/26 ip
- Q Inspection reports: IE Bulletins & correspondence
- 9009100034 Forwards IE Insp Rept 50-217/80-11 on 800318-19 Noncompliance noted GRIER, B H Region 1. Philadelphia, Office of the Director 80/07/08 2p
- --B009100044 IE insp Rept 50-219/80-11 on 800318-19 Noncompliance noted failure to use engineering controls & procedures & to perform surveys in accordance w/100F20 201(b) to assure compliance w/100FR20 10(a)(3)

 KNAPP,P J Region I, Philadelphia, Fuel Facility & Materials Safety Branch NIMITZ,R L Region I, Philadelphia, Office of the Director 80/03/02 13pp
- 8009150119 Forwards IE Insp Rept 50-219/80-20 on 800513-15 No noncompliance noted SMITH.O H Region i, Philadelphia, Fuel Facility & Materials Safety Branch 80/07/14 2pp
- ---8007150124 IE Insp Rept 50-217/80-20 on 800513-15 No noncompliance noted Major areas inspected program for 6C of analytical measuraments & performance on radiological analyses of split actual effluent samples BORES:R J Region 1: Philadelphia, Fuel Facility & Materials Safety Branch KOTTAN, J J Region 1: Philadelphia, Office of the Director 80/07/10 7pp
- BO07090i65 Ack receipt of B006i0 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-219/80-03 GRIER, B.H. Region 1, Philadelphia, Office of the Director BD/07/28 ip
- --8009090181 Responds to NRC 800519 itr re violations noted in IE Insp Rept 50-219780-03 Corrective actions breathing air fittings used for purposes other than radiation protection confiscated FINFROCK. IR Jersey Central Power & Light Co 80/06/10 App
- --8009090168 Forwards IE Insp Rept 50-219/80-03 on 800121-25 & notice of violation Details withheld (ref 10CFR2 790) GRIER, B H Region 1, Philadelphia, Office of the Director 80/05/19 2pp
- --8009070184 Notice of violation from insp on 800121-25
 * Region 1, Philadelphia, Office of the Director 80/04/02 3pp
- --8009090189 IE Insp Rept 50-219/80-03 on 800121-25 Noncompliance noted failure to perform evaluation of radiation hazards.use respiratory protection equipment & label radioactive matl Pp 18-16 withheld (ref 10CFR2 790) NIHITZ.R L. Region 1, Philadelphia, Office of the Director 80/04/02 17pp
- BOOT110507 Forwards IE Insp Rept 50-217/80-22 on B00602-06 No noncompliance noted BRUNNER,E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/07/30 2pp
- --B009i103iB IE Insp Rept 50-219/80-22 on 800602-06 No noncompliance noted Major areas inspected licensee action on previous findings.pipe support & restraint sys & primary containment integrated leak rate test.

 CAPHION.D L. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. REKITO,W A. Region 1, Philadelphia, Office of the Director 80/07/29 · 10pp
- BO07070235 Responds to IE Builetin 77-03A No fusion welded stainless steel pipe installed in any safety-related sys ROSS,D,A Jersey Central Power & Light Co BO/OB/O1 ip
- BOO9120179 Responds to IE Bulletin 80-17 re failure of control rods to fully insert during scram No significant amount of water detected Applicable procedures revised to insure safety No action required re ATWS FINFROCK, IR Jersey Central Power & Light Co 80/08/06 2pp
- BO09230104 Responds to 1E Bulletin 80-17, Supp A.1-A.5 Analysis showed adequacy of as-built scram discharge vols w/vent & drain sys Addi analyses will be preformed & NRC will be provided w/description if deficiencies identified FINFROCK, I.R. Jursey Cantral Power & Light Co. 80/08/07 2pp

- 8009090031 Responds to 1E Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protection 8ys of Operating Nuclear Power Plants Designed by C-E " Facility does not utilize mercury-wetted relays in safety-related equipment FINFROCK, I R Jersey Central Power & Light Co 80/08/13 1p
- 8007030068 Forwards Revision 1 to IE Builetin BO-17, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required CRIER,B H Region I. Philadelphia, Office of the Director 80/08/15 ip
- 8009160510 Responds to Item B 1 of IE Bulletin 80-17, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR "
 Continuous waste level monitoring sys will not be installed by 800901 due to extended lead time for mat1 FINFROCK.1 R Jersey Central Power & Light Co 80/08/15 2pp
- 8009120087 Forwards Suppl 3 to 16 Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR " Hritten response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/08/22 ip
- 8009180006 Forwards 1E Circular 80-18, "10CFR90 59 Safety Evaluations for Changes to Radwaste Treatment Bys " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/08/22 ip
- 8009120229 Forwards IE Info Notice 80-31, "Maioperation of Gould-Brown Boveri 480 Volt Type K-600S & K-DDN 600S Circuit Breakers " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/08/27 1p
- 8009230493 Forwards Revision 1 to IE Bulletin 79-26, "Boron Loss From DNR Control Blades " Written response required GRIER, B H Region 1. Philadelphia, Office of the Director BO/08/29 ip
- 8009230782 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/09/10 ip
- 8007240349 Forwards IE Info Notice 80-32, "Clerification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required ORIER,8 H Region 1. Philadelphia. Office of the Director 80/09/12 ip
- 8009300345 Ack receipt of full payment of civil penalties,in response to NRC 800708 ltr w/notice of proposed imposition of civil penalties Corrective actions documented in 800731 ltr will be examined during future insp
 8TELLD.V Office of Inspection & Enforcement, Office of the Director 80/09/17 lp
- R Periodic operating reports & related correspondence
- 8007070348 Forwards Bemiannual Rept 80-i, "Radioactive Effluent Releases, Jan-June 1980" ROSS, D.A. Jersey Central Power & Light Co. 80/09/02 1p
- --B009090371 Bemiannual Rept 80-1, "Radioactive Effluent Releases, Jan-June 1980 " * Jersey Central Power & Light Co 80/09/02 100pp
- 8009230541 Forwards monthly operating rept for Aug 1980 ROSS:D A Jersey Central Power & Light Co 80/09/16 ip
- --8009230564 Monthly operating rept for Aug 1980 MCCLAIN.C M Jersey Central Power & Light Co 80/09/16 9pp
- S Reportable occurrences, LERs & related correspondence
- 8009090354 Forwards LER 80-033/03L-0. ROSS.D A Jersey Central Power & Light Co 80/08/14 ip
- --8009090381 LER 80-033/03L-0 on 800806,24-h after reactor mode switch was placed in RUN, torus oxygen concentration found in excess of 5% Caused by torus oxygen analyzer out of callbr & reduced flow capability of nitrogen purge sys
 ROSS, D A Jersey Central Power & Light Co 80/08/28 4pp

- 8009020379 Forwards Monroutine Environ Operating Rept 50-219/80-5 FIN-ROCK.1 R Jersey Central Power & Light Co 80/08/26 1p
- 8009020392 Forwards Nonroutane Environ Operating Rept 50-219/80-6 FINFROCK.1 R Jersey Central Power & Light Co 80/08/26 ip
- 8009030340 Nonroutine Environ Operating Rept 50-219/80-5 Total of ten dilution pump trips occurred between 800808 & 800912 Caused by high lubricating oil temp Evaluation completed for upgrading cooling water sys FINFROCK, 1 R Jersey Central Power & Light Co 80/08/26 3pp
- 8009090351 Forwards LER 80-028/03L-0 ROSS.D A Jersey Central Power & Light Co 80/08/28 lp
- --8009070365 LER 80-028/03L-0 on 800730, while performing monthly surveillance testing of reactor high pressure scram sensors, RED3C & RED3D were found to trip at lower than specified pressure values Caused by sensor repeatability ROSS,D A Jersey Central Power & Light Co 80/08/28 3pp
- 8009090353 Forwards LER 80-034/03L-0 RDSS,D A Jersey Central Power & Light Co 80/09/02 1p
- 8009140471 Forwards LER 80-035/03L-0 ROSS:D A Jersey Central Power & Light Co. 80/09/10 ip
- --8009160474 LER 80-035/03L-0 on 800914 during containment spray sys automatic actuation test, high drywell pressure switches IP-15A & IP-15D ripped at higher than specified setpoint of 2 psig Caused by instrument repeatability ROSS:D A Jersey Central Power & Light Co 80/09/10 3pp
- 8009230481 Forwards LER 80-036/03L-Q ROSS.D A Jersey Central Power & Light Co 80/09/15 1p
- ~8009230489 LER 80-036/03L-0. on 800815 & 16 stack releases were not continuously menitored due to failure of stack gas sample sys Caused by loose motor cooling fan on sample pump "B" Sample pump filter replaced & motor cooling fan tightened ROSS: D A Carolina Power & Light Co 80/09/15 3pp
- 3009260447 LER 90-037/03L-0 on 800Bi9 during standby gas treatment sys SOTS surveillance testing, SOTS 2 tripped Caused by misaligned welding lead run across tubing below duct Welding lead realigned & functionally tested ROSS. D A Jersey Central Power & Light Co 80/09/18 3pp
- 300404 Nonroutine Environ Operating Rept 80-7 on 800901.02 & 04, or individual dilution pump trips occurred during which operative or reserve pump could not be started within quired 15 minutes Caused by component failure NFROCK, I R Jersey Central Power & Light Co 80/09/19 2pp
- 300522 Forwards LER 80-039/03L-0 NFROCK, I.R Jersey Central Power & Light Co 80/09/25 3pp
- 09300528 LER 80-039/03L-0 on 800829, during low pressure main steam line functional test & calibr.RE238 & 23D pressure switches actuated at valve above Tech Spec limits Caused by instrument repeatability Switches reset to desired limit CROS8Y.P J Jersey Contral Power & Light Ca 80/09/26 lp
- 300541 LER 80-021 has been cancelled. Jersey Central Power & Light Co 80/09/25. 2pp

- 8009300564 Forwards LER 80-038/03L-0 FinfRDCK, 1 R Jorsey Central Power & Light Co 80/09/25 3pp
- --B009300569 LER 80-03B/03L-0 on B00B26 during surveillance testing of reactor triple low water level sensors REIBB tripped at level ises conservative than Tech Spec limits Caused by sensor repeatability Sensor reset within prescribed limits QUINTENZ.T E Jersey Central Power & Light Co 60/09/25 ip
- T Hearing transcripts on non-antitrust matters
- 8009030162 Transcript of 800822 hearing before NJ Dept of Energy, Board of Public Utils in Newark, NJ, re application for electric svc rate increase Pp 313-470

 * New Jersey, State of 80/08/22 158pp
- DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 80092301BA Requests that all personnel be reminded of purpose of emergency motification sys & health physics network Sys installed for govt use during emergency GRIER.O H Region 1. Philadelphia. Office of the Director 80/08/22 3pp
- 8009240515 Ack receipt of 800807 request for mod of fire protection implementation schedules Response amends App R rulemaking iPPOLITO.T A Operating Reactors Branch 2 80/09/15 2pp
- O Adjudicatory correspondence
- 8007220013 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101, PPOLITO.T A Operating Reactors Branch 2 80/08/27 2pp
- --8009220014 Order for mod of License DPR-63 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101
 EISENHUT, D O Division of Licensing 60/08/29 App
- P Operating license stage documents & correspondence
- 8009110554 Buppls NRC 800707 request for proposed Yech Specs changes rescram discharge vol vent & drain valves. & reactor protection sys & control rod block limit switch surveillance requirements Class Ill license fee to be submitted w/change EISENHUT.D O Division of Licensing 80/07/22 22pp
- 8009020297 Bubmits intorim critoria for shift staffing to all OL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative prayisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D 9 Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl 4/0 NUREG EISENHUT, D & Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D Q Division of Licensing 80/08/07 60pp
- 8009170389 Advises that two specific Event 5 valve configurations do not exist at facility per review of response to NRC 800223 ltr "Primary Coolant Sys Pressure Isolation Valves," technical systuation rept enc! IPPOLITO,T A Operating Reactors Branch 2 80/08/08 3pp
- --9009170402 "Primary Coolant Sys Pressure Isolation Valves," technica evaluation rept NDELL,P N , STILWELL,T C Franklin Institute/Franklin Research Center NRC-03-79-118 80/07/21 5pp
- 8009190758 Forwards NUREG-0661, "Mark I Containment Long-Term Program SER Resolution of Goneric Technical Activity A-7 " Rept discusset generic suppression pool hydrodynamic load definition W/o enci IPPOLITO.T A Operating Reactors Branch 2 80/08/20 2pp

- 8009190770 Summary of 80082i meeting w/util at plant site re crack in reactor aldg wall POLK-P J Operating Reactors Branch 2 80/08/26 App
- 8009180547 Advises that response to NRC 791109 ltr re ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture is acceptable No further action necessary 1PPDLITO.T A Operating Reactors Branch 2 80/09/05 2pp
- 8009240591 Ack receipt of 800628 ltr re util commitment to meet NUREG-0578 Charification ltr revising requirements & other TMIrelated problems was forwarded in NRC 800905 ltr Notifies of 800922 meeting to discuss TMI action plan IPPOLITO.T A Operating Reactors Branch 2 80/09/09 2pp
- 8009180340 Forwards application to amend License DPR-63, changing Tech Specs Sections 3 6,4 6 & 6 0 Fee encl THOMAS,E 8, LeBoeuf, Lamb, Leiby & MacRae 80/09/17 2pp
- --8009180344 Application to amend License DPR-43 changing Tech Specs Sections 3 6.4 6 & 6 0 re accident monitoring instrumentation 5 min shift crew composition DISE.D P. Niagara Mohawk Power Corp 80/09/16 2pp
- --8009180348 Proposed Tech Specs 3 6.4 6 5 6 0 re accident monitoring instrumentation & min shift crew composition Supporting info entl

 * Niegara Mohawk Power Corp 80/09/16 13pp
- 8009250403 Submits supplemental response to NRC 800620 ltr re plant shielding design review per NUREO-0378 Solenoids for air operated valves 201 2-03 & 201 2-32 in N-2 purge sys will be relocated Original proposal impractical DISE.D P Niegara Mohawk Power Corp 80/09/17 lp
- G Inspection reports, 1E Bulletins & correspondence
- 3009160240 Forwards IE Insp Rept 50-220/80-06 on 800623-27 No noncompliance noted MARTIN:N 0 Region 1: Philadelphia: Safeguards Branch 80/07/24
- --8009160242 IE Insp Rept 50-220/80-06 on 800623-27 No noncompliance noted Major areas inspected approved physical security plan, security program audit 5 security organization Details withheld (ref 100FR2 790)
 BAILEY,R J. Region 1, Philadelphia, Office of the Director DELVIN.J W Region 1, Philadelphia, Safeguards Branch 60/07/17
- 800922013B Forwards response to IE Bulletin 80-14. Items 1-6, re scram dump vol sys No instances of switch degradation identified Operating Procedure Ni-0P-5 revised to include logging requirement in case of valve inoperabllity LEMPOEB.TE Nlagara Mohawk Power Corp 80/07/25 3pp
- 8C09090668 Responds to IE Bulletin 80-16 Investigations determined no transmitters installed or to be installed u/specified output Codes A or D LEMPGES-T E Niegara Mohawk Power Corp 80/07/28 lp
- B009120263 Forwards response to IE Bullatin B0-17. Supp 1, re control rod scram sys, Item A Scram discharge vol sys w/associated vant & drain sys are believed to be reliable & adequate to ansure tafety, based on series of analyses Affidavit encl LEMPOES, T E Niagara Mohawk Power Corp B0/08/07 10pp
- 8009030099 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C+E " Written response required ... GRIER. B.H Region 1, Philadelphia, Office of the Director 80/08/15 19
- 8009160508 Describes proposed mod to scram discharge vol vent & drain sys in response to IE Bulletin 80-17. Suppl 1. Item B 1
 Dedicated vent & drain line will be utilized to svc scram discharge vol Detailed description to be sent by 800901
 LEMPGEB.T E Niegara Mohawk Power Corp 80/08/15 2pp
- BD09160513 Advises that based on B00814 telcon w/NRC, extension granted until B00905 for util to address IE Bulletin B0-15. Item 3 & submit written rept required by Item 6 LEMPGES.TE Niagara Mohawk Power Corp 80/08/15 1p
- 8009120097 Forwards Suppl 3 to 1E Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR " Written response required ORIER.B H Region 1, Philadelphia, Office of the Director 80/08/22 lp

- 8009180022 Forwards 1E Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GRIER, B H Region 1. Philadelphia, Office of the Director 80/08/22 ip
- 8009090281 Responds to 1E Bulletin 80-19. Revision 1. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Relays are not used at facility

 LEMPGES,T E Niagara Mohawk Power Corp 80/08/27 1p
- 8009120230 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover: 480 Volt Type K-6005 & K-DON 6005 Circuit Breakers" No written response required ORIER: H Region 1, Philadelphia. Office of the Director 80/08/27 lp
- B009300622 Responds to 1E Bulletin 80-19 No mercury-wetted relays installed at facility Eight manhours expended on bulletin LEMPGES:T E Niagara Mohawk Power Corp 80/08/27 19
- 8009090264 Responds to 1E Bulletin 80-17, Suppl 2. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR " Special Operating Procedures Ni-BOP-15, Malfunction of Control Drive Sys & Ni-DPS, Control Rod Drivetine Sys were revised LEMPGES,T E Niagara Mohawk Power Corp 80/08/29 Jpp
- 8009230495 Forwards Revision 1 to 16 Bulletin 79-26, "Boron Loss From Bulk Control Blades " Written response required ORIER.B H Region 1, Philadelphia, Office of the Director 80/08/29 1p
- 8009240346 Forwards IE Info Notice 80-32. "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls "No written response required GRIER.B H Region 1. Philadelphia, Office of the Director 80/09/12 ip
- R Periodic operating reports & related correspondence
- 8009160213 Forwards "Radioactive Effluent Release Semiannual Rept.Jan-June 1980 " ROMAN, W Niagara Mohawk Power Curp 80/08/29 [p
- --8009160214 "Radioactive Effluent Release Semiannual Rept.Jan-June 1980 " * Niagara Mohawk Power Corp 80/08/29 50pp
- 8009190297 Forwards monthly operating rept for Aug 1980 & narrative rept of operating experience for Aug 1980 & JuliAug.Sept & Oct 1979
 LEMPOES, T E Niagara Mohawk Power Corp 80/09/08 3pp
- --8009150299 Monthly operating rept for Aug 1980 ROMAN:T W Niagara Mohawk Power Corp 80/09/08 3pp
- 8009250331 Forwards corrected monthly operating rept for Aug 1980 LEMPGES.T E Niagara Mohawk Power Corp 80/09/17 1p
- --8009250332 Corrected monthly operating rept for Aug 1980
 * Niagara Mohawk Power Corp 80/09/17 lp
- S Reportable occurrences, LERs & related correspondence
- 8009160460 Forwards LER 80-016/03L-0 LEMPGES,T E Niagara Mohawk Power Corp 80/09/05 ip
- --8009160467 LER 80-016/03L-0 on 800809, during turbine anticapatory bypass reactor scram switches 02-138 & D surveillance setpoints found out of tolerance Caused by instrument drift Switches readjusted Monthly testing planned HARR150N.P Niagara Mohawk Power Corp 80/09/05 1p
- 6009150265 Forwards LER 80-018/03L-0 LEMPGEB.T E Niagara Mohawk Power Corp 80/09/08 1p
- --8009130264 LER 80-01B/03L-0 on 800808, during normal operation, emergency dissel generator 103 fuel oil day tank low level alarm was received Caused by inadvertent opening of day tank drain valve Tank refilled 011 valve sys locked HARR1SON.P Niagara Mohawk Power Corp 80/09/05 2pp

- 8009180268 Forwards LER 80-019/04T-0
 DARTLETT, J Hagara Mohawk Power Corp 80/09/10 in
- --8009180270 LER 80-019/04T-O on 800827.during NRC insp at normal operation.discovered removable bottom door seals of outer door of reactor bidg track bay were not installed properly Caused by personnel error
 HAPRISON.P Niagara Mohamk Power Corp 80/09/09 200
- 8009300491 Forwards LER 80-017/03L-0 LEMPGES.TE Niagara Mohawk Power Corp 80/09/18 tp
- --B009300495 LER B0-017/03L-0 on B00822 during normal operation, excessive outboard seal water loakage observed on Reactor Feedwater Pump [] Caused by normal seal degradation Maint performed & pump returned to svc HARR1501AP Niagara Hohawi Power Corp 80/09/19 1p

V Operator Examinations

- 8009120408 Forwards Administrative Procedures APN-10A & 10B.which document licensed operator training & retraining programs
 No ravision to training program is warranted
 DISE.D P Niagara Mohawk Power Corp 80/09/05 [p
- --8009120413 Administrative Procedura APN-LOA,Revision 2. "Training of Licensed Operator Candidates " ROMAN,T N . PERKINS,T J . BRYANT,W M. Niagara Mohawk Power Corp BO/05/07 5pp
- -8009120417 Administrative Protedure APN-100, Revision 2, "Licensed NRC Operator Retraining "
 ROMANTA W, PERKINS T J , BRYANTAW M Niagara Mohawk Power Corp 80/05/07 20pp

CME1 50-222 COLOMBIA RESEARCH REACTOR Inspection reports, to Bulletins & correspondence

O9120254 Responds to IE Bulletin 79-03A re iongitudinal weld defects in SA-312. Type 304 stainloss steel pipe SA-312 piping used at facility satisfies criteria Bys pressure-temp values lower than reduced allowable code NOVARRO. J P Long Island Lighting Co 80/08/04 2pp

CKET 50-223 UNIV OF LONELL RESEARCH REACTOR Inspection reports. iE Bulletins & correspondence

O9240242 Forwards 1E Info Notice 80-32. "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls" No written response required CRIER. B H Region 1. Philadelphia. Office of the Director

ERECUPITY, medical, emergency & fire protection plans

109020049 Forwards revised Page 15 of proposed security plan Plan withheld (ref 10CFN2 790)
KAPLAN.B N California, Univ of, Berkeley 80/08/25 2pp

Operating license stage documents & correspondence

- 1009020040 Application for changes to Amend 2 of License R-101.allowing possession of enriched U other than fuel elements, use of Puberylium sources for activities other than reactor operation & Tech Spec changes recentral rod drop times
 KAPLAN.5 N California, Univ of, Berkeley 80/08/07 3pp
- 8009180505 Forwards assessment of conservative assumptions in evaluation of DBA, in response to 800717 request re-Ofc of Policy Evaluation analysis Limiting dosa to thyroid probably conservative by at least three orders of magnitude DENION. HR Office of Nuclear Reactor Regulation, Director 80/09/13 6pp

DOCKET 50-225 API CRITICAL EXPERIMENT

- F Security, medical, emergency & fire protection plans
- 8009020012 Forwards critical experiments facility security plan Plan withheld (ref 10CFR2 790) Telcon w/P Trimble informed of shipment of excess SNM to Dak Ridge.TN NELBON.PR Rensselaer Polytechnic Inst 80/08/22 lp
- O Inspection reports, IE Bulletins & correspondence
- 8009240234 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls "No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/09/12 1p

DOCKET 50-227 TRICA THERMIONIC PROTOTYPE REACTOR

- P Operating license stage documents & correspondence
- 8009160583 Discusses projected fuel utilization for Tarapur reactors Current supply of fuel in India is adequate for four refuelings & would permit scheduled operation of TAPS II to Aug 1791 > TAPS I to Feb 1782 PETERSON

DOCKET 50-237 DREBDEN NUCLEAR POWER STATION, UNIT 2 F Security, medical, emergency & fire protection plans

- 8007230288 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Bys installed for govt use during emergency KEPPLER, J O Region 3. Chicago. Office of the Director BO/08/22 3pp
- 8007100378 Forwards review of util generating station emergency plan & draft ltr requesting addl info & commitments from util PAOANO.F O Emergency Preparedness Licensing Branch 60/08/28
- 8009120453 Notifies that Comm Ed does not wish to participate in proposed study re review of people-related problems in nuclear safeguards Responses would be misleading, reflecting inexperience & short-term problems

 ABEL. J S Commonwealth Edison Co 80/09/02 1p

G Adjudicatory correspondence

- 8009040200 Advises that, subsequent to discussions w/NRC & applicant, State of IL Second Amended Contentions 2, 3, 4, 5(B), 6, 7, & B are admissible Second Amended Contention 10 should be held until 801001 white security plan is reviewed by IL SEKULER.8 N 111inois, State of 80/08/27 2pp
- --8009040209 Notice of filing & svc of second amended contentions SEKULER, S. N., FAHNER, T.C. 111ingis, State of 80/08/27 2pp
- --B00904021B Second amended contentions alleging absence of demonstrated need for spent fuel pool storage expansion Claims inadequacy of monitoring equipment & inadequacy of assessment re rack corrosion Proof of svc encl
 SEKULER.S N , FAHNER.T C Illinois, State of B0/08/27 App.
- 8009110813 Memorandum & order rejecting State of IL 800827 Second Amended Contention 1 Directs util & NRC to respond to ASLB question re status of spent fuel storage capacity Ruiing on Second Amended Contention 10 held in abeyance until 801101.
 LIYTLE, L W . REMICK, F J . WOLF, J F Atomic Safety and Licensing Board Panel 80/09/09. Spp
- B009300007 Notice of appearance in spent fuel pool mod proceeding Cartificate of Byc encl
 BARTH, C A Hearing Branch 3 80/09/26 2pp
- 8007300045 Response to 800909 inquiry re applicability of Commission 730916 policy statement, "Intent to Prepare OEIS on Handling & Storage of Spent LWR Fuel " Not applicable due to issuance of GEIS in Aug 1779. Certificate of Svc encl GODDARD, R J Hearing Branch 2 80/09/26 Spp

1

H General correspondence

- 8009110218 Forwards response to 800728 ltr requesting assistance in answering constituent questions re nuclear power & effects of radiation DIRCKS, W J Office of the Executive Director for Operations 80/08/28 4pp
- P Operating license stage documents & correspondence
- 7910110018 Notification of 790918 meeting w/util in Bethesda.MD to discuss impact of free standing liquid requirements for solid waste
 LD.R Environmental Evaluation Branch (Pre 791030) 79/09/17 2pp
- B009i10954 Supple NRC B00707 request for proposed Tech Specs changes re scram discharge vol vent & drain valves, & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT.D O Division of Licensing 80/07/22 22pp
- 8009020297 Submits interim criteria for shift staffing to all GL & CP licensees & applicants.per NRC 800507 itr Discusses administrative provisions for smergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D O Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT, D G Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submitted should include proposed class of amend EISENHUT.D G Division of Licensing 80/08/07 60pp
- 8009020456 Forwards evaluation of util response to NRC 800223 request for info re primary coolant sys pressure isolation valves. Two specific Event 5 valve configurations do not exist at factlities.

 CRUICHFIELD, D. Operating Reactors Branch 5 80/08/12 3pp
- --8009020467 "Primary Coolant Sys Pressure Isolation Valves," technical evaluation rept NOELLP N, STILWELL,T C Franklin Institute/Franklin Research Center. NRC-03-79-118 80/07/21 5pp
- 8009120279 Forwards evaluation of SEP Topic V-l1 A. "Requirements for Isplation of High & Low Pressure Sys." to be used in integrated safety assessment May be revised to reflect as-bulkt conditions.design changes or NRC criteria mod GRUTCHFIELD.D Operating Reactors Branch 5 80/08/12 6pp
- 8007120281 Forwards evaluation of SEP Topic VIII-3 B, "DC Power Sys Bus Voltage Monitoring & Annunciation " Requests notification if as-built facility differs from licensing basis assumed in assessment GRUTCHFIELD.D Operating Reactors Branch 5 80/08/12 5pp
- 8009180060 Forwards evaluation of SEP Topic III-10A, "Thermal Overload Protection for Motors of Motor Operated Valves " Assessment may be revised to reflect as-built conditions, facility design changes or NRC criteria mod CRUTCHFIELD.D Operating Reactors Branch 5 80/08/12 6pp
- 9009180312 Forwards evaluation of SEP Topic VI-10 B, "Shared Engineered Bafety Features" Requests to be informed if as-built facility differs from licensing basis CRUTCHFIELD.D Operating Reactors Branch 5 80/08/12 18pp
- 8009190401 Confirms 800811 discussion re arranging 800821 meeting w/util in Chicago. IL re facility cooling lake dike seepage & remedial action to be taken KEPPLER.J O Region 3. Chicago, Office of the Director 80/08/15
- BOO9140214 Responds to BOO614 ltr re BEP Topic XV-14, "Radiological Consequences of Small Lines Carrying Primary Coolant Dutside Containment " Questions 1-4 addressed by encl table entitled, "Bmall Lines Penetrating Containment "

 JANECEK.R F. Commonwealth Edison Co 80/08/18 4pp
- 8009180252 Forwards NUREO-0661, "Mark I Containment Long-Term Program EER Resolution of Generic Technical Activity A-7" Rept discusses generic suppression pool hydrodynamic load definition W/o encl IPPOLITO.T A Operating Reactors Branch 2 80/08/20 2pp

- B009020105 Forwards NUTECH Rept COM-0708-03, "Evaluation of 18-inch Containment Isolation Valves for Dresden Station, Units 2 % 3 % Guad Cities Station, Units 1 & 2." in response to NRC 791022 & 23 itrs re containment vent & purgs valves JANFCEK, R F Commonwealth Edison Co 80/08/22 ip
- --B007020111 "Evaluation of 18-Inch Containment Isolation Valves for Dresden Station, Units 2 % 3 % Quad Cities Station, Units 1 % 2 "

 OERDER, D. A. DEARDORFF. P. E., MARTIN-J. B. Nuclear Technology, Inc. (Nutech) CCM-0708-03 B0/05/14 [16pp
- 8009050349 Forwards addl response re SEP environ qualification of electrical equipment, per NRC request JANECEK, R Commonwealth Edison Co 80/08/22 41pp
- 8009110746 Notification of 800916 meeting w/SEP owners group to discuss NRC initial review & recommendations for site-specific ground response spectra & owners group program plans for seismic functional qualification of Class IE equipment LEVIN.H A Division of Engineering 80/08/26 1p
- 8009120404 Forwards Attachments 1-5 to util 800630 ltr re facility electric distribution sys voltage adequacy Ltr inadvertently transmitted w/o attachments

 JANECEK, R F Commonwealth Edison Co 80/08/28 6pp
- 8009110250 Requires submittal of ATMS emergency operating procedure for NRC review Generic analysis should confirm ATMS mitigation capability described in Vol 3 of NUREO-O460 Commission will determine required mods 5 implementation schedules TEDESCO.R L Assistant Director for Licensing 80/08/29 3pp
- 8009240555 Forwards final critique of 800619 SEP exercise Critique discusses problem areas identified during exercise & presents corrective actions H/o critique DELQEORGE: LO Commonwealth Edison Co 80/08/29 ip
- 8009110376 Comments on NRC 800612 evaluation re SEP Topic V-5,RCPB Leakage Detection Info provided re air sampling sys,leak detection sys & reactor drain tank instrumentation Plant is in compliance w/Reg Quide 1 45

 JANECEK.R F Commonwealth Edison Co 80/09/02 2pp
- 8007070394 Forwards add1 info re min critical configuration in support of 800515 application to amend Licenses DRR-19, 25, 29 % 30, changing requirements for source range monitor count rates JANEGEK, R F Commonwealth Edison Co 80/09/03 Spp
- 8009180501 Forwards Amends 49,44,58 & 93 to Licenses DPR-19,DPR-25, DPR-27 & DPR-30, respectively, safety evaluation & notice of issuance & availability IPPOLITO, T A Operating Reactors Branch 2 80/09/08 2pp
- --8009180506 Amends 49.44.58 & 53 to Licenses DPR-19.DPR-29.DPR-29 & DPR-30.respectively.revising Tech Specs to allow count rate on source range monitor channels below 3 counts per second when there are two or less fuel assemblies in quadrant IPPOLITO.T A. Operating Reactors Dranch 4 80/09/08 22pp
- --8009180516 Safety evaluation supporting Amends 49,44.58 & 53 to Licenses DPR-19, DPR-25.DPR-29 & DPR-30, respectively * Office of Nuclear Reactor Regulation, Director 80/09/08 4pp
- --8009180526 Notice of issuance & availability of Amends 49,44,58 & 53 to Licenses DPR-19,DPR-25,DPR-29 & DPR-30,respectively IPPOLITO,T A Operating Reactors Branch 2 80/09/08 2pp
- 8009290143 Notification of 800926 meeting w/utils & Kerr-McGee Chemical Corp in Bethesda, MD to discuss review & recommendations for site specific ground response spectra & program plans for seismic functional qualification of Class IE equipment ALLISON, D P Systematic Evaluation Program Branch 80/09/08 3pp
- 8009240022 Notification of second rescheduling until 801003 for meeting w/SEP owners group & KMC. Inc to discuss NRC initial review of site-specific ground response spectra & util program for seismic functional qualification of Class IE equipment ALLISON, D P Systematic Evaluation Program Branch 80/09/10 3pp
- 8007230463 Forwards proposed Tech Spec changes re implementation of TMI Lessons Learned. Category A requirements, in response to NRC 800702 request Dresden Unit 1 Tech Spec changes will be submitted 90 days prior to scheduled startup JANECEK, R F Commonwealth Edison Co 80/09/18 3pp
- --8007230466 Proposed Tech Spec changes re implementation of TMI-2 Lessons Learned Category A items * Commonwealth Edison Co 80/09/10 29pp

- 8009280292 Requests add1 60-90 days for review to determine whether as-built facilities differ from basis in NRC assessment Add1 time would allow for reproduction, distribution & review methods to function properly

 JAMECEK, R F Commonwealth Edison Co 80/09/19 1p
- 8009260465 Forwards Inst of Nuclear Power Operations rept. "Evaluation of Dresden Nuclear Power Station"

 LEE. B Commonwealth Edison Co 80/09/23 tp
- --8007260468 "Evaluation of Dresden Nuclear Power Station "

 Institute of Nuclear Power Operations EA 80-01 H0/09/12
 40pp
- Q Inspection reports. IE Bulletins & correspondence
- 6009040517 Forwards IE Bulletin RO-07, Suppl 1, "BHR Jet Pump Assembly Failure " Response required KEPPLER, J O Region 3, Chicago, Office of the Director 60/05/14
- 8007040432 Provides addi response to 1E Bulletin 80~17 Results of analysis of ATM3 w/o recirculation jump trip encl Analyses required no deratings to remain below svc level C limit JANECEK.R F Commonwealth Edison Co 80/07/14 Spp
- 8009100143 Forwards IE Insp Repts 50-010/80-12, 50-237/80-12 & 30-239/80-14 on 800809-0703 No noncompliance noted HEISHMAILR F. Region G. Chicago, Reactor Operations Nuclear Support Branch 80/07/23 2pp
- --8009100148 IE Insp Repts 50-010/80-12,30-237/80-12 & 50-249/80-16 on 800&09-0703 Na noncompliance noted Hajor areas inspected operational safety verification & monthly maint & surveillance observations spessand, R L , BarkEr.J L , TONGUE, T M Region 3, Chicago, Office of the Director 80/07/23 App
- 8009020107 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASNE SA-312, Type 304 Stainless Steel Pipe " SA-312 pipe not present in operating plants Final confirmation from suppliers anticipated by 800915 re const plant piping sys NAUGHTON-N F Commonwealth Edison Co 20/08/07 2pp
- 8009170230 Forwards response to IE Bulletin 80-17. Suppl i. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR" Scram discharge vol piping. scram instrument vol piping & drain piping meet requirements re downward pitch PEOPLES. D. L. Commonwealth Edison Co. 80/08/07 App
- 8009030231 Forwards Revision 1 to 1E Bulletin 80~19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/08/15 lp
- 8009110945 Responds to IE Bulletin 80-08, "Eram of Containment Liner Penetration Welds," supplementing 800709 response Corrects Zion response re-rings used for field circumferential butt weld Reviews accuracy of other statements ABEL. J S Commonwealth Edison Cu 80/08/15 4pp
- 8009110562 Responds to Suppl i to IE Bulletin 80-17. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at EWR "
 Util will not have continuous SDV water level monitoring sys installed & Functional by 800901

 JANECEK.R F Commonwealth Edison Co 80/09/15 2pp
- 8009160581 Submits supplementary response to IE Bulletin 80-08. "Examination of Containment Liner Penetration Helds." correcting statement made in DL Peoples 800709 ltr Further review not necessary ABEL, J S Commonweelth Edison Co 80/08/15 4pp
- 5009260375 Forwards IE Insp Repts 50-010/80-13,50-237/80-14 & 50-249/80-18 on 800707-0801 & notice of vialation HEISHHAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/08/18 2pp
- --8009260379 Notice of violation from insp on 800707-0801, * Region 3, Chicago, Office of the Director 60/08/18 is
- --BD09260404 IE Insp Repts 50-010/60-13,50-237/80-14 & 50-249/80-18 on B00707-0801 Noncompliance noted failure of licensed operators to trop themselves cognitant of design changes BARKER.J L. STREETER.J F. SPESSARD.R L Region 3. Chicaga. Office of the Director 80/08/18 11p

- 8009090013 Submits addit response to IE Builetin 80-17. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at DHR "
 Procedures have been developed to monitor scram discharge yelfor residual water on daily basis
 JANECEK, R. F. Commonwealth Edison Co. 80/08/20 ip
- 8007150495 Forwards 1E Info Notice 80-30. "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain QE BHR Facilities " No specific action or response requested KEPPLER, J O Regson 3. Chicago, Office of the Director 60/08/20
- 8009120060 Forwards Suppl 3 to IE Bulletin 80-17. "Failure of Conirol Rods to Insert During Scram at BMR " Written response required KEPPLER. J O Region 3. Chicago, Office of the Director 80/08/22
- 8009180551 Forwards IE Circular 80-18. "10CFR50 59 Bafety Evaluation for Changes to Radwaste Treatment Bys " No written response required KEPFLER.J O Region 3. Chicago. Office of the Director 80/08/21
- 8009230094 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6005 & K-DON 6008 Circuit Breakers " No written response required KEPPLER, J O Region 3, Chicago, Diffice of the Director 80/08/28
- 6009170411 Forwards response to IE Bullstin 80-15 re possible loss of emergency notification sys w/loss of offsite power Review revealed inoperability of Dresden sys Investigation being conducted Operating Order 26-80 changed JANACEK, R F Commonwealth Edison Co 80/08/29 4pp
- 8009180466 Responds to IE Builetin 80-19 re failures of mercury-weited matrix relays in reactor protective sys Identified relays are not used in facility No action required Twenty-four manhours expended on review RAUSCH. T J Commonwealth Edison Co. 80/08/29 1p
- B009230470 Forwards Revision 1 to 1E Bulletin 79-24, "Boron Loss From BUR Control Blades " Written response required KEPPLER. J G Region 3. Chicago, Office of the Director 80/08/29 ib.
- 8009170421 Responds to JE Bulletin 80-17. Buppl 1. re failure of control rads to fully insurt during scram at BWR Vent sys will provide reliable source of air during draining. Bys will be steadily purged until mode installed

 JANECEK, R F Commonwealth Edison Co. 80/09/02 2pp
- 8009260109 Forwards response to IE Bulletin 80-17, Suppl 3, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BMR," Procedure at Dresden 2 & 3 changed to require immediate manual scram when air pressure reaches 60 psi RAUSCH, T J Communuealth Edison Co 80/09/02 4pp
- 8009290504 Responds to NRC 791213 request for add1 info in response to IE Bulletin 79-02. "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Expansion anchor test results show installation of anchors acceptable JANECEK.R F Commonwealth Edison Co. 80/09/05 17pp
- 8009240133 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required KEPPLER. J Q Region 3, Chicago. Office of the Director 80/09/10
- 8009300200 Forwards response to IE Builatin 80-20 No Mestinghouse Type N-2 control switches are used in safety-related sys at Dresden Ouad Cities & LaSalle County Responses for Zion & Byron are encl RAUSCH, T J Commonwealth Edison Co 80/09/15 App
- R Periodic operating reports & related correspondence
- 8007030456 Forwards semiannual rept of radioactive effluent discharges 1 solld radwaste, for Jan-June 1980 SCOTT.D J Commonwealth Edison Co 80/08/20 ip
- --8009030467 Semiannual rept of radioactive offluent discharges & solid radwasterfor Jan-June 1980 # Commonwealth Edison Co 60/08/20 15pp
- 80092307/3 Forwards monthly operating repts for Aug 1980 SCOTT, D J Commonwealth Edison Co 80/09/12 1p

- ~~8009230720 Monthly operating repts for Aug 1980 CIESZKIEWICZ.S Commonwealth Edison Co 80/09/03 iSpp
- S Reportable occurrences, LERs & related correspondence
- BO09030509 Forwards LER 80-028/03L-0 SCOTT.D J Commonwealth Edison Co 80/08/14 ip
- --B009030516 LER 80-028/03L-0 on B00727, during test of control rod driveline C-11. overtrayel alarm came up & rod position indication was lost Caused by detachment of inner filter Driveline C-11 will be replaced at next refueling autage HOLLAND.P Commonwealth Edison Co 80/08/15 ip
- 8007020381 Forwards LER 80-027/03L-0 SCOTT.D J Commonwealth Edison Co 80/08/18 1p
- --B009020388 LER BD-027/03L-0 on B00728, during normal operation, water found leaking from weld on instrument line off Rx water cleanup sys Gause by thermal cracking due to insufficient clearance on weld socket Weld partially ground out CIESZKIEWICZ, B Commonwealth Edison CO 80/08/18 ip
- 8009230676 Forwards LER 80-030/03L-0 SCOTT.D J Commonwealth Edison Co 80/09/15 ip
- --8009230487 LER 80-030/03L-0 on 800818,2A LPC1 pump mechanical seal leaked during torus cooling operations Caused by dirt between sealing surfaces Pump seal replaced & tested ZIRMAB,K Commonwealth Edison Co 80/09/15 2pp
- 8009300469 Forwards LER 80-031/03L-0 SCOTT.D J Commonwealth Edison Co 80/09/19 1p
- --B009300473 LER B0-031/03L-0 on B00827, diesel driven fire pump gverheated & unavailable for longer than 7-day limit Overheating caused by faulty cooling water heat exchanger Heat exchanger replaced Np further swidence of overheating KQRCHYNSKY, M Commonwealth Edison Co B0/09/19 ip
- 8009300472 Forwards LER 80-032/03L-0 SCOTT,D J Commonwealth Edison Co 80/09/25 1p
- --BO09300478 LER BO-032/03L-0 on S00829, during GA audit, discovered that dissel fuel tank tamples were not being taken on monthly basis Caused by lack of definition on surveillance sheet Sheets revised to include sampling frequency KORCHYNSKY.H Commonwealth Edison Co 80/09/19 1p
- T Hearing transcripts on non-antitrust matters
- 80091000B4 Transcript of 800819 prehearing conference in Chicago.iL Pp 1-72 * Atomic Safety and Licensing Doard Panel 80/08/19 75pp
- V Operator Examinations
- 8009300287 Forwards preliminary topical putlines of proposed modules on thermal hydraulics & core damage mitigation to be included in revised reactor operator training program per 800228 proquest NAUGHTON.W F Commonwealth Edison Co 80/09/15 7pp
- COCKET 50-243 DRECON STATE UNIV REBEARCH REACTOR

 F Security, medical, emergency & fire protection plans
- 8009300184 Bubmits info supporting amend to physical security plan Info withheld (ref 10CFR2 790) WANO,C H . SMITH.C V Ohio State Univ 80/09/19 4pp
- R Periodic operating reports & related correspondence
- 6009300192 Forwards "GR State Univ TRIGA Reactor Annual Rept" for Jul 1979-June 1980 MANG,C H Ohio State Univ 80/09/08 1p
- --BO09300197 "DR State Univ TRIOA Reactor Annual Rept" for Jul 1979-June 1980 ANGERSON, T V , JOHNSON, A G , BENNETT, S L Ohio State Univ 80/09/31 121pp

- DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8009190655 Forwards supplied 800214 ltm relyital area analysis results whilst of vital areas & equipment Requests review of security plan to assure adequate protection of vital areas & equipment Encl withheld (ref 100FR2 790) CRUTCHFIELD, D. Operating Reactors Granch 5 80/08/22 tp
- BOO9230196 Requests that ail personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency GRIER. BH Region I, Philadelphia, Office of the Director BO
- 8009160317 Forwards info re security plan Plan withheld (ref 10CFR2 790 WHITE, L D Rochester Oas & Eiectric Corp 80/09/10 2pp
- G Adjudicatory correspondence
- 8009300247 Forwards order for mod of license, requiring info to support environ qualification of safety-related electrical equipment Briefings were held w/all interested licensees during wt of 800717 CRUTCHFIELD, D Operating Reactors Branch 9 80/08/29 2pp
- --B009300251 Order for mod of License DPR-18, requiring anfo to support environ qualification of safety-related electrical equipment EISENHUT, D O Division of Licensing 80/08/29 App
- P Operating license stage documents & correspondence
- 8009170295 Forwards "Piping Btress Analysis Rept.RHR Bys.Section 250 "
 Analysis results & support loads reflect layout arrangement shown on enci Isometric C-381-354. Sheet i.Revision D Ang mods to layout of sys will warrant reanalysis of piping sys NOON.F Hestinghouse Electric Corp 80/07/18 1p
- --BO09170296 "Piping Stress Analysis Rept.RHR Sys, Section 250 " NO.C. MASSIE.W A. LOCEFF.F Westinghouse Electric Corp SDTAR-80-05-05 80/07/31 80pp
- 9009170298 Forwards "RE Ginna Nuclear Power Plant, Geismic Upgrading Program Piping Stress Analysis, Main Steam Sys, Section 200 " Minor design changes or const mods will generally not affect stress results & support recommendations NODN,F Westinghouse Electric Corp 90/07/18 2pp
- --B009170301 "RE Qinna Nuclear Power Plant Seismic Upgrading Program Piping Stress Analysis, Main Steam Bys, Section 200 " Main steam containment drawing enci MASSIE.W A. DREYER, E. P. LOCEFF, F. Westinghouse Electric Corp SDTAR-80-05-08 80/07/31 142pp
- 8007170312 Forwards "Piping Stress Analysis Rept.RHR Sys. Section 200 "
 Analysis results & support loads reflect layout arrangement shown in enci Isometric C-3B1-334, Sheet I.Revision D Any mods to layout will warrant rea
- ---S009170314 "Piping Stress Analysis Rept.RHR Sys.Section 200 " MASSIE,W A , No.C , LOCEFF.F Westinghouse Electric Corp SDTAR-80-05-03 80/07/31 138pp
- BO0902027 Submits interim criteria for shift staffing to all GL & CP iicansees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to de reviewed within 90 days EISENHUT.D O Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 enti H/o NUREG EISENHUT.D 0 Division of Licensing 80/08/01, 119pp
- 8007230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lassons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D O Division of Licensing 80/08/07 60pp.

- 8009190794 Forwards revised Westinghouse STS 3 9 8 2,3 9 10 & Bases 3/4 9 8 2 3/4 9 10 to require 23 ft of water over top of reactor gressure vessel flange during movement of fuel assemblies or control rock Written response required ROWAK.TH Assistant Director for Operating Reactors 80/08/15
- --8007490817 Revised Restinghouse STS 3 9 8 2.3 9 10 % Bases 3/4 9 8 % 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods

 # Assistant Director for Operating Reactors 80/06/23 2ipp
- 8009230757 Forwards current SEP Topics 3-10 A.6-7 C 1.6-7 F & 3-3 D Assessments compare facility w/current NRC licensing criteria Requests proposed Tech Spec change to prevent transfer of all four instrument buses to same source CRUICKFIELD.D Operating Reactors Branch 5 80/08/20 22pp
- 8009020026 Notifies that revised definition of "operable" should not be incorporated into Tech Spacs w/o adding corresponding action statements Revision may be deferred for incorporation w/further Tech Spac changes
 UHITE
- 8009110746 Natification of 800916 meeting w/BEP awners group to discuss NRC initial review & recommendations for site-specific ground response spectra & owners group program plans for setemic functional qualification of Class IE equipment LEVIN.H & Division of Engineering 80/08/26 ip
- 8007030474 Submits info confirming that util meets requirements for TMI Lessons Learned requirement. Item 2 i 8 b re increased range of radiation monitors Literature describing monitors encl for review WHITEL D Rochester Gas & Electric Corp 80/08/27 5pp
- B009030545 Discusses task action plan re asymmetric LOCA loads Specified repts support conclusion that under worst combination of loadings including SEE effects realistically postulates flaw will not cause guillotine breat WHIVE.L D Rochester Oas & Electric Corp 80/08/27 2pp
- 909030485 Submits info describing current status & schedules re anchorage & support of tafety-related electrical equipment HHITE.L D Rochester Gas & Electric Corp 80/08/28 2pp
- 19040413 Forwards application for amend to License BPR-18 consisting of changes to Tech Space for control rod misalignment centificate of svc encl
 FARONER S LeBourf, Lamb, Leiby & MacRae 80/09/03 4pp
- -8009040414 Application for amend to License DPR-18 consisting of Tech Specs changes re control rod misalignment BHITE.L D Rochester Cas & Electric Corp 80/08/29 2pp
- --8609040415 Revised Tech Specs 3 5,3.10 k 4 1 for control rod position indication sys ** Rochester Gas & Electric Corp ** 80/08/29. 17pp
- BO09090513 Responds to NRC BOOB11 request for info re generic review of degraded grid voltage All low-voltage, 125-volt ac Class IE buses are supplied from either uninterruptable power source or regulated 480/125-volt transformers.

 WHITE:L D Rochester Gas & Electric Corp B0/09/03 ip.
- -009090377 Forwards inservice pump & valve tasting program for Jan 1981 - Dec 1990.App C to QA manual WHITE: L D Rochester Cas & Electric Corp 80/09/04. ip.
 - 090903B2 Inservice pump & valve testing program for Jan 1981 Dec 990.App C to OA manual WDERSON,C R Rochester Qas & Electric Corp 80/09/02 28pp
- J90551 Advises that response to NRC 800702 ltr.requesting submittal license amend application incorporating model Fech Specs e THI Lessons Learned Category A Items will not be completed until late Oct 1980 WHITE.L D Rochester Gas & Electric Corp 80/09/05 ip
- 8005270143 Notification of 800926 meeting w/utils & Kerr-McOse Chemical Corp in Bethesde. MB to discuss review & recommendations for site specific ground response spectra & program plans for seismic functional qualification of Class IE equipment ALLISON. D P. Systematic Evaluation Program Spanch 80/09/08 Spp

- BOO9160539 Forwards stress repts for A RHR&B mainstream piping inside containment Analyses are part of seismic upgrade program & incorporate several proposed piping sys mods Analyses do not represent current as-built plant configuration W/encl UHITE.L D Rochester Gas & Electric Corp 80/09/09 ip
- 8009170303 Application for amend to License DPR-i8 adding requirements for undervoltage protection
 WillTE:L D Rochester Gas & Electric Corp 80/09/09 3pp
- --B009170394 Proposed Tech Spec Pages 3 5-4a & 4 1-7 replacing encl Pages 2 3-4 through 2 3-iO re undervoltage protection Submitted as Amend 14 to License DPR-18 Util safety evaluation encl Rochester Gas & Electric Corp
- B009260022 Notification of second rescheduling until 801003 for mesting w/SEP owners group & KMC. Inc to discuss NRC initial review of site-specific ground response spectra & util program for selsmic functional qualification of Class IE equipment ALLISON, DP Systematic Evaluation Program Branch 80/09/10 App
- B009300365 Forwards comments on NUREO-0696, "Functional Criteria for Emergency Response Facilities " Detailed criteria require revision to provide more effective & cost-effective sys WHITE,L D Rochester Gas & Electric Corp B0/09/19 13pp
- O Inspection reports, IE Bulletins & correspondence
- 8009160220 Forwards 1E Insp Rept 50-244/80-07 consisting of 800315 meeting in Untario.NY CRIER.8 H Region 1. Philadelphia, Office of the Director 80/07/25 2pp
- --8009160223 iE Insp Rept 50-244/80-07, consisting of 800518 meeting in Ontario.NY Areas addressed regulatory performance JOHNSDN,D F. KISTER.H B Region 1. Philadelphia, Office of the Birector 80/07/22 6pp
- 8009220326 Responds to IE Bulletin 80-16 re patential misapplication of pressure transmitters Rosemount 1191 & 1152 pressure transmitters not used or planned for use in safety-related areas SABDOCK, H Q Rochester Gas & Electric Corp 80/07/29 ip
- 8009110485 Suppls rasponse to 1E Bulletin 79-03A Lists fittings on safety-related stainless steel sys Calculated wall thickness based on 100% code allowable stress
 WHITE,L D Rochester Gas & Electric Corp 80/08/05 2pp
- B009030090 Forwards Revision i to iE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E " Hritten response required GRIER-B H Region i, Philadelphia, Office of the Director 80/08/15 ip
- 8009240186 Ack receipt of 800807 ltr informing NRC of steps taken to correct violations moted in 1E Insp Rept 30-244/80-06 SMITH.0 If Region i, Philadelphia, Fuel Facility & Materials Safety Branch 80/08/19 Ip
- --8009240192 Responds to NRC 800717 ltr re violations noted in IE Insp Rept 50-244/80-06. Corrective actions procedure established to obtain permission to deviate from radiation work permit WHITE, L. D. Rochester Gas & Electric Corp. 80/08/07 3pp
- ---8007240176 Forwards IE Insp Rept 50-244/80-06 on 800427-0502 & notice of violation SMITH.9 M Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/07/17 2pp
- --8009240200 Notice of violation from insp on 800429-0502
 Region i, Philadelphia, Office of the Director 80/07/14 ip
- --8007240205 IE Insp Rept 50-244/80-06 on 800427-0502 Noncompliance noted failure to follow radiation protection procedures in accordance w/Tech 8pec & 11 & intentionally handling contaminated math w/o protective gloves.

 KNAPP.P J Region i, Philadelphia, Fuel Facility & Materials Safaty Branch SERABIN, J A Region i, Philadelphia, Office of the Director 80/07/14 13pp
- 8009180050 Forwards IE Circular 80-i8. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required.
 GRIER, B. Region 1. Philadelphia. Office of the Director 80/08/22. 10

DOCKETED ITEMS

- 8007120243 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Soveri 480 Volt Type K-6005 & K-DON 6005 Circuit Breakers" No written response required ORIER, B H. Region i, Philadelphia, Office of the Director 80000 (27)
- 8009240048 Forwards IE Circular 80-21, "Regulation of Refueling Crews "No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/09/10 ip
- BO09170311 Submits info re steam generator insp program in response to NRC BC070B request Multifrequency eddy current exam will be performed on 100% of inlet tubes including first support plate intersection in A & B steam generators by B01101 WHITE/L D Rochester Gas & Electric Corp B0/09/12 ip
- 8009240361 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls "No written response required GRIER.8 H Region 1. Philadelphia. Office of the Director 80/09/12 ip
- A Periodic operating reports & related correspondence
- 8009180245 Forwards semiannual radioactive effluent rept for Jan-June 1980 MRITEL D Rochester Gas & Electric Corp. 80/08/29 10
- --8009180272 Semiannual radioactive effluent release rept for Jan-June 1980 * Rochester Gas & Electric Corp 80/08/29 5pp
- S Reportable occurrences, LERs & related correspondence
- 8009020346 Forwards updated LER 77-015/01X-1 WHITE.L D Rochester Gas & Electric Corp 80/08/25 1p
- --8007020351 Updated LER 79-015/01X-1 on 790724 during piping sys insp per IE Bulletin 79-14.found pipe supports not installed per Tech Spers Caused by lack of documented approvals for Field changes Fipe supports reworked to establish acceptability HUTTON.J C Rochester Gas & Electric Corp 80/08/25 lipp
- V Operator Examinations

11

- 8009090274 Forwards "Operator Requalification Program," Procedure A-102 14,Revision 3,in response to NRC 800328 1tr MHITE.L D Rochester Gas & Electric Corp 80/08/22 1p
- --8009050278 "Operator Requalification Program," Procedura A-102 14, Ravision 3 * Rochester Gas & Electric Corp. 80/05/21 14pp
- 8009020086 Forwards documentation of implementation of NRC 800828 suggestions re operator licensing requirements Shift manning requirements, resulting from TMI action plan, will be responded to in separate Itr WHITE/L D Rockester Gas & Ciectric Corp 80/08/25 4pp
- DOCKET 50-245 HILLSTONE NUCLEAR POWER STATION, UNIT 1

 F. Security, medical, emergency & fire protection plans
- BOO8280056 Notification of BOO817.20 & 22 workshops in Valley Forge, PA, Chicago, IL & Atlanta, GArrespectively, to solicit public comment re NUREQ-0696, "Functional Criteria for Emergency Response Facilities"
 GRIER: B H Region 1, Philadelphia, Office of the Director BO/08/11 2pp
- 8009230180 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency ORIER, BH Region I, Philadelphia, Office of the Director 80/08/22 Spp.
- P Operating license stage documents & correspondence
- 8009110554 Buppls NRC 800707 request for proposed Tech Specs changes reseram discharge vol yent & drain velves. & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT, D O Division of Cicensing 80/07/22 22pp

- 8009020157 Submits draft interim reliability evaluation program, P II re-procedure & schedule, evant tree guids & guids for selecting component failure rates per 800612 meeting concerns EISENMUT, D.G. Division of Licensing 80/0//25 Upp
- 8009020297 Submits interim criteria for shift staffing to all lift licensees & applicants, per NRC BOOSO7 lir Discusses administrative provisions for emergency & overtime while Development & implementation to be reviewed within 90 days EISENHUT, D.Q. Division of Licensing 80/07/41 /pp
- B009080080 Forwards draft NUREO 0696, "Functional Citteria for Emergency Response Facilities" Community inquested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/O NUREO EISENMUT. D G Division of Licensing 80/08/61 1140p
- 8009120709 Forwards agends of RODR21 meeting at util ofce to diess assessment of regulatory performance ORIER, B.H. Region I. Philadelphia. Office of the Director BO/08/04 2pp
- BOO9230052 Informs that exemption from fee re licenting actions associated w/ffil-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D.O. Division of Licensing 80/00F/0/ FORE
- BOQ9020311 Bubmits schedule for 5 months of interim reliability evaluation program annotated to highlight potential NRC participation Anticipated start date scheduled for 000915 EISERBUT, D. O. Division of Licensing 89/00/15 App
- 8009100454 Advises that myt meeting w/NRC in Berlin, CT has been rescheduled for 800914 Agenda encl ORIER, B. H. Region 1. Philadelphia. Office of the Birectur 80/08/20 2pp
- 8009240596 Forwards "Mark 1 Containment Long-Term Program ULR. Resolution of Generic Technical Activity A-7 " MURLO-0861 M70 encl CRUTCHFIELD, D. Operating Reactors Branch 4 180/08/20 Upp
- 8009020286 Submits info superseding 7912.11 & 100016 info re 1H1 2 Short-Term Lessons Learned implementation of Item 2 1 Ab. shielding design review mode COUNSIL-40 0, FEC.4F Torotheast Nuclear Energy Co. (subb of Northeast Utilities) 100/08/25 2pp
- 8009110746 Notification of 800916 meeting w/GLP numers years to de NRC initial review & recommendations for site specific ground response spectra & owners group program plans for selsmic functional qualification of Cless II, squipment LEVIN, H A Division of Engineering 100/00/26 by
- BOOPOSO378 Advises that util will not meet deading for implementa of NUREO-0578 requirements to emergency procedures to the training for accidents to transients INEC feedback needed COUNSIL-W O Connecticut Yankee Atumic Fover on COUNSIL-W O Northeast Nuclear Energy Co (subs of Northeast Vitilities) BO/08/28 200
- 8009:10245 Informs of discrepancies between facility to iterating bused in BEP Topic III-4: "Clectrical Penetrations of Hasikor Containment" Util concludes that subj penetrations must current requirements No design change blanned COUNSIL-NO. FEE. W.F. Northeast Nuclear Library Co. (subs. of Northeast Utilities). BO/08/27 Spp.
- 8009190434 Forwards add1 info re BBP Topic III-6 re setemts design review per NRC request Oversize encls include general arrangement drawings for burbine bidg-battery charger drawings & spece-switchgear panel & control rod driveline COUNSILW O, FEE.W F Northeast Ruclear Energy Co taubs of Northeast Utilities B0/09/02 22746
- 8009190670 Requests Class III fee for plant specific review of SRN O610 ltrs requesting relief from inservice tosp & testing program requirements Request involves consideration of single safety issue DIOGS, R M License Fee Management Branch 80/09/07 Ep
- 8007090636 Proposed amend to License DPR-21 incorporating enri fet Bpec changes to enable full core off-lad to be perferned during sweanth refueling outage. Heload 7 licensing submitted until be provided under separate cover Afficavit enci CDUNBIL, U. G., FEE, W.F. Northeast Nuclear Energy Co. (auba of BO/09/04 App.

- --809990642 Tech Spec changes for full core off-load re limiting condition for operation & surveillance requirements * Northeast Utilities 80/09/30 App
- 8009270143 Notification of 800926 meeting w/utils & Kerr-McGee Chemical Corp in Bethesda MD to discuss review & recommendations for site specific ground response spectra & program plans for seismic functional qualification of Class IE equipment ALLISON, D.P. Systematic Evaluation Program Branch 80/09/09 3pp
- 8009300297 Proposed amend to License DPR-21 for Reload 7 Supplemental changes will be provided by 800930 Related proprietary rept NEDE-20992-5p will be forwarded under separate cover Supporting documentation & proposed Tech Spec changes enci COUNSIL-N 0 Northeast Utilities 80/09/09 5pp
- ---80073G0302 "Supplemental Reload Licensing Submittal for Hillstone Unit | Reload 7 " * General Electric Co Y1003J01A09 80/05/30 19pp
- --- BD09300307 "LOCA Analysis Rept for Millstone Unit 1 Nuclear Power
 - Oenaral Electric Co NEDO-24085-1 R1 80/07/31 32pp
- --80093003i1 Proposed Tech Spec changes for Killstone 1.Reload 7 re max average planar linear heat generation rate limits * Northeast Utilities 80/09/09 100pp
- 8009240571 Forwards NEDE-20592-5P. "STR Bundle Submittal Hillstone 1 Segmented Test Rod Bundle." Suppl 5 Rept is app to Reload 7 license amend submitted on 800909 Rept aveilable in Central Files only CDUMBIL, H G COUNSIL, W G Northeast Nuclear Energy Co. (subs of Northeast Utilities) 80/09/10 3pp
- 8009260032 Notification of second rescheduling until 801003 for masting w/8EP numers group & KMC. Inc to discuss NRC initial review of site-specific ground response spectra & util program for sessmic functional qualification of Class IE equipment ALLISON.D P Systematic Evaluation Program Branch 80/09/10 3pp
- 209190427 Discusses reasons for inability to fully support NRC plans b schedules for interim reliability evaluation program input into contractor selection process should be permitted COUNSILH Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/09/12 2pp
- CO9180357 Forwards implementation status of Category B TMI-2 Lessons Learned requirements for each facility Schedules specifically identify items where requirement cannot be met or schedule is not feasible COUNSIL.W C Connecticut Yankee Atomic Power Co COUNSIL.W C Northeast Nuclear Energy Co (subs of Northeast Utilities) BO/09/15 43pp
- O09290351 Application for amend to Licenses DPR-61, DPR-21 & DPR-65, incorporating revisions to Tech Specs for RCS per TMI-related requirements Fee encl TOWNSIL.40 Connecticut Yankes Atomic Power Co COUNSIL.44 G lortheast Utilities 80/09/16 6pp
- 1009290367 Proposed revisions to Tech Specs & O for administrative
- Connecticut Yankes Atomic Power Co 78/12/08 4pp
-)09300239 Forwards "Millstone Nuclear Power Station,Unit i Inservice Insp & Testing Program for iO-yr Interval B01228-901228 " Program is based on existing inservice insp & testing rogram GUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast t(lities) COUNSIL.W O Northeast Utilities 80/09/18 2pp
- _009300245 "Millstone Nuclear Power Station Unit 1 Inservice Insp & Testing Program for 10-yr Interval.801228-901228 " Program is based on existing inservice insp & testing program.

 4 Northeast Nuclear Energy Co (subs of Northeast Utilities)
 80/09/3Q 70pp
- à Inspection reports. IE Bulletins & correspondence
- 8009090iii Forwards IR Builetin 80-07, Suppl 1, "BHR Jet Pump Assembly Failure " Response required.
 GRIER, B H Region 1, Philadelphia, Office of the Director 80/05/13 1p
- 8009150082 Forwards IE Insp Repts 50-249/80-10 % 50-336/80-07 on 800601-0705 No noncompliants noted BRUNNER.E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/07/14 2pp

- --8009190088 IE insp Repts 50-245/80-10 & 50-336/80-07 on 800601-0705
 No noncompliance noted Major areas inspected control room,
 accessable portions of Unit 1 reactor & intate bldgs.Unit 2
 enci & condensate polishing facility
 KEIMIO.R R Region 1. Philadelphia, Reactor Operations Nuclear
 Support Branch SHEDLOSKY.J T . ZIMMERNAN.R P Region 1,
 Philadelphia, Office of the Director 80/07/11 7pp
- 8009120197 Responds to IE Bulletin 80-14 re degradation of scram discharge vol capabilities No degradation instances found No vent or drain vaives failure identified Procedures re valve operability changed Surveillance for level switches revised COUNSIL-N 0 . FEE. W F Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/27 3pp
- 8009230749 Responds to 1E Duiletin 80-i6 re Rosemount pressure transmitters identified transmitters will be installed in facility Analysis shall identify erroneous indications No corrective actions required COUNSIL.N 0 , FEE.W F Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/31 3pp
- 8009090017 Responds to IE Bulletin 80-17, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BMR " Daily monitoring of scram discharge vol will continue until permanent continuous monitoring sys is operational COUNSIL, W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/08/07 4pp
- 8009150465 Discusses 800805 meeting w/util re physical protection program insp findings & forwards outline of corrective actions Encl withheld (ref 100FR2,790) ORIER, B H Region 1, Philadelphia, Office of the Director, 80/08/07 ip
- 800903008i Forwards Revision i to IE Bullatin 80-19, "Failures of Mencung-Watted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER.D H Region i, Philadelphia, Office of the Director 80/09/19 ip
- 8009120090 Forwards Suppl 3 to 1E Bulletin 80-17, "Failure of Control Rods to Insert During Scram at EWR " Written response required required GRIER.B H Region I. Philadelphia. Office of the Director BO/OB/22 ip
- 8009180017 Forwards 1E Circular 80~18, "10CFR50 59 Bafety Evaluations for Changes to Radwaste Treatment Bys " No written response required
 GRIER, B. H. Region i, Philadelphia, Office of the Director
 BO/08/22 ip
- 8009120190 Forwards IE Info Notice 80-31, "Maloperation of Qould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required CRIER,B H Region i, Philadelphia, Office of the Director 80/08/27 ip
- H009230519 Forwards Revision 1 to IE Bulletin 79-26, "Boron Loss From BWR Control Blades " Written response required ORIER,B M. Region 1, Philadelphia, Office of the Director 80/08/29 1p
- 8009230791 Forwards IE Circular 80-21, "Regulation of Refueling Crews " nv.ca.v/71 rouwares in tyrcular 80-21, "Regulation of Refuel No written response required GRIER.B H Region i, Philadelphia, Office of the Diractor 60/09/10 ip
- 8009240319 Forwards IE Info Notice 80-32, "Ciarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls "No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 60/09/12 ip
- 8009300239 Forwards "Millstone Nuclear Power Station, Unit 1 Inservice Insp & Testing Program for 10-yr Interval 801228-901228 " Program is based on existing inservice insp & testing program COUNSIL,W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W O Northeast Utilities 80/09/18 2pp
- --8009300245 "Milistone Nuclear Power Station,Unit i Inservice Insp & Testing Program for 10-yr Interval B01228-901228 " Program is based on existing Inservice insp & testing program * Northeast Nuclear Energy Co. (subs of Northeast Utilities) 80/09/30 70pp

R Periodic operating reports & related correspondence

- 8009020283 "Semiannual Radioactive Effluents Release Rept.Jan-June. 1980 " * Northeast Nuclear Energy Co (subs of Northeast Utilitles) 80/08/29 100pp
- 8009190456 Forwards monthly operating rept for Aug 1980 MRDCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Utlities) 80/09/08 1p
- --ECO9170439 Monthly operating rept for Aug 1980 HARRAN,O Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/09/03 7pp
- S Reportable occurrences, LERs & related correspondence
- B009020377 Forwards LER 80-012/03L-0 MRGCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Utllities) 80/08/22 lp
- --8009020383 LER 80-012/03L-0 on 800725,while performing routine surveillance, average power range monitor (APRM) channel 5 was reading iOX below Toch Spec Cause unstated APRM adjusted to proper value & observed to insure stable reading BIGIARELLI.M J Northeast Nuclear Energy Co (subs of Northeast Utilitles) 80/08/22 3pp

DOCKET 50-247 INDIAN POINT STATION, UNIT 2

- F Security, medical, emergency & fire protection plans
- 8009090884 Requests participation in NRC study of people-related problems in nuclear safeguards Request includes NRC visit to facility to interview security mgt personnel Confidentiality of info will be maintained during all phases of study VARQA/S A Operating Reactors Branch 1 80/08/14 2pp
- 8009230167 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network 8ys installed for govt use during emergency GRIER.B H Region 1, Philadeiphia, Office of the Director 80/08/22 3pp

G Adjudicatory correspondence

- 8009090337 Add1 response to FOIA request for TMI~2. "Startup Problem Rept" & intervenor Citizens Committee for Protection of Environ Proposed Findings of Fact & Conclusions of Law re Indian Point 2 Forwards intervenor filing FELTON.J M Division of Rules and Records 80/08/12 1p
- ---8009090342 Forwards nonproprietary version of intervenor.Citizons Committee for Protection of Environ proposed findings of fact & conclusions of law re facility Finding 15 & portions of Finding 5 deleted to protect public health & safety ROISMAN.A Z Berlin, Roisman & Kessier 72/02/08 ip
- --B009090363 Nonproprietary version of proposed findings of fact & conclusions of law re plant security Includes memorandum in support of questions certified to ASLE & suppl to reply brief.

 ROISMAN.A Z Citizens Committee for Protection of the Environment ROIBMAN.A Z Berlin, Roisman & Kessler 72/02/08 i55pp
- 8009220009 Forwards order raquiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 901101 VARGA-8 A Operating Reactors Branch 1 80/08/29 3pp
- --B009220011 Order for mod of License DPR-26 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment info should be submitted by 801101
 EISENHUT, D 0 Division of Licensing 80/08/29, 6pp
- BO09120394 Order granting extension until B00926 for Commission to review ALAB-436 & relayant portlons of ALAB-961 CHILK-S J Office of the Secretary of the Commission B0/09/10 1p
- 8007300320 Order granting extension until 801024 for Commission to review ALAB-436 & ALAB-561
 CHILK: B J Office of the Secretary of the Commission 80/07/26
 3pp

H General correspondence

- 800918044B Responds to 800319 itr requesting public debate re issues appropriate to evacuation of large population ctrs near plants
 DENION.H R Office of Nuclear Reactor Regulation. Director 80/04/21 | 388
- --8009180462 Requests public debate re issues appropriate to evacuation of large population ctrs near plants Expresses confidence in attempts by Commissioners to represent public concerns EMORY.K Affillation Unknown 80/03/19 ip

P Operating license stage documents & correspondence

- 8007300167 "Rept of Zion/Indian Point Study Vol 2," informal rept STEVENBON,M 0 Los Alamos Scientlfic Laboratory FIN A-7015 NUREG/CR-1411 V2 80/04/30 165pp Available at NTIS
- 8009020297 Submits interim criteria for shift starfing to ail CL & CP ilcensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & Implementation to be reviewed within 90 days EISENHUT.D @ Division of Licensing 80/07/31 7pp
- 8009030i74 Confirms 800723 teicon re meteorological sys for facility Another telephone line would be acceptable as Interim functional back-up communications link, but unacceptable as permanent solution Radio or satellite would be acceptable VAROA.S A Operating Reactors Branch i 80/07/31 2pp
- 8007080080 Forwards draft NUREG-0596. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-05496 encl W/o NUREG EISENHUT.D 6 Division of Licensing 80/08/01 i19pp
- G009230092 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D G Division of Licensing G0/OB/O7 60pp
- 8009190794 Forwards revised Westinghouse STS 3 9 8 2.3 9 10 & Bases 3/4 9 8 2/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control reds Written response required NDVAK.T M Assistant Director for Operating Reactors 80/09/15 ip
- --8009190817 Revised Westinghouse 8T6 3 9 8 2,3 9 10 & Mases 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control reds
 4 Assistant Director for Operating Reactors 80/06/23 21pp
- 8009100060 Forwards request for add1 info re LOPAR fuel VAROA, B A Operating Reactors Branch i 80/08/19 3p.
- 8009030616 Forwards "Profilometry of Steam Generator Tubes," describing R&D work leading to development of profilometry & summarling results of special examinations of Steam Generator 24 during 1979 refueling outage ZARAKAS,P Consolidated Edison Co of New York 80/08/20 lp
- --8009030618 "Profilometry of Steam Generator Tubes " 4 Consolidated Edison Co of New York 80/08/31 200pp
- 8007130517 Requests long-term solution to correct electrical override/ bypass problem KRC review determined that manual sys-level actuation features for containment isolation & spray will not function after automatic safety signals reset VAROA.8 A Operating Reactors Branch 1 80/08/20 3pp
- 8007030337 Discusses NRC 800227.0410.0611.0702.07 & 28 requests re changes to util Tech Specs Util will submit one package addressing all concerns by 801107 ZARAKAG.P Consolidated Edison Co of New York 80/08/26 ip
- 8007080327 Submits response to 60-day Interim Action Items C 5(2) & (3) re gas turbines improved maint & testing will be implemented includes schedule for completion of overail improvement program
 ZARAKAS.P Consolidated Edison Co of New York 80/08/27 2pp

- 8009030458 Responds to NRC 800721 request for info re fracture—toughness design of steam generator & reactor coolant pump supports at facility Westinghouse advises that required response uili not be available until 810301 2ARAKAS.P Consolidated Edison Co. of New York 80/08/28 ip
- 8009300631 Forwards Amend 62 to License DPR-26, safety evaluation & notice of issuance & availability
 VAROA S A Operating Reactors Branch i 80/08/28 2pp
- --8009100538 Amend 62 to License DPR-26, reducing number of snubbers required by Tech Specs, reflecting reducing of support sys of certain safety-related pipe lines VARGA.S A Operating Reactors Branch 1 80/08/28 19pp
- --8009100645 Notice of issuance & availability of Amend 62 to License DRR-26 NEIGHBORS, J D Operating Reactors Branch 1 80/08/28 2pp
- 8009190134 Forwards Amend 63 to License DPR-26, safety evaluation & notice or issuance & availability
 EISERMUT.D C Division of Licensing 80/08/28 3pp
- --B009190140 Amend 63 to License DPR-26, vevising Tech Specs se primary containment leakage testing E1SENHUILD 0 Dirision of Licensing 80/08/28 32pp
- ~-8009190143 Safety evaluation supporting Amend 63 to License DPR-26 → Division of Licensing 80/08/29 4pp
- 80090903B3 Forwards "Rept on Evaluation of Thermal Piume Studies of Indian Point Nuclear Generating Station " Objectives of thermal plume program have been fulfilled Rept available in Central Files only ZARAKAS.P Consolidated Edison Co of New York 80/08/29 ip
- 109090484 Provides status of valve qualification program for ontainment purge & pressure relief isolation valves equested by NRC 800902 ltr % of evaluation of SRP & 2 4, evision 1 issues Response will be provided by 810105 ARAKAS,P Consolidated Edison Co of New York 80/08/29
- P120042 Confirms util commitment to staff 791023 interim position on ontainment purging & venting ARGA-8 A Licensing Branch 1 80/08/29 2pp
- .09120502 "Rept of Zion/Indian Point Study," Vol i MURFIN.W B Sandia Laboratories FIN A-1218 NUREO/CR-1410 Vi 80/08/31 400pp
- 8009120626 "Task Force Rept on interim Operation of indian Point " BERNERO,R M , BLOND,R M , PRITCHARD,H C Office of Policy Evaluations RUREG-0715 80/08/31 78pp Available at NTIS \$3.75
- 1009090505 Forwards table outlining effects of combining SSE & LOCA responses in analysis of Unit 2 RCS for postulated LOCAs.in response to NRC 800731 ltr ZARAKAS.P Consolidated Edison Co of New York 80/09/03 3pp
- 09180144 Discusses two risk studies currently underway Preliminary assessment of Indian Point risk profile contained in SECY 80-283 Zion risk profile assessment will combine accident sequence evaluation & containment failure analysis ERNSTIM L. Assistant Director for Technology Review 80/09/11
 - 230451 Forwards corrected response to Question 4 to 800720 ltr backfitting of severe accident mitigation features YURL J P Power Authority of the State of New York nsolidated Edison Co of New York 80/09/16 Jpp
- 250266 Forwards current training course outlines re heat transfer, id flow & thermodynamics, in response to NRC 800328 ltr ARAS.P Consolidated Edison Co of New York 80/09/19 30pp
- OCCSA Forwards response to 800820 itr re manual systemal nation features for containment isolation \$\psi\$ containment and Discusses proposed mod to containment ventilation lation circuitry

 AKAS.P. Consolidated Edison Co. of New York 80/09/22 2pp

- 8009300481 Notifies of planned change to Tech Spec 4 2 .item 7 2 re surveillance specimen removal schedule Change would provide better data to evaluate effects of radiation on reactor vessel Amend application will be filed shortly ZARAKAS,P Consolidated Edison Co of New York 80/09/24 1p
- Q inspection reports. IE Bulletins & correspondence
- 8009120195 Forwards IE Insp Rept 50-247/80-01 on 800203-0329 No noncompilance noted BRUNNER, E.J. Region I. Philadeiphia, Reactor Operations Nuclear Support Branch 80/07/08 2pp
- --B009120210 IE Insp Rept 50-247/80-01 on 800203-0329 No noncompliance noted Major areas inspected physical security, minor seismic event, turbine rotor disc insp & plant tour KISTER, H Region 1. Philadelphia, Resctor Operations Nuclear Bupport Branch REBELOUSKI.T Region 1. Philadelphia, Office of the Director 80/07/07 10pp
- B009100847 Forwards IE insp Rept 50-247/80-04 t on B00330-0510 No noncompliance noted BRUNNER,E J Region i, Philadelphia. Reactor Operations Nuclear Support Branch B0/07/18 2pp
- --8009103833 IE insp Rept 50-247/80-04 on 800330-05i0 No noncompliance noted Major areas inspected safety injection pump functional testscheduled emergency drill & selected aspects of physical security plans & procedures REBELOWSKI.T Region i. Philadelphia, Office of the Director KISTER.N Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/07/13 169
- 8007070242 Responds to IE Bulletin 80-16 Unit 2 has no specified transmitters installed Unit 1 shut down since 741031 & in defueled condition ZARAKAS.P Consolidated Edison Co of New York 80/07/30 2pp
- 8007120187 Responds to 1E Bulletin 79-03A re iongitudinal weld defects in SA-312 or A-312 Type 300 stainless steel piping Unit i is in defueled condition Unit 2 piping satisfies criteria re allowable stress ZARAKASIP Consolidated Edison Co of New York 80/08/06 2pp
- 8009030073 Forwards Revision 1 to iE Bulletin 80-i9. "Failures of Mercury-Netted Matrix Rolays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Hritten response required GRIER.B H Region 1. Philadeiphia. Office of the Director 80/08/15 ip
- 8009i80339 Forwards IE Circular 80-i8. "iOCFR50 59 Safety Evaluations for Changes to Radwaste Treatment Bys " No written response required GRIER.D H Region I, Philadelphia, Office of the Director 80/08/22 ip
- 8009120171 Forwards IE info Notice 80-31, "Maloperation of Govid-Brown Boveri 480 Volt Type K-6008 & K-DDN 6008 Circuit Breakers " No written response required CRIER,8 H Region 1, Philadelphia, Office of the Director 80/08/27 ip
- 8007090423 Responds to IE Bulletin 80-i5, "Possible Loss of Emergency Notification Sys W/Loss of Offsite Power" insp revealed loss of emergency notification sys on 800602 due to poor motor generator brush contact ZARAXAS,P Consulidated Edison Co of New York 80/09/02 2pp
- 8009230778 Forwards IE Circular 80-21, "Regulation of Refueiing Crews"
 No written response required
 GRIER, 8 H Region 1, Philadelphia, Office of the Director
 80/09/10 1p
- B009240304 Forwards IE 1nfo Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required CRIER.8 H Region 1, Philadeiphia, Office of the Director B0/09/12 ip
- R Periodic operating reports & related correspondence
- 8009030382 Forwards "Effluent & Waste Disposal Semiannual Rept. Jan-June 1980 " ZARAKAS, P Gonsolidated Edison Co of New York 80/08/29 ip
- ---8007030384 "Effluent & Waste Disposal Semiannual Rept, Jan-June 1980."
 * Consolidated Edison Co of New York 80/08/29 43pp

- 8009230432 Forwards daily record of fish collections for Aug 1980, including dally species breakdown & total weight Unit 2 & 3 circulators were run for entire month Unit 1 circulators were run on 800808, 10, 13, 17, 19, 21, 23, 30 & 31 ZARAKAS,P Consolidated Edison Co of New York 80/09/15 lp
- --8009230433 Daily record of fish collections from intake screens for Aug 1980 & Consolidated Edison Co. of New York 80/09/13 5pp
- 8009230568 Forwards monthly operating rept for Aug 1980 ZARAXAB:P Consolidated Edison Co of New York 80/09/15 1p
- --8009230571 Monthly operating rept for Aug 1980 EICH.E Consolidated Edison Co of New York 80/09/11 7pp
- 8009240452 Forwards quarterly rept on "Seismic Monitoring Network in Vicinity of Indian Point NY.Consolidated Edison Project, Mar-May 1980 " ZARAKAS:P Consolidated Edison Co of New York 80/09/15 ip
- --8009240455 "Beismic Monitoring Network in Vicinity of Indian Point,NY, Consolidated Edison Project:Mar-May 1980 " * Woodward-Clyde Consultants, Inc 80/08/15 44pp
- S Reportable occurrences. LERs & related correspondence
- 6005140025 PNS-I-80-003 on 800321.local telephone company received bomb threat re facility from unidentified male caller Search was conducted but no bomb was found Threat was repeated on 800321 but no bomb was found * Region 1. Philadelphia. Office of the Director 80/03/24 lp
- BOO9030610 RD on BOOB04, circulating water sys discharge temp exceeded Tech Specs limit Caused by high ambient river temps, high discharge temps & broken circulating water pump Demand load & discharge temp reduced ZARAKAS,P Consolidated Edison Co of New York 80/08/28 2pp
- 8009120353 Forwards LER 80-006/99X-1 ZARAKA9:P Consolidated Edison Co of New York 80/09/05 ip
- --8009120381 LER 80-006/99X-1 on 800603.during normal plant operation. all offsite electrical power was lost to site Caused by lightning strike on sys trensmission tower Faulted conditions were cleared & normal svc restored MAKEFEACE.J M Consolidated Edison Co of New York 80/09/05 23pp
- 8009160365 Forwards LER 80-009/03L-0 ZARAKAB,P Consolidated Edison Co of New York 80/09/10 !p
- ---8009160369 LER 80-009/03L-0 on 800810, following manual plant shutdown, spurious safety injection signal caused startup of three amergency diseal generators Caused by premature operation of series overcurrent tripping device Device replaced MAKEPEACE, J M Consolidated Edison Co of New York 80/09/10 2pp.
- 8009300324 Forwards LER 80-010/04X-0 ZARAKAS,P Consolidated Edison Co of New York 80/09/22 lp
- ---E009300530 LER E0-010/04X-O on B00910, green vegetable sample from unit vicinity demonstrated radioactivity in excess of area historic levels Cause not determined Assures that corrective action will be taken upon discovery of cause Cansolidated Edison Co of New York 80/09/19 3pp
- DOCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3

 F Security, medical, emergency & fire protection plans
- 8009230288 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/22 3pp
- 8009100378 Forwards review of util generating station emergency plan & draft ltr requesting addl info & commitments from util PAGANO,F 0 Emergency Preparedness Licensing Branch 80/08/28 500

- 8009120453 Notifies that Comm Ed does not wish to participate in proposed study re review of people-related problems in nuclear safeguards Responses would be misleading reflecting inesperience & short-term problems
 ABELJ 8 Commonwealth Edison Co 80/09/02 lp
- G Adjudicatory correspondence
- 8009040200 Advises that subsequent to discussions w/NRC \$ applicant. State of IL Second Amended Contentions 2,3,4,5(B),6.7, & B are admissible Second Amended Contention 10 should be held until 80(00) while security plan is reviewed by IL SEKULER.8 N 1111nois, State of 80/08/27 2pp
- --8009040208 Notice of filing & svc of second amended contentions SEKULER.S N , FAHNER.T C Illinois. State of 80/08/27 2pp
- --9009040218 Second amended contentions alleging absence of demonstrated need for spent fuel pool storage expansion Claims inadequacy of monitoring equipment b inadequacy of assessment re rack corrosium Prout of sex encl
 SEKULER.S N . FANNER.T C Illinois, Stato of GO/08/27 App
- 8009220015 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801[0] IPFOLITO.T A Operating Reactors Branch 2 80/08/29 2pp
- --8009220017 Drder for mod of Licenses DPR-29 & DPR-30 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment info should be submitted by 801101
 EISENHULD Q Division of Licensing 80/08/27 6pp
- 8009110813 Memorandum & order rejecting State of IL 800827 Second Amended Contention 1 Directs util & NRC to respond to ASLB question re status of spent fuel storage capacity Ruling on Second Amended Contention 10 held in abeyance until 801101 LITTLE.L W. REMICK.F J. WOLF.JF Atomic Safety and Licensing Board Panel 80/09/09 Spp
- 8009300603 Farwards 800919 order revising 800929 order for mad of DLs. In entirety EISERHUT,D O Division of Licensing 80/09/19 2pp
- --E009300614 Order revising 800829 order for mod of OLs OPR-29 & DPR-30, published in 800912 FR. in entirety Info re IE Dulletin 79-018 shall be filed by 801101 Request for hearing will not stay order effective 800919 UCS petitions discharged EISENHUT, D O Division of Licensing 80/09/19 app
- --8009300619 Order revising 800829 order for mod of OL DPR-25, published in 800912 FR, in entirety info responsive to IE Bulletin 79-018 shall be submitted by 801101 Request for hearing will not stay order effective 800919 UCS petitions discharged EISENHUT, D O Division of Licensing 80/09/19 App
- 8009300007 Notice of appearance in spent fuel pool mod proceeding Certificate of Svc encl BARTH.C A Hearing Branch 3 80/09/26 2pp
- 8009300049 Response to 800909 inquiry re applicability of Commission 750916 policy statement, "Intent to Propare OEI8 on Handling & Storage of Spent LMR Fuel " Not applicable due to issuance of GEI8 in Aug 1979 Certificate of Byc encl OODDARD, R J Hearing Branch 2 80/09/26 5pp
- P Operating license stage documents & correspondence
- 8007110354 Buppis NRC 800707 request for proposed Tech Spece changes re scram discharge vol vent & drain valves. & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted wichange EISENHUT.D 0 Division of Licensing 80/07/22 22pp
- 8009020297 Submits interim criteria for shift staffing to all OL & CP licensers & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENMUT, D O Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREO EISENHUT.D O Division of Licensing 80/08/01 149pp

- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT. B O Division of Licensing 80/08/07 60pp
- 6009020456 Forwards evaluation of util response to NRC 800223 request for info re primary coolant sys pressure isolation valves. Two specific Event 5 valve configurations do not exist at facilities. CRUCHFIELD, D. Operating Reactors Branch 5 80/08/12 3pp
- --8009020470 "Primary Coolant Sys Pressure Isolation Valves." technical evaluation rept PUELL.P N. STILMELL.T C Franklin Institute/Franklin Research Center NRC-03-79-118 80/07/21 4pp
- 8009150401 Confirms 800811 discussion re arranging 800821 meeting wouth in Chicago. It re facility cooling lake dike seepage 5 remedial action to be taken XEPPLER. J O Region 3. Chicago. Office of the Director 60/08/15
- 8009180252 Forwards NUREG-0661, "Mark I Containment Long-Term Program SER Resolution of Generic Technical Activity A-7 " Rept discusses generic suppression pool hydrodynamic load definition W/o encl [PPOLITO,T A Operating Reactors Branch 2 80/08/20 2pp
- 8009020105 Forwards NUTECH Rept CCM-0708-03. "Evaluation of 18-1nch Containment Isolation Valves for Dresden Station.Units 2 \$ 3 \$ Quad Cities Station.Units 1 & 2." in response to NRC 791022 \$ 23 16rs re containment vent \$ purge valves JANFCEX.R F Commonwealth Edison Co 80/08/22 1p
- --8009020111 "Evaluation of 18-Inch Containment Isolation Valves for Dresden Station,Units 2 & 3 & Ouad Cities Station,Units 1 & 2 " GERBER, D. A. DEARDDRFF, P. E. MARTIN, J. D. Nuclear Technology, Inc (Nutech) COM-0708-03 80/05/14 116pp
- PO09120404 Forwards Attachments 1-5 to util 800630 ltr re facility electric distribution sys voltage adequacy Ltr advertently transmitted w/o attachments NECEK.R F Commonwealth Edison Co 80/08/28 6pp
 - 10250 Requires submittal of ATMS emergency operating procedure for review Generic analysis should confirm ATMS mitigation ability described in Vol 3 of NUREG-0460 Commission will emmine required mods & implementation schedules ESCO.R L Assistant Director for Licensing 80/08/29 3pp
 - 240555 Forwards final critique of 800619 BEP exercise Critique scusses problem areas identified during exercise & esents corrective actions W/o critique . LGEDROELL D Commonwealth Edison Co 80/08/29 1p
 -)9090394 Forwards add1 info re min critical configuration in support of 800515 application to amend Licenses DPR-19.25.29 & 30, changing requirements for source range monitor count rates JANECEK, RF Commonwealth Edison Co
- 109180501 Forwards Amends 49,44,58 & 53 to Licenses DPR-19,DPR-25, 1PR-29 & DPR-30,respectively,safety evaluation & notice of ssuance & availability PDL110.T A Operating Reactors Branch 2 80/09/08 2pp
 - D9180506 Amends 49, 44,58 & 53 to Licenses DPR-19.DPR-25, DPR-29 & DPR-30, respectively, revising Tech Specs to allow count rate on source range monitor channels below 3 counts per second when there are two or less fuel assembles in quadrant PPPOLITO.T A Operating Reactors Branch 4 80/09/08 22pp
 - 180516 Safety evaluation supporting Amends 49.44,58 & 53 to enses DPR-19.DPR-25.DPR-29 & DPR-30.respectively Office of Nuclear Reactor Regulation, Director 80/09/08 4pp
 - 0926 Notice of (ssuance & availability of Amends 49,44,58 & 53 to uses DPR-19,DPR-25,DPR-29 & DPR-30,respectively 110,T A Operating Reactors Branch 2 80/09/08 2pp
 - 3 Forwards proposed Tech Spec changes re implementation of TMI Learned Category A requirements in response to NRC equest Dresden Unit i Tech Spec changes will be d 90 days prior to scheduled startup R F Commonwealth Edison Co 80/09/18 3pp
 - r Proposed Tech Spec changes re implementation of THI-2 Learned Category A items invealth Edison Co 80/09/10 27pp

- 8009250292 Requests addl 60-90 days for review to determine whether as-built facilities differ from basis in NRC assessment Addl time would allow for reproduction distribution & review methods to function properly

 JANFCEK,R F Commonwealth Edison Co 80/09/19 1p
- 8009260465 Forwards Inst of Nuclear Power Operations rept, "Evaluation of Dresden Nuclear Power Station"

 LEE,B Commonwealth Edison Co 80/09/23 1p
- --8007260468 "Evaluation of Dresden Nuclear Power Station "

 * Institute of Nuclear Power Operations EA 80-01 80/09/12
 40pp
- G Inspection reports: IE Builetins & correspondence
- 8009040517 Forwards IE Bulletin 80-07. Suppl 1. "BWR Jet Pump Assembly Failure " Response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/05/14
- 8007040632 Provides addl response to 1E Bulletin 80-17 Results of analysis of ATWS w/o recirculation pump trip encl Analyses raquired no deratings to remain below svc level C limit JANECEK,R F Commonwealth Edison Co 80/07/14 6pp
- B009100143 Forwards IE Insp Ropts 50-010/B0-12.50-237/B0-12 & 50-219/B0-16 on B00609-0703 No noncompliance noted HEISHMAN,R F Region 3. Chicago. Reactor Operations Nuclear Support Branch B0/07/23 2pp
- --8009100148 lE Insp Repts 50-010/80-12.50-237/80-12 & 50-249/80-16 on 800607-0703 No noncompliance noted Major areas inspected operational safety verification & monthly maint & surveillance observations SPESSARD, R L., BARKER, J L., TONGUE, T M. Region 3, Chicago, Office of the Director. 80/07/23 4pp
- 8009020109 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steol Pipe " 8A-312 pipe not present in operating plants Final confirmation from suppliers anticipated by 800915 re const plant piping sys NAUOHTON, W F Commonwealth Edison Co 80/08/07 2pp
- 8009170230 Forwards response to IE Bulletin 80-17. Suppl t. "Failure of 74 of 185 Control Rods to Fully Insert During Scram at BWR" Scram discharge vol piping. scram instrument vol piping & drain piping meet roquirements re dounward pitch PEOPLES. D. L. Commonwealth Edison Co. 80/08/07 4pp
- 8009030231 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER. J & Region 3, Chicago, Office of the Director 80/08/15
- 8009ti0545 Responds to IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds," supplementing 800709 response Corrects Zion response re rings used for field circumferential butt weld. Reviews accuracy of other statements ABEL.JS Commonwealth Edison Co 80/08/15 4pp
- 8009110562 Responds to Suppl 1 to IE Bulletin 80-17. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR "
 Util will not have continuous SDV water level monitoring sys installed & functional by 800901

 JANECEK, R F Commonwealth Edison Co 80/08/15 2pp
- 8009160681 Submits supplementary response to IE Bulletin 80-08, "Examination of Containment Liner Penetration Helds," correcting statement made in DL Peoples 800709 ltr Further review not specessary ABEL.J S Commonwealth Edison Co 80/08/15 App
- 8009260395 Forwards IE Insp Repts 50-010/80-13,50-237/80-14 & 30-249/80-18 on 800707-0801 & notice of violation HEISHMANLR F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/08/18 2pp
- ---8007260377 Notice of violation from insp on 800707-0801
 * Region 3, Chicago, Office of the Director 80/08/18 ip
- --8009260404 IE Insp Repts 50-010/80-13.50-237/80-14 & 50-249/80-18 on 800707-0801 Noncompliance noted failure of licensed operators to keep themselves cognitant of design changes BARKER, J E. STRESTER, J F. SPESSARD, R L Region 3. Chicago, Office of the Director 80/08/18 11pp

ì

- 8009090013 Submits add) response to IE Bulletin B0-17. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BHR" Procedures have been devaloped to monitor scram discharge vol for residual water on daily basis

 JANECEK.R F Commonwealth Edison Co 80/08/20 1p
- BOO9150495 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE BWR Facilities "No specific action or response requested Region 3. Chicago, Office of the Director BO/08/20
- 8009120060 Forwards Suppl 3 to IE Bulletin 80-17. "Failure of Control Rods to Insert During Scram at BWR " Written response required KEPPLER.J 0 Region 3. Chicago. Office of the Director 80/08/22
- BO09180551 Forwards IE Circular 80-18, "10CFR80 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response ranulred
 - KEPPLER, J G Region 3. Chicago, Office of the Director 80/08/22
- 8009230094 Forwards 1E Info Notice 80-31, "Malaperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers" No written response required KEPPLER.J O Region 3. Chicago, Office of the Director 80/08/28
- 80091704(1 Forwards response to IE Bulletin 80-15 re possible loss of emergency notification sys w/loss of offsite power Review revealed inoperability of Dresden sys Investigation being conducted Operating Order 26-80 changed JANACEK.R F Commonwealth Edison Co 80/08/29 4pp
- 8009180466 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys identified relays are not used in facility No action required Twenty-four manhours expended on review RAUSCHIT / Commonwealth Edison Co 80/08/27 lp
- 8009230478 Forwards Revision 1 to IE Bulletin 79-26, "Boron Loss From BWR Control Blades " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/29
- BOO9170421 Responds to IE Bulletin 80-17. Suppl 1. re failure of control rods to fully insert during scram at BWR Vent sys will provide reliable source of air during draining. Sys will be steadily purged until mods installed JANECEK.R F. Commonwealth Edison Co. 80/09/02 2pp
- 8009260107 Forwards response to IE Bulletin 80-17. Suppl 3, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR "Procedure at Dresden 2 & 3 changed to require immediate manual scram when air pressure reaches 60 ps; RAUSCH, T J Commonwealth Edison Co 80/09/02 4pp
- 8309250804 Responds to NRC 771213 request for addl info in response to IE Bulletin 79-02, "Pipe Bupport Base Plate Designs Using Goncrete Expansion Anchor Bolts" Expansion anchor test results show installation of anchors acceptable JANECEKAR F Commonwealth Edison Co. 80/09/05 17pp
- 8009240133 Forwards 1E Circula: 80-21, "Regulation of Refueling Crews" No written response required
 KEPPLER.J 0 Region 3. Chicago, Office of the Director 80/09/10
- 8009300200 Forwards response to IE Bulletin 80-20 No Westinghouse Type W-2 control switches are used in safety-related sys at Bresden, Guad Cities & LaBalle County Responses for Zion & Byron are encl RAUSCH, T J C Commonwealth Edison Co. 80/09/15 And
- R Perladic operating reports & related correspondence
- BCO9030456 Forwards semiannual rept of radioactive effluent discharges a solid radwaste, for Jan-June 1980 BCOTT.D J Commonwealth Edison Co 80/08/20 lp
- --B009030467 Semiannual rept of radioactive effluent discharges & solld radwaste,for Jan-June 1980 * Commonwealth Edison Co B0/08/20 15pp
- BOO9230713 Forwards monthly operating repts for Aug 1980 SCOTT, D J Commonwealth Edison Co 80/09/12 1p

- ---8009230720 Monthly operating repts for Aug 1980 CIESZKIEWICZ.S Commonwealth Edison Co 80/0 80/09/03 15pp
- T Hearing transcripts on non-antitrust matters
- 8009100084 Transcript of 800819 prehearing conference in Chicago, IL # Atomic Safety and Licensing Board Panel 80/08/19 75pp
- V Operator Examinations
- B009300287 Forwards preliminary topical outlines of proposed modules on thermal hydraulics & core damage mitigation to be included in revised reactor operator training program per 800328 request NAUSHTON, U.F. Commonwealth Edison Co. 80/09/15 7pp
- DOCKET 50-250 TURKEY POINT PLANT, UNIT 3
- F Security, medical, emergency & fire protection plans
- 8007070862 Requests participation in IRC study of people-related problems in nuclear safeguards Request includes NRC visit to facility to Interview security personnel Confidentiality of info will be maintained during all phases of study VAROA,S A Operating Reactors Branch 1 80/08/14 2pp
- 8007230261 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Bys Installed for goyt use during energency O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22
- G Adjudicatory correspondence
- B009190046 Motion for order to show cause why facility should not be shutdown by B00731 to inspect & repair steam generator Util B00630 request for extension until Oct 1980 to perform insp should be denied Certificate of Svc encl BARRACK, T. BRODKS, R. HOSKINS, W. Affiliation Unknown 80/07/30 1800
- 8009150084 Ack receipt of 800730 petition on behalf of certain residents 8 homeowners of south FL requesting that NRC issue order to show cause to util Petition is being treated under 100FR2 206 100FH2 206 DENION,H R Office of Nuclear Reactor Regulation, Director 80/08/15 2pp
- --8009150089 Notice of request for action under 10CFR2 206 by 800730 patition on behalf of residents in south FC, for NRC to Issue to util order to show cause why facility should not be shut down by 800731 for insp & repair DENTON-H R Office of Nuclear Reactor Regulation, Director Regulation, Director
- -8009150095 Motion for order to show cause why facility should not be shut fown by 800731 to perform steam generator insp & repair, on behalf of certain residents & homeowners in south FL Certificate of 8vc & util press release encl HODDER, M H Hodder, M H FLAXMAN, C A Flaxman, C A 80/07/30
- 8009020073 Forwards Ft Power 5 Light Co comments on 800730 petition for show cause order to 800731 facility shutdown for steam generator insp 5 repair REJS-H F Lowenstein Newman.Rels.Axeirad 5 Toll 80/08/27 lp
- -8007020079 Comments opposing 800730 petition for show cause order re 800731 facility shutdown for steam generator inso & repair Petition is w/o merit & should be dismissed & Florida Power & Light Co 80/08/27 15pp
- 8007170267 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 80(10) VARGA: S A Operating Reactors Branch 1 80/08/27 2pp
- --8009190275 Order for mod of Licenses DPR-31 & DPR-41 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment info should be submitted by 801101 EISENHUT.D O Division of Licensing 80/08/29 App
- 8009250024 Advises that contrary to 800702 ltr. DES re proposed GLs amend to permit steam generator repair will be issued by 801031 OOLDBERG, S.C. Hearing Branch 2 80/09/23 1p

- 8307270180 Kotson to participate as interested state in proceeding Review of EIA safety evaluation 5 EIS may reveal areas of unagus concern to petitioner SANICERS.P. L. GINZBURG.R. A. Dade County.FI 80/09/24 2pp
- M Ambitrust correspondence
- BCCT300476 Response before US Court of Appeals for DC Carcuit in apposition to petitioners' motion for expedited completestion of Cavil Actson 80-1099 Certificate of Svc ercl Related correspondence DMH, BCCM-NIGHT, J.A. Fibrida Power & Light Co. DYM, H. Covington & Burling BO/67/25 Spp
- P Operating lacense stage documents & correspondence
- eGG7050029 Discusses void formation in vessel head during 800611 natural circulation reolfdon event Requests opinion repotential for voiding phenomenon in C-E designed NSSS CMECK.P.S. Assistant Director for Plant Systems 80/07/20 Zpp
- 8009020297 Submits interin criteria for shift staffing to all OL & CP licenses & applicants per NRC 800507 Itr Discusses administrative previsions for energency & overtime work Development & implementation to be revised within 90 days ESSENGUT. D C Division of Licensing 80/07/31 7pp
- 8009090000 Forwards draft NUREG-0695, "Functional Criteria for Emergency Response Facilities Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0595 encl W/o NUREG ERSENANT D G Division of Licensing 80/08/01 119pp
- BOGT230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENMUT. D G Division of Licensing 80/09/07 40pp
- 8009190794 Forwards revised Westinghouse STS 3 9 8 2.3 9 to & Bases 3/4 9 8 % 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required NOVAK.T H. Assistant Director for Operating Reactors 80/08/15 1p
- --5009196817 Revised Westinghouse STS 3 9 8 2.3 9 10 & Bases 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during novement of fuel assemblies or control ross

 * Assistant Director for Operating Reactors 80/06/23 21pp
- 8039150429 Forwards formal request for add1 info re design mod to add undervoltage relay protection sys to present loss of voltage scheme
 609AX.T H Assistant Director for Operating Reactors 80/08/18
- 8009090001 Forwards request for add) info re adequacy of station electric distributor sys voltages VARGA. B a Operating Reactors Branch 1 80/08/19 5pp
- BOG913G436 Forwards requests for add1 info re environ statement on proposed steam generator repair Outstanding areas include accident evaluation endangered species distribution & desiceralization VARCA.S A Operating Reactors Branch I 80/08/22 Epp
- BJ09030236 Forwards responses to NRC BJ09717 questions concerning radwaste From condensate polishing deminerallising sys UHR16.R E Florsda Power & Light Co B0/08/29 7pp
- 8009090257 Responds to NRC 800729 request for info re lou fracture toughness info is being prepared by AE Rept will be provided by 8009390 UNRIG.R E Florida Power & Light Co 80/09/05 ip
- BO09120949 Notification of 800917 meeting w/util at plant site to discuss steam generator repair program GRDIENHUIS.N Operating Reactors Branch 1 80/09/08 2pp
- BOO919090B Notification of BOO93D environ site visit w/util to plant out/all-canal sys & associated areas around facilities GROIENOWIS: Operating Reactors Branch 1 BO/09/11 299
- 8009160378 Responds to NRC 800702 ltr re THI-related Tech Specs Proposed specs have been drafted & forwarded to ensite & affisite review committees for review & approval URIO, R E Florida Power & Light Co 80/09/12 1p

- 8009190206 Application for amend of Liconses DPR-31 & DPR-41, resta Tech Specs to include definition of "operability" & to clarify application of limiting conditions for apprations Amend is submitted in response to NRC 800410 it; UHR10:RE Fiorida Power & Light Co 80/09/12 ip
- --8009190209 Proposed Tech Specs, Section 1 re definition of "optral & Section 3 re limiting conditions for operation Safety evaluation encl + Florids Power & Light Co 80/09/12 21pp
- 8009260015 Confirms arrangements for site visits on 80091/ € JO resteam generator repair program at plants
 VARQA-S A Operating Reactors Branch 1 80/09/12 App
- 8009270343 Discusses util response to NRC 800917 & 18 requests for info re adequacy of station electric distribution sys voltages A/E info expected by Dct 1980 Response to B000119 & 20 requests planned for 801101 & 15 reopectively UHR10:R E Florida Power & Light Co 80/09/24 1p
- 6009300129 Forwards responses to NRC request for add1 info re occurrence of endangered species at facility Steam generator repairs will not adversely affect crocodiles & turties Add1 response contained in nonradiological environ rept for 1979 UHRIG.R E Florida Power & Light Co 60/09/24 Spp
- 8009300177 Forwards response to request for additinfo re accident evaluation for steam generator repair
 UHRIG.R E Florida Power & Light Co 80/09/24 8pp
- @ Inspection reports, IE Bulletins & correspondence
- 8009100049 Forwards IE Bulletin 80-18, "Maint of Adequate Him Filow Through Centrifugal Charging Pumps Following Secondary Dids High Energy Line Rupture "Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director (10/07/24)
- 8009020195 Submits response to IE Bulletin 79-03A Completed answer to be forwarded by 801001 UHRIG,R E Florida Power & Light Co GO/08/08 Ip
- 8007030300 Responds to IE Bulletin 79-03A. "Longitudinal Hald Dafetts in ASKE SA-312. Type 304 Stainless Steel Pips " Preliminary info indicates seam welding piping in safety-related sys will meet code allowable stress criteria UHRIO.R E Florida Power & Light Co 80/08/08 lp
- 8009030158 Forwards Revision 1 to IE Bullatin 80-15, "Failures of Mercury-Netted Matrix Relays in Reactor Protective 8ys of Deparating Nuclear Power Plants Designed by C-F " Written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 800/09/15 p
- 8009160639 Responds to IE Bulletin 79-17 re pipe cracks in stagnant borated water sys Visual & ultrasonic examinations revealed no unresolved indications of stress corrosion in identified circumferential welds

 UHR10,R E Florida Power & Light Co 80/08/20 ip
- 8009160639 Responds to IE Bulletin 79-17 re pipe cracks in stagnant borated water sys Visual & ultrasonic examinations revealed no unresolved indications of stress corrosion in identified circumferential welds UHRIO:RE Florida Power Corp. 80/08/20 ip
- 8009160143 Forwards 1E Circular 80-18, "10CFR90 59 Bafety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 400/02/22
- 8009120486 Ack receipt of 800804 ltr informing NRC of steps taken is correct violation noted in IE Insp Rept 90-250/80-20 & 50-251/80-17 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/25 ip
- --8009i2049i Responds to NRC 800703 ltr re violations noted in IE lr; Repts 50-250/80-20 & 50-25i/80-17 Corrective actions.written instructions.w/specific details on implementation of Spec 5177-M-53, issued to contractor welders UHR10, R E Florida Power & Light Co 80/08/04 2pp
- --8009120495 Forwards IE Insp Repts 50-250/80-20 & 50-251/80-17 on 800527-29 & 0603-04 & notice of violation MURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/03 2pp

--8007120477 Notice of violation from insp on 800527-27 & 0603-04 * Region 2, Atlanta, Office of the Director 80/06/27 ip

rons

451141

3 .,

for

1

)g

177.4

r fa

124

413

--8009120499 IE Insp Repts 50-250/80-20 & 50-251/80-17 on 800527-29 & 0603-04 Noncompliance noted failure to follow weld electrode procedural requirements
HERDT, A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch ECONOMOB, N Region 2. Atlanta, Office of the Director 80/06/27 6pp

8009120515 Ack receipt of 800728 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-250/80-19 & \$0-251/80-20 MURPHY.C E Region 2: Atlanta. Reactor Construction & Engineering Support Branch 80/08/25 1p

- ~~8009120520 Responds to NRC 800627 ltr re violations noted in 1E Insp Repts 90-250/80~19 & 50-251/80-20 Corrective actions each item will be evaluated & implemented in accordance w/ guideline UHR10,R E Florida Power & Light Co 80/07/28 3pp
- --G00912052& Forwards IE Insp Repts 50-250/80-17 & 50-251/80-20 on 800&04-0& notices of violation & deviation MURPHY, C E Region 2, Atlanta. Reactor Construction & Engineering Support Branch 80/06/27 2pp
- --8007120531 Natice of violation from insp on 800604-06
 * Region 2, Atlanta, Office of the Director 80/06/27 lp
- --8009120535 Notice of deviation from insp on 800604-06
 * Region 2. Atlanta, Office of the Director 80/0 80/06/27 10
- --B007120539 lE Insp Repts 50-250/B0-19 & 50-251/B0-20 on B00604-04 Noncompliance noted inadequate fire brigade training program & fire protection administrative control procedures CONLON.TE Region 2. Atlanta, Reactor Construction & Engineering Support Branch MILLER.W H Region 2. Atlanta. Office of the Director 80/06/27 6pp
- 8009110121 Ack receipt of 800806 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-250/80-23 t 50-251/80-23 KENNA, W.B. Region 2. Atlanta, Bafeguards Branch 80/09/27 ip
- --8009110166 Responds to NRC 800711 ltr re violations noted in IE lnsp Repts 50-250/80-23 & 50-251/80-23 Corrective actions withheld (ref 10CFR2 790) UHRIG-R E Florida Power & Light Co 80/08/06 lp
- ---B009110169 Forwards IE lnsp Repts 50-250/80-23 & 50-251/80-23 on 800616-20 & notice of violation Notice of violation withheld (ref 10CFR2 790) KENNALU B Region 2. Atlanta, Safeguards Branch 80/07/11 2pp
- --8009110173 lE Insp Repts 50-250/80-23 & 50-251/80-23 on 800616-20 Noncompliance noted failure to maintain positive control over all designated vehicles Details withheld (ref 10CFR2 790) (ref 10CFR2 790) TILLMANA , HOWELL J C Region 2, Atlanta, Office of the Director OILLESPIE,F P Region 2, Atlanta, Safeguards Branch 80/07/11
- BO09120300 Forwards IS Info Notice BO-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers "No written response required G'REJILY, J P Region 2. Atlanta, Office of the Director 80/08/27
- 8009120871 Responds to 1E Bulletin 80-19.Revision 1 ra failures of mercury-wetted matrix relays in reactor protective sys Identified relays are not used in facility Four manhours expended for review
 UHRIG,RE Florida Power & Light Co 80/09/02 ip
- 8009110853 Submits response to IE Bulletin 80-04 Final response to bulletin will be submitted by 801001

 UHRIG.R E Florida Power & Light Co 80/09/03 ip
- BO09240412 Forwards response to IE Bullstin 80-15 re possible loss of emergency notification sys w/loss of offsite power Onsite extensions powered by reliable power supply Thirty-three manhours expended on review & corrective action W/affidavit UMRIQ.R E Florida Power & Light Co B0/09/04 App
- 8009250209 Forwards response to NRC ltr re violation noted in IE lnsp Repts 50-250/80-18 & 50-251/80-18 Corrective actions expansion anchors for listed supports will be reinspected No proprietary info in rept UMRIG.R E Florida Power & Light Co 80/09/08 2pp

- 8009290277 Forwards IE Circular 80-21, "Regulation of Refueling Crews " No written response required O'REILLY, J P Region 2: Atlanta, Office of the Director 80/09/10
- R Periodic operating reports & related correspondence
- 8009090290 Forwards "Radioactive Effluent Release Data, Jan-June 1980" & Environ Radiological Monitoring Program Summary, Jan-June UMRIG.R E Florida Power & Light Co 80/09/03 1p
- ~-8009090306 "Radioactive Effluent Release Data, Jan-June 1980 "

 → Florida Power & Light Co 80/08/14 17pp
- -8009090311 "Environ Radiological Monitoring Program Summary, Jan-June Florida Power & Light Co 80/09/03 8pp
- BOO9170279 Forwards monthly operating repts for Aug 1980 SCHMIDT, A D Florida Power & Light Co 80/09/06 ip
- --8009170281 Monthly operating repts for Aug 1980 CHILSON V T Florida Power & Light Co 80/09/06 15pp
- S Reportable accurrences, LERs & related correspondence
- 8009120350 Forwards LER 80-015/03L-0 5CHMIDT, A D Florida Power & Light Co 80/09/02 1p
- --8009120385 LER 80-015/03L-0 on 800802, during power operation & in preparation to increase vol in accumulators, safety injection pump 3A failed to start following manual initiation Caused by broken support for driving pawl PACE,P L Florida Power & Light Co 80/09/02 2pp
- 8009300490 Forwards LER 80-016/03L-0 SCHMIDT,A D Florida Power & Light Co 80/09/12 Lg
- --- 8009300494 LER 80-016/03L-0 on 800813, process radiation monitors R-11 & DUTATION THE OUT OF SVC CAUSED ON DOUBLES PROCESS regulation monitor.

 R-12 were out of svc Caused by air sampling blower suction
 line becoming plugged & overheating Mod to substitute blower
 W/longer duty cycle being prepared
 PACE,P L Florida Power & Light Co 80/09/12 1p

DOCKET 50-291 TURKEY POINT PLANT, UNIT 4

- F Security, medical, emergency & fire protection plans
- 8009090862 Requests participation in NRC study of people-related problems in nuclear safeguards Request includes NRC visit to facility to interview security personnel Confidentiality of info will be maintained during all phases of study VARGA. S A Operating Reactors Branch 1 80/09/14 2pp
- 8009230261 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency Grant Park Sys Grant Park Sys Region 2, Atlanta, Office of the Director 80/08/22
- G Adjudicatory correspondence
- B009190267 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of infu by B01101 VAROA, B A Operating Reactors Branch 1 80/08/29 2pp
- --8009190275 Order for mad of Licenses DPR-31 & DPR-41 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment info should be submitted by 801101 EISENHUT.D & Division of Licensing 80/08/27 4pp
- 8009250024 Advises that contrary to 800702 ltr.DES re proposed OLs amend to permit steam generator repair will be issued by 801031 GOLDBERG, S.C. Hearing Branch 2 80/09/23 1p
- 8009290180 Motion to participate as interested state in proceeding Review of ElA: safety evaluation & EIS may reveal areas of unique concern to petitioner SAUNDERS, B.L., GINSBURG, R.A. Dade County, FI 80/09/24 2pp

41 Antitrust correspondence

- 8009300476 Response before US Court or Appeals for DC Circuit.in appeals ton to petitioners' motion for expedited consideration of Civil Action 80-1099 Certificate of Svc and Related correspondence PYH-H . BOUNNIGHT.J A Florida Power & Light Co DYM, H Covington & Burling 80/09/25 5pp
- P Operating license stage documents & correspondence
- 8009050029 Discusses void formation in vessel head during 800511 natural circulation cooldown event Requests opinion repotential for voiding phenomenon in C-E designed NSSS CHECKLP S Assistant Director for Plant Systems 80/07/28 2pp
- 8009020297 Eubmits interim triteria for shift staffing to all OL & CP licenses & applicants, per NRC 800507 ltr Discusses administrative provisions for smergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D O Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities " Cornents requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISEKHUT, D G Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TM1-2 Lessons Learned is unjustified Frevious determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D G Division of Licensing 80/09/07 60pp
- 8009190794 Forwards revised Westinghouse STS 3 9 8 2,3 9 10 & Bases 3/4 9 8 % 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flangs during movement of fuel assemblies or control rods Hritten response required NOVAK, T M Assistant Director for Operating Reactors 80/08/15
- --8009190817 Revised Mestinghouse STS 3 9 8 2.3 9 10 & Bases 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods

 * Assistant Director for Operating Reactors 80/06/23 21pp
- 8009150429 Forwards formal request for addition or design mod to add undervoltage relay protection sys to present loss of voltage schame NOVAK.T M. Assistant Director for Operating Reactors 80/08/18 680
- 6009090091 Forwards request for addl info re adequacy of station electric distributor sys voltages VARGA.S A Operating Reactors Granch 1 80/08/19 5pp
- 6009150436 Forwards requests for additinfoire environ statement on proposed steam generator repair Outstanding areas include accident evaluation, endangered species distribution & demineralization VARQA.8 A Decrating Reactors Branch 1 80/08/22 800
- 8009030236 Forwards responses to NRC 800717 questions concerning radwaste from condensate polishing demineralizing sys UHRIG.R E Florida Power & Light Co 80/08/29 7pp
- 8009090257 Responds to NRC 800729 request for info re low fracture toughness info is being prepared by AE Rept will be provided by 800935 UHRIO, R E Florida Power & Light Co 80/09/05 ip
- 8009120049 Notification of 800917 meeting w/util at plant site to discuss steam generator repair program GNOTENHUIS.M Operating Reactors Branch 1 80/09/08 2pp
- 0009190908 Notification of 800930 environ site visit w/util to plant outfallicanal sys & associated areas around facilities GROTENHUIS, M. Operating Reactors Branch 1 80/09/11 2pp
- 8009140378 Responds to NRC 800702 ltr re TMI-related Tech Specs Proposed specs have been drafted & forwarded to onsite & offsite review committees for review & approval UHRIO.R E Florida Power & Light Co 80/09/12 tp.

- 8009190206 Application for amend of Licenses DPR-31 & DPR-41, revising Tech Specs to include definition of "operability" & to clarify application of limiting conditions for operations Amend is submitted in response to NRC 800410 ltr UHRIO.R E Florida Power & Light Co 80/09/12 1p
- --8009170209 Proposed Tech Specs, Section I re definition of "operab(Iligo | & Section 3 re limiting conditions for operation Safoty evaluation enc)

 4 Florida Power & Light Co 80/09/12 2100
- 8009260015 Confirms arrangements for site visits on 800917 & 30 resteam generator repair program at plants
 VAROA.S A Operating Reactors Branch i 80/09/12 2pp
- 8009290343 Distusses util response to NRC 800819 & 18 requests for info re adequacy of station electric distribution sys voltages A/E info expected by Oct 1980 Response to 800819 & 20 requests planned for 801101 & 15, respectively UMRIO, R E Florida Power & Light Co 80/09/24 ip
- 8009300129 Forwards responses to NRC request for add1 info re occurrence of endangered species at facility Steam generator repairs will not adversely affect crocodiles & turtles Add1 response contained in nonradiological environ rept for 1979 UNRIG.R E Florids Fower & Light Co 80/09/24 3pp
- 8009300177 Forwards response to request for add1 info re accident evaluation for steam generator repair UHRIG.R E Florida Power & Light Co 80/09/24 8pp
- Q Inspection reports. IE Bulletins & correspondence
- 8009100049 Forwards IE Bulletin 80-i8, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Written response required O'REILLY, J.P. Region 2, Atlanta. Diffice of the Director 80/07/24
- 8009020195 Submits response to IE Bulletin 79-03A Completed answer to be forwarded by 801001

 UMRIG.R E Florida Power & Light Co 80/08/08 1p
- 8009030300 Responds to IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME 8A-312. Type 304 Stainless Steel Pipe " Preliminary into indicates seam welding piping in safety-related syswill meet code allowable stress criteria UHR10.R E Florida Power & Light Co 80/08/08 1p
- 8009030159 Forwards Revision i to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E "Written response required O'REJLLY, J.P. Region 2. Atlanta, Office of the Director 80/08/15 in
- 8009160639 Responds to IE Bulletin 79-17 re pipe cracks in stagnant borated water sys Visual & ultrasonic examinations revealed no unresolved indications of stress corrosion in identified circumferential welds
 UMRIG.R E Florida Power & Light Co 80/08/20 ip
- 8009160143 Forwards IE Circular 80-18, "10CFR90 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22
- 8009:120486 Ack receipt of BOO804 itr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-250/80-20 & 50-251/80-17 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Bupport Branch 80/08/25 1p
- --8009120491 Responds to NRC 800703 ltr re violations noted in IE Insp Repts 80-250/80-20 & 50-251/80-17 Corrective actions written instructions, w/specific details on implementation of Spec 5177-M-53, issued to contractor weiders URRIG,R E Florida Power & Light Co 80/08/04 2pp
- --8009120495 Forwards IE lnsp Repts 50-250/80-20 & 50-251/80-17 on 800527-29 & 0403-04 & notice of violation MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/07/03 2pp

--8007120497 Notice of violation from insp on 800527-29 & 0603-04 * Region 2, Atlanta, Office of the Director 80/06/27. 1p

- --B009120499 IE Insp. Repts 50-250/B0-20 & 50-251/80-17 on 800527-29 & 0603-04 Noncompliance noted failure to follow weld electrode procedural requirements
 HERDT.A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch ECGNOMOS.N Region 2. Atlanta, Office of the Director 80/06/27 6pp
- 8009120515 Ack receipt of 800728 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-290/80-19 & 50-291/80-20 MURPHY.C E Region 2. Atlanta Reactor Construction & Engineering Support Branch 80/08/25 1p
- --B009120520 Responds to NRC B00627 ltr re violations noted in IE [nsp Repts 50-250/80-19 & 50-251/80-20 Corrective actions each item will be evaluated & implemented in accordance w/ guideline UHRIO:RE Florida Power & Light Co B0/07/20 3pp
- --8009120526 Forwards IE Insp Repts 50-250/80-17 % 50-251/80-20 on BOO604-06 & notices of violation & deviation MURFHY,CE Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/06/27 2pp
- --8009120531 Notice of violation from insp on 800604-06
 * Region 2. Atlanta, Office of the Director 80/06/27 lp
- --8009120535 Natice of deviation from insp on 800604-06 * Region 2. Atlanta. Office of the Director 80/06/27 ip
- --8009120539 IE Insp Repts 50-250/80-19 & 50-251/80-20 on 800404-04 Noncompliance noted inadequate fire brigade training program & fire protection administrative control procedures CONLDN.TE Region 2. Atlanta. Reactor Construction & Engineering Support Branch MILLER,W H Region 2. Atlanta. Office of the Director 80/06/27 6pp
- 8009110121 Ack receipt of 800806 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-250/80-23 & 50-251/80-23 RENNALU B Region 2. Atlanta. Safeguards Branch 80/08/27 1p
- --8009110166 Responds to NRC 800711 ltr re violations noted in IE lnsp Repts 50-250/80-23 & 50-251/80-23 Corrective actions withheld (ref 10CFR2 790) UHRIQ:R E Florida Power & Light Co 80/08/06 ip
- ~-B009110169 Forwards 1E Insp Repts 50-250/80-23 & 50-251/80-23 on 800616-20 & notice of violation Notice of violation withheld (ref 10CFR2 790)
 KENNA,W B Region 2. Atlanta. Bafeguards Branch 80/07/11 2pp
- --8009110173 IE lnsp Repts 50-250/80-23 & 50-251/80-23 on 800616-20
 Noncompliance noted failure to maintain positive control
 over all designated vehicles Details withheld
 (ref 100FR2 770)
 TILLMAN.A. HOWELL, J. C. Region 2, Atlanta, Office of the Director
 QILLEGPIE, F. P. Region 2, Atlanta, Safeguards Branch 80/07/11
- 8009120308 Forwards IE Info Notice 80-31, "Maloperation of Could-Brown Bovers 480 Volt Type K-6008 & K-DDN 6005 Circuit Breakers "
 No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/27 to
- 9009120671 Responds to IE Bulletin 80-19. Revision 1 re failures of marcury-wetted matrix relays in reactor protective sys Identified relays are not used in facility Four manhours expended for review UHRIO, RE Florida Power & Light Co 80/09/02 ip
- 8009110853 Submits response to IE Bulletin 80-04 Final response to bulletin will be submitted by 801001 UHRIG.R E Florida Power & Light Co 80/09/03 ip
- 8009240412 Forwards response to IE Bulletin 80-15 re possible loss of emergency notification sys w/loss of offsite power, Onsite extensions powered by reliable power supply Thirty-three manhours expended on review & corrective action M/affidavit UHRIG.R.E Florida Power & Light Ca 80/09/04 4pp
- BO09250209 Forwards response to NRC ltr re violation noted in IE Insp Repts 50-250/80-18 & 50-251/80-18 Corrective actions expansion anchors for listed supports will be reinspected No proprietary info in rept UKRIQ.R.E Florida Power & Light Co 80/09/08 2pp

- 8009290277 Forwards IE Circular 80-21, 'Regulation of Refueling Crews " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/10 5pp
- R Periodic operating reports & related correspondence
- 8009090290 Forwards "Radioactive Effluent Release Data, Jan-June 1980" & "Environ Radiological Monitoring Program Summary, Jan-June 1980 "
 UHRIOR E Florida Power & Light Co 80/09/03 lp
- --8009090304 "Radioactive Effluent Release Data, Jan-June 1980 "
 + Florida Power & Light Co 80/08/14 17pp
- --80070903(1 "Environ Radiological Monitoring Program Summary, Jan-June 1780 " + Florida Power & Light Co 80/07/03 Spp
- 8009170279 Forwards monthly operating repts for Aug 1980 SCHMIDT.A D Florida Power & Light Co 80/09/06 ip
- --8007170281 Monthly operating repts for Aug 1980 CHILSON, V 7 Florida Power & Light Co 80/07/06 15pp
- S Reportable occurrences, LERs & related correspondence
- 8009120313 Forwards LER 80~011/03L-0 SCHMIDT,A D Florida Power & Light Co 80/09/02 ip
- --8009(20315 LER 80-011/031-0 on 8008(8, during surveillance testing.six ionization detectors in 4W electrical penetration room found inoperable Caused by improper installation of upgrade to fire protection sys PACE.P L Florida Power & Light Co 80/09/02 2pp
- DOCKET 90-254 QUAD-CITIES STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8009230288 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Bys installed for govt use during emergency KEPPLER.J O Region 3. Chicago. Office of the Director 80/08/22 Jpp
- 8009:00378 Forwards review of util generating station emergency plan & draft itr requesting addl info & commitments from util PAGANO, FO Emergency Preparedness Licensing Branch 90/08/28 5pp
- O Adjudicatory correspondence
- 8007220015 Forwards order requiring info supporting environ qualification of safety-related electrical equipment. Requests submittal of info by 801101 [PPOLITO, T A Operating Reactors Branch 2 80/08/27 2pp
- --8007220017 Order for mod of Licenses DPR-29 & DPR-30 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment, Info should be submitted by 801101

 EISENHUT, D © Division of Licensing 80/08/29 App
- 8009300603 Forwards 800919 order revising 809829 order Por mod of OLs. in entirety EIEENHUT.D O Division of Licensing 80/09/19 2pp
- --8009300614 Order revising 800829 order for mod of OLs DPR-29 & DPR-30, published in 800912 FR, in satirety Info re IE Bulletin 79-018 shall be filed by 801101 Request for hearing will not stay arder effective 800919 VCS petitions discharged EISENHUT, D O Division of Licensing 80/09/17 App
- P Operating license stage documents & correspondence
- 8009110354 Suppls NRC 800707 request for proposed Tech Specs changes re scram discharge vol vent & drein valves, & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT.D 0 Division of Licensing 80/07/22 22pp

- 8009020277 Submits interim criteria for shirt staffing to all OL & CP licenses? applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & inplementation to be reviewed within 90 days EISERHUT, D.G. Division of Licensing 80/07/31 7pp
- 8007080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities". Cornents requested within 30 days Proposed implementation schedule for meeting criteria of NUREC-0696 and Wo NUREG EISEKHUT.D C Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated u/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISECHUT. D C Division of Licensing 80/08/07 40pp
- 6309020454 Forwards evaluation of util response to NRC 800223 request for info re primary coolant sys pressure isolation valves. Two specific Event 5 valve configurations do not exist at facilities. CRUICHFIELD. D. Operating Reactors Branch 5 80/09/12 3pp
- --8009020473 "Prinary Coolant Sys Pressure Isolation Valves." technical evaluation rept "DELLP H. STILKELL.T C Franklin Institute/Franklin Research Center NRC-03-77-118 80/07/21 4pp
- 2007180252 Forwards NUREG-0661, "Mark 1 Containment Long-Term Program SER Pesolution of Generic Technical Activity A-7 " Rept discusses generic suppression pool hydrodynamic load definition H/o enc! 1PPOLITO T A Operating Reactors Branch 2 80/08/20 2pp
- 8009020105 Forwards NUJECH Rept COK-0708-03. "Evaluation of 18-Inch Containment Isolation Valves for Dresden Station.Units 2 & 3 & Gwad Cities Station.Units 1 & 2." in response to NRC 791022 1 23 Itrs re containment vent & purge valves JANECEK.R F Commonwealth Edison Co 80/08/22 lp
- ---8007020111 "Evaluation of IB-Inch Containment Isolation Valves for Dresden Station,Units 2 & 3 & Quad Cities Station,Units 1 & 2 "

 GERBER.D A , DEARDORFF.P E , MARTIN.J B Nuclear Technology, Inc (Nuclear) COM-0708-03 80/05/14 116pp
- 8307120404 Forwards Attachments 1-5 to util 800630 ltr re facility electric distribution sys voltage adequacy Ltr inadvertently transmitted u/o attachments

 JAFECEK.R F Commonwealth Edison Co 80/08/28 6pp
- 8009090338 Application for amend of License DPR-27, changing Tech Specs to support review of future reloads Cycle 6 operation is scheduled to begin 801123 Class III fee encl
 JAM'ECEM.R F Commanuealth Edison Co 80/09/02 4pp
- --8002080341 Proposed Tech Specs to support review of future reloads.
 including Tech Specs 1 i/2 1 re fuel cladding integrity. 1 2/
 2 2 re safety limit.3 1/4 1 re reactor protection sys & 3 2/
 4 2 through 3 5/4 5 re limiting conditions for operation
 4 Commonwealth Edison Co 89/09/02 47pp
- 8009090224 Forwards addl info re min critical configuration in support of 800515 application to amend Licenses DPR-19,25,29 ½ 30, changing requirements for source range monitor count rates JANeCEK.R F Commonwealth Edison Co 80/09/03 5pp
- --8009180506 Amends 49,44,58 % 53 to Licenses DPR-19,DPR-25,DPR-29 & DPR-30,respectively-revising Tech Specs to allow count rate on source range monitor charnels below 3 counts per second when there are two or less fuel assemblies in quadrant IPPOLITO.T A Operating Reactors Branch 4 80/09/08 22pp
- --BOO9180516 Safety evaluation supporting Amends 49,44,58 & 53 to Licenses DPR-19,DPR-25,DPR-29 & DPR-30,respectively • Office of Nuclear Reactor Regulation, Director 80/09/08 4pp
- --8009180524 Notice of issuance & availability of Amends 49, 44,58 & 53 to Licences DPR-19,DPR-25,DPR-29 & DPR-30.respectively IPPGLITO.T A Operating Reactors Branch 2 80/09/08 2pp

- 8009230463 Forwards proposed Tech Spec changes re implementation of TMI Lessons Learned, Category A requirements, in response to NRC 800702 request Dresdem Unit 1 Tech Spec changes will be submitted 90 days prior to scheduled startup JANECEK,R F Commonwealth Edison Co 80/09/18 3pp
- --8009230466 Proposed Tech Spec changes re implementation of TMI-2 Lessons Learned Category A Items * Commonwealth Edison Co 80/09/10 29pp
- G Inspection reports: IE Bulletims & correspondence
- 8009190166 Forwards IE Investigation Rept 50-254/79-31 on 791205-800115 No noncompliance noted KEPPLER.J O Region 3. Chicago, Office of the Director 80/02/14
- --B009170171 IE Investigation Rept 50-254/79-31 on 791205-800115 No noncompliance noted Major areas investigated circumstances surrounding closure of two core spray suction valvos to ECCS NORELIUS.C E . BPESSARD.L . MCCARTEN.J B Region 3. Chicago. Office of the Director B0/02/04 13pp
- 8009040517 Forwards IE Bulletin 80-07, Suppl 1, "SWR Jet Pump Assembly Fallure" Response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/05/14 to
- 8007040632 Provides addi response to IE Bulletin 80-17 Results of analysis of ATMS w/o recirculation pump trip enci Analyses required no deratings to remain below svc level C limit JANECEK.R F Commonwealth Edison Co 80/07/14 App
- 8007020109 Responds to IE Bulletin 79-03A. "Longitudinal Held Defects in ASKE SA-312, Type 304 Stainless Steel Pipe " SA-312 pipe not present in operating plants Final confirmation from suppliers anticipated by 800915 re const plant piping sys NAVOHTON, W F Commonwealth Edison Co 80/08/07 2pp
- 8009170230 Forwards response to IE Bulletin 80-17, Suppl 1, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BMR "
 Scram discharge vol piping, scram instrument vol piping & drain piping meet requirements re downward pitch PEOPLES, D. L. Commonwealth Edison Co. 80/08/07 4pp
- B008280488 Forwards IE Insp Repts 50-254/80-18 & 50-265/80-20 on 800714-18 & notice of violation Notice of violation withheld tref 100FR2 790)
 H1ND, J.A. Region 3, Chicago, Safeguards Branch 80/08/12 2pp
- --8009280495 IE Insp Repts 50-254/80-18 % 50-265/80-20 on 800714-18 Noncompilance noted failure to establish compensatory measures for failed security-related equipment & to control access to vital areas Details withheld fref 100FR2 790) HIND, J A Region 3. Chicago. Safeguards Branch 80/08/11 2pp
- 8007030231 Forwards Revision 1 to 1E Bulletin 80-19. "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required MEPPLER.J G Region 3. Chicago. Office of the Director 80/08/15
- 8009110545 Responds to IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds," supplementing 800709 response Corrects Zion response re rings used for field circumferential butt weld Reviews accuracy of other statements ABEL.J 8 Commonwealth Edison Co 80/08/15 App
- 8009110562 Responds to Suppl 1 to IE Bulletin 80-17, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at EMR "
 Util will not have continuous SDV water level monitoring sys installed & functional by 800901

 JANECEK.R F Commonwealth Edison Co 80/08/15 2pp
- 8007160681 Submits supplementary response to IE Builetin 80-08, "Examination of Containment Liner Penetration Walds." correcting statement made in DL Peoples 800709 ltr Further review not necessary ABEL. J S Commonwealth Edison Co 80/08/15 4pp
- 8009270123 Forwards Waste Packaging Insp Rept 15000046/80-65 on 800527-30 % notice of violation DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/00/18 2pp
- --8007290126 Notice of violation from insp on 800527-30
 * Region 3, Chicago, Office of the Director 80/07/23 lp

- ~-800929013i Waste Packaging Insp Rept 15000046/80-65 on 800527-30 Noncompliance noted failure to most strong, tight package requirement contained in DOT regulation LOVENDALE,P C. THOMAS,R D. Region 3, Chicago, Office of the Director BOOK,H E. Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/07/23 2pp
- 8009110732 Ack receipt of 800812 itr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-254/80-16 HIND.J A Region 3. Chicago. Safeguards Branch 80/08/20 ip
- --8007110737 Responds to NRC 900721 ltr re violations noted in IE lnsp Rept 30-254/80-16 Corrective actions withheld (ref 10CFR2 790) Commonwealth Edison Co 80/08/12 1p ABEL. J B
- 8009150495 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Konessential Control Air at Certain OE BWR Facilities " No specific action or response requested KEPPLER.J G Region 3. Chicago. Office of the Director 80/08/20
- 8009:20060 Forwards Suppl 3 to IE Bulletin 80-17. "Failure of Control Rods to Insert During Scram at BWR " Written response required KEPPLER. J 9 Region 3. Chicago, Office of the Director 80/08/22
- 800918055) Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Troatment Bys " No written response KEPPLER. J G Region 3. Chicago. Office of the Director 80/08/22
- 8009230094 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers "
 No written response required
 KEPPLER, J O Region 3. Chicago, Office of the Director 80/08/28
- BOO9100659 Ack receipt of 800715 itr informing NRC of steps taken to correct violation noted in 800620 IE inspired & payment of civil penalty
 BTELLOV Office of Inspection & Enforcement, Office of the Director 80/08/29 2pp
- ECO9170411 Forwards response to IE Builetin 80-15 re possible loss of emergency notification sys w/loss of offsite power Review revealed inoperability of Dresden sys Investigation being conducted Operating Order 26-80 changed JANACEK.R F Commonwealth Edison Co 80/08/29 4pp
- 8009[80466 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protectivo sys Identified relays are not used in facility No action required Twenty-four manhours espended on review RAUSCH.T J, Commonwealth Edison Co 80/08/29 ip
- 8009230478 Forwards Revision 1 to IE Bulletin 79-26, "Doron Loss From BWR Control Blades" Written response required KEPPLER.J O Region 3. Chicago. Office of the Director 80/08/29
- 8009170421 Responds to IE Bulletin 80-17. Suppl i/re failure of control rods to fully insert during scram at BMR Vent sys will provide reliable source of air during draining Bys will be steadily purged until mods installed JANECEK,R F Commonwealth Edison Co 80/09/02 2pp
- 9009250109 Forwards response to IE Bulietin 80-17. Suppl 3. "Failure of 75 of 185 Control Rods to Fully Insert During Scram at DWR" Procedure at Dresden 2 5 3 changed to require immediate manual scram when air pressure reaches 60 psi RAUSCH.TJ Commonwealth Edison Co 80/09/02 4pp
- GOO9230504 Responds to NRC 791213 request for addl info in response to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expension Anchor Boits " Expansion anchor test results show installation of anchors accoptable JANECEK,R F Commonwealth Edison Co 80/09/05 17pp
- 8009240133 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required KEPFLER.J 0 Region 3, Chicago, Office of the Director 80/09/10

- 8009300200 Forwards response to 1E Bulletin 80-20 No Westinghouse Type W-2 cuntrol switches are used in safety-related sys at Dresden.Quad Cities & LaSalle County Responses for Zion & Byron are encl Commonwealth Edison Co 80/09/15 Apr
- R Periodic operating reports & related correspondence
- B009030448 Forwards semiannual rept of radioactive effluent discharges & solid radwaste, for Jan-June 1980 KALIVIANAKIS, N Commonwealth Edison Co 80/08/43 1p
- --8009030453 Semiannual rept of radioactive effluent discharges & solld radwaste, for Jan-June 1980 * Commonwealth Edison Co 80/08/13 20pp
- 8009160272 Forwards monthly operating repts for Aug 1980 KALIVIANAKIS,N Commonwealth Edison Co 80/09/02 1p
- --8009160276 Monthly operating repts for Aug 1980 BROWN, B , TUBBS, B Commonwealth Edison Co 80/09/02 2200
- 8009120253 Forwards changes, tests & experiments completed during Aug KALIVIANAKIS,N Commonwealth Edison Co 80/09/08 2pp
- 8 Reportable occurrences, LERs & related correspondence
- 8009020390 Forwards LER 80-01//03L-0 KALIVIANAKIS, N Commonwealth Edison Co 80/08/06 ip
- --8009020396 LER 80-017/03L-0 on 800716.alarm in control room indicated vacuum breaker valve A0-1601-20B opened Valve position indicating lights inoperable Caused by coll burnup in air actuator solenoid Valve closed & defective coll replaced STEFFES.C Commonwealth Edison Co 80/08/06 2pp
- 8009080422 Forwards LER 80-018/03L-0 KALIVIANAVIS,N Commonwealth Edison Co 80/08/19 1pp
- --8009080427 LER 80-018/03L-0 on 800805, main chimney offgas sample pump tripped Backup pump tripped also producing low flow alarm Caused by excessive vano wear on pump rotors HAFERA.T Commonwealth Edison Co. 80/08/15 2pp
- 8009120391 Forwards LER 80-019/03L-0 KALIVIANAKIS.N Commonwealth Edison Co 80/08/25 1p
- ---B009120399 LER B0-019/03L-0 on B00B17, while operating at 400 MW, after performance of reactor core isolation cooling monthly pump operability surveillance test, flow controller was left in manual Caused by operator failure to readjust to automatic KOPACZ, J Commonwealth Edison Co B0/0B/25 2pp
- V Operator Examinations
- 8009300287 Forwards preliminary topical outlines of proposed modules on thermal hydraulics & core damaga mitigation to be included in revised reactor operator training program per BOODER request * Commonwealth Edison Co 80/09/15 7pp
- DOCKET 50-255 PALISADEB NUCLEAR PLANT
- F Security, medical, emergency & fire protection plans
- 8007230275 Requests that all personnel be reminded of purpose of umergency notification sys & health physics network Sys installed for govt use during emergency KEPPLER, J G Region 3, Chicago. Office of the Director 80/0 80/0B/22
- 8009i10428 Submits revised description of reactor coolant pump oil leak originally submitted in 800502 itr Installation of oil leak collection sys has been completed Additions to correct design unissions will be completed by 801f01 HOFFMAN.D P Consumers Power Co 80/09/09 2pp
- O Adjudicatory correspondence
- 6007090446 Provides status rept of discovery & other prehearing matters re civil penalty proceeding per 800229 memorandum & order Addl info was submitted to licensee on 800818, in response to 800722 memorandum & order MURPHY, P 11 Isham, Lincoln & Beale 80/09/03 2pp

- 5309110317 Second round of interrogatories & request for production of documents directed to util Requests inno re steps taken by PD Story when rilter was replaced & circumstances relocked-open value condition Certificate of Svc encl BURNES G Rulemaking & Enforcement Division 60/09/09 9pp
- BD092602£0 Response to CPC BD0820 second round of interrogatories Explains seriousness of breach of containment integrity re protection of public & consequences of LOCA Identifies prinalty factors W/affidavit.resume & Certificate of Svc BRYAN.6 E Office of Inspection & Enforcement. Office of the Director 80/09/24 20pp
- J. Insurance & andemnsty information
- 8009180292 Forwards executed Endorsement 65 to MELIA Policy NF-179 reflecting 307 shutdown credit for fecility from 790909-800522 IRELAND. J H Consumers Power Co. 80709715 2pp
- P Operating license stage documents & correspondence
- 8009110575 Forwards Amend 59 to provisional OL DPR-20, safety evaluation 5 notice of issuance & availability CRUICHFIELD D Operating Reactors Branch 5 80/07/29 8pp
- --8007i10581 Amend 59 to provisional License BPR-20, deleting Tech Specs Table 4 12. Item 12-5 requirement for quarterly strolling of valves associated u/operation of safety injection & refueling tank level suitch interfects CRUICHFIELD.D Operating Reactors Branch 5 80/07/29 App
- --8007110597 Safety evaluation supporting Amend 57 to provisional License DPR-20 • Operating Reactors Branch 5 80/07/27 3pp
- --8009110594 Notice of issuance & availability of Amend 59 to provisional License DPR-20 CRUICHFIELD.D Operating Reactors Branch 5 80/07/29 2pp
- 8009020297 Submits interim criteria for shift staffing to all DL & CP incenses & applicants, per ARC 800597 itr Discusses administrative provisions for energency & overtime work Development & implementation to be reviewed within 90 days EISEMMUT, D G Division of Licensing 80/07/3i 7pp
- B009080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREO EISENHUT, D G Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend CISENHUT, D C Division of Licensing 80/08/07 60pp
- 8009110746 Hotsfication of 800916 meeting u/SEP owners group to discuss MRC initial review & recommendations for site-specific ground response spectra & owners group program plans for ielsmic functional qualification of Class IE equipment LEVIN.H A Division of Engineering 80/09/26 Ip
- 8009160430 Immediate action litring steam generator level indication Power level will not exceed 55% full power until matter is rasolved Power operation will continue only while both availiary feed pumps are operable MEPPLER, J. G. Region 3. Chicago. Office of the Director 80/08/24 ip
- 8009030430 Advises that util is committing to increasing strength of spacer grids supplied by Erxon Nuclear Co starting w/Reload J in late 1982 or early 1983 Cavity shield wall analysis rapt will be submitted by 801114 H
- 6009040423 Notifies of procedural problem in complying w/NRC 800523 menorandum & order re electrical equipment qualification Emergency radiation assessment sys cannot involve IEEE 323-1974 Best components consistent w/order will be used HOFFMAN, D.P. Consumers Power Co. 80/09/02 3pp
- 3009230769 Notification of 800903 mmeting w/util in Bethesda. MD to discuss util arguments for lifting 55% power limit VILLALVA.! Office of Inspection & Enforcement. Office of the Director 80/09/02 2pp

- 8007270224 Immediate action ltr reaffirms discussions & agreements reached during 800903 meeting in Bethesda.MD re reactor power level.steam generator level indication.auxiliary feedwater flou rates & water hammer KEPPLER.J G Region 3. Chicago. Office of the Director 80/09/04 2pp
- 8009290143 Notification of 800926 meeting w/utils & Kerr-McGee Chemical Corp in Bethesda, MD to discuss review & recommendations for site specific ground response spectra & program plans for sessmic functional qualification of Class IE equipment ALLISON, D P Systematic Evaluation Program Branch 80/09/08 3pp
- 8007260022 Notification of second rescheduling until 801003 for meeting w/SEP owners group & KMC.Inc to discuss NRC initial review of site-specific ground response spectra & util program for sessent functional qualification of Class IE equipment ALLISON.D P Systematic Evaluation Program Branch 80/09/10 3pp
- 8007160500 Requests remittance of fee for 800425 request for relief from inservice pump testing requirements,per NRC 800724 ltr Fee due in 15 days MILLER.H O License Fee Management Branch 80/09/12 lp
- 8007230440 Advises that wide range steam generator level instrumentation will be installed during 1981 refueiing outage, as a result of evaluation requested in NUREG-0635, Item X & 3 3 4(c)
 FROST S R Consumers Power Co 80/09/18 1p
- E009230436 Responds to NRC 8006i1 & 0702 Tech Spec change requests providing for redundancy in decay heat removal capability & TMI Tech Spec changes Internal review & approval should be complete by 801i03 Changes will be submitted after approval HOFFMAN, D P Consumers Power Co 80/09/19 ip
- 8009230458 Responds to NRC 800728 request for action plan to resolve questions re-seismic design of cable trays Response by RE Schaffstali of KMC. Inc on 800828 for SEP owners group constitutes util response HOFFMAN. D P Consumers Power Co 80/09/19 ip
- 8007270354 Forwards Class III fee payment per lOCFR170 22, in response to NRC 800912 request Amend fee applicable to updating inservice pump testing program to 1777 edition of ABME Boiler & Pressure Vassel Code Section XI M/o encl HOFFMAN, D P Consumers Power Co 80/09/23 2pp
- 9 Inspection reports, IE Bulletine & correspondence
- 8009030208 Forwards IE Insp Rept 50-255/80-10 during June & notice of deviation HEIGHMAN,R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/07/17 200
- ---90070502ii Notice of deviation from insp during June. * Region 3, Chicago, Office of the Director 90/07/17 lp
- --80090502;6 IE Insp Rept 50-255/80-10 during June Noncompliance nated failure to man control room w/two licensed personnel JORGELESEN, B. L. HELLER, J. K. BOVD, D. C. Region G. Chicago, Office of the Director 80/07/17 9pp
- 8009100132 Forwards IE Insp Rept 50-255/80-09 on 800624-25 & notice of violation HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/07/21 2pp
- --8009100134 Notice of violation from insp on 800624-25 * Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/07/18 ip
- --8009100140 IE Insp Rept 50-255/80-09 on 800624-25 Noncompliance noted failure to follow procedures for documentation & training BAKER, K R Region 3, Chicago, Reactor Operations Nuclear Support Branch SCHULZ, R D , SWANSON. E Region 3, Chicago, Office of the Director 80/07/18 3pp
- 8009290109 Forwards IE insp Rept 50-255/80-11 on 800722-24 No noncompliance noted HEISHMAN,R F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/08/11 2pp
- --8009290118 IE Insp Rept 50-255/80-11 on 800722-24 No noncompliance noted Hajor areas inspected core thermal gower evaluation, reactivity measurement & critical boron concentration CHONLES,N C. CHONLET T. Region 3, Chicago, Office of the Director STREETER,J F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/08/11 3pp

DOCKETED ITEMS

- 8009030229 Forwards Revision i to IE Builetin 80-19, "Failures of Mercury-Netted Matris Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written rasponse required KEPPLER.J C Region 3. Chicago, Office of the Director 80/08/15 to
- 8009030115 Ack receipt of 800623 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-255/80-08 HEISHMAN.R F Region 3, Chicago, Reactor Operations Nuclear Support Branck 80/08/19 ip
- --B009030117 Responds to NRC B00701 ltr re violations noted in IE Insp Rept 50-255/80-08 Corrective actions shift supervisory personnel instructed to verify proper completion of turnover check sheets HDFFMAN.D P Consumers Power Co 80/07/23 3pp
- 8009300217 Forwards IE Insp Rept 50-255/80-13 during Jul 1980 & notice of vielation
 HEISHMAN.R F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/08/19 2p
- --8009300221 Notice of violation from insp during Jul 1980
 4 Region 3, Chicago, Office of the Director 80/09/18 in
- --8009390224 IE Insp Rept 90-255/80-i3 during Jul 1980 Noncompliance noted failure to adhere to administrative procedures for equipment control BGYO.D C . JURGENSEN.B L . HELLER.J K Region 3, Chicago, Office of the Director 80/08/18 7pp
- 8009110727 Ack receipt of 800808 ltr informing NRC of steps taken to correct violation noted in IE insp Rept 50-255/80-10 HEISHMAN,R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/08/20 ip
- --800911073D Responds to NRC 800717 ltr re violations noted in IE Insp Rept 50-255/80-10 Corrective actions standing orders to maintain two operators in control room lissued HOFFMAN.D P Consumers Power Co 80/08/08 ip
- BOO9170415 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Bys " No written response required KEPPLER.J O Region 3, Chicago, Office of the Director 80/08/22
- 8009020262 Requests extension to 800923 for response to deficiency noted in IE Insp Rept 50-255/60-09 HOFFMAN, D P Consumers Power Co 80/08/25 lp
- 8007030624 Forwards final inservice insp rept covering 790908-800528 HDFFMAN.D P Consumers Power Co 80/08/27 ip
- --8009030627 Final inservice insp rept covering 790708-800528 Includes data submitted by Southwest Research Institute MARTIN.8 E . CHERBAR B . ADAMS.A. Consumers Power Co 80/08/18 500p
- 8007230073 Forwards IE Info Notice 80-31, "Maioperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers "
 No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/28, 1p
- 8009090548 Responds to IE Bulletin 80-15 Emergency notification sys powered from instrument bus Y-01,8 reaker 42, from offsite power & is automatically powered by i-1 generator upon loss of offsite power FROST.8 R Consumers Power Co 80/09/04 4pp
- 8009240096 Forwards IE Circular 80-21, "Regulation of Refueling Crews "
 No written response required
 XEPPLER, J.O. Region 3, Chicago, Office of the Director 80/09/iO
 1p
- 8009290160 Discusses IE insp on 800729 & forwards notice of violation & notice of proposed imposition of civil penalty SIELLAL V Office of Inspection & Enforcement, Office of the Director 80/09/16 3pp
- --8009290162 Notice of violation from insp on 800729 Noncompliance noted plant operated at high power witwo high pressure safety injection pumps & one low pressure pump inoperable 4 Office of Inspection & Enforcement, Office of the Director 80/09/16 2pp

- --B009290164 Notice of proposed imposition of civil penalty for item of noncompliance noted in IE insp or 800729

 4 Office of Inspection & Enforcement, Office of the Director 80/09/16 | 19
- R Periodic operating reports & related correspondence
- 8009120457 Forwards monthly operating rept for Aug 1980 KENNEDY, D M Consumers Power Co 80/09/05 ip
- --8009120462 Monthly operating rept for Aug 1980 BODTKE,P J Consumers Power Co 80/09/05 3pp
- BOO9140370 Bimonthly status rept for Aug-Bept 1780 Bechtel Corp is preparing final design details for long-term cooling mods Mods scheduled for 1981 outage HOFFMAN.D P Consumers Power Co 80/09/12 ip
- 8009230512 Forwards addition & corrections to summary of radioactive afficients released from facility during 1978 DICKSON.M 9 Consumers Power Co 80/09/17 5pp
- S Reportable occurrences. LERs & related correspondence
- 8009020132 Ack receipt of 800731 telcon re-corrective actions taken as result of 800726 & 27 event involving ECCS containment sump suction valve CV-3030 Discusses NRC understanding of currective actions Immediate action Itr KEPPLER, J 0 Region 3. Chicago, Office of the Director 80/07/31 200
- 8009030583 Forwards LER 80-027/01T-0 HDFFMAN, D.P. Consumers Power Co. 80/08/27 1p
- --8009030594 LER 80-027/01T-0 on 900812, during venting of quench tank to waste gas surge tank, unplanned gaseous release occurred w/o min holdup Caused by broken pin which held diaphrage to operating what Pin replaced a Consumers Power Co. 80/08/27 ip
- 8007080404 Forwards LER 80-027/017-0 HOFFMAN, D P Consumers Power Co 80/09/02 1p
- --R0090B0414 LER B0-029/DIT-O on B00B19 during normal operation. CV-3031 was stroked closed & immediately reopened Caused by failure to follow procedural requirements related to plant conditions needed to perform test 4 Consumers Power Co. 80/09/02 ip
- 8009080418 Forwards LER 80-028/03L-0 HOFFMAN, D. P. Consumers Power Co. 80/09/02 1p
- --8009080426 LER 80-028/03L-0 on 800807, during normal power operations.

 low level alarm received from switch on 81 tank A (T 82 A)

 Apparently caused by slow leakage from tank Inaccuracy of analog channel attributed to liquid loss in ref leg

 * Consumers Power Co 80/09/02 ip
- 8007080432 Forwards updated LER 80-023/03X-1 HDFFMAN, D P Consumers Fower Co 80/09/02 1p
- ---8009080437 Updated LER 80-023/03X-1, on 800710, containment high radiation detectors RE 1805 & 1807 determined inoperable No apparent cause for failure Detectors disassembled, cleaned & recoated & are now functional + Consumers Power Co. 80/09/02 ip
- 8009120384 Farwards LER 80-030/03L-0 HOFFMAN D P Consumers Power Co 80/09/08 1p
- --8009120388 LER 80-030/03L-0 on 800811-during normal operation, discovered indicating lamps for CV-04378 & CV-04388 (indine removal sys tanks outlet valves) were not lit Caused by moisture in junction box resulting in blown fuses & Consumers Power Co. 80/09/08 1p
- BO09190565 EN-80-040 on 800916, notice of violation & notice of proposed imposition of civil penalties will be issued to ifcenses, based upon alloged items of noncompliance re operation of reactor plant sys

 BROCKETT, T W , THOMPSON, D Office of Inspection & Enforcement, Office of the Director 80/09/12 ip
- G009220285 Forwards NPDES noncompliance notification re turbine sump oil separator waste HOFFMAN. D P. Consumers Power Co. B0/09/16 | Ia

- --8009220289 NPDES noncompliance notification on 800818.weekly grab sample indicated 27 3 ng/l oil & grease Caused by oil separator sys ineffectively removing component oil in floor drains Oil absorbent pads will be placed throughout plant FOBES.R L Consumers Power Co 80/09/09 Ip
- 8009230612 Forwards updated LER 80-027/01%-1 HOFFMAN, D P Consumers Power Co 80/09/17 1p
- --8009230618 Updated LER 80-027/01X-1 on 800812 during venting of quench tank to waste gas surge tank gaseous release occurred w/o 15 day min holdup Caused by leaking isolation valve & valve pin disassembly Pin replaced 4 Consumers Power Co. 80/09/17 ip
- 8009260488 Forwards LERs 80-031/017-0 & 80-032/03L-0 FROST, S R Consumers Power Co 80/09/23 1p
- --8009260492 LER 80-031/01T-0 on 800826, group 1 control rads withdrew 121 inches which resulted in unplanned reactivity insertion Caused by loss of both primary & secondary data loggers Laggers restored & control rods reinserted + Consumers Power Co 80/07/23 1p
- 8009300484 Forwards LER 80-033/01T-0 HGFFMAN, D Consumers Power Co 80/09/25 1p
- --8009300487 LER 80-033/017-0 on 800911 during control rod exercising Rod 31 was misaligned Caused by rod insertion length Procedures revised to lessen insertion & remain within Tech Spec requirements HDFFMAILD P Consumers Power Co 80/09/25 to
- 8009300492 Forwards LER 80-034/031-0 HOFFMAN, D P Consumers Power Co 80/09/26 1p
- --8009300499 LER 80-034/03L-0 on 800826.during pretest review of check valve inservice insp survaillance, procedures required closing & reopening of STRR tank outlet valves Caused by inadaquate procedures Procedures revised HOFFMAN.D P Consumers Power Co 80/09/26 ip
- DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1
 F Security, medical, emergency & fire protection plans
- 8009120121 Forwards request for addl info re guard training & qualification Encl withheld (ref 100FR2 770)
 1PPOLITO, T A Operating Resitors Branch 2 80/08/22 2pp
- 8009230267 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency O'REILLY. J P Region 2. Atlanta Office of the Director 80/08/22
- 8009250272 Discusses will 800509 response re responsibility matrix of safeguards contingency plan.including interrelationships of contingency actions NRC cannot give formal approval until info is specifically submitted for approval 1 (PPOLITO, T A Operating Reactors Branch 2 80/09/09 2pp
- G Adjudicatory correspondence
- 8009220018 Forwards order requiring into supporting environ qualification of safety-related electrical equipment Requests submittal of info by 901101 IPPOLITO.T A Operating Reactors Branch 2 80/08/27 2pp
- --8009220019 Order for mod of Licenses DPR-33, DPR-52 & DPR-68 to add info which fully responds to MRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 80310! EISEMHUT, D O Division of Licensing 80/08/29 App
- H General correspondence
- 8009300316 Responds to 800808 ltr to JF Abearne re cheating on NRC OL exams while employed at facilities Allegation to be subj of inquiry headed by B Marsh
 STELLOV Office of Inspection & Enforcement, Office of the Director 80/09/19 ip

- --BC07300323 Guestions safety design of facilities SMITH, 0 Affiliation Unknown 80/09/24 ip
- --8009300327 Informs of unreported RD at facility re high radiation in offgas sys SMITH.O Affiliation Unknown 80/09/24 lp
- I Financial information
- 8007070543 Forwards Annual Financial Rept 1979 CRDSS.J L Tennessee Valley Authority 80/09/04 ip
- --8009090563 Annual Financial Rept 1979
 * Tennessee Valiey Authority 80/09/04 44pp
- P Operating license stage documents & correspondence
- 80071i0554 Suppis NRC 800707 request for proposed Tech Specs changes re scram discharge vol vent 3 drain valves. & reactor protection sys & control rod block limit switch surveillance requirements Class lil license fee to be submitted w/change EISENHUT.D G Division of Licensing 80/07/22 22pp
- 8009020297 Submits interim criteria for shift staffing to ail DL & CP licensees & applicants.per NRC 800507 itr Discussew administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D G Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT.D O Division of Licensing 80/08/01 119pp
- 8007230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lossons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D Q Division of Licensing 80/08/07 60pp
- 8009020318 Submits schröule for first 5 months of interim reliability evaluation program, annotated to highlight potential NRC participation Anticipated start date scheduled for 800915 EISENHUT.D O Division of Licensing 80/08/15 4pp
- 8009030406 Application to amend Licenses DPR-33.DPR-52 & DPR-68, changing Tech Specs re containment sys
 MILLS.L M Tennessee Valley Authority 80/08/19 2pp
- --8009030411 Proposed Tech Specs 3 7 & 4 7 re limiting conditions for operation & surveillance requirements for containment sys

 * Темпеssee Vailey Authority 80/08/19 47pp
- 8009190697 Forwards NUREO-0661, "Mark I Containment Long-Term Program SER Resolution of Generic Technical Activity A-7 " Rept discusses generic suppression pool hydrodynamic load definition H/o encl IPPOLITO.T A Operating Reactors Branch 2 80/08/20 2pp
- B007070367 Forwards response to NRC B00423 ltr requesting that util confirm conclusions of analysis re min ECCS equipment availability w/dc gower supply failure CRDS8.J L Tennessee Valley Authority 80/07/03 2pp
- 8009090555 Forwards corrected page to proposed Tech Bpecs 3 7 & 4 7 rs containment sys integrated leak testing.originally submitted on 800819 CROSS.J.L Tennessee Vailey Authority 80/09/03 3pp
- ---8007070560 Corrected page to proposed Tech Specs 3 7 & 4 7 recontainment sys integrated leak testing originally submitted on 800819
 * Tannessee Valley Authority 80/07/03 ip
- 8009160219 Forwards changes to Tech Specs Section & O for OL amend re administrative controls in response to NRC 800702 itr to all BWR licensees Changes are based on model specs provided in Encl i to itr Fee encl MILLS.L M Tennessee Valley Authority 80/09/09 2pp

- --B009160221 Proposed changes to Tech Spec Section 6 O re administrative controls based on model specs in NRC 800702 ltr to all BMR licenses
 - * Tennessee Valley Authority 80/09/09 9pp
- BOO9170206 Forwards comments re extent of util participation in Interim reliability evaluation program Phase II study, in response to DO Eisenbut 800725 ltr to HO Parris Decision on util performance of risk assessment will be made by mid-Oct 1980 MiLLS.L H Tennessee Valley Authority 80/09/09 3pp
- 8D09240545 Ack receipt of response to NRC 791109 questions re ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture Response is acceptable IPPOLITO,T A Operating Reactors Branch 2 80/09/10 2pp
- BOO9240601 Confirms util commitment to NRC 791023 "Interim Position on Containment Purging & Venting Pending Resolution of Isolation Valve Operability " Util position will remain in effect pending completion of NRC long-term review IPPOLITO.T A Operating Reactors Branch 2 80/09/10 2pp
- 8009220210 Notifies that 800731 application to amend Licenses DPR-33, DPR-52 & DPR-68 has not yet appeared as FR notice inforequested re-schedule for licensing & FR notice publication date
 MILLS, L M Tennessee Valley Authority 80/09/16 2pp
- BOOG19048B Application to amend Licenses DPR-33 & DPR-52 Forwards proposed Tech Spec changes clarifying requirements for RHR svc water sys & adding spec which allows standby coolant capability to be inoperable for specified period MILLS, L M Tennessee Valley Authority 80/09/17 2pp
- --8009190495 Proposed changes to Tech Specs clarifying requirements for RNR svc water sys & adding spec which allows standby coolant capability to be inoperable for period not to exceed 10 days
 * Tennessee Valley Authority 80/09/17 10pp
- 6009300400 Forwards technical questions re implementation of interlm policy on 10CFR50 & 51 MILLS,L M Tennessee Valley Authority 80/09/23 3pp
- 8009300147 Requests amend to DPR-33.DPR-52 & DPR-68.consisting of Tech Spec changes re reactor protection sys MILLS.L M Tennessee Valley Authority 80/07/24 2pp
- --B009300156 Proposed Tech Specs 1 0.3 3 & 4 3 re reactor protection sys * Tennessee Valley Authority B0/09/24 15pp
- 8009300393 Revises util 791106 schedulo for shipment of motor generator sets to be installed as part of LPC1 sys power supply mods Generator sets will be installed during Fall 1980 Unit 3. Spring 1981 Unit 1 & Spring 1982 Unit 2 outages MILLB.L M Tennessee Valley Authority 80/09/24 1p
- G Inspection reports, 1E Bulletins & correspondence
- BOO9090073 Forwards 1E Bulletin 80-07. Suppl 1, "BWR Jet Pump Assembly Failure" No response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/13 19
- BD09020184 Submits response to 1E Bulletin 77-03A No SA-312 or A-312. Type 300 series fusion welded pipe is in use or planned for use in safety-related sys MILLS,L M Tennesses Valley Authority B0/08/06 1p
- EOD7020222 Forwards IE Insp Repts 50-259/80-32, 50-260/80-23 & 50-276/80-26 on 800628-0704 No noncompliance nated D'REILLY, J. P Region 2, Atlanta, Office of the Director 80/08/08 2pp
- --B009020225 IE Insp Repts 50-257/80-32.50-260/80-25 & 50-276/80-26 on B0062B-0704 No moncompliance noted Major areas inspected ilcensee investigation of Unit 3 failure to fully insert control rods after 800628 scam
 DANCE-H. C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/09/08 18pp
- 8009030146 Forwards Revision 1 to IE Bulletin 80-17, "Failures of Mencury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Fower Plants Designed by C-E " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/15

- 8009020133 Forwards response to IE Bulletin 80-17. Suppl 1 re failure of control rods to insert during scram at BHR I tem B & scram discharge header sys will be modified to preclude necessity of level monitoring w/exception of instrument vol MILLS.L M Tennessee Valley Authority 80/08/18 2pp
- B009160045 Forwards IE Info Notice B0-30. "Potential for Unacceptable Interaction Detween Control Rod Drive Scram Function & Nonessential Control Air at Certain GE BWR Facilities "No specific action or response requested O'REILLY, J P Region 2. Atlanta, Defice of the Director B0/08/19 ip
- 8007190603 Ack receipt of 800815 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/80-22. 50-269/80-16 & 50-296/80-17 "ENNA.N B Region 2. Atlanta, Safeguards Branch 80/08/21 lp
- --8009190610 Forwards response to NRC 800717 ltr re violations noted in IE Insp Repts 50-259/80-22.80-260/80-16 & 50-296/80-17 Enci uithheld (ref 10CFR2 790) MILLS,L M Tennessee Valley Authority 80/08/15 ip
- --8009170617 Ack receipt of 800710 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-259/80-22, 50-260/80-16 & 50-296/80-17 Notes commitment to provide addiresponse within 20 days KENNA, W B Region 2, Atlanta, Safeguards Branch 80/07/17 ip
- --8009190643 Forwards response to NRC 800616 Itr re violations noted in IE Insp Repts 50-259/80-22,50-260/80-16 & 50-276/80-17 Encl withheld (ref 10CFR2 790) HILLS,L M Tennessee Valley Authority 80/07/10 Ip
- --8009190646 Forwards iE lnsp Repts 90-259/80-22.50-260/80-16 & 50-296/80-17 on 800519-23 & notice of violation Notice of violation withheld (ref 10CFR2 790)

 KENYA, W B Reglon 2. Atlantar Safeguards Branch 80/06/16 2pp
- --8009i90651 iE lnsp Repts 50-259/80-22,50-260/80-16 \$ 50-296/80-17 on 8005i9-23 Noncompliance noted incomplete vital area barrier. Inadequate lock installation & absence of portable radio in vehicle escort Details withheld (ref locra2 790) TILLMAN.A. TOBIN.W J. OILLESPIE.F P Region 2, Atlanta, Office of the Director 80/06/16 1p
- 8009120082 Forwards Suppl 3 to 1E Builetin 80-17. "Failure of Control Rods to Insert During Scram at BWR" Written response required O'REILLY, J P Region 2. Atlanta, Orfice of the Director 80/08/22
- B009160153 Forwards 1E Circular B0-18 "10CFR50 59 Gafety Evaluations for Changes to Radwaste Treatment Sys " No written response required D'REILLY,J P Region 2. Atlanta. Orfice of the Director B0/08/22
- 8009250075 Responds to 1E Bulletin 80-14. "Degradation of BWR Scram Discharge Vol Capability " Corrects error in 800728 responso re Item A 1 One Instance of broken rod on ball float also occurrod MILLS.L M Tennessee Valley Authority 80/08/26 ip
- B009120340 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-6005 & K-DON 6005 Circuit Breakers "
 No written response required O'REILLY, J.P. Rogion 2, Atlanta, Office of the Director 80/08/27
- 8009180068 Submits response to 1E Bulletin 80-19 No mercury-wetted matrlx relays are in use in reactor protection sys MILLS.L. N Tennessee Valley Authority 80/08/29 1p
- 8009180087 Bubmits response to 1E Bulletin 80-19 No mercury-wetted matrix relays are in use in reactor protection sys MiLLS.L M Tennessee Valley Authority 80/08/29 1
- 8009230521 Forwards Revision 1 to IE Bulletin 79-26, "Boron Loss From BMx Control Blades " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/29 ip
- 8009240261 Forwards response to IE Bulletin 80-17 re failure of control rods to fully insert during scram at BHR Plant instructions changed on 800827 to provide for manual scram & functional test This ty-five manhours expended in bulletin review MILLS, L M Tennessee Vailey Authority 80/08/27 3pp

- 8009240393 Forwards response to IE Bulletin 80-15 re possible loss of emergency notification sys u/loss of off-site power Design change request submitted Administrative procedure issued to compily w/requirements
 HILLS.t K Tennessee Valley Authority 80/08/29 4pp
- 8007240446 Forwards response to IC Bulletin 80-17 re failure of control rods to fully insert during scram at RMR Vent mod being coordinated w/overall scram distharge header ays review & mod program Schedule estimates will be provided MILLS.L M Tennesses Valley Authority 80/08/27 3pp
- 8009260375 Forwards IE Circular 80-21. "Regulation of Refueling Crews "
 No written response required
 O'REFILLY, J P Region 2, Atlanta, Office of the Director 80/09/10
 Sno
- 8009300529 Forwards Progress Rept 4 for 1E Builetin 80-06 re engineered safety features reset controls MtcLS.L M Temessee Valley Authority 80/09/10 7pp
- B009300060 Ark receipt of B00819 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-259/80-24, S0-260/80-16 & 50-296/80-17 LEMIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Oranch B0/09/(1 1)
- --8009300072 Forwards IE Insp Repts 50-259/80-24.50-260/80-18 & 50-294/80-19 on 800503-0601 & notice of violation LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 80/07/24 2pg
- --8009300075 Natice of violation from Insp on 800503-0401 * Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/07/15 | Ip
- --8009300081 IE Insp Repts 50-259/80-24,50-260/80-18 & 50-296/80-19 on 800503-0601 Noncompliance noted fallure to use latest revision of surveillance instruction data sheet SULLIVAN.R F. CHASE.J W Region 2. Atlanta. Office of the Director DANCE.H C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/07/15 7pp
- R Persodic operating reports & related correspondence
- 8009110352 Forwards "Radiological Impact Assessment,Browns Ferry Nucfear Plant,Jan-Jume 1980 " MILLS,L M Tennessee Valley Authority 60/08/29 lp
- --8009110353 "Radiological Impact Assessment Browns Ferry Nuclear Plant. Jan-June 1980 " 4 Tennessee Valley Authority RH-80-5-8F-3 80/08/29 44pp
- BOO9170274 Forwards monthly operating repts for Aug 1980 ABERCROMBIE.H Tennessee Valley Authority B0/09/17 is
- --8009170277 Monthly operating repts for Aug 1980 ABERCROMBIE, H., THOM, F., GREEN, D. Yennessee Valley Authority 80/09701 30pp
- S Reportable occurrences, LERs & related correspondence
- 8009190765 PND-78-147 on 780818, one of slx air compressors experienced massive failure resulting in rapid loss of control air pressure to all units Caused by large hole in cylinder head State of AL notified Media attention anticipated KLINGER.O. NDLAN.F., SMIETEK.J. Office of Inspection & Enforcement, Office of the Director 78/08/18 1p
- BO09190753 Provides interim assessment of PNO-78-147 re partial fallure to screm event Margin of safety inherent in licensed design basis should be promptly restored Improved temporary measure acceptable pending permanent mods
 MICHELSON.C Director's Office 80/08/18 3pp
- GOOOOOON TO TOWARDS LER BO-058/03L-0 CALHOUN, J R Tennessee Valley Authority 60/08/28 1p

- --8009030496 LER 80-058/03L-0 on 800728 during normal operation while performing \$1 4 1 A-14. pressure switches P8-1-81A & 8. turbine first stage pressure permissive setpoints found set above Tech Spec I Haft Caused by instrument drift Tennessee Valley Authority 80/08/28 2pp
- 8009030558 Forwards LER 80-057/03L-0 CALHOUN, J R Tennessee Valley Authority 60/08/30 1p
- --9009030556 LER 80-057/03L-0 on 800730, during past two refueling outages, required Tech Spec 4 6 G & testing was not performed Caused by testing not boing identified as outage work item Insp wiii be completed at next refueling outage * Tennessee Valley Authority 80/08/27 2pp
- 8009090557 Forwards LER 80-059/03L-0 CALHOUN,J R Tennessee Valley Authority 80/09/04 1p
- --B009090565 LER 80-059/03L-0 on 800010, during normal operation, lightning caused Athens 161 kV line to trip momentarily Cooling tower transformer tripped, causing loss of 4 kV tie board Cause of transformer trip unknown Athens line re-energized

 * Tennessee Valley Authority 80/09/04 2pp
- BOO9190465 Forwards LER 80-060/O3L-0 CALHOUN,J R Tennessee Valley Authority 80/09/12 1p
- --8009190524 LER 80-060/OGL-O on 800814.during normal operation,8 core spray pump area cooler fan thermostat T8-64-73 setting was above Tech Spec limit. Caused by setpoint being moved Thermostat reset Caution signs posted to prevent recurrence - Tennessee Valley Authority 80/09/12 lp
- 8009190467 Forwards LER 80-051/03L-0 CALHOUN, J R Tennessee Valley Authority 80/09/12 ip
- --B009190619 LER B0-061/03L-0 on B00814.during normal operation.thermal overload on IA residual heat removal area cooler fan breaker tripped Caused by thermal overload being improperly set Overload reset & properly adjusted
 -- Tennessee Valley Authority 80/09/12 2pp
- 8009230705 Forwards LER 80-063/03L-0 CALHOUN, J R Tennessee Valley Authority 80/09/16 1p
- --9009230714 LER 80-063/03L-0 on 800820, during normal operation, CAM-1~RH-90-251 for turbine bidg roof vent removed from svc for period exceeding 1-h due to failure of Schwitzer Series 325 Model 145473 vacuum prump Pump replaced
 * Tennessee Valley Authority 80/09/16 2pp
- 8009180400 LER 79-010 has been cancelled * Tennessee Valley Authority 80/09/17. Ip
- 8009180402 LER 79-014 has been cancelled * Tannessee Valley Authority 80/09/17 ip
- 8009230716 Forwards LER 80-064/03L-0 CALHDUN, J R Tennesses Valley Authority 80/09/17 ip
- ~-8009230728 LER 80-064/03L-0 on 800820, during normal operation, CAM-1-RM-90-249 for turbine bldg roof vents removed from syc for period exceeding 1-h Caused by personnel error Personnel cautioned to observe time limit

 * Tennessee Valley Authority 80/09/17 2pp
- 8009290345 Forwards LER 80-065/03L-0 CALHOUN, J.R. Tennesses Valley Authority 80/09/22 ip
- --8009290347 LER 80-065/03L-0 on 800828, during normal operation, wind direction indication was lost at elevation 887 min/sec Limiting condition for operation was entered Caused by noisy potentiometer Potentioneter was replaced * Tennessee Valley Authority 80/09/22 2pp
- 8009300562 Forwards LER 80-068/01T-0 CALHOUN, J R Tennessee Valley Authority 80/09/22. 1p
- ~-8009300567 LER 80-068/01T-0 on 800901, fire protection sys insp not performed as required by Tach Spec Caused by failure to obtain consultant sycs within specified time interval, insp to be performed at earliest possible date CALHOUN, J.R. Tennessee Valley Authority 80/09/22 ip
- 8009300516 Forwards LER 80-069/03L-0 CALMOUN, J. R. Tennessee Valley Authority 80/09/26 1p

- --8009300521 LER 80-069/03L-0 on 800902.while performing SI 4 2 A-17, Channel B of refueling zone isolation static pressure permissive & static pressure logic sys damper 0-PDC64-8 failed to close Contacts adjusted

 * Tennessee Valley Authority 80/09/26 2pp
- DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8009120121 Forwards request for add1 info re guard training & qualification Enc1 withheld (ref 100FR2 790)

 1PPOLITO, T A Operating Reactors Branch 2 80/08/22 2pp
- BO09230267 Requests that all personnel be reminded of purpose of amergency notification sys & health physics network Sys installed for govt use during emergency O'REJLLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22
- 8009250272 Discusses util 800509 response re responsibility matrix of safeguards contingency plan, including interrelationships of contingency actions NRC cannot give formal approval until info is specifically submitted for approval IPPOLITO, T A Operating Reactors Branch 2 80/09/09 2pp
- Q Adjudicatory correspondence
- BO0922001B Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by B01101 IPPOLITO, T A Operating Reactors Branch 2 B0/08/29 2pp
- --8009220019 Order for mod of Licenses DPR-33, DPR-52 & DPR-68 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 80(10) EISENHUT, D 0 Division of Licensing 80/08/27 App EISENHUT, D 0
- H General correspondence
- 80093003i6 Responds to 800808 ltr to JF Ahearne re cheating on NRC OL exams while employed at facilities Allegation to be subj of inquiry headed by B Marsh STELLO,V Office of Inspection & Enforcement, Office of the Director 80/09/19 tp
- --8009300322 Alieges cheating on NRC OL exams at facility Ltr to HJ Green offering to expose cheating encl SMITH,O Affiliation Unknown 80/08/08 3pp
- ---8009300325 Questions safety design of facilities SMITH. G Affiliation Unknown 80/09/24 ip
- --8009300327 Enforms of unreported RD at facility re high radiation in offgas sys. SMITH, G Affiliation Unknown 80/09/24 ip
- f Financial information
- BOC9090543 Forwards Annual Financial Rept 1979 CROSS.J L Tennesses Valley Authority 80/4 80/09/04 1p
- --B009090563 Annual Financial Rept 1979
 * Tennessee Valley Authority B0/09/04 44pp
- P Operating license stage documents & correspondence
- BOO9110354 Buppls NRC BOO707 request for proposed Tech Spacs changes re stram discharge vol vent & drain valves, & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT, D O Division of Licensing 80/07/22 22pp
- 8D09020297 Bubmits interim criteria for shift staffing to all DL & CP licensess & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D 9 Division of Licensing 80/07/31 7pp
- 8D070B00B0 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 enci Wo NUREO EISENHUT, D O Division of Licensing 80/08/01 119pp

- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D G Division of Licensing 80/08/07 60pp
- 8009030406 Application to amend Licenses DPR-33.DPR-52 & DPR-68. changing Tech Specs re containment sys MILLS,L M Tennessee Vailey Authority 80/08/19 2pp
- ~-B009030411 Proposed Tech Specs 3 7 & 4 7 re limiting conditions for operation & surveillance requirements for containment sys * Tennessee Valley Authority 80/08/19 47pp
- 8009190697 Forwards NUREO-0661, "Mark I Containment Long-Term Program SER Resolution of Generic Technical Activity A-7 " Rept discusses generic suppression pool hydrodynamic load definition W/o encl IPPOLITO.T A Operating Reactors Branch 2 80/08/20 2pp
- 8009030508 Application for amend to License DPR-52, changing Tech Specs to reflect new primary conteinment atmospheric hydrogen instrumentation to be installed during upcoming refueling outage Changes suppl 800714 changes
 MILLS.L M Tennessee Valley Authority 80/08/29 2pp
- --B009030514 Proposed Tech Specs 3 7.4 7 & Table 3 2 F re containment sys Description of primary containment hydrogen monitoring sus encl
 - Tennesses Vailey Authority 80/08/29 5pp
- B009090367 Forwards response to NRC 800425 ltr requesting that util confirm conclusions of analysis re min ECCS equipment availability w/dc power supply failure
 CROSS.J L Tennessee Valley Authority B0/09/03 2pp
- 8009090555 Forwards corrected page to proposed Tech Specs 3 7 & 4 7 recontainment sys integrated leak testing originally submitted on 800819 on BOOB19 CROSS, J.L. Tennessee Valley Authority BO/09/03 3pp
- --8009090960 Corrected page to proposed Tech Specs 3 7 % 4 7 re containment sys integrated leak testing originally submitted on 800819
 - Tennessee Valley Authority BO/09/03 ip
- 8009160219 Forwards changes to Tech Specs Section 6 0 for OL amend re administrative controls in response to NRC 800702 itr to all 8WR licensees Changes are based on model specs provided in Encl i to itr Fee encl MILLS.L N Tennessee Valley Authority 80/09/09 2pp
- -8009140221 Proposed changes to Tech Spec Section 4 0 re administrative controls, based on model specs in NRC 800702 ltr to all BUR
 - Tennessee Valley Authority 80/09/09 9pp
- 8007240545 Ack receipt of response to NRC 791107 quastions re ECCS evaluation models dealing w/foel cladding, swelling & incidence of rupture Response is acceptable IPPOLITO T A Operating Reactors Branch 2 80/09/10 2pp
- 8009240601 Confirms util commitment to NRC 791023 "Interim Position on Containment Purging & Venting Pending Resolution of Isolation Valve Operability "Util position will remain in effect pending completion of NRC long-term review IPPQLITG.T A Operating Reactors Branch 2 80/09/10 2pp
- 8009220210 Notifies that 800731 application to amend Licenses DPR-33, DPR-52 & DPR-68 has not yet appeared as FR notice info requested re schedule for licensing & FR notice publication MILLS, L M Tennesses Valley Authority 80/09/16 2pp
- 8009190488 Application to amend Licenses DPR-33 & DPR-52 Forwards proposed Tech Spec changes clarifying requirements for RHR svc water sys & adding spec which allows standby coolant capability to be inoperable for specified period MILLG.L M Tennessee Valley Authority 80/09/17 2pp
- --8009190495 Proposed changes to Tech Specs clarifying requirements for RHR svc water sys & adding spec which allows standby coolant capability to be inoperable for period not to exceed 10 days * Tennessee Valley Authority 80/09/17 10pp
- 8009300400 Forwards technical questions re implementation of interim policy on iOCFR50 t 51
 MILLS,L M Tonnessee Valley Authority 80/09/23 3pp

- G009300147 Requests amend to DPR-33.DPR-52 & DPR-68.consisting of Tach Spec changes re reactor protection sys MILLS.L M Tennessee Valley Authority E0/09/24 2pp
- --8009300156 Proposed Tech Specs & 0.3 3 & 4 3 re reactor protection sys
- 8009300333 Revises util 79t106 schedule for shipment of motor generator sets to be instalted as part of LPCI sys power supply mods Generator sets will be installed during Fall 1780 Unit 3. Spring 1982 Unit 3 Spring 1982 Unit 2 outages
 MILLG.L M Tennosses Valley Authority 80/09/24 1p
- Q Inspection reports, IE Bulletins & correspondence
- 8009090073 Forwards IE Bulletin 80-07, Suppl 1, "GWR Jet Pump Assembly failure" No response required
 O'REILLY.J P Region 2, Atlanta, Office of the Director 80/05/13
 lp
- 8007020184 Submits response to iE Bulletin 79-03A No SA-312 or A-312. Type 300 series fusion wolded pipe is in use or planned for use in serety-related sys MILLS, L M Tennessee Valley Authority 80/08/06 ip
- 8009020222 Forwards IE losp Repts 50-259/80-32,50-260/80-25 & 50-286/80-26 on 800628-0704 No noncompliance noted O'REILLY, J P Region 2, Atlanta, Défice of the Director 80/08/08 2pp
- ~~8009020225 [E Insp Repts 50~259/80~32.50~260/80~25 & 50~296/80~26 on 800628~0704 No noncompilance noted Najor areas inspected licensee investigation of Unit 3 Pailure to fully insert control rods after 800628 scam DANCE.H C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/08/09 18pp
- 8009030146 Forwards Revision 1 to IE Bulletin 80-17, "Failures of Mercury-Wetted Natrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Mritten response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/15 ip
- 8009020133 Forwards response to 1E Bulletin 80-17. Suppl i re failure of control rods to insert during scram at BMR I tem B i scram discharge header sys will be modified to preclude necessity of level monitoring wesception of instrument vol MILLS.L K Tennessee Valley Authority 60/08/18 2pp
- 8009160045 Forwards iE Info Notice 80-30. "Potential for Unacceptable Interaction Between Control Rod Drive Scram Furction & Nonessential Control Air at Certain GE BUR Facilities "No specific action or response requested O'REILLY.J P Region 2. Atlanta. Office of the Director 80/08/19
- 8009190603 Ack receipt of 800815 ltr informing NRC of steps taken to correct violations noted in 16 Insp Repts 50-259/80-22, 50-260/80-16 & 50-296/80-17 KERNA, W 3 Region 2. Atlanta. Safeguards Branch 80/08/21 1p
- --8009190610 Forwards response to NRC 800717 ltr re violations noted an IE lnsp Repts 50-259/80-22,50-260/80-16 & 50-296/80-17 Encl unthheld (ref 100FR2 790) MCLL5.L M Tennessee Valley Authority 80/08/15 ip
- --8009190617 Act receipt of 800710 ltr informing NRC of steps taken to correct violations noted in 1E lnsp Repts 50-259/80-22, 50-260/80-16 & 50-296/80-17 Nates commitment to provide additections within 20 days

 KERNA.N B Region 2. Atlanta, Safeguards Branch 80/07/17 1p
- --8009190643 Forwards response to NRC 800616 ltr re violations noted in IE Insp Repts 50-289/80-22,50-260/80-16 & 50-296/80-17 Encl withheld (ref 10GFR2 790) MILLS,L N Tennessee Valley Authority 80/07/10 [p
- -8007170646 Forwards IE Insp Repts 50-259/80-22,50-260/80-16 & 50-276/80-17 on 800519-23 & notice of violation Notice of violation withheld (ref 10CFR2 790)
 KENNA.H B Region 2. Atlanta, Safaguards Branch 80/06/16 2pp
- 6009190651 IE Insp Repts 50-259/80-22,50-260/80-16 & 50-296/80-17 on B00519-23 Noncompliance noted incomplete vital area barrier, inadequate lock installation & absence of portable radio in vahicle escort Details withheld (ref 10CFR2 790) TILLMANA A . TOBIN W J . GILLESPIE, F P Region 2, Atlanta, Office of the Director 80/06/16 ip

- 8009120082 Forwards Suppl 3 to IE Suiletin 80-17, "Failure of Control Rods to Insert During Scram at BWR" Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 60/08/22
- 8007160153 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Bys " No written response required O'REILLY. J P Region 2. Atlanta, Office of the Director 80/08/22 ip
- 8009250075 Responds to IE Bulletin 80-14, "Degradation of BWR Stram Discharge Vol Capability " Corrects error in 800728 response re Item A i One instance of broken rod on ball flust also occurred MILLS,L M Tennessee Valley Authority 80/08/26 ip
- 8007120340 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/27 lp
- 8009230521 Forwards Revision i to IE Builetin 79-26. "Boron Loss From BUR Control Blades" Written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/29 in
- 8009240261 Forwards response to iE Bulletin 80-i7 re failure of control rods to fully insert during scram at BWR Plant instructions changed on 800827 to provide for manual scram & functional test Thirty-five manhours expended in bulletin review MILLS.L M Tennessee Valley Authority 80/08/29 3pp
- 8009240383 Forwards response to IE Bulletin 80-15 re possible loss of emergency notification sys w/loss of offsite power Design change request submitted Administrative procedure issued to comply w/requirements
 HILLS.L M Tennessee Valley Authority 80/08/29 4pp
- 8007240446 Forwards response to iE Bulletin 80-i7 re failure of control rods to fully insert during scram at BWR Vent mod being coordinated w/overall scram discharge header sys review & mod program Schedule estimates will be provided KILLS.L M Tennessee Valley Authority 80/08/29 3pp
- 8009260375 Forwards iE Circular 80-21, "Regulation of Refueling Craws" No wratten response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/10-588
- 8009300529 Forwards Progress Rept 4 for IE Bullstin 80-06 re engineered safety features reset controls MILLS.L M Tennessee Valley Authority 80/09/10 7pp
- 8009306060 Ack receipt of 800819 itr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-259/80-24, 50-269/80-18 & 50-296/80-19 LENIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 60/09/11 1p
- ---8009360067 Forwards response to NRC 800724 ltr re violation noted in It insp Repts 50-259/80-24.50-260/80-18 & 50-296/80-19 Corrective actions, autoated surveillance instruction sheets replaced w/current revisions MILL8.L M Tennessee Vailey Authority 80/08/19 2pp
- --8009300072 Forwards IE insp Repts 50-259/80-24,50-260/80-18 & 50-276/80-19 on 800503-0601 & netice of violation LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/07/24 2pp
- --8009390075 Notice of violation from insp on 800503-0601 * Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/07/15 1p
- ---80093000B1 IE Insp Repts 50-259/80-24,50-260/80-18 & 50-296/80-19 on E00503-Q601 Nuncompliance noted failure to use latest revision of surveillance instruction data sheet SULLIVAN.R F. CHASE.J.W Region 2, Atlanta, Office of the Director DANCE.H.C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/07/15 7pp
- R Periodic operating reports & related correspondence
- 8009110352 Forwards "Radiological Impact Assessment, Browns Ferry Nuclear Plant, Jan-June 1980 " MILLS, L M Tennessee Valley Authority 80/08/29 1p

- --B009110353 "Radiological Impact Assessment Browns Ferry Nuclear Plant. Jan-June 1980 " * Yennessee Vallsy Authority RH-80-5-8F-3 80/08/29 44pp
- 80G9170274 Forwards monthly operating repts for Aug 1980 ASERCROMBIE, H Tennessee Valley Authority 80/09/17 1
- --8009170277 Monthly operating repts for Aug 1980 ABERCROM81E.H , THOM.T , GREEN.D Tennessee Valley Authority 80/09/01 30pp
- S Reportable occurrences, LERs & related correspondence
- 8009190765 PNO-78-147 on 780818, one of six air compressors experienced massive failure resulting in rapid loss of control air pressure to all units Caused by large hole in cylinder head State of AL notified Middle attention anticipated KLINGER: 0 , NOLAN.F , SNIEZEK, J Office of Inspection & Enforcement, Office of the Director 78/08/18 19
- 8007190753 Provides interim assessment of PNO~78-147 re partial failure to scram event Margin of safety inherent in licensed design basis should be promptly restored Improved temporary measure acceptable pending permanent mods
 MICHELSON, C Director's Office 80/08/18 3pp
- 8009090467 Forwards LER 80-031/01T-0 CALHOUN.J R Tennessee Valley Authority 80/08/29 ip
- --8007070481 LER 60-031/01T-0 on 800811 during normal operation, two nodes in fuel assambly T2 396 exceeded upper boundary limits for max average planar linear heat generation rate Caused by failure to incorporate revised limits into Tech Specs Tennessee Valley Authority 80/08/29 2pp
- BOOG9890445 Forwards LER 80-030/03L-0 CALHDUN.J R Yennessee Valley Authority 80/09/04 1
- --8007070462 LER 80-030/03L-0 on 800811.during normal operation, performing Surveillance Instruction 4 2 B 69.pressure switches PB-3-204A & PB-3-204B found outside limits Caused by setpoint drift Switches recalibr & tested = Tennessee Valley Authority 80/09/04 2pp
- 8009090490 Forwards LER 80-032/03L-0 CALHOUN.J R. Tennessee Valley Authority 80/09/05 tp
- --8009090509 LER 80-032/03L-0 on 800812. w/unit at steady state 94%, performing surveillance instruction 4 5 E 1 d & e.HPCI turbine tripped Caused by failure of teflon sheet portion of rupture disc. resulting in inadequate protection W Tennexsee Valley Authority 80/09/05 2pp
- E009160432 Forwards LER 80-033/03L-0 CALHOUN.J R. Tennessee Valley Authority 80/07/08 lp
- --B009160440 LER 80-033/03L-0 on B00B15.w/unit at 93% power in steady state operation.indicated leak on RHR heat exchanger 2B found during T1-36A Probably caused by leaking gasket.due to boose flange nuts as result of thermal cycling & vibration a Tennessee Valley Authority 80/09/08 2pp
- BOO9160454 Forwards LER 80-034/03L-0 CALHOUN, J R Tennessee Valley Authority BO/09/08 lp
- ---B009160466 LER B0-034/03L-0 on B00815.w/unit at 94% power in steady state operation, RHR heet exchange 2C found leaking during TI-36A Caused by loose lock nuts & Full nuts due to thermal cycling & vibration resulting in gasket leak # Tennessee Valley Authority 80/09/08 2PP
- BOO9190440 Forwards LER 80-033/03L-0 GALHOUN, J R Tennessee Valley Authority 80/09/12 ip
- --ECO9190454 LER BO-035/03L-O on BOOB30, during normal operation while performing TI-36, increase in pressure on shell side of RHR heat exchanger 2D was detected Caused by leaking check valve between heat exchangers

 Tennessee Valley Authority 80/09/12 3pp
- BCO9180379 LER 79-020 has been cancelled * Tennessee Valley Authority B0/09/17
- BO0930054B Farwards LER B0-036/03L-0 CALHOUM, J. R Tennessee Valley Authority 80/09/26 lp

- --8009300554 LER 80-036/03L-0 on 800829, while performing 5 I 4 7 4, H2E76-39 hydrogen monitor for drywell would not calibr Caused by sensor type 47E22642862 failure Sys will be replaced

 Tennessee Valley Authority 80/09/26 2pp
- DOCKET 50-261 H B ROBINSON PLANT, UNIT 2
- F Security, medical, emergoncy & fire protection plans
- 8009230252 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/22 in
- G Adjudicatory correspondence
- 8009230124 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 VARGA.B A Operating Reactors Branch 1 80/08/27 2pp
- ---B009230130 Order for mod of License DPR-23 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by B01101
 EIBENHUT: D 0 Division of Licensing 80/08/29 App
- H General correspondence
- 8009120437 Advises of BMR owners group organizational changes & that future correspondence be forwarded to DB Waters Future requests for util action should be addressed to individual licensees & applicants
 WATERS.D B Carolina Power & Light Co 80/07/02 2pp
- BOO9120437 Advises of BWR owners group organizational changes & that future correspondence be forwarded to DB Waters Future requests for util action should be addressed to individual licensees & applicants
 WATERB.D B Carolina Power & Light Co 80/07/07 2pp
- P Operating license stage documents & correspondence
- 8009020297 Submits interim criteria for shift staffing to all GL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D O Division of Licensing 80/07/31 7pp
- 9007080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl H/o NUREO EISENHUT, D O Division of Licensing 80/08/01 117pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend, EISENHUT, D & Division of Licensing 80/08/07 60pp
- 8008210180 Responds to 800709 itr requesting interpretation of ANSI N45 2 10 rm longhand signature on certificates of conformance Recommends forwarding details to ASME for official interpretation HAASS.W P Quality Assurance Branch 80/09/12 1p
- 8009190794 Forwards revised Westinghouse STS 3 9 8 2/3 9 10 % Bases 3/4 9 8 % 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required NDVAW.T M Assistant Director for Operating Reactors 60/08/15 ip
- --8009190817 Revised Westinghouse 8TS 3 9 8 2,3 9 10 & Bases 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods # Assistant Director for Operating Reactors 80/06/23 21pp
- 8009180107 Forwards Amend 48 to License DPR-23, safety evaluation & notice of issuance & availability
 VARGA.8 A Operating Reactors Branch 1 80/08/29 2pp

- --BCO7180113 Amend 48 to License DPR-23, revising Tech Space re control red position indication sys misalignment limits VARGA, S.A. Operating Reactors Branch 1 80/08/29 7pp.
- --8009160116 Safaty evaluation supporting Amend 48 to License DPR-23 • Office of Nuclear Reactor Regulation, Director 80/08/29 2pp
- --8009180122 Notice of issuance & evailability of Amend 48 to License DRR-23 NEIGHBURS.J D Operating Reactors Branch 1 80/08/29 2pp
- 8009250262 Submits application for amend revising util 791003 proposed OL amend re degraded grid voltage Error in 1tem 6 a due to difference in setpoint rounding for Tech Specs & mod UTLEY.E £ Carolina Power & Light Co 80/09/19 2pp
- Q Inspection reports, If Bulletins & correspondence
- 8009100042 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side Hegh Energy Line Rupture " Written response required O'AEJLLY. J P Region 2. Atlanta. Office of the Director 80/07/24 Ip
- 800702017B Submits response to IE Bulletin 79-03A re longitudinal weld defects in SA-312 stainless steel pipe Required info will be provided by 800722 FURR.B J Carolina Power & Light Co 80/08/05 lp
- 8007030307 Requests extension until 800722 to respond to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe "Bactground info necessary to perform engineering evaluation was only recently received FURR. 8 J Carolina Power & Light Co 80/08/06 ip.
- 8009300051 Ferwards 1E Insp Rept 50-261/80-15 on 800624-0702 No moncompliance noted LEWIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/09/14 2pp
- --8009300063 IE lasp Rept 50-261/80-15 on 800624-0702 No noncompliance noted Major areas inspected general plant operations, follows insport of outstanding items & review of plant safety committee meeting minutes the safety with the safety of the NITENER, H. L. OUICK, D.R. Region 2, Atlanta, Office of the Director 80/08/14 3pp
- B009030169 Forwards Revision I to IE Bulletin B0-19, "Failures of Hercury-Wested Hatris Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/08/15
- 8009300069 Forwards 1E Insp Rept 50-261/80-16 on 800707-18 No noncompliance noted LEWIS,R C Region 2, Atlanta, Reactor Operatione Nuclear Support Branch 80/08/15 2pp
- --8009300073 IE Insp Rept 50-261/80-16 on 800707-18.No noncompliance noted Major areas inspected operations, fullowup of LERs & bulleting SKOLDS.J L . XELLDGO.P J Region 2, Atlanta, Office of the Director. 80/08/15 Spp
- 8009240348 Responds to IE Bulletin 80-20 No Westinghouse Type M-2 switches, incorporating use of normally closed contact in newtral or socomatic start position, used in safety-related applications
 FURR, B J Caroline Power & Light Co 80/09/21. 1p
- 8009160124 Forwards IE Circular 80-18, *100FR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/08/22 to
- 8009120228 Responds to IE Bulletin 80-19 Mercury-Wetted matrix relays are not used in reactor protection sys FURR.B J Carolina Power & Light Co 80/08/26 to
- 8009120290 Forwards IE Info Notice 80-31, "Maloperation of Quild-Brown Boveri 480 Volt Type K-6008 & K-DON 6005 Circuit Breakers."
 No written response required. 0ffice of the Director 80/08/27 in

- 8007110271 Responds to IE Sulletin 79-01B, supplementing 800707 response Forwards 90-day rept re environ qualification of electrical equipment EURY.L W Caroline Power & Light Co 80/08/29 15pp.
- 8009270287 Forwards IE Circular 80-21. "Regulation of Refueling Crew."
 No written response required
 U'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/10
 Spp
- R Periodic operating reports & related correspondence
- BOO7169255 Forwards monthly operating rept for Aug 1980 STARKEY, R. B Carolina Power & Light Co 80/09/10 ip
- --8009160258 Monthly operating rept for Aug 1980 WATFORD, M Carolina Power & Light Co 80/09/07 3pp
- S Reportable occurrences. LERs & related correspondence
- 8007030457 Forwards LER 80-017/03L-0 STARKEY,R B Carolina Power & Light Co 80/08/29 ip
- --8009030463 LER 80-017/03L-0 on 800730 while performing air flow test. CPL-PT-24 0.positioner on Grad-U-Motor failed to function properly Caused by accumulation of moisture in air supply line. Orad-U-Motor & positioner were removed from svc STARKEY, R B Carolina Fower & Light Co 80/08/29 2pp
- 8009180286 Forwards LER 80-018/03L-0. STARKEY,R B Carolina Fower & Light Co 80/09/10 1p
- --8009150289 LER 80-018/03L-0-on 800011, w/unit in refueling shutdown condition & while performing refueling period test GPL-PT-2 1, valve PCV-1716 failed to close due to isolation override switch being on Cause not determined STARKEY, R B Carolina Power & Light Co 80/09/10 2pp
- 8009190449 Forwards updated LER 80-015/017-1 STARKEY,R B Carolina Power & Light Co 80/09/15 ig
- --8009190477 Updated LER 80-015/01T-1 on 800823 three Westinghouse most NBFD-315 relays used in reactor protection sys failed within 28 days Caused by open circuit & short circuit coil failures
 STARKEY, R B Carolina Power & Light Co 80/09/15 2pp
- 8007250301 Forwards LER 80-019/03L-0 STARKEY,R B Carolina Power & Light Co. 60/09/19 1p
- --8009250304 LER 80-019/03L-0 on 800822 during refueling outage shutdow small pinhols leaks & linear defects on campy seel welds discovered Caused by weld degradation Defects repaired & nondestructive examination performed STARKEY, R B Carolina Power & Light Co. 80/09/19 4pp
- DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT
 F Becurity, medical, emergency & fire protection plans
- 8009030688 Forwards IE Health Physics Appraisal Rept 50-263/80-11, notice of violation & significant appraisal findings KEPPLER.U G Region 3. Chicago. Office of the Director 80/08/07 4pp
- --B009030A91 Notice of violation from health physics appraise1 on 800A09-20 * Region 3. Chicago, Office of the Director 80/08/01 ip.
- --8009030595 IE Health Physics Appraisal Rept 50-263/80-11 Noncompliant noted inadequate radiation areas access controls & inadequate posting of radiation areas HILLER, D.E. LOVENDALE, P.C. FISHER, W.L. Region 3, Chicago, Office of the Director 80/08/01 25pp
- 8009030381 Forwards Revision 1 to safeguards contingency plan Plan withheld (ref 10CFRZ 790) MAYER,L.O Northern States Power Co 80/08/20 ip
- 8008260337 Forwards draft upgraded emergency plan MAYER. L O Northern States Power Co 80/08/21, 1p
- --8008260340 Draft upgraded emergency plan * Northern States Power Co 80/08/15 130pp

10

, |

, , ,

- 8009030524 Requests that completion date for fire protection mod be extended to 801031 due to unanticipated problems in project design & heavy consultant & operating staff work loads MAYERL 0 Northern States Power Co 80/08/22 ip
- 8009230305 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency KEPPLERIJ O Region 3, Chicago, Office of the Director 80/08/22 300.
- 8039020055 Forwards 800410 "Emergenty Preparedness Evacuation Time Estimates." Revision 1 Conforms to revised vehicle per hour capacity of state highway & country roads within 10-mile radius of facility

 MAYER.L D Northern States Power Co 80/08/25 1p
- --8007020060 Evacuation time estimates form areas near facility
 * Morthern States Power Co 80/08/31 18pp
- 8007020009 Forwards add1 info re two fire protection mods planned for facility Complete failure of turbine lube oil reservoir unlikely During emergency. 12-inch drain line can be used to drain reservoir to outside underground tank MAYERIL O Northern States Power Co 80/08/26 2pp
- 8009240700 Notifies that facility security plan does not establish assequate commitment to meet code requirements Amend incorporating encl change is required within 60 days IPPOLITO, T A Operating Reactors Branch 2 80/09/07 3pp
- B009260017 Transmits emergency planning info to be made available to public at LPDR in Minneapolis.MN W/o enci SOUDER, J.L. Division of Ruies and Records B0/09/11 1p
- 8009190473 Requests add1 time for completion of work re fire protection mods Problem w/reactor core isolation cooling has become one of qualifying.procuring & engineering new control logic sys Task shall be completed by May 1781

 MAYER.L O Northern States Power Co 80/09/12 2pp
- G Adjudicatory correspondence
- 8D09240012 Responds to FOIA request for nine categories of documents re AEC amend to 10CFR50 57(c) proposed on 701028 & adopted on 710514 Forwards documents listed in App A responding to Items I-5 Bearch is continuing for addI records FELTON, J B Division of Ruies and Records 80/08/21 2pp
- --8009240125 Requests settiment of privilege controversy in proceeding re submission of rulings to ASLB Pending settlement ASLD cannot rule on util license for operation w/reactor vessel head in place Refs encl GEYER, J. C., GREULINO.E., DEALE, V.B. Atomic Bafety and Licensing Board Panel. 70/10/06 18pp
- 8009220098 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101
 IPPOLITO, TA Operating Reactors Branch 2 80/08/29 2pp
- --8009220101 Order for mod of License DPR-22 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101
 EISENMUT, D Q Division of Licensing 80/08/29 App
- BOO9080518 Memorandum & order ALAB-611, concurring w/A9LB conclusion that facility may continue to operate safely pending resolution of ATMS issue NRC shall suppl record re unrasolved generic safety issues by 801015.
 BIEHOP.C J Atomic Safety and Licensing Appeal Panel 80/09/03 22pp.
- G009120403 Memorandum amending Footnate 11 on Page 16 of ASLAB 800903 memorandum & order ALAB-611 Publication printed copy will reflect amend
 BISHOP.C J Atomic Safety and Licensing Appeal Panel G0/09/10
- P Operating license stage documents & correspondence
- EOO9110554 Supple NRC 800707 request for proposed Tech Specs changes rescrare discharge vol vent & drain valves, & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT.D G Division of Licensing 80/07/22 22pp

- 8009020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D G Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed Implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREO EISENHUT,D 0 Division of Licensing 80/08/01 119pp
- 8007230052 Informs that exemption from fee re licensing action associated w/TM1-2 Lessons Learned is unjustified Provious determination should be disregarded Requested submittal should include proposed class of amend Else/
- 8009040125 Advises that two specific Event 5 valve configurations do not exist at facility per review of response to NRC 800223 ltr "Frimary Coolant Sys Pressure Isolation Valves," technical evaluation rept encl IPPOLITO, T A Operating Reactors Branch 2 80/08/08 3pp
- --BC07040129 "Primary Coolant Sys Pressure Isolation Valves. Northern States Power Co.Monticeilo Unit i." technical evaluation rept NOELL.P N . STIMELL.T C Franklin Institute/Franklin Research Center NRC-03-79-118 80/07/21 5pp
- 8009230243 Forwards NUREO-0661, "Mark I Containment Long-Term Program BER, Resolution of Generic Technical Activity A-7 " Rept describes NRC review results re generic suppression pool hydrodynamic load definition U/o encl IPPOLITO, T A Operating Reactors Branch 2 80/09/20 2pp
- B009090775 Advises that util response to NRC 791109 ltr re portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture is acceptable No further action necessary iPPOLITO.T A Operating Reactors Branch 2 80/08/22 2pp
- 8009090375 Responds to NRC 800425 request for evaluation to consider loss of equipment due to water spillage No addl ECCB equipment would be affected by water spillage Util 800530 list of equipment remains unchanged MAYER.L O Northern Statas Power Co 80/08/28 lp
- 8009120579 "Degraded Grid Protection for Class IE Power Sys For Monticello Nuclear Generating Plant," technical evaluation rept CLEVELAND, C J Eg&G idaho, Inc FIN A-6256 8009120579 80/08/31 14aa
- 8009240110 "Technical Evaluation Rept on Degraded Orid Protection for Class IE Power Sys for Monticelio Nuclear Generating Plant," Revision 2 CLEVELAND, C J EGAG idaho, Inc FIN A-6256 8009260110 80/08/31
- 8009190084 Advises that commitments to NRC 791023 "Interim Position on Containment Purging & Venting Pending Resolution of isolation Valve Operability:" are acceptable & will remain in effect pending completion of NRC long-term review IPPOLITO.T A Operating Reacters Branch 2 80/09/03 2pp
- BD091904B6 Notifies of deiay until 80iii4 for submittal of proposed Tech Specs for Lessons Learned Category A requirements. requested by NRC 800702 ltr MAYEN.L O Northern States Power Co 80/09/12 2pp
- Q Inspection reports, IE Builetins & correspondence
- 8009090050 Forwards IE Bulletin 80-07. Suppl 1, "BWR Jet Pump Assembly Failure" No response required KEPPLER. J 0 Region 3. Chicago. Office of the Director 80/05/14
- 8009090088 "Response to 1E Dulletin 79-01B," re environ qualification of Class IE equipment

 * EDS Nuclear, inc 01-0910-1087 80/05/28 210pp
- 8007030210 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Watted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/15 tp

- 8009(1)534 Responds to IE Bulletin 80-17, "Failure of 74 of 185 Control Rods to Fully Insert During Stram at DNR " Matls presently on order to provide sys to continuously noniter water level in stram discharge vols GILBERTS, D.E. Northern States Power Co. 80/08/15 2pp
- 8009150466 Forwards IE Info Notice 80-30. "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function by Nonestential Control Air at Certain GE BWR Facilities "No specific action or response requested KEPPLER, J O Region 3. Chicago. Office of the Director 80/08/20 in
- BD09120057 Forwards Suppl 3 to IE Bulletin BO-17. "Failure of Control Rods to Insert During Scram at SWR" Written response required KEPPLER.J G Region 3. Chicago, Office of the Director BO/UB/22
- 8009170433 Forwards JE Circular 80-18 "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEFPLER.J G Region 3. Chicago. Office of the Director 80/08/22
- 8009110499 Responds to IE Bulletin BO-19.Revision i. "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Auclear Power Plants Designed by C-E." No mercury-wetted relays used in reactor protection sys at facility CILBERTS, D.E. Northern States Power Co. 80/08/26 ip
- 8009170441 Responds to IE Builetin 80-17 re failure of control rods to Fully insert during scram at 3MR Potential design studies for improvement of venting sys performed Required mods will be completed during 1991 refueling outage, prior to startup OILBERTS, D.E. Northern States Power Co. 80/08/28 2pp
- 6009180007 Responds to 1E Bulletin 80-17 to failure of control rods to fully insert during scram at BHR Procedure revisions incorporating requirements issued Scram rept revision implementing functional testing issued GILBERTS, D & Northern States Power Co 80/09/28 2pp
- 8009230066 Forwards IE Info Notice 80-31, "Maloperation of Could-Brown Bover: 480 Voit Type K-6005 & K-DOM 6005 Circuit Breakers" " No written response required KEPPLER.J Q Region 3. Chicago, Office of the Director 80/08/28
- 8009170413 Forwards response to IE Bulletin 79-018 re environ qualification of Class IE equipment Substantial efforts in progress to obtain required data Complete response will be submitted by 801101
 GILBERTS. B 6 Northern States Power Co 80/08/29 2pp
- 009230483 Forwards Revision (to IE Bulletin 79-26. "Boron Loss From TWR Control Blades " Written response required TPPLER. J G Region 3, Chicago, Office of the Director 80/08/27
 - 250408 Act receipt of 800827 ltr informing NRC of steps taken to rect violations noted in IE Insp Rept 50-263/80-11
 PLER.J C Region 3. Chicago. Office of the Director 80/09/09
 - 009250411 Responds to NRC 800807 ltr re violations noted in 1E Insp Right 50-263/80-fl Corrective actions addl health physics staff to be hired & mgt support reinforced CILBERTO, D.E. Northern States Power Co. 80/08/27 9pp
- B009240[12 Forwards [E Circular 80-21, "Regulation of Refueling Crows"
 No written response required
 KEPPLER.J G Region 3, Chicago, Office of the Director B0/09/10
 - reriodic operating reports & related correspondence
 - 050348 Forwards "Effluent & Waste Disposal Semiannual Rept." n 1980-June 1980 YERL O Northern States Power Co 80/08/27 1p
 - 09030355 "Effluent & Waste Disposal Semiannual Rept," Jan-June 1980 & Northern States Power Co 80708/27 13pp
 - 7090282 Forwards monthly operating rept for Aug 1980 WER.L.O Northern States Power Co 80/09/05 ip
 - 109090287 Monthly operating rept for Aug 1980 MEGENER, D. Northern States Power Co. 80/09/05 4pg

- 8009300234 Errata to "Environ Monitoring & Ecological Studies Program Rept, 1979 " Figures 2 2-3 through -7 have drafting error in legend Solid line should be identified as Sector A & dashed line as Sector B WARD.E C Northern States Power Co 80/09/25 ip
- S Reportable occurrences. LERs & related correspondence
- 8009030380 Forwards LER 80~025/03L-0 MAYER.L 0 Northern States Power Co 80/08/28 1p
- --8009030401 LER 80-029/03L-0 on 800729 during normal operation.while performing surveillance test outboard HPCI steam supply valve operator failed Caused by breakdown of motor winding insulation Motor replaced w/upgraded insulation GVERLID.T W Northern States Power Co 80/08/28 ip
- 8009230632 Forwards LER 80-026/03L-0 MAYER: L D Northern States Power Co 80/09/16 1p
- --8009230641 LER 80-026/03L-0 on 800817, while performing surveillance test on outboard KSIV, AD-2-86A, valve closed in 9-s Caused by binding of piston in 4-way assembly Replaced 4-way assembly MSIV actuating assemblies will be rebuilt DVERLID, TW Northern States Power Co 80/09/16 1p
- B009230420 Forwards LER 80-028/03L-0 MAYER, L U Northern States Power Co 80/09/19 ip
- --B009230630 LER 80-028/OSL-0 on B00825.while performing surveillance test.operator observed steam leak in elbow in drain line to condenser Caused by pinhole failure due to erosion from high velocity steam Leaking elbow & proximate elbows replaced OVER&ID.T W Northern States Power Co 80/09/19 lp
- 8009260626 Forwards LER 80-027/03L-0
 HAYER, L O Northern States Power Co 80/09/22 lp
- --8009260640 LER 80-027/03L-0 on 80823, during monthly surveillance, 42-12 test control rod could not be withdrawn after partial insertion Caused by closed drive withdraw riser isolation valve CRD-102 Valve opened & rod was openable NIERQDE, CF Northern States Power Co 80/07/22 ip

DOCKET 50-265 GUAD-CITIES STATION, UNIT 2

- F Security, medical, emergency & fire protection plans
- 8009230288 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys (nstalled for govt use during emergency KEPPLER, J O Region 3. Chicago, Office of the Director 80/08/22 3pp
- 8007100378 Forwards review of util generating station emergency plan & draft ltr requesting addl info & commitments from util PAGANN.F G Emergency Preparedness Licensing Branch 80/08/20 500
- O Adjudicatory correspondence
- 8009220013 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 IFPOLITO, T A Operating Reactors Branch 2 80/08/29 2pp
- --8009220017 Order for mod of Licenses DPR-29 & DPR-30 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment info should be submitted by 801101
 EISENKUT.D 0 Division of Licensing 80/08/29 6pp
- 8009300603 Forwards 800919 order revising 800829 order for mod of OL: in entirety EISENHUI, D O Division of Licensing 80/09/19 2pp
- --8009300614 Order revising 800829 order for mad of ALs DPR-29 & DPR-30, published in 800912 FR, in entirety Info re IE Bulletin 79-018 shall be filed by 801101 Request for hearing will not stay order effective 800919 UCS petitions discharged EISENHUT.D & Division of Licensing 80/09/19 App

1

- P Operating license stage documents & correspondence
- BOO9:10554 Suppls NRC BO0707 request for proposed Tech Specs changes re scram discharge voi vent & drain valves, & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISERHWT, D O Division of Licensing 80/07/22 22pp
- 8009020297 Submits interim criteria for shift staffing to all DL & CP iicensess & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D O Division of Licensing 80/07/3i 7pp
- 800708008D Forwards draft NUREG-0676. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT,D © Division of Licensing 80/08/01 i17pp
- BOO9230052 Informs that exemption from fee re licensing action associated w/TMI~2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISEMHUT, D O Division of Licensing 80/08/07 60pp
- BOO7020456 Forwards ovaluation of util response to NRC 800223 request for info re primary coolant sys pressure isolation valves. Two specific Event 5 valve configurations do not exist at facilities. CRUTCHFIELD, D Operating Reactors Branch 5 80/08/12 3pp
- --BD09020474 "Primary Coolant Sys Pressure isolation Vaives," technical evaluation ropt NOELL.P N , STILWELL.T C Franklin Institute/Franklin Research Center NRC-03-79-118 80/07/21 4pp
- 8009180232 Forwards NUREC-0661, "Mark I Containment Long-Term Program BER Resolution of Generic Technical Activity A-7" Rept discusses generic suppression pool hydrodynamic load definition H/o encl IPPOLITO.T A Operating Reactors Branch 2 80/08/20 2pp
- BOO9020105 Forwards NUTECH Rept COM-0708-03. "Evaluation of 18-inch Containment Isolation Valvos for Dresden Station.Units 2 % 3 & Quad Cities Station,Units 1 & 2," in response to NRC 791022 % 23 itrs re containment vent & purgo valves JANECEX.R F Commonwealth Edison Co 80/08/22 ip
- --B00902011! "Evaluation of 1B-Inch Containment Isolation Valves for Dresden Station.Units 2 % 3 & Quad Cities Station.Units 1 & 2 " GERBER.D A Nuclear Technology, Inc (Nutech) COM-0708-03 80/05/14 116pp
- BOO9120404 Forwards Attachments 1-5 to util BOO630 ltr re facility electric distribution sys voltage adequacy Ltr inadvertently transmitted w/o attachments

 JANECEK.R F Commonwoalth Edison Co BO/08/28 App
- 8009090374 Forwards add1 info re min critical configuration in support of 800515 application to amend Licenses DFR-19.25.29 & 30, changing requirements for source range monitor count rates JANECEKIR F Commonwealth Edison Co 80/09/03 5pp
- BD09180501 Forwards Amends 49,44,58 & 53 to Licensos DPR-19,DPR-25,DPR-29 & DPR-30.respectively.safety evaluation & notice of issuance & evaluation in the second interest of the second interest of the second interest of the second interest in the second in the second interest in the second interest in the second interes
- --BOO9180506 Amends 49.44,58 & 53 to Liconset DPR-19.DPR-25.DPR-29 & DPR-30.respectively, revising Tech Specs to allow count rate on source range monitor channols below 3 counts per second when there are two or less fuel assemblies in quadrant IPPOLITO.T A Operating Reactors Branch 4 80/09/08 22pp
- --8009180516 Safety evaluation supporting Amends 49, 44, 58 & 53 to Licenses DPR-19, DPR-25, DPR-27 & DPR-30, respectively * Office of Nuclear Reactor Regulation, Director 80/09/08 4pp
- --8009180326 Notice of issuance & availability of Amends 49,44,58 & 53 to Licenses DPR-19,DPR-25,DPR-29 & DPR-30, respectively IPPOLITO,T A Operating Reactors Branch 2 80/09/08 2pp
- 8009230463 Forwards proposed Tech Spec changes re implementation of TMI Lessons Learnsd.Category A requirements.in response to NRC 800702 request Dresden Unit 1 Tech Spec changes will be submitted 90 days prior to scheduled startup JANECEK.R F Commonwealth Edison Co 80/09/18 3pp

- --8007230466 Proposed Tech Spot changes re implementation of TMI-2 Lessons Learned Category A Items # Commonwealth Edison Co 80/09/10 29pp
- @ Inspection reports. IE Buileting & correspondence
- 8009040517 Forwards IE Bulietin 80-07. Suppl 1. "BWR Jet Pump Assembly Failure " Response required KEPPLER, J Q Region 3. Chicago. Office or the Director 80/05/14
- 8009040632 Provides addi response to iE Builetin 80-17 Results of amaIysis of ATMS w/o recirculation pump trip enci Analyses required no deratings to remain belou svc level C ilmit JANECEK.R F Commonwealth Edison Co 80/07/14 6pp
- 8009020109 Responds to IE Bulietin 79-03A, "Longitudinal Held Defects in ASME SA-312. Type 304 Stainless Stepi Pipe " SA-312 pipe not present in operating plants Final confirmation from suppliers anticipated by 800915 re const plant piping sys NAVOHTON, N F Commonwealth Edison Co 80/08/07 2pp
- 8009170230 Forwards response to IE Bulletin 80-17. Suppl i, "Fallur# of 76 of 185 Control Rods to Fully Insert During Scram at BWR "
 Scram discharge voi piping, scram instrument vol piping & drain piping meet requirements re downward pitch
 PEOPLES.D L Commonwealth Edison Co 80/08/07 4pp
- BD09030231 Forwards Revision 1 to IE Builetin 60-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/08/15
- 8009110545 Responds to IE Bulletin 80-08, "Exam of Containment Liner Penotration Weids." supplementing 800709 response Corrects Zion response re rings used for field circumferential butt wold Reviews accuracy of other statements ABELIJS Commonwealth Edison Co 80/08/15 4pp
- 8009110562 Responds to Suppi i to iE Builetin 80-17, "Failure of 76 of 185 Control Rods to Fully insert During Scram at BWR "
 Util will not have continuous SDV water level manitoring sys installed & functional by 800901

 JANECEK.R F Commonwealth Edison Co 80/08/15 2pp
- 8007160681 Bubmits supplementary response to IE Bulletin 80-08, "Examination of Containment Liner Penetration Weids," correcting statement made in DL Peoples 800707 itr Further review not necessary ABELIJ S Commonwealth Edison Co 80/08/15 4pp
- 8009290123 Forwards Waste Packaging insp Rept 15000046/80-65 or 800527-30 & notice of violation DAVIS.A B Region 3, Chicago. Fuel Facility & Materials S: Branch 80/08/18 2pp
- ~-8009290126 Notice of violation from insp on 800527-30
 * Region 3. Chicago. Office of the Director 80/07/23
- --8007290131 Waste Packaging Insp Rept 15000046/80-65 on 800 Noncompliance noted failure to meet strong tight packag/ raquirement contained in DDT raquilation LOVENDALE,P C , THOMAS,R D Region 3, Chicago, Office Director BOOK,H E Region 3, Chicago, Fuel Facility Safety Branch 80/07/23 Zpp
- 8009:50495 Forwards IE Info Natice 80-30, "Potential for Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE BMR Facilities specific action or response requested KEPPLER, J G Region 3, Chicago, Office of the Directo
- B009120060 Forwards Suppl 3 to iE Bulletin 80-i7, "Fail Rods to Insert During Scram at BWR " Written response required KEPPLER, J G Region 3, Chicago, Office of the Direct
- 8009180551 Forwards IE Circular 80-18, "10CFR50 59 S for Changes to Radwaste Treatment Sys " No written raquired KEPPLER.J Q Region 3, Chicago, Office of the Dir io

- SOUNTING Forwards IE info Notice 80-31. "Maloperation of Gould-Brown Bover: 450 Volt Type K-6005 & K-DGY 6005 Circuit Breekers"

 No written response required KEPPLER, J.G. Region 3 Chicago, Ornice of the Director 80/08/28
- 2007100659 Ack receipt of 800715 itr informing NRC of steps taken to correct violation noted in 850620 IE inspired & payment of civil penalty SIELEO V Diffice of Inspirition & Enforcement, Office of the Director 80/08/29 2pp
- ECC9:70411 Forwards response to LE Bulletin BO-15 re possible loss of e-ergency notification sys U/loss of offsite power Review revaled imparability of Dresden sys investigation being conducted Operating Order 22-80 changed JANACEM.R F Com-pruealth Edison Co 80/08/29 4pp
- 8009180466 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Identified relays are not used in facility No action required Twenty-four manhours espended on review RAUSCH.T J Commonwealth Edison Co. 80/08/29 1p
- BOO9230478 Forwards Pevision 1 to 1E Bulletin 79-26, "Boron Loss From BUR Control Blades' Mritten response required KEPPLER, J G Region 3, Chicago Office of the Director BO/08/29
- 8009170421 Responds to IE Bulletin 80-17. Suppl lire failure of control rods to fully insert during scran at BMR Vent sys will provide reliable source of air Juring dealning. Sys will be steadily purged until node installed JANECEK R F Commonwealth Edison CO. 80/09/02 2pp
- 8005260109 Forwards response to 1E Bulletin BO-17, Suppl 3, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR "
 Procedure at Dresden 2 & 3 changed to require inmediate manual scram when air pressure reaches 60 psi
 RAUSCH 7 J Componwealth Edison Co 80/09/02 4pp
- 8009250504 Responds to NRC 791213 request for add1 info in response to IE Bulletin 79-02 "Pipe Support Base Plate Designs Using Concrete Eigansion Anchor Bolts " Eigansion anchor test results show installation of anchors acceptable JANFCEK.R F Commonwealth Edison Co 80/09/05 17pp
- 8009240133 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required KEFPLER J G Region 3, Chicago, Office of the Director 80/09/10 lp
- 8009300:00 Forwards response to IE Bulletin 80-20 No Hestinghouse Type M-2 control suitches are used in safety-related sys at Dresden. Quad Cities & LaBails County Responses for Zion & Byron are enc!
 RAUSCH 7 J Componue
- R Periodic operating reports & related correspondence
- B00903044B Forwards semiannual rapt of radioactive effluent discharges & solid radwaste, for Jan-June 1980 KALIVIANAKIS N Commonwealth Edison Co 80/08/13 1p
- --8007690453 Semiannual rept of radioactive effluent discharges & solid rad_aste.for Jan-June 1980 # Cornometalth Edison Co 80/08/13 20pp
- EC07160272 Forwards monthly operating repts for Aug 1980 MALIVIANAMIS,N Commonwealth Edison Co 80/09/02 1p
- --8009160276 Monthly operating repts for Aug 1980 BROWN. 3 . TUBBS. 8 Commonwealth Edison Co 80/09/02 22pp
- 8009120253 Forwards changes, tests & esperiments completed during Aug 1983 KALIVIANAKIS,N Commonwealth Edison Co 80/09/08 2pp
- S Reportable occurrences, LERs & related correspondence
- 8007080378 Forwards LER GO-016/03L-0 KALIVIANAXIS N Commonwealth Edison Co 80/08/11 2pp

A

--8009080407 LER 60-016/031-0 on 600723, discovered that pressure switch PS-2-261-30C would trip at 84j psig, under limit of 850 psig Caused by instrument drift Pressure switch recalibr & tested satisfactorily KANLS Componwealth Edison Co 80/08/11 ip

- 8009080412 Forwards LER 80-036/03L-0 KALIVIANAKIS,N Commonwealth Edison Co 80/08/13 2pp
- --8009080417 LER 80-036/03L-0 on 800724, during testing, pressure switch PS-2-1622B was found to actuate at 20 3 rather than 13 8 inches of water Caused by setpoint drift Switch replaced STEFFES,C Commonwealth Edison Co
- 8009220268 Forwards LER 80-018/017-0 KALIVIANAKIS,N Commonwealth Edison Co 80/09/11 1p
- --8009220271 LER 80-018/01T-0 on 800829, while performing HPCI agerability test, discovered that HPCl motor gear unit would not come off high speed stop Caused by failure of component in flow controller replaced KODI.M Commonwealth Edison Co 80/09/08 2pp
- V Operator Examinations
- BO09300287 Forwards preliminary topical outlines of proposed modules on thermal hydraulics & core damage mitigation to be included in revised reactor operator training program per BO0328 request NAUGHTON W F Commonwealth Edison Co 80/09/15 7pp
- DOCKET SO-266 POINT BEACH NUCLEAR PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8009:10619 Requests participation in study of people-related problems in nuclear safeguards Study involves collection of data on licenses security forces & practices EISENHUT.D G Division of Licensing 80/07/25 2pp
- 8009030542 Forwards safeguards contingency plan Plan withheld (ref 10CFR2 790) BURSTEIN,S Nisconsin Electric Power Co 80/08/22 1p
- 8009230314 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency KEPPLER. J G Region 3, Chicago, Office of the Director 80/08/22
- 8009260215 Responds to 800822 request for info re emergency notification sys & health physics network & requests clarification of notification requirements FAY.C N Wisconsin Electric Power Co 80/09/05 3pp
- 8009290177 Forwards security measures for proposed sewage treatment plant Encl withheld (ref 10CFR2 770)

 BURSTEIN, S Wisconsin Electric Power Co 80/09/17 ip
- G Adjudicatory correspondence
- 8007080348 Discusses 800808 ltr authorizing restart & alluding to informal understanding between NRC & licensee re future insp Expresses belief that action thwarts meaningful public participation
 FALK.K M Wisconsin's Environmental Decade 80/08/26 2pp
- 8009190352 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 CLARK,R A Operating Reactors Branch 3 80/08/29 2pp
- ~-8009190357 Order for mod of Licenses DPR-24 & DPR-27 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101 EISENHUT.D. Q Division of Licensing 80/08/29 App
- 8009230255 Response to WI Environ Decade 800826 ltr on acceptability of certain test results re steam generator tube integrity Admits that NRC legal arguments against right to hearing are groundless Certificate of Svc encl CYR.K D Rulemaking & Enforcement Division 80/09/17 4pp
- 8009230447 Ack receipt of 800826 ltr re facility Since ltr deals w/matters currently before ABLB.Commission comments inappropriate at this time MURRAY.UP Rulemaking & Enforcement Division 80/09/19 ip

BOO9300410 Notifies that util has been served w/NI Environ Decade, Inc 800808 ltr to Senator Proxmire & Congressman Zablocki Ltr akieges corrosion problem in steam generator tubes Ltr encl
O'NEILLJ H Shaw, Pittman, Potts & Trowbridge 80/09/25 7pp

H General correspondence

- EQ09050424 Responds to League Against Nuclear Dangers 800715 ltr re relocating local PDR to Two Rivers.WI Two Rivers library will Mouse documents re Wood County special repts NRC 1979 Annual Rept encl SGUDER.J L Division of Rules and Recnrds 80/08/15 22pp
- --8009030426 Requests submitted on behalf of League Against Nuclear Dangers, concerning relocation of local PDR to Manitowoc. WI Lists types of documents & specific documents that should be retained at Univ of WI library DIXON.G Affiliation Unknown 80/07/18 3pp
- SCO9110411 Requests establishment of LPDR in Madison.WI, on behalf of WI Public Syc Commission State agency personnel will review replacement of steam generators at Point Beach Unit 1 in 1981 or 82 Related correspondence YORK: 8 . PARSONS, E. M. . NUNNERY, W. J. Wisconsin. State of 80/08/24 250
- 8009250187 Forwards FR notice of relocation of facility LPDR from Univ of WI Library, Stevens Point to Joseph Mann Library, Two Rivers, VI FELTON, J M Division of Rules and Records 80/09/09 2pp
- P Operating license stage documents & correspondence
- 8009020277 Submits interim criteria for shift staffing to all OL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D O Division of Licensing 80/07/31 7pp
- 800908080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl M/o NUREO EISENHUT.D O Division of Licensing 80/08/01 119pp
- 8009020497 Responds to NRC 800708 itr re weldments in Graver tanks Evaluations show that connections & penetrations would withstand design loading conditions assuming as-found configuration SURSTEIN.8 Wisconsin Electric Power Co 80/08/04 3pp
- 80G9230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENRUT, D O Division of Licensing 80/08/07 AOpp
- BOOT040279 Forwards safety evaluation re facility steam generator tube degradation Based on review of util steam generator tube insprunnecessary to place further restriction on resumption of facility operation CASE.E G Office of Nuclear Reactor Regulation, Director 80/08/08
- --8009040305 Safety evaluation re facility steam generator tube degradation * Office of Nuclear Reactor Regulation, Director 80/08/08 7pp
- 8009190794 Forwards revised Westinghouse 8TB 3 9 B 2,3 9 10 8 Bases 3/4 9 B & 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required NOVAKIT M Assistant Director for Operating Reactors 80/08/15
- --B009190B17 Revised Westinghouse STS 3 9 B 2.3 9 10 & Bases 3/4 9 B & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods

 Assistant Director for Operating Reactors 80/06/23 21pp
- 8009030498 Requests permission to suppl WI Environ Decade previous filings supporting adjudicatory hearing re patitioner preliminary contentions NRC 800808 ltr authorizes facility restart w/o offer for adjudicatory hearing FALK.K M Wisconsin's Environmental Decade 80/08/26 2pp

- -8009030501 Notifies that restrictions re facility operation resumption not necessary per review of util 800805 steam generator tube inspiresults Conditions of 791130 order 2 800103 mods to 791130 order remain in effect Safety evaluation not encl CASE.E 0 Office of Nuclear Reactor Regulation. Director 80/08/08 Ip
- 8009120575 Forwards requests for add1 info re adequacy of station electric distribution sys voltages to continue review Response requested within 45 days or Itr receipt CLARK.R A Operating Reactors Branch 3 80/09/08 App
- 8009160442 Responds to NRC 800819 itr re IAEA design info questionnaire to be utilized in submittal of installation info by facilities Compiling data will require significant effort NRC should utilize existing info in files BURSTEIN. S Wisconsin Electric Power Co 80/09/11 1p
- 8009230660 Responds to 800815 request for review of Tech Specs & procedures assuring that exposure or fuel assemblies & control rods cannot occur during transfer w/plant in refueling shutdown mode Changes to Tech Specs unnecessary FAY, C W Wisconsin Electric Power Co 80/09/15 2pp
- 8009230666 Notifies NRC that util unable to comply w/800714 request re Tech Specs applicable to implementation of TMI-2 Lessons Learned Category A items Initial review of model Tech Specs completed FAYIC W Wiscunsin Electric Power Co. 80/09/18 3nn
- 8009250249 Application to amend Licenses DPR-24 & DPR-27, changing Tech Specs 15 1, 15 3 & 15 6, re limiting conditions for operations, definitions of operability & administrative structure
 BURSTEIN, S Wisconsin Electric Power Co 80/09/19 3pp
- ~-8009250253 Tech Spec Change Request 64.consisting of proposed Tech Specs 15 1,15 3 & 15 6 re limiting conditions for operations, definition of operability & administrative structure 4 Misconsin Electric Power Co 80/09/19 Spp
- 8009290341 Proposed Change 45, modifying 770728 request to amend Licenses DPR-24 & DPR-27 to incorporate Tech Spec changes Changes modify trip & time delay setting for undervoltage protection circuitry BURSTEIN, S Wisconsin Electric Power Co 80/09/22 2pp
- --8009270342 Tech Spec change for Item 7 of Table 15 3 5-1 % Item 3a of Table 15 3 5-3 re time % trip delay settings for undervoltage protection sys

 4 Wisconsin Electric Power Co 80/09/22 2pp
- 8009300461 Forwards comments on draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " NUREG should include alternate methods of satisfying functional requirements FAY.C W Wisconsin Electric Power Co 80/09/22 App
- Q Inspection reports: 1E Bulletins & correspondence
- B00929G011 Forwards IE Insp Repts 50-266/80-10 & 50-301/80-10 on B00604-27 & notices of violation, App A & R App B withheld (ref 100FR2 790)
 KEPPLER, J 0 Region 3, Chicago, Office of the Director 80/08/11 3pp
- --8007290013 Notice of violation App A from insp on 800404-27 * Region 3. Chicago. Office of the Director 80/08/05 ip
- --8009290015 IE Insp Repts 50-266/80-10 b 50-301/80-10 on 800604-27 & 0708 Noncompliance noted RHR pumps operability impaired & engineered safety feature crossconnected Details withheld (ref 10CFR2 790)
 SMITH.J D , GULDEMGND, W G . WARNICK, R F Region 3, Chicago, Office of the Director 80/08/05 12pp
- B009030219 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E "Written response required KEPPLER.J G Region G, Chicago, Office of the Dijector 80/09/15
- B009290017 Forwards 1E Insp Repts 50-246/80-13 & 50-301/80-13 on 800717 & 22 No noncompliance noted DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch B0/08/19 2pp

- --8009290018 IE Insp Repts 50-266/80-13 t 50-301/80-13 on 800717 t 22
 No noncompliance noted Major areas inspected confirmatory
 measurements
 JANUSKA:A O . ESSIG.T H Region 3. Chicago, Office of the Director
 80/08/15 4pp
- 8009180520 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys ' No written response required KEPPLER, J C Region 3, Chicago, Office of the Director 80/08/22
- 8009110557 Responds to 1E Bulletin 80-18. "Maint of Adequate Min Flow Thru Centrifugal Charging Pumps Following Secondary Bide High Energy Line Rupture " Corrective actions are not necessary FAY.C W Wisconsin Electric Power Co 80/08/26 2pp
- 8009230089 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-6005 & K-DDN 6005 Circuit Breakers " No written response required KEPPLER. J G Region 3. Chicago. Office of the Director 80/08/28 in
- 8009180158 Responds to IE Sulletin 80-19 re failures of mercury-wetted matrix relegs in reactor protective sys Identified relays not used in facility and facility FAY.C W. Wisconsin Electric Power Co. 80/08/29 1p
- 8009240124 Forwards (E Circular 80-21, "Regulation of Refueling Crews" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/09/10
- 8009300305 Responds to IE Bulletin 80-20 Identifies safety-related equipment control circuits utilizing Westinghouse Type W-2 switches w/spring-return-to-neutral position All but four circuits have been modified to indicate switch closure BURSTEIN.S Wisconsin Electric Power Co 80/09/16 2pp
- R Periodic operating reports & related correspondence
- 8009090539 Forwards "Semiannual Monitoring Rept, Jan-Jun, 1980 " FAY, C W Wisconsin Electric Power Co 80/08/29 ip
- --8009090545 "Semiannual Monitoring Rept. Jan-Jun. 1980 " + Wisconsin Electric Power Co 80/08/29 15pp
- 8009160302 Forwards monthly operating repts for Aug 1980 FAY.C W Wisconsin Electric Power Co 80/09/09 1p
- --8009160304 Monthly operating repts for Aug 1980 FAY.C & Wisconsin Electric Power Co 80/09/04 9pp
- U Congressional/Executive Correspondence
- 8009020030 Expresses concerns re potential consequences from stoam generator tube degradation Full adjudicatory hearing needed Requests to be informed of continuing development STRONL.J. BERGER,D. MODDY.J. Misconsin State of 80/08/22 ip
- 8007290002 Responds to 800822 ltr urging full adjudicatory hearings on plant safety issues Commission has referred similar WI Environ Decade request to ABLB for determination Further Commission comment is inappropriate pending ABLB doctsion MURRAY, J P Rulemaking & Enforcement Division 80/09/09 lp
- --8009290004 Responds to 800822 ltr urging full adjudicatory hearings on plant safety issues Commission has referred similar WI Environ Becade request to ASLB for determination Further Commission comment is inappropriate pending ASLB decision MURRAY. J P Rulemaking & Enforcement Division 80/09/09 ip
- --B009290605 Responds to B00822 ltr urging full adjudicatory hearings on plant safety issues Commission has referred similar WI Environ Decade request to AGLB for determination Further Commission comment is inappropriate pending AGLB decision MVRRAY. J P Rulemaking & Enforcement Division 80/09/09 ip
- '009240490 Urges NRC to order full-scale adjudicatory hearing on safety concerns re degradation of steam generator tubes Related correspondence MUNIS.M L. Wisconsin, State of 80/09/16 ip

- DOCKET 50-267 FORT ST VRAIN NUCLEAR GENERATING STATION
 F Security, medical, emergency & fire protection plans
- 8009230731 Advises that list of 60 add1 heavily populated areas has been included in encl revised guidance document, NUREQ-0561 Amend rule for physical protection of Irradiated reactor fuel for transit will be effective 800829 W/o encl MCCURKLE. O W Physical Security Licensing Branch 80/07/QB 1p
- 8009020153 Invites participation in 800822 workshop in Atlanta, GA to solicit comment re proposed functional criteria for emergency response facilities in NUREG-0696 Discussion to include location, size & staffing of emergency ctr SEYFRIT. K V Region 4. Dallas. Office of the Director 80/08/12
- G Adjudicatory correspondence
- 8009230127 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101
 MILLER, J. R. Standardization & Special Projects Branch 80/08/29
 20n
- --8009230129 Order for mod of License DPR-34 to add info which fully responds to ARC request for info re environ qualification of safety-related electrical equipment info should be submitted by 801101
 EISENHUT, D G Division of Licensing 80/08/29 App
- 8009240194 Responds to NRC 800829 order modifying License DPR-34 to require info by 801101 re environ qualifications of IE electrical equipment in operation sys exposed to high energy time break ambience Hearing requested re order FULLER, J K Public Bervice Co of Colorado 80/09/17 3pp
- P Operating license stage documents & correspondence
- 8009020297 Submits interim criteria for shift staffing to all OL & CP ilcensees & applicants.per NRC 800307 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D O Division of Licensing 80/07/31 7pp
- 80090B00B0 Forwards draft NUREO-0696, "Functional Critoria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 entl W/o NUREO EISENHUT, D 0 Division of Licensing 80/08/01 119pp
- B009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of Amend EISENHUT, D G Division of Licensing B0/08/07 40pp
- 8009040506 Forwards Amend 22 to License DPR-34 & safety evaluation TEDE8CO.R L Assistant Director for Licensing 80/08/19 2pp
- ---B009040509 Amend 22 to License DPR-34, revising diesel fuel storage requirements, updating company reorganization & altering fire protection Tech Specs
 TEDLSGO.R L Assistant Director for Licensing 80/08/19 31pp
- --8009040513 Safety evaluation supporting Amend 22 to License DPR-34 * Office of Nuclear Reactor Regulation, Director 80/09/19 35pp
- 8009150427 Forwards safety evaluation & statement of NRC positions re safety-related electrical equipment for licensee response Requests comparison w/current energency power sys design & plant mods to meet NRC positions TEDESCO-R L Assistant Director for Licensing 80/08/25 3pp
- --B009150431 Safety evaluation & statement of NRC positions re emergency power sys for operating reactors * Assistant Director for Licensing 80/08/25 12pp
- 8009030940 Responds to NRC 800802 ltr requesting add1 info re thermal stresses in core support blocks. Net effect of analytical models & assumptions on stresses not clear at present Short-term efforts in progress Results to be reviewed FULLER.J K Public Service Co of Colorado 80/08/29 App

- 90,914,0344 Informs that immediate Amend 22 implementation not feasible due to time difference between issuance 2 receipt Requests that amend provisions be made effective 801025 & amended SR 5 4 I effective date be determined mutually w/NRC WAREMBOURG, D Public Service Co of Colorado 80/09/08 4pp
- QCQ9160364 Requests relief from LCO 4 3 10 for 60 days, after return to power, to check & readjust hangers & snubbers for main steam & cold & hot reheat lines Many hangers will require new position settings which must be made at full steam WAREMBOURO, D Public Service Co of Colorado 80/09/08 2pp
- 8009160314 Forwards "Fort St Vrain Initial Approach to Power Tests (8-Series)," Interim Rept 16 for period ending 800822 WAREMBOURG, D Public Service Co of Colorado 80/09/09 (p
- ~8009160316 "Fort St Vrain Initial Approach to Power Tests (B-Series)," Interim Rept 16 for period ending 800822 • Public Service Co of Colorado 80/08/22 2pp
- 8009230689 Comments on NUREO-0696 document late considering number of significant changes imposed to criteria of NUREOs-0578 & 0694 which were utilized by nuclear industry in planning energency response faculties HAREHBOURG, D Public Service Co of Colorado 80/09/16 lOpp
- 1 Inspection reports, IE Bulletins & correspondence
- 8009220319 Discusses objectives & conclusions re helium circulator C-2102 insp Forwards QA Co rept.QA-C15847, re insp results Requests review of proposed inservice insp program in draft Tech Specs submitted 800331 HAREMBOURG,D Public Service Co of Colorado 80/07/02 2pp
- ~~8009220321 "Exam of Helium Circulator C-2102 " RDSENBERG,R General Atomic Co (subs of Gulf Cil Co) QA-C15847 80/04/30 75pp
- 8009020221 Responds to IE Bulletin 80-li re masonry walls in proximity to or that have attachments w/safety-related piping or equipment Utli completed investigation of all concrete masonry block walls in turbine & reactor bldgs
 SWART.F E Public Service Co of Colorado 80/07/07 3pp
- --8009050467 Notice of violation from insp on 800616-19
 * Region 4. Dallas, Office of the Director 80/07/11 2pp
- --8009050477 lE Insp Rept 50-267/80-14 on 800616-19 Noncompliance noted failure to document qualifications of personnel performing calibrs on measuring & test equipment & failure to provide record of test equipment OACLIARDO, JE Region 4. Dallas, Reactor Operations Nuclear Support Branch YANDELL, LA, MESTERMAN, TF Region 4. Dallas, Office of the Director 80/07/11 7pp
- 8009100033 Forwards IE Insp Rept 50~267/80-12 on 800601-30 \$ notice of violation MADSEM G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/07/16 2pp
- --2009100057 Notice of violation from insp on 800401-30
 ** Region 4, Dallas, Office of the Director 80/07/12 2pp
- --8009100055 IE Insp Rept 50-267/80-12 on 800601-30 Noncompliance noted failure to follow procedures, failure to implement equipment control procedure & failure to maintain records required by Tach Spec 4 2 9.

 GAOLIARDOD, JE . WEBTERMAN, T F., DICKERBON, M W. Region 4. Dallas, Office of the Director 80/07/12 13pp
- 8009180140 Forwards IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches " Written response required 5EYFRIT.K V Region 4, Dallas, Office of the Director 80/07/91
- g009180132 Forwards IE Bulletin BO-19, "Failure of Marcury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required SEYFRITIK V Region 4, Dallas, Office of the Director, G0/07/31

- 8009260286 Forwards IE Info Notice 80-29. 'Broken Studs on Terry Turbine Steam Inlet Flange " No written response required SEYFRIT, X V Region 4, Dallas, Office or the Director 80/08/07 to
- 800925045B Forwards Revision i to IE Bulletin 80-19. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E ' Mritten response required EEYFRIT.X V Region 4. Dallas. Office of the Director 80/08/15 in
- 8009300274 Forwards IE Insp Rept 50-267/80-15 on B00701-30 & notice of violation MADSEN.G L Region 4. Dallas. Reactor Operations Nuclear Support Branch 80/08/18 2pp
- --8009300279 Notice of violation from insp on 800701-30
 * Region 4. Dallas, Office of the Director 80/08/13 lp
- --8009300282 1E 1nsp Rept 50-267/80-15 on 800701-30 Noncompliance noted failure to comply w/requirements of radiation work permit DICKERSON.M W. COLLINS.R E. WESTERMAI, T. F. Region 4. Dallas. Office of the Director 80/08/13 Spp
- 8009170403 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required SEYFRITIK V Region 4, Dallas, Office of the Director 80/08/22
- BO09100B36 Ack receipt of B00B07 ltr informing NRC of steps taken to correct violations noted in 1E insp Rept 50-267/B0-14
 MADBEN.O L Region 4. Dallas. Reactor Operations Nuclear Support Branch B0/08/25 ip
- --8009100841 Responds to NRC 800714 ltr re violations noted in 1E lasp Rept 50-267/80-14 Corrective actions review panel established to survey cases of suspected deficiencies by personnel involved in tests LEE,O R Public Service Co of Colorado 80/08/07 2pp
- HO09150450 Specifies followup actions re IE life Natice 79-04 Util should review electric power sys to determine capacity of offsito power sys Bactground info re event & guidelines for calculations encl
 TEDESCO.R L Assistant Director for Licensing 80/08/25 Gpp
- 8007120433 Forwards 1E Info Notice 80-31, "Maloperation of Gould-Brown Bovers 480 Volt Type K-6005 & K-DDN 6008 Circuit Breakers"
 No written response required
 SEYHRIT, K V Region 4, Dallas, Office of the Director 80/08/27
- 8009170185 Ack receipt of 800806 ltr informing NRC of steps taken to correct violations noted in 1E insp Rept 50-267/80-12

 MADSEN.O L Region 4. Dallas. Reactor Operations Nuclear Support Branch 80/09/02 ip
- --8009170189 Responds to NRC 800716 itr re violations noted in IE lnsp Rapt 50-267/80-12 Corrective actions seals installed in three unsealed valves defactive pen repaired, status card replaced & use of log sheet implemented LEE,O R Public Service Co of Colorado 80/08/06 2pp
- R Periodic operating reports & related correspondence
- 8009260227 Forwards "Environ Radiation Surveillance Program, Summary Rept for Jan-June 1980" SWART, F E Public Service Co of Colorado 80/08/27 ip
- --8009260233 "Environ Radiation Survelliance Program, Summary Rept for Jan-June 1980 " JOHNSON, J E Colorado State Univ SWART, F E Public Service Co of Colorado 80/08/29 132pp
- 8009160290 Forwards monthly operating rept for June 1980 WAREMBOURD, D Public Service Co or Colorado 80/09/03 4p
- 8009160292 Forwards monthly operating rept for Aug 1980 WAREMSOURG.D Public Service Co of Colorado 80/09/Q8 1p
- --B009160299 Monthly operating rept for Aug 1980
 GAHM, J W Southwestern Public Service Co 80/09/02 5pp
- 8009160286 Forwards revised monthly operating rest for Aug 1980 WAREMBOURG,D Public Service Co of Colorado 80/09/09 lp

- --8009160288 Monthly operating rept for Aug 1980
 QAHM.J W Public Service Co of Colorado 80/09/02 5pg
- 8009230723 Forwards monthly operating rept for Jul 1980
 WAREMBDURG, D. Public Service Co. of Colorado 80/09/15 10
- B009260369 Forwards Page 1 revision to monthly operating repts for Mar & Apr 1980 WARREMORURG, D. Public Service Co. of Colorado. 80/09/18 200
- --8009260372 Revised Page 1 for monthly operating rept for Mar 1980 * Public Service Co of Colorado 60/09/18 [p
- --8009260374 Revised Page 1 for monthly operating rept for Apr 1980 * Public Service Co of Colorado 80/09/18 ip
- 8009260378 Forwards monthly operating rept for Aug 1980
 WAREMODURO.D Public Service Co. of Colorado 80/09/18 2pp
- --8009260386 Monthly operating rept for Aug 1980 GALMAJ W Public Service Co of Colorado 80/09/02 10pp
- S Reportable occurrences. LERs & related correspondence
- 8009030625 Forwards LER 80-043/03L-0
 WAREMBBURG D Public Service Co of Colorado 80/08/27 5co
- --8009030640 LER 80-043/03L-0 on 800728 during plant rise-to-power, out-gassing of oxidents from core resulted in degraded mode operation of LCO 4 2 10 Caused by residual moisture from leakage past HV-21352 8 primary coolant carculation trip GAHN, J N Public Service Co of Colorado 80/08/27 ip
- 8007233598 Forwards LER 80-045/03L-0 WAREMBOURD, D. Public Service Co. of Colorado 80/09/15 4pp
- --8009230404 LER 80-045/03L-0 on 800816 fitting on hydraulic oil line ruptured spraying oil on hot steam pipes & producing heavy smoke Fitting ruptured due to normal usage & was replaced Valve group was isolated to prevent addi oil loss * Public Service Co of Colorado 80/09/15 1p
- B00923060B Forwards LER 80-044/03L-Q
 WAREMBOURD, D Public Bervice Co of Colorado 80/09/15 4pp
- --8009230614 LER 80-044/03L-0 on 800816.wh(le operating at 30% power, boiler feed pump A was removed from svc dur to unstable gavernor controls Boiler feed pump B was out of svc also Caused by governor worm gear being loose on shaft # Public Barvice Co of Colorado 80/09/15 ip
- E009230597 Forwards LER 80-046/03L-0 WAREMBOURG, D Public Service Co of Colorado 80/09/19 App
- --8009230607 LER 80-046/03L-O on 800820, w/plant operating at approx 25% thermal power.PCRV cooling water outlet temp exceeded 120 F iimit Caused by isolation of cooling water due to operation of wrong controllers. Controllers reset to proper position 0ARM.J R Public Service Co of Colorado 80/09/19 ip
- 8009300556 Forwards LER 80-047/03L-0 WAREMBOURG,D Public Service Co or Colorado 80/09/24 7pp
- --8007300563 LER 80-047/03L-0 on 800825, several hydraulic snubbers were found inoperable Caused by improper hot position adjustment on constant support hangurs Snubbers repaired or readjusted OIDSON, J W Public Service Co of Colorado 80/09/24 lp
- DOCKET 50-269 MIDNEST FUEL RECOVERY PLANT
- P Operating license stage documents & correspondence
- 8009(30049 Advises that list of 60 add1 heavily populated areas has been included in encl revised guidance document.NUREG-0561. per NRC amend rule for physical protection of irradiated reactor fuel in transition effective 800703 M/o epc1 MCCORKLE.G W Physical Security Licensing Branch 80/07/07 1p

- DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- B009230256 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Bys installed for govt use during emergency O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/22
- G Adjudicatory correspondence
- BDD9260664 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by B01101 REID.R W Operating Reactors Branch 4 80/08/29 2pp
- --8007260667 Order for mod of Licenses DPR-39.DPR-47 & DPR-55 to add into which fully responds to NRC request for into re environ qualification of safety-related electrical equipment info should be submitted by 801101
 EISENHUT, D © Division of Licensing 80/08/27 App
- J Insurance & indemnity information
- 8009190424 Forwards Endorsement 58 to NELIA Policy NF-182 & Endorsement 43 to MAELU Policy MF-61 SANDERS:F D Duke Power Co 80/08/25 3pp
- 8009300428 Advises that invoices for facility indemnity fees should be addressed to MD Parker, not AC Thies PARKER, W G Duke Power Co 80/09/24 ip
- P Operating license stage documents & correspondence
- 8009150070 Responds to 800523 recommendations concerning lessons learned from 800226 transient at Crystal River Submits results of investigations re use of atmospheric dump valve at 8cohec Units 1-3.AR Unit 1.Davis-Besse Unit 1 & TMI-1 DENTON.H R Office of Nuclear Reactor Regulation. Director 80/07/21 2pp.
- --8009150079 Discusses 800226 translent at facility Recommends investigation to determine whether atmospheric dump valve design deficiency is present in other B&W plants MICHELSDN, C Director's Office 80/05/23 2pp
- 8009030343 Discusses void formation in vessel head during 800611 natural circulation cooldown event Requests opinion repotential for voiding phenomenon in 88W designed N885 CMECK.P 8 Assistant Director for Plant Bystems 80/07/28 2pp
- BOO9020297 Bubmits interim criteria for shift staffing to all DL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D & Division of Licensing 80/07/31 7pp
- 8007080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0676 encl W/o NUREO EISENMUT,D O Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D Q Division of Licensing 80/08/07 60pp
- 8009040085 Requests written confirmation of appraisal of critical alectrical power generation situation in region served by Duke Power Co NOVAK.T K Assistant Director for Operating Reactors 80/08/11 299
- G007160501 Forwards Amends 86,86 & 83 to Licenses DPR-38,DPR-47 & DPR-55,respectively,safety evaluation & notice of issuance & availability REID.R W Operating Reactors Branch 4 80/08/20 2pp
- --8009160502 Amends 86.86 & 83 to Licenses DPR-38,DPR-47 & DPR-55, respectively,incorporating test frequency requirements of tOCFR50.App J.into containment leak test program REID.R W Operating Reactors Errach 4 80/08/20 7pp

- --8009160506 Safety evaluation supporting Amends 86,86 & 83 to Licenses DPR-38,DPR-47 & DPR-55,respectively • Office of Nuclear Reactor Regulation, Director 80/08/20 2pp
- -~8009140507 Notice of issuence & availability of Amends 86,86 & 83 to Licenses DPR-38,DPR-47 & DPR-55, respectively REID,R W Operating Reactors Brench 4 80/08/20 2pp
- GO09160505 Notification of 800903 meeting w/util & Franklin Research Ctr in Bethesda. MD to review NUREO-057B. Items 2 1 7 A&B FAIRTILE. M B Operating Reactors Branch 4 BO/08/21 ip
- 8009020025 Forwards B&W rept. "Evaluation of Instrumentation to Detect Inadequate Core Cooling Prepared for 177 Gwners Group," supplementing earlier util submittals re Lessons Learned Item 2 i 3 b No addl Instrumentation needed W/o encl PARKER, W Q Duke Power Co 80/08/26 lp
- BO09100489 Informs NRC that revised radiological CTB "Offsite Dose Calculation Manual" & proposed process control program for solid waste sys will be forwarded by 800930 PARKER.W O Duke Power Co 80/09/03 ip
- 8009190154 Advises of NRC review of util 800328 submittal re standby shutdown facility Pages 2-1.5-1.5-2.5-3.4-3 & 7-1 should be withhold per 10CFR2 790 Util should resubmit document w/ deletions within 30 days
 REID.R W Operating Reactors Branch 4 80/09/09 2pp
- 8009250434 Informs of acceptability of response to NRC 791109 ltr re portions of ECCS evaluation models dealing w/fuel cladding swelling & Incidence of rupture REID-R ti Operating Reactors Branch 4 80/09/09 2pp
- 8009230724 Disagrees w/NRC 800907 ltr re classification of Standby Shutdown Facility licensing document Document should be withheld (ref 10CFR2 790) No nonpropietary version will be submitted PARKER. H O Duke Pawer Co 80/09/17 ip
- 8009300486 Forwards response to NRC 800611 request for change in facility Tech Specs, providing for redundancy in decay heat removed capability No changes necessary to Tech Specs PARKER, N G Duke Power Co. 80/09/24 3pp
- O Inspection reports, IE Bulletins & correspondence
- 800910005B Forwards IE Builetin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Escondary 81de High Energy Line Rupture " Written response required O'REILLY. J P Region 2. Atlanta. Office of the Director 80/07/24 ip
- B009040640 Responds to IE Bulletin 80-16 Rosemount Model 1151 \$ 1152 pressure transmitters w/output codes A or D are used for indicating reactor coolant pressure & providing input to control steam generator level PARKER, W O Duke Power Co 80/07/30 3pp
- 8009030175 Forwards Revision 1 to 1E Bulletin BO-19, "Failures of Hercury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/15 to
- 9009160137 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22 to
- 8009170233 Responds to IE Bulletin 80-19, Revision 1, "Failures of Mercury-Hetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Review indicates relays are not in use at facility PARKER, H 0 Duke Power Co 80/08/22 1p
- 8009100801 Ack receipt of 800623 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/80-17, 50-270/80-12 & 50-289/80-11 LEUIS. R C Region 2, Atlanta, Reactor Operations Nuclear Support Br
- --8009100807 Responds to NRC 800523 ltr re violations noted in IE lnsp Repts 50-269780-17,50-270/80-12 & 50-287/80-11 Corrective actions incidents involving failure to perform surveillance are being reviewed & new procedures will be established PARKER, N O Dute Power Co 80/06/23 3pp

- --8007100811 Forwards TE Insp Repts 50-267/80-17.59-270/80-12 & 50-287/80-11 on 800401-30 & notice of violation LEWIS,R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/05/23 2pp
- --8009100813 Notice of violation from insp on 800401-30
 * Region 2. Atlanta, Office of the Director 80/05/23 lp
- --800910081à 1E Insp Regts 50-269/80-17.50-270/80-12 & 50-287/80-11 on 800401-30 Noncompliance noted failure to submit 30-day repts when survelllance test frequency was missed MARTIN.R D Region 2. Atlanta, Reactor Operations Nuclear Support Brench JAPE.F Region 4. Dallas, Office of the Director 80/05/23 11pp
- 8009030605 Submits Revision 3 to util 90~day response to 1E Bulletin 79 01B re Class 1E equipment environ qualification Raychem heat shrink tubing, scotth Cast-9, transmitter 0-ring seals & lubricating grease to be replaced during refueling outage THIES A C Dute Power Co 80/48/27 2pp
- 8009110498 Responds to IE Bulletin 80-15 Emergency notification sys reviewed Sys is powered by onsite power.but does not have backup ansite emergency power Emergency power supplied by telephone Company PARKER.W D Duke Power Co 80/08/27 2pp
- 8009120343 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover! 480 Valt Type K-6008 & K-DDN 6008 Circuit Breakers "
 No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/27 lb
- 8009140533 Ack receipt of 800627 Ltr & 0806 supplemental response informing NRC of steps taken to correct violations noted in IE Insp Repts 50-267/80-19 & 50-270/80-10 MURPHY REP Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/09/04 ip
- --8009160540 Responds to NRC 800710 ltr requesting supplemental response to IE Insp Rept 50-270/80-10 Corrective actions Block 40303 will be modified to meet ASME requirements PARKER. H O Date Power Co 80/08/06 Zpp
- --8009160939 Ack receipt of 800623 ltr responding to 800922 natice of violation Understands supplemental response will be provided by 800803 MURPHY.C E. Region 2. Atlanta. Reactor Construction > Engineering Support Branch 80/07/10 1p
- --8009160541 Responds to NRC 800322 ltr re violations noted in IE losp Repts 50-269/80-15 & 50-270/80-10 on 800415-17 & 21-23 Corrective actions design of calibr blocks reviewed & will be modified to meet ASME requirements PARKER.N O Dute Power Co 80/06/23 2pp
- --8009160537 Forwards 1E Insp Repts 50-269/80-15 & 50-270/80-10 on B00415-17 & 21-23 & notice of violation MURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch 80/05/22 app
- --8009160550 Notice of violation from insp on 800415-17 & 21-23 * Region 2, Atlanta, Office of the Director 80/05/15 lp
- --8009160552 IE Insp Repts 50-269/80-15 & 50-270/80-10 on 800415-17 & 21-23 Moncompliance noted improperly designed inservice inspicalibr blocks
 ECONOROB.W Region 2. Atlanta. Office of the Director 80/05/15
- 8009290297 Forwards IE Circular 80-21. "Regulation of Refueling Crews " No written response required O'REILLY.J P Region 2, Atlanta, Orfice of the Director 80/09/10
- 8009300616 Ack receipt of 800825 itr informing NRC of steps taken to correct violations noted in IE insp Repts 50-269/80-23, 50-270/80-20 J 50-287/80-17 LEMIS, R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/09/16 1p
- --8009300626 Forwards response to NRC 800730 itr re violations noted in IE Insp Repts 90-267/80-23.50-270/80-20 & 50-287/80-17 Corrective actions informed operations personnel that use of correct & verified procedures must be ascertained FARKER.W D Duke Power Co 80/09/25 3pp

- --8009300630 Forwards IE Insp Repts 50-269/80-23 % 50-270/80-20 % 50-287/80-17 on 800602-30 % notice of violation LEWISR C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/07/30 2pp
- ~-8009300631 Notice of violation from insp on 800602-30 # Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/07/28 ip
- --8009300440 IE Insp Repts 50-289/80-23,50-270/80-20 & 50-287/80-17
 Noncompliance noted use of Unit 1 procedure to perform periodic test on Unit 2
 ORDERS W , JAPE.F Region 2, Atlanta, Office of the Director MARTIN.R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/07/28 13pp
- R Periodic operating reports 0 related correspondence
- 8009020044 Forwards "Radioactive Effluent Release Semiannual Rept." Jan-June 1980 PARKER.W O Duke Power Co 80/08/25 1p
- --8009020047 "Radioactive Effluent Rejease Semiannual Rept," Jan-June 1980 * Dute Powar Co 80/08/25 App
- 8009090577 Farwards revision to "Radioactive Effluent Release Semiannual Rept," Jan-June 1980 PARKER, W.O. Duke Power Co. 80/09/03 4pp
- --8009090582 Revision to "Radioactive Effluent Release Semiannual Rept." Jan-June 1980 * Dute Power Co 80/09/03 3pp
- 8009190462 Forwards monthly operating repts for Aug 1980 PARKER.W G Duke Pawer Co 80/09/15 ip
- --8009190473 Monthly operating tepts for Aug 1760 REAVIS.J A Duke Power Co 80/09/15 17pp
- S Reportable occurrences, LERS & related correspondence
- 8009030445 Forwards LER 80-024/03L-0 PARKER.H O Duke Power Co 80/09/29 3pp
- --8009030449 LER 80-024/03L-0 on 800731 cable controlling automatic initiation of HPSW pumps was taken out of svc to continue excavation of svc storage facility (SSF) cable trench Caused by conduit bank encased in concrete crossing trench route JONES. J. L. Duke Power Co. 80/08/29 lp
- 8009120444 Forwards LER 80-025/03L-0 PARKER, W 0 Dute Power Co 80/09/05 3pp
- --800912043& LER 80-025/03L-0 on 800807, keause hydro unit 2 failed to close-in automatically into overhead line Caused by dirty contacts on relay K3 Contacts cleared Replacement relays ordered although not required for safe operation JUNES, J L. Dute Power Co. 80/09/05 1p
- 8009160477 Forwards LER 80-026/03L-0 PARKER: W O Duke Power Co 80/09/10 3pp
- --8009160480 LER 80-026/03L-0 on 800811.HPSW pump 8 declared inoperable & removed from syc when water discovered leaking from cooler casing Gaused by erosion created by constant water flow Cooler b housing replaced Solenoid valves added JONES.J L Duke Power Co 80/09/10 Ip
- DOCKET 50-270 OCONEE NUCLEAR STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8009230236 Requests that all personnel be reminded of purpose of smergency notification sys & health physics network Sys installed for govt use during smergency O'REJELY, J P Region 2. Atlanta, Office of the Director 80/08/22 to
- @ Adjudicatory correspondence
- 8009260664 Forwards order requiring info supporting environ qualification or safety-related electrical equipment Requests submittal of info by 80:101 REID.R W Operating Reactors Branch 4 80/08/29 2pp

- --B009260667 Order for mod of Licenses DPR-38, DPR-47 & DPR-55 to add into which fully responds to NRC request for info re environ qualification of safety-related electrical equipment info should be submitted by 801101 EISENHUT, D C Division of Licensing 80/08/29 6pp
- J Insurance & indemnity information
- 8009190424 Forwards Endorsement 58 to NELIA Policy NF-182 & Endorsement 43 to MAELU Policy MF-61 SANDERS. F D Duke Power Co. 80/08/25 Spp
- 8009300428 Advises that invoices for facility indemnity fees should be addressed to WD Parker, not AC Thies PARKER, N 0 Duke Power Co 80/09/24 ip
- P Operating license stage documents & correspondence
- 8009150070 Responds to 800523 recommendations concerning lessons learned from 800226 transient at Crystal River Submits results of investigations reuse of atmospheric dump valve at Oconee Units 1-3, AR Unit 1, Davis-Sesse Unit 1 & TMI-I DENTON-H R Office of Nuclear Reactor Regulation, Director 80/07/21 2pp
- 8009050343 Discusses void formation in vessel head during 800611 natural circulation cooldown event Requests optnion repotential for voiding phenomenon in B&W designed NSS8 CHECK.P B Assistant Director for Plant Systems 80/07/28 2pp
- 8009020297 Bubmits interim criteria for shift staffing to all OL & CP licenses & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISEMMUT, D C Division of Licensing 80/07/31 7pp
- BOOTOBOORO Forwards draft NUREG-0676, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl W/o NUREG EISENHUT, D Q Division of Licensing 80/08/01 117pp
- BOO7230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D G Division of Licensing 80/08/07 60pp
- 8007040085 Requests written confirmation of appraisal of critical electrical power generation situation in region served by Duke Power Co NGAK.T M Assistant Director for Operating Reactors 80/08/11
- 8009160501 Forwards Amends 86.86 % 83 to Licenses DPR-38,DPR-47 % DPR-55,respectively, safety evaluation & notice of issuance & availability REID.R W Operating Reactors Branch 4 80/08/20 2pp
- --8009160502 Amends 86.86 & 83 to Licenses DPR-38, DPR-47 & DPR-58, respectively, incorporating test frequency requirements of 100FR50, App J, into containment leak test program REID.R W Operating Reactors Branch 4 80/08/20 7pp.
- --8009160506 Safety evaluation supporting Amends 86,86 & 83 to Licenses DPR-38,DPR-47 & DPR-55, respectively * Office of Nuclear Reactor Regulation, Director 80/08/20 2pp
- --B007160507 Notice of issuence & availability of Amends 84,86 & 83 to Licenses DPR-38,DPR-47 & DPR-55,respectively REID:R U Operating Reactors Branch 4 80/08/20 2pp
- 8009160505 Notification of 800903 meeting w/util & Franklin Research Ctr in BethesdaimD to review NUREO-0578, Items 2 i 7 A&B FAIRTILE, M. B. Operating Reactors Branch 4 80/08/21 ip
- 8009020025 Forwards BEW rept, "Evaluation of Instrumentation to Detect Inadequate Core Cooling Prepared for 177 Owners Oroup," supplementing earlier util submittals re-Lessons Learned Item 2: 3 b No addl instrumentation needed W/o encl PARKER,N D Duke Power Co 80/08/26. ip
- 8009100489 Informs NRC that revised radiological ETS "Offsite Dose Calculation Manual" & proposed process control program for solid waste sys will be forwarded by 800930 PARKER.W O Dose Power Co 80/09/03 ip

- 8009190154 Advises of NRC review of util 800328 submittal re standby shutdown facility Pages 2-1,5-1,5-2,5-3,6-3 & 7-1 should be withheld per 10CFR2 790 Util should resubmit document u/deletions within 30 days Operating Reactors Branch 4 80/09/09 2pp
- 8009250434 informs of acceptability of response to NRC 79:109 ltr reportions of ECCS evaluation models dealing w/fuel cladding suelling & incidence of rupture REID.R W Operating Reactors Branch 4 80/09/09 2pp
- 8009230724 Disagrees w/NRC 800909 ltr re classification of Standby Shutdown Facility licensing document Document should be withheld (ref 10CFR2 790) No nonpropietary version will be submitted PARKER. H D Duke Power Co 80/09/17 1p
- 8009300486 Forwards response to NRC 800611 request for change in facility Tech Specs-providing for redundancy in decay heat removal capability No changes necessary to Tech Specs PARKER: If O Duke Power Co 80/09724 3pp
- G Inspection reports: 1E Bulletins & correspondence
- BO09100058 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Written response required D'REILLY. J P Region 2, Atlanta, Office of the Director 80/07/24
- BOO7040640 Responds to IE Bulletin 80-16 Rosemount Model 1151 & 1152 pressure transmitters w/output codes A or D are used for indicating reactor coolant pressure & providing input to control steam generator level PARKER, H D Dute Fower Co 80/07/30 Spp
- 8009030175 Forwards Revision 1 to IE Sulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Hritten response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/15
- 8009160137 Forwards 1E Circular 80-18. "10CFR50 39 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22
- BO09170233 Responds to IE Bulletin 80-19. Revision 1. "Failures of Marcory-Natted Matrix Relays in Reactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E " Review indicates relays are not in use at facility PARKER. W O Duke Power Co 80/08/22 ip
- 8009100801 Ack receipt of 800423 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 30-269/80-17, 30-270/80-12 & 50-287/80-11 LEWIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 60/08/26 ip
- --8009100807 Responds to NRC 800523 ltr re violations noted in IE Insp Repts 50-269/80-17,50-270/80-12 & 50-287/80-11 Corrective actions incidents involving failure to perform surveillance are being reviewed & new procedures will be established PARKER: # 0 Duke Power Co 80/06/23 3pp
- --8009100911 Forwards IE Insp Repts 50-269/80-17,50-270/80-12 & 50-287/80-11 on 800401-30 & notice of violation LEMIS:R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/05/23 2pp
- ---8007100813 Notice of violation from insp on 800401-30

 Region 2, Atlanta, Office of the Director 80/05/23 ip
- --8009100814 IE Insp Repts 50-269/80-17,50-270/80-12 \$ 50-287/80-11 on 800401-30 Noncompliance noted failure to submit 30-day repts when surveillance test frequency was missed MARTIM-R D Region 2. Atlanta, Reactor Operations Nuclear Support Branch JAPE,F Region 4. Dallas, Office of the Director 80/05/23. 11pp
- 8009030605 Bubmits Revision 3 to util 90-day response to IE Bulletin 79-018 re Class IE equipment environ qualification Raychem heat shrink tubing, scotch Cast-9, transmitter O-ring seals & lubricating grease to be replaced during refusing outage THIES, A C Dute Power Co 80/08/27 2pp

- 8009110658 Responds to IE Bulletin 80-15 Emergency notification sys reviewed 8ys is powered by onsite power, but does not have backup onsite emergency power Emergency power supplied by telephone company PARKER, W D Duke Power Co 80/08/27
- BO09120343 Forwards IE Info Notice 80-31. "Maloperation of Oould-Brown Bover1 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required O'REILLY, J.P. Rogion 2, Atlanta, Office of the Director B0/00/27
- 8009160533 Ack receipt of 800623 its & 0806 supplemental response informing NRC of steps taken to correct violations noted in IE Insp Repts 50-267/80-15 % 50-270/80-10 MMRPHY/C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/09/04 ip
- --B007160540 Responds to NRC 800710 ltr requesting supplemental response to IE Insp Rept 50-270/80-10 Corrective actions Block 40303 will be modified to mest ASME requirements PARKCR.W O Duke Pawer Co 80/08/06 2pp
- --8009160535 Ack receipt of 800629 ltr responding to 800522 notice of violation Understands supplemental response will be provided by 800803 KWRPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/10 ip
- --B009160541 Responds to NRC 800522 ltr re violations noted in [£ Insp Repts 50-269/80-15 & 50-270/80-10 on 800415-17 & 21-23 Corrective actions design of callbr blocks reviewed & will be modified to meet ASME requirements PARKER.(f O Duke Power Co 80/05/23 2pp
- --8099160537 Forwards IE Insp Repts 99-269/80-15 & 50-270/80-10 on 800415-17 & 21-23 & notice of violation MURPHY,C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/22 2pp
- --8009160550 Notice of violation from insp on 800415-17 & 21-23 * Region 2, Atlanta, Office of the Director 80/05/15 1
- -8009160552 IE Insp Repts 50-269/80-15 & 50-270/80-10 on 800415-17 & 21-23 Moncompliance noted improperly designed inservice insp calibr blocks Region 2. Atlanta. Office of the Director 80/05/15 ECOHOKOS. N
- 8009290297 Forwards IE Circular 80-21, "Regulation of Refueling Crews " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/09/10
- 8009300616 Act receipt of 800825 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-269/80-23. 50-287/80-17 LEWIS, R C C Region 2, Atlanta, Reactor Operations Nuclear Support 80/09/16 ip
- -8009300626 Forwards response to NRC 800730 ltr re violations noted in IE Insp Repts 50-269/80-23.50-270/80-20 % 50-287/80-17 Corrective actions informed operations personnel that use of correct & verified procedures must be ascertained PARKER.N D Duke Power Co 80/08/25 3pp
- --8009300630 Forwards IE Insp Repts 50-267/80-23 & 50-270/80-20 & 50-287/80-17 on 800602-30 & notice of violation LEMIS:R C. Region 2: Atlanta. Reactor Operations Nuclear Support Branch 80/07/30 2pp
- --8009300631 Notice of violation from insp on 800602-30 # Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/07/28 | Ip
- --B009300640 IE Insp Repts 50-269/80-23,50-270/80-20 & 50-287/80-17 Noncompliance noted use of Unit 1 procedure to perform periodic tost on Unit 2 GRDERG.W. JAPE.F. Region 2. Atlanta. Office of the Director. MARTIN.R. D. Region 2. Atlanta. Reactor Operations Nuclear Suppl 7. JAPE.F. Region 2, Atlanta, Office of the Director. 1. D. Region 2, Atlanta, Reactor Operations Nuclear Support 80/07/28 13pp
- R Periodic operating reports & related correspondence
- B009020044 Forwards "Radioactive Effluent Release Semiannual Rept." Jan-June 1980 PARKER.W O Duke Power Co 80/08/25 to

- --8009020047 Radioactive Effluent Release Seniannual Rept." Jan-June
 - Duke Power Co 83/03/25 699
- BOC9090977 Forwards revision to 'Radioactive Effluent Release Centaminual Rept " Jan-June 1980 PARKER. N. D. Dute Power Co. 80709703 4pp
- -- E007070382 Revision to "Padicactive Effluent Release Semiannual Rept, " Jan-June 1980 • Dute Pouer Co 80/69/03 3pp
- EIC9190452 Forwards monthly operating repts for Aug 1980 PARKER W D Duke Power Co 80/09/15 1p
- 5 Reportable occurrences, LERs & related correspondence
- 1007030459 Forwards LER 80-012/031-0 PAGMER.W O Dute Pawer Co 80/03/29 3pp
- --8009020474 LER 80-012/03L-0 on 800730, w/unit at 59% full power. DUMP_UPAGE LER UP-012/021-0 on BUTON_UPAGE AT A THIS PUBLIC concentrated bors acid storage tank pump failed to pump to letdown storage tank Cause unknown Pump was repaired by adding oil & increasing stroke of pump JUNES.J L Dute Power Co 80/08/29 ip
- 8007120418 Forwards LER 80-013/03L-0 PARMER.W O Dute Power Co 80/09 80/09/04 300
- --5009123431 LER 80-013/03L-O on 800805.concentrated boric acid storage tank pump failed to pump to letdown storage tank Cause due to suction strainer blockage Suction strainer backwashed & pump verified operable
 JONES, J L Dute Power Co 80/09/04 1p
- 8007230494 Forwards LER 80-014/031-0 PARMER.W D Duke Power Co 80/09/18 1p
- --8009230504 LER 80-G14/03L-O on 800822, concentrated boric acid storage NYESDOW Len GWOISFORD SYE due to cil & flange leaks Caused by torn oil seel worn worn gear, bad flange gasket & stuck pressure relief valve Items replaced JONES J L Duke Power Co B9/09/19 Jpp
- 6009230509 Forwards LER 80-010/03L-0 PARKER-W B Duke Power Co 80/09. 80/09/18 1p
- --8009230517 LER 80-010/03L-0 on 800820.2 Low Pressure Svc Hater-19 valve failed to open from control room switch after closing to perform operational valve functional test Caused by failure of torque switch preventing valve opening USNES.J L Dute Power Co 80/09/19 2pp
- T Hearing transcripts on non-antitrust matters
- E009260313 Submittal of prepared testimony for first hearing session No attempts made to provide complete answers to ASLB 800908 mamorandum & order re-physical separation of TMI units Certificate of Svc enci Related correspondence TROMBRIDGE.CF Metropolitan Edison Co TROMBRIDGE.OF Shaw, Pittman, Potts & Trowbridge 80/09/15 7pp
- --8007260365 "Shall Break Operating Guidelines " Related correspondence.
 Babcock % Hilcox Co 67-1106001-00 79/11/30 48pp
- DOCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION F Sacuraty, medical, emergency & fare protection plans
- 8009230197 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency GRIER-BH Region 1. Philadelphia. Office of the Director BO/08/22 3pp
- 3 Adjudicatory correspondence
- 8005220115 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 IPPOLITO.T A Operating Reactors Branch 2 80/08/29, 3pp

- --8099220117 Order for mod of License DPR-28 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment info should be submitted by 801101 EISENHUT, D O Division of Licensing 80/08/29 App
- 8009300591 Forwards 800919 order revising 800829 grder for mod of QL, in EISENHUT.D G Division of Licensing 80/09/19 3pp
- --8009300598 Order revising 800929 order for mod of OL DPR-28, published in 800911 FR. in entirety Info responsive to IE Bulletin 79-01B shall be submitted by B01101 Request for hearing will not stay order effective 800919 UCS petitions discharged E1SENHUT.D 9 Divisson of Licensing 80/09/19 App
- P Operating license stage documents & correspondence
- 8009:10554 Suppls NRC 800707 request for proposed Tech Specs changes re scram discharge vol vent & drain valves, & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT,D G Division of Licensing 80/07/22 22pp
- 8009020297 Submits interim criteria for shift staffing to all QL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D 9 Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl. M/o NUREG EISENHUT, D O Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D O Division of Licensing 80/08/07 40pp
- 8007040532 Advises that two specific Event 3 valve configurations do not exist at facility per review of response to NRC 800223 ltr "Primary Coolant Sys Pressure Isolation Valves," technical evaluation rept encl
 IPPOLITO
- ~-8009040544 "Primary Coolant Eys Pressure Isolation Valves." technical evaluation rept NUELL,P N , BTILMELL,T C Franklin Institute/Franklin Research Center NRC-03-79-118 80/07/21 Spp
- 8009190991 Forwards "Mark 1 Containment Long-Term Program SER: Resolution of Generic Technical Activity A-7," NUREG-0661 W/o enci IPPOLITOIT A Operating Reactors Branch 2 80/08/20 3pp
- 8009110259 Forwards Amend 57 to License DPR-28.safety evaluation & notice of issuance & availability
 | IPPOLITO.T A Operating Reactors Branch 2 80/08/22 2pp
- --B0091102B5 Amend 57 to License DPR-28, incorporating limiting conditions for operation expressing max average planar linear heat generation rate timits for fuel in Cycle 7 IPPOLITO, T A Operating Reactors Brench 2 B0/08/22 5pp
- --8009110287 Safety evaluation supporting Amend 57 to License DPR-28
 * Office of Nuclear Reactor Regulation, Director 80/08/22 4
- --8009110270 Notice of issuance & availability of Amend 57 to License IPPOLITO, T A Operating Reactors Branch 2 80/08/22 2pp
- 8007080375 Proposed Change 90 to amend App A to License DPR-28,deleting containment air sampling sys valves 109-75A-Di182 & 109-76A & B from Tech Spec Table 4 7 2b & adding Valves VQ-23,VQ-26, 109-76A & B to Table 4 7 2a Fee enc!

 HEIDER,L H Vermont Yankee Nuclear Power Corp 80/08/28 4pp
- --8009080381 Proposed Change 90 to Tech Spec Tables 4 7 2.a & 4 7 2 b

 * Vermont Yankee Nuclear Power Corp 80/08/28 2pp
- 8009090478 Responds to NRC 800818 request for add1 info re adequacy of station electrical distribution voltages Add1 60 days needed to provide info due to current in-house work schedule SMITH.R L. Vermont Yankee Nuclear Power Corp. 80/08/29 1p

- 6039120401 Application for Suppl i to Proposed Change 81 amending App A Tech Specs of License DRR-28 concerning reactor vessel pressure/temp limitations Class III fee encl HEIDER:L. H Vermont Yankee Nuclear Power Corp 80/09/05 3pp
- --8009120405 Proposed mods to Tech Specs 3 & & 4 & re RCS pressure & temp imitations & coolant chemistry & Figure 3 & 1 at Versont Yankee Nuclear Power Corp 80/09/05 App
- 8009240548 Confirms util commitment to NRC 791023 "Interim Position on Containment Purging & Venting Pending Resolution of Etolation Valve Operability "Util position util remain in effect pending completion of NRC long-term review IPPOLITO.TA Operating Reactors Branch 2 80/09/10 3pp
- 8007240577 Ack response to NRC 791109 questions re ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture Response is acceptable IPPOLITO.T A Operating Reactors Branch 2 80/09/10 3pp
- 8309300575 Forwards request for add1 info re RCS vents, needed within 60 days for compiction of review re NUREO~0578 requirements NOVAK, T M Assistant Director for Operating Reactors 80/09/10 4pp
- 8309180431 Application for Proposed Change 91 to Tech Specs in response to TMI Lessons Learned Category A stoms Revises Tables 3 2 & & 4 2 & to incorparate instrumentation monitoring requirements & Table & 1 ire shift technical advisor HE(TER, L H Vermont Yankee Nuclear Power Corp 80/09/12 3pp
- --E009180452 Proposed Change 91 to Tech Specs in response to TMI Lessons Learned Category A items Revises Tabios 3 2 6 % 4 2 6 to incorporate requirements for monitoring instrumentation & Table 6 1.1 re shift technical advisor * Vermont Yantee Nuclear Power Corp 80/09/12 6pp
- 8009240207 Describes util alternative for reactor recirculation pump lubrication sys protection, in response to NRC 800220 ltr Proposed method incorporates oil collection sys designed to withstand Category I seismic event CCRMAY.W F Vermont Yankee Nuclear Power Corp 80/09/19 20p
- BO09260458 Forwards "Local Leak Test Program " Implementation of program wili require piping mods Anticipated that compliance w/program will be achieved during Fall 1981 refueling outage MARSOLAIB,1, D. Vermont Yankee Nuclear Power Corp. 80/09/19 2pp
- --8009260461 "Local Leak Test Program "
 + Vermont Yankee Nuclear Power Corp 80/09/19 13pp
- BO09260221 Submits add1 info supporting Proposed Change 79 rerecirculation pump trip/analog trip sys Info details equipment qualification for radiation exposure & temp & method of radiation dose calculation SHITH,R L Vermont Yankee Nuclear Power Corp 80/09/23 4pp
- G Inspection reports, IE Bulletins & correspondence
- BO09090101 Forwards IE Bulletin 80-07. Suppl 1. "SWR Jet Pump Assembly Fallure" Response required GRIER, BH Region 1. Philadelphia. Office of the Director BO/05/13 ip
- B009150130 Forwards IE Insp Rept 50-271/80-09 on 800627 No noncompliance noted GRIER, B H Region 1, Philadelphia, Office of the Director 80/07/18 2pp
- --8007150137 IE insp Rept 50-271/80-09 on 800627 No noncompliance noted, Major areas inspected systematic assessment of licensee performance program radioactive math transport & surveillance BRUNNER.E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch BORES.R J. COLLINS, B J Region 1. Philadelphia, Office of the Director 80/07/16 7pp
- BO09020113 Responds to IE Bulletin 80-17. "Failure of 76 of i85 Control Rods to Fully Insert During Scram at BWR " Mods made to existing vent lines so that vaive is effective regardless of component operability other than vent valve TRIBBLE.J E Vermont Yankee Nuclear Power Corp 80/07/28 2pp
- BOC7190947 Forwards response to 1E Bulletin 80-14 re degradation of BMR scram discharge vol capability No instances of level switches or vent & drain valve failure identified Bulletin required io manhours
 TRIBBLE, J E Vermont Yankee Nuclear Power Corp 80/07/28 3pp

- 8009i10467 Responds to IE Builetin 79-03A. "Longitudinal Weld Defects in ABME BA-312. Type 304 Stainless Steel Pipe " Facility has determined that none of subj pipe is used or planned for use in safety-related sys MARSOLAISIL D Vermont Yankee Nuclear Power Corp 80/08/05 2pp
- 8009230100 Responds to IE Rulietin 80-17. Suppl 1 Continued analysis of scram discharge vois will identify changes necessary for improvement Operating procedure for control rod drive sys & standby liquid control sys revised

 HEIDER.L H Vermont Yankes Nuclear Power Corp 80/08/11 4pp
- 8009030066 Forwards Revision i to IE Bulletin 80-19, "Failures of Morcury-Metted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER. B Region i, Philadelphia, Office or the Director 80/08/15 ip
- 8009100127 Responds to 1E Builetin 80-17. Suppl 1. "Fallure of 76 of 185 Control Rods to Fully Insert During Scram at BWR "
 Installation of water level monitoring sys by 8009901 is not possible for listed reasons
 TRIBBLE.J E Vermont Yankee Nuclear Power Corp 80/08/15 2pp
- 8009120114 Forwards Buppl 3 to IE Builetin BO-17, "Failure of Control Rods to Insert During Stram at BWR " Written response required GRIER,B H Region 1, Philadelphia, Office of the Director 80/08/22 1p
- 8009180035 Forwards iE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GRIER, B H Region i, Philadelphia. Dffice of the Director 80/08/22 1p
- 8009120215 Forwards IE Info Notice 80-31, "Maioperation of Gould-Brown Boveri 480 Volt Type K-600S & K-DON 600S Circuit Breakers "No written response required ORIER.B H Region 1, Philadelphia, Office of the Director 80/08/27 1p
- 8009230514 Forwards Revision 1 to IE Bulletin 79-26. "Boron Loss From BWR Control Dlades " Written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/08/29 1p
- 8009240027 Forwards IE Circular 80-21, "Regulation of Refueling Creus." No written response required GRIER.B H Region I, Philadolphia, Office of the Director 80/09/10 1p
- 8009240337 Forwards IE Info Notice 80-32. "Ciarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required QRIER.8 H Region i. Philadeiphia, Office of the Director 80/09/12 ip
- R Periodic operating reports & related correspondence
- 8009090535 Forwards "Efficient & Waste Disposal Semiannual Rept. Radiological Impact on Man.Jan-June 1980 " EMITH.R L Vermont Yankee Nuclear Power Corp 80/09/04 1p
- --8007070540 "Effluent & Waste Disposal Semiannuel Rept.Radiological Impact on Man.Jan-June 1980 " * Vermont Yankee Nuciear Power Corp 80/07/04 50pp
- 8009160291 Forwards monthly operating rept for Aug 1980 CDNMAY,W F Vermont Yankee Nuclear Power Corp 80/09/08 1p
- --8009140301 Monthly operating rept for Aug 1780 BURGER, F. J. BEERS, F.C. Vermont Yankee Nuclear Power Corp 80/09/08 6pp
- S Reportable occurrences, LERs & related correspondence
- 8009050318 Forwards LER 80-019/01T-1 MURPHY, N P Vermont Yankee Nuclear Power Corp 80/09/02 ip
- ---8009080322 LER 80-019/017-i on 8009i6:AE00 radiation monitors 17-190 A

 B were made inoperative under controlled conditions while
 evaluating low augmented off-gas sys recombiner temps
 Caused by hydrogen recombination upstream of recombiners
 HURHY,W P Vormont Yankee Nuclear Power Corp 80/09/02 5pp

- 8009190575 PND-1-80-126 on 60090B, pictet line was set up at station entrance Licensed operators are honoring picket line Shift staffing plan prepared using supervisory personnel RAYMOND, U. J. MARTIN, T. T. SRUNKER, E. J. Region 1. Philadelphia, Office of the Director 60/09/08 3pp
- U Congressional/Executive Correspondence
- 8009150020 Responds to Subcommittee on Nuclear Regulation 780906 ltr no Senator Stafford request for hearing to discuss 1972 memo re pressure suppressing containments. UCS criticisms ne ATMS safety problems & West Valley insp problems HENORIE, J M Commission 80/08/18 2pp
- --8009150039 Discusses AEC 720801 affidavit on rod drop accident Upgrading of rod worth minimiser or acceptance of faster scram times is proposed for ruture BHR reviews Temporary basis recommended in encl nemo acceptable HatMRIE. J M Atomic Energy Commission. Deputy Director for Technical Review (Pre-1975) 72/03/04 Ep
- --8009150044 Advises that affidavit on facility rod drop accident allows temporary use of add) operator during startup Permanent fires uill be required beyond 12-month period BOVA. 6 Atomic Energy Commission. Directorate of Licensing 72/08/01 1p
- DOCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- 8009090882 Requests participation in NRC study of people-related problems in nuclear safeguards Request includes NRC visit to facility to interview security agt personnel Confidentiality of info will be maintained during all phases of study VARGA.S A Operating Reactors Branch 1 80/08/14 2pp
- 80082803ii Forwards addl info re NUREC-0674 fire protection requirements that will not be met, as identified in util 800808 2:19 ltrs Addl justification in support of implementation schedule & oversized drawings encl MITTLR L Public Service Electric & Gas Co of New Jersey 80/08/22 12pp
- --8007040074 "Containment Sump Level Transmitter.Installation Detail " Drawing Number 237086-8-7637-1R-IEC-0549-02/0 * Public Service Electric & Gas Co of New Jersey 80/06/24 ip
- --B009040375 "Auxiliary Bidg Reactor Containment & Fuel Handling Area, Elevation 100 Ft " Sheet 1 of 1 4 Public Service Electric & Gas Co of New Jersay 78/09/01 ip
- -8009040378 "Auxiliary Bldg.Elevation 84 ft.Reactor Containment 78 ft & 81 ft & Fuel Handling Area Elevation 85 ft & 89 ft 6 inches "Sheet 1 of I # Public Service Electric & Gas Co of New Jersey 78/09/05 ip
- ---B009040379 "Auxiliary Bldg & Reactor Containment Elevation 64 Ft " Public Service Electric & Gas Co of New Jersey 78/08/31 1p
- --8009040381 "Auxiliary Bldg & Reactor Containment Elevation 45 Ft & 5 ft " Sheet 1 of 1 Public Service Electric & Gas Co of New Jersey 78/08/31 ip
- --8009040384 "Auxiliary Bidg & Reactor Containment Section A-A" Sheet 1 of t # Public Service Electric & Gas Co of New Jersey 77/01/24 1p
- --8009040385 "Auxiliary Bldg & Reactor Containment, Sections B-B & C-C " Public Service Electric & Gas Co of Naw Jersey 76/12/29 1p
- --8007040388 "Reactor Containment Slab at Elevation 78 Ft & Elevation 81 Ft " Sheet 1 of 5 Public Service Electric & Qas Co or New Jersey 75/06/23 1p
- --8009040392 "Reactor Containment Slab at Elevation 78 Ft & 81 Ft. Sections " Sheet 4 of 5 * Public Service Electric & Gas Co. of New Jersey 70/12/01 1p
- --8007040394 "Reactor Containment Internat Walls & Reactor Foundation Plan Elevation 90 ft " Sheet 1 of 15 Public Service Electric & Gas Co. of New Jersey 71/07/06 1p

- ---B009040376 "Reactor Containment Internal Walls & Reactor Foundation Plan -- Elevation 94 Ft." as-built Sheet 2 of 15 * Public Service Electric & Gas Co of New Jersey 76/03/23 1p
- ---8009040398 "Reactor Containment Internal Walls & Reactor Foundation Plan Elevation 104 Ft " Sheet 3 of 15 Public Service Electric & Gas Co of New Jersey 74/08/08 19
- --8009040399 "Reactor Containment Internal Walls & Reactor Foundation. Sections." as-built Sheet 6 of 15 * Public Service Electric & Gas Co of New Jersey 76/03/23 19
- --8009040402 "Reactor Containment Internal Walls & Reactor Foundation. Sections " Sheet 5 of 15 * Public Service Electric & Qas Co of New Jersey 75/06/24 ip
- --8009040403 "Reactor Containment.Reactor Pit " Sheet & of 2 # Public Service Electric & Gas Co. of New Jersey 76/01/28 ip.
- --8007040405 "Reactor Containment, Reactor Pit," as-built Sheet 2 of 2 Public Service Electric & Oas Co of New Jersey 74/01/29 is
- --8009040407 "Reactor Containment Internal Walls & Reactor Foundation, Sections " Sheet 7 of 15 * Public Service Electric & Qas Co of New Jersey 71/03/10 ip
- ---B009040408 "Reactor Containment Internal Walls & Reactor Foundation, Reinforcement Plans & Sections," as-built Sheet 13 of 15 * Public Service Electric & Gas Co of New Jersey 76/03/22 19
- --8009040410 "Reactor Containment Internal Halls & Reactor Foundations Reinforcement Plans & Sections " Sheet 14 of 15 # Public Service Electric & Gas Co of New Jersey 74/03/06. Ip
- --8009040411 "Reactor Containment Drain Trench Elevation 81 ft & 70 ft --Sump Pit Elevation 54 ft & Inches > 72 ft 7 Inches " Sheet 1 of 1
 - Public Service Electric & Gas Co of New Jersey 77/08/08
- 8009230193 Requests that all personnel be reminded of purpose of emergency notification sys 5 health physics network Sys installed for goot use during emergency GRIER, B H Region 1. Philadelphia, Office of the Director 80/08/22 3pp
- G Adjudicatory correspondence
- 8009190283 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 VARGA.S A Operating Reactors Branch 1 80/08/27 2pp
- --8009190269 Order for mod of License DPR-70 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted 601101 EIGENHUT, D & Division of Licensing 80/08/29 App
- P Operating license stage documents & correspondence
- 8009090792 Advises that control rod guide thimble tube wear issue is resolved for 17 x 17 Westinghouse fuel assemblies at facility, based on encl evaluation
 VARGA, S.A. Operating Reactors Branch 1. 80/07/22 4pp
- 8009020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D O Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREC-0494. "Functional Criteria for Emergency Response Facilities." Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0494 encl. M/O NUREG EISENHUT, D G Division of Licensing 80/08/01 119pp
- B009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend.

 EISENHUT.D G Division of Licensing 80/08/07 40pp

- BCO9190794 Forwards revised Westinghouse STS 3 9 8 2.3 9 10 & Bases 3/4 9 8 & 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuol assemblies or control rods Written response required NOVAK, T M Assistant Director for Operating Reactors 80/08/15 to
- --8009190817 Revised Wastinghouse STS 3 9 8 2,3 9 10 5 Bases 3/4 9 8 5 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods

 * Assistant Director for Operating Reactors 80/06/23 21pp
- 8009150511 Forwards request for add1 info re plant electric distribution sys Details re capability of plant to operate w/one power transformer out of syc needed to complete NRC review VAROA+S A Operating Reactors Branch 1 80/08/18 3pp
- 6009120513 Forwards questions pertaining to turtle specimen collected from intake structure at unit VARGA.S A Operating Reactors Branch 1 80/08/26 3pp
- 8009180518 Requests compliance w/QA procedures for sampling fuel oil described in Reg Guide 1 137 Justification needed reposition that diesel fuel oil need not be included in QA program Response requested within 20 days VARGA.8 A Operating Reactors Branch 1 80/08/26 2pp
- 8009160401 Requests that util response to NRC 800702 ltr be delayed 90 days after formal issuance of Unit 2 Tech Specs Tech Spec amends per TMI Lessons Learned Category A requirements for Unit 1 will be implemented after issuance of Unit 2 OL 4. ISRIZZI.F P Public Service Electric & Oas Co of New Jersey 80/09/09 1p
- 8009250260 Requests amend & analysis of change to Licenso DPR-70 re encl safety Tech Specs for refuoling operations Class III amend fee encl LIBRIZZI.F P Public Service Electric & Qas Co of New Jersey POLITYIS
- 8009300503 Advises of util review & plans re Cycle 3 reload core Postulated evants are within allowable limits Application for amend to license is not required Reload core design will be veriffed during startup physics testing program LIBRIZZI.FP Public Service Electric & Oas Co of New Jersoy BO/09/24 3pp
- 8009300512 Ack receipt of 800826 ltr requesting addl info re collection of loggerhead sea turtles & Kemp Ridley sea turtles Responses enci LIERIZZI,FP Public Service Electric & Gas Co of New Jersey 80/09/24 ip
- ---8009300518 Forwards list of questions re specimens of Atlantic loggerhead turtle & Kemp Ridley sea turtle Response requested within 30 days of receipt of ltr VAROA:B A Operating Reactors Branch 1 80/08/26 19pp
- O Inspection reports, IE Bulletins & correspondence
- BOO9080330 Responds to IE Bulletin 80-05 Per 800606 response, subsequent investigation revealed two addl tanks which could be subjected to conditions' that might cause inward buckling SCINEIDER.F M Public Bervice Electric & Gas Co of New Jersey 80/07/29 ip.
- BOO9090230 Forwards addl response to IE Bulletin 79-27 re loss on monclass IE instrumentation Evaluation of feasibility of design mods completed & results encl BCHNEIDER: FW Public Service Electric & Cas Co of New Jersey 80/07/31 9pp,
- 8009030091 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required ORIER.B H Region 1, Philadelphia, Office of the Director 80/08/15 ip

- 8009180042 Forwards IE Circular 80-18, "(OCFR50 59 Safety Evaluations for Changes to Radwasto Treatment Sys " No written response required ORIER: B H Region I. Philadelphia, Office of the Director 80/08/22 10
- 8009120206 Forwards IE Info Hotice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Typo K-6005 & K-DON 6005 Circuit Breakers " No written response required GRIER. B H Region 1, Philadelphia, Office of the Director 80/00/27 1p
- 8009240045 Forwards IE Circular 80-21, "Regulation of Rafueling Crews " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/09/10 ip
- B009240355 Forwards 1E Info Notice B0-32. "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/09/12 lp
- R Periodic operating reports & related correspondence
- 8009050290 Forwards "Radioactive Effluent Release Rept,Jan-June 1980 " LIBRIZZI.F P Public Service Electric & Gas Co of New Jersey 80/08/29 1p
- ---8009030294 "Radioactive Effluent Release Rept, Jan-June 1980 "

 * Public Service Electric & Oas Co of New Jersey 80/08/31
 37pp
- 8009160298 Forwards monthly operating rept for Aug 1980 MIDURA.H J Public Service Electric % Gas Co of New Jersey 80/09/10 lp
- --8009160300 Monthly operating rept for Aug 1980
 MILLER.L K Public Service Electric & Gas Co of New Jersey
 80/09/10 18pp
- S Reportable occurrences. LERs & related correspondence
- B009110663 PNU-I-B0-110 on 800725. IBEN union went on strike Unit 1 operations are continuing w/licensed supervisory personnel All phone lines at facility have been disabled BRI003. L. KEIMIG. R. SRUNNER, E. J. Region 1, Philadelphia, Office of the Director B0/07/25 lp
- 8009090593 Forwards LER 80-043/03L-0 LIBRIZZI.F P Public Service Electric & Gas Co of New Jersey 80/08/28 2pp
- --8009090595 LER 80-043/03L-0 on 800801, during routine surveillance of control console, water level in refueling water storage tank determined to be below min level (350,000 gallons) Cause due to addition of water to spent fuel pit Tank refilled NEMMAN.R J Public Service Electric & Gas Co of New Jersey 80/08/28 Ip
- 8009090578 Forwards updated LER 79-004/03X-1 LIBRIZZI, F P Public Service Electric & Gas Go of New Jersey 80/09/02 3pp
- --8007070587 Updated LER 79-004/03X-1 on 770103, during normal operations, status alarm panel indicated loop 1 steam pressure t00 psi less than loop 4 Bteam pressure channels checked & loop 4 Channel 4 read 100 psi high Caused by Frozen sensing line KAPPLE, A W Public Service Electric & Cas Co of New Jersey 80/09/02 ip
- 8007070587 Forwards updated LER 79-057/01X-1 LIBRIZZI,F P Public Service Electric & Gas Co of New Jersey 80/09/04 1p
- --8009090591 Updated LER 79-057/01X-1 on 790907 during IE Bulletin 79-14 insp of pipe hangers on Stismic I systhmae hangers found to hve broken weld bolt & pipe guide Caused by irregular pulsations of charging pump 13 stressing supports KEPPLER.A W Public Sprvice Electric & Gas Co of New Jersey 80/09/04 2pp
- 8009120357 Forwards LER 80-044/03L-0 LIBRIZZI,F P Public Service Electric & Gas Go of New Jersey 80/09/04 2pp

DOCKETED ITEMS

- --8007;20372 LER 80-044/03L-0 on 800805 during routine containment entry, containment air lock became inoperable Caused by broken roller on outer door Roller replaced & tested satisfactorily MURPHY, M J Public Service Electric & Gas Co of New Jersey 80/09/04 ip
- 8009120375 Forwards (ER 80-045/03L-Q LIBRIZZI,F P Public Service Electric & Qas Co of New Jersey 80/09/04 2pp
- --8009120382 LER 80-045/03L-0 on 800805.air particulate detector pump seried Apparently caused by equipment failure Pump replaced MURPHY.M U Public Service Electric & Gas Co of New Jersey 80/09/04 2pp
- 8009120424 Forwards LER 80-044/03L-0 LIBRIZZI.F P Public Service Electric & Gas Co of New Jersey 80/09/04 2pp
- --8009120428 LER EO-046/03L-O on 800810.during routine operation, steam generator level feed flow-steam flow mismatch circuit 12 failed Caused by failure of comparator in circuit Unit replaced 8 tested satisfactorily MURPHY. M UP Hublic Service Electric & Oas Co of New Jersey EO/09/04 1p
- 8009300633 PNS-I-80-021 on 800910, potential act of sabotage may have occurred when high chloride concentrations were found in hydraxine addition tank for auxiliary feed water after anonymous caller gave notice of such problems DEVLIM.J. MARTIN.W. KLEIMIG.R. Region 1. Philadelphia, Office of the Director 80/09/12 lp

V Operator Examinations

- 8009120669 Refers to 800801 discussion w/J Zupto & 800804 telcon w/F Schneider re training & qualification for position of shift technical advisor Qualifications for position documented in Suppl 4 to facility SER GRIER, B H Region 1, Philadelphia, Office of the Director 80/08/05 lp
- 8009180306 Summary of 600805 meeting U/applicant in Bethesda.MD re operatur oram results KERRIOAN.J Licensing Branch 3 80/08/21 App
- 8009110323 Notifies that all reactor operators & senior reactor operators received low power test program training Lists operators not trained because unit taken to Mode 5 operation on 800805 due to control rod drive mechanism vent leakage ECKERTIR M Public Service Electric & Gas Co of New Jersey 80/09/05 lp
- 8007230368 Requests waiver of 6-month experience requirement for three interim shift technical advisors Maiver will expedite licensed operator staffing plan Personnel info encl available in Central Files only LIBRIZZIFP Public Service Electric & Oas Co. of New Jersey 80/09710 2pp

DOCKET 50-273 BEZNAU NUCLEAR STATION, UNIT

- 4 Inspection reports, 1E Bulletins & correspondence
- 8009150495 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Red Drive Scram Function & Nonessential Control Air at Certain GE BHR Facilities " No specific action or response requested KEPPLER, J G Region 3. Chicago, Office of the Director 80/08/20 in
- DUCKET 90-274 U S GEOLOGICAL SURVEY RESEARCH REACTOR
- O Inspection reports. IE Builetins & correspondence
- B009150495 Forwards IE Info Notice B0-30, "Potential for Unacceptable Interaction Between Control Red Drive Stram Function & Nonessential Control Air at Certain GE BNR Facilities " No specific action or response requested KEPPLER.J O Region 3. Chicago, Office of the Director 80/08/20 in

- DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- 8007020263 Forwards response to questions re Category 1 concrete masonry walls, sample calculation 5 pertinent location drawings, in response to NRC 800421 ltr CRANE.P A Pacific Gas & Electric Co 80/08/27 32pp
- --8009020265 "Plan Area A Elevation 107 Ft "
 * Pacific Gas & Electric Co 79/12/11 1p
- --8009020268 "Plan Area H Elevation 100 Ft "
 # Pacific Gas & Electric Co 78/02/24 ip
- --B007020269 "Plan Area A Elevation 119 Ft "
 # Pacific Gas & Electric Co 80/07/15 ip
- --8007020270 "Plan Area H Elevation 115 Ft "
 # Pacific Gas & Electric Co 79/09/22 is
- --8009020272 "Plan Area H Elevation 128 Ft "
 * Pacific Gas & Electric Co 78/10/30 1
- --8009020274 "Plan Area & Elevation 185 Ft "
 * Pacific Gas & Electric Co 78/11/01 ig
- ---B009020277 "Miscellaneous Concrete Block Detalls " # Pacific Qas & Electric Co 78/09/27 ip
- 8009:10707 Forwards request for add1 info to continue review & evaluation for full power GL Info should be provided re low power turbine discs & rotors & evaluation of turbine missiles

 SCHWENCER, A Licensing Branch 3 80/08/27 7pp
- 8009090544 Advises that habitability aspects of facility control room comply w/requirements of Reg Guldes 1 78 & 1 95 & BRP. Sections 2 2 1-3 & 4 4 as specified in NUREG-0660.per NRC 800907 request Conclusion confirmed in Buppl 9 to SER CRANE.P A Pacific Oas & Electric Co. 80/09/03 ip
- 8009180486 Forwards Revision 4 to "Description of Sys Interaction Program for Setsmically-Induced Events" Requests that recetely of rept be ack CRANE.P A Pacific Qas & Electric Co 80/09/16 ip
- --8009180493 "Description of 8ys Interaction Program for Swismically-Induced Events," Revision 4 * Pacific Gas & Electric Co 80/08/29 92pp
- 8009250289 Forwards response to NRC 800606 itr requesting addl info re shielding review containment monitors % iodine sampling at facilities Monitors are mutually redundant using separate power supplies from separate vital instrument busses CRANE.P A Pacific Gas & Electric Co. 80/09/22 6pp
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8009090195 Forwards Suppl 10 to facility SER covering TMJ-2-related matters W/o encl SCHMENCER, A Licensing Branch 3 80/08/15 5pp
- F Security, medical, emergency & fire protection plans
- 8009030337 Notifies of 800819,22 & 30 regional workshops re development of guidance for acceptable method for coping w/emergencies at facility Requests that representative be sent Subj areas to be discussed include function of facilities & location EXOSELKEN.R H Region 5, San Francisco. Office of the Director 90/08/12 2pp
- 8009230337 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during amergency ENDELKEN,R H Region 5, San Francisco, Office of the Director
- 8009150565 Requests addi info & commitments re NRC evaluation of emergency preparedness program for conformance w/NUREG-0654 TEDESCO,R L. Assistant Director for Licensing 80/08/26 9pp

- BO09090512 Requests clarification of apparent omission of ltr of agreement between util & Field Ranch on Page 5-6 of Feb 1980 Energency Plan Revision 2.App 7
 SCHMENCER.A Licemsing Branch 3 80/08/30 3pp
- 8009290049 Forwards S Schwencer 800910 memo to HR Denton re alleged inaccuracies in emergency plan text Requests assistance in determination of substantiation of alleged inaccuracies TEDESCO.R L Division of Licensing 80/09/11 ip
- 8009220220 Forwards lighting maps of protected area of facility in response to NRC request Maps withheld (ref iOCFR2 790) ROSE.D G Los Alamos Scientific Laboratory 80/09/17 19
- G Adjudicatory correspondence
- 8009030157 Executed amended affidavit of nondisclosure protecting licensee physical security plan Certificate of Svc encl LEHIS.W L Affiliation Unknown 80/08/20 6pp
- BOOTGOOGET Response in opposition to Governor of CA motion for revision of nondisclosure affidavit re security plan Takes exception to Governor of CA BOOSIA & 19 ltrs submitted in response to ASLAB order Certificate of Svc encl NORTON.B , GEHR.A C , FURBUSH.H H Pacific Gas & Electric Co BO/OSI/21 7pp
- 8009020071 Motion for JE Luco & MD Trifunac to provide testimony by 800905 instead of 800902 Secretarial help unavailable NCRDLINGER,M 8 Office of the General Counsel 80/08/27 1p
- B009030112 Order scheduling Sept-Nov 1980 security plan hearings Parties may move for supplemental evidence re issues reopened in seismic ALAB-5983-by 800919 State of CA motion to revise nondisclosure affidavit denied BIEHOP.C J Atomic Safety and Licensing Appeal Panel 80/08/28
- 8007030679 Response to ASLB 800814 order re util motion to load fuel & for low power tests Covernor of CA & joint intervenors' replies should be stricken as failures to make substantive responses Certificate of Svc encl CRANC.P A , CEHR, A C , NORTON, B Pacific Gas & Electric Co 80/08/28 7pp
- B009110019 Request for 800925 site lnsp visit Becurity plan w/maps, diagrams & safeguards contingency plan must be available for seview by HH Brown.LC Lanpher.LO Giuffrida.RE White & DR Sievers who will undertake visit BROWN.R H , GEORGIOU, B S , LANPHER, L C California, State of E0/09/08 2pp
- 8009150404 Response to ASLB 800814 order re util 800804 motion for low power tests Urges summary dismissal of motion Sacurity & seismit issues not yet resolved & are needed for low power testing BROWN.H H . LANPHER.L C California. State of BROWN.H H Hill Christopher & Phillips 80/09/11 4pp
- 8009160234 Response to ASLB 800814 order re util motion for low power testing Urges dismissal of motion due to reopening of record on security plan & seismic design Late discovery of Hosgri fault warrants consideration of Class 9 accidents FLEISCHAKER, D San Luis Obispo Mothers for Peace, FLEISCHAKER, D Fleischaker, D 8 80/09/11 5pp
- 8009160360 Forwards JF Devine & RF Yerkes combined testimony w/latter prof qualifications.per ASLB 800819 memorandum & order Explains avc process re repts mentioned in testimony XETCHEN.E 0 Hearing Branch 4 80/09/12 2pp
- --8009160363 Combined testimony in response to ASLB 800819 memorandum & order on Question 9 re geology & seismology repts New data & canclusions re LNO repts have no impact on USO8 position RF Yerkes prof qualifications encl DEVINE. JF, YERKES, RF Interior, Dept of, Geological Survey 80/09/12 App
- 6009190036 Forwards 800819 FR notice re upgraded emergency plan regulations DAVIB.L D Hearing Branch 4 80/09/15 19pp
- 8009220406 Response in opposition to util & NRC objections to 8tate of CA 800902 statement of security plan issues upon which participation is requested Challenged subjs are responsive to ABLB 800808 fourth prehearing conference order BROWN,H H , LANPHER,L.C., GEORGIOU, B S California, State of 60/09/15 4pp

- 8009220262 Forwards plaintiff, San Luis Obispo Nothers for Peace, complaint for declaratory judgement, injunctive relief & mandamus, disqualifying JM Hendrie from further participation in OL proceedings FLEISCHAXER, D. Fleischaker, D. 8 FLEISCHAXER, D. San Luis Obispo Hothers for Peace 80/07/16 20pp
- 8009230616 Correction to State of CA 800908 interrogatories directed to NRC re security plan proceeding Certificate of Svc encl Related correspondence BRCMK H H , LANPHER, L C , GEORGIOU, B S California, State of 80/09/16 4pp
- 8009240544 Forwards RB Hubbard affidavit re need for Class 9 accident analysis to accompany joint intervenors' reply to ASLB 800814 order Related correspondence FLEISCHAXER.D Fleischaker, D S 80/09/19 1p
- ~-8009240546 Affidavit re need for Class 9 accident & sys reliability analyses of facility by util Analysis needed due to effect of reactor contamination on economic cost & health risks CEG 800320 ltr encl Related correspondence HUBBARD.R B MHB Technical Associates 80/09/17 lBpp
- ~-8009240550 Submits conclusion of study on NRC regulations & policy re environ analysis of possible nuclear accidents under NEPA Typical EIS does not consider or analyse possibility of major accident in Class 9 category SPETH, 0 Council on Environmental Guality 80/03/20 App
- 8009260469 Notice of 801020 evidentiary hearings in San Luis Obispo.CA re ASCAB 800624 decision.ALAB-598, which reopened seismic issues
 BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/09/23
- H General correspondence
- 8007070534 Urges use of influence for speedy & successful approval of facility Industrial & agricultural production could be Jeopardized SLOTF, N Affiliation Uninown 80/07/23 lp
- 8009110382 Urges opening of facility as necessary enterprise in area Newspaper articles encl BRADBURY,V A Affiliation Unknown 80/08/05 4pp
- 8009170200 Responds to 800326 ltr to President Carter re delays in licensing process Delays attributed to seismic re-evaluation of facility.lessons issened from TMi accident by public hearings resafety & security SCHWENCER.A Licensing Branch 3 80/08/22 5pp
- 8009030581 Requests that facilities be cortified for startup operations \$\psi\$ plans for RY81-82 be devloped \(\omega/\text{0}\) delay, CA could face serious power shortages Electronics industry \$\psi\$ economy could be adversely affocted QARCIA.K California, State of 80/08/25 lp
- 8009090342 Urges denial of licensing Diablo Nuclear power plant & any other plants SCHUMGHER.J Affiliation Unknown 80/08/27 1p
- 8009100457 Ack receipt of 800705 ltr & forwards Friends of the Earth Class 9 petition & Director's decision on petition W/o enci SCHHENGER, A Licensing Branch 2 80/08/27 2pp
- --B009100463 Requests Director's decision on Friends of the Earth petition to consider Class 9 accidents in supplemental EIS FRIESEMA, H P Northwestern Univ 80/07/05 1p
- B009220042 Responds to 800319 ltr opposing licensing of facilities NRC has reacted positively in light of TMI accident to improve safety at all nuclear plants in operation & under const SCHWENCER, A Licensing Branch 3 80/09/03 ip
- 8009180248 Responds to 800422 ltr to President Catar re potential radiological risks at facility NRC has re-examined plant for conformance to fuel loading & low power testing requirements
 ECHWENCER, A Licensing Branch 3 80/09/09 3pp
- 8007270054 Forwards 800830 ltr to util requested by C Neiburger of Telegram Tribune on 800909 re alleged inaccuracies in emergency plan text Matter must be resolved prior to issuance of full power CL.
 EISENHUT, D G Division of Licensing 80/09/10 1pp

- --R007290057 Responds to 800721 Itr expressing conterns we util emergency plan Agreement between Field Ranch & util re emergency evaruation route has been requested from util Matter util be resolved before ARC issues full power OLDEMON. HR Office of Nuclear Reactor Regulation, Director BROWS In
- 8009300293 Responds to 790920 Itr to President Carter to concurr over affect of low level radiation:storage & transportation of high level radiaste & ability of plant to withstand sessmic activity Fact sheets addressing concerns that MIRAGLIA:F Licensing Branch 3 80/09/19 opp
- --E009300305 Forwards misdirected T Come: 790920 Itr to President Carter re effects of low level radiation Requests response RATHKOPF.C L Energy. Dept of 60/01/22 3pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8009090514 Forwards Amend 85 to DL application, including matl for Chapters 4,13,14 & 17 of FSAR CRAME,P A Parific Gas & Electric Co 80/09/03 2pp
- --8009090520 Amend 85 to OL application including math for FSAR Chapters 4,13,14 & 17 SCHWILER.J O Pacific Gas & Electric Co 80/08/28 7pp
- --8007090526 Revision to FSAR.including matl re GA & conduct of operations for Chapters 4.13,14 & 17
 * Pacific Gas & Electric Co 80/08/31 403pp
- P Operating license stage documents & correspondence
- 8009080080 Forwards draft NUREG-0296, "Functional Criteria for Emergency Response Faculities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 and W/a NUREG EISENHUT, D C Division of Licensing 80/08/01 119pp
- Q Inspection reports. IE Bulletins & correspondence
- SD09260299 Forwards 1E Info Notice 80-29, "Broken Studs on Terry Turbine Steam Injet Flange " No written response required ENGELXEM R H Region S. San Francisco, Office of the Director EO/08/07 1p
- 6009230212 Forwards IE Insp Rept 50-275/80-15 on 800701-31 No noncompliance noted CREUS, J. L. Region 5. San Francisco, Reactor Operations Nuclear Support Branch 80/08/12 2pp
- --8009230219 IE Insp Rept 50-275/80-15 on 800701-31 No noncompliance noted Major areas inspected preoperational testing plant tour-fire protection/prevention & operator training STERNBERG, D K Region 5, San Francisco, Reactor Operations Nuclear Support Branch YOUNG, T. BAGAGLIOLH Region 5, San Francisco, Office of the Director 80/08/11 4pp
- 8009030278 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Mercury-Hetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Hritten response required ENGELKED, R H Region 5, San Francisco, Office of the Director 80/08/15 1p
- 8009270305 Forwards 1E Info Notice 80-27, "Degradation of Reactor Coolant Pump Stude " No written response required ENGELXEN.R H Region 5, San Francisco, Office of the Director 80/09/18 4ps
- 8009160181 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required ENGELKEN R H Region S, San Francisco, Office of the Director 80/08/22 lp
- 8009120458 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6005 & K-DDN 6005 Circuit Breakers " No written response required ENSELERIR H Region 5, San Francisco, Office of the Director 80/08/27 lp
- I dearing transcripts on non-antitrust matters
- 1009070779 Testamony in response to ASLAB 800807 order, ALAB-604 LUCQ, E. NORDLINGER, M.S. Luco, J.E. 80/09/04 71pp

- 8009090652 Testimony in response to ASLAB 800807 order, ALAB-604 TRIFUNAC, M. Southern California. Univ. of MORDLINGER, M.B. Office of the General Counsel. 80/09/05 162pp
- --8009090656 "Preliminary Empirical Models for Scaling Absolute Acceleration Spectra" TRIFUNAC, M D. ANDERSON. J O Southern California, Univ 68 77-03 77/08/31 143pp
- ~~8009090664 "Dependence of Pauedo Relative Velocity Spectra of Strong Motion Acceleration on Depth of Sedimentary Deposits," TRIFUNAC.M D., LEE,V W. Southern California, Univ. of CE~79~02 77/02/28 93pp
- --8009090472 "Dependence of Fourier Amplitude Spectra of Strong Motion Acceleration on Depth of Sedimentary Deposits " Supporting documentation encl TRIFUNAC.M D. LEE.V W. Southern California, Univ. of CE-78-14 78/12/31 130pp
- 8009160360 forwards JF Devine & RF Yerkes combined tastimony w/latter prof qualifications.per ASLB 800819 memorandum & onder Explains svc process re repts mentioned in testimony KETCHEN:E O Hearing Branch 4 80/09/12. 2pp
- ~-8009160363 Combined testamony in response to ASLB 800819 memorandum & order on Question 9 re geology > seismology repta New data & conclusions re LNG repta have no impact on USOS position RF Yerkes prof qualifications encl BEVINE.J F. YERKES.R F. Interior, Dept of, Geological Survey 80/09/12 6pp
- U Congressional/Executive Correspondence
- BOOP110514 Responds to BOO530 ltr re facility licensing status Major const Completion delays result of seismic re-evaluation & of TMI-2 Lessons Learned Task Force recommendations Facility will not be authorized to load fuel until approx 1981 DIRCKS.W J Office of the Executive Director for Operations. 80/08/21 2pp
- ---8009110920 Urges prompt completion of necessary requirements for granting facility license Delays result in Increase in constituent util bills Requests licensing status BHUMNAY,N D House of Rep 80/05/30, ip
- 8009220255 Provides status of NRC efforts re final licensing of facility Further actions will be required by ASLAB, ABLB & Commission
 DIRCKS U J Office of the Executive Director for Operations 80/09/17 2pp
- DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

 E NRC Safety Evaluation Report (SER), supply & correspondence
- BOO9020053 Forwards draft comments on SER Items 3 2 3(1)-(4),3 2 9, 3 2 13-15 t 3 2 4 from fire protection review Final Item 3 1 B(2) will be sent shortly HALLRE Brookhaven National Laboratory BO/08/21 5pp
- F Security, medical, emergency & fire protection plans
- 8009250274 Requests permission to record conversations on dedicated telephone connection installed between facilities & NRC Bethesda, MD headquarters GOUNEY/H J Philadelphia Electric Co 80/04/18 ip
- 8009090364 Forwards amended fire protection review. Item 3 1 1 re Area 6 cable spreading room fire detection sys
 HALL:R E Argonne National Laboratory 80/07/15 2pp
- 8009040079 Forwards Suppl 1 to SER re fire protection program Evaluation approves cartain proposed mods & resolves cartain issues identified in NRC 790523 evaluation REID:R W Operating Reactors Branch 4 80/08/14 2pp
- 8009090362 Forwards comments on fire protection review Items 3 2 3(1), (2), (3), (4), 3 2 9, 3 2 13, 3 2 14, 3 2 15 6 3 2 4 re fire detection sys & ventilation ducts F;nel Item 3 1 8(2) comments will be sent shortly HALL.RE Broothaven National Laboratory 80/08/21 6pp

- 8009230191 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed far govt use during emergency GRIER.8 H Region i. Philadelphia. Office of the Director BO/08/22 3pp
- 8009090424 Forwards info on Item 3 2 8(i) & (2) re fire barrier penetration reals for fire protection review HALL:RE Drockhaven National Laboratory 80/08/26 2pp
- 8069150478 Forwards revised plant security personnel training & qualification plan Plan withheld (ref locfr2 790)
 BRADLEVE J Philadelphia Electric Co 80/09/i1 3pp
- 8009300230 Forwards Suppl 2 to safety evaluation re fire protection program in which mod schedule is in accordance w/Amends 53 & 53 to DPR-44 t DPR-56 respectively REID.R W Operating Reactors Branch 4 80/07/13 2pp
- --8009300235 Suppl 2 to safety evaluation supporting fire protection program
 4 Operating Reactors Branch 4 80/09/15 4pp

Adjudicatory correspondence

- 80091903A2 Forwards order requiring info supporting environ qualification of safety-rotated electrical equipment Requests submittal of info by 801101 REID.R W Operating Reactors Branch 4 80/08/29 2pp
- --8009190369 Order for mod of Licenses DPR-44 & DPR-56 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101
 EISENHUT.D Q Division of Licensing 80/08/29 App
- P Operating license stage documents & correspondence
- BCO9110354 Suppis NRC BO0707 request for proposed Tech Specs changes re scram discharge voi vent & drain valves, & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EIBEMHUT,D O Division of Licensing BO/07/22 22pp
- BOOPO2D297 Submits interim criteria for shift staffing to all GL & CP licensees & applicants, per NRC 800507 itr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 70 days EISENRUT, D O. Division of Licensing 80/07/31 7pp
- BOOPOBCOSO Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schodule for meeting criteria of NUREG-0696 enci W/o NUREO EISENHUT.D O Division of Licensing 80/08/01 i19pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D Q Division of Licensing 80/08/07 60pp
- E009020154 Approves Class III fee refund for 800730 license amend re 800729 application for max permissible water temp in containment suppression pool MILLER.W D License Fee Management Branch 80/08/13 Ip
- 5009030352 Advises that high range noble gas monitors described in util 800102 & 0604 ltrs satisfy Lessons Learned Short-Term Item 21 8 b t TMI Action Pien Item III D 2 1 HEID-R U Operating Reactors Branch 4 80/08/14 2pp
- BOO919093 Forwards "Mark I Containment Long-Term Program SER Resolution of Generic Technical Activity A-7," NUREO-0461. W/g encl REID,R W Operating Reactors Branch 4 80/08/20 2pp
- 8009130033 Forwards request for add1 info on degraded grid voltage re NRC review of application to amend Tech Specs to provide second level of undervoltage protection w/time delay for safety-related loads REID.R N Operating Reactors Branch 4 80/08/21 3pp
- 8009220384 Requests add1 fees re 800808 application proposing seismic sunitoring Tech Specs Application requires Classes III & I fees pather than submitted Classes II & I fees D1008.8 M. License Fee Management Branch 80/08/26 ip

- 8009250430 Informs of acceptability of response to NRC 791109 ltr reportions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of tupture
 REID.R W Operating Reactors Branch 4 80/09/09 2pp
- 6009180304 Forwards application for amend of Licenses DPR-44 & DPR-56 changing Fech Specs in response to NRC 800702 ltr re THI Lessons Learned Category A requirements Class III fee encl BRADLEY, E J Philadelphia Electric Co 80/09/15 ip
- --8009180316 Application for amend of Licenses DPR-44 & 36 changing Tech Specs 3 2 F.4 2 F.6 2-2.6 3-6 3.6 14 & 6 15 in response to TMI Lessons Learned Task Force Category A requirements Certificate of Svc enci BAUER.E 0 , BRADLEY,E J Philadelphia Electric Co BO/09/15 Bpo
- --8009180335 Proposed Tech Specs 3 2 F.4 2 F.6 2-2.6 3-6 5.6 14 % 6 15 re water level instrumentation & safety relief valve position indication Revision made in response to TMI Lessons Learned Task Force Category A requirements # Philadelphia Electric Co 80/09/15 7pp
- 8009300367 Forwards comments on NUREG-0696, "Functional Criteria for Emergency Response Facilities " Delay of implementation of data transmission requirements recommended until specific transmission requirements issued BOYER, V S Philadelphia Electric Co 80/09/23 App
- Q Inspection reports. 15 Bulistins & correspondence
- 8009090105 Forwards iE Bujietin 80-07, Suppl i, "BNR Jet Pump Assembly Failure " Response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/05/i3 ip
- 8009160225 Forwards 1E Insp Repts 50-277/80-22 % 50-278/80-16, consisting of 600619 meeting in Philadelphia, PA ORIER, 8 H Region 1, Philadelphia, Office of the Director 80/07/21 1p
- --8009i60229 1£ Insp Repts 50-277/80-22 % 50-278/80-16, consisting of 8006i9 meeting Major areas addressed plant operations, radiation protection, refueling % raduaste operations, security & safeguards, surveillance % preoperational testing COWOILL, C J. MCCABE, E C Region i, Philadelphia, Office of the Director SRUNNER, E J Region t, Philadelphia, Reactor Operations Nuclear Support Branch 80/07/17 7pp
- 8009150180 Forwards IE Insp Repts 50-277/80-21 & 50-278/80-15 on 800630-0703 No noncompliance noted BRUNNER, E J Region I, Philadelphia, Reactor Operations Nuclear Support Branch 80/07/24 2pp
- ---B009150184 IE Insp Repts 90-277/80-21 & 50-278/80-15 on 800430-0703
 No noncompliance noted Major areas inspected containment
 integrated leak rate procedure, containment leak rate test
 activities & surveiliance of pipe supports & restraints
 REKLTO,W A. WIGGINS,J T. CAPHTON,D L. Region i, Philadelphia,
 Reactor Operations Nuclear Support Branch 80/07/22 lipp
- B007100857 Forwards IE Insp Rept 50-277/80-20 on B00423-25 No noncompliance noted BRUNNER, E.J. Region I. Philadelphia, Reactor Operations Nuclear Support Branch B0/07/25 2pp
- --B007100861 IE Insp Rept 50-277/80-20 on 800623-25 No noncompliance noted Major areas inspected fuel handling activities including removal of fuel bundles from spant fuel pool & installation into reactor core BETTENHAUSENL . PETRONE.C D Region i, Philadelphia, Office of the Director CAPHTON.D L Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/07/24 4pp
- B009220376 Responds to IE Bulletin 80-16 re potential misapplication of pressure transmitters Rosemount 1191 & 1152 are utilized in facility Worst case analyses revealed that anomalous transmitter output would not violate design DALTROFF, S.L. Philadelphia Electric Co 80/07/30 5pp
- GOO9080333 Responds to IE Bulietin 79-14 Need identified for mod to, or addition of 24 supports to correct overstressed conditions in piping ar supports or overloading of concrete expansion bolts Nine of 24 items exceeded operability critaria DALTROFF, B L Philadelphia Electric Co 80/08/01 2pp
- 8009150502 Responds to IE Bulletin 79-03A. "Longitudinal Wald Defects in ASKE SA-312 Type 304 Stainless Steel Pipe " Three piping component spools in reactor core isolation cooling pump sys do not exceed 85% of code allowable stresses DALTROFF, 8 t. Philadelphia Electric Co 80/08/01 2pp

- 8009120165 Responds to IE Bulletin 80-17 & Supp i re failure of control rods to fully insert during scram Mods added to provide positive venting capability for vent valves Design changes to scram sys may be warranted GALLAGHER.J W Philadelphia Electric Co 80/09/07 7pp
- 8009/00121 Provides addl info re ltem 6 c of util 800717 response to IE Bulletin 80-17. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BMR " Operation of two standby liquid control sys pumps is unreviewed safety question DALTROFF, S L Philadelphia Electric Co 80/08/08 3pp
- 8009160619 Ack receipt of 800806 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-277/80~13 & 50-278/80-33 Util ltr to be withheld (ref 10CFR2 790)
 MARTIN.N O Region I. Philadelphia, Safeguards Branch 80/08/13
- --8009160621 Forwards IE Insp Repts 50-277/80-15 & 50-278/80-13 on 800519-23 & 29 & notice of violation.Apps A & B App A withheld tref lOCFR2 790) GRIER, B H Region J. Philadelphia. Office of the Director 80/07/14 2pp
- --8009160623 Notice of violation App B. From insp on 800519-23 & 29
 * Region 1. Philadelphia. Office of the Director 80/06/27 1p
- --8009160625 IE Insp Repts 50-277/80-15 & 50-278/80-13 on 800519-23 & 29 Noncompliance noted lack of lighting access control physical barriers & response Details withheld (ref 100FR2 790) DEVLINJ Region 1, Philadelphia, Safsguards Branch 6M17N,0 C Region 1, Philadelphia, Office of the Director 80/06/27. Ip
- 8007030076 Forwards Revision I to 1E Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER.B H Region I, Philadelphia. Diffice of the Director 80/03/15 1p
- 8009100090 Responds to [E Bulletin BO-17, Suppl 1, "Failure of 76 of 185 Control Rods to Fully Insert During Boram at BHR " Program for monitoring scram discharge vol established until instrumentation mod is completed DALTROFF, S.L. Philadelphia Electric Co. 80/08/19 Spp
- 8009t10251 Updates environ qualification rept for Class IE electrical equipment, in response to IE Bulletin 79-01B forwards revised sys component evaluation work sheets, revised refs & revised environ equivalent room tabulation

 DALTROFF, 8 L Philadelphia Electric Co 80/08/19 136pp
- 8009120103 Forwards Suppl 3 to IE Bullatin 80-17, "Failure of Control Rods to Invert During Scram at BHR " Written response required GRIER.B H Region 1, Philadelphia. Office of the Director 80/08/22 1p
- 8009180030 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/08/22 1p
- 8009120237 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Voit Type K-600S & K-DON 600S Circuit Breakers " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/08/27 lp
- 8009230498 Forwards Revision 1 to IE Bulletin 79-24, "Daron Loss From BMR Control Blades " Written response required CRIER.9 H Region 1, Philadelphia, Office of the Director 80/09/29 1p
- 8009240049 Forwards IE Circular 80-21. "Regulation of Refueling Crows " No written response required ORIER. H Region 1. Philadelphia. Office of the Director 80/09/10 1p
- 8009240325 Forwards IE Info Notice BO-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matie " No written response required ORIER, BH Region 1, Philadelphia, Office of the Director 80/09/12 ip

- R Periodic operating reports & related correspondence
- BOO9020245 Forwards "Peach Bottom Atomic Power Station Thermal Mapping Rept 80-3 for 800715,23 \$ 31 " WILLSEY, W B Philadelphia Electric Co 80/08/26 1p
- --8009020246 "Peach Bottom Atomic Power Station Thermal Mapping Rept 80-3 for 800715,23 & 31 " * Philadelphia Electric Co 80/08/26 &pp
- 8009080340 Forwards "Bemiannual Effluent Releases Rept 9. Jan-June 1980 "ALDEN,W M Philadelphia Electric Co 80/08/29 ip
- --8009080342 "Semiannual Effluent Releases Rept 9. Jan-June 1980 " ULLRICH W t Philadelphia Electric Co 80/08/29 7pp
- 8009160294 Forwards monthly operating repts for Aug 1980 COONEY, M J Philadelphia Electric Co 80/09/10 5pp
- --B009160276 Monthly operating repts for Aug 1780 ALDEN,W M Philadelphia Electric Ca 80/07/10 5pp
- 8009160427 Forwards "Thermal Mapping Rept 80-4 for 800807" & "Thermal Monitoring Rept 80-5 for 800816" WILLSEY.N B Philadelphia Electric Co 80/09/10 ip

- 8009180439 Forwards revised pages for monthly operating rept for Aug 1980 GOUNEY,M J. Philadelphia Electric Co. 80/09/12 1p
- --8009180442 Revised pages to monthly operating rept for Aug 1980 re
 "Cause & Corrective Action"
 " Philadelphia Electric Co. 80/09/12 2pp
- 8009230569 Forwards "Thermal Mapping Rept 80-6 for 800821 & 25 for Thermal Monitoring Requirements " WILLSEY,W B Philadelphia Electric Co 80/09/18 1p
- ---8009230576 "Thermal Mapping Rept 80-6 for 800821 for Thermal Monitoring Requirements "

 * Philadelphia Electric Co 80/09/18 5pp
- S Reportable occurrences, LERs & related correspondence
- 8007020501 PNO-I-80-122 on B00815, unplanned release of gaseous radioactivity from Unit 3 reactor bids vent accurred Release rate was 33% of Tech Spec limit Caused by malfunction of Unit 2 offgas sys during mods GREENKAN.E., BRUNNER.E.J. Region 1, Philadelphia, Office of the Director 80/08/15 2pp
- BOOPOGOAGS LER BO-013/OGL-O on BOOBOL, during refueling outage, surveillance leak tast results exceeded Tech Spec limits due to leakage failure of eight MBIVs Caused by improper seat contact due to damage to seats, plugs & guides COONEY.M J, WERGARD, A J Philadelphia Electric Co BO/08/29 1p
- DDCKET 50-276 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

 E NRC Safety Evaluation Report (SER), supple & correspondence
- 8009020053 Forwards draft comments on SER Items 3 2 3(1)-(4),3 2 9, 3 2 13-19 & 3 2 4 from fire protection review Final Item 3 1 8(2) will be sent shortly HALL.RE Broothaven National Laboratory 80/08/21 5pp
- F Security, medical, emergency & fire protection plans
- 8007250274 Requests permission to record conversations on dedicated telephone connection installed between facilities & NRC Bethesda, MD headquarters CDUNEY.N J Philadelphia Electric Co 80/04/18 1p
- 8009090364 Forwards amended fire protection review. Item 3 1 1 re Area 6 cable spreading room fire detection sys HALL-RE Argonne National Laboratory 80/07/13 2pp

- 8009040079 Forwards Suppl 1 to SER re fire protection program Evaluation approves certain proposed mods & resoives certain issues identified in NRC 790523 evaluation REID.R W Operating Reactors Branch 4 80/08/14 2pp
- --8009040083 Suppl 1 to SER re facility fire protection program
 4 Operating Reactors Branch 4 80/08/14 App
- 8009090362 Forwards comments on fire protection review Items 3 2 3(1), (2), (3), (4), 3 2 9, 3 2 13.3 2 14.3 2 15 & 3 2 4 re fire distaction sys & ventilation ducts Final Item 3 i B(2) comments will be sent shortly HALL.R E Brookhaven National Laboratory 80/08/21 6pp
- 600923019i Requests that all personnal be reminded of purpose of margency notification sys & health physics network Sys installed for govt use during emergency GRIERS H Region I. Philadeiphia. Office of the Director 80/08/22
- 8007090424 Forwards info on Itom 3 2 8(1) & (2) re fire barrier genetration seals for fire protection review HALL-R E Brookhaven National Laboratory 80/08/24 2pp
- B009180478 Forwards revised plant security personnel training & qualification plan Plan withheld (ref 10CFR2 790)
 BRADLEY.E J Philadelphia Electric Co B0/09/i1 3pp
- B009300230 Forwards Suppl 2 to safety evaluation re fire protection program in which mod schedule is in accordance w/Amends 93 & 93 to DPR-44 & DPR-56, respectively REID.R 4 Operating Reactors Branch 4 80/09/15 2pp
- --8909390235 Suppl 2 to safety evaluation supporting fire protection program
 4 Operating Reactors Branch 4 80/09/15 4op
- O Adjudicatory correspondence
- BC09190362 Forwards order requiring info supporting environ qualification of safety-related electrical equipment. Requests submittal of info by 801101 REID, R W Operating Reactors Branch 4 80/08/29 Zpp
- --B009190369 Order for mod of Licenses DPR-44 & DPR-96 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment info should be submitted by 801101
 EISENHUT.D O Division of Licensing 80/08/29 App
- P. Operating license stage documents & correspondence
- BO09110354 Suppls NRC 800707 request for proposed Tech Space changes re scram discharge vol vent & drain valves, & reactor protection sys & control rod block limit switch surveillance requirements Class III license fes to be submitted w/change EISENHUT,D Q Division of Licensing 80/07/22 22pp
- 8009020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for amergency & overtime work Development & Implementation to be reviewed within 90 days EISENHUT.D C Division of Licensing 80/07/31 7pp
- 8007080080 Forwards draft NUREO-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl N/o NUREO EISENHUT,D O Division of Licensing 80/08/01 119pp
- BD09230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded. Requested submittal should include proposed class of amend ETSENHUT, D Q Division'of Licensing B0/08/Q7 60pp
- 8009020154 Approves Class III fee refund for 800730 license amend re 800728 application for max permissible water temp in containment suppression pool MILLER,W D License Fee Management Branch 80/08/13 ip
- 8009030352 Advises that high range noble gas monitors described in util 800102 & 0604 ltrs satisfy Lessons Learned Short-Term Item 2 1.8 b & TMI Action Plan Item III D.2 1 REID,R W. Operating Reactors Branch 4 80/08/14 2pp

- 8009050210 Forwards Amend 71 to License DPR-56, safety evaluation & notice of issuance & availability
 REID.R W Operating Reactors Branch 4 80/08/14 2pp
- --8009050217 Amend 71 to License DPR-56 revising Tech Spec 3 11 D 2 to parmit inoperability of snubber on RHR sys lines for 800717-26 for repairs REID.R W Operating Reactors Branch 4 80/08/14 4pp
- --8009050219 Safety evaluation supporting Amend 71 to License DPR-56 * Office of Nuclear Reactor Regulation. Director 80/09/14 2pp
- --8009050221 Notice of issuance & availability of Amend 71 to License DPR-56 REID,R W | Departing Reactors Branch 4 80/08/14 | 2pp
- 8009190953 Forwards "Mark I Containment Long-Term Program SER Resolution of Generic Technical Activity A-7," NUREO-0661 H/o encl REID.R W Operating Reactors Branch 4 80/08/20 2pp
- 8009150033 Forwards roquest for add1 info on degraded grid voltage re NRC review of application to amend Tech Specs to provide sacond level of undervoltage protection w/time delay for safety-related ioads REID,R W Operating Reactors Branch 4 80/08/21 3pp
- B0092203B4 Requests additees re B00B0B application proposing seismic monitoring Tech Specs Application requires Classes III & I fees rather than submitted Classes II & I fees D100S,R M License Fee Management Branch B0/08/26 [p
- B0071B0304 Forwards application for amend of Licenses DPR-44 & DPR-56 changing Tech Specs In response to INC 800702 itr re THI Lessons Learned Category A requirements Class III fee encl BRADLEY, E J Philadelphia Electric Co 80/09/15 1p
- --B0091B0316 Application for amend of Licenses DPR-44 & 96 changing Tech Specs 3 2 F.4 2 F.6 2-2.6 3-6 5.6 14 & 6 19 in response to TMI Lessons Learned Task Force Category A requirements Certsficate of Svc encl BAUER E 0 , BRADLEY E J Philadelphia Electric Co 80/07/15 Boo
- --8009180335 Proposed Tech Specs 3 2 F.4 2 F.6 2-2.6 3-6 5.6 14 & 6 15 re wate. level instrumentation & safety relief valve position indication Revision made in response to TM1 Lessons Learned Task Force Category A requirements

 * Philadelphia Electric Co 80/09/15 7pp
- B009300367 Forwards comments on NUREC-0676, "Functional Criteria for Emergency Response Facilities " Delay of implementation of data transmission requirements recommended until specific transmission requirements issued BDYER.V S Philadelphia Electric Co 80/09/23 6pp
- O Inspection reports, IE Bulletins & correspondence
- 8009300131 "Response to IE Bulletin 79-018 "
 * Philadelphia Electric Co 80/04/15 350pp
- 8007070105 Forwards 1E Bulletin 80-07, Suppl 1, "BNR Jet Pump Assembly Fallure" Response required CRIER, BH Region 1, Philadelphia, Office of the Director 80/05/13 1p
- 8009160225 Forwards IE Insp Repts 50-277/80-22 & 90-278/80-16, consisting of 800619 meeting in Philadelphia, PA GRIER, B H Region 1, Philadelphia, Office of the Director 80/07/21 1p
- --8009160229 IE Insp Repts 50-277/80-22 % 50-278/80-16, consisting of B00619 meeting Major areas addrossed plant operations, radiation protection, refueling & raduatse operations, security & safeguards, surveillance & preoperational testing COMOILL, C J , MCCABE, E C Region I, Philadelphia, Office of the Director DRUNNER, E J Region I, Philadelphia, Reactor Operations Nuclear Support Branch 80/07/17 7pp
- 8009150180 Forwards IE Insp Repts 50-277/80-21 & 50-278/80-15 on 800630-0703 No noncompliance noted BRUNNER,E J Region i. Philadelphia, Reactor Operations Nuclear Support Branch 80/07/24 2pp

- --8009150184 IE Insp Repts S0-277/80-21 & 50-278/80-15 on 800630-0703
 No noncompliance noted Major areas inspected containment
 integrated leak rate procedure containment leak rate test
 activities & surveillance of pipe supports & restraints
 REKITO.W A . WIGGING.J T . CAPHTON.D L Region i. Philadelphia,
 Reactor Operations Nuclear Support Branch 80/07/22 iipp
- 8007220376 Responds to IE Bulletin 80-16 re potential misapplication of pressure transmitters Rosemount 1151 & 1152 are utilized in Pacility Worst case analyses revealed that anomalous transmitter output would not violate design DALYROFF, B L Philadelphia Electric Co 80/07/30 5pp
- 8009080533 Responds to IE Buliotin 79-14 Need identified for mod to.or addition of 24 supports to correct overstressed conditions in piping or supports or overloading of concrete expansion bolts Nine of 24 items exceeded operability criteria DALTROFF.S L Philadelphia Electric Co 80/08/01 2pp
- 8009150502 Responds to IE Bulletin 79-03A. "Longitudinal Neid Defects in ASME 9A-312 Type 304 Stainless Steel Pipe " Three piping component spools in reactor core isolation cooling pump sys do not exceed 65% of code allowable stresses DALTROFF.S L Philadelphia Electric Co 80/08/01 2pp
- 8009120165 Responds to IE Bulletsn 80-17 & Supp i re failure of control rods to fully insert during scram Mods added to provide positive venting capability for vent valves Design changes to scram sys may be warranted OALLAGMER.J W Philadelphia Electric Co 80/08/07 7pp
- 8009100121 Provides add1 info re item 6 c of util 800717 response to 1E Bulletin 60-17. 'Failure of 76 of 185 Control Rods to Fully insert During Scram at BUR " Operation of two standby liquid control sys pumps as unreviewed safety question DALTROFF, St. Philadelphia Electric Co. 80/08/08 3pp
- 8009160619 Act receipt of 800806 ltr informing NRC of steps taken to correct violations noted in iE Insp Repts 50-277/80-15 & 50-278/80-13 Util ltr to be withheld (ref 10CFR2.790).
 MARTIN.W O Region 1. Philadelphia, Safeguards Branch 80/08/13
- --8009160621 Forwards IE Insp Repts 50-277/80-15 & 50-278/80-13 on 800517-23 & 29 & notice of violation Apps A & B App A withheld (ref 10CFR2 790) ORIERS B H Region I. Philadelphia. Office of the Director 80/07/14 2pp
- --8009160623 Notice of violation.App B.from insp on 800519-23 & 29 ** Region i. Philadelphia. Office of the Director. 80/06/27 ip
- --8007160625 IE Insp Repts 50-277/80-15 & 50-278/80-13 on 800519-23 & 29 Noncompliance noted lack of lighting access control, physical barriers & response Details withheld (ref 10CFR2 790) DEVLIN,J Region i, Philadelphia, Safeguards Branch SMITH, Q C Region I, Philadelphia, Office of the Director 80/06/27 tp.
- 8009090015 Responds to [E Bullatin BO-17, "Failure of 76 of 185 Control Rods to Fully Insert During Stram at BWR." Stram tests for facility successfully completed on 800808 & 09 DALTROFF, B L Philadelphia Electric Co 80708/14 App
- 8009030076 Forwards Ravision 1 to IE Bulietin 80-19. "Failures of Mercury-Nettad Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required ORIER.B H Region I, Philadelphia, Office of the Director 80/08/15 ip
- 8009100090 Responds to [E Bulletin 80-17, Suppl 1, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BUR" Program for monitoring scram discharge vol established until instrumentation mod is completed DALTROFF, B L Philadelphia Electric Co 80/08/19 Opp
- 8009110251 Updates environ qualification rept for Class IE electrical equipment, in response to IE Bulletin 79-018 Forwards revised sys component evaluation work sheets, revised refs & revised environ equivalent room tabulation
 DALTROFF. S L Philadelphia Electric Co 80/08/19 136pp
- 8009120103 Forwards Suppl 3 to IE Butletin 80-17, "Failure of Control Rods to Insert During Scram at BMR" Written response required GRIER, 8 H Region I, Philadelphia, Office of the Director 80/09/22 ip

- 8009180030 Forwards IE Circular 80-18, "100FR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GRIER, B H. Region 1, Philadelphia, Office of the Director 80/08/22 1p
- 8009120237 Forwards IE info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Voit Type K-600S & K-DON 600S Circuit Breakers " No written response required GRIEA, B H Region 1, Philadelphia, Office of the Director E0/08/27 1p
- 8009230498 Forwards Revision 1 to 1E Bulletin 79-26, "Boron Loss From BWR Control Blades "Written response required GRIER.B H Region 1. Philadelphia, Office of the Director 80/08/27 1p
- 9009240043 Forwards IE Circular 90-21, "Regulation of Refueling Crews"
 No written response required
 GRIER, B H Region 1, Philadelphia, Office of the Director
 BO/09/10 ip
- 8009240325 Forwards IE Info Notice 80-32. "Ciarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required ORIER.8 H Region 1. Philadelphia, Office of the Director 80/09/12 ip
- R Periodic operating reports & related correspondence
- 8009020245 Forwards "Peach Bottom Atomic Power Station Thermal Mapping Rept 80-3 for 800715,23 & 31 " WILLSEY,N B Philadelphia Electric Co 80/08/26 ip
- --8009020244 "Peach Hottom Atomic Power Station Thermal Mapping Rapt 80-3 for 800715.23 % 31 " * Philadelphia Electric Co 80/08/24 App
- 8009080340 Forwards "Semiannual Effluent Releases Rept 9.Jan-June 1980 " ALDEN N H Philadelphia Electric Co 80/08/29 Ip
- --8007080342 "Semiannuai Effluent Releases Rept 9, Jan-June 1980 " ULLRICH,W T Philadelphia Electric Co 80/08/29 7pp
- BO09160294 Forwards monthly operating repts for Aug 1980 COONEY, M J Philadelphia Electric Co 80/09/10 5pp
- --8009160296 Monthly operating repts for Aug 1980 ALDEN,W M Philadelphia Electric Co. 80/09/10 Spp
- B009160427 Forwards "Thermal Mapping Rept 60-4 for 800807" & "Thermal Monitoring Rept 80-5 for 800816" WILLSTIN Rept 80-5 for 800816 WILLSTIN Rept 80-6 for 8000816 WILLSTIN Rept 80-70 ip
- --8009i6043i "Thermal Mapping Rept 80-4 for 800807 " * Philedelphia Electric Co 80/09/10 App
- --8009150435 "Thermal Mapping Rept 80-5 for 800816 "
 * Philadelphia Electric Co 80/09/10 4pp
- BOD9180439 Forwards revised pages for monthly operating rept for Aug 1780 CODNEY, M J Philadelphia Electric Co 80/09/12 ip
- --8007180442 Revised pages to monthly operating rept for Aug 1780 re "Cause & Corrective Action" * Philadelphia Electric Co 80/07/12 2pp
- 8009230569 Forwards "Thermal Mapping Rept 80-6 for 800821 & 25 for Thermal Monitoring Requirements" WILLEST'4B Philadelphia Electric Co 80/09/18 ip
- --8009230576 "Thermal Mapping Rept 80-6 for 800821 for Thermal Monitoring Requirements." * Philadelphia Electric Co 80/09/18, Spp
- 8 Reportable occurrences, LERs & related correspondence
- BOO9020501 PNO-I-80-122 on BOOB15, unplanned release of gaseous radioactivity from Unit 3 reactor bldg vent occurred Release rate was 33% of Tech Spec limit Caused by malfunction of Unit 2 offgas sys during mods OREENMAN.E. BRUNNER.E. J. Region i. Philadelphia, Office of the Director BO/OS/15 2pp.

- 8009120330 LER 80-017/03L-0 on 800802, during surveillance test on PCIS normally open valves, drywell 2-inch valve A0-3509 failed to close Caused by tight packing on valve Packing & proper operation verified COONEY.N J Philadelphia Electric Co 80/09/01 ip
- 8007120367 LER 80-018/03L-0 on 800802, during surveillance test on PCIS NOTICEST LET CO-018/02-0 on GOOGUS during surveillance mormally open valves w/unit at full power reactor water cleanup sys return isolation valve MO-3-12-68 failed to close using control switch Cause not determined COCNEY.H J Philadelphia Electric Co 80/09/01 ip
- 8009\$60439 LER 80-019/03L-0 on 800806, while performing surveillance test on RHR sys w/unit at power.MD-3-10-25A LPCI injection valve failed to open Caysod by multiple full penetration cracks on Grive sleeve of type SMB-4 Limitorque operator CDONEY.M J Philadeiphia Electric Co 80/09/05 1p
- 8009160441 LER 80-021/03L-0 on 800818.during PCIS logic sys functional testing w/glant shutdown.primary containment ventilation valve A0-3506 failed to close Caused by ASCO model 856756 solenoid valve stuck in energized position Valve cleaned COCNEY.M J Philadelphia Electric Co 80/09/09 ip
- 6009260621 LER 80-021/03X-i on 800818, during PCIS logic sys functional testing w/plant shutdown, primary containment valve A0-3506 failed to close Caused by A8CO Model 936796 solenoid valve stuck in energized position Solenoid valve cleaned COUNEY.M J Philadelphia Electric Co 80/09/09 ip
- 6009190482 LER 80-020/03L-0 on 800815, while performing leak test, containment ventilation valve A0-35218 was found leaking excessively Caused by valve 7-ring inflating before closure Air valves adjusted & valve tested CDONEY.H J Philadelphia Electric Co 80/09/12 lp
- BOD9260616 LER 80-022/03L-0 on 800829, during core spray logic sys test. 38 pump started 0 3-s below Tech Spec time range Caused by agastat time delay relay setpoint drift Relay adjusted & testing resumed satisfactorily CDONEY,M J Philadelphia Electric Co 80/09/19 tp
- DOCKET 50-280 SURRY POWER STATION, UNIT 1
- F. Security, medical, emergency & fire protection plans
- 8007030184 Forwards revised emergancy plan Plan is based on existing meteorological capabilities 8 reflects criteria of NUREG-0.554 York County, VA emergency plan encl BAUM, E A Virginia Electric & Power Co 80/06/30 2pp
- --8007030202 Draft York County.VA radiological emergency response plan peacetime Plan withheld per Privacy Act

 Virginia. State of 80/06/30 Sipp
- --BOO7D30207 Revised emergency plan
 # Virginia Electric & Power Co 80/06/16 500pp
- 8009190739 Requests participation in NRC study of people-related problems in nuclear safeguards Request includes NRC visit to interview security personnel Confidentiality of info will be maintained during all phases of study UARGA.S A Operating Reactors Branch i 80/08/14 2pp
- SOOP230273 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Bys installed for govt use during emergency OfREILLY.JP Region 2, Atlanta, Office of the Director 80/08/22
- BOO9090274 Notifies that execution of util emergency drill has been deferred until BO1231 NRC has not approved of revised radiological response plan & corporate emergency drill plan Extension will enable proper personnel training period BAUM.E A Virginia Electric & Power Co BO/09/04 2pp
- SOO9260043 Forwards facility emergency planning info W/o encl SOUDER, J L Division of Rules and Records 80/09/12 ip
- 8007230343 Forwards revised nuclear security personnel training & qualifications program Program withheld (ref 10CFR2 770)

 BYLVIA:B.R Virginia Electric & Power Co 80/09/19 1p

- @ Adjudicatory correspondence
- B007230121 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by B01101 VARGA.S A Operating Reactors Branch 1 80/08/29 2pp
- --8009230132 Order for mod of License DPR-32 & DPR-37 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101
 EISENHUT, D O Division of Licensing 80/08/29 6pp
- 80092300i3 Motion for stay of effectiveness of Amend 47 to OL, authorizing replacement of steam generators, pending Appeal before US Court of Appeals for DC Circuit in which FES is challenged M/Civii pleadings & excerpts of NUREO-0523 DOUGHERTY, J B Potomac Alliance DOUGHERTY, J B Citizens Forum DOUGHERTY, J B Dougherty, J B 80/09/18 ilipp
- H General correspondence
- 8007070436 Responds to encl Botetourt County Chamber of Commerce 800626 request to FERC for into re when facilities will be operational Lists status of piant operating schedules DENION, HR Office of Nuclear Reactor Regulation, Director Зрр 80/09/05
- J lasurance & Indomnity information
- 8009090384 Forwards Endorsement i to NELIA Binder EB-70 ANDREWS.C L Marsh & McLennan, Inc., M & M Nuclear Consultants, inc Div 80/09/03 2pp
- P Operating license stage documents & correspondence
- B009020297 Submits interim criteria for shift staffing to all GL & CP licensees & applicants.per NRC 800507 ltr Discussos administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D O Division of Licensing 80/07/31 7pp
- 8009100673 Forwards FES for facility & notice of availability W/o FES VARQA.S A Operating Reactors Branch 1 80/07/31 2pp
- --B009100675 Notice of availability of FES for facility VARQA, S A Operating Reactors Branch 1 80/07/31 2pp
- BOOPOBOOBO Forwards draft NUREO-0676. "Functional Criteria for Emergency Response Facilaties " Comments requested within 30 days Proposed implementation schedule for moeting criteria of NUREO-0696 encl W/a NUREO EISENHUT, D O Division of Licensing 80/08/01 119pp
- 8009230052 informs that exemption from fee relicensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D O Division of Licensing 80/08/07 60pp
- 8009090785 Approves util 800806 request to return facility to power operation in accordance w/provisions of Amend 59 Forwards safety evaluation re leaks in steam generator C, findings of subsequent insp & corrective actions VARCA, S A Operating Reactors Branch | 80/08/08 2pp
- --BO09090786 Safety evaluation supporting continued operation of facility steam generators # Operating Reactors Branch 1 80/08/08 Jpp
- B009190794 Forwards revised Westinghouse BTS 3 9 8 2,3 9 10 \$ Bases 3/4 9 8 & 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required NOVAK.T M Assistant Director for Operating Reactors 80/08/15
- --8009190817 Revised Weetinghouse STS 3 9.8 2.3 9 10 & Bases 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or Assistant Director for Operating Reactors 80/04/23 21pp
- BOOP020437 Application to amend Tech Specs in Licenses DPR-32 & DPR-37 Proposed changes will transfer independent review & audit responsibilities Amend fee encl FEROUSON, J H Virginia Electric & Power Co BO/08/28 Spp

- --800902044! Proposed changes to Tech Specs 6 1-1 through 4 3-1 for administrative controls of organization, safety & operation review Tech Specs will transfer independent review & audit responsibilities

 Virolinia Electric & Power Co 80/08/28 12pp
- 6009180538 Forwards Amends 60 & 60 to Licenses DPR-32 & DPR-37, respectively Notice of issuance & availability VARGA/S A Operating Reactors Branch 1 80/08/29 3pp
- --8009180545 Amends 60 & 60 to Licenses DPR-32 & DPR-37, respectively, revising Oct 1974 amends to allow possession of byproduct nati
 VARCALS A Operating Reactors Branch 1 80/08/27 4pp
- --8009180552 Notice of issuance & availability of Amends 60 \$ 60 to Licenses DPR-32 \$ DPR-37, respectively NEIOHBORS. J D Operating Reactors Branch 1 80/08/29 2pp
- 8009290461 Forwards Amend 61 & 61 to Licenses BPR-32 & BPR-37, respectively. & notice of issuance & availability VARGA.S A Operating Reactors Branch 1 80/09/05 269
- --8009270464 Amends 61 & 61 to Licenses DPR-32 & DPR-37, respectively, to require implementation of safaguards contingency plan within 30 days of Commission approval VARCA:S A Dperating Reactors Branch 1 80/09/05 4pp
- --8009290468 Notice of issuance & availability of Amends 41 & 61 to Licenses DPR-32 & DPR-37, respectively VARGA.S A Operating Reactors Branch 1 80/09/05 2gp
- 8009180251 Forwards addI info re annual U feed requirements for range of discharge burnups to support proposed Tech Specs Change 85 to Licenses DPR-32 & DPR-37 Feed & SHU requirements shown in anci table considered conservative SYLVIA-B R Virginia Electric & Power Co 80/09/15 2pp
- 8009190525 Bubmits info re maintaining min of 23 ft of water over reactor vossel flange during fuel movement in response to NRC 800815 ltr Changes to Tech Specs to include RHR sys requirements identified in NRC 800615 ltr being reviewed SYLVIA-B R Virginia Electric & Power Co 80/09/16 2pp
- 8009220334 Forwards comments on NUREG-0696 in response to NRC 800801 request Implementation of requirements according to time schedule not considered feasible Requests meeting to discuss preliminary plan re effective emergency response facilities FERGUSCH.J H Virginia Electric & Power Co 80/09/18 14pp
- 8009260278 Submits add1 info re proposed Tech Spec Change Request 85 Util will provide general evaluation of reactor operation to extended fuel burnups possible w/higher fuel enrichment by 610101 SYLVIA, 8 R Virginia Electric & Power Co 80/09/23 1p
- Q Inspection reports: IE Bulletins & correspondence
- 8009100056 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Funns Following Secondary Side Migh Energy Line Rupture " Written response required O'REILLY.J P Region Z. Atlanta, Office of the Director 80/07/24
- 8009180148 Forwards IE Insp Repts 50-280/80-26 & 50-281/80-29 on 800709-10 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/08/05 2pp
- --8009180162 IE Insp Repts 50-280/80-26 & 50-281/80-29 on 800709-10 No noncompliance noted Major areas inspected IE Bulletins 79-02 & 79-14 & licenses actions on previous insp findings COMPTOINE M Region 2. Atlanta, Office of the Director HERDT, A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/08/04. 4pp
- 8007020207 Forwards IE Insp Repts 50-280/80-23 \$ 50-281/80-24 on 800607-0703 & notice of violation LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/08/08 2pp
- --8097020216 Notice of violation from insp on 800609-0703
 * Region 2, Atlanta, Office of the Director BO/08/08 ip

- --8009020220 IE Insp Repts 50-280/80-23 & 50-281/80-26 on 800609-0703 Noncompliance noted failure to follow plant maint & mod procedures BURKE,D J. Region 2, Atlanta, Office of the Director KELLOGO.P J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/08/08 7pp
- 8009020242 Submits response to IE Bullotin 79-03A for North Anné, πο SA-312 or A-312. Type 300 series fusion welded pipe in use at greater than 85% design stress for Surry, eight fittings determined in excess of 85% design stress SYLVIA, B R Virginia Electric & Power Co 80/08/08 2pp
- B009030141 Forwards Revision i to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective 8ys of Decrating Nuclear Power Plants Designed by C-E " Written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/08/15 in
- 8009050422 Ack receipt of 800801 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/80-10 & 50-281/80-11 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22
- ~-8009050431 Forwards IE Insp Repts 50-280/80-10 & 50-281/80-11 on 800505-09,12-16 & 20-23 & notice of violation O'REILLY:J P Region 2, Atlanta, Office of the Director 80/07/03 2pp
- --8009050436 Notice of violation from insp on £00505-09,12-16 & 20-23

 ★ Region 2, Atlanta, Office of the Director 80/07/03 5pp
- --B007050441 IE Insp Repts 50-2B0/80-10 & 50-281/80-11 on 800505-09, 12-16 & 20-23 Noncompliance noted, failure to follow Tech Spec procedures, perform corrective actions, control vendor manuals & perform & document safety evaluation UPRIGHT.C M Region 2, Atlants. Reactor Operations Nuclear Support Branch RUMLMAN,W A BELISLE, G A Region 2, Atlanta, Office of the Director 80/07/03 32pp
- BO09160172 Forwards IE Circular B0-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys." No written response required O'REILLY.JP Region 2. Atlanta. Office of the Director 80/08/22 to
- 8009160473 Ack receipt of 800804 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-280/80-21 & 50-281/80-22 STOHR, J P Region 2. Atlanta. Fuel Facility & Materials Safety Branch 80/08/22 ip
- ---S009160487 Forwards IE Insp Repts 50-280/80-21 & 50-281/80-22 on S00603-06 & notice of violation STOHR.J P Region Z. Atlanta. Fuel Facility & Materials Safety Branch. B0/07/07 2pp
- --8009160490 Notice of violation from insp on 800603-06 STDHR, J.P. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch 80/07/07 1p
- ~-B009160497 IE Insp Repts 50-280/80-21 & 50-281/80-22 on 800603-06 Noncompliance noted failure to have written procedures for preparation of efficiency calibr stds for OE detectors TROUP, Q L. Region 2, Atlanta, Fuel Facility & Materials Safety Branch MONTODKERY, D M. Region 2, Atlanta, Office of the Director 80/07/07 9pp
- 8009240180 Responds to NRC BD0728 request for continuing action re IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Estimated anchor bolt insp & testing schedule enci SPENCER, N C Virginia Electric & Power Co 80/08/26 2pp
- 8009120031 Responds to IE Bulletin 80-19 Surry Units 1 & 2 do not use mercury-wested relays in reactor protection sys No response for North Anna Units 1 & 2 SYLVIA B. R Virginia Electric & Power Co 80/08/27, 2pp
- 8009120314 Forwards IE Info Notice 80-31, "Maloperation of Qould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/27.

DOCKETED ITEMS

- BOO9090528 Forwards response to NRC 800808 ltr re violation noted in 1E Insp Repts 50-280/80-23 & 50-281/80-26 Corrective action cleared trays & installed cable tray covers required by slectrical maint procedures SYLVIA:B R Virginia Electric & Power Co 80/09/05 2pp
- 8009240399 Forwards response to IE Bulletin 80-15 re possible loss of emergency notification sys w/loss of offsite power Design change initiated to change power supply to vital bus Adainistrative Procedure 29 & revised Affidavit encl SYLVIA:B R Virginia Electric & Power Co 80/09/05 3pp
- 8009240493 Ack receipt of 800811 Itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/80-20 & 50-281/80-21 LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Eranch 80/09/08 1p
- --8007240701 Responds to NRC 800715 ltr re violation noted in IE Insp Repts 50-280/80-20 & 50-281/80-21 Corrective actions trash ranged from containment recirculation sump screens & proposed Tech Spec change submitted to NRC SYLVIA.B R Virginia Electric & Power Co 80/08/ii 3pp
- --8009240706 Forwards 1E Insp Repts 50-280/80-20 & 50-281/80-21 on 800508-0606 & notice of violation LEHIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/07/15 2pp
- --8009240709 Notice of violation from insp on 800509-0606 • Region 2, Atlanta, Office of the Director 80/07/15 2pg
- ~-8099240713 IE Insp Repts 50-280/80-20 & 50-281/80-21 on 800505-0606 Noncompliance noted failure to follow operating procedures to maintain recirculating sump screens. & inadequate inplementation of design control measures for mods KELLDGC.P J. BURKE.D J Region 2. Atlanta, Office of the Director 80/07/15 App
- BO09250357 Forwards IE lnsp Repts 50-280/80-33 & 50-281/80-36 on BO0820-22 No noncompliance noted Insp summary only encl fref 10CFR2 790)
 KEINA,W B Region 2, Atlanta, Safeguards Branch B0/09/08 2pp
- --8009250360 IE Insp Repts 50-280/80-33 & 50-281/80-36 on 800820-22
 No noncompliance noted Major areas inspected access control.
 Lighting & power supply Details withheld (ref 100FR2 770)
 HDRG.D E Region 2. Atlanta. Office of the Director
 MCGUIRE.D Region 2. Atlanta. Safeguards Branch 80/09/08 ip
- 8009260517 Forwards 1E Circular 80-21, "Regualtion of Refueling Craws " No written response required D'AEELLY, J.P. Region 2. Atlanta, Office of the Director 80/09/10 5pp
- B009300i16 Forwards response to 1E Dulletin 80-20 Westinghouse Type W-2 control switch applications found Subj switches have been tasted satisfactorily
 SYLVIA:8 R Virginia Electric & Power Co 80/09/15 3pp
- A Periodic operating reports & related correspondence
- 8009190437 Forwards monthly operating repts for Aug 1780 SYLVIA.B R Virginia Electric & Power Co 80/09/15 ip
- --8009190444 Monthly operating repts for Aug 1980 HILSON.J., DVNN.S D. Virginia Electric & Power Co. 80/09/08 48pp
- 8 Reportable occurrences, LERs & related correspondence
- B009030525 Forwards LER 80-040/03L-0 H[LS0N,J.L Virginia Electric & Power Co 80/08/28 ip
- --8009030535 LER 80-040/03L-0 on 800731, in steady state operation, found that primary to secondary leakage through 10 steam generator was 0 33 ppm Caused by primary to secondary leakage through four steam generator tubes

 * Virginia Electric & Power Co 80/08/28 2pp
- SO09020344 Forwards LER 80-058/01T-0 HILSON.J.L Virginia Electric & Power Co 80/08/29 1p
- --8009020350 LER 80-058/01T-0 on 800819, w/unit at 90%, refueling water storage tank vol found different than assumed in 780629 order for mod Caused by failure to specify number of available gallons in order Correct vol calculated RILBOH. J T Virginia Electric & Power Co 80/08/29 2pp

- 8009100252 Forwards LFR 80-042/03L-0 WILSON, J L Virginia Electric & Pawer Co 80/09/05 tp
- --8007100262 LER 80-042/03L-0 on 800805.pump for drawing radiation samples from process vent sys froze & triggered low flow alarm Caused by moisture condensation in pump area Pump pulled & replaced WILSUN, J. Virginia Electric & Power Co 80/08/05 2pp
- 8009150274 Forwards LER 80-046/03L-0 WILSON,J L Virginia Electric & Power Co 80/09/08 1p
- --8009150278 LER 80-046/03L-0 on B00807, during startup operations, containment vacuum sys steam ejector was placed in svc u/o obtaining containment gaseous release form Caused by personnel error WILSON, J. L. Virginia Electric & Power Co. 80/09/08 2pp
- 8009220253 Forwards LERs 80-051/03L-0,80-054/03L-0 & 80-052/03L-0 WILSON,J L Virginia Electric & Pawer Co 80/09/12 ip
- --8009220298 LER 80-051/03L-0 on 800813.discharge tunnel radiation monitor found out of sec during release of liquid waste test tanh A Caused by defective circuit card Roplaced defective card WILSGIBJ L Virginia Electric & Power Co 80/07/12 2pp
- --8009280260 LER 80-094/03L-0 on 800815 during periodic teating motor operated valve SU-1070 failed to cycle Valve required to close on loss of offsite power coincident w/loss of coolant Caused by previous exposure of motor windings to water WILSON.J L Virginia Electric & Power Co 80/07/12 2pp
- ~~8009220263 LER 80-052/03L-0 on 800812.low flow alarm sounded on RM-QW iOI & 102 Process vent sys & RM-QW-IOI & 102 were found to be full of water Caused by flooding of gas stripper Bys flushed & dried Pump & filter replaced WILSON, J L Virginia Electric & Power Co 60/09/12 2pp
- 8009190593 Forwards LERs 80-055/03L-0 & 80-014/03L-0 WILBON, J L Virginia Electric & Power Co 80/09/15 10
- --B009190597 LER B0-055/O3L-0 on B00816 during performance of PT 19 2. MOV-FH-151A failed to indicate in closed position Investigation showed valve in open position Probably caused by mechanical failure of valve operator WILSON, J L Virginia Electric & Power Co B0/09/15 2pp
- --8009170966 LER 80-014/03L-0 on 800816.w/reactor critical, discovered level in refueling water storage tank & CAT below min set by Tech Specs Caused by excessive makeup to 8 St accumulator w/o refilling WILSON-J L. Virginia Electric & Power Co 80/09/13 2pp
- 8009230645 Forwards LERs 80-056/03L-0 & 80-057/03L-0 WILSON, J & Virginia Electric & Power Co 80/09/17 ip
- --8009230461 LER BO-056/03L-0 on BOOBIG at B-/X power.periodic lest 27D revealed low amperage for circuit 7.panel B Caused by damage to heat tracing tape during mechanical work nearby Defective tape replaced 2 voxified uperablo WILBON.J L. Virginia Electric 8 Power Co. 80/09/\$7 2pp
- ---B007230673 LER B0-097/03L-0 on B00BiB.at D9% power.periodic test 2/D revealed low amperage reading for circuit 13A boron injection recirculation to boric acid tanks.panel 9 Caused by failure of heat tracing tape Design change initiated WILSOW, J. Virginia Electric & Power Co. B0/09/1/ 2pp
- DOCKET 50-281 SURRY POWER STATION, UNIT P
 F Security, medical, quergency & fire protection plans
- 8007030184 Forwards revised emergency plan Plan is based on existing meteorological capabilities 3 reflects criteria of NUREG--0654 York County, VA emergency plan encl BAUM, E.A. Virginia Electric 8 Power Co. 80/06/30 2pp
- --8007030297 Revised emergency plan * Virginia Electric & Power Co 80/06/16 500pp
- 8007190739 Requests participation in NRC study of paople-related problems in nuclear safeguards Request includes NRC visit to interview security personnel Confidentiality of info will be maintained during all phases of study VARQA,S A Operating Reactors Branch | 80/08/14 2pp

- 8009230273 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Gys installed for govt use during emergency O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/08/22 in
- 8009090274 Notifies that execution or util emergency drill has been deferred until 801231 NRC has not approved of revised radiological response plan & corporate emergency drill plan Extension until enable proper personnel training period DAUM.E A Virginia Electric & Power Co 80/09/04 2pp
- 8007260043 Forwards facility emergency planning info W/o and SOUDER.J L Division of Rules and Records 80/07/12 ip
- 8009230343 Forwards revised nuclear security personnel training & qualifications program Program withheld (ref 1005R2 790) SYLVIA:B R Virginia Electric & Power Co 80/09/19 ip

@ Adjudicatory correspondence

- 8009230121 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 VAROA.6 A Operating Reactors Branch 1 80/08/29 2pp
- --8009230132 Order for mod of License DPR-32 & DPR-37 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101 EISENHUT.D & Division of Licensing 80/08/29 App
- 8009230013 Motion for stay of effectiveness of Amend 47 to OL.
 authorizing replacement of steam generators, pending appeal
 before US Court of Appeals for DC Circuit in which FES is
 chailenged W/Civil pleadings & succepts of NUREO-0523
 DOUOHERTY, J B Potomac Alliance DOUCHERTY, J B Citizens Energy
 Forum DOUGHERTY, J B Dougherty, J B 80/09/18 11ipp

H General correspondence

- 8009090436 Responds to encl Botetourt County Chamber of Commerce 800526 request to FERC for info re when facilities will be operational Lists status of plant operating schedules DEMION.H R Office of Nuclear Reactor Regulation. Director 80/09/05 3pp
- J Insurance & indemnity information
- 8009090384 Forwards Endorsement i to NZLIA Binder EB-70 ANDREWB.C L Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/09/03 2pp
- 8009160324 Submits payment of Invoice 1077-80, extending indemnity agreement for facility License DPR-32 to B10910
 BYLVIA-3 R Virginia Electric & Power Co 80/09/12 lp
- P Operating license stage documents & correspondence
- 8009020297 Submits interim criteria for shift staffing to ail DL & CP licensees & applicants.per NRC 800507 ltr Discusses adalnistrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D O Division of Licensing 80/07/31 7pp
- 8009050505 Forwards Amend 59 to License DPR-37.safety evaluation & notice of issuance & availability VAROA.9 A Operating Reactors Branch 1 80/08/01 2pp
- --BO09050510 Amend 59 to License DPR-37, revising Tach Specs to reflect changes as result of mods made to alievlate NPBH problems w/low head safety injection & recirculation spray pumps VAROA: A Operating Reactors Dranch 1 80/08/01 27pp
- ---8009050516 Safety evaluation supporting Amend 59 to License DPR-37 * Office of Nuclear Reactor Regulation, Director 80/08/01 13pp
- --8009050519 Notice of issuance & availability of Amend 59 to License DPR-27 VAROALS A Operating Reactors Branch 1 80/08/01 2pp
- 8009080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 enti N/o NUREG EISEKHUT.D G Division of Licensing 80/08/01 119pp

- 8009230092 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D O Division of Licensing 80/08/07 60pp
- 8009190794 Forwards revised Westinghouse STS 3 9 8 2.3 9 10 & Bases 3/4 9 8 5 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control roofs Written response required NOVAK, T M. Assistant Director for Operating Reactors 80/08/15
- --B009190817 Revised Westinghouse STS 3 9 8 2.3 9 10 & Bases 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblles or control rods

 * Assistant Director for Operating Reactors 80/06/23 2ipp
- 8009020437 Application to amend Tech Specs in Licenses DPR-32 & DPR-37 Proposed changes will transfer independent review & audit responsibilities Amend fee enci FERGUSON, J H Virginia Electric & Power Co 80/08/28 Spp
- --8009020441 Proposed changes to Tech Specs 6 i-i through 6 3-i for administrative controls of organization, safety & operation review Tech Specs will transfer independent review & audit responsibilities

 * Virginia Electric & Power Co 80/08/28 12pp
- 8009180539 Forwards Amends 40 & 40 to Licenses DPR-32 & DPR-37, respectively Notice of issuance & availability VARGA,S A Operating Reactors Branch 1 80/08/29 3pp
- --BOO9180545 Amends 60 & 60 to Licenses DPR-32 & DPR-37, respectively, revising Oct 1974 amends to allow possession of byproduct mat!
 VAROA, S. A. Operating Reactors Branch 1 BO/08/29 4pp
- --8009180552 Notice of issuance & availability of Amends 60 & 60 to Licenses DPR-32 & DPR-37, respectively NFIGHBORS, J D Operating Reactors Branch 1 80/08/29 2pp
- 800927046: Forwards Amend 6: & 6: to Licenses DPR-32 & DPR-37, respectively, & notice of issuance & availability VAROA,S A Operating Reactors Branch : 60/09/09 2pp
- --8009290464 Amends 61 % 61 to Licenses DPR-32 & DPR-37, respectively, to require implementation of safeguards contingency plan within 30 days of Commission approval VARQALS A. Operating Reactors Branch 1 80/09/05 4pp
- --B009270469 Notice of issuance & availability of Amends 61 & 61 to Licenses DPR-32 & DPR-37, respectively VAROA.B A Operating Reactors Branch 1 80/09/05 2pp
- 8007180291 Forwards addl info re annual U feed requirements for rangs of discharge burnups to support proposed Tech Specs Change 85 to Licenses DPR-32 & DPR-37 Feed & SHU requirements shown in smc1 table considered conservative SYLVIA.8 R Virginia Electric & Power Co 80/09/15 2pp
- 8009170321 Forwards "Reactor Containment Bldg Integrated Leak Rate Tast Types A.B & C.Surveillance Test " SYLYIA.B R Virginia Electric & Power Co 80/09/16 ip
- --8009170323 "Reactor Containment Bldg Integrated Leak Rate Test. Types. A.B & C. Burveillance Test " * Virginia Electric & Power Co 80/05/31 48pp
- 8009170523 Bubmits info re maintaining min of 23 ft of water over reactor vessel flange during fuel movement in response to MRC 800813 ltr Changes to Tech Specs to include RHR sys requirements adentified in NRC 800611 itr being reviewed BYLV1A, B R Virginia Electric & Power Co 80/09/14 2pp
- 8009220134 Forwards comments on NUREO-0696 in response to NRC 800801 request Implementation of requirements according to time schedula not considered feasible Requests meeting to discuss preliminary pian re effective emergency response facilities FERGUEON, J H Virginia Electric & Power Co 80/09/18 16pp
- BOO924027B Bubmits add1 info re proposed Tech Spec Change Request 85 Util will provide general evaluation of reactor operation to extended fuel burnups possible w/higher fuel enrichment by 810101 SYLVIA.8 R Virginia Electric & Power Co 80/09/23 1p

Q Inspection reports, 1E Bulletins & correspondence

- 8009100056 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Gide High Energy Line Rupture " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/07/24
- BOO9050056 Submits final response to 1E Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchors " All anchor bolt design loads meet safety factors Base plates b bolts which do not meet criteria modified SPENCER.W C Virginia Electric & Power Co BO/08/04 5pp
- 8009180148 Forwards 1E Insp Repts 50-280/80-26 & 50-281/80-29 on E00709-10 No noncompliance noted HURPHY, C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/08/05 2pp
- --8009180162 IE Insp Repts 50-280/80-26 & 50-281/80-29 on 800709-10
 No noncompliance noted Major areas inspected IE Bulletins
 79-02 & 79-14 & licensee actions on previous insp findings
 COMPTOW, R M Region 2. Atlanta: Office of the Director
 HERDIA R Region 2. Atlanta: Reactor Construction & Engineering
 Support Branch 80/08/04 App
- B009020209 Forwards IE Insp Repts 50-280/80-23 & 50-281/80-26 on B00009-0703 & notice of violation LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/08/08 2pp
- --BC09020216 Natice of violation from insp on 800609-0703 * Region 2, Atlanta, Office of the Director 80/08/08 1p
- --8009020220 IE Insp Repts 50-280/80-23 & 50-281/80-26 on 800609-0703
 Nancompifance noted failure to follow plant maint & mod
 procedures
 BURKE, D. J. Region 2, Atlanta, Office of the Director
 KELLU90, P. J. Region 2, Atlanta, Reactor Operations Nuclear Support
 Branch 80/08/08 7pp
- 6009020242 Submits response to IE Builetin 79-03A For North Anna, no SA-312 or A-312. Typa 300 series fusion welded pipe in use at greater than 85% design stress For Surry, eight fittings determined in excess of 80% design stress SYLVIA, B R Virginia Electric & Power Co 80/08/08 2pp
- 8009030141 Forwards Revision 1 to 1E Bulletin 80-17, "Failures of Hercury-Hetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Hritten response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/11 to
- 8009050422 Ack receipt of 800801 itr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-280/80-10 & 50-281/80-11 U'REJLLY, J P Region 2, Atlanta, Office of the Director 80/08/22 ip
- --8009050431 Forwards IE Insp Repts 50-280/80-10 & 50-281/80-11 on 800505-09, (2-16 & 20-23 & notice of violation O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/07/03 2pp
- --8007050436 Natice of violation from insp on 800505-07,12-16 & 20-23 * Region 2, Atlanta, Office of the Director 80/07/03 5pp
- ---B00905044i IE Insp Repts 50-280/80-10 & 50-281/80-11 on 800505-09, 12-16 & 20-23 Noncompliance noted failure to follow Tech Spec procedures, perform corrective actions, control vendor manuals & perform & document safety evaluation UPRIGHT, C M Region 2. Atlanta, Reactor Operations Nuclear Support Branch RUHLAN, M A. BELISLE, O A Region 2. Atlanta, Office of the Director 80/07/03 32pp
- 8009140172 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys." No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/08/22 1p
- 8009140479 Ack receipt of 800804 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-280/80-21 & 50-281/80-22 STOHR.J P. Region 2, Atlanta, Fuel Facility & Materials Bafety Erench 80/08/22, ip.

- --8039160487 Forwards IE Insp Repts 50-280/80-21 & 50-281/80-22 on 800603-06 & notice of violation STOHR, J.P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/07/07 2pp
- --8009160490 Notice of violation from insp on 800509+06 BTOHR. J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/07/07 ip
- --8009160497 IE Insp Repts 50-280/80-21 t 50-281/80-22 on B00603-06 Noncompliance noted failure to have written procedures for preparation of efficiency callbr stds for GE detectors TROUP.6 L Region 2. Atlanta. Fuel Facility & Materials Safety Branch MONTOUNERY.D M Region 2. Atlanta. Office of the Director 80/07/07 9pp
- B009120031 Responds to IE Bulletin 80-19 Surry Units 1 & 2 do not use mercury-wetted relays in reactor protection sys No response for North Anna Units 1 & 2 SYLVIA.B R Virginia Electric & Power Co 80/08/27 2pp
- 8009120314 Forwards 1E Info Notice 80-31, "Maioperation of Gould-Brown Bover! 480 Volt Type K-6003 2, K-DON 6003 Circuit Breakers" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/27
- 8009090528 Forwards response to NRC 800808 itr re violation noted in 1E Insp Repts 50-280/80-23 \$ 50-281/80-26 Corrective action cleared trays & installed cable tray covers required by electrical maint procedures
 SYLVIA.B R Virginia Electric & Power Co 80/09/05 2pp
- 8009240399 Forwards response to IE Bulietin 80-15 re possible loss of emergency notification sys w/loss of offsite power Design change initiated to change power supply to vital bus Administrative Procedure 29 6 revised Affidavit enci SYLVIA.B R Virginia Electric & Power Co 80/09/05 3pp
- 8009240652 Ack receipt of 800821 ltr informing NRC of steps taken to correct violation noted in 1E insp Rept 50-281/80-24 LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/09708 ip
- --8009240661 Responds to NRC 800723 ltr re violations noted in 1E insp Rept 50-281/80-24 Corrective actions startup time for auxiliary steam generator feed pumps brought into compliance w/acceptance criteria 8YLVIA,8 R Virginia Electric & Power Co 80/08/21 3pp
- --8009240669 Forwards 1E Insp Rept 50-281/80-24 on 800623-27 & notice of violation
 LEMIS.R C Region 2, Atlanta, Office of the Director 80/07/25
 29p
- --8009240675 Notice of violation from insp on 800623-27
 * Region 2, Atlanta, Office of the Director 80/07/25 ip
- ---8009240484 iE insp Rept 50-281/80-24 on 800623-27 Noncompliance noted failure to adequately review test results KELLOO,P J., SAVER.R C Region 2, Atlanta, Office of the Director 80/97/25 App
- 8009240693 Ack receipt of 900811 itr informing NRC of steps taken to correct violations noted in IE insp Repts 50-280/80-20 & 50-281/80-21 LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/09/08 ip
- --8007240701 Responds to NRC 800715 ltr re violation noted in IE Insp Repts 50-280/80-20 & 50-281/80-21 Corrective actions trash removed from containment recirculation sump screens & proposed Tech Spec change submitted to IRC BYLVIA, B R Virginia Electric & Power Co 60/08/11 3pp
- --B007240706 Forwards 1E Insp Repts 50-280/80-20 & 50-281/80-21 on 800505-0606 & notice of violation LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/07/15 2pp
- --B007240709 Notice of violation from insp on 800505-0404 4 Region 2. Atlanta. Office of the Director 80/07/15 2pp
- --B009240713 IE Insp Repts 50-280/80-20 & 50-281/80-21 on 800505-0606 Nancompliance noted failure to follow operating procedures to maintain recirculating sump screens, & Inadequate implementation of design control measures for mode KELL030,P J , BURKE,D J Region 2. Atlanta, Office of the Director 80/07/15 App

- 8009250357 Forwards IE Insp Repts 50-280/80-33 & 50-281/80-36 on B00820-22 No noncompliance noted Insp summary only encl (ref 100FR2 790) wEVMAN N Region 2, Atlanta, Safeguards Branch 80/09/09 2pp
- --8009250360 fE Insp Repts 50-280/80-33 & 50-281/80-36 on 800820-22 No moncongliance noted Major areas inspected access control. Tighting & power supply Details uithheld (ref 100FR2 790) P0096.0 E Region 2. Atlanta. Orfice of the Director MCGUIRE.D R Region 2. Atlanta. Safeguards Branch 80/09/08
- 8009260517 Forwards IE Circular 80-21, "Regualtion of Refueling Crews "
 No Written response required
 D REILLY, J P Region 2 Atlanta, Orrice of the Director 80/09/10
- 8907300116 Forwards response to IE Bulletin 80-20 Westinghouse Type H-2 control suitch applications found Subj suitches have been tested satisfactorily SYLVIA.B R Virginia Electric & Power Co 80/09/15 3pp
- R Periodic operating reports & related correspondence
- 8009190437 Forwards monthly operating repts for Aug 1980 SYLVIA 3 R Virginia Electric & Power Co 80/09/15 1p
- --8009190444 Monthly operating repts for Aug 1980 WILSON, J. DUNN, S.D. Virginia Electric & Power Co. 80/09/08
- S Reportable occurrences, LERs & related correspondence
- 800902008B Forwards updated LER 79-008/03x-1 WILSONJ L. Virginia Electric & Power Co. 80/08/25 (p.
- --8007020070 Updated LER 79-008/03%-1 on 790209, during surveillance check found deterioration of piping on low portion of rectriviation spray subsystems Caused by chloride attess corresion Piping replaced w/nonsensitized piping #ILSON, J L Virginia Electric & Power Co 80/08/25 3pp
- 8009030351 Forwards LER 80-011/017-0 WHESOM J L Virginia Electric & Power Co 80/09/02 1p
- --8009080366 LER 80-011/017-0 on 800819. at 12% power, steam flow transmitters (FI-474, 475, 484, 485, 494 & 495) isolated contrary to Tech Spec-3 7 B Caused by transmitters being isolated following containment integrated leat rate test WILSON, J L Virginia Electric & Power Co 80/09/02 2pp
- 8009220248 Forwards LERs 80-012/03L,80-013/03L-0 & 80-015/03L-0 WILSOM, J L Virginia Electric & Power Co 80/09/12 1p
- ---BC09220309 LER 80-012/03L-0 on 800B15, review of Unit 2 pipe support showed that seismic support for charging pump 2-CH-P-1B had not been installed Caused by administrative error Support installed HIL50KJL Virginia Electric & Power Co B0/09/12 2pp
- --8009220398 LER 80-013/03L-0 on 800B15.during startup testing boric acid concentration of 13 8% was reported in I-CH-TK-IC & 2-51-TK-2 Caused by pumping boric acid from boron evaporator bottoms tank to boric acid storage tank u/o sampling WILSON.J L. Virginia Electric & Power Co. 80/09/12 2pp
- ~-8009220402 LER 80-015/03L-0 on 800816, after pressurization of accumulator tanks, level indicator for 'B" SI accumulator indicated 61% level, above Tech Spec mar of 58 3% Caused by condensation & high pressure in nitrogen feed line HILSON, J L Virginia Electric & Power Co. 80/09/12 2pp
- 8009190553 Forwards LERs 80-055/03L-0 & 80-014/03L-0 WILSOR J L Virginia Electric & Power Co 80/09/15 ip
- --8009190566 LER 80-014/03L-0 on B00816.w/reactor critical.discovered level in refueling water storage tank & CAT below min set by Fich Specs Caused by excessive makeup to 8 SI accumulator w/o refilling
 HfLSOMJ L Virginia Electric & Power Co 80/09/15 2pp
- B009240869 Forwards LERs 80~017/03L-0.80~019/03L-0 & 80~020/03L-0 W%LSOM, J L Virginia Electric & Power Co 80/09/19 ip

- --8007240470 LER 80-01//03L-0 on 800820, during Unit 2 startup at 18X power, control room surveyllance revealed terd reading from main steam flow transmitter Caused by partially closed equalizing valve Bistables tripped 5 valve closed HILSON, J Virginia Electric & Power Co 80/07/19 2pp
- ~-8009240471 LER 80-019/03L-0 on 800822, during operation trip valve TV-SS-2068 would not stay closed when actuated from control room Caused by misadjusted limit switch Valve isolated & position limit switch readjusted UKLSOUKJ L Virginia Electric & Power Co 80/09/19 2pp
- --8009240473 LER 80-020/03L-O on 800822 after boric acid batching, chemist reported concentration above Tech Spec requirements Caused by transfer of batch tank to inservice bask Manual shutdown instituted & boric acid diluted to Tech Spec limits
 WILSON, J. L. Virginia Ejectric & Power Co. 80/09/19 2pp
- 8009300498 Forwards LERs 80-022/03L-0 & 80-021/03L-0 WILSDN,J L Virginia Electric & Power Co 80/09/25 ip
- --8009300504 LER 80-022/03L-O on 800826, w/unit operating at steady state. Channel III flow computer, for steam generator steam flow FC 2474: failed Caused by loose printed circuit board & cold solder joint on filter capacitor. Board & Capacitor repaired WILSON, J L. Virginia Electric & Power Co. 80/09/25 2pp
- --8009300508 LER 80-021/03L-D on 800826, while attempting to pressurize Accumulator B using normal nitrogen supply, pressure fetl below allowable limits Caused by leak & low pressure in nitrogen fill header Added pressure to sys & repaired leak WILSON, J L Virginla Electric & Power Co 80/09/25 2pp
- DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STAILON, UNIT 1

 F Security, medical emergency & fire protection plans
- B009240239 Forwards Health Physics Appraisal Repts 50-282/80-08 & 50-306/80-09 on 800505-15, notice of violation & significant appraisal findings KEPPLER, J 0 Region 3, Chicago, Office of the Director 80/08/12 4an
- --8009240246 Notice of violation from health physics appraisal on 800505-15
 4 Region G. Chicago, Office of the Director 80/08/11 Ip
- --8009240255 Health Physics Appraisal Repts 50-282/80-08 & 50-206/80-09 on 800505-15 Noncompliance noted inadequate radiation survey instrument use in high radiation area & inadequate offshift chemistry & radiation protection coverage FIBMER.W L Region 3. Chicago, Fuel Facility & Materials Bafety Branch OREGER.R N. ANUSKAAA Q. Region 3. Chicago, Office of the Director 80/08/11 30pp
- 8008200282 Forwards final draft of upgraded emergency plan, consisting of corporate nuclear & plant emergency plans Delay in submittal due to incorporation of new 100FRSO rules MAYER.L O Northern States Power Co 80/08/15
- --B009200284 Final draft of upgraded emergency plan, consisting of corporate nuclear & plant emergency plans

 * Northern States Power Co B0/08/15 225pp
- BOO9230305 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Bys installed for govt use during emergency KEPPLER. J G Region 3, Chicago. Office of the Director 80/08/22 3pp
- 8009020072 Forwards "Evacuation Time Estimates From Areas Near Prairie Island Nuclear Generating Plant," Revision 1 MAYER.L O Northern States Power Co 80/08/25 1p
- ~-8009020076 "Evacuation Time Estimates From Areas Near Prairie Island Nuclear Generating Plant," Revision 1 * Northern States Power Co 80/08/31, 18pp
- B009100930 Transmits emergency planning info to be made available to public at LPDR in Minneapolls.MN M/o enci B0UDER.J L Public Document Branch 80/07/04 ip
- 8009240015 Transmits emergency planning info to be made available to public at LPDR in Kinneapolis.MN W/o encl SOUDER.J L. Division of Rules and Records 80/09/11 1p

G Adjudicatory correspondence

- 8009030726 Motson to hold proceedings in abequance until 800923, when MN Pollution Control Agency will act on settlement Settlement. If adopted, would result in withdrawal of hearing request SENECHAL, M.E., OLSON, J.F., SPANNAVS, W. Minnesota, State of 80/08/28 Jpp
- --8009030728 Affidavit stating that proposed settlement will be placed on next MH Pollution Control Agency monthly meeting agenda or considered at special meeting for affirmative majority vote of board members

 ERIEMHURGT.L. J. Minnesota, State of 80/08/28 2pp
- B007190295 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by B01101 CLARK.R A Operating Reactors Branch 3 80/08/29 2pp
- --B009190304 Order for mod of Licenses DPR-42 & DPR-60 to add info which fully responds to NRC roquest for info re environ qualification of safety-related electrical equipment Info should be submitted by B01101 EIBENRUT, D O Division of Licensing B0/08/27 App
- 6007100427 Response in opposition to State of MN 800828 motion to hold spent fuel pool mod proceeding in abeyance pending MN Poliution Control Agency Board 800923 meeting Accepting settlement during meeting very remote W/Certificate of Svc BILBERGOJE. BERNSTEIN.D L. Northern States Power Co SILBEROJE Shaw. Pittman. Potts & Trowbridge 80/09/04 7pp
- 8009110023 Response in support of State of MN motion to defer ASLB action until 800923 Bettlement, if accepted during MN Pollution Centrol Agency 800923 meeting, would obviate proceeding Centificate of Svc encl
 EARTH, C A Hearing Branch 3 80/09/08 2pp
- BO09230825 Hemorandum & order granting MN Pollution Control Agency B0092B motion in which deferral of action was requested pending Agency Board B00923 meeting Petitioner shall file reply to will objections by B01001 if settlement rejected LAZO,R H Atomic Safety and Licensing Board Panel 80/09/18 3pp
- 8009300039 Joint motion to terminate proceeding re OL amend application for spent fuel pool storage expansion Agreement incorporating certain language in OL amend has been reached between parties Contentions withdrawn SILBEROUJE Northern States Power Co OLSON, J F Minnesota, State of BARTH.C Hearing Branch 3 80/09/23 3pp
- P. Operating license stage documents & correspondence
- 8009020297 Submits interim criteria for shift staffing to all OL & CP ticensess & applicants,per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Disvelopment & implementation to be reviewed within 90 days EISENHUT,D & Division of Licensing 80/07/31 7pp
- BOO90800BD Forwards draft NUREQ-0694, "Functional Criteria for Exergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for mosting criteria of NUREG-0694 encl W/o NUREG EISENHUT.D O Division of Licensing 80/08/01 119pp
- GOOY230032 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D. O Division of Licensing 80/08/07 60pp
- 8009190794 Forwards revised Wastinghouse BYS 3 9 8 2,3 9 10 & Bases 3/4 9.8 & 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required NOVAK.T M Assistant Director for Operating Reactors 80/08/15
- --8009190817 Revised Westinghouse STS 3 9 8 2.3 9 10 & Bases 3/4 9 8 & 3/4 9.10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods

 4 Assistant Director for Operating Reactors 80/06/23 21pp
- 8009190745 Discusses review of util 800611 response to NRC 800507 ltr identifying five new TMI-2 requirements Review based on HR Denton 800328 ltr re qualifications of reactor operators Item (1) A is does not satisfy criteria GDLLINS,P F. Operator Licensing Branch 80/08/25 2pp

- 8009170082 Forwards Amends 42 & 36 to Licenses DPR-42 & DPR-60respectively.EIA & notice of issuance & availability CLARK.R A Operating Reactors Branch 3 80/08/27 3pp
- --8009170088 Amends 42 & 36 to Licenses DPR-42 & DPR-60, respectively.
 changing Tech Specs, App B, to permit addition of chlorination
 program for circulating water sys in order to destroy
 parasitic amoebs in sys
 CLARK.R A Operating Reactors Branch 3 80/08/27 6pp
- --8009170099 EIA supporting Amends 42 & 36 to Licenses DPR-42 & DPR-60, respectively

 Office of Nuclear Reactor Regulation, Director 80/08/27 4pp
- --8009170092 Notice of issuance & availability of Amends 42 & 36 to Licenses DPR-42 & DPR-60, respectively # Operating Reactors Branch 3 80/08/27 1p
- 8009290421 Advises that 791109 response acceptable re ECCS evaluation models dealing ω/fuel cladding swelling & incidence of rupture No further action necessary CLARK.R A Operating Reactors Branch 3 80/09/10 2pp
- B009170341 Gubmits further response to NRC B00805 inquiries re proposed fuel surveillance program for refueling outage Fabrication methods used for gadolinia-bearing rods were typical of production-type fuel MAYER.L O Northern States Power Co 80/09/12 3pp
- 8007190481 Notifies of delay until 801114 for submittal of proposed Tech Specs for Lessons Learned Category A requirements, requested by NRC 800702 ltr MAYER.L O Northern States Power Co 80/09/12 2pp
- 8009300334 Forwards JC Lehr 800826 memo documenting EIA re 800826 issuance of Amends 42 & 36 to Licenses DPR-42 & DPR-60, respectively MARTIN.R Operating Reactors Branch 3 80/09/12 lp
- --8009300340 Forwards compilation of telcons re 800821 license amend request Correspondence w/MN Pollution Control Agency & MN Dept of Matl Resources encl LEHR, J C Assistant Director for Environmental Technology 80/08/26 7pp
- 8009250244 Submits supplemental info to 800505 request for amend to Licenses DPR-42 & DPR-60 re Sl actuation & power distribution limits Lists detailed responses to NRC questions MAYERIL O Northern States Power Co 80/09/19 Jpp
- **G** Inspection reports, IE Builetins 3 correspondence
- 8009110620 Forwards IE Insp Rept 50-282/80-11 on 800710 No noncompliance noted FIGRELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/07/22 2pp
- ---8007i10427 IE Insp Rept 50-282/80-11 on 8007i0 No noncompliance noted Major areas inspected GA/OC program implementing procedures, work activities & records re steam generator tube nondestructive examinations DANIELSON.D H Region 3. Chicago, Reactor Construction & Engineering Support Branch WARD, K D Region 3. Chicago, Office of the Director 80/07/21 4pp
- 8009150076 Advises that response to Item 6 of IE Bulletin 79-17. Revision 1.was satisfactorily completed on Unit 1 in Jul 1980 No corrective actions necessary OLLERTS.D E Northern States Power Co 80/08/14 ip
- B007150218 Responds to IE Bulletin 80-19 re failure of mercury-wetted matrix relays (to relays of type described are used in reactor protection sys at facility OILBERTS, D E Northern States Power Co 60/08/14 ip
- 8009260263 Forwards IE Insp Repts 50-282/80-13 & 50-306/80-13 on 800501-0731 No noncompliance noted HEISHMANR F Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/14 2pp
- --8009260271 IE Insp Repts 50-282/80-13 % 50-306/80-13 on 800601-0731 No noncompliance noted Major areas inspected operation, maints surveillance, security & radiation protection FEIERABEND, C D , BURGES9, B L , LITTLE-W S Region 3, Chicago, Office of the Director 80/08/11 Spp

- 8009030210 Forwards Revision 1 to 15 Bulletin 60-17, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Unitten response required KEPPLER.J G Region 3, Chicago. Office of the Director 80/08/15
- 8009110539 Responds to 1E Bulletin 80-18, 'Possible Disconnect Mode 4 Automation Industries Inc Model 200-008 Sealed Source & Pigtail Assembly " High injection pumps assured min cooling GILBERTS, D.E. Northern States Power Co. 80/08/15 ip
- 8009090019 Gubmits addl response to LE Bulletin 80-08, "Exam of Containment Liner Panetration Welds "Factifity does have containment penetration connections of type described Factifity was built to ANSI BSI in 1947 Summary rept encl OILBERTS, D.E. Northern States Power Co. 80/08/21 i9pp
- 8009i70433 Forwards IE Circular 80~18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER.J G Region 3. Chicago, Ofrice of the Director 80/08/22
- 8009170405 Responds to IE Bulletin 80-15 re possible loss of emergency natification sys w/loss of offsite power New sys will be installed in Oct 1980 Test will be conducted upon completion of power supply sys Notification made on 800625 OILBERTS.D E Northern States Power Co 80/08/28 2pp
- 8007230066 Forwards IE Info Notice 80-3i, "Maloperation of Gould-Brown Bosesi 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers" No written response required XEPPLER, J O Region 3. Chicago, Office of the Director BO/08/28
- 8009100500 Forwards Revision 5 to "ASME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ASME Code Section XI Requirements " MAYER.L O Northern States Fower Co 80/07/03 2pp
- --8009100505 Revision 5 to "ABME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ASME Code Section XI Requirements "
 • Northern Status Power Co 80/09/03 10pp
- 8009240112 Forwards IE Circular 80-21, "Regulation of Refueiting Crews " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/10
- R Periodic operating reports & related correspondence
- B009090297 Forwards "Effluent t Waste Disposal Semiannual Rept for Jan-June 1980 " MAYER,L O Northern States Power Co 80/08/28 1p
- --8009090302 "Efrivent & Waste Disposal Semiannual Rept for Jan-June 1980 " Northern States Power Co 80/08/28 9pp
- 8009160279 Forwards monthly operating repts for Aug 1980 MAYER-L D Northern States Power Co 80/09/08 1p
- --8007160282 Monthly operating repts for Aug 1980 HJNSTAD, A A Northern States Power Co 80/09/01 8pp
- 8 Reportable occurrences, LERs & related correspondence
- 8009090356 Forwards LER 80-024/03L-0 MAYER, L D Northern States Power Co 80/09/05 19
- --80090903B8 LER 80-024/03L-0 on 800829, fatiure to perform inservice insp of tafety notile to shell weld of both reactor vessels was noted Cause due to equipment unavailability Rescheduling requested for 1980 & 1984 outages KRUMPOS.P J Northern States Power Co 80/09/05 Ip
- 8009180422 RO 80~25 on 800904, w/unit in refueling shutdown uitrasonic axamination of steam generator support bolts revealed most bolts had crack indications Several bolts failed when detensioning was attempted Cause not determined TIERNEY, F P Northern States Power Co 80/09/05 2pp
- 8009230738 Forwards LER 80~025/01T-0 MAYER.L O Northern States Power Co 80/09/18 1p

- --8009230741 LER 80-025/CIT-0 on 800904.during refueling shutdown, ultrashnic exam of steam generator support bolts revealed crack indications Unit 2 also inspected Caused by environ assisted cracking All Unit 1 bolts will be replaced * Northern States Power Co 80/07/18 ip
- BOO9230743 Forwards LER 80-023/03L-0 MAYER, L O Northern States Power Co 80/09/19 1p
- ---8009230750 LER 80-023/03L-0 on 800820, during review of surveillance gragram annual test, SP1185 for control room special ventilation flow verification found omitted for 1978-1980 Caused by personnel error Personnel will review rept HUMSTAD.A A Northern States Power Co 80/09/19 ip
- B009300551 Forwards updated LER 80-025/01T-1 MAYER, L O Northern States Power Co 80/09/25 1p
- --B009300558 Updated LER 80-025/01T-1 on 800904, ultrasonic examination of steam generator support boits revealed that most had crack indications Preliminary cause suggests environmentally assisted cracking HUISTAD, A A Northern States Power Co 80/09/25 1p
- 8009300979 Environ Event Rept 80-03 on 800820, during special chlorination program, certain levels of chlorine found outside circulating water sys that exceeded concentration limits in Tech Specs 2 4 1
 WARD, P C Northern States Power Co 80/09/25 4pp
- DOCKET 50-285 FORT CALHOUN STATION. UNIT 1

 F Security, medical, emergency & fire protection plans
- 8009040076 Informs of need for revisions & add1 info re 800817 training & qualification plan Enci withheld (ref iOCFR2 790)
 NDVAN,T H Assistant Director for Operating Reactors 80/08/11
- 8009020149 Invites participation in 800822 workshop in Atlanta. 0A to solicit comment re proposed functional criteria for emergency response facilities in NUREO-0696 Discussion to include location. size > staffing of emergency ctrs SEYHRIT.K V Region 4. Dalias. Office of the Director 80/08/12 in
- BD09120107 Confirms telcon re vital area analysis team & disposition of info in plant drawings Enci identifying info for team members withheld per Privacy Act Plant drawings will be withheld (ref 10CFR2 790) CLARK, R A Operating Reactors Granch 3 80/08/15 2pp
- 8009090564 Forwards input on fire protection review, Items 3 1 15/3 2 4. 3 1 16/3 1 28 & 3 2 2 re cable separation, fire water supply, protection for stairways & open hatch & testing fire detectors

 HALL.R E Brookhaven National Laboratory, 80/08/25 3pp
- O Adjudicatory correspondence
- 8009190336 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 CLARK.RA Operating Reactors Branch 3 80/08/29 2pp
- --8009190343 Order for mod of License DPR-40 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101
 EISENHUT.D 0 Division of Licensing 80/08/29 App
- O Advisory Committee on Reactor Safeguards reports & correspondence
- EOO7030347 Forwards ACRE BOOBil memb advising that ACRE does not object to NRC licensing facility to operate at power levels up to 1,500 MHt NRC is preparing related license amend WAONER.P C Operating Reactors Branch 3 80/08/13 2pp
- P Operating license stage documents & correspondence
- 8009020297 Bubmits interim criteria for shift staffing to all GL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overfime work Development & implementation to be reviewed within 90 days EISENHUT, D Q Division of Licensing 80/07/31 7pp

- EOO9980080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/O NUREG EISENHUT, D @ Division of Licensing 80/08/01 119pp
- B009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D 0 Division of Licensing 80/08/07 60pp
- BOO9190175 Forwards Amend 51 to License DPR-40.EIA & negative declaration CLARK A Operating Reactors Branch 3 BO/OB/2B 2pp
- ---S009190179 Amend 51 to License DPR-40, revising App B Tech Specs to delete certain environ monitoring & reporting requirements & increasing max & differential condenser cooling water discharge temp limits
 CLARK.R A Operating Reactors Branch 3 80/08/28 10pp
- --8009190182 Safety evaluation supporting Amend 51 to License DPR-40
 Office of Nuclear Reactor Regulation, Director 80/08/28 2p
- --8009190185 Negative declaration re issuance of Amend 51 to License DPR-40 CLARK:R A Operating Reactors Branch 3 80/08/28 2pp
- 8009090581 Advises that Amend 51 to License DPR-40 became effective on 800828 when NPDES permit covering same subj was approved by NE Digit of Environ Control JONES W C Omaha Public Power District 80/09/02 ip
- SOOP150444 Informs of evaluation of current Tech Specs compared to STS re iodine spiking & primary & secondary coolant activity level requirements in response to NRC 800722 itr DL amend will be forwarded by 80114

 JONES.W C Omaha Public Power District 80/07/05 ip
- 8009290457 Advises that util response re ECCS evaluation models, dealing w/fuel cladding swelling & incidence of rupture, is acceptable CLARK, R L Operating Reactors Branch 3 80/09/10 2pp
- G Inspection reports, IE Bulletins & correspondence
- 8009020106 Responds to IE Bullstin 80-12 re decay heat removal sys operability Facility fundamental design differences would prevent similar event at Fort Calhoun Shutdown cooling sys reviewed & decay heat removal sys operability ensured JONES.W C Gmaha Public Power District 80/06/26 App
- 8009180147 Forwards IE Bulletin 80-i8, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Written response required GEYFRIT, X V Region 4, Dallas, Office of the Director 80/07/24 ip.
- BOD9180105 Forwards IE Bulletin 80-20. "Failures of Westinghouse Type M-2 Spring Return to Neutral Control Switches" Written response required SEYFRIT, X V. Region 4. Dallas. Office of the Director 80/07/3i 10
- GOO9180154 Forwards IE Bulletin 80-19, "Failure of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/07/31 to
- 8007260283 Forwards IE Info Notice 80-27, "Broken Bluds on Terry Turbine Steam Inlet Flange " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/08/07 1p.
- 8009260526 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Hercury-Hetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/08/15, 1p
- 8009170401 Forwards IE Circular 80-18, "100FR50 59 Bafety Evaluations for Changes to Radwaste Treatment Sys " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/08/22

- 8009120432 Forwards IE info Notice 80-31, "Malaperation of Gould-Brown Bover: 480 Voit Type K-6005 & K-DON 6008 Circuit Breakers" No written response required SEYFRIT.K V Region 4, Dalias, Office of the Director 80/08/27
- BOO9190577 Forwards IE Insp Rept 50-285/80-14 on B00811-15 No nencompliance noted Cover itr only enci (ref 10CFR2 790) KELLY, J A F Region 4, Dailas, Office of the Director B0/09/05 in
- --8009190584 IE Insp Rept 50-285/80-14 on 800811-15 No moncompliance noted Major areas inspected security plansecurity program audit security organization & access control Details withheld (ref 10CFR2 790)
 EVANS.A , KELLYJ A F Region 4, Dallas, Office of the Director 80/09/04 Ip
- R Periodic operating reports & related correspondence
- B009030479 Forwards "Semiannual Rept for Tech Spec 5 9 4 5 App B." Jan-June 1980 JDNFS.W C Omaha Public Power District 80/08/29 lp
- --8009030486 "Bemlannual Rept for Tech Spec 5 9 4 & App B." Jan-June 1980 BTEVENS, S C Ommana Public Power District 80/08/29 190pp
- 8007230347 Forwards monthly operating tept for Aug 1980 JDNFS,W C Omaha Public Power District 80/09/08 19
- --8009230351 Monthly operating rept for Aug 1980
 HICKLE, B J Omaha Public Power District 80/09/08 9pp
- 8009230721 Responds to NRC 800825 ltr requesting verification of draft summary of radioactive efficient releases Requires corrections for liquid efficients of Br-87 & Sr-70 for second quarter continuous & batch modes

 JONES.W C Omaha Public Power District 80/09/18 ip
- S Reportable occurrences, LERs & related correspondence
- 8009090525 Forwards LER 80-017/03L-0 STEVEN8,S C Omaha Public Power District 80/08/27 ip
- 8009090505 Forwards LER 80-018/03L-0 STEVENS, 8 C Omaha Pubilo Power District 80/09/05 lp
- --8009090519 LER 80-018/03L-0 on 800808.while attempting to monitor gas space on VCT, inadvertent release of radioactive mati to auxiliary bidg environ occurred Caused by deteriorated surgical tubing on gas analyter Tubing replaced HYDE,K C Omaha Public Power District 80/09/05 4pp
- 8009300532 Forwards LER 80-021/03L-0 STEVENS,8 C Gmaha Public Power District 80/09/17 lp
- --8009300339 LER 80-021/03L-0 on 800910.transformer T4 of D9-1 failed Transformer feeds diesel oii immersion heater & alarm relays Caused by moveable armature iocated on immersion heater contractor Armature repaired MUELLER.R J Omaha Public Power District 80/09/11 4pp
- DOCKET 50-286 INDIAN POINT STATION: UNIT 3

 F. Security, medical, emergoncy & fire protection plans
- BD09020252 Requests 30-day extension for providing comments to NRC due on B00905 re security guard force training at facility MALTESE: M J. Power Authority of the State of New York 80/08/21
- 8009230185 Requests that all personnel be reminded of surpose of emergency notification sys & health physics network Bys installed for govt use during emergency GRIER, B H Region i, Philadelphia, Office of the Director BO

- 8009090773 Approves 800815 request for extension to complete installation of addidry sipe sprinklers in cable tunnel Barety evaluation enci VARGA.S A Licensing Branch 1 80/08/27 2pp
- --8009090775 Safety evaluation supporting extension for completion of installation of addi dry pips sprintlers in cable tunnel of Office of Nuclear Reactor Regulation, Director 80/08/27 3pp

@ Adjudicatory correspondence

- 8007/90255 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801/01 VARGA.S A Operating Reactors Branch i 80/08/29 3pp
- --B009190260 Order for mod of License DFR-64 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment info should be submitted by 801101 EISENHULD 6 Division of Licensing 80/08/29 App
- 8009120394 Order granting extension until 800926 for Commission to review ALAB-436 & relevant portions of ALAB-561 CMILK-S J Office of the Secretary of the Commission 80/09/i0 to
- 6007300320 Order granting extension until 801024 for Commission to review ALAB-436 & ALAB-561 CHILK.S J Office of the Secretary of the Commission 80/09/26 350

H General correspondence

- 8009180448 Responds to 600319 ltr requesting public debate re issues appropriate to evacuation of large population ctrs near plants
 DENIGH.H R Diffice of Nuclear Reactor Regulation, Director 80/04/21 3pp
- --8009/80462 Requests public debate ralissues appropriate to evacuation of large population ctrs near plants Expresses confidence in attempts by Commissioners to represent public concerns EMORY.X Affiliation Unknown 80/03/19 ip
- 8009110218 Forwards response to 800728 itr requesting assistance in answering constituent questions re nuclear power & effects of radiation DIRCKS.W J Office of the Executive Director for Operations 80/08/28 4pp

I Financial information

8009120396 Forwards estimated cash flow & audited financial statements for 1979
SERRY.G T Power Authority of the State of Neu York 80/09/03
1200

P Operating increse stage documents & correspondence

- E009300169 "Rept of Zion/Indian Point Study Vol 2," informal rept STEVENSOR, M 0 Los Alamos Scientific Laboratory FIN A-7015 NUREC/CR-1411 V2 E0/04/30 165pp Available at NTIS
- ED09050343 Discusses void formation in vessel head during 800611 natural circulation cooldown event Requests opinion repotential for voiding phenomenon in B&W designed NSSS CHECK.PS Assistant Director for Plant Systems 80/07/28 2pp
- 8009020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants, per NRC 800507 jtr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISERMUT, D & Division of Licensing 80/07/31 7pp
- 80090900B0 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl N/o NUREG EISERHUT, D.C. Division of Licensing 80/08/01 ii9pp
- 9007070774 Forwards request for add1 info to fracture toughness design of steam generator & reactor coolant pump supports Facility has been classified as Group 1 plant in accordance interest of the pump of the

- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISEMHUT, D.G. Division of Licensing 80/08/07 40pp
- 8007190794 Forwards revised Westinghouse STS 3 9 8 2/3 9 10 & Bases 3/4 9 8 & 3/4 9 10 to require 23 #t of water over top of reactor pressure vessel fiange during movement of fuel assemblies or control rods Written response required NOVAK/TM Assistant Director for Operating Reactors BO/OB/i3 10
- --8007170817 Revised Westinghouse STS 3 9 8 2.3 9 10 8 Bases 3/4 9 8 k 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods * Assistant Director for Operating Reactors 80/06/23 21pp
- BOO91505i5 Requests long-term solution to correct electrical override/ bypass problem NRC review found that manual sys-level actuation features for containment isolation & spray will not function after automatic safety signals reset VARGALS A Operating Reactors Branch 1 B0/08/20 3pp
- 8009220388 Advises that Ofc of Controller has been authorized to refund Class III amend fee sent w/util 800325 application Refund authorized due to exemption re certain fire protection Tech Spec changes authorized by law & in public interest MILLER.W D License Fee Management Branch 80/08/25 1p
- 8007040420 Forwards details of proposed steam generator insp to be performed during mid-cycle outage as required by Amend 31 to 0L Multi-frequency insp will be performed on 800 tubes in 32 steam generator hot leg (inlet)

 BAYNELUP Power Authority of the State of New York 80/08/28
 30s
- 8007050273 Forwards info in response to NRC 800731 request re combination of SSE & LOCA responses for RCS Strain components of SSE & LOCA leads were combined since 86E responses were calculated elasticative & LOCA inelastically BAYNE.J P Power Authority of the State of New York 80/08/29 300
- BOO9090383 Forwards "Rept on Evaluation of Thermal Plume Studies of Indian Point Nuclear Generating Station" Objectives of thermal plume program have been fulfilled Rept available in Central Files only ZARAKAS,P Consolidated Edison Co of New York 60/08/29 ip
- 800707071 Confirms util commitments to NRC 791023 interim position on containment purging & venting Util position to remain in effect pending completion of long-term review VARGA, S A Dyperating Reactors Branch 1 80/08/27 3pp
- 8009;2018: Forwards request for add1 info to complete review of electrical override/bypass aspects of engineered safety features VARGA-S A Operating Reactors Branch i 80/08/29 Spp
- 8009120502 "Rept of Zion/Indian Point Study," Vol 1 MURFIM,N B Sandia Laboratories FIN A-1218 NUREO/CR-1410 VI. 80/08/31 400pp
- 8009120624 "Task Force Rept on Interim Operation of Indian Point "BERNERO,R M , BLOND,R K , PRITCHARD,W C Office of Policy Evaluations NUREG-0715 80/08/31 78pp Available at NTIS
- 8009120191 Forwards review & comments of dose calculation methods in offsite dose calculation manual (ODCM) Requests revised ODCM within 60 days
 VARGA-S A Operating Reactors Branch 1 80/09/02 7pp
- 8007070506 Forwards table outlining effects of combining SEE & LOCA responses in analysis of Unit 2 RCS for postulated LOCAs, in response to NRC 800731 ltr
 ZARAKAS,P Consolidated Edison Co of New York 80/09/03 3pp
- B009230230 Notification of B00910 meeting w/util in Bethesda.MD to discuss sys interactions study CLSHAN.L N Licensing Branch i 80/09/05 2pp
- 8009290439 Forwards Amends 32 % 50 to Licenses DPR-64 & DPR-59, respectively safety evaluation & notice of issuance & availability VAROA.S A Operating Reactors Branch 1 80/09/05 3pp

- --8009290446 Amends 32 & 50 to Licenses DPR-64 & DPR-59, respectively, changing organization charts & position titles & increasing mambership of safety review committee for both units VAROALB A Operating Reactors Branch 1 80/09/05 26pp
- --8009290451 Safety evaluation supporting Amends 32 & 50 to Licenses

 DPR-64 & DPR-59 respectively

 + Office of Nuclear Reactor Regulation, Director 80/09/05 3pp
- --8009290454 Notice of issuance & availability of Amends 32 & 50 to Licenses DPR-64 & DPR-59, respectively VARGA, S A Operating Reactors Branch 1 80/09/05 3pp
- EOG9150254 Forwards "Cycle 3. Startup Physics Test Rept " Rept available in Central Files only BAYNE. J P Power Authority of the State of New York 80/09/11 1p
- 8009170325 Responds to NRC 800820 request for proposed long-term solution to correct blocking of manual sys-level actuation asstration containment isolation & containment spray Forwards sketches of actuation schemes & proposed solution EAYNELJP Power Authority of the State of New York 80/09/14pp
- BO09180144 Discusses two risk studies currently underway Preliminary assessment of Indian Point risk profile contained in SECY 80-283 Zion risk profile assessment will combine accident sequence evaluation & containment failure analysis ERNST.M L Assistant Director for Technology Review 80/09/11 55p
- 8009260537 Forwards Amend 33 to License DPR-64.notice of issuance & availability
 VAROA.8 A Operating Reactors Branch 1 80/09/12 4pp
- --80092&0541 Amend 33 to Licanse DPR-64, requiring safeguards contingency plan be fully implemented within 30 days of Commission approval VAROA.S A Operating Reactors Branch 1 80/09/12 2pp
- ---8009260545 Notice of issuance & availability of Amend 33 to License DPR-64
 - DPR-64 VARQA:8 A Operating Reactors Branch 1 80/09/12 2pp
- 8009180384 Requests 6-month extension of due date for response to NRC 800804 ltr re fracture-toughness design of steam generator & reactor coolant pump supports Addl time needed to obtain orginal support mati from original suppliers

 BAYNE.J P Power Authority of the State of New York 80/09/15 lp
- BOO9230451 Forwards corrected response to Question 4 to BO0720 ltr re backfitting of severe accident mitigation features BAYNE, J P Power Authority of the State of New York ZARAKAS, P Consolidated Edison Co of New York B0/07/16 3pp
- BOO9250266 Forwards current training course outlines re heat transfer.

 Fluid flow & thermodynamics, in response to NRC 800328 ltr

 ZARAKAS,P Consolidated Edison Co of New York 80/09/19 30pp
- 8009260442 Advises that staffing requirement to have three persons onshift during all scheduled outages when unit is in cold shutdown mode will be deleted, due to reduced potential for emergency during such periods BAYNE, J P Power Authority of the State of New York 80/09/23 ip
- G Inspection reports, IE Bulletins & correspondence
- 9009090537 Responds to IE Bulletin 80-16, "Potential Misapplication of Rosemount, Inc Models 1151 & 1152 Pressure Transmitters H/Either A or D Output Codes" Models specified not used at facility
 ZULLA.6 S Power Authority of the State of New York 80/07/25 1p
- GOO9190936 Advises that response to IE Bulletin 80-14 will be consolidated w/reply to IE Bulletin 80-17 due to similarity of action items

 FASTERNAK, R J Power Authority of the State of New York 80/07/28
- BO09220379 Forwards response to IE Bulletin 79-09A re longitudinal weld defects in ASME SA-912 Type 304 stainless steel pipe. All A-312 pipe used has seemless const SA-912 is not used in safety-related piping No action required BAYNE. J P Power Authority of the State of New York 80/07/29 3ap

- 8009220030 Responds to LE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protection Sys of Operating Muclear Plants Designed by C-E " Relays are not used at facility ZULLA,S S Power Authority of the State of New York 80/08/08 1p
- 8009030039 Forwards Revision 1 to IE Sulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required ORIER 0 H Region 1, Philadelphia, Office of the Director 80/08/15 1p
- 8004150303 Discusses IE insp on 800624-26 & forwards notice of violation b notice of proposed imposition of civil penalty STELLO.V Office of Inspection & Enforcement, Office of the Director 80/08/22 2pp
- --8009150306 Notice of violation from insp on B00624-26 Noncompliance noted failure to implement appropriate procedures for incore flux monitoring sys repair & neutron detector replacement & radiation overexposure to personnel 4 Office of Inspection & Enforcement, Office of the Director 80/08/22 Spp
- --8009150308 Natice of proposed imposition of civil penalties in amount of \$12,000 00 for items of noncompliance noted in IE insp on 800624-26

 * Office of Inspection & Enforcement, Office of the Director 80/08/22 lp
- 8009180025 Forwards IE Carcular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwasto Treatment Sys " No written response required ORIER B H Region 1, Philadelphia, Office of the Director 80/08/22 1p
- 8009120196 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover: 480 Volt Type K-6008 & K-DDN 6008 Clrcuit Breakers " No written response required GRIER B H Region 1, Philadelphia, Office of the Director 80/08/27 ip
- 8009230793 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/09/10 1p
- 8009240349 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matis " No writton response required ORIER.B H Region 1. Philadelphia, Office of the Director 80/09/12 ip
- R Periodic operating reports & related correspondence
- BOO90303B2 Forwards "Effluent & Waste Disposal Semiannual Rept.Jan-June 1980 " ZARAKAS,P Consolidated Edison Co of New York 80/08/29 ip
- --8009030386 "Effluent % Waste Disposal Semiannual Rept, Jan-June 1980 "
 * Consolldated Edison Co of New York 80/08/29 43pp
- B009080323 Forwards "Effluent & Waste Disposal Semiannual Rept.Jan-June 1980 " ZULLA.S S Power Authority of the State of New York 80/08/29 in
- --8009080325 "Effluent & Waste Disposal Semiannual Rept. Jan-June 1980 "
 # Power Authority of the State of New York 80/08/29 44pp
- 8009190442 Forwards monthly operating rept for Aug 1980 ZULLA, 8 8 Power Authority of the State of New York 80/09/15 ip
- ---8009190451 Monthly operating rept for Aug 1980 CONNELL, C Power Authority of the State of New York 80/09/02 60p
- BOO9230432 Forwards daily record of fish collections for Aug 1980, including daily species breakdown & total weight Unit 2 & 3 circulators were run for entire month Unit 1 circulators were run on BOOBOB, 10, 13, 17, 17, 21, 23, 30 & 31 ZARAKAS, P Consolidated Edison Co of New York BO/09/15 1p
- ---8007230433 Daily record of fish collections from intake screens for Aug 1980 * Consolidated Edison Co of New York 80/09/15 5pp

- 8009240452 Forwards quarterly rept on "Seismic Monitoring Network in Vicinity of Indian Point NY, Consolidated Edison Project, Mar-May 1980 "
 ZARAKAS:P Consolidated Edison Co of New York 80/09/15 lp
- --8009240455 "Seismac Monitoring Network in Vicinity of Indian Point,NY, Consolidated Edison Project,Mar-May 1980 " * Woodward-Clyde Consultants, Inc 80/08/15 44pp
- S Reportable occurrences, LERs & related correspondence
- 8009020510 EN-80-038 on 800822, notice of violation & notice of proposed imposition of civil penalties of \$12,000 will be issued Action based upon alleged noncompliance re overexposure of two individuals BRGCKEIT, TW. THOMPSON D Office of Inspection & Enforcement, Office of the Director 80/08/20 (p
- 8009030510 RU on 800804.circulating water sys discharge temp exceeded Tech Specs limit Caused by high ambient river temps high discharge temps 5 broken circulating water pump Demand load & discharge temp reduced ZARAKAS.P Consolidated Edison Co of New York 80/08/28 2pp
- DOCKET 50-287 GCONEE NUCLEAR STATION, UNIT 3
- F Security, medical, emergency & fire protection plans
- 8007230256 Requests that all personnel be reminded of purpose of emergency notification sys & health physics networt Sys installed for got use during smergency OfREILLY.J P Region 2. Atlanta. Office of the Director 80/08/22
- Q Adjudicatory correspondence
- 800926064 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 80101 REID:R W Operating Reactors Branch 4 80/08/29 2pp
- --8009260667 Order for mod of Licenses DPR-38, DPR-47 & DPR-55 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801104 EISENHUF, D O Division of Licensing 80/08/29 App
- J Insurance & indemnity information
- 8009190424 Forwards Endorsement 58 to NELIA Policy NF-182 & Endorsement 43 to MAELU Policy MF-61 SANDERS, F D Duke Power Co 80/08/25 3pp
- 8007300428 Advises that invoices for facility indemnity fees should be addressed to MD Parker.not AC Thies PARKER.N O Duke Power Co 80/09/24 ip
- P Operating license stage documents & correspondence
- 8009150070 Responds to 800923 recommendations concerning lessons learned from 800226 transsent at Crystal River Submits results of investigations re use of atmospheric dump valve at Doonee Units 1-3, AR Unit 1, Davis-Besse Unit 1 & TMI-1 DENTON, H R Office of Nuclear Reactor Regulation, Director 80/07/21 2pp
- 8009020297 Submits interim criteria for shift staffing to all GL & CP licensees & applicants, per NRC 800807 itr Discusses addinistrative provisions for amergency & overtime work Development & implementation to be reviewed within 90 days EISEMMUT.D O Division of Licensing 80/07/91 7pp
- B009080080 Forwards draft NUREG-0696, "Functional Critaria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 entl N/o NUREG EISEN-NUT.D & Division of Licensing 80/08/01 i19pp
- 6009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D 0 Division of Licensing 80/08/07 60pp

- 8009040085 Requests written confirmation of appraisal of critical electrical power generation situation in region served by Duke Power Co MDVAK.T M Assistant Director for Operating Reactors 80/08/11
- E009160501 Forwards Amends 86.86 & 83 to Licenses DPR-38 DPR-47 & DPR-55 respectively, safety evaluation & notice of issuance & availability REID.R W Operating Reactors Branch 4 80/08/20 2pp
- ---8009160502 Amends 86.86 % 83 to Licenses DPR-38.DPR-47 % DPR-55, respectively, incorporating test frequency requirements of 10CFR50.App J. into containment leak test program REID.R W Operating Reactors Branch 4 80/08/20 7pp.
- ---B009160506 Safety evaluation supporting Amends 86,86 & 83 to Licenses

 OPR-3B,DPR-47 & DPR-59,respectively

 4 Office of Nuclear Reactor Regulation, Director 80/08/20 2pp
- --B009160507 Notice of issuance & availability of Amends 86,86 & 83 to Licenses DPR-38,DPR-47 & DPR-55,respectively REID,R W Operating Reactors Branch 4 80/08/20 2pp
- 8009160505 Notification of 800903 meeting w/util & Franklin Research Ctr in Bethesda, MD to review NUREO-0578, Items 2 1 7 A&B FAIRTILE,N B Operating Reactors Branch 4 80/08/21 ip
- 8009030507 Forwards proposed revision to Tech Bpecs to support Unit 3 at full rated power during Cycle 6 & B&W rept, "Oconee Unit 3, Cycle 6 Reload Rept."
 PARKER, W D Duke Power Co 80/08/25 3pp
- --8009030519 "Oronee Unit 3,Cycle 6 Reload Rept "
 # Babcock & Wilcox Co BAW-1634 80/08/31 38pp
- 8009020025 Forwards B&W rept, "Evaluation of Instrumentation to Detect Inadequate Core Cooling Prepared for 177 Owners Group," supplementing warlier util submittals re Lessons Learned Item 2 1 3 b No addl instrumentation needed W/o encl PARKER.W O Duke Power Co 80/08/26 ip
- B009100489 informs NRC that revised radiological ETS "Offsite Dose Calculation Manuel" & proposed process control program for solid waste sys will be forwarded by 800930 PARKER:N D Duke Power Co 80/09/03 ip
- B009190194 Advises of NRC review of util 800328 submittal re standby shutdown facility Pages 2-1.9-1.5-2.9-3.4-3 & 7-1 should be withheld per 10CFRR 770 Util should resubmit document w/ deletions within 30 days
 REID.R W Operating Reactors Branch 4 80/09/09 2pp
- 8007250434 Informs of acceptability of response to NRC 791109 1tr re portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture REID.R W Operating Reactors Branch 4 80/09/09 2pp
- BOO9230707 Submits corrections to 800711 ltr re cracked steam generator manway studs at Oconee 3
 TAYLOR, J H Babcock & Wilcox Co 80/09/15 lp
- 8009230724 Disagrees w/NRC 800909 1tr re classification of Standby Shutdown Facility licensing document Document should be withheld (ref 10CFR2 790) No nonpropietary version will be submitted PARKER, U O Buke Power Co 80/09/17 1p.
- 8009300486 Forwards response to NRC 800611 request for change in facility Tech Specs.providing for redundancy in decay heat removal capability No changes necessary to Tech Specs PARKER.N O Duke Power Co. 80/09/24 3pp
- G Inspection reports, IE Bulletins & correspondence
- 8009100058 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Written response required O'REILLY, J.P Region 2, Atlanta, Office of the Director 80/07/24

- CODGO40540 Responds to IF Bulletin 80-16 Resembunt Model 1151 & 1152 pressure transmittors w/autput codes A or D are used for indicating reactor coolant pressure & providing input to control steam generator level PARKER, N D Duke Power Co 80/07/30 3pp
- SOQ9030175 Forwards Revision 1 to IE Builetin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/15 to 16
- 8009160137 Forwards IE Circular 80-18. "LOCFRSO 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/22
- BOOF170233 Responds to IE Bulletin 80-19. Revision 1. "Failures of Marcury-Natted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Review indicates relays are not in use at facility PARKER.N O Duke Power Co 80/08/22 lp
- SOC9100801 Ack receipt of 800423 itr informing NRC of steps taken to correct violations noted in IE insp Repts 90-269/80-17, 50-270/80-12 & 50-287/80-11 LEMISR C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/08/26 ip
- --8009100807 Responds to NRC 800523 ltr re violations noted in IE Insp Rigts 50-269/80-17,50-270/80-12 & 50-287/80-11 Corrective actions incidents involving failure to perform survelllance are being reviewed & new procedures will be established PARKER.N O Dute Power Co 80/06/23 3pp.
- --8099100811 Forwards 1E Insp Repts 50-269/80-17.50-270/80-12 & 50-287/80-11 an 800401-30 & notice of violation LENIS,R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/05/23 2pp
- --BOC9100BI3 Notice of violation from insp on 800401-30
 # Region 2, Atlanta, Office of the Director 80/05/23 lp
- --B009100B16 IE Insp Repts 50-269/B0-17.50-270/B0-12 & 50-287/B0-11 on B00401-30 Moncompliance noted fallure to submit 30-day repts when surveillance test frequency was missed MARTIN,R D Region 2. Atlanta, Reactor Operations Nuclear Support Branch JAPE,F Region 4. Dallas, Office of the Director B0/03/23 (1pp
- 8007030605 Submits Revision 3 to util 70-day response to IE Bulletin 79 018 re Class IE equipment environ qualification Raychem heat shrink tubing, scotch Cast-0, transmitter O-ring seals & lubricating grease to be replaced during refueling outage THIES, A C Duke Power Co 80/08/27 2pp
- ECOS110659 Responds to IE Bulletin 80-15 Emergency notification system reviewed Sys is powered by onsite power, but does not have tackup ansite emergency power Emergency power supplied by telephone company
 PARKER, U D buke Power Co 80/08/27 2pp
- 8009120343 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover! 480 Volt Type K-6008 & K-DDN 6008 Circuit Breakers " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/27 io.
- 8009290297 Forwards IE Circular 80-21, "Regulation of Refueling Crews "
 No written response required
 D'REICLY, J P Region 2, Atlanta, Office of the Director 80/09/10
 50#
- 8009300816 Ack receipt of 800825 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-269/80-23, 50-270/80-20 & 50-287/80-17 LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/09/16 ip
- --8007300526 Forwards response to NRC 800730 ltr re violations noted in IE Imap Repts 50-269/80-23,50-270/80-20 & 50-287/80-17 Corrective actions informed operations personnel that use of correct & verified procedures must be ascertained PARKER.N O Buke Power Co 80/08/25 3pp
- --8009300630 Forwards IE Insp Repts 50-269/80-23 & 50-270/80-20 & 50-287/80-17 on 800602-30 & notice of violation LEWIS,R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 60/07/30 2pp

- --8009300631 Notice of violation from insp on 800602-30
 * Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/07/28 1p
- --8009300640 IE Insp Repts 50-269/80-23,50-2/0/80-20 & 50-287/80-17 Noncompliance noted use of Unit 1 procedure to perform periodic test on Unit 2 QRDERS.W. JAPE.F. Region 2, Atlanta, Office of the Director MARTIN.R D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/07/28 i3pp
- R Periodic operating reports & related correspondence
- 8009020044 Forwards "Radioactive Effluent Release Semiannual Rept." Jan-Jure 1980 PARKER.W O Duke Power Co 80/08/25 lp
- --8009020047 "Radioactive Effluent Rejease Semiannual Rept." Jan-June 1980 * Duke Power Co 80/08/25 App
- 8009090577 Forwards revision to "Radioactive Erfluent Reluase Semiannual Rept." Jan-June 1980 PARKER.W O Duke Power Co 80/09/03 App
- --8009090582 Revision to "Radioactive Efficent Release Semiannual Rept."

 Jan-June 1980

 * Duke Power Co 80/09/03 3pp
- BO09190462 Forwards monthly operating repts for Aug 1980 PARKER.W O Duke Power Co 80/09/15 1p
- ---8009190473 Monthly operating repts for Aug 1980 REAVIS, J A Duke Power Co 80/09/15 17pp
- S Reportable occurrences, LERs & related correspondence
- 8009150393 Updates RO-287/80-il re cracked studs on gove-through steam generator manuay BSM has completed examination of three cracked studs Final results will be documented in rept for util by mld-Sept PARKER, W O Duke Power Co 80/09/08 5pp
- B009180395 Forwards LER 80-009/01F-2 PARKER, W D Duke Power Co 80/09/12 6pp
- --8009180409 LER 8D-009/01T-2 on 800710.after reactor trip, relay in A phase of normal source voltage monitor circuit of emergency power switching logic falled Caused by reactor trip & auxiliary power transfer Relay replaced & returned to syc PHILPOTI.F T Duke Power Co 80/09/12 ip
- B009260450 Forwards LER 80-012/01T-0 PARKER, U D Duke Power Co 80/09/22 3pp
- --8009260455 LER 80-012/01T-0 on 800909 discovered boron analysis on concentrated boric acid storage tank was not conducted as required Caused by personnel error Min concentration verified & appropriate disciplinary action taken JONES, J. L. Duko Power Co. 80/09/22 lp
- T Hearing transcripts on non-antitrust matters
- 8009260313 Bubmittal of prepared testimony for first hearing session No attempts made to provide complete answers to ASLB 800908 memorandum & order re physical separation of TMI units Certificate of Syc enci Related correspondence TROWBRIDGE OF Metropolitan Edison Co TROWBRIDGE OF Shaw, Pittman, Potts & Trowbridge 80/09/19 7pp
- ---8007260366 "Small Break Operating Guidelines" Related correspondence
 4 Babcock & Wikcox Co 49-1106001-00 79/11/30 48pp
- DOCKET SO-289 THREE MILE ISLAND NUCLEAR STATION. UNIT E
 F Securaty, medical, emergency & fire protection plans
- 8009230175 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency GRIER, B H Region 1. Philadelphia, Office of the Director 80/08/22 3pp

- 8009290077 Forwards comments on emergency plan indicating need for addl info 2 co-maitment to complete review Revision meeting NUREC-0654 evaluation criteria, must be provided within 45 days REID.R U Operating Reactors Branch 4 80/09/09 App
- Q Adjudicatory correspondence
- 8009260301 Memorandum laying out grouping & sequence of hearing issues analysis % mod of plant design & procedures separation of Units 1 & 2 emergency planning & preparedness mgt capability & financial qualifications Comments welcomed TROMBRIDGE, G F Ketropolitan Edison Co TROMBRIDGE, G F Shaw. Pittman. Potts & Trowbridge 80/07/18 11pp
- 8009160590 Requests that testimony re emergency preparedness for TMI-1 restart hearings be submitted as soon as possible GRIMES, B.K. Emergency Preparedness Program Office 80/07/29 2pp
- 8009020273 Notifies that math re util 800729 filing u/PA Public Util Commission.petition for eitraordinary rate relief, transcripts of interim hearings & brief will be forwarded, per NGC 790921 & 1109 requests KETNER.M H. Metropolitan Edison Co. 80/08/20 1p
- 8009110528 Forwards NUREC-0578, NUREC-0585, NUREC-0680 & NUREC-0694 Represents V Taulic Co of America, petitioners in TMI-1 restart proceeding M/o encls SOUDER, J L Division of Rules and Records 80/08/21 lp
- 800702042i Forwards Exhibits JC-O, JC-H & index of exhibits filed on 800920 % 21 to keep NRC informed of significant regulatory developments affecting General Public Utils companies SWEENEY-L E Jersey Central Power & Light Co 80/08/22 17pp
- 8009020052 Suppl response in opposition to Victaulic Company of America late intervention Review of second prehearing conference transcript 8 encl 800822 Harrisburg Evening News article indicates prior avareness of problem WCErtificate of Byc SHGLLY/S C Affiliation Unknown 80/08/23 8pp
- 8007020407 Revision of Contention 5 per ASLB 800820 order Specifies aspects demonstrating that licensee is not technically qualified to operate facility re safety-related maint & repair Certificate of Svc encl WIDDFF.M P Three Mile Island Alert WIDDFF.M P Widoff, Reager, Sekouttz 2 Adler 80/08/26 300
- E007080332 Forwards info re costs of purchasing energy, in response to NRC 770921 & 1109 requests for info re significant developments affecting General Public Util companies in restart proceeding SMEENEY, L.E. Jersey Central Power & Light Co. 80/09/26 66pp
- 8009050427 Motion for supplemental interrogatories & request for documents directed to incenses & based on new info revealed in Met Ed publication "TMI Today." Aug 1980 issue,Page 2 Certificate of Svc encl SHCLLY.S C Affiliation Unknown 80/08/27 Spp
- 8009040278 Response to licensee interrogatories re Revision 2 of emergency plan Addresses evacuation conditions; staging area provisions; receiving points for patients & participation of surrounding counties Certificate of Svc encl CURNINGHAM, J D Reuberry Township, York Haven, PA CUNNINGHAM, J D Foz, Farr & Cunningham 80/08/28 9pp
- 8007050425 Motion for correction of record to include failures of instruments & equipment outside containment that contributed to TM1-2 accident Focuses on TM1-2 fuel pool which may endanger TM1-1 aperation

 LEWIS.K 1 Affiliation Unknown 80/08/28 3pp
- 8009040358 Response to ASLB 800820 order re UCS motions for summary disposition Suggests 800910 for response to motion on Contention 5 % 801001 for responses to motion on Contention 13 Certificate of Svc enci WEISS, & R Union of Concerned Scientists WEISS, & R Sheldon, Harmon & Weiss 80/08/29 3pp
- 8007040361 Inquires whether Subparagraph d to Antinuclear Group Representing took Contention 4 was filed w/ASLB.re licensee diagnostic & analysis work Transcript of 791i10 prehearing conference inficated addition at Pages 597-597 MDRAN.D M Atomic Safety and Licensing Board Panel 80/08/29 is
- 8009110450 Notifies of delay in Sept 1980 hearing re restart proceedings NRC is not prepared on first five items in NRC 790809 order Requests cooperation in assuring that further delays are obviated SHAPAR, H K Office of the Executive Legal Director 80/08/29 2p

- 8009160169 Suppl to 800804 response to licensee interrogatories re emergency plan in local counties Plans do not address evacuation during significant population changes Certificate of Svc enct SHOLLY, & C Affiliation Unknown 80/08/29 Spp
- B009260592 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by B01101 REIO.R W Operating Reactors Branch 4 B0/08/27 App
- --8009260597 Order for mod of License DPR-50 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment info should be submitted by 80101
 EISENIULD G Division of Licensing 80/08/29 6pp
- 8009040227 Motion for clarification of ASLB questions at 800812-13 prehearing conference Addresses HPI sys pump operation to dissipate docay heat & feedwater sys vulnerability to nonsafety-grade sys WiCertificate of Syc SINGER.L N Hearing Branch 2 80/09/02 App
- 8009040365 Response to UCS 800817 ltr seeking reconsideration of ASLB 800812-13 prehearing conference ruling which denied UCB motion for summary disposition Discusses UCS facts which do not entitle UCS to favorable decision W/Certificate of Svc 1RDUBRIDGE, G F Metropolitan Edison Co TROUBRIDGE, G F Shaw, Pittman, Potts & Trowbridge 80/09/02 9pp
- 8009050420 Memorandum & order denying Victaulic Company of America 800813 petition to intervene on grounds of lateness & lack of standing SMITH: I W Atomic Safety and Licensing Board Panel 80/09/02
- E009100431 Memorandum advising that SC Sholly will inspect licensee control room mock-up in lieu of 800827 request to suppl discovery re new info in TMI Today 800826 article Sholly 800827 request withdrawn Certificate of Svc encl TROMBRIDGE. OF Metropolitan Edison Co TROMBRIDGE, O F Shaw. Pittman, Potts & Trowbridge 80/09/03 5pp
- 8009120226 Response to licensee interrogatories re emergency plan.
 Revision 2 Testimony ro Midas radiological assessment sys
 must be provided by licensee Supporting documentation &
 Certificate of Svc enci Related correspondence
 PELL.D M Anti-Nuclear Group Representing York PELL.D.M
 Peil.D M 80/09/03 12pp
- 8009;20232 Application for subposna duces tecum directed to RL Curry of York County Emergency Mgt Agency to give 8009;7 deposition & to bring log of 8007;10 test exercise Affidavit & Certificate of Svc encl Related correspondence, PELL.D M. Anti-Nuclear Group Representing York PELL.D M. Pell.D M. 80/07/03 7pp
- B009090249 Response stating no objection to TMI Alert 800B08 motion seeking free copy of hearing transcript ASLB 800B15 memorandum & order authorized such supply Certificate of Byc encl
 SINGER.L N Hearing Branch 2 80/07/04 4pp
- 8009ii0394 Forwards responses to NRC 790921 & 1109 requests for info re significant regulatory developments affecting General Public Utils companies in restart proceeding Federal executive agencies & rate coursel data requests and SWEENEY.4. E Jersey Central Power & Light Co 80/09/09 23pp
- 8009110020 Rotice advising that beginning 600915, discovery reading room will be spen upon 24-h advance notice Room will be permanently closed on 801015 Hearing documents will be maintained in vicinity W/Certificate of Svc BLAKE, E.L. Metropolitan Edison Co. 80/09/08 5pp
- 8009110799 Memorandum & order forwarding contentions & ASLB questions to be heard at 801015 evidentiary hearing per ASLB 800815 memorandum & order. Directs parties to report corrections to contentions by 800915 Courtesy notification encl
 SMITH-I H Atomic Safety and Licensing Board Panel 80/09/08, 400a
- 8009160030 Revised emergency planning Contention B. incorporating significant developments re York County 800827 revised emergency plan & release of FEMA 800812 rept to US President Certificate of Bvc and SMCLLY.S C Affiliation Unknown 80/09/09 20pp

- E009160371 Forwards Public Advocates Ofc B00903 data request.Dept of Army B00821 ltr to State of NJ Board of Public Utils,JB Kirsten B00826 ltr to Judge Marshall & third info request of Faderal Executive Agencies re TMI-1 restart proceeding SWEENEY,L E Jersey Central Power & Light Co 80/09/08 lipp
- 8009180436 Second final amended contentions re util. York & Dauphin Counties' emergency plans York plan evacuation routes not uind-dependent Util plan unacceptable due to lack of siren warning sys Certificate of Svc encl CUNNINGHAM, J. D. Newberry Township TMI Steering Committee 80/09/08 330pp
- 8009110768 Response stating no objection to M1 Lewis 800826 request for hearing transcript. If limited to portions dealing w/Lewis contention Objects to request re reconsideration of status as intervener.

 SINGERL N Hearing Branch 2 80/09/10 7pp
- 80091f0791 Response stating no objection to Environ Coalition on Nuclear Power 800822 request for free transcripts if limited to 1-yr period starting 800725 ASLB not empowered to provide same for other than stated period W/Certificate of Bvc SINGERL N Hearing Branch 2 80/09/10 5pp
- BOOP150041 Request for extension until 10 days after responses to UCS BOORDS motion are summary judgment for UCS to file direct testimony on Contention of Contention does not relate to safety issues & has no hearing impact W/Certificate of Svc HEISS,E R. Union of Concerned Scientists WEISS.E R. Sheldon, Harmon & Heiss. BO/07/10 3pp
- B009170291 Responds to NRC 800921 & 1109 data requests re restart proceeding Forwards Administrative Law Judge recommended decision, Commission 800828 final order & PA Public Util Commission 800729 order initiating investigation KEINER, M H Metropolitan Edison Co 80/09/10 25pp
- BOOPIBOI31 Advises of issuance of Amend 57 to OL, revising ECCS design & surveillance requirements Mods to ECCS design involve astists re restart proceeding CUTCHIN.J M Hearing Branch 3 80/09/10 2pp
- 8009160534 Kemorandum & order requesting normal svc of written testimony & exhibits per ASLB 800815 order Extra cupies of cross-exemination matl must be brought to hearing Free trenscripts denised for prehearing & granted for hearing SMITH. I W Atomic Safety and Licensing Board Panel 80/09/11 3pp
- BO09170219 Request for extension until 801015 to respond to ASLB 800908 memorandum & order re UCS Contentions 6.8 & 12 Certificate of 8vc encl TROUBERIDGE, 0 F Metropolitan Edison Co TROUBERIDGE, 0 F Shaw, Pittman, Potts & Troubridge 80/09/(1 5pp
- 8009170302 Response in opposition to UCS 800910 request for extension to file direct testimony re Contention 3 Info needed to prepare testimony already filed by applicant & NRC Basis for estension obviated Cartificate of Bvc encl TRCMBRIDGE.O F Hetropolitan Edison Co TRCMBRIDGE.O F Shaw. Pittman, Potts & Trowbridge 80/09/11 5pp
- BOO918057) Second amended final addl Contentions 12,13,16,17,18 & 17 re Dauphin County emergency plan Plan deficient due to lack of Long-karm mot planning Affidavit & Centificate of Svc encl CURNINGHAM.J D. Newberry Township TMI Steering Committee 80/09/11
- BO09160139 Response in support of licensee 800825 request to dismiss Environ Coalition on Nuclear Power Contentions 2-4,2-7,2-11, 2-13,2-20/2-30,2-26 & 2-28 due to failure to respond to applicant 800729 interrogatories. Certificate of Svc ancl GRAY, J R Hearing Branch 1 80/09/12 5pp
- 8009170137 Memorandum & order granting licensee motion to compel Environ Coalition on Nuclear Power response to 800727 interrogatories re emergency plantRevision 2 Licensee may move for dismissal if answers are not filed in 10 days SMITH. [U Atomic Safety and Licensing Board Panel 80/09/12 2pp
- BOO9170182 Memorandum & order granting extension until 10 days after svc of NRC or licenses testimony for UCB to file written testimony re Contention 5 Licenses & NRC written testimony may be filed by 801015 Addl extensions will be considered SMITH I W Atomic Safety and Licensing Board Panel 80/09/12 2pp
- BOOG170198 Mamorandum specifying ASLB questions to be addressed by NRC & licensee prior to & at hearing Questions of ASLB 800908 mamorandum & order will be heard at first hearing segment Other parties may respond to questions if interest affected SHITH, I N Atomic Safety and Licensing Board Panel 80/09/12 9pp

- 8009170122 Forwards safety evaluation & Amend 58 to License DPR-50, revising Tech Specs on mot reorganization in shutdown status Changes may be modified by ASLB W/d encls SWANSON, D T Hearing Drench 1 80/09/19 1p
- 8009170165 Response in support of Antinuclear Group Representing York B00903 application for issuance of subpoena for RL Curry deposition Urges reasonable date for examination after 800917 Certificate of Svc encl GRAY, J R Hearing Granch 1 80/09/15 7pp
- 8009170254 Request for add1 time to file testimony Info must be coordinated among witnesses Affected parties except Environ Coalition on Nuclear Power will not file testimony prior to NRC filing
 TOURTELLOTTE, J. Hearing Branch 4 80/09/19 1p
- --8009170256 Affidavit forwarding schedule for NRC testimony which will be filed on 800925 re core cooling & during Sept-Oct 1980 re equipment design & mods Certificate of Svc encl NOVAX.T K Assistant Director for Operating Reactors 80/09/15 500
- 8009180557 Memorandum & order granting State of PA extension until B01006 to present position on emergency planning contentions SMJTM, I W Atomic Safety and Licensing Doard Panel 80/09/15 ip
- 8009230639 Request for 45-day extension to file direct testimony on Contention V(D) re emergency filtration of containment, due to change of coursel & involvement in answering interrogatories
 PELL.D N Anti-Nuclear Group Representing York 80/09/15 2pp
- 8009230628 Advises that York,PA LPDR will be closed on 800929 York TM1-1 & 2 documents will be available at restart hearing NRC must be informed by 800924 if parties object to course of action BWARTZ,L L. Antitrust Division 80/09/16 3pp
- BOO926017S Forwards info containing significant regulatory developments affecting General Public Util companies re restart proceeding Info consists of responses to Rate Counsel, FEA & DDD requests
 SWELNEY, L E Jersey Central Power & Light Co BO/09/16 Sipp
- B00922040B Memorandum & order granting indefinite extension for NRC & intervenors to file testimony on UCS Contention 7. Shelly 6(b) & 15 & Antinuclear Group Representing York V(B) & V(C) Util response to emergency planning may be filed on B00919 SMITH.I W Atomic Safety and Licensing Board Panel B0/09/17 2ρρ
- 8009220411 Memorandum supplementing ASLN 800820 memorandum & order in which UCB motion for summary disposition of Contentions 5 & 13 was denied Cites & discusses authorities in support of ASLB discretionary action questioned by UCB SMITH, I U Atomic Safety and Licensing Board Panel 80/09/17 3pp
- 8009230024 Memorandum & order directing NRC to report suggested schwdule for remainder of proceeding NRC written testimony on contentions & issues must be filed by 800925 & 1002 Rept re fallure to file timely testimony may be made on 801010 SMITH, I (4) Atomic Safety and Licensing Board Panel 80/09/17 7pp
- 8007230449 informs NRC of significant regulatory developments Affecting General Public Utils companies Administrative Law Judge S Harshell initial decision encl SWEENEY.L E Jersey Central Power & Light Co 80/09/17 5pp
- BO07230434 Forwards Exhibits JC-600 & JC-601 filed in restart proceeding Includes LS Reis testimony & "Certain Data Used in Determination of Fair Rate of Return." prepared by Reis & Chandler, Inc SWEENCY, L E Jorsey Central Power & Light Co 80/07/18 44pp
- 8009250017 Response to contentions re emergency plan, Revision 2 Antinuclear Oroup Representing York Contention IIJA(L) untimely No new info presented in Newberry & SC Sholly contentions Certificate of Bvc encl ZAHLER, R E Metropolitan Edison Co ZAHLER, R E, Shaw, Pittman, Potts & Troubridge 80/09/18 13pp
- 8007240535 Submits list of people to be subpoonaed re Contention 5 & identifies work requests, maint log books & payroll register to be subpoenaed Brief Justifying subpoenas enci Rolated correspondence

 ADLER, T A Widoff, Reager, Selkowitz & Adler 80/09/19 2pp
- --8009240936 Outlines planned DJ Bonetti testimony re Contention 5 & work request summaries Related correspondence # Widorf, Reager, Seltowitz & Adler 80/09/19 2pp

- --8009240538 Brief justifying subpoends re Contention 5 Work request logs & Certificate of Svc enct Related correspondence ADLER,T A Metropolitan Edison Co ADLER,T A Widoff, Reager, Seltowiti & Adler 60/09/19 70pp
- 800924053: Forwards NRC subpoens for the upon AL Curry Cites appearance time discrepancy between recipient request & subpoens Related correspondence
 SMITH.: U Atomic Safety and Licensing Board Panel 80/09/22 ip
- --8009240532 Subpoons requiring appearance of RL Curry for 801002 oral exam Related correspondence
 SMITH, I W Atomic Safety and Licensing Board Panel 80/09/22
- B009260666 Request for extension until mid-Oct to respond to licensee interrogatories per ASLB 800932 order to compel Issues of emergency planning & evacuation plans will not be subj of hearing until substantially later N/Certificate of Svt JBHNSRUB.J H Environmental Coalition on Nuclear Power 80/09/22
- 8007300010 Motion for 2-wk extension to reply to ficensee emergency planning interrogatories in response to ASLB 800712 order to compel intervenor representative unreachable due to absence for personal matter Certificate of Svc encl PERKINS.J Environmental Coalition on fuclear Power 80/07/22
- 80093000ii Forwards util 800916 inter-ofc memo organizing ASLB 801014 tour to facilities Syc list encl Related correspondence BLAXE.E L. Shau, Pittman. Potts & Trowbridge 80/09/22 7pp
- 8009300629 Motion for appointment of independent experts to determine questions of safety-related maint Bases request on Kemeny Commission rept.Vol IV.Page 106 & on NRC practices not assuring proper maint procedure Certificate of Evc encl ADLER.T A Three Mile island Alert ADLER.T A Hidolf, Reager, Selkowit; & Adler 80/09/22 3pp
- --8009300632 Motion for right to submit surrebuttal testimony TMI Alert case must be presented out of sequence prior to IRC safety evaluation on maint issue-per ASLB previous ruling Centificate of Svc encl ADLER.T A. ADLER.T A. Three Mile Island Alert 80/09/22 3pp
- 8009260903 Response in opposition to portions of Newberry Township TMI Steering Committee Contentions 13 & 15 & all of Contentions 12.13 & 29 Does not object to 600998 & 11 contentions Requests status of prior contentions re-emergency planning ORAY, J R Hearing Branch 1 60/09/23 App
- --8009260004 Response in opposition to Environ Coalition on Nuclear Power 80090B revised wmergency planning Contentions 2-2 & 2-4 Intervenor should be permitted to adopt 8C bholly revised Contention B-1 H due to similarity & adequate specificity GRAY, J R Hearing Branch 1 80/09/23 App
- --8009260006 Response stating no objection to 86 Sholly 800908 revised emergency planning contention Opposes admission of Portions 8 | 8(4).8 | 9(14)-(23).8 | L & B | II | A Certificate of 8vc encl ORAY.J R | Hearing Branch | 1 | 80/09/23 | 11pp
- 8009260645 Memorandum % order granting extension until E01003 for Antinuclear Group Representing York to file J Bayea testimony NRC & licenses may file cross-ecamination by 801015 Requests for relief will be considered if prejudiced SMITH I W Atomic Safety and Licensing Board Panel 80/09/23 2pp
- 8007300022 Response in opposition to Environ Coalition on Nuclear Power 800717 motion for additione to respond to licensee interregatories re emergency planning Good cause not shown Certificate of Svc enc! ZAHLER.R E Metropolitan Edison Co ZAHLER.R E Show, Pittman, Potts & Troubbridge 80/09/23 Spp
- 8009300617 Response in opposition to licensee B00918 objections to portions of revised emergency plan Contention B Contention arose from discovery on Contention 4 which revealed new problems re radiation dose reading w//certificate of Syc SHCLLY.8 C Affiliation Unknown 80/09/23 14pp
- 8009300003 Memorandum & order re TH1 Alert Contention 5 Intervenor plan to offer 1.100 work orders unrealistic Burden of proof re pattern of deferred maint falls on Licensee, Fifty work orders must be designated by 801003 Bets testingny filings SMITH.I W Atomic Safety and Licensing Board Panel 80/09/24 App

- G009300006 Memorandum & order directing Environ Coalition on Nuclear Power to respond to util interrogatories re emergency plan, by B01016 Intervenors' responses to util & NRC objections to emergency planning contentions shall be filed by B01016 SMITH.1 W Atomic Safety and Licensing Board Panol 80/09/24 2pp
- 8009300015 Forwards 18 subpoends directed to util employees for evidentiary hearing appearance per 800923 telcon & ASLB 800924 memorandum & order SMITH.1 17 Atomit Safety and Licensing Board Panel 80/09/24 ip.
- 8009300020 Request for extension until 801030 to file cross-examination plans per ASLB 800015 memorandum & order Urges further extension until 801103 for hand-delivery filing Certificate of 8vc encl TROUBRIDGE, G F Metropolitan Edison Co TROUBRIDGE, G F Bhaw. Pittman, Potts & Troubridge 80/09/24 4pp
- 8009300417 forwards UCS direct testimony on Contentions 3 & 10 re restart hearing Also forwards UCS interrogatories to NRC based on new info Testimony on Contention 5 will be provided pending receipt of NRC testimony WEISS.E R Sheldon. Harmon & Weiss 80/09/25 ip
- --8007300420 Direct testimony of RD Pollard on behalf of UCS re UCS Contention 3 POLLARD, R D Union of Concerned Scientists 80/09/25 18pp.
- ---8009300422 Direct testimony of RD Pollard on behalf of UCS re UCS Contention 10 PDLLARD, R D Union of Concerned Scientists 80/07/25 25pp
- --8009300423 UCB interrogatories requesting clarification of NUREO-0578 based on new info. HEISB.E R Union of Concorned Scientists WEISB.E R Sheldon, Harmon & Weiss 80/09/25 10pp
- 8009300315 Question 11 directing licenses & NRC to present evidence that Page A-45 requirements of NUREO-0578 are met ASLB not satisfied w/NRC findings in SER re Recommendation 2 1 9 C on transients & accidents SMITH.18 Atomic Safety and Licensing Board Panel 80/09/26 Lp

H General correspondence

- 8009110642 Responds to Jonke 800218 ltr to President Carter expressing concerns re delay in TMI-1 return to svc & rate structure NRC has ordered that public hearings be conducted to determine whether facility should be operated REID.R W. Operating Reactors Branch 4 80/07/10 Spp
- 8009220205 Responds to LF Wirth 800323 itr to President Carter expressing concerns to delay in TML-1 return to svc & rats structure NRC has ordered that public prehearings be conducted to determine whether facility should be operated REID.R W Operating Reactors Branch 4 80/07/10 2pp
- 8007090212 Responds to 800527 postcard re delay in returning facility to operation Public hearing to address issues appropriate to public health & safety scheduled for Fall 1980 REID.R U Operating Reactors Branch 4 80/07/15 ip
- --B007090216 Expresses concern for delay in returning facility to operation Nuclear power essential to economic health of country & state DULANNV R Affiliation Unknown 80/05/27 1p
- B007i10637 Responds to CP Cole B00214 itr to President Carter expressing concerns re rate structure NRC has ordered that public hearings be conducted to determine whether facility should be operated REID,R W Operating Reactors Branch 4 80/07/25 App
- 8009220188 Responds to LE Adam 800502 ltrs expressing concerns re delay in TMI-1 return to see NRC has ordered that public hearings be conducted to determine whether facility should be operated REID, R K Operating Reactors Branch 4 80/07/25 2pp
- --8009220190 Expresses concerns re delay in placing TMI-1 back into evc & rate structure prescribed for Met Ed ADAM.L E Affiliation Unknown 80/05/02 2pp
- 8009220198 Responds to J Folk 800520 ltr expressing concerns re delay in TKI-1 return to svc NRC has ordered that public hearings be conducted to determine whether facility should be operated REID, R W Operating Reactors Branch 4 80/07/25 2pp

- --8009220200 Expresses concerns re delay in placing TMI-1 back into svc FOLK, J Affiliation Unknown 80/05/20 3pp
- 8009220201 Responds to O Albert 800510 ltr expressing concerns re delay in TMI-1 return to svc NRC has ordered that public hearings be conducted to determine whether facility should be operated REID.R & Operating Reactors Branch 4 80/07/25 2pp
- -8009220209 Expresses concorns re delay in placing TMI-1 back into ave ALEERT.O Affiliation Unknown 80/05/10 2pp
- 8039220202 Responds to L. Lesh 900725 Itr expressing concerns re delay in TMI-1 return to svc & rate structure prescribed for Met Ed NRC has ordered that public hearings be conducted to dateraine whether facility should be operated REID.R N Operating Reactors Branch 4 80/07/25 2pp
- ---8009220211 Expresses concerns re delay in placing TMI-1 back into eve to rate structure prescribed for Met Ed LESH.L Affiliation Unknown 80/03/25 2pp
- 8009220203 Responds to E Knausman 800331 Itrs to President & NRC supressing concerns re deiay in TM1-1 return to svc NRC has ordered that public hearings be conducted to determine whether facility should be operated PEID.R W Operating Reactors Branch 4 80/07/25 4pp
- --8009220207 Expresses concerns re delay in placing TMI-1 back into svc KNAUSHAN, E Affiliation Unknown 80/03/31 2pp
- 8007020465 Responds to postcards re release of Kr-83 Potential public health impact from using any proposed strategies for removing Kr-83 is negligible Purging method is quickest & safest for workers to accomplish SNYDER.B J TMI Program Office 80/08/11 20p
- --8009020472 Expresses concern re release of Kr-85 from facility (IL. should be revoked Health of local people being damaged PETROSXY, J A Affiliation Unknown 80/08/26 2pp
- 8009030678 Responds to 8002i5 itr urging revocation of util OL & germanent shutdown of facility Commission has ordered public hearing to determine if facility should be operated Forwards order outlining issues re public health & safety W/o encl SNYOER.B. J TMI Program Office 80/08/ii ip
- --8009030&80 Urges revocation of util QL & permanent shutdown of facility due to threat posed to public health & safety ALIMOUSE,V Affiliation Unknown 80/02/15 ip
- B0070306BI Responds to 8002i5 ltr urging revocation of util OL & permanent shutdown of Facility Commission has ordered public hearing to determine facility operation Forwards order outlining issues re public health & safety H/o encl SKYDER, B. J. TMI Program Office 80/09/11 ip
- --8007030483 Urges revocation of util OL & permanent shutdown of facility due to threat pased to public health & safety SMEENEY, A A Affiliation Unknown 80/02/15 3pp
- B009100062 Responds to 791206 ltr re TMI cleanup operations Commission issued order on 800612 for temporary mod of license, authorizing controlled purging of Kr-85 from reactor bldg atmosphere ENYDER, B J TMI Program Office 80/08/11 2pp
- 8009230143 Responds to 800806 ltr urging expeditious restarting of facility No action will be taken until completion of public hearing re facility .

 [NGRAM.F Office of Public Affairs 80/08/13 lp
- --8009230148 Urges restarting of facility NRC is being unfair to util & ratepayers by delay
 FRANCIS.Q P. Affiliation Unknown 80/08/06 lp
- 8009020293 Responds to 800212 telegram to President Carter requesting action to prevent major disaster at nuclear station Studies have resulted in add] licensee requirements SNYDER.B J TMI Program Office 80/08/14 3pp
- ©007020279 Responds to 800329 ltr expressing concerns re nuclear energy & apposing venting of radioactive gases & release of contaminated water Forwards summary of NUREO-0539, re population dose & health impact, & other mgtl W/o encl SNYDER, B J TMI Program Office 80/08/14 4pp

- --B009020304 Expresses concerns re nuclear energy Opposes venting of radioactive gases & release of contaminated water ROGERS.L Affiliation Unknown B0/03/29 3pp
- BOD9090350 Urges that period for comment of EIB be extended for period not less than 90 days WALTERS.P W. NALTERS.H D. Affiliation Unknown B0/0B/14 lp
- 800910006B Responds to 790B16 ltr to President Carter re release of radioactive math from facility Only low or nondetectible levels currently permitted to be released Disposal of water processed by EPICOR-II to be discussed in programmatic E18 SKYDER. N J TMI Program Office 80/0B/14 3pp
- --8007100074 Forwards C Whitney 770816 ltr & newspaper article for proper handling RATHKOPF,C L. Energy, Dopt of 79/09/21 4pp
- 8009020488 Responds to encl L Octive 800321 telegram to President Carter re health effects of radiation from TMI Team of Investigators has concluded that health effects from TMI accident represents minimal risk to offsite population SNYDER, B J TMI Program Office 80/00/t5 2pp
- BOO9050366 Responds to BOO225 itr to First Lady re continuing operation of facilities Public hearing to be held to determine if facilities should be operated & conditions of restart W/o Commission 790809 order SNYOER.S J TMI Program Office 80/08/15 2pp
- 8009220049 Responds to enci 800905 ltm to President Camber organg revocation of facility OLs Public hearing will be held refuture operation of Unit 1 Licensee has not yet submitted proposal for overall recovery of Unit 2 BRYDER: II J THI Program Office 80/00/15 4pp
- 0009030432 Forwards JW Zoller 900918 ltr urging that NRC return facility to operation as soon as possible after reasonable safety imps
 GGODLING, B Pennsylvania, State of 80/09/18 1p
- 8009090022 Responds to 800815 ltr urging expeditious reopening of facility Commission has directed that facility be kept in shutdown condition pending further order Evidentiary phase of public hearing re-facility has not yot started INGRAM.F Office of Public Affairs (0/00/20)p
- --B007090024 Urges expeditious restarting of facility Cost of Soying electricity by util is being passed on to ratepayers ITSCHNER.L C Affiliation Unknown G0/00/15 ip
- 8009:50324 Responds to 79070: ltr to NRC so TML accident Commission has ordered public hearing to determine whether TML-i should be operated Communication difficulties attributed to impairment of info free control room to offsite groups SNYDER. B J TMI Program Office 80/00/22 App
- --8009190327 Expresses concern re TMI accident Util deliberately deceived public in crucial days fellowing accident & should not be allowed to reopen TMI-1 WOODLEY, 8 E. Affiliation Unknown 77/07/01 4pp
- 8009150330 Responds to 800326 ltr re reopening of THI Licenses has not submitted proposal for overall recovery of Unit 2 NRC 790702 order directed Unit i to remain in cold shutdown, pending outcome of restart hearing SNYDER, B J THI Program Office 80/08/22 2pp
- --8009150336 Requests cleanup & reopening of TMI RABUCK:9 Affiliation Unknown 80/03/26 App
- 8009150343 Rosponds to 16r to NRC re reopening of THI facilities Public hearing will be held re TMI-1 restart Licensee has not submitted proposal for overall recovery of TMI-2 SNYDER.B J TMI Program Office 80/00/22 2pp
- --B609150346 Expresses desire for TMI restart. Util followed all notification procedures on 790928 NRC & util should be supported in cleanup apelation EMITH. J W. Affiliation Unknown 80/08/22 2pp
- 8007iA0101 Responds to encl 79103| Itr to President Carter relactions taken at TMI Licensees of all operating plants utilizing PMRs have been instructed to take actions relators of equipment procedures & facility designs
 SNYDER.B J TMI Program Office 80/08/P2 4pp

- 8009170297 Responds to 800215 itr urging revocation of util OL NRC has ordered public hearing re TMI-1 restart Util has not submitted proposal for overall recovery of Unit 2 SNYOER. B. J. TMI Program Office 80/08/22 19
- 8009170271 Responds to encl 800411 ltr to President Carter re safety of TMI vicinity NRC.EPA & HEW investigations have shown offsite dose associated w/radioactive matl released from 790928-0429 represents minimal Tisk SNYDER.B J TMI Program Office 80/08/22 3pp
- E009230194 Responds to ltr urging revocation of util OL NRC has ordered public hearing to determine Unit 1 operation feasability & possible restart conditions Licensee has not submitted proposal for overall recovery of Unit 2 SNYDER.D J THI Program Office 80/08/22 Ip
- --8009230202 Urges revocation of util OL BRISCOE.G A Affiliation Unknown 80/08/22 ip
- 800915032: Responds to postcard re safe decommissioning of nuclear reactors & studies of reactor health effects Specific NRC actions include employment of full-time inspectors at TMI, licensee instruction & emergency preparedness planning SNYDER.B J TMI Program Diffice 80/08/25 2pp
- --8009150325 Requests safe decommissioning of all commercial nuclear reactors 3 performance of health impact studies to determine effects of nuclear energy KELLY, K. Affiliation Unknown 80/08/25 2pp
- 6009170004 Responds to 790810 ltr re accident at TMI NRC has ordered public haaring to determine whether TMI-1 should be operated & under what conditions restart would take place Licensee has not yet submitted proposal for overall recovery GNYDER BJ TMI Program Office 80/08/26 3pp
- ~-8009170011 Urges NRC to restore feeling of normalcy to community around TMI Recommends that NRC wait until all investigations are completed before respening TMI-1 Any premature opening would suggest that economics come before public safety H-IVLY, B J Affiliation Uninoun 79/08/10 Opp
- 8009260200 Responds to 8003il ltr to President Carter re delay in placing TMI-8 back into svc & rate structure prescribed for util Public hearing on restart scheduled to begin in Fall 1980 to determine whether facility should be operated REID.R U Operating Reactors Branch 4 80/09/09 4pp
- 8009290386 Responds to 800805 ltr re delay in placing TMI-1 back into svc Commission orders of 800702 directed unit remain shutdown & restart hearing conducted on 801015 DENION, HR Office of Nuclear Reactor Regulation, Director 80/09/10 ip
- --6009290389 Requests TM1-1 be allowed to return to svc TREAT, E H Affiliation Unknown 80/08/05 lp
- BO09300159 Responds to 1tr re excessive electric bill NRC does not set rates that utils charge for electricity Accident at Unit 2 also caused Unit 1 to be shut down Excerpt from DDE rept encl
 DENION-H R Office of Nuclear Reactor Regulation, Director BO/097/15 Opp
- --8009300163 Expresses concern to high util bills People on fixed incomes cannot afford cost of energy FAS10,F Affiliation Unknown 80/09/15 lp
- 8009230441 Responds to ltr re J Zoller request for prompt return of facility operation Public hearing ordered to determine facility operability Based on proceeding status development of record for restart decision not expected before 1981 KAPMERER.C Office of Congressional Affairs 80/09/18 2pp
- -8009230442 Requests response to encl J Zoller Itr requesting prompt return of famility operation GDDDLING, B House of Rep. 80/09/18 2pp
- Financial information
- 1009030201 Ack receipt of 790921 & 1205 financial info & forwards request for addl info to account for subsequent developments re financial plan & cost estimates

 NOVAK.T M Assistant Director for Operating Reactors 60/08/11

- 8009020428 Forwards State of NJ Rate Counsel latest data request to top NRC informed of significant regulatory developments affecting General Public Utils companies Kirsten, Friedman & Cherin 800818 forwarding Itr also encl SMEENEY,L E Jersey Central Power & Light Co 80/08/20 7pp
- 8009090602 Summary of 800814 meeting w/Met Ed & General Public Utils (OPU) at NRC re-GPU financing plan over next iO yrs Basis for plan: "Financial Forecast Reflecting Revised Estimate of TMI-2 Clean-up & Recovery" encl
 SILVER, H Operating Reactors Branch 4 80/08/26 5pp
- --8009090608 "Financial Forecast Reflecting Ravised Estimate of TNI-2 Clean-up & Recovery " Util 800808 press release encl + General Public Utilities - GPU Service Corp 80/08/14 4ipp
- 9007110374 Forwards responses to NRC 790921 & 1109 requests for info re significant regulatory developments affecting General Public Utils companies in restart proceeding Federal executive agencies & rate counsel data requests encl SWEENEY, L.E. Jersey Central Power & Light Co. 80/09/05 25pg.
- 8009290357 Forwards util 800908 ltr to 8 Marshall re metter of petition for increase in levelised energy cost adjustment charge.per NRC 790921 request for ongoing info re significant regulatory developments
 SWEENEY, L.S. Jersey Central Power & Light Co. 80/09/10 llpp
- 8009180370 Forwards Citibank, N A 800905 ltr notifying Oeneral Public Utils Corp of reduction in util credit availability,per 800910 telcon request CARRULL, D General Public Utilities OPU Service Corp 80/09/11
- BOD9260175 Forwards info containing significant regulatory developments affecting General Public Util companies re restart proceeding Info consists of responses to Rate Counsel.FEA & DOD requests

 BHEENEY, L. E. Jersey Central Power & Light Co. 80/09/16. 31pp
- 8009230434 Forwards Exhibits JC-600 & JC-601 filed in restart proceeding Includes LS Reis testimony & "Certain Data Used in Determination of Fair Rate of Return," prepared by Reis & Chandler, Inc.
 SMEENEY, L.E. Jersey Central Power & Light Co. 80/09/18 44p
- P Operating license stage documents & correspondence
- 8009150070 Responds to 800923 recommendations concerning lessons learned from 800226 transient at Crustal River Submits results of investigations re use of atmospheric dump valve at Ocones Units 19.AR Unit 1.Davis-Besse Unit 1 & TMI-1 DENION.H R Office of Nuclear Reactor Regulation, Director 80/07/21 2pp
- 8009020297 Submits interim criteria for shift staffling to all CL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D G Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREQ-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days. Proposed implementation schedule for meeting criteria of NUREQ-0696 encl H/o NUREQ EISENHUT, D © Division of Licensing 80/08/01 119pp
- BOO9230052 Informs that exemption from fee re licensing action associated w/TNI~2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D G Division of Licensing 80/08/07 60pp
- 8009030472 Forwards Revision 1 to 800521 "Process Control Program " Changes are based on discussions w/NRC HERBEIN.J 0 Metropolitan Edison Co 80/08/21 1p
- --8009030478 Revision 1 to "Process Control Program" re incontainer solidification.

 * Hittman Nuclear & Development Corp (subs Hittman Corp) 80/08/21 130p
- 8009050275 Forwards Tech Spec Pages 4-41 & 4-42 re ECCS, inadvertently amitted from 800728 Amend 56 to License DPR-50 REID,R () Operating Reactors Branch 4 80/08/22 4pp
- --8009050281 Tech Spec Pages 4-41 & 4-42 re ECCS, inadvertently amitted from 800728 Amend 56 to License DPR-50

 Operating Reactors Branch 4 80/08/22 2pp

-)9 Forwards commitment dates, as requested during 800725 exit meeting re near-term OL mgt review insp HERBEIN.J 0 Metropolitan Edison Co 80/08/25 2pp
- B009930421 Requests 45-day extension to comment period for programmatic EIS re TMI cleanup process Public hearing should be conducted prior to drafting of final version SHOLLY,S G Three Mile Island Public Interest Resource Center B0/08/27 2pp
- 8009030481 Forwards changed pages to 800807 Tech Spec Change Request 93 for License DPR-50 MERBEIN, J G Metropolitan Edison Co 80/08/28 ip
- --8009030487 Changed pages to 800807 Tech Spec Change Request 93 re mgt reorganisation 4 Metropolitan Edison Co 80/08/28 App
- BOOTOBO367 Informs NRC that Tech Spec Change Request 93 does not alter responsibility that util has for operation of unit MERBEIN, J G Metropolitan Edison Co 80/09/02 1p
- 8009120645 Forwards Amend 57 to License DPR-50, safety evaluation & notice of issuance & availability
 REID.R H Operating Reactors Branch 4 80/09/02 4pp
- ~-8009120548 Amend 57 to License DPR-50, revising Tech Specs to include surveillance requirements for high & low pressure safety injection sys
 REID.R W Operating Reactors Branch 4 80/09/02 50p
- ~-8009120450 Safety evaluation supporting Amend 57 to License DPR-50
 6 Office of Nuclear Reactor Regulation, Director 80/09/02 3pp
- ~-8009120453 Notice of issuance & availability of Amend 57 to License DPR-50 REID.R W Operating Reactors Branch 4 80/09/02 2pp
- 8009170037 Requests Class III fee for review of 800807 application for asend to License DPR-50 Organizational changes were considered to be of safety significance KILLER.W O License Fee Management Branch 80/09/02 1p
- 6009270242 Requests response schedule to coordinate review of open items identified in SER since issuance of NUREG-0680 REID.R W Operating Reactors Branch 4 B0/07/04 4pp
- 8009260559 Informs util that response to NRC 79:109 ltr re portions of ECCB evaluation models dealing w/fuel cladding swelling & incidence of rupture is acceptable Util has adequately confirmed representations made by fuel supplier.

 REID.R W Operating Reactors Branch 4 80/09/09 4pp
- BO09160329 Forwards response to B0070i ltr re TML-i fuel assembly holddown springs No feliad or damaged holddown springs identified BM investigations revealed no significant safety concerns HUKILL+H D Metropolitan Edison Co 80/09/10 iOpp
- BO09170292 Forwards response to NRC 790921 & 1109 requests for info re significant regulatory developments affecting General Public Utils companies in restart proceeding SHEENEY,L E Jersey Central Power & Light Co B0/09/10 3pp
- --B007170273 Ltr to all operating nuclear power plants re followup actions resulting from NRC review of implementation of THI-2 Lessons Learned Task Force short-term requirements Implementation schedule & exhibits encl EISENHUT.D 0 Division of Operating Reactors 80/09/13 77pp
- SOC9160367 Informs that Phase 2 rept by B&W reviewed & found applicable to TMI-1 Rept demonstrates ability of TMI-1 to withstand effects of asymmetric LOCA loads HUXILL, H D Metropolitan Edison Co 80/09/ii 2pp
- BOO9270155 Forwards human factors engineering control room design review Requests meeting during wk of 801006 to discuss, comment & suggest corrective actions REID,R W Operating Reactors Branch 4 80/09/16 12pp
- Q Inspection reports, IE Bulletins & correspondence
- 8009100875 Forwards IE Insp Rept 50-289/80-13 on 800509-0619 No mentempliance noted CARLSON,R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/21 2pp

- --8009100899 IE Insp Rept 50-289/80-13 on 800509-0619 No noncomp noted Major areas inspected licensee response to IE Bulletin 79-02, high pressure injected crossconnect mod & identification of safety-rolated sys & components CHAUDHARY, S. HOBREARTY, R. Region 1, Philadelphia, Office of Director EUNITER: 8 Region 1, Philadelphia, Reactor Constr & Engineering Support Branch 80/07/11 Spp
- 8009090237 Ack receipt of 800716 ltr informing NRC of steps taken correct violations noted in 1E Insp Rept 50-289780-05 BRUNNER:E J. Region 1. Philadelphia, Reactor Operations Noclea Support Branch 80/07/31 ip
- --8007070244 Forwards IE Insp Rept 50~287/80~05 on 800227-29 No noncompliance noted BRU4NER:E J Region i. Philadelphia, Reactor Operations Nucl Support Branch 80/06/12 2pp
- --8009090250 iE Insp Rept 50-289/80-05 on 800227-27 No noncomplia noted Deviation noted failure to incorporate recommended restart requirements into established engineering dept procedures GREENMAN.E Region 1, Philadelphia, Reactor Operations Nucle Support Branch NAPUDALO, PADLINGOR Region 1, Philadelphia Office of the Director 80/06/04 7pp
- 8009030044 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Gys of Operating Nuclear Power Plants Designed by C-E " Uritten response required GRIER, B H Region I. Philadelphia, Office of the Director 80/09/15 1p
- 8009180013 Forwards 1E Circular 80-18, "10CFR50 99 Safety Evaluat for Changes to Radwaste Treatment Bys " No written response required GRIER, B H Region i, Philadelphia, Office of the Director BO/08/22 1p
- 8007020013 Modifies 800814 response to 1E Bulletin 80-16 re poten misapplication of certian Rosemount Medels 1151 b 1152 pressure transmitters Four 1152 OF transmitters used w/A output code MERBEIN: J G Metropolitan Edison Co 80/08/25 3pp
- 8009120184 Forwards IE Info Notice BO-31. "Maloperation of Gould-Bover: 480 Volt Type K-6008 & K-DDN 6008 Circuit Breakers" No written response required GRIER, B H Region i. Philadelphia, Office of the Director 80/08/27 ip
- G009230790 Forwards IE Circular 80-21, "Regulation of Refueling C No written response required ORIER.B H Region 1, Philadelphia, Office of the Director 80/09/10 1p
- B009240316 Forwards IE Info Notice 80-32, "Clarification of Certa Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required ORIER, B H Region i, Philadelphia, Office of the Director B0/09/12 b
- R Periodic operating reports & related correspondence
- 8009090796 Forwards status rept for wk of 800810-16 CDLLINS,J T TMI Program Office 80/08/18 App
- 8007ii03i6 Forwards supplemental info to "Cffluent & Haste Dispos Semiannual Regt, Jan-June 1980," for IMI-1 & 2 & EPICOR-11 & supplemental info to "Effluent & Haste Semiannual Rept, 7910i5-123i," for EPICOR-11 HERBEIN.J O Metropolitan Edison Co 80/07/05 ip
- --B007i1031B Supplemental info to "Effluent & Waste Disposal Bemi Rept, Jan-June 1980" * Metropolitan Edison Co B0/09/09 Bpp
- ---8009110333 Supplemental info to "Effluent & Waste Disposal Semi Rept.Jan-June 1980" # Metropolitan Edison Co 80/09/05 24pp
- --8007i10340 Supplemental info to "Effluent & Wasto Disposal Semi Rept. Jan-June 1980," for EPICOR-II * Matropolitan Edison Co 80/07/05 Gpp
- --B007i10344 Supplemental info to "Effluent & Waste Disposal Bemi Rept, for 77i015-1231" re EPICOR-11 * Metropolitan Edison Co B0/07/05 Bpp

- 8009180204 THI Program Oft weekly status rept for wk of 800830-0906 COLLINS.J T THI Program Office 80/09/08 App
- 8009220288 Forwards monthly operating rept for Aug 1980 MUKILL, H D Hetropolitan Edison Co 80/09/18 to
- --8009220291 Monthly operating rapt for Aug 1980 MITCHELL.D 0 Metropolitan Edison Co 80/09/15 Spp
- B009300550 Forwards tritium results from TMI groundwater & soil samples obtained on B00930,70707. (8 & 25 Results of analyses performed on soil samples from GM-13B,0M-14 & GM-17 included
 RIETHLE: II E General Public Utilities - GPU Service Corp BO/09/16
- 8009300299 Forwards "Esecutive Summary, TM1 Units 1 & 2 Liquid & Gaseous Releases for Jul 1980." addl data for liquid discharges to Susquebanna River for 1980 t explanation of TM1 effluent & dose assessment group monthly summary PORTER S W Porter-Gerbs Consultants, Inc. 80/09/19 2pp
- --8009300401 "Esecutive Summary, TMI Units 1 & 2 Liquid & Gasebus Releases for Jul 1980 " Tables providing addit data for liquid discharge to Susquehanna River encl " Porter-Gertz Consultants, Inc 80/09/19 13pp
- S Reportable occurrences. LERs 3 related correspondence
- 8009020305 Ack receipt of util itrs re actions to correct intergranular stress corrosion pipe cracks & forwards safety evaluation Corrective actions are acceptable Util committed to submit REID.R W Operating Reactors Branch 4 80/08/11 4pp
- -- 8009020308 Bafety evaluation supporting actions taken on pipe cracks n borated water sys Operating Reactors Branch 4 80/08/11 4pp
- 8009120341 Forwards LER 80-015/04T-1 HERBEIN, J O Metropolitan Edison Co 80/09/07 1p
- --8009120342 LER B0-015/04T-1 on 800721, w/unit in cold shutdown, actual river water temp change exceeded limit for approx 6-h Caused by calculation error in instrument loop used to measure river water outlet temp MITCHELL.D G Metropolitan Edison Co 80/09/09 2pp
- 800930050A RO 80-17 determined insufficient documentation to demonstrate that brakes on motor operators for purge valves AH-VIS & AH-VIC environmentally qualified Redundant valves Metropolitan Edison Co 80/09/23 ip
- T Hearing transcripts on non-antitrust matters
- 8009020087 Forwards transcript of 800820 hearing in response to NRC 790921 & 1109 requests for info re significant regulatory developments affecting General Public Util companies in restart proceeding
 SHEENEY, LE Jersey Central Power & Light Co 80/08/25 ip
- ~-8009020089 Transcript of 800620 hearing before NJ Dept of Energy,Board of Public Utils in Newark,NJ Pp 1-176 # New Jersey, State of 80/08/20 176pp
- 8009030431 Forwards transcript of NJ Board of Public Utils 800821-22 hearings in Newark.NJ re util potition for rate increases, per NRC 770921 request to be kept informed of significant regulatory developments
 SMEENEY.L E Jersey Central Power & Light Co 80/08/27 125pp
- 8007030372 Forwards transcripts for 800725 & 26 hearings.per NRC 790721 & 1109 requests to be tept informed of significant davelopments SHEENEY, L E Jersey Central Power & Light Co 80/08/29 60pp
- 8009030582 Forwards transcript of 800825-26 hearings before NJ Board of Public Utlls in Newart.NJ to increase in rates for electric syc & for amend to levelized energy adjustment clause SKEENEY.L E Jarsey Central Fower & Light Co 80/08/29, 300pp
- 8009150252 Forwards transcript of NJ Board of Public Utils 800827 hearing re util request for rate increase; in response to NRG request for info on any significant regulatory devalopments Pp 678-729 SMEENEY, L E Jersey Central Power & Light Co 80/09/02 47pp

- 8009110405 Forwards transcript of NJ Board of Public Utils 800903 hearing. In response to NRC 790921 & 1109 requests for info re significant regulatory developments affecting General Public Utils companies SWEENEY, L.E. Jersey Contral Power & Light Co. 80/09/05 94pp
- 8009:70346 Forwards RG Fitzpatrick testimony re UCS Contention 4.PC Hearn testimony re Sholly Contention 1.DF Thatcher testimony re Sholly Contention 6(a) & PO Stoddart testimony re Sholly Contention 9(b) & Leuis contention CUTCHIN.J M Hearing Branch 3 80/09/15 2pp
- --8009170349 Testimony in response to UCS Contention 4 demonstrating connection of pressurizer heaters to onsite emergency power supplies does not yiolate General Design Criteria 17 & will not degrade emergency power supply performance F1T2PATRICK,R Power Systems Branch 80/09/15
- -8009170351 Testimony in response to Shoily Contention i demonstrating containment isolation signals need not include safety-grade high rediation signal to assure automatic & timely isolation of reactor bidg yent & purge or sump lines HEARN:P C Division of Safety Technology 80/09/15 6pp
- --8009170354 Testimony in response to Sholly Contention &(a) demonstrating that failure mode & effects analysis of instrumentation & control sys has been performed THATCHER.D F instrumentation & Control Systems Branch 80/09/15 10pp
- --8007170358 Testimony in response to Sholly Contention 5.ANGRY Contention V(D).Lewis contention & Chesapeake Energy Alliance Contentions 5.6 & 7 Certificate of Svc encl. STODDART.P G Assistant Director for Environmental Technology 60/09/15 68pp
- 800923G011 Direct testimony re Contention 4 Explains proper application of single failure criterion Connection of heaters in proposed manner violates General Design Criterion 1F Certificate of Svc encl POLLARD.R D Union of Concerned Scientists 80/09/15. 18pp
- 8009260313 Submittal of prepared testimony for first hearing session No attempts made to provide complete answers to ASLE 800908 memorandum & order re physical separation of TMI units Cartifficate of Buc encl Related correspondence TROWERIDGE, OF Ketropolitan Edison Co TROWERIDGE, OF Shaw, Pittman. Potts & Trowbridge 80/09/15 7pp
- 8009260313 Submittal of prepared testimony for first hearing session No attempts made to provide complete answers to ASLB 800908 manorandum & order re physical separation of Mil units Certificate of Sec enci Relaked correspondence TROMBRIDGE, Q.F. Metropolitan Edison Co. 80/09/15 7pp
- --8009260320 Testimony in response to UCS Contentions 1 & 2 re natural & forced circulation Explains feasibility of adequate core cooling Prof qualifications encl Related correspondence KEATEN,R W. JUNES,R C. Matropolitan Edison Co. 80/09/15 23pp
- --8009260322 Testimony in response to UCS Contention S & Environ Coalition on Nuclear Power Contention 1(e) re addl LOCA analysis Describes purpose, assumptions & results of analyses Prof qualifications encl Related correspondence UCNESS C . BROUGHTON, T G Metropolitan Edison Co 80/09/15 BO/09/15
- --B009260329 Revision 3 to "ECCS Analysis of B&W 177-Fuel Assembly-Loop NSS " Related correspondence * Babcock & Wilcox Co BAW-10103A R3 77/07/31 317pp.
- --8009260335 "Evaluation of Transient Behavior & Small RCB Breaks in 177 Fuel Assembly Plant," Vol 1.Section 6 0.8upal 2 to 790507 rept Related correspondence * Babcock & Wilcox Co 79/05/12 22pp
- -- 8009260340 "Sus Response to Total Loss of Steam Cenerator Heat Sint " Related correspondence

 # Babcock & Wilco, Co. 86-1103585-00 79/08/07 7pp
- -- 8009260352 "Analysis Summary in Support of Early Reactor Coolant Pump Trip "Related correspondence * Babcock & Wilcox Co 79/08/21 53pp

- --8007260359 "Supplemental Small Break Analysis." suppl to 790821
 "Analysis in Support of Carly Reactor Coolant Pump Trip "
 Related correspondence
 + Babcock & Wilcox Co 79/09/12 25pp
- --8009260366 "Small Break Operating Guidelines " Related correspondence * Babcock & Wilcox Co 69-1106001-00 79/11/30 48pp
- --8009260380 "Small Break W/Failed Power Operated Relief Valve " Related correspondence # Babcock Wilcox Co 86-117679-000 80/02/11 140p
- ---8009260388 Testimony in response to UCS Contention 7.Antinuclear Group Representing York Contention V(B) & SC Shally Contention 6(B) re detection of inadequate core cooling Prof qualifications encl Related correspondence KEATEN,R W , ROSS,M J , JONES,R C Metropolitan Edison Co. 80/09715 3ipp
- --B009260394 Testimony in response to UCS Contention 10 & BC Bholly Contention 3 re safety sys bypass & override Bhows that operator intervention in safety function does not violate criteria Prof qualifications encl Related correspondence CLARK.PR.ROSS.MJ.PATTERSON.ES Metropolitan Edison Co B0/09/15 2ipp
- --B009240394 Testimony in response to UCS Contentions 3:12 & 14 re safety classification Instrument failures re TMI-2 accident posed no threat to safety Prof qualifications encl Related correspondence KEATEN, R W. BRAULKE, O R., BRAZILL, O J. Metropolitan Edison Co. B0/09/15 30pp
- --BD09260400 Testimony in response to UCS Contentions 5 & 6 re valves & valve testing Power operated relief valve was not designed to fulfil safety function Prof qualifications oncl Related correspondence CORREA,J H. UROUHART, Q T., JONES, R C. Metropolitan Edison Co. BO/09/15 20pp
- --8009260402 "Overpressure Protection for B&W PWR " Related correspondence, # Babcock & Milcox Co BAN-10043 72/05/31 17pp
- --B007260411 Testimony in response to SC Sholly Contention 6(a) re integrated control sys Addresses complimentary evaluations of field data 8 results of sys analysis Prof qualifications encl Related correspondence BROUDHTON, TO . BADAUSKAS, O J . JOYNER, L L Metropolitan Edison Co B0/09/15 12pp
- --8009260412 Testimony in response to SC Sholly Contention 1 recontainment isolation Discusses relevant TMI-2 experience & licensee actions to add initiation signals due to reactor trip Prof qualifications encl Related correspondence LANESE.L.C Metropolitan Edison Co 80/09/15 9pp
- --B009260414 Testimony in response to Lewis contention & Antinuclear Oroup Representing York Contention V(D) re filters Bhows reduction of redioactive gases & minimization of leakage Prof qualifications encl Related correspondence.
 ITSCHNER.W F , BARLEY.R , MOORE.J Metropolitan Edison Co B0/09/15 24pp
- --8009260417 Testimony in response to Sholly Contention 15 & Antinuclear Group Representing York Contention V(C) re control room design-human factors engineering Improvements can be made Prof qualifications encl Related correspondence (MALSH.P S. MEEK.R E., ESTRADA.H Metropolitan Edison Co 80/09/15 49pp
- --8009260421 Testimony in response to Sholly Contention i3 & Environ Coalition on Nuclear Power Contention 1(a) re adequacy of plant computer sys Computer performs no safety or control functions Prof qualifications and I Related correspondence HAMILTON.W P. KEATEN.R W. Metropolitan Edison Co. 80/09/15.
- --B009260431 Testimony in response to UCS Contention 9 & Environ Coslition on Nuclear Power Contention 1(x) re safety systatus panel Identifies instrumentation & control assuring safety, U/Prof qualifications Related correspondence, WALSH, P S . TOOLE, R J Metropolitan Edison Co B0/09/15 17pp

- --8009260439 Testimony in response to Sholly Contention 5 & Environ Coalition on Nuclear Power Contention 1(4) re instrument ranges Lays out comparison showing adequacy of instrument ranges Prof qualifications encl Related correspondence BROUGHTON-T G . DUBIEL.R W . WILLIEMS.V H Metropolitan Edison Co 80/09/15 20pp
- --8009260443 Testimony in response to ASLB Question 8 & Chesapeake Energy Alliance Contention 5 re physical separation of Units 1 & 2 Addresses waste handling restoration & decontamination Wyprof qualifications Related correspondence FUNRER.E C . MCGOEY.R J Metropolitan Edison Co 80/09/15 60pp
- 8009230445 Forwards transcript of 800829 hearing before NJ Dept of Energy, Board of Public Utils,Pp 724-860, in response to NRC 791109 request to be kept informed of significant regulatory developments affecting General Public Utils companies SWEENEY,L E Jersey Central Power & Light Co 80/09/16 137pp
- 8009300417 Forwards UCS direct testimony on Contentions 3 & 10 re restart hearing Also forwards UCS interrogatories to NRC based on new info Testimony on Contention 5 will be provided pending receipt of NRC testimony WEISS,E R Sheldon. Harmon & Weiss 80/09/25 ip
- --8009300420 Direct testimony of RD Pollard on behalf of UCS re UCS Contention 3 POLLARD, R D Union of Concerned Scientists 80/09/25 18pp
- --8009300422 Direct testimeny of RD Pollard on behalf of UCS re UCS Contention 10 POLLARD.R D Union of Concerned Scientists 80/09/25 25pp
- U Congressional/Executive Correspondence
- 8007080346 Protests NRC decision not to permit psychological stress issue at restart hearings Failure to address issue would raise question re credibility of including issue in Unit 2 cleanup hearing ERTEL, A E House of Rep 80/09/03 2pp
- V Operator Examinations
- 8009030444 Forwards Administrative Procedure 1006, operator requalification program 8 status of requalification program for Unit II operators Replacement operator training program will be submitted upon completion HERBEIN.J G Metropolitan Edison Co 80/08/08 2pp
- ---B009030469 "Administrative Procedure 1006.Revision 3," operator requalification program Status of requalification program for Unit 11 operators enc!

 * Metropolitan Edison Co 80/07/31 42pp
- 8009080240 Forwards operator requalification program per 800328 ltr HERBEIN.J 0 Metropolitan Edison Co 80/08/08 2pp
- DOCKET 50-293 PILORIM NUCLEAR POWER STATION, UNIT i E NRC Safety Evaluation Report (SER), supple & correspondence
- 8009020032 Forwards input to Item 3 1 19 of facility 8ER Licensee should demonstrate that all pips penetrations have fire resistance rating of 3-h All tests in 800529 submittal were for electrical penetrations HALL: R E Brookhaven National Laboratory 80/08/19 24p
- F Security, medical, emergency & fire protection plans
- 8009090569 Forwards recommendation for Item 3 i 6/3 2 4 re cable combustibility for fire protection review Recommends that licensee bo required to coat okonite & kerite cables MALLRE Brookhaven National Laboratory 80/07/14 3pp
- 8009150437 Forwards commonts on security force training & qualification plan Requests response within 45 days Comments withheld (ref 10CFR2 790)
 1PPOLITO.T A Operating Reactors Branch 2 80/08/21 3pp
- 8009230162 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency ORIER. BH Region 1, Philadelphia, Office of the Director 80

- 8009170329 Forwards supplemental anfo re fire protection program, per NRC 800619 request MARISA, A V Boston Edison Ca 80/09/11 Bpp
- G Adjudicatory correspondence
- 8009300584 Forwards 800912 order revising 800829 order for mod of DL, in entirety EISENHUT, D O Division of Licensing 80/09/12 2pp
- --B009300588 Order revising B00829 order for mod of DL DPR-35.in entirety Info responsive to IE Bulletin 79-018 shall be submitted by 803101 Request for hearing will not stay order effective B00912 UCS 771104 b 780302 petitions discharged EISENHUT.D 0 Division of Licensing B0709/12 App
- P Operating license stage documents & correspondence
- 8009110554 Supple NRC BOD707 request for proposed Tech Specs changes re scram discharge vol vent & drain valves. & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT.D G Division of Licensing 80/07/22 22pp
- 8009020297 Submits interim criteria for shift staffing to all OL & CP dicensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D & Division of Licensing 80/07/31 7pp
- 8007080080 Forwards draft NUREC-0676, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREC-0676 encl W/o NUREC EISENHUT, D 0 Division of Licensing 80/08/01 117pp
- B009120101 States understanding relactions to be taken per 800805 telcon on testing of D safety relief valve NRC must be informed uithin 24-h if specified actions are not in accordance w/actual plans GRIER, B H Region 1. Philadelphia, Office of the Director 80/08/06 1p
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Leasons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D O Division of Licensing 80/08/07 60pp
- 8009030450 Informs that NRC evaluation confirmed two specific Event 5 valve configurations discussed in NRC 800223 ltr.60 not exist at facility NRC activities re valve configurations finalized for facility Technical evaluation rept encl 1PPOLITO,T A Operating Reactors Branch 2 80/08/08 3pp
- --8007030456 "Primary Coolent Sys Pressure Isolation Valves,Pflgrim Unit 1." technical evaluation rept NOELL,P N. STILKELL,T C Franklin Institute/Franklin Research Center NRC-03-77-11B 80/07/21 4pp
- B007040114 Forwards request for addl info re request for exemptions from 10CFR50 App J, containment leakage testing NOVAK.T M Assistant Director for Operating Reactors 80/08/12 App
- 6009150500 Forwards NUREG-0661, "Mark I Containment Long-Term Program Safety Evaluation Rept.Resolution of Generic Technical Activity A-7 " Rept describes NRC review results & requirements (1/o encl 1970LITO, T A Operating Reactors Branch 2 80/08/20 2pp
- B009150270 Application to amend License DPR-35 changing App A Tech Specs definition of "high radiation area" Proposed change allows flexibility in complying W/requirements Fee encl HOWARD, J E Boston Edison Go 80/09/01 Zpp
- --8009150279 Proposed Tech Spec & 13, changing definition of "high radiation area" * Beston Edison Co 80/09/01 2pp.
- 6009150284 Application for Proposed Change 80-3 to License DPR-95, re definition of "operable" as applied to single failure criterion for safety sys Request is in response to 1E Info Notice 79-35 t NRC 600410 ltr, Fee encl HOHARD, J E Boston Edison Co 80/09/01, 2pp

- ---B009150289 Proposed Change 80-3 to App A Tech Specs, Section i re definition of "operable" as it applies to single failure criterion for safety sys • Boston Edison Co 80/09/0i ip
- 8009180531 Requests submittal of program re baseline photographic survey of breakwater for comparison w/future conditions. Also requests proposed Tach Spec change re reporting requirements for approval Response requested within 90 days IPPOLITO.T A Operating Reactors Branch 2 80/09/03 3pp
- 8009160346 Forwards fee for 800403 application for Tech Spec changes per ARC 800702 request MDR181.A V Boston Edison Co 80/09/04 2pp
- 8009220193 Advises of need for add1 response to NRC 790808 ltr requesting analytical & test info re adequacy of station sys Response of 790808 was inadequate Response to encl should be provided within 45 days of ltr receipt 1PPOLITO.7 A Operating Reactors Branch 2 80/09/04 App
- 8007180541 Advises that 800104 reaponse to NRC 791107 ltr re ECCS evaluation models dealing w/cladding swelling & incidence of rupture is acceptable No further action necessary IPPOLITO.T A Operating Reactors Branch 2 80/09/05 2pp
- 8009170166 Forwards final rept re operating experience of plant augmented offgas treatment sys Data was compiled during EGGG ID. Inc 781010-13 site visit W/o encl.

 IPPOLITO, T A Decrating Reactors Branch 2 80/09/09 2pp
- 8009240641 Confirms util commitment to NRC 791023 "Interim Position on Containment Purging & Venting Pending Resolution of Isolation Valve Operability " Util position will remain in effect pending completion of NRC long-term review IPPOLITO.T A Operating Reactors Branch 2 80/09/09 2pp
- 8009230453 Responds to NRC 800425 ltr Provides info to assure that GE 781101 analysis re min ECCS equipment availability w/dc power supply failure conservative re plant sys availability combinations Lista min ECCS components available MORISI.A V Boston Edison CO 80/09/16 2pp
- @ Inspection reports, IE Bulletins & correspondence
- 8007070113 Forwards IE Bulletin 80-07. Suppl 1, "BWR Jet Pump Assembly Failure" Response required GRIER. B H Region 1. Philadelphia. Office of the Director BO/05/13 lp
- 8009100037 Forwards IE Insp Rept 50-293/80-09 on 800303-21 Noncompliance noted GRIER, B H Region 1. Philadelphia, Office of the Director, 80/07/09 2pp
- --8009100038 IE Insp Rept 50-293/80-07 on 800303-21 Noncompliance noted movement of irradiated fuel w/o secondary containment integrity & failure to log plant evolutions as required by station procedures

 MARTILLT T. Region i, Philadelphia, Reactor Operations Nuclear Support Branch KEHOE.D. ROBERTS.K Region 1, Philadelphia, Office of the Director 80/06/12 7pp
- 8009100874 Forwards IE Insp Rept 50-293/80-21 on 800504-16 & 28-30. No noncompliance noted BRUNNER.E J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/07/23 2pp
- --8009100877 IE Insp Rept 50-293/80-21 on 800504-16 & 28-30 No noncompliance noted Major areas inspected refueling restoration planning b surveillance activities, startup testing of new & modified sys & review of plant operations ROBERTS.K P. RAYMOND, W. Region i. Philadelphia, Office of the Director MARTIN.T T. Region i. Philadelphia, Reactor Operations Nuclear Support Branch 80/07/18 App
- 8009020110 Responds to IE Bulletin 80-17 Supp 2, "Failure of Control Rods to Insert During Scram at BWR " Alternate vent path was provided to scram discharge vol vent sys within 48-h of 800717 telcon notsfication ANDDONINI.O C Boston Edison Co 80/07/28 1p
- 8009080546 Responds to IE Bulletin 80-16 Util has not installed nor plans to install Rosemount Model 1151 or 1152 pressure transmitters ANDOONINI.6 C Boston Edison Co 80/07/29 1p

- 8007050494 Responds to NRC 800708 notice of violations Corrective actions licensed operators given training meetings prior to recommencement of fuel handling ALUKONIG.J Boston Edison Co 80/08/01 2pp
- 8309090041 Ack receipt of 800711 ltr informing NRC of steps taken to correct violation moted in 1E lnsp Rept 50-293/80-16
 CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/08/01 1p
- --8009090048 Responds to NRC 800612 ltr re violations noted in IE Insp Rept 50-293/60-16 Corrective actions plant fire extinguisher surveillance procedure revised ANDOGNINI.O C Boston Edison Co 80/07/11 2pp
- ---ECO9090038 Forwards IE lnsp Rept 50-293/80-i6 on 800421-25 & notice of violation CARLSDN,R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/12 2pp
- --8009090062 Notice of violation from insp on 800421-25
 * Region i, Philadelphia, Office of the Director 80/06/ii ip
- --8009090066 IE Insp Rept 50-293/80-16 on B0042i-25 Noncompliance noted failure to follow plant fire extinguisher check procedure EBMETER.8 D Region 1. Philadelphia, Reactor Construction & Engineering Support Branch KQLTAY.P S Region 1. Philadelphia, Office of the Director 80/06/11 8pp
- B009090660 Responds to IE Bulletin B0-17 Fifty control rod drivelines selected for manual scram & 50 control rod drivelines selected for automatic scram Scram times reviewed to determine fastest.slowest & average times for each scram ANDOGNINI.O G Boston Edison Co 80/08/01 4pp
- 8009110297 Inservice insp rept.Vol 1, from Jan-Feb 1980 refueling outage Describes exam of selected components Forwards results of remote visual exam of selected components & manual exam of selected areas of facility RIOO3, M H , FLACK, M L , LAUTZENHEISER Southwest Research Institute 80/09/07 280pp
- --E007110297 Inservice insp rept.Vol 1.from Jan-Feb 1980 refueling outage Describes remote visual exam of selected components at facility RIOOS.M W. DUNAVONT.D W. LAUTZENHEISER Southwest Research Institute 80/08/07 40pp
- --B009110304 Inservice insp rept.Vol 1.from Jan-Feb 1980 refueling outage Describes manual exam of selected areas of facility RIQGS.M W. DUNAVONT, D W. LAUTZENMEISER Bouthwest Research tostitute 80/08/07 100pp
- 8009120036 Responds to IE Bulletin 80-17, Suppl 1, Section A, Items 2-5
 Applicable procedure contains guidance to control room
 personnel on initiation of standby liquid control sys
 Procedure re scram discharge vol revised, Affidavit encl
 ANODONINI, G C Boston Edison Co 80/08/08 4pp
- 8009t605i6 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type U-2 Bpring Return to Neutral Control Switches " No subj switches used or planned for use in safety-related application at facility ANDGONINI.G C Soston Edison Co 80/08/08 ip
- BOO9160519 Responds to 1E Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E "No subj relays used or planned for use in sys

 ANDOGNINI.O C Boston Edison Co 80/08/08 ip
- 8009190940 Responds to IE Bulletin 80-17 re failure of certain control rods to fully insert during BWR scram Examination revealed absance of failure mode AMOUGNINI.0 C Boston Edison Co 80/08/12 4pp
- 6009190073 Ack receipt of 800715 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-293/80-20
 BRUNNER E J Region i, Philadelphia, Reactor Operations Nuclear Support Branch 60/08/13 ip
- --8009190076 Responds to NRC 800604 ltr re violations noted in 1E lnsp Rept 50-293/80-20 Corrective actions Procedure 8 7 i 4 wili be revised to specify clearly actions to be taken by test director re leakages & valve lineup deviations ANDOGNINI, G C Boston Edison Ca 80/07/15 2pp

- ---8009190078 Forwards IE Insp Rept 50-293/80-20 on 800504-08 & notace of violation

 DRUNNER,E J Region i. Philadeiphia, Reactor Operations Nuclear Support Branch 80/06/04 2pp
- --B009190079 Natice of violation from insp on 800504-08
 Region 1, Philadelphia, Office of the Director 80/06/03 1p
- --8009190081 IE Insp Rept 90-293/80-20 on 800504-08 Noncompliance noted failure to conduct containment integrated leak rate test prior to making repair & adjustment & to perform local leak rate test after maint CAPHTQIN D L Region i. Philadelphia. Reactor Operations Nuclear Support Branch REKITO.W A Region i. Philadelphia, Office of the Director 80/06/03 10pp
- BO09090034 Responds to 1E Builetin BO-19, "Failure of 76 of iB5 Cantrol Rods to Fully Insert During Scram at BWR " Util has ordered scram discharge header water level monitoring sys ANDDONINI.G C Boston Edison Co BO/08/14 ip
- BO09030iii Forwards Revision I to 1E Bulletin 80~i9. "Failures of Mercury-Metted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Hritten response required GRIER, B H Region I. Philadelphia, Office of the Director 80/08/15 ip
- B009i20084 Forwards Suppi 3 to 1E Bulletin B0-i7, "Failure of Control Rods to Insert During Scram at BMR " Written response required GRIER: B H Region 1, Philadelphia, Office of the Director B0/08/22 ip
- 8009180568 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Bys " No written response required CRIER.8 H Region i, Philadelphia, Office of the Director 80/08/22 ip
- 8009i20144 Forwards 1E Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-600S & K-00N 400S Circuit Breakers " No written response required ORIER, B H Region I, Philadelphia, Office of the Director 80/08/27 Ip
- 8007230490 Forwards Revision i to IE Bulietin 79-26, "Boran Loss Fram BNR Control Blades " Written response required QRIER, B H Region 1, Philadelphia, Office of the Director 80/88/29 1p
- BOD9230775 Forwards IE Circular BO-21, "Regulation of Refueling Crews " No written response required ORIER, B H Region i, Philadelphia, Office of the Director BO/09/iO ip
- 8009240303 Forwards IE Info Notice 80-32. "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required GRIER, B H Region i, Philadeiphia, Office of the Director 80/09/12 ip
- R Periodic operating reports & related correspondence
- 8009090261 Forwards "Radioactive Effluent & Waste Disposal Rept, Including Radiological Impact on Humans, Jan-June 1980 " MGR181, A V Baston Edison Co 80/09/01 Ip
- ~~8009090267 "Radioective Effluent & Haste Disposal Rept.including Radiological Impact on Humans, Jan-June 1980 " BOWDON, T L , ZIEMIANSKI, E J Boston Edison Co 80/09/01 74pp
- 8009160267 Forwards monthly operating rept for Aug 1980 MACHON R D Boston Edison Co 80/09/11 ip
- ~-8009140271 Monthly operating rept for Aug 1980 WHITNEY, O O Boston Edison Co 80/09/11 App
- 8009300500 Forwards revision to monthly operating rept for Aug 1980 MACHON, R D Boston Edison Co 80/09/23 1p
- --8009300505 Revision to monthly operating rept for Aug 1980 * Boston Edison Co 80/09/23 ip

- 8309170329 Forwards supplemental info re fire protection program, per NRC 800619 request MARISE, N V Boston Edison Co 80/09/11 8pp
- G Adjudicatory correspondence
- 8009300584 Forwards 800912 order revising 800829 order for mad of OLin entirety Eleckhulto O Division of Licensing 80/09/12 2pp
- --B0093005B8 Order revising E00827 order for mod of DL DFR-35.in entirety Info responsive to IE Bulletin 79-018 shall be submitted by B01101 Request for hearing will not stay order effective B00912 UCS 77:104 & 780502 petitions discharged EISENHUT, D O Division of Licensing E0/09/12 6pp
- P Operating license stage documents & correspondence
- 8009110554 Suppls NRC 800707 request for proposed Tech Specs changes re scram discharge vol yent & drain valves, & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENNUT.D G Division of Licensing 80/07/22 22pp
- 6009020297 Submits interim criteria for shift staffing to all CL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtice work Development & Implementeation to be reviewed within 90 days EISENHUT, D G Division of Licensing 80/07/31 7pp
- B0090900B0 Forwards draft NUREQ-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT, D G Division of Licensing 80/09/01 [19pp]
- E009120101 States understanding reactions to be taken per 800805 teleon on testing of D safety relief valve RRC must be incommed outhin 24-h is specified actions are not in accordance w/actua) plans GRIER/B H Region 1. Philadelphia. Office of the Director 80/08/06 lp
- 8007230052 Informs that exemption from five re licensing action associated w/TKI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D O Division of Licensing 60/08/07 60pp
- 8007030450 Informs that NRC evaluation confirmed two specific Event 5 valve configurations, discussed in NRC 800223 ltr.do not erist at facility NRC activities re valve configurations finalized for facility Technical avaluation rept encl IPPOLITO,T A Operating Reactors Branch 2 80/08/08 3pp
- --2007050456 "Primary Coolant Sys Pressure Isolation Valves, Pilgrim Unit i," technical evaluation rept NDELL,P N. STILMELL.T C Franklin Institute/Franklin Research Center (RC-03-79-118 80/07/21 App
- 8009040114 Forwards request for add1 info re request for exemptions from tOCFR50 App J, containment leakage testing NDVAK.T M Assistant Director for Operating Reactors 80/08/12 4pp
- 8009150500 Forwards NUREC-0661, "Mark I Containment Long-Term Program Safety Evaluation Rapt. Resolution of Generic Technical Activity A-7 " Rept describes NRC review regults & requirements U/o enci IPPOLITO, T A Operating Reactors Branch 2 80/08/20 2pp
- 8009150270 Application to amend License DPR-35, changing App A Tech Specs definition of "high radiation area" Proposed change allows flexibility in complying w/requirements Fee anci MOWARD.J E Boston Edison Co 80/09/01 Zpp
- --- E009150279 Proposed Tech Spec 6 13 changing definition of "high radiation area" * Boston Edison Co 80/09/01 2pp.
- 8009150284 Application for Proposed Change 80-3 to License DPR-35, re definition of "operable" as applied to single failure criterion for safety sys Request is in response to IE Info Notice 79-35 to NRC 800410 ltr fee entl HGWARD.J E Boston Edison Co 80/09/01 2pp

- --8009150285 Proposed Change 80~3 to App A Tech Specs, Section 1 re definition of "operable" as it applies to single failure criterion for safety sys e Boston Edison Co 80/09/01 ip
- BOOPIBO531 Requests submittal of program re baseline photographic survey of breakwater for comparison w/future conditions. Also requests proposed Tech Spec change re reporting requirement for approval Response requested within 90 days IPPOLITO, T.A. Operating Reactors Branch 2 80/09/03 3pp
- B009160346 forwards fee for B00403 application for Tech Spec changes per HRC B00702 request MGRISI, A V Boston Edison Co B0/09/04 2pp
- 8009220153 Advises of need for add1 response to NRC 790B0B itr requesting analytical & test info re adequacy of station sys Response of 790B0B was inadequate Response to encl should be provided within 45 days of ltr receipt IPPDLITO.T A Operating Reactors Branch 2 80/09/04 App
- 8009180941 Advises that 800104 reaponse to NRC 791109 itr re ECCS evaluation models dealing w/cladding swelling & incidence of rupture is acceptable No further action necessary IPPOLITO.T A Operating Reactors Branch 2 80/09/05 2pp
- 8009170166 Forwards final rept re operating experience of plant augmented offgas treatment sys Data was compiled during EGAO ID, Inc 781010-13 site visit W/o encl IFPOLITO.T A Operating Reactors Branch 2 80/09/09 2pp
- 8009240641 Confirms will commitment to NRC 791023 "Interim Position on Containment Purging & Venting Pending Resolution of Isolation Valve Operability" Util position will remain in effect pending completion of NRC long-term review IPPOLITO.T A Operating Reactors Branch 2 80/09/09. Zpp
- 8007230453 Responds to NRC 800425 ltr Provides info to assure that GE 781101 analysis re min ECC8 squipment availability w/dc power supply failure conservative re plant sys availability combinations Lists min ECC8 components available MORISI: A V. Boston Edison Co 80/07/16 2pp
- G Inspection reports, IE Bulletins & correspondence
- 8007070113 Forwards IE Bulletin 80~07. Suppl 1, "BWR Jet Pump Assembly Failure" Response required GRIER. B H Region 1. Philadelphia, Office of the Director 80/05/13 1p
- 9009100037 Forwards IE Insp Rept 50-293/80-09 on 800303-21. Noncompliance noted GRIER, B H Region i, Philadelphia, Office of the Director 80/07/09 2pp
- --8009100038 IE Insp Rept 50-293/80-09 on 800303-21 Noncompliance noted movement of irradiated fuel w/o secondary containment integrity & failure to log plant evolutions as required by station procedures

 MARTIN.T T Region 1, Philadelphia, Reactor Operations Nuclear Support Branch KEHOE, D, ROSERTS K Region 1, Philadelphia, Office of the Director 80/06/12 9pp
- 8009100874 Forwards lE Insp Rept 50-293/80-21 on 800504-16 & 28-30 No noncompliance noted BRUNNERFE J Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 80/07/23 2pp
- --B009100877 lE Insp Rept 50-293/80-21 on 800504-16 & 28-30 No noncompliance noted Major areas inspected refueling restoration planning & surveillance activities startup testing of new & modified sys & review of plant operations ROBERTS.K.P. RAYMOND.W. Region 1. Philadelphia. Office of the Director MARTIN.T T Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/07/18 6pp
- BO09020110 Responds to IE Bulletin 80-17 Supp 2. "Failure of Control Roos to Insert During Scram at BHR " Alternate vent path was provided to scram discharge vol vent sys within 48-h of 800719 telcon notification ANDOONINI.G C Boston Edison Co 80/07/28 lp
- 8007080544 Responds to 1E Builetin 80-14 Util has not installed nor plans to install Rosemount Model 1151 or 1152 pressure transmitters ANGGONINI.O C Boston Edison Co 80/07/29 1p

- BOO9050484 Responds to NRC 800708 notice of violations Corrective actions licensed operators given training meetings prior to recommencement of fuel handling ALDKONIS, J. Boston Edison Co. 80/08/01 2pp
- 800909004i Ack receipt of 80071i itr informing NRC of steps taken to correct violation noted in 1E Insp Rept 50-293/80-16
 CARLSOM.R T Region i. Philadelphia. Reactor Construction & Engineering Support Branch 80/08/01 ip
- --800709004B Responds to NRC 8006i2 ltr re violations noted in 1E Insp Rept 50-293/80-16 Corrective actions plant fire extinguisher surveillance procedure revised ANDOGNIMI.0 C Boston Edison Co 80/07/11 2pp
- --800909005B Forwards IE Insp Rept 50-293/80-16 on 800421-25 & notice of violation CARLSON, R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/06/12 2pp
- --8009070062 Notice of violation from insp on 800421-25
 * Region i, Philadelphia, Office of the Director 80/06/11 ip
- --8007070066 IE Insp Rept 50-293/80-16 on 800421-25 Noncompliance noted failure to foliow plant fire extinguisher check procedure ERNETER, 8 D. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch KOLTAY, P.S. Region 1, Philadelphia, Office of the Director 80/06/11 Spp
- 8009090660 Responds to IE Bulletin 80-17 Fifty control rod drivelines selected for manual scram & 50 control rod drivelines selected for automatic scram Scram times reviewed to determine fastest slowest & average times for each scram ANDDONINI.O.C Boston Edison Co 80/08/01 4pp
- BCO9510297 Inservice insp rept, Vol i, from Jan-Feb 1980 refueling outage Describes exam of selected components Forwards results of remote visual exam of selected components & manual exam of selected areas of facility RIGGS: M W . FLACK, W L . LAUTZENHEISER Southwest Research Institute, BO/08/07 250pp
- ---BD09110299 Inservice insp rept.Vol 1.from Jan-Feb 1980 refueiing outage Describes remote visual exam of selected components at facility RIGOS.M W. DUNAVONT,D W. LAUTZENHEIBER Bouthwest Research Institute 80/08/07 60pp
- --B009i10304 Inservice insp rept, Vol 1, from Jan-Feb 1980 refueling outage Describes manual exam of solected areas of facility RIO05.M W . DUNAVONT, D W , LAUZENMEISER Southwest Research Institute. B0/08/07 100pp
- 8009120036 Responds to IE Bulletin 80-17, Suppl 1. Section A, Items 2-5 Applicable procedure contains guidance to control room personnel on initiation of standby liquid control sys Procedure re scram discharge vol revised Affidavit encl ANDOGNINI.0 C Boston Edison Go 80/08/08 App
- 8009140516 Responds to IE Builetin 80-20, "Failures of Westinghouse Type M-2 Egring Return to Neutral Control Switches " No subj switches used or planned for use in safety-related application at facility, ANDOGNINI.O C Boston Edison Co 80/08/08 ip
- 8009180519 Responds to IE Builetin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E," No subj relays used or planned for use in sys ANDDONINI.O C Boston Edison Co 80/08/08 ip
- EOO9190740 Responds to IE Bulletin 80-17 re failure of certain control rods to fully insert during BWR scram Examination revealed absence of failure mode ARDOONINI.O C Boston Edison Co 80/08/32 4pp
- BOD9190073 Ack receipt of 800715 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-293/80-20 BRUNNER.E J Region 1, Philadelphia, Reactor Operations Nuclear Buppert Branch 80/08/13 1p
- --BO09190076 Responds to NRC B00604 ltr re violations noted in IE Insp Rept 50-293/80-20 Corrective actions Procedure B 7 1 4 will be revised to specify clearly actions to be taken by test director re leakages & valve lineup deviations ANDDONINI.Q C Boston Edison Co 80/07/15 2pp

- --8009190078 Forwards iE Insp Rept 50-293/80-20 on 800504-08 & notice of violation DRUNNER: E J Region I. Philadelphia. Reactor Operations Nuclear Support Branch 80/06/04 2pp
- --8009190079 Notice of violation from insp on 800504-08
 * Region i, Philadelphia, Office of the Director 80/06/03 ip
- --8009170081 IE Insp Rept 50-293/80-20 on 800504-08 Noncompilance noted failure to conduct containment integrated leak rate test prior to making repair & adjustment & to perform local leak rate test after maint CAPHTONIO L. Region 1. Philadeiphia. Reactor Operations Nuclear Support Branch REKITON A. Region 1. Philadelphia, Office of the Director 80/06/03 10pp
- 8009090034 Responds to 1E Bulletin 80~19. "Failure of 76 of 185 Control Rods to Fully Insert During Screm at BWR " Util has ordered screm discharge header water level monstoring sys ANDOGNINI.G C Boston Edison Co 80/08/14 ip
- 8009030iii Forwards Revision 1 to IE Builetin 80-17, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER.B H Region i, Philadeiphia, Office of the Director 80/08/15 ip
- B009:20084 Forwards Suppl 3 to IE Bulletin 80-i7. "Failure of Control Rods to insert During Scram at BWR " Written response required GRIER.B H Region i, Philadelphia. Office of the Director 80/08/22 ip
- 8007180568 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GRIER, B H Region i, Philadelphia, Office of the Director 80/08/22 ip
- 8009120166 Forwards IE info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6005 Circuit Breakers " No written response required GRIER, II H Region i, Philadelphia, Office of the Director 80/08/27 Ip
- 8009230490 Forwards Revision i to IE Bulietin 79-26, "Moran Loss From BWR Control Biades " Written response required QRIER, B H Region i, Philadelphia, Office of the Director 80/08/29 ip
- 80D9230775 Forwards IE Circular 80-21, "Regulation of Refueling Crews " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director BO/09/iO ip
- 8009240303 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matis " No written response required GRIER, B H Region i, Philadelphia, Office of the Director 80/09/12 tp
- R Periodic operating reports & related correspondence
- 8009090261 Forwards "Radioactive Efficient & Waste Disposal Rept. Including Radiological Impact on Humans, Jan-June 1980 " MORISI.A V Boston Efison Co 80/09/01 ip
- --B009090267 "Radioactive Effiuent & Waste Disposai Rept, Including Radiologicai Impact on Humans, Jan-June 1980 " SOMDDN: T L . ZIEMIANSKI: E J Boston Edison Co B0/09/01 74pp
- 8009140267 Forwards monthly operating rept for Aug 1980 MACHON, R D Boston Edison Co 80/09/11 ip
- --8009140271 Monthly operating rept for Aug 1980 WHITNEY, O O Boston Edison Co BO/09/11 App
- 8009300500 Forwards revision to monthly operating rept for Aug 1780 MACHON.R D Roston Edison Co 80/09/23 ip
- --8009300305 Revision to monthly operating rept for Aug 1980 * Boston Edison Co -80/09/23 ip

```
S Reportable occurrences, LERs & related correspondence
8009090389 Farwards LER 80-042/04T-0
MCQUIRE.P J Boston Edison Co 80
                                                                         E0708/26 1p
--8009090401 LER 80-042/04T-0 on 800820, analyses rept indicated reportable concentration of Co-60 existed in mussel sample taken from plant discharge canal Caused by normal plant
        operation
MCLOUGHLIN, M T Boston Edison Co 80/08/26 1p
8009030611 Forwards LER 80-043/04L-0
MACHON: R D Boston Edison Co 80/09/28 1p
 --8009030A17 LER 90-043/041-0 on 800901.conductivity on outlet of
         demineralizer increased rapidly after placing D condensate in svc Caused by lateral backing out & allowing media to
         enter process
WHITNEY, 0 0 Boston Edison Ca 80/08/28 ip
         HHITKEY, O C
8009020382 Forwards LER 80-044/03L-0
MCGUIRE.P J Baston Edison Co 80/08/29 19
 --8009020386 LER 80-044/03L-0 on 800801 reactor core isolation cooling
        inhoard isolation valve failed to close on reactor lou pressure signal Motor overload annunciator came in & breaker tripped Caused by valve motor burn out WHITNEY, Q G Boston Edison Co 80/08/29 ip
8009030477 Forwards LER 80-046/93L-0.
MCGUIRE.P J Boston Edison Co 80/08/29 1p
--8009030463 LER 80-046/03L-0 on 800802, during reactor shutdown, high
water level isolation main steam line drain valve MD-220-1
failed to isolate Caused by incorrect setpoint on Varway
level suitch Switch adjusted & recalibr
WHITNEY.O G Boston Edison Co 80/08/27 ip
8009030596 Forwards LER 80-039/01T-0
MCGUIRE, P J Boston Edison Co 80/08/29 ip
---B009030599 LER 80-039/01T-0 on 8008R0.callbr techniques for limiting safety sys setting & for average power range monitor found to be nonconservative Cause unstated Interim administrative limits established pending final guidelines MCLAUGHLIN.M T Boston Edison Co. B0/08/29 ip
   )09030603 Forwards LER 80-038/01T-0
MCQUIRE.P J Boston Edison Co 80/08/29 1p
   -8009030607 LER 80-038/01T-0.or B00818,mode switch in shutdown trip function of reactor protection sys failed when 8 vital motor generator syst tripped Caused by relay 5A-K16B being energized & relay 5A-K17B being de-energized ATHIS.C J Boston Edison Co 80/08/29 2pp
BO09090422 Forwards LER 80-045/03L-0
MACHON:R D Boston Edison Co 80/09/02 1p
--8009090426 LER 80-049/03L-0 on 800804 after injecting furmanite into leaking packing gland on reactor core isolation cooling outboard isolation valve valve would not close electrically. Probable cause was inproper torque setting WHITNEY.0 0 Boston Edison Co 80/09/02 ip
    J9090430 Forwards LER 80-047/03L-0
4ACHON.R D Boston Edison Co 80/09/02 1p
     3009090433 LER 80-047/03L-0 on 800801, reactor vessel 203-3D did not
        respond to manual open signal Air operator assembly, solenoid assembly & pilot assembly removed & tested No apparent cause determined Unit reassembled that Hashes & J. Boston Edison Co. 80/09/02 ... 3pp
         )70369 Forwards LER 80-048/03L-0
HDN,R D Boston Edison Co. 80/09/05 1p
          19090376 LER BO-048/03L-D on 800807. actuation of HPCI & reactor core
           olation cooling fire detectors did not annunciate alarms 
panel in control room Caused by dirt on belirreducing 
diblity & bad but bys repaired & returned to svc. 
LOUGHLIN. R T Boston Edison Co 80/09/05 ip
            0452 Forwards LER 80-049/03L-0
0M R D Boston Edison Co 80/09/09 1p
```

```
--B0091604B3 LER B0-049/03L-0; on B00B10; salt svc water pump (SSN) P208E tripped On B00B1; SSW P208E tripped Caused by thermal overloads Permanent corrective actions under study Haanwhite, inlet water temp decrease has alleviated problem MCLQUGHLIN, M T Boston Edison Co 80/09/09 2pp
8009160404 Forwards LER 80-052/03L-0
MACHON, D Boston Edison Co 80/
                                                                                           BD/09/11 1a
 --8009160410 LER 80-052/03L-0 on 800812, while calibr reactor coolant lest detection air sampling sysiparticulate chamber cover retaining nuts were stripped Maint personnel replaced nuts MCLQUOHLIN, M T Boston Edison Co 80/09/11 1p
8009160447 Forwards LER 80-051/03L-0
MACHON, R D Boston Edison Co 80/09/11 1p
     -8609160455 LER 80-051/03L-0 on 800813.while performing surveillance test, reactor water level instrument LiS 263-728.switches 3 & 4.erceeded setpoint limit Caused by setpoint drift Instrument recalibr & returned to svc MCLOUCHLIN.M T Boston Edison Co 80/09/11 ip
8009170381 RO 80-090/01X-0 on 800907.during surveillance testing diesel generator removed from svc when RBCCW pump P202D found inoperable Caused by ambiguous Tech Specs Tech Specs will be revised to clarify limiting condition of operation MCLOUGHLIN.M T Baston Edison Co 80/09/11 2pp
 8009160396 Forwards LER 80-053/03L-0
MECHON.R D Boston Edison Co 80/09/12 1p
 --BOD9160402 LER 80-053/03L-0 on 800814, HPCI enubber 23-3-36 was found
to be inoperable Caused by low reservoir fluid Analysis by
engineering dept underway
MCLAUGHLIN.M T Boston Edison Co 80/09/12 ip
 8009290264 Forwards LER 80-054/03L-0
MACHON, R D Boston Edison Co 80/09/18 ip
 --8009290317 LER 80-054/03L-D on 800901, changed station organization of
           Tech Specs Caused by continuing efforts to improve mgt
Amends to Tech Specs re organizational changes will be
submitted for review & approval Organizational charts encl
GRAHAM.E T Boston Edison Co 80/09/16 3pp
 8007230732 Forwards LER 80-057/03L-0
MACHON, R D Boston Edison Co 80/09/19 ip
 --8009230739 LER 80-057/03L-0 on 800821, fluid drive pump tripped & battup & emergency dil pump did not start Caused by coil burnout on 125 voit DC Agastat relay model #2412 Relay replaced & design change initiated MCLAUGHLIN, M T Boston Edison Co 80/09/19 ip
8009240462 Forwards LER 80-056/03L-0
MACHULR D Boston Edison Co 80/09/19 1p
 --8009240463 LER 80-056/03L-0 on 800821, "A" 125-voit dc control battery
on panel C3 became inoperable Caused by faulty electronic
modules in battery charger voitage regulator Battery charger
repaired & returned to avo
                                                      Boston Edison Ca 80/09/19 1p
B009240467 Forwards LER 80-055/03L-0
MACHON R D Boston Edison Co 80/09/19 1p
--8009240466 LER 80-055/03L-0 on 800821,motor overload alarm was received on MO 1301-62 valve in reactor cooling isolation sys Caused by valve thermal overload device Evaluation of capacity rating of overloaded device being conducted MCLOUGHLIN, M. T. Boston Edison Co. 80/09/19 1p
B009260470 Forwards LER 80-050/01T-0
MACHON, R D Boston Edison Co 80/09/19 1p
--8009260475 LER 80-050/0iT-0:on 800911, during mgt review, concluded that operation & maint on containment cooling sys had been conducted in less conservative manner than prescribed in Tech Specs Caused by sparse & ambiguous Tech Specs Gaused by sparse & ambiguous Tech Specs MCLOUGHLIN, M T Boston Edison Co 80/09/19 2pp
8009260481 Forwards LER 80-097/03L-0
MACHON: R D. Boston Edison Co 80
                                                                                           B0/09/19 1p
```

- --8009260484 LER 80-057/03L-0 on 800821 during HPCI sys performance test.

 HPCI sys declared inoperable due to steam throttle valve
 oscillation Probably caused by dirt in sys Sys recalibr
 RCCUUSHLIN.M T Boston Edison Co 80/09/19 lp
- 8009250430 Forwards LER 80-032/01T-0 MACHON, R D Boston Edison Co 80/09/22 1p
- --8009260485 LER 80-032/01T on 800724.0E SIL 299 review revealed higher drywell ambient temp than used for original safeguard Yarway calibrs Caused by high temp due to inadequate drywell cooling Recalibr \$ survey of drywell ventilation conducted MATHIS.C J Boston Edison Co 80/09/22 ip
- 8009290283 Forwards LER 80-040/03L-0 MACHON, R D Boston Edison Co 80/09/24 1p
- --B009290313 LER B0-060/03L-0 on B00B25, while performing HPCI sys performance test. HPC1 sys declared inoperable due to escillating steam throttle valve Caused by dirt filtering through sys Sys recallor MCLAUGHLIN. M Y Boston Edison Co 80/09/23 ip
- 8009300531 Forwards LER 80-061/03L-0 NACHON: R D Boston Edison Co 80/09/24 1p
- --8009300535 LER 80-061/03L-0 on 800825.core spray valve MD 1400-24A failed & prevented valve MD 1400-25A from being tested Caused by lack of lubrication Valve lubricated & returned to svc Valve inep scheduled during next outage MCLQUOHLIN.M T #0ston Edison Co 80/09/24 2pp
- U Congressional/Executive Correspondence
- B009150020 Responds to Subcommittee on Nuclear Regulation 780906 ltr re Senator Stafford request for hearing to discuss 1972 memo re pressure suppressing containments: UCS criticisms re ATMS safety problems & West Valley insp problems HENDRIE: J M Commission 80/08/18 2pp
- --8009150074 Responds to request for view on util 731226 ltr arguing "need for power" Util did not make substantive & specific case on need Most effective way to save fuel oil would be to shut down & repair core damage HENDRIE.J M Atomic Energy Commission. Deputy Director for Technical Review (Pre-1975) 74/02/04 1p
- --8009150081 Protests AEC 731217 determination & order requiring shutdown during wk of 731223 Action penalties consumers Review & approval of licensee submittal must be expedited to avoid extended outages
 STASZESKY,F M Boston Edison Co 73/12/26 App
- --8009153085 Responds to util 731226 itr re facility shutdown Limited operation is justified in view of probable fuel channel box degradation AEC will expedite review of licensing actions re return to power MUNITALIO, L M Atomic Energy Commission 74/02/01 3pp
- V Operator Examinations
- 8009220230 Forwards revised Section 3 l 1, "Initial Operator Training," of facility training manual Complete revised training manual to be issued MATHIS, C J Boston Edison Co 80/07/12 ip
- --8009220252 Section 3.1 1. "Initial Operator Training." Revision 2

 4 Boston Edison Co 80/09/12 lopp
- DOCKET 80-295 ZION NUCLEAR POWER STATION, UNIT 1

 F. Security, medical, emergency & fire protection plans
- BOO9230288 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys (nstailed for govt use during emergency KEPPLER, J G Region 3, Chicago, Office of the Director BO/08/22 3pp
- 8009100378 Forwards review of util generating station emergency plan & draft ltr requesting addl info & commitments from util PAGANO.F O Emergency Preparedness Licensing Branch 80/08/28 5pp

- G Adjudicatory correspondence
- 800922008B Forwards order requiring into supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 VAROA.S A Operating Reactors Branch 1 80/08/29 2pp
- --8009220091 Order for mod of Licenses DPR-39 & DPR-48 to add info which fully responds to NRC request for info re environ qualification of safoty-related olectrical equipment info should be submitted by 801101 EISENHUT,D O Division of Licensing 80/08/29 &pp
- 80090904/1 Forwards AB Johnson testimony.Pages 63-64 & 80-82.400 to difficulty in reading original submittal STEPIDE.P P Isham. Lincoln & Beale 80/09/03 ip
- --8009090487 Testimony of AB Johnson re proposed amends to increase apart fuel storage capacity Resubmitted Pp 63-64 & 80-82 JOHNSON, A B Brookhaven National Laboratory 80/09/03 Spp
- ₩ General correspondence
- 8009180448 Responds to 800319 ltr requesting public debate re issues appropriate to evacuation of large population ctrs near plants DENTON:H R Office of Nuclear Reactor Regulation. Director 80/04/21 3pp
- --8009180462 Requests public debate re issues appropriate to evacuation of large population ctrs near plants Expresses confidence in attempts by Commissioners to represent public concerns EMORY. K Affiliation Unknown 80/03/19 ip
- 8009110218 Forwards response to 800728 itr requesting assistance in answoring constituent questions re nuclear power & effects of radiation DIRCKS.W J Office of the Executive Director for Operations 80/09/28, 4pp
- P Operating license stage documents & correspondence
- 8009300169 "Rept of Zion/Indian Point Study Vol 2," informal rept STEVENSON, M O Los Alamos Scientific Laboratory FIN A-7019 NUREG/CR-1411 V2 80/04/30 165pp Available at NT/S
- 8009050032 Discusses void formation in vessel head during 800611 natural circulation coeldown event Requests opinion repotential for voiding phenomenon in Westinghouse designed NSSS CHECKLP S Assistant Director for Plant Systems 80/07/28 2pp
- BOO9020297 Bubmits interim criteria for shift staffing to all OL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D O Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREC-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREC-0676 ent. N/A NUREC EISENHUT.D Q Division of Licensing 80/08/01 119pp
- 8007230052 Informs that exemption from foo re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D O Division of Licensing 80/08/0/ 60pp
- 8009050528 Forwards Amends 56 % 59 to Licenses DPR-39 & DPR-46, respectively, safety evaluation & notice of issuance & availability VARGA, S A Operating Reactors Branch i 80/06/08 2pp
- --8007050531 Amends 56 & 53 to Licensea DPR-37 & DPR-48, respectively, revising & upgrading certain limiting conditions of operation & associated surveillance requirements for ventilation filter sys VAROA.8 A Operating Reactors Branch 1 80/08/08 22pp
- --8009050534 Safety evaluation supporting Amends 56 \$ 53 to Licenses DPR-39 & DPR-48, respectively * Office of Nuclear Reactor Regulation. Director 80/00/00 4pg
- --8009050538 Notice of issuance & availability of Amends 56 & 93 to Licenses DPR-39 & DPR-48, respectively VARGA:S A Operating Reactors Branch 1 80/08/08 2pp

- 8009100178 Forwards request for add1 info re bypass & reset of engineered safety features MGVAK T M Assistant Director for Operating Reactors 80/08/14 4pp
- 8009190794 Forwards revised Westinghouse STS 3 9 8 2.3 9 10 4 Bases 3/4 9 8 5 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required NOVAK.T M Assistant Director for Operating Reactors 80/08/15 fo
- 8009110773 Forwards Tech Spec Page 282 issued w/Anands 56 & 53 to Licenses DPR-38 & DPR-48, respectively on 800808 VARGA,S A Operating Reactors Bianch I 80/08/20 2pp
- --8009110777 Corrected Tech Spec Page 282 to Amends 56 & 53 to Licenses BPR-38 & DPR-48, respectively 4 Operating Reactors Branch (80/08/20 ip
- 8007150424 Act receipt of 800814 ltr re route approval for shipment of spent fuel rods Fee will be determined by prof manhours expended to conduct review HEISS.D License Fee Management Branch 80/08/22 1p
- 8009100007 Notification of 800827 meeting w/util in Bethesda.KD to ailow util to respond to interim technical rept on equipment environ qualifications PEEVES.E Operating Reactors Branch i 80/08/25 ip
- 8009030499 Forwards response to 800229 confirmatory order re Explementation of A-month items Response includes LER review & evaluation of reliability & failure modes of selected sys & components NAUGHTON IS F Commonwealth Edison Co 80/08/29 33pp.
- --8009030440 "Gifsite Dose Cairviation Sys " Compliance study re Item F 3 of 800229 confirmatory order enci GGLDERIJ C Commonwealth Edison Co BRADLEY, J P. Murray & Trettei, inc LAHTI, G P Sargent & Lundy, inc 80/07/31 532pp
- E009120S02 'Rept of Zion/Indian Point Study," Vol 1 MURFIN. II & Sandia Laboratories FIN A-1210 NUREO/CR-1410 VI 60/08/31 400pp
- BOOP080355 Forwards response to NRC BOO702 request for addl info re bacifitting of severe accident mitigation features Oversile drawings available in Central Files only NAUGHTON, N F Commonwealth Edison Co 80/09/03 13pp
- DO9110300 Submits add1 info re NRC 800125 request for util evaluation of asymmetric loads that could develop during LOCA Mechanistic fracture toughness of RCS discussed in Westinghouse 800430 ttr to NRC NAUGHTON.W F Commonwealth Edison Co 80/09/04 2pp
- 3009190468 Forwards addi info required to complete NRC review of util response to NUREC-0578. Items 2 | 8 a 2 2 i 8 b re improved post-accident sampling capability & increased range of radiation monitors respectively Oversize drawing encl.
 NAUCHTONLE Commonwealth Edison Co 80/09/05 4pp
- --8009150474 "Auiiliary Bidg Ethaust Sys Control Diagram " 4 Sargunt & Lundy, Inc 3782 80/07/23 1p
- BOO9230395 Forwards Amends 57 % 54 to Licenses DPR-39 & DPR-48, respectively, safety evaluation & notice of issuance & availability VARGA.S A Operating Reactors Branch 1 80/09/09 2pp
- -8009230390 Amends 57 % 54 to Licenses DPR-39 & DPR-48 respectively, incorporating changes to Tech Specs to allow maint of circulating water pumps during operation VARGA.S A Operating Reactors Branch 1 80/09/09 8pp
 - 09230394 Safety evaluation supporting Amends 57 & 54 to Licenses PR-39 & DPR-48:respectively Operating Reactors Branch 1 80/09/09 4pp
 - 230379 Notice of issuance & availability of Amends 57 & 54 to censes DPR-39 & DPR-4B.respectively RGA.S A Operating Reactors Branch 1 80/09/09 2pp

- 8007180144 Discusses two risk studies currently underway Preliminary assessment of Indian Point risk profile contained in SECY 80-283 Zion risk profile assessment will combine accident sequence evaluation & containment failure analysis ERNST,M L Assistant Director for Tachnology Review 80/07/11
- BOO9190403 Forwards revised portions of inservice valve test program, per 800618 request Revisions do not change typo or method of testing containment isolation valves Contains necessary info for meeting pump & valve inservice testing requirements NAUGHTON.W F Commonwealth Edison Co 90/09/11 83pp
- 8009300099 Forwards safety evaluation re proposed periodic testing performance of diesel generators at facilities Util 800522 request re acceptability of safeguard actuation tests prior to 800519 is acceptable VAROALS A Operating Reactors Branch 1 80/09/11 3pp
- --8009300i01 Safety evaluation supporting proposed periodic testing performance of diesel generators at facilities a Sperating Reactors Branch (80/09/11 2pp
- 8009260213 Advises of delay until 801003 for submittal of Tech Specs upgraded to requirements of STS for Westinghouse PWR in response to NRC 800716 request Review scope & time more extensive than originally planned NAUOHTON, N F Commonwealth Edison Co 80/09/fG 1p
- 8009300267 Forwards "Ropt of Endurance Tests for Auxiliary Feedwater Pumps 1A.18.16:2A.2N.2C.Jan-Jume 1980 " NAUGHTON:N F Commonwealth Edison Co 80/09/23 Ip
- ---8009390273 "Rept of Endurance Tests for Auxiliary Feedwater Pumps iA. 18.iC. 2A. 2D. 2C. Jan-June 1980." • Commonwealth Edison Co 80/06/30 Sipp
- O Inspection reports, iE Bulletins & carrespondence
- 8007020107 Responds to iE Builetin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainloss Steel Pipe " SA-312 pipe not present in operating plants Final confirmation from suppliers anticipated by 800915 re const plant piping sys NAUCHTON.W F Communwealth Edison Co 80/08/07 2pp
- B009190012 Forwards iE insp Repts 50-275/B0-15 & 50-304/B0-19 on B00722 No noncompliance noted FiORELLI.0 Region 3, Chicago. Reactor Construction & Engineering Support Branch B0/08/07 2pp
- --800918002i IE Insp Repts 50-295/80-15 & 50-304/80-15 on 800722 No noncompliance noted Major areas inspected documentation for anstaliation of spent fuel racks & containment liner penetration weids
 DANIELSON.O H. Region 3. Chicago, Reactor Construction & Engineering Support Dranch KEY.W.J. Region 3. Chicago, Office of the Director 80/08/05 6pp
- 800703023i Forwards Revision i to IE Bulietin 80-19, "Failures of Mercury-Netted Matrix Relays in Roactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E " Uritten response required KEPPLER.J & Region 3. Chicago. Office of the Director 80/08/15 ip
- BOO9ii0545 Responds to iE Bulletin 80-08, "Exam of Containment Liner Penetration Welds," supplementing 800709 response Corrects Zion response re rings used for field circumferential butt weid Reviews accuracy of other statements ABEL.J S Commonwealth Edison Co 80/08/15 4pp
- 8007i60681 Submits supplementary response to IE Bulletin 80-08: "Examination of Containment Liner Penetration Welds." correcting statement made in DL Peoples 800709 ltr Further review not necessary ABEL.J 8 Commonwealth Edison Co 80/08/15 4pp
- 8007030126 Forwards 1E Insp Repts 50-275/80-18 & 50-304/80-18 en 800730 & 31 No noncompliance noted HIND.J A Region 3, Chicago. Safeguards Branch 80/08/18 2pp
- --B009030133 IE Insp Repts 50-295/80-18 % 50-304/80-18 on 800730 % 31
 No noncompliance noted Major areas inspected physical
 security, physical barriers & previous insp findings Details
 withheld (ref 100CFR2 790)
 HIND. J A Region 3, Chicago, Safeguards Branch MADEDA, Y J,
 CHRISTOFFER, G Region 3, Chicago, Office of the Director
 80/08/14 1p

- E009290425 Forwards IE Insp Repts 50-295/80-16 & 50-304/80-16 on B00804-05 & notice of violation HEISHMAN R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/08/18 2pp
- --8009290428 Notice of vigiation from insp on 800804-05 a Region 3. Chicaga, Office of the Director 80/08/15 ip
- --8009290436 IE Insp Repts 50-295/80-16 \$ 50-304/80-16 on 800804-05 Noncompliance noted failure to follow licensed operator requalification training program KCHLER, J E , SCHULL, R D , BAKER, K R Region 3, Chicago, Office of the Director 80/08/15 3pp
- 8009250338 Ack receipt b? 800729 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/80-12 & 50-304/80-12 HEISHMANR F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/08/20 Ip
- --8009250344 Forwards response to NRC 800709 ltr re violations noted in IE insp Repts 50-295/80-12 & 50-304/80-12 Corrective actions info tap has been placed on gauge indicating that tank is empty at reading of 6% Recallbr complete by 801231 NAUCHTON.W F Commonwealth Edison Co 80/07/29 3pp
- 8009180551 Forwards IE Carcular 90-18, "iOCFRSO 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/22
- 8009230094 Forwards 1E Info Notice 80-3i. "Maloperation of Gould-Brown Boveri 480 Volt Type K-6005 & K-DON 6008 Circuit Breakers" No written response required KEPPLER, J Q Region 3. Chicago, Office of the Director 80/08/28
- 80091704ii Forwards response to 1E Bulletin 80-15 re possible loss of eaergency notification sys w/loss of offsite power Review revealed inoperability of Dresden sys Investigation being conducted Operating Order 26-80 changed

 JAMACEK, R F Commonwealth Edison Co 80/08/29 4pp
- 8009180466 Responds to 1E Builetin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys identified relays are not used in facility No action required Twenty-four manhours espended on review RAUSCH-T J Commonwealth Edison Co 80/08/29 ip
- BOO9250504 Responds to NRC 791213 request for addl info in response to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Boits " Expansion anchor test results show installation of anchors acceptable JANECEK.R F Communication Edison Co 80/09/05 17pp
- 8009240133 Forwards IE Circuiar 80-21. "Regulation of Refueling Crews " No written response required XEPPLER, J G Region 3, Chicago, Office of the Director 80/09/10 Ip
- 8009260656 Ack receipt of 800819 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/80-05 & 50-304/80-04 KEPPLER, J G Region 3. Chicago, Office of the Director 80/09/10 ip
- --8009260558 Responds to NRC 800727 ltr re violations noted in IE Insp Repts 50-295/80-03 & 50--304/80-04 Corrective actions mgt & mgt support of health physics program reviewed & changed to laplement regulations REED, C Commonwealth Edison Co 80/08/19 10pp
- 8009300200 Forwards response to IE Bulletin 80-20 No Westinghouse Tgps M-2 control switches are used in safety-related sys at Dresden Guad Cities & LaSalle County Responses for Zion & Byron are encl RAUSCH.T J Commonwealth Edison Co 80/09/15 6pp
- R Periodic operating reports & related correspondence
- 8007030441 Forwards semiannual rept of radioactive efficient discharges & solid radwaste for Jan-June 1980 GRAFSSER,K L Commonwealth Edison Co 80/08/07 1p

- 8009090294 Forwards monthly operating repts for Aug 1980 GRAESSER. K. L. Commonwealth Edison Co. 80/09/09 (p
- --8009090278 Monthly operating rept for Aug 1980 COOK.J M Commonwealth Edison Co 80/09/05 tipp
- S Reportable occurrences, LERs 4 related correspondence
- 8009020447 Forwards LER 80 029/03X-1 GRAESSER, K L Commonwealth Edison Co 80/08/04 1
- --8009020455 LER 80-029/03x-l on 800531, while removing insulation to repair leak on discharge time to boric acid filter, heat trace on circuits OME 190/205 were damaged Caused by nicks to heat trace by maint personnel removing pipe insulation HAZELRIGO.8 Commonwealth Edison Co 80/08/04 ip
- 8009120697 Part 21 rept re area monitor countrate assembly RP-2C which has within it electronic parts under excessive strose All purchasers of Class 1E qualified units were notified of potential problem
 RICKARD, C. L. General Atomic Co. (subs. of Oulf Dil Co.) UD/OB/13
 3pp
- 8009020095 Forwards LER 80-026/03L-0 GRAESSER, K L Commonwoalth Edison Co 80/08/14 1p
- --G00902040: LER B0-026/OGL-0 on G00715, during normal operation. Class I pipe tunnel todine monitor IRT-PRO7d failed low Caused by natural end-edf-life of photo-multiplier tube Part replaced Monitor functionally tested & returned to svc AKER.R E Commonwealth Edison Co G0/09/14 lp
- 8009020452 Forwards LER 80-031/03L-0 08AESSER.K L. Commonwealth Edison Co 80/08/19 tp
- --8009020457 LER 80-031/03L-0 on 800718 during normal operation, auxiliary bldg area monitor ORT-AR09 failed law Caused by slight drift in monitor electrical join point Zero point adjusted & monitor functionally tested & returned to svc AKER.R E Commonwealth Edison Co 80/08/15 ip
- 8009120299 Forwards LER 80-003/03L-0 GRAESSER.K L Commonwealth Edison Co 80/08/29 I;
- --8007120331 LER 80-003/ORL-0 on 800802. after OB lake discharge tank rolease was started, personnel noted that liquid selease form did not include sample taken after 2,000 gallons of wastewater were added Gaused by poor communications GURUNATHAN. 8 Commonwealth Edison Co 80/08/29 ip
- 8009120302 Forwards LER 80-004/031-0 GRAESSER.K L Communuealth Edison Co 80/00/29 Lp
- ---8009120324 LER 80-004/03L-0 on 800802.6000 gallons of DA lake discharge tank discharged into lake Caused by value being left open To prevent recursionce discharge valves have been "caution carded"

 OURUNATHAN. 8 Commonwealth Edison Co 80/08/29 Lp
- 8009120305 Forwards LTR 80-006/01T-0 GRAESSER.K L Commonwealth Edison Co 80/09/02 1p
- --B009120320 LER B0-006/01T-0 on B00B21.charcoal filters sorving fuel bldg were not available during nonrefueling modes of operation Caused by improper installation of dampers Dampers reinstalled per original design
 BTAHMER.F Commonwealth Edison Co 80/07/02 tp
- BOO9140400 Forwards LER 80-007/01T-0 GRAEBSER, K L Commonwealth Edison Co 80/09/09 Ip
- --B007i60426 LER B0-007/OiT-O on B00B15 during normal operation while mods were performed on post-LOCA hydrogen recombiner piping, hydrogen purge fan IRV020 was made inoperable Caused by failure of Const Dept to notify Operating Dept of mod POLANSKI, X Communically Edison Ca B0/07/07 2pg
- BOO9220349 Forwards LER BO-03B/O3L-O GRAFBSER: K L Commonwealth Edison Co 80/09/11 ip
- --B009220352 LER B0-038/03L-0 on B00B20, during normal operation, operability surveillance for Pyra-Alarm Dotectors could not be performed in prescribed interval Caused by insufficient amount of test gas to test all alarms

 EVERST. E J Commonwealth Edison Co 80/09/11 1p

- 8007220261 Forwards LER 80-037/03L-0 ORAESSER.K L Commonwealth Edison Co 80/09/12 1p
- ~~8009220207 LER 80-037/03L-0 on 800812 during normal operation while performing monthly functional tests of 63AST reactor trip suitches suitches were set il psig off in nonconservative direction Caused by faulty test gauge CLARX.B Commonwealth Edison Co 80/09/12 ip

V Operator Examinations

- 8009300287 Forwards preliminary topical outlines of proposed modules on thermal hydraulics 3 core damaga mitigation to be included in revised reactor operator training program per NAUGHTON N F Commonwealth Edison Co 80/09/15 7pp
- DOCKET 50-296 GROWNS FERRY NUCLEAR PONER STATION, UNIT 3 F Security, medical, emergency & fire protection plans
- 8009120121 Forwards request for addl info re guard training & qualification Enci withheld (ref 10CFR2 770) IPPOLITO.T A Operating Reactors Branch 2 80/08/22 2pp
- 8009230267 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt usp during emergency O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/22
- 8007250272 Discusses util 800509 response re responsibility matrix of safeguards contingency plan, including Interrelationshipe of contingency actions NRC cannot give formal approval until Info is specifically submitted for approval IPPOLITO, T A Operating Reactors Branch 2 80/09/09 2pp

O Adjudicatory correspondence

- B009220018 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 IPPOLITO, T A Operating fleactors Branch 2 80/08/29 2pp
- --8009220019 Order for mod of Licenses DPR-33.DPR-52 & DPR-68 to add info which fully responds to NRC request for 1nd re snython qualification of safety-related electrical equipment info should be submitted by 80(10) EIEERHUT.DO Division of Licensing 80/08/27 App

I Financial information

- 8007070343 Forwards Annual Financial Rept 1977 CROSS.J.L. Tennessee Valley Authority 80/-60/09/04 ta
- --8007070363 Annual Financial Rept 1979
 * Tennesses Valley Authority 80/09/04, 44pp
- P Operating license stage documents & correspondence
- 8009110554 Supple NRC 800707 request for proposed Tech Specs changes re scram discharge vol vent & drain valves. & reactor protection sys & control rod block limit switch surveillance requirements Class III liconse fee to be submitted w/change EISENHUT.D O Division of Licensing 80/07/22 22pp
- 8009020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENRUT, D Q Division of Licensing 80/07/31 7pp
- 8007090080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities. " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/o NUREO EISENHUT, D O Division of Licensing, 80/08/01 117pp.
- 8009230052 Informs that examption from fee ra licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D O Division of Licensing 80/08/07 60pp

- 8009030406 Application to amend Licenses DPR-33,DPR-52 & DPR-48, changing Tech Specs re containment sys MILLS,L M Tennessee Vailey Authority 80/08/19 2pp
- --8007030411 Proposed Tech Spacs 3 7 & 4 7 re limiting conditions for operation & surveillance requirements for containment sys # Tennossee Valley Authority 80/08/19 47pp
- 8009190697 Forwards NUREO-0661. "Mark I Containment Long-Term Program SER Resolution of Ceneric Technical Activity A-7" Rept discusses generic suppression pool hydrodynamic load definition W/o encl IPPOLITO.T A Operating Reactors Branch 2 80/08/20 2pp
- 8009020069 Application for expedited amend to License DPR-68 Forwards proposed revisions to Tech Specs re residual heat removal sec water sys & standby coolant supply capability Class III fee forthcoming Justification for changes enc!
 MILLS-L M Tennessee Vallay Authority 80/08/26 2pp
- --8009020074 Proposed revisons to Tech Specs re residual heat removal svc uater sys & standby coolant supply capability, Sections 3 5 & 4 5 * Tennessee Valley Authority 80/08/26 5pp
- 8007020406 Application for amend of Licenso DPR-68, changing Tech Specs to accompdate Reload 3, Cycle 4 operation of Unit 3 Shutdown planned for 801020 to begin refueling outage w/restart on 801201 class iII fee encl
 MILLS, L M Tennessee Valley Authority 80/08/27 2pp
- ---8009020409 Proposed Tech Specs 1 2 & 2 2 re RCS integrity & 3 5 & 4 5 re core & containment cooling sys Changes will accommodate Reload 3.Cycle 4 operation

 * Tennessee Valley Authority 80/08/27 14pp
- --8007020412 "Supplemental Reload Licensing Submittal for Browns Ferry Nuclear Power Station Unit 3.Reload 3 " HILF.C L , ENGEL.R E General Electric Co Y1003J01A03 80/08/31 29pp
- 8009030631 Forwards add1 justification for proposed Tech Specs changes in application to amend License DPR-68 submitted by 800826 ltr GROSS, J. L. Tennessee Valley Authority 80/08/28 3pp
- 8009090367 Forwards response to NRC 800425 ltr requesting that util confirm conclusions of analysis re min ECCS equipment availability w/dc power supply failure CROSS.J.L. Tennossee Valley Authority 90/09/03 2pp
- B009090555 Forwards corrected page to proposed Tech Specs 3 7 & 4 7 recontainment sys integrated leak testing, originally submitted on 800819 on account CROSS.J L Tennessee Valley Authority 80/09/03 3pp
- --B009090560 Corrected page to proposed Tech Specs 3 7 & 4 7 recontainment sys integrated leak testing originally submitted on B00819 Tennessee Valley Authority 80/09/03 1p
- 8009120245 Application to amend License DPR-68 Forwards proposed Tech Spec changes reflecting new primary containment atmospheric hydrogen monitoring instrumentation to be installed during upcoming refueling outage Requests approval by 801203 CROSS, J.L. Tennessee Valley Authority 80/09/05 2
- --- 8009120249 Proposed Tech Spec changes re primary containment atmospheric hydrogen monitoring instrumentation to be installed during upcoming refueling outage Bys description & justification enci.

 * Tennessee Valley Authority 80/09/05 5pp
- 8009160219 Forwards changes to Tech Specs Section 6 0 for OL amend re administrative controls in response to NRC 800702 ltr to all BWR licensees Changes are based on model specs provided in Encl i to ltr Fee encl MILLS.L
- --B007160221 Proposed changes to Tech Spec Section 6 0 re administrative controls, based on model specs in NRC 800702 ltr to all BMR licensess Tennessee Valley Authority 80/09/09 9pp
- 8007250324 Forwards Amend 34 to License DPR-68, safety evaluation \$ notice of issuance & availability IPPOLITO, T A Operating Reactors Branch 2 80/09/09 2pp

- --BC09260331 Amend 34 to License DPR-68, changing Tech Specs to permit continued operation following isolation of residual heat removal sec water to Unit 2 residual heat removal heat exchanger

 IPPCLITO Y A Operating Reactors Branch 2 80/09/09 App
- --B009260336 Safety evaluation supporting Amend 34 to License DPR-68 • Operating Reactors Dranch 2 80/09/09 5pp
- --800926034i Notice of issuance & availability of Amend 34 to License DPR-68, IPPDLITO.T A Operating Reactors Branch 2 80/07/09 2pp
- 8009240545 Act receipt of response to NRC 791109 questions re ECC8 evaluation models dealing w/fuel cladding.swelling & incidence of rupture Response is acceptable IPPOLITO.T A Operating Reactors Branch 2 80/09/10 2pp
- 8009240501 Confirms util commitment to NRC 791023 "Interim Position on Containment Purging & Venting Pending Resolution of Isolation Valve Operability "Util position util remain in sffect pending completion of NRC long-term review IPPOLITO, T.A. Operating Reactors Branch 2 80/09/10 2pp
- 8009220210 Notifies that 800731 application to amend Licenses DPR-33, DPR-52 & DPR-68 has not yet appeared as FR notice Info raywested reschedule for licensing & FR notice publication date
 MILLS,L M Tennessee Valley Authority 80/09/16 2pp
- 8009300400 Forwards technical questions re implementation of interim policy on 10GFR50 & 51 MILLS.L M Tennessee Valley Authority 80/09/23 3pp
- 8009300429 Requests notification if concerns re GE GEXL critical power correlation & conservatism in predictions for 8x8 retrofit fuel remain as open item for facility Cycle 4 operation MillS.L # Tennessee Valley Authority 80/09/23 2pp
- 8009300147 Requests amend to DPR-33.DPR-52 & DPR-68.consisting of Tath Spec changes re reactor protection sys MILLS, L M Tennesses Valley Authority 80/09/24 2pp
- --8009300156 Proposed Tech Spacs 1 0.3 3 & 4 3 re reactor protection sys * Tennessae Valley Authority 80/09/24 iSpp
- 8009300333 Revises util 791104 schedule for shipment of motor generator sets to be installed as part of LPCI sys power supply mods Generator sets will be installed during Fall 1980 Unit 3. Bpring 1981 Unit 1 & Bpring 1982 Unit 2 outages MILLB.L M Tennessee Valley Authority 80/09/24 lp
- G Inspection reports, IE Bulletins & correspondence
- 8009090073 Forwards IE Bulletin 80-07, Suppl 1. "BNR Jet Pump Assembly Failure "No response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/13 to
- 8009020184 Submits response to IE Bulletin 79-03A No 8A-312 or A-312. Type 300 series fusion welded pipe is in use or planned for use in safety-related sys MILLS.L M Tennessee Valley Authority 80/08/06 ip
- 8009020222 Forwards IE Insp Repts 50-259/80-32, 50-260/80-25 & 50-276/60-26 on 800628-0704 No noncompliance noted O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/08 2no
- --8009020225 IE Insp Repts 50-259/80-32,50-260/80-25 & 50-296/80-26 un 800628-0704 No noncompliance noted Major areas inspected licensee investigation of Unit 3 failure to fully insert control rods after 800628 scam DANCE, H. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/08/08 18pp
- 800903014A Forwards Revision 1 to IE Bulletin 80-19, "Failures of Harcury-Weited Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J.P Region 2, Atlanta, Office of the Director 80/08/15 in
- BOO7020133 Forwards response to IE Bulletin 80-17. Suppl 1 pe failure of control rods to insert during scram at BWR I tem B 1 scram discharge hander sys will be modified to preclude necessity of level monitoring whereption of instrument vol MILLS, L M Tennessee Valley Authority 80/08/18 2pp

- B009160045 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Stram Function & Nonessential Control Air at Certain OE BUR Facilities "No specific action or response requested O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/19 in
- 8009190603 Ack receipt of 800815 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/80-22, 50-26/80-16 & 50-296/80-17 KERMA, M. B. Region 2. Atlanta, Safeguards Branch 80/08/21 ip
- --8009190610 Forwards response to NRC 800717 ltr re violations noted in 15 Insp Repts 50-259/80-22,50-260/80-16 & 50-296/80-17 Encl Lithheld (ref 10CFR2 790) MILLS.L M Tennessee Valley Authority 80/08/15 ip
- --8009190617 Ack receipt of 800710 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/80-22, 50-260/80-16 & 50-296/80-17 Notes commitment to provide addiresponse within 20 days KENNA, W B Region 2, Atlanta. Safeguards Branch 80/07/17 lp
- --8009190443 Forwards response to NRC 800616 ltr re violations noted in IE lnsp Repts 50-259/80-22,50-260/80-16 & 50-296/80-17 Encl withheld (ref 10CFR2 790) MILLS.L M Tennessee Valley Authority 80/07/10 Ip
- --8009190646 Forwards IE Insp Repts 50-259/80-22.50-260/80-16 & 50-296/80-17 on 800519-23 % notice of violation Notice of violation withheld (ref 100FRZ 790)
 KENNA, W D Region 2. Atlanta. Safeguards Branch 80/06/16 2pp
- --8009190651 IE Insp Repts 50-259/80-22,50-240/80-16 & 50-296/80-17 on 800519-23 Noncompliance noted incomplete vital area barrier, inadequate lock installation & absence of portable radio in vehicle escert Details withheld (ref 100FR2 790) TILLMAN, A. TOBIN, W. J. OILLESPIE, F. P. Region 2. Atlanta, Office of the Director 80/06/16 ip
- 8009120082 Forwards Suppl 3 to 1E Bulletin 80-17, "Failure of Control Rods to Insert During Stram at BWR" Written response required O'REILLY, JP Region 2, Atlanta, Office of the Director 60/08/22 to
- 8009160193 Forwards IE Circular 80-18, "100FR90 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22
- 8009250075 Responds to IE Bulletin 80-14. "Degradation of BUR Scram Discharge Vol Capability " Corrects error in 800728 response re Item A i One instance of broken rod on ball float also occurred MILLS, L M Tennessee Valley Authority 80/08/26 lp
- BOO9120340 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 (K-DDN 6008 Circuit Breakers " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 60/08/27
- 8007230521 Forwards Revision 1 to 1E Bulletin 79-26, "Boron Loss From BMR Control Blades " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/29 ta
- 8009240261 Forwards response to IF Bulletin 80-17 re failure of control rods to fully insert during scram at BWR Plant instructions changed on 800827 to provide for manual scram & functional test Thirty-five manhours expended in bulletin review MILLB.L M Tennessee Valley Authority 80/08/29 3pp
- 8009240383 Forwards response to 1E Bulletin 80-15 re possible loss of mergency notification sys w/loss of offsite power Design change request submitted Administrative procedure issued to comply w/requirements MILLS.L M Tennessee Valley Authority 80/08/29 4pp
- 8009240446 Forwards response to IE Bulletin 80-17 re failure of control rods to fully insert during scram at BMR,Vent mod being coordinated w/overall scram discharge header sys roylew & mod program Schedule estimates will be provided MILLS.L M Tennessee Valley Authority 80/08/29 3pp
- 8009260375 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/10 Sop

- E009300539 Forwards Progress Rept 4 for IE Bulletin 80-06 re angineered safety features reset controls MILLS:L K Tennessee Valley Authority 80/09/10 7pp
- 80093000040 Act receipt of 800819 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-259/80-24, 50-260/89-18 & 50-296/80-19 LEHIS.R C Region 2 Atlanta, Reactor Operations Nuclear Support Branch 80/09/11 ip
- --8009300067 Forwards response to NRC 800724 ltr re violation noted in IE
 Imap Repts 50-239780-24.50-260780-18 & 50-276780-19
 Corrective actions outdated surveillance instruction sheets
 replaced u/current revisions
 MILLS.L & Tennessee Valley Authority 80/08/19 2pp
- --8009300072 Forwards lE Insp Repts 50-259/80-24.59-260/80-18 & 50-296/80-19 on 800363-0601 & notice of violation LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/07/24 2pp
- --800936G075 Notice of violation from insp on 800503-0601
 Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/07/15 19
- --B009300031 IE Insp Repts 50-259/80-24,50-260/80-18 & 50-296/80-19 on 800503-0601 Noncompliance noted failure to use latest revision of surveillance instruction data sheet SULLIVAN, R.F., CHASE. J.W. Region 2, Atlanta, Office of the Director DANCE. H.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/07/15 7pp
- R Periodic operating reports & related correspondence
- 8009110352 Forwards "Radiological Impact Assessment Browns Ferry Nuclear Plant Jan-June 1980 " MILLS.L M Tennessee Valley Authority 80/08/29 1p
- --B009110353 "Radiological Impact Assessment.Browns Ferry Nuclear Plant. Jan-June 1980 " • Tennessee Valley Authority RK-80-5-8F-3 80/08/29 46pp
- BGO9170274 Forwards monthly operating repts for Aug 1980
 ABERCRCM818.H Tennessee Valley Authority 80/09/17 1
- --8009170277 Honthly operating repts for Aug 1980
 ABERCROMBIE.H . THOM.T . GREEN.D Tennessee Valley Authority
 80/09/01 30pp
- S Reportable occurrences. LERs & related correspondence
- 8009190765 PNO-78-147 on 780818 one of six air compressors experienced massive failure resulting in rapid loss of control air pressure to all units Caused by large hole in cylinder head State of AL notified Media attention anticipated KLINGER.G . NOLAN.F . SNIETEK.J Diffice of Inspection & Enforcement, Ofrice of the Director 78/09/18 lp
- 8009190753 Provides interim assessment of PNO-78-147 re partial failure to scram event Margin of safety inherent in licensed design basis should be promptly restored Improved temporary measure acceptable pending permanent mods
 MICHELSON. C Director's Office 80/08/18 3pp
- 8007030577 Forwards LER 80-028/03L-0 CALHOUX: J R Tennessee Valley Authority 80/08/28 19
- --B009030604 LER B0-028/03L-0 on B00806.while performing Special Instructions 4 1 A-7.level switch LIS-3-203C, reactor water level suitch 2.which treps reactor core isolation cooling, found to exceed Tech Spec Idmit Gaused by Instrument drift * Tennessee Valley Authority B0/08/28 2pp
- 8009090314 Forwards LER 80-029/03L-0 CALHGUR.J R Tennessee Valley Authoraty 80/09/04 1p
- --B009090328 LER B0-029/03L-0 on B00802, Surveillance Procedure 2 1 performed w/computer valve improperly set resulting in use of previous day values for mal average planar linear heat generation rate Caused by personnel error

 * Tennessee Valley Authority B0/09/04 2pp
- 8009090332 Forwards LER 80-030/03L-0 CALH9UN, J. R. Tennessee Valley Authority 80/09/05 ip

- --8009090341 LER 80-030/03L-0 on 800813, during normal operation, performing Surveillance Instruction 4 1 A 14, pressure switches PS-1-81-A & PS-1-91-A found set above limits Caused by setpoint drift Switches recallbr & tested * Tennesses Valley Authority 60/09/05 2pp
- 8009160416 Forwards LER 80-031/03L-0 CALHOUN, J R Tennessee Valley Authority 80/09/08 1p
- --8009160422 LER 80-031/03L-0 on 800809.during performance of MRI 303.
 discovered that emergency equipment cooling water flow was
 below min allowed on 38 RHR pump seal heat exchanger Caused
 by mud & shells restricting flow in piping inlet
 # Yennessee Valley Authority 80/09/08 2pp
- 8009180441 LER 79-016 has been cancelled COLLINS.M Tennessee Valley Authority 80/09/17 1p
- 8009230674 Forwards LER 80-032/03L-0 CALHOUN, J R Tennessee Valley Authority 80/09/18 1p
- --8009230479 LER 80-032/03L-0 on 800825, while performing reactor core isolation cooling steam line space high temp SI 4 2 8-32, lead wires were accidentally pulled out of speed feedback magnetic pickup connector Caused by personnel error * Tennessee Valley Authority 80/09/18 ip
- 8009230669 Forwards LER 80-034/03L-0 CALHOUN.J R Tennessee Valley Authority 80/09/19 1p
- --8007230675 LER BO-034/03L-O on B00829, during normal operation, investigation of overload for RHR area cooler fans revealed overload for RHR pump area cooler fan 3A was set too high Cause unstated Relay replaced

 * Tennessee Valley Authority 80/09/19 2pp
- 8009300544 Forwards LER 80-035/03L-0 CALHOUN, J R Tennessee Valley Authority 80/09/26 lp
- ---8009300553 LER 80-035/03L-0 on 800901. "A" reactor recirculation pump tripped Caused undetermined Unit load reduced to 700 mW & pump restarted in A-h * Tennessee Valley Authorlty 80/09/26 2pp
- DOCKET 90-297 NORTH CAROLINA STATE UNIV PULSTAR REACTOR
 P Operating license stage documents & correspondence
- 8009300296 Forwards Amend 6 to License R-120 & safety evaluation MILLER, J R Standardization & Special Projects Branch 80/09/17
- --B009300300 Amend 6 to License R-120, revising provisions re quality & form of SNM authorized
 MILLER.J R Standardization & Special Projects Branch 80/09/17
- --8009390301 Safety evaluation supporting Amend 6 to License R-120 MILLER.J R Standardization & Special Projects Branch 80/09/17
- R Periodic operating reports & related correspondence
- E009020352 Forwards "Annual Rept, Jul 1977 to Jul 1980"
 COCKRELL.R O North Carolina State Univ 80/08/27 ip
- --8009020355 "Annual Rept. Jul 1979 to Jul 1980"
 COCKRELL.R G . SRAY.T C North Carolina State Univ 80/08/27
 24pp
- DUCKET 50-298 COOPER NUCLEAR STATION
- F Security, medical, emergency & fire protection plans
- 8009020195 Invites participation in 890822 workshop in Atlanta, GA to solicit comment re proposed functional criteria for emergency response facilities in NUREO-0696 Discussion to include location, size & staffing of emergency ctrs SEYFRIT, K V Region 4, Dalias, Office of the Director 80/08/12 in
- 8009030551 Forwards security plan re guard training & qualification Plan withheld (ref 10CPR2 790) PILANT.J M Nebraska Public Power District 80/08/29 2pp

@ Adjudicatory correspondence

- 8009260596 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 | PPOLITO TA Operating Reactors Branch 2 80/08/29 2pp
- --B009260601 Order for mod of License DPR-46 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 80101
 EISENRUTID 0 Division of Licensing 80/08/29 App
- P Operating license stage documents & correspondence
- 8009110354 Suppls NRC 800707 request for proposed Tech Specs thanges re scram discharge vol vent & drain valves. & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT.D O Division of Licensing 80/07/22 22pp
- BOO9020297 Submits interim criteria for shift staffing to all OL & CP ficensees & applicants.per NRC 800507 itr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D G Division of Licensing 80/07/31 7pp
- BOO9080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/a NUREG EISENHUT.D O. Division of Licensing 80/08/01 119pp
- BQD9230092 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D Q Division of Licensing 80/08/07 60pp
- 8009040176 Requests that Tech Specs be proposed re completed facility mods for fire protection described in Amend 55 to License DPR-46 Forwards STS for guidance 1PPOLIYO.T A Operating Reactors Branch 2 80/08/11 2pp
- --8009040180 STS re fire protection * Westinghouse Electric Corp 79/12/07 15pp
- 8009150503 Forwards NUREO-0661, "Mark I Containment Long-Term Program Safety Evaluation Rept.Resolution of Generic Technical Activity A-7" Rept describes NRC review results & requirements W/o encl
 EPPOLITO.T A Operating Roactors Branch 2 80/08/20 2pp
- 8009190478 Forwards summary rept. "Primary Containment Integrated Leak Rate Test Performed 800523" PILANT, J M Nebraska Public Power District 80/08/27 lp
- --8009190493 "Primary Containment Integrated Leak Rate Test Performed
 - 4 Nebraska Public Power District 80/05/23 150pp
- 8009240644 Confirms util commitment to NRC 791023 "Interim Position on Containment Purging & Venting, Pending Resolution of Isolation Valve Operability "Util position will remain in affect pending completion of NRC long-term review IPPOLITO, T A Operating Reactors Branch 2 80/09/09 2pp
- BOG9240649 Ack receipt of response to NRC 791109 questions re ECCS, evaluation models dealing w/fuel cladding swelling & incidence of rupture Response is acceptable IPPOLITO.T A Operating Reactors Branch 2 80/09/10 2pp
- 8009170287 Informs NRC that acceptance criteria for all startup physics tests have been met PILANT.J M Nebraska Public Power District 80/09/11 ip
- O Inspection reports, IE Bulletins & correspondence
- BOOGGOGOA Forwards IE Bulletin 80-07, Suppl 1, "BWR Jet Pump Assembly Failure" No response required SEYFRIT.K V Region 4, Dallas. Office of the Director 80/05/13
- 8009CB0997 Forwards IE Insp Rept 50-29B/80-10 on 800421 & notice of violation BRCMN.0 D Region 4. Dallas, Fuel Facility & Materials Safety Branch 80/06/17 2pp

- --8009080559 Notice of violation from insp on 800421 * Region 4. Dallas, Office of the Director 80/06/12 ip
- --B009080562 IE lnsp Rept 50-298/80-10 on 800421 Noncompliance noted radwaste shipment in excess of spec % in unapproved package BRONN. G D Region 4. Dallas. Fuel facility & Materials Safety Branch 80/06/12 1p
- --B009080549 Forwards Waste Packaging Insp Rept 15000027/80-54 on 800421 BOOK.H E Region 5. San Francisco. Fuel Facility & Materials Safety Branch B0/05/18 ip
- --8009080566 Waste Packaging Insp Rept 15000027/80-54 on 800421
 Noncompliance noted radwaste shipment in excess of spec & in
 unapproved package
 BOOK.NE E Region 5. San Fiencisco. Fuel Facility & Materials
 Safety Branch THOMAS.R D . BASSIN.N Region 5. San Francisco.
 Office of the Director 80/05/15 12pp
- 8009100674 Advises of 800708 expiration date for Item 2 re lE Mulletin 80-17. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BUR " Addl parameter is being considered to determine pressure variation during test scrams
 SEYFRIT, K V Region 4, Dallas, Office of the Director 80/07/07 ip
- --8009100677 Forwards IE Bulletin 80-17. 'Failure of 74 of 185 Control Rods to Fully Insert During Sciam at BWR " Written response required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/07/03
- GOO9100031 Responds to IE Bulletin GO-OB, 'Examination of Containment Liner Penetration Welds "Penetration weld adequacy assured by length of weld sycitest results show weld root & final pass soundness & acceptance not based on ultiasons; tests PILANT, J M Nebraska Public Power District 80/07/08 Bpp
- 8009180115 Forwards Suppl 1 to IE Bulletin 80-17, "Failure of 76 of 183 Control Rods to Fully Insert During Scram at BNR " No written response required SEYFRIT.K V Region 4. Dailas. Office of the Director 80/07/18
- 8009180117 Forwards Suppl 2 to IE Builstin 80-17, "Failures Revealed by Yesting Subesequent to Failure of Control Rods to Insert During Scram at SNR" Uritten response required SEYFRIT,X V Region 4, Dallas, Office of the Director 80/07/22 Ip
- 8009020102 Responds to IE Bulletin 80-16 re Rosemount, Inc pressura transmitter misapplication Feedwater flow transmitters indirectly safety-related & used primarily for plant startup & shutdown Erromeous indiration not expected PILANT.J H Nebraska Public Power District 80/07/24 4pp
- 8009020098 Responds to 1E Bulletin 80-17.Suppl 2.re failure of control rods to insert during scram Swing check valve operation checked daily 8 meets positive venting requirement PILANT.J M Nebraska Public Power District 80/07/28 1p
- 8069020539 Forwards supplemental IE Into Notice 80-06. "Notification of Significant Events at Operating Power Reactor Facilities"
 No written response required
 SEYFRIT, K V Region 4. Dalles, Office of the Director 80/07/29
- 8009020101 Rosponds to IE Bulletin 80-17, re failure of control rods to insert during scram Forwards special test procedure 80-9 sequence of events indicating that all equipment performed as designed \$ no corrective action necessary PILANT.J 11 Nebraska Public Power District 80/07/30 5pp
- 8009180108 Forwards IE Bulletin 80-20, "Fallures of Westinghouse Type W-2 Spring Return to Neutral Control Switches" (Pritten response required SEYFRITIK V Region 4, Dalles, Office of the Director 80/07/31
- 8009180157 Forwards IE Bulletin 80-19, "Failure of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E "Written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/07/31
- 8009260291 Forwards IE Info Notice 80-29, "Broten Studs on Terry Turbine Steam Inlet Flange" No written response required SEYPRIT,K V Region 4, Dallas, Office of the Director 80/08/07 Ip

- 009100842 Ack receipt of 800805 ltr informing NRC of steps taken to correct violations noted in LE lisp Rept 50-298/80-09 HADSEN,G L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/08/13 ip
- --80091^0844 Responds to NRC B00714 ltr re violations noted in IE Insp Rept 80-298/80-09 Corrective actions training session on housekeeping & cleanup conducted for maint personnel PILANT.J M Nebraska Public Power District B0/08/06 3pp
- 009230116 Forwards Revision I to 1E Bulletin 80-19. "Failures of Mercury-Natted Matrix Rolays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Nritten Tesponse required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/08/15
- 009160035 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE BWR Facilities " No specific action or lesponse requested SEY+RIT.K V Region 4. Dallas. Office of the Director 80/08/17
- 2009120026 Forwards Suppl 3 to 12 Bulletin 80-17, "Failure of Control Rods to Ensert During Scram at BHR " Written response required SEYFPIT,X V Region 4. Dailas, Office of the Director 80/08/22
- 3009170399 Forwards IE Circular 80-18 "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required BEY-RII.K V Region 4, Dallas. Office of the Director 80/08/22
- BEY-RITIN V Region 4. Dallas. Office of the Director 80/08/22 lp
- 3009120429 Forwards 1E Info Notice 80-31, "Maloperation of Gould-Brown Dovert ABO Volt Type K-6009 & K-DDN 6009 Circuit Breakers " No written response required SEY/RTI.K V Region 4, Dallas, Office of the Director 80/08/27
- 8009180127 Forwards Revision 1 to 1E Bulletin 79-26, "Boron Loss From BUR Control Blades" Written response required BEYRIT.X V Region 4, Dallas, Office of the Director 80/08/29
- GOO9300605 Requests site orientation relevant to issuance of badges, escort dutios & mergency evacuation be afforded NRC personnel listed on enclosure GEVFRIT.X V Region 4. Dallas. Office of the Director GO/09/05
- R Periodic operating reports 3 related correspondence
- 8009160262 Forwards monthly operating rept for Aug 1980 LESSOR, L. C. Nebraska Public Power District 80/09/04 (p
- 8009260282 Forwards "Symjannual Operating Rept Radio4ctive Efluants,' for Jan-June 1980 PILANT, M Nebraska Public Power District 80/09/10 2pp
- --8009260784 "Semiannual Operating Rept Radioactive Effluents," for Jan-June 1980 KFAY,N S . EVANS,A K Hazleton Laboratories, Inc. 80/08/26
- 9 Reportable occurrences, LERs & related correspondence
- 9009050260 Forwards LER 80-028/03L-0 LESSOR,L C Nebraska Public Power Distilct 80/08/11 2pp
- -8009050264 LER 80-028/03L-0 on 800713 while increasing power during normal operation. GE reactor vent monitor failed downscale Caused by two failed capacitors New capacitors installed & unit returned to operable status

 SCHEER, J. L. Nebraska Public Power District 80/08/11 1p
 - 050326 Forwards LER 80-029/03L-0 580R.L C Nebraska Public Power District 80/08/12 2pp

- --B009090331 LER B0-029/03L-0 on B00723, during performance of EP & 4 5 i0.fire hydrant HT-1 could not be opened Caused by broken stem top section Section replaced & personnel instructed to avoid using unnecessary force when closing ALLEN.M D Nebraska Public Power District 80/08/12 1p
- 8009050252 Forwards LER 80-031/01T-0 LEB50R.L C Nebraska Public Power District 80/08/18 2pp
- --8009050255 LER B0-031/03T-0 on 800804, voltage transfents were induced into turbine generator digital electrical hydraulic sys computer Reactor scrammed when MSIVs closed Caused by 345 kV distribution sys line fault SCHEER, J L Nebraska Public Power District 80/09/18 ip
- 8009050187 Forwards updated LER 80-008/03X-1 LESSOR, L C Nebraska Public Power District 80/08/20 3pp.
- --8009050190 Updated LER 80-008/03X-1 on 800312, during scheduled lisp of reactor core isolation cooling turbine, two damaged buckets on wheel were discovered Caused by nonimpact type impingement of foreign object on wheel FLANNIGAN, R D Nebraska Public Power District 80/08/20 ip
- 8007030284 Forwards LER 80-030/03L-0 LESSOR, L C Nebraska Public Power District 80/08/21 2pp
- --B0090502B9 LER B0-030/03L-O on B00Bi3, during normal surveillance testing of RHR motor operated valves, RHR loop B suppression pool cooling inboard throttle valve would not operate Caused by failure of key between motor pinion gear & motor shaft DOAN, P F Nebraska Public Power District 80/08/21 lp
- 8009050199 Forwards LER 80-032/03L-0 LESSOR, L C Nebraska Public Power District 80/08/22 2pp
- --8009050203 LER 80-032/03L-0 on 800725 during performance of surveillance procedure 6 2 2 2 1.isolation of HPCI steam line occurred Cause not fully determined Probable cause due to transient in common sensing line LAMPENCE, L. 1 Nebraska Public Power District 80/08/22 ip
- DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8009:10619 Requests participation in study of people-related problems in nuclear safeguards Study involves collection of data on licenses security forces & practices EISENHUT, D.Q. Division of Licensing 80/07/25 2pp
- BOO9030542 Forwards safeguards contingency plan Plan withheld (ref 100FR2 790) BURSTEIN.B Wisconsin Electric Power Co 80/08/22 ip
- BOO92303i4 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Bys installed for govt use during emergency KEPPLER, J G Region 3, Chicago, Office of the Director BO/08/22 Jpp
- 8009260215 Responds to 800822 request for info re emergency notification sys & health physics network & requests clarification of notification requirements FAY, C.W. Wisconsin Electric Power Co. 80/09/05. 3pp
- 8005290177 Forwards security measures for proposed sewage treatment plant Encl withheld (ref 10CFR2 790)
 BURSTERMS Wisconsin Electric Power Co 80/09/19 ip
- Q Adjudicatory correspondence
- 8009190352 Forwards order requiring into supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 CLARKIR A Operating Reactors Branch 3 80/08/29 2pp
- --8009190357 Order for mod of Licenses DPR-24 & DPR-27 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by GOIOI EISENHUT.D O Division of Licensing 80/08/29 App

H General correspondence

- 8009050424 Responds to League Against Nuclear Dangers 800715 itr re relocating local PDR to Two Rivers, WI Two Rivers inbrary will house documents re Wood County special repts NRC 1979 Annual Rept encl SCUDER, J. L. Division of Rules and Records 80/08/15 2200
- --B009030426 Requests submitted on behalf of League Against Nuclear Dangers, concerning relocation of local PDR to Manitowoc, WI Lists types of documents & specific documents that should be retained at Univ of KI library DIXON, O Affiliation Unknown 80/07/18 3pp
- 8009110411 Requests establishment of LPDR in Madison.WI, on behalf of WI Public Svc Commission State agency personnel will review raplacement of steam generators at Point Beach Unit 1 in 1981 or 92 Related correspondence YORK.5. PARSONS.E M., NUNNERY, W. J. Wisconsin, State of 80/08/26 208
- 6009260187 Forwards FR notice of relocation of facility LPDR from Univ of WI Library, Stevens Point to Joseph Mann Library, Two Rivers, WI FELTON, J & Division of Rules and Records 80/09/09 2pp
- P Operating license stage documents & correspondence
- 8009020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Dsvelopment & Implementation to be reviewed within 90 days EISENHUT.D O Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREO-0296, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0496 encl W/o NUREO EISENHUT, D C Division of Licensing 80/08/01 119pp
- 8007020497 Responds to NRC 800708 itr re weldments in Graver tanks Evaluations show that connections & penetrations would withstand design loading conditions assuming as-found configuration BURSTEIN. S. Wisconsin Electric Power Co. 80/08/04. 3pp
- 8009230052 Informs that examption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disreparded Requested submittal should include proposed class of amend EISENHUT, D Q Division of Licensing 80/08/07 60pp
- 8009190794 Forwards revised Westinghouse STS 3 9 8 2,3 9 10 & Bases 3/4 9 8 & 3/4 9 10 to require 23 ft of water over top of reactor pressure vessei flange during movement of fuel assemblies or control rods Written response required NOVAK: T M Assistant Director for Operating Reactors 80/08/15
- --8009190817 Revised Westinghouse 8T8 3 9 8 2.3 9 10 & Bases 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods

 4 Assistant Director for Operating Reactors 80/06/23 21pp
- 8009120575 Forwards requests for addl info re adequacy of station affectric distribution sys voltages to continue review Response requested within 45 days of itr receipt CLARK.R A Operating Reactors Dranch 3 80/09708 App
- BOO9160442 Responds to NRC BOOB19 ltr re IAEA design info questionnaire to be utilized in submittal of installation info by facilities Compiling data will require significant effort NRC should utilize existing info in files BURBTEIN.B Wisconsin Electric Power Co BO/09/11 ip
- BO09230660 Responds to B00B15 request for review of Tech Spacs & procedures assuring that exposure of fuel assemblies & control rods cannot occup during transfer w/plant in refueling shutdown mode. Changes to Tech Specs unnecessary FAY, C W Wisconsin Elactric Power Co B0/09/15 2pp
- BO09230564 Notifies NRC that util unable to comply w/B00714 request re Tech Specs applicable to implementation of TMI-2 Lessons Learned Category A items Initial review of model Tech Specs completed FAY.C H Wisconsin Electric Power Co 80/09/18 3pp

- BOO9250249 Application to amend Licenses DPR-24 & DPR-27 changing Tech Specs 15 1.15 3 \$ 15 6.re limiting conditions for operations, definitions of operability & administrative structure

 BURBTEIN-S Wisconsin Electric Power Co BO/09/19 3pp
- ~-8009250253 Tech Spec Change Request 64, consisting of proposed Tech Specs 15 i, 15 3 & 15 6 re limiting conditions for operations, definition of operability & administrative structure

 4 Misconsin Electric Power Co 80/09/19 8pp
- 8005290341 Proposed Change 45 modifying 770728 request to amend Licenses DPR-24 5 DPR-27 to incorporate Tech Spec changes Changes modify trip & time delay setting for undervoltage protection circuitry BURSTEIN.8 Wisconsin Electric Power Co 80/09/22 2pp
- --8009290342 Tech Spec change for Item 7 of Table 15 3 5-1 & Item 3e'of Table 15 3 5-3 re time & trip delay settings for undervoltage protection sys * Wisconsin Electric Power Co 80/09/22 2pp
- 8009300461 Forwards comments on draft NUREO-0696. "Functional Criteria for Emergency Response Facilities" NUREO should include alternate methods of satisfying functional requirements FAY.C W Wisconsin Electric Power Co 80/09/22 6pp
- G Inspection reports, IF Builetins & correspondence
- BO09290011 Forwards IE Insp Repts 50-266/80-10 & 50-301/80-10 on B00604-27 & notices of violation, App A & B App B withheid (ref 100FR2 790)
 KEPPLER. J G Region 3, Chicago. Office of the Director RO/08/11 3pp
- --8007270013 Notice of violation, App A, from insp on 800404-27 Region 3, Chicago, Office of the Director 80/08/05 ip
- --8009270015 IE Insp Repts 50-266/80-10 & 50-301/80-10 on 800604-27 & O708 Noncompliance noted RiR pumps operability Impaired & engineered safety feature crosscannected Details withheld (ref 10CFR2 790)
 SMITH.J D. OULDEMOND.W G. WARNICK.R F. Region 3: Chicago, Office of the Director 80/08/05 12pp
- GOD7030219 Forwards Revision 1 to IE Bulletin 80-19, "Fallures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Dosigned by C-E " Written response required KEPPLER.J G Region 9. Chicago. Office of the Director GD/08/15
- 8007270017 Forwards IE Insp Repts 50-266/80-13 & 50-301/80-13 on 800717 & 22 No noncompliance noted DAVIS, A B Region 3, Chicago, fuel Facility & Materials Gafety Branck 80/08/19 2pp
- --8009270018 IE Insp Repts 50-266/80-13 & 50-301/80-13 on 800717 & 22
 No nuncompliance noted Hajor areas inspected confirmatory
 measurements
 JANUSKA; A G , EESIO, T H Region 3, Chicago, Diffice of the Director
 80/08/19 4pp
- 8007180520 Forwards IE Circular 80-18. "10CFR90 57 Bafety Evaluations for Changes to Radwasto Treatment Sys " No written response required KEPPLER, J O Region 3. Chicago, Office of the Director 80/08/22
- 8007110557 Responds to IE Bulletin 80-18, "Maint of Adequate Min Flow Thru Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Corrective actions are not necessary. FAY.C W Wisconsin Electric Power Co 80/08/26, 2pp
- 8009230089 Forwards IE Info Notice 80-31. "Maloperation of Oould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required KEPPLER, J O Region 3. Chicago, Office of the Director 80/08/28
- 8009:80158 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys identified relays not used in facility
 FAY.C.W Wisconsin Electric Power Co 80/08/29 ip

- 8009240124 Forwards IE Carcular 80-21, "Regulation of Refueling Crews" No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/09/10 to
- 8009300305 Responds to 1E Bulletin 80-20 Identifies safety-related equipment control circuits utilizing Hestinghouse Type M-2 switches w/spring-return-to-neutral position All but four circuits have been modified to indicate switch closure BURSTEIM. S Wisconsin Electric Power Co 80/09/16 2pp
- R Periodic operating reports & related correspondence
- 8009090537 Forwards "Semiannual Monitoring Rept, Jan-Jun, 1980 " FAY, C W Wisconsin Electric Power Co 80/08/29 1p
- --8009090545 "Semiannual Monitoring Rept.Jan-Jun. 1980 "

 Wisconsin Electric Power Co 80/08/29 15pp
- 8009160302 Forwards monthly operating repts for Aug 1980 FAV.C W Wisconsin Electric Power Co 80/09/09 Up
- --G009160304 Monthly operating repts for Aug 1980 FAY.C U Wisconsin Electric Power Co 80/09/04 9pp
- U Congressional/Executive Correspondence
- GOOPO20050 Expresses concerns re potential consequences from steam generator tube degradation Full adjudicatory hearing needed Requests to be informed of continuing development STROHL.J. GERGER.D., MOODY.J. Wisconsin, State of BO/08/22 1p
- DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

 F. Sacurity, medical, emergency & rire protection plans
- 8009230258 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency O'REFLLY, J P Region 2, Atlanta, Office of the Director 80/08/22 in
- 8009030230 Responds to NRC 800624 ltm requesting revised site emergency plan Util will submit plan following review of State of FL draft "Radiological Emergency Plan for Fixed Nuclear Facilities: "NUREC-0696 NUREC-0644, Revision 1 BAYNARB, P Y Florida Power Corp 80/08/26 3pp
- 8009180285 Submits security info re safeguards contingency plan Info withheld (ref 10CFR2 790) BAYNARD,P Y Fjorida Power Corp 80/09/15 2pp
- Adjudicatory correspondence
 - D9190375 Forwards order requiring info supporting environ qualification of safety-related electrical equipment acquests submittal of info by 80110!
 REID.R W Operating Reactors Branch 4 80/08/27 2pp
 - 3009190380 Order for mod of License DPR-72 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101 EIGENHUT.D G Division of Licensing 80/08/29 App
- d General correspondence
- 8009020517 FOIA request for four categories of info re facility GIVEL.KIS Affiliation Unknown 80/07/31 ip
- 009020911 Responds to FDIA request for four categories of info re facility Documents re Items 1-3 can be found in PDR No documents were found re Item 4 FELTON. J N Division of Rules and Records 80/08/19 1p
- Operating license stage documents & correspondence
- 19150070 Responds to 800523 recommendations concerning lessons earned from 800224 transient at Crystal River Submits esuits of investigations re use of atmospheric dump valve t Occnee Units 1-61.4R Unit 1.Davis-Nesse Unit 1 & TRI-1 ENTON-H R Office of Nuclear Reactor Regulation, Director 2/07/21 20s

- ---B009150079 Discusses 800226 transient at facility Recommends investigation to determine whether atmospheric dump valve design deficiency is prasent in other BMV plants MICHELSON.C Director's Office B0/05/23 2pp
- B009020297 Submits interim criteria for shift staffing to all DL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENMUT, D & Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for mosting criteria of NUREO-0696 and N/O NUREO EISEMHUT, D G Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TM1-2 Lessons Loarned is unjustified Provious determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D G Division of Licensing 80/08/07 60pp
- B009240611 Add1 F0IA request for documents re-util weld chemistry as surveyed by BBU GIVEL-M S Affiliation Unknown B0/08/25 lp
- 8009190582 Approves of 800730 request for relief from THI Lessons Learned Task Force Item 2 2 1 b S Johnson may be assigned as technical advisor REID.R W Operating Reactors Branch 4 80/09/02 2pp
- BO09090442 Forwards response to NRC BO0701 request for add1 info re fuel assembly holddown springs BAYNARD:P Y Florida Power Corp B0/09/03 5pp
- 8007090278 Forwards evaluation of instrumentation to detect inadequate core cooling Responses to IE Bulletin 79-05C & NUREO-0578, included operator guidelines & evaluation of supplemental instrumentation No add1 instrumentation BAYNARD, P Y Florida Power Corp 80/09/04 24pp
- BO09250427 Informs of acceptability of response to NRC 791107 ltr reportions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture REID:R W Operating Reactors Branch 4 80/09/09 2pp
- BO07240606 Add1 response to FOIA request for documents re weld chemistry at facility as surveyed by 18&W Forwards documents listed in App A Proprietary document is under review FELTON-J II Division of Rules and Records 80/09/ii. 2pp
- --8009240617 Approves 770830 request for withholding info re reactor vessel matl surveillance program from public inspiper 10CFR2 790 Info contains trade secrets or privileged commercial or financial info REID:R W Operating Reactors Branch 4 (Pre 791030). 77/12/07 3pp
- --8009240628 Forwards info re reactor vessel & associated surveillance specimen in response to NRC 770319 request Info contains weld chemistry info taken from existing matl test repts JH Taylor affidavit only encl STEWART. H P Florida Power Corp 77/08/30 2pp
- --8009240634 Affidavit of JH Taylor re procedures & criteria for classifying documents as proprietary (ref 10CFR2 790) TAYLOR, J H Babcock & Wilcox Co 77/08/12 7pp
- 8009170288 Application to amend App A to OL, changing aspects of NUREO-0578 including model license conditions & emergency feedwater initiation & flow monitoring Affidavit & Certificate of 8vc encl BAYNARD.P Y. Fjorida Power Corp 80/09/15 4pp
- --8009170289 Tech Specs 3/4 3-38, requesting changes re model literage conditions, emergency feedwater initiation & flow monitoring, diverse containment isolation & emergency power supply to pressurizer heaters
 + Florida Power Corp 80/09/15 24pp
- @ Inspection reports, IE Bulletins & correspondence
- 8009190786 Forwards response to IE Bulletin 79-018, "Environ Gualification of Class IE Equipment," Items 1-3
 BAYNARD, P Y Florida Power Corp 80/04/21 223pp.

- B009100046 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Changing Pumps Following Secondary Side High Energy Line Rupture " Written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/07/24
- B309150104 Forwards IE insp Rept 50-302/80-26 on 800630-0703 No noncompliance noted LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch B0/07/25 2pp
- --8009150i15 IE Insp Rept 50-302/80-26 on 800430-0703 No noncompliance noted Major areas inspected containment integrated leakage rate testing, safety-related plping support & restraint sys GUICK,D Region 2, Atianta, Reactor Operations Nuclear Support Branch BRODKS,E H Region 2, Atianta, Office of the Director 80/07/24 5pp
- E009030125 Forwards Revision i to IE Bulletin 80-19. "Failures of Marcury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/15 to
- 8009100933 Responds to IE Bulletin 80-19 & Revision 1 re faliure of C-E mercury-wetted matrix relays in reactor protective sys Identified relays are not used in facility Twenty-four manhours expended on review ERICHT.R II Fiorida Power Corp 80/08/21 2pp
- 8009160it3 Forwards IE Circular 80-i8. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REFLLY.J.P Region 2, Atlanta, Office of the Director 80/08/22
- 8009120289 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Rover! 480 Voit Type K-6008 & K-DDN 6008 Circuit Breakers "
 No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/27
- 8009240176 Ack receipt of 800808 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/80-10 STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/08/28 ip
- --8007240184 Responds to NRC 600715 itr re violations noted in IE Insp Rept 50-302/80-i0 Corrective actions implementation of procedures to assure compliance w/requirements for radioactive matl tagging HANCOCK.JA Fiorida Power Corp 80/08/08 2pp
- --8009240189 Forwards IE Insp Rept 50-302/80-10 on 800524-28 & notice of violation STORR.J P Region 2, Atlanta, Fuei Facility & Materiais Safety Branch 80/07/15 2pp
- ---S009240195 IE Insp Rept 50-302/80-10 on 800524-28 Noncompliance noted failure to tag & identify radioactive matl w/appropriate labels FUCKETT.J M Region 2. Atlanta, Office of the Director OtESUN,A F Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 80/07/11 6pp
- 8009170145 Ack receipt of 800829 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-302/80-29 KENNA.H B Region 2. Atlanta. Safeguards Branch 80/09/05 lp
- --8009170147 Forwards IE insp Rept 50-302/80-29 on 800707-11 & notice of violation Notice of violation withheld (ref 10CFR2 790)
 XENNARW B Region 2. Atlanta, Safeguards Branch 80/08/05 2pp
- --8009170152 IE Insp Rept 50-g02/80-29 on 800707-11 Noncompilance noted tamper indicating capability could not be demonstrated for entire alarm sys & required sacurity emergency drill not cansucted Datails withheld (ref 100FR2 790)
 OILLESPIE.F P., HOMELL, J C Region 2, Atlanta, Safeguards Branch 80/08/04 1p
- 8009290274 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/10 San

- 8009300143 Submits response to IE Builetin 80-10 re contamination of nenradioactive sys On 800728, nitrogen sys became contaminated necessitating revised response to bulietin Will require until 801015 to respond to bulletin BAYNARD, P y Florida Power Corp 80/09/10 2pp
- R Periodic operating reports & related correspondence
- 8009030200 Forwards "Effluent & Waste Disposal Semiannual Rept," Jan-June 1980 HANCOCK J A Florida Power Corp 80/08/29 2pp
- --8009030204 "Effluent & Waste Disposal Semiannual Rept." Jan-June 1980 POOLC.D . BAYNARD.P Florida Power Corp 80/08/26 59pp
- 8009220361 Forwards monthly operating rept for Aug 1980 BAYNARD, P Y Fiorida Power Corp 80/09/15 1p
- --8009220365 Monthly operating rept for Aug 1980 CULVER, M W Florida Power Corp 80/09/02 4pp
- S Reportable occurrences, LERs & related correspondence
- 8009020197 Part 21 rept re improper fluid provided w/reactor coolant pump hydraulic shock suppressors fluid will be changed to hydraulic fluid for use in radioactive environs HAMCOCK.J A Florida Power Corp 80/08/07 3pp
- 8009030475 Forwards LER 80-031/04L-0 HANGGCK.J A Florida Power Corp 80/08/29 1p
- --80090304B2 LER 80-03i/04L-0 on 800806, determined that established procedures were not adhered to in carrying out environ monitoring program Caused by contractor errors Procedures for three of eight identified areas will be clarified LANCASTER.K F Florida Power Corp 80/08/25 4pp
- 8009030497 Forwards LER 80-032/03L-0 HANCOCK, J A Florida Power Corp 80/08/29 ip
- ---B009030503 LER 80-032/03L-0 on 800805, while performing special load test, emergency diesel generator 1A tripped when loaded Caused by actuation of field over-current relay below design setpoint Relay adjusted to proper value HEINAMDY. V A Fiorida Power Corp B0/08/28 2pp
- G009030600 Ferwards LER 80-033/03L-0 HANCOCK, J A Florida Power Corp 80/08/29 1p
- --8009030409 LER 80-033/03L-0 on 800803 following routine sampling of core flood tank A sample isolation valve CFV-ii failed to close Caused by failed contact rotor in Limitorque operator Contact rotor 2 replaced % declared operable NEUSCHAEFER: E Florida Power Corp 80/08/28 2pp
- 8009050265 Forwards LER 80-034/04T-0 HANCOCK, J A Florida Power Corp 80/09/02 fp
- --8009050269 LER 80--34/04T-0 on 800820.max clrculating water discharge temp exceeded 103 F for more than three consecutive hours Apparent cause was high temp of intake water ℓ high power levels Temp lowered by increased water flow ℓ reduced load HERNANDEZ.V A Florida Power Corp 80/09/28 2pp
- 8009110337 Forwards LER 79-102/03L~1 HANGOCK, J A Florida Power Corp 80/09/08 ip
- --B009110342 LER 79-102/03L-1 on 791023, following routine sampling of D core flood tank (CFT), B CFT sample isolation valve CFV-12 Uould not close CFT isolation valve CFV-42, in closed position, isolated penetration Cause unknown NEUSCHAEFER, E Florida Power Carp B0/08/29 2pp
- 8009150280 Forwards LER 80-035/03L-0 HANCOCK, J A Florida Power Corp B0/09/11 ip
- ~~8009150282 LER 80~035/03L-0 on 800816, during startup operation, postaccident monitoring instrumentation found inoperable Caused by instrument drift instrumentation recallible & verified operable LANCASTER.K F Florida Power Corp 80/09/08 2pp
- 8009290290 Forwards LER 80-036/03L-0 HANGOCK, J A Fiorida Power Corp 80/09/24 ip

- --B009290305 LEP 80-036/03L-0 on 800927, "8" decay heat pump discharge throatile valve would not control flow in automatic Caused by water in sensing line Operability restored by blowing down sensing line b performing functional check heRNANDEZ, V A Florida Power Corp 80/09/19 2pp
- T Rearing transcripts on non-antitrust matters
- 8009260313 Submittal of prepared testimony for first hearing session No attempts made to provide complete answers to ASLB 800908 menorandun & order re physical separation of IM1 units Certificate of Svc encl Related correspondence TRUMBRIDGE.G F Metropolitan Edison Co 80/09/15 7pp
- --8009260366 "Small Break Operating Quidelines " Related correspondence » Babcock & Milcox Co 69-1106001-00 79/11/30 48pp
- DOCKET 50-304 ZION NUCLEAR POHER STATION. UNIT 2
 F Security, medical, emergency & fire protection plans
- 8009230288 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency KEPPLER, J G Region 3. Chicago, Office of the Director 80/08/22 3pp
- 8009100378 Forwards review of util generating station emergency plan & draft ltr requesting addl info & commitments from util PAGANO,F G Emergency Preparadness Licensing Branch 80/08/28 Son
- G Adjudicatory correspondence
- 8009220089 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 VARGA.S A Operating Reactors Branch 1 80/08/29 Zpp
- --B009220091 Order for mod of Licenses DPR-39 & DPR-48 to add info which fully responds to NRC request for info re environ quaiffication of safety-related electrical equipment info should be submitted by 801101

 EISENNUT.D C Division of Licensing 80/08/29 App
- 8009090471 Forwards AB Johnson testimony, Pages 63-64 & 80-82, due to difficulty in reading original submittal STEPIDE.PP Isham, Lincoln & Beale 80/09/03 1p
- --8009090487 Testimony of AB Johnson re proposed amends to increase spent feel storage capacity Resubmitted Pp 63-64 & 80-82 JOHNSON AB Brookhaven National Laboratory E0/09/03 3pp
- H General correspondence
- 8009180448 Responds to 800319 ltr requesting public debate re issues appropriate to evacuation of large population ctrs near plants
 DENTON, H R Diffice of Nuclear Reactor Regulation, Director, 80/04/21 3pp
- --8009180462 Requests public debate re issues appropriate to evacuation of large population ctrs near plants Expresses confidence in attempts by Commissioners to represent public concerns EMORY. K Affiliation Unknown 80/03/19 ip
- 5009110218 Forwards response to 800728 ltr requesting assistance in answering constituent questions re nuclear power & effects of radiation DIRCKS.W J Office of the Executive Director for Operations 80/09/28 4pp
- P Operating license stage documents & correspondence
- BO09300169 "Rept of Zion/Indian Point Study Vol 2." informal rept STEVENSON.M C Los Alamos Scientific Laboratory FIN A-7015 NUREC/CR-1411 V2 B0/04/30 165pp Available at NTIS
- 8009050032 Discusses void formation in vessel head during 800611 natural circulation cooldown event Requests opinion repotential for voiding phenomenon in Westinghouse designed NBSS CHECK.P S Assistant Director for Plant Systems 80/07/28, 2pp

- 8009020297 Submits interim criteria for shift staffing to all QL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT,D Q Division of Licensing 80/07/31 7pp
- BOD9080380 Forwards dreft NUREG-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 enti M/o NUREO EISENHUT, D G Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TM1-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D O Division of Licensing 80/08/07 40pp
- 8009050528 Forwards Amends 56 & 53 to Licenses DPR-39 & DPR-40, respectively safety evaluation & notice of issuance & availability VAROA.S A Operating Reactors Branch 1 80/08/08 2pp
- --8009050531 Amends 56 & 53 to Licenses DPR-39 & DPR-48 respectively, revising & upgrading certain limiting conditions of operation & associated surveillance requirements for ventilation filter sys VAROA, S A Operating Reactors Branch 1 80/08/08 22pp
- ---8009050534 Safety evaluation supporting Amends 56 & 53 to Licenses

 OPR-39 & DPR-46, respectively

 * Office of Nuclear Reactor Regulation, Director 80/08/08 4pp
- --B009050538 Notice of issuance & availability of Amends 56 & 53 to Licenses DPR-39 & DPR-48, respectively VARGA.5 A Operating Reactors Branch 1 B0/08/08 2pp
- 8009100178 Forwards request for add1 info re bypass & reset of engineered safety features
 NOVAK.T M Assistant Director for Operating Reactors 80/08/14
- 8009190794 Forwards revised Westinghouse ST8 3 9 8 2.3 9 10 & Bases 3/4 9 8 2/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required NOVAK-T M Assistant Director for Operating Reactors 80/08/15
- --B009190B17 Revised Westinghouse STB 3 9 B 2,3 9 10 & Bases 3/4 9 B & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods # Assistant Director for Operating Reactors B0/06/23 21pp.
- 8009110773 Forwards Tech Spec Page 282 issued w/Amends 56 & 53 to Licenses DPR-38 & DPR-48, respectively on 800808 VARGA:8 A Operating Reactors Branch i 80/08/20 2pp
- --8009110777 Corrected Tech Spec Page 282 to Amends 56 & 53 to Licenset DRR-38 5 DRR-48.respectively # Operating Reactors Branch 1 80/08/20, ip
- 8009100007 Notification of 800827 meeting w/util in Bethesda.MD to allow util to respond to interim technical rept on equipment environ qualifications REEVES.E Operating Reactors Branch 1 80/08/25 1p
- BOD9030439 Forwards response to 800229 confirmatory order reimplementation of 6-month items Response Includes LER review & evaluation of reliability & failure modes of selected sys & components NAUGHTON, W.F. Commonwealth Edison Co. 80/08/29. 33pp
- --B009030440 "Offsite Dose Calculation Sys " Compliance study re Item F,3 of 800227 confirmatory order enc! GOLDENIJ C Commonwealth Edison Co BRADLEY, J P Murray & Trettel, Inc. LAHTI.0 P Sargent & Lundy, Inc. 80/07/31, 532pp
- 8009120502 "Rept of Zion/Indian Point Study," Vol 1 MURFIN, W. 8 Sandia Laboratories FIN A-1218 NUREQ/CR-1410 VI 80/08/31 400pp
- 8007080355 Forwards response to NRC 800702 request for add1 info re backfitting of severe accident mitigation features Oversize drawings available in Central Files only NAU0HTON, W F Commonwealth Edison Co 80/07/03 13pp

- 8009110300 Submits addl info re NRC 800125 request for util evaluation of asymmetric loads that could develop during LOCA Mechanistic fracture toughness of RCS discussed in Hestinghouse 800630 ltr to NRC NAUCHTON, W.F. Commonwealth Edison Co. 80/09/04 ≥pp
- 8009190468 Forwards add1 info required to complete NRC review of util response to NUREG-0570 ltems 2 ; 8 a & 2 ; 8 b re improved post-accident sampling capability & increased range of radiation monitors respectively Oversite drawing encl NAUGHTON W F Commonwealth Edison Co 80/09/05 App
- --8009190474 "Auxiliary Bldg Exhaust Sys Control Diagram "
 Sargent & Lundy, Inc. 3782 80/07/23 ip
- 8009230385 Forwards Amends 57 & 54 to Licenses DPR-39 & DPR-48, respectively safety evaluation & notice of issuance & availability VAROA.S A Operating Reactors Branch 1 80/09/09 Zpp
- --E009230390 Amends 57 & 54 to Licenses DPR-39 & DPR-48 respectively, incorporating changes to Tech Specs to allow maint of circulating water pumps during operation VAROALS A Operating Reactors Branch 1 80/09/09 Bpp
- --8009230399 Notice of issuance & availability of Amends 57 & 54 to Licenses DPR-37 & DPR-48, respectively VARGA, 8 A Operating Reactors Branch 1 80/09/09 2pp
- BOOGHO144 Discusses two risk studies currently underway Proliminary assessment of Indian Point risk profile contained in BECY BD-203 Zion risk profile assessment will combine accident sequence evaluation & containment failure analysis EARSTIN L Assistant Director for Technology Review 80/09/11
- BOOTITO403 Forwards revised portions of inservice valve test program, pay 800618 request Revisions do not change type or method of trating containment isolation valves Contains necessary info for meeting pump & valve inservice testing requirements NAUGHTON.W F Commonwealth Edison Co 80/09/11 83pp
- 8609300099 Forwards safety evaluation re proposed periodic testing performance of diesel generafors at facilities Util 800522 request re acceptability of safeguard actuation tests prior to 800519 is acceptable VAROA.S A Operating Reactors Branch 1 80/09/11 3pp
- --8009300101 Safety evaluation supporting proposed periodic testing performance of diesel generators at facilities * Operating Reactors Branch 1 80/09/11 2pp
- 80092&0213 Advises of delay until 801003 for submittal of Tech Bpscs upgraded to requirements of STB for Mostinghouse PMR in response to NRC 800716 request Review scope & time more extensive than originally planned NAUGHTON. H F Commonwealth Edison Co 80/09/18 lp
- 8009300267 Forwards "Rept of Endurance Tests for Auxiliary Feedwater Pueps 1A: 1B:1C:2A, 2D: 2C, Jan-June 1980 " RAUGHTON: W F Commonwealth Edison Co 80/09/23 lp
- --80093C0273 "Rept of Endurance Tests for Auxiliary Feedwater Pumps 1A.1B.1C.2A.2B.2C.Jan-June 1980 " * Commonwealth Edison Co 80/06/30 Sipp.
- O Inspection reports, IE Bulletins & correspondence
- 8009020109 Responds to IE Bulletin 79-03A, "Longitudinal Weld Defects to ASME 8A-312 Type 304 Stainless Steel Pipe " 8A-312 pipe not present in operating plants Final confirmation from suppliers anticipated by 800915 re const plant piping sys NAUGHTON, H F Commonwealth Edison Go 80/08/07 2pp
- 8009180012 Forwards IE Insp Repts 50-295/80-15 & 50-304/80-15 on 800722 No noncompliance noted FIGRELLI.O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/08/07 2pp

- --8009180021 1E Insp Repts 50-295/80-15 & 50-304/80-15 an 800722 No noncompliance noted Major areas inspected documentation for shitaliation of spent fuel racks & containment hiner penetration welds

 OANIELSON, D.H. Region 3, Chicago, Reactor Construction & Engineering Support Branch KEV, U.J. Region 3, Chicago, Office of the Director 80/08/05 6pp
- 8009030231 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Mercury-Ketted Matrix Relays in Reactor Protective Bys of Operating Auctear Power Plants Designed by C-E ' Written response required KEPPLER, J G Region 3, Chicago. Office of the Director 80/09/15 to 10
- 8009:110545 Responds to IE Bulletin 80-08, "Exam of Containment Liner Penetration Wolds," supplementing 800709 response Corrects Zion response re rings used for field (ircumterential butt weld Reviews accuracy of other statements ABEL.J S Commonwealth Edison Co 80/08/15 4pp
- 8009150681 Submits supplementary response to 1E Bulletin 80-08. "Examination of Containment Liner Penetration Welds." correcting statement made in DL Peoples 800709 ltr Further review not necessary ABEL. J 8 Commonwealth Edison Co 80/08/15 4pp
- 8009030126 Forwards IE Insp Repts 50-275/80-18 & 50~304/80-18 on 800730 & 31 No noncompliance noted HIND⋅J A Region 3. Chicago, Safeguards Branch 80/08/18 2pp
- --8007030133 IE insp Repts 50-295/80-18 > 50-304/80-18 on 800730 & 31 No noncompliance noted Major areas inspected physical security, physical barriers & previous insp findings Details withheld (ref 10CFR2 790) HIND. J A Region 3, Chicago, Safeguards Branch MADEDA, T J . CHRISTOFFER, O Region 3, Chicago, Office of the Director 80/08/14 10
- 8009290425 Forwards IE Insp Repts 50-275/80-16 % 59-304/80-16 on 800804-05 % notice of violation HEISHMAN,R F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/08/18 2pp
- --8009290428 Notice of violation from insp on 800804-05 * Region 3. Chicago. Office of the Director 80/08/15 ip
- --8009290436 [E lnsp Repts 30-295/80-16 / 50-304/80-16 on 800804-05 Noncompliance noted failure to follow licensed operator requalification training program KOMLER.J E , SCHWLZ, R D , DAKER,K R Region 3, Chicago, Office of the Director 80/08/15 3pp
- 8009250338 Ack receipt of 800727 itr informing NRC of steps taken to correct violations noted in IE lasp Repts 50-295/80-12 & 50-304/80-12 HEIBHMANR F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/08/20
- ---8009250344 Forwards response to NRC 800709 ltr re violations noted in IE Insp Repts 50-275/80-12 & 50-304/80-12 Corrective actions info tag has been placed on gauge indicating that tank is empty at reading of 6% Recallbr complete by 801231 NAUOHTON, W F Commonwealth Edison Co 80/07/29 3pp
- B0071B0551 Forwards IE Circular 80-18, "10CFR30 59 Safety Evaluations for Changes to Radwaste Treatment Bys " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/08/22 in
- 8009230094 Forwards IE info Notice 80-31, "Maloperation of Gould-Brown Soveri 430 Volt Type K-6005 & K-DON 6006 Circuit Breakers "
 No written response required KEPPLER. J G Region 3. Chicago. Dffice of the Director 80/08/28 in
- 800917041i Forwards response to IE Bulletin 80-15 re possible loss of ømergency notification sys w/loss of affsite gowor Review revealed inoperability of Dresden sys Investigation being conducted Operating Order 26-80 changed JANACEX.R F Commonwealth Edison Co 80/08/27 4pp
- 8009180466 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Identified relays are not used in facility No action required Twenty-four manhours expended on review RAUSCH.T J Commonwealth Edison Co 80/08/29 ip

- G007250504 Responds to NRC 771213 request for addl info in response to IE Bulletin 79-02. "Pipe Support Dase Plate Designs Using Concrete Expansion Anchor Bolts " Expansion anchor test results show installation of anchors acceptable JAMECEK.R F Commonwealth Edison Co 80/09/05 17pp
- 8009240133 Forwards IE Circular 80~21, "Regulation of Refueling Crews" No written response required KEPPLER.J & Region 3, Chicago, Office of the Director 80/09/10 in
- 8009260656 Ack receipt of 800819 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/80-05 & 50-304/80-04 KEPPLER.J O Region 3. Chicago. Office of the Director 80/09/10
- --8007260658 Responds to NRC 860727 ltr re violations noted in IE Insp Repts 30-275/80-05 & 50-304/80-04 Corrective actions mgt & mgt support of health physics program reviewed & changed to implement regulations REED C Commonwealth Edison Co 80/08/19. 10pp
- 8009300200 Forwards response to IE Bulletin 80-20 No Westinghouse Type N-2 control switches are used in safety-related sys at Dresden Juad Cities & LaSalie County Responses for Zion & Byron are encl RAUSCHI J Commonwealth Edison Co 80/09/15 6pp
- R Periodic operating reports & related correspondence
- 8009030441 Forwards semiannual rept of radioactive effluent discharges & solid radwaste for Jan-June 1980 ORAESSER.K.L. Commonwealth Edison Co. 80/08/07 ip
- --8009030444 Semiannual rept of radioactive effluent discharges & solid radwaste for Jam-June 1980 ** Commonwealth Edison Co 80/08/07 35pp
- 6009090294 Forwards monthly operating repts for Aug 1980 GRAFESER.K L. Commonwealth Edison Co. 80/09/05 lp
- ---BOO9090298 Monthly operating rept for Aug 1980 COOK, J K Commonwealth Edison Co 80/09/05 Ilpp
- B Reportable occurrences, LERs & related correspondence
- 8009020276 Forwards LER 80-007/01T-0 GRAEBSER, K L Commonwealth Edison Co 80/08/19 ip
- ---B007020279 LER 80-007/01T-0 on 800803.while performing containment isolation phase A final actuating relay continuity check. isolation valve seal water sys partially actuated. Caused by sloppy tost switch Madei 40703-000R-C Switch to be replaced MADDER, J J Commonwealth Edison Co B0/08/15 2pp
- 8009160293 Forwards LER 80-005/03L-0 GRAEBSER,K L Commonwealth Editor Co 80/09/05 ip
- --8009160305 LER 80-005/03L-0 on 800805.NIS channel 41 declared inoperable due to large incore/excore difference Channel 43 out of exc for maint Plant operated w/min redundancy degree violated Cause unknown Channel 43 returned & 41 removed NEALE.JB Commonwealth Edison Co. 80/09/05 19
- B009220274 Forwards LER 80-021/03L-0 GRAESSER, K L Commenwealth Edison Co 80/09/11 ip
- --8009220278 LER 80-021/03L-0 on 800726, steam generator 2A steam flow channel 2F-5!2 failed to start indicating prior to placing unit on sys grid Caused by low output from square root Extractor 2FM-5!2B(Hagan Model 127-112)
 JENKINS.R A Commonwealth Edison Co 80/09/11 1p
- B009230681 Forwards LER B0-003/03L-0 GRAFSSER, K.L. Commonwealth Edison Co 80/09/15 Ip
- --8007230704 LER 80-003/03L-0 on 800816.MSIV low pressure annunciator alarmed & oil pump would not run Caused by failed control power transformer replaced PRINTZ, T A Commonwealth Edison Co 80/09/15 ip

- V Operator Examinations
- 8009300287 Forwards preliminary topical outlines of proposed modules on thermal hydraulics 2 core damage mitigation to be included in revised reactor operator training program per 800328 request
 NAUDHION N F Commonwealth Edison Co 80/09/15 7pp
- DOCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT
- F Security, medical, emergency & fire protection plans
- 8009230318 Requests that all personnel be reminded of purpose of amergency notification sys & health physics network Sys installed for govt use during emergency KEPPLER. J O Region 3. Chicago. Office of the Director 80/08/22
- 8009180544 Requests interview & visit to facility to discuss security practices & to collect data for study of people-related problems in nuclear safeguards VARGA.B A Operating Reactors Branch i 80/09/05 2pp
- 8009290173 Forwards security guard training & qualification manual Encl withheld (ref 10CFR2 790) MATHEMS,E R Wisconsin Public Service Corp 80/09/24 2pp
- O Adjudicatory correspondence
- 8009230120 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 VARGA.S A Operating Reactors Branch 1 80/08/29 2pp
- --8009230i34 Order for mod of License DPR-43 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment info should be submitted by 801101
 EISENHUT, D 0 Division of Licensing 80/08/29 App
- P Operating license stage documents & correspondence
- BOO9020297 Submits interim criteria for shift staffing to all GL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUF, D Q Division of Licensing 80/07/31 7pp
- BOO9D900BO Forwards draft NUREC-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREC-0696 enci W/o NUREC EISENHUT, D O Division of Licensing 80/08/01 119pp
- GOO9230052 informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT. D G Division of Licensing GO/OB/O7 60pp
- B009100196 Forwards request for addl info re loss of offsite power avents
 VARGA.S A Operating Reactors Branch 1 80/08/14 3pp
- 8009190794 Forwards revised Westinghouse STS 3 9 8 2.3 9 10 & Bases 3/4 9 8 & 3/4 9 10 to require 23 ft of water over top of reactor pressure vessal flange during movement of fuel assemblies or control rods Written response required NOVAK,T M. Assistant Director for Operating Reactors 80/08/15 1p
- --8009190817 Revised Westinghouse STS 3 9 8 2.3 9 10 & Bases 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods # Assistant Director for Operating Reactors 80/06/23 21pp
- 8009100125 Forwards request for addl info re requirements for auxiliary feedwater sys Requests response within 45 days VARGA.S A Operating Reactors Branch 1 80/08/18 9pp.
- BOO9100064 Forwards request for add1 info re adequacy of station electric distribution sys voltages
 VARGA,S A Operating Reactors Branch i BO/OB/21 4pp

- 8009:20511 Requests submittal of Tech Specs defining operability for safety sys Requests submittal within 15 days VARCA, S.A. Operating Reactors Branch 1 80/08/22 2pp
- 800909D355 Forwards "Reactor Containment Bldg Integrated Leak Rate Test - 1980 "
 MATHENS, E R Wisconsin Public Service Corp 80/09/04 ip
- --8009090358 "Reactor Containment Bidg integrated Leak Rate Test 1980 "
 + Wisconsin Public Service Corp * Wisconsin Power % Light Co
 + Madison Gas & Electric Co 80/06/30 33pp
- 8009180504 Forwards request for addl info re degraded grid voltage protection VAROA, S.A. Operating Reactors Branch 1 80/09/05 4pp
- 800911037B Application for Amend 42 to License DPR-43, revising Tech Specs, Bection 6 re administrative controls to reflect reorganization of Nuclear Dept Fee encl MATHENS, E R Wisconsin Public Service Corp 80/09/08 2pp
- --8009110381 Proposed Tech Specs, Section 6 re administrative controls, raflecting reorganization of Nuclear Dept + Wisconsin Public Service Corp S0/09/08 10pp
- Q Inspection reports, IE Bulletins & correspondence
- 8009030323 Forwards IE insp Rept 50-305/80-14 on 800610 & 30 No
- --800903032& iE insp Rept 50-305/80-14 on 800610 & 30 No noncompliance noted Major areas inspected confirmatory measurements including telephone discussion & closeout of results of previous sample collection & submission of spiked samples JANUSKA, A G , ESBIO, T H Region 3. Chicago, Office of the Director 80/07/15 App
- 8009160610 Forwards iE insp Rept 50-305/80-15 on 800602-06,09-10,16-20, 23-27 & 30 & notice of violation HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/07/28 2pp
- -- 8007150514 Notice of violation from insp on 800602-06.09-10.16-20.23-27
 - Region 3. Chicago, Office of the Director 80/07/24 1p
- --8007160616 IE Insp Rept 50-305/80-15 on 800602-06,07-10,16-20,23-27 & 30 Noncompliance noted failure to develop required maint procedure for repairs to residual heat removal pump MARRICK.R F., CHOULES.N C. TAMBLING.T N Region 3, Chicago, Office of the Director 80/07/24 App
- 8007030223 Forwards Ravision 1 to iE Bulletin 80-19. "Failures of Mercury-Watted Matrix Relays in Reactor Protective Sys of Operating Muclear Power Plants Designed by C-E " Written response required, REPPLER, J O Regi Region 3. Chicago, Office of the Director 80/08/15
- 8009150462 Ack receipt of 800801 ltr informing NRC of steps taken to correct violations noted in iE Insp Rept 50-305/80-i3 Ferwards comments re Items 3 & 4, Comments withheld (ref 10CFR2 790) Region 3, Chicago: Safequards Branch 80/08/21 2pp
- --8009150464 Responds to NRC ltr re violations noted in iE insp Rept 50-305/80-13 Corrective actions withheld (ref 10CFR2 790) MATHENS, E R Wisconsin Public Service Corp 80/08/01 ip
- 8007180524 Forwards IE Circular 80-18, "10CFR50 57 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response KEPPLER. J G Region 3, Chicago, Office of the Director 80/08/22
- 8009230057 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover(480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required KEPPLER. J O Region 3, Chicago, Office of the Director 80/08/28
- 8009260061 Clarifies 800713 response to IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas " Tests identified area where alarms were inaudible Design change to install speakers processed MATHEWS, E.R. Wisconsin Public Service Corp. 80/09/04 ip

- 8009260091 Responds to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E "No mercury-wetted relays in Use or planned for use in sys Ten manhours expended MATHEWBLE R Wisconsin Public Service Corp 80/09/04 ip
- 8009240126 Forwards IE Circular 80-21, "Regulation of Refueling Crews "
 No written response requires
 KEPPLER.J G Region 3, Chicago, Office of the Director 80/09/10
- R Periodic operating reports & related correspondence
- 8009030506 Forwards "Semiannual Efficient Release Rept, Jan-June 1980" per Tech Bpec 6 9 requirement MATHEMSE R Wisconsin Public Service Corp 80/08/29 1p
- --8009030512 "Seminannya'i Effluent Release ReptiJan-June 1980 " → Wisconsin Public Service Corp 80/08/27 32pp
- 8009090273 Forwards monthly operating rept for Aug 1980
 MATHEWS E R Wisconsin Public Service Corp 80/09/05 1p
- 80/09/01 5pp
- 8009300425 Advises of changes to efficient b waste disposal semiannual repts previously submitted for 1978 Changes should be made to Pages 1 0.2 0 & 3 0 as indicated MATHEWS.E R Wisconsin Public Service Corp 80/09/25 ip
- S Reportable occurrences, LERs & related correspondence
- 8009240495 Forwards LER 80-031/03L-0 8 updated LER 80-029/01X-1 MATTHEWS, E R Wisconsin Public Service Corp 80/09/19 ip
- --8009240508 LER 80-031/03L-0 on 800822.during hot shutdown & startup after reactor trip caused by lightning strike condensate water storage tank level went below Tech Spec limit Caused by water usage coincident w/demineralizer regeneration SMOXER.C S Wisconsin Public Service Corp 80/09/19 lp
- --8007240701 Updated LER 80-027/01X-1 on 800715. w/facility at 100% power, charcoal filter samples taken from Train III of spent fuel pit sweep ventilation sys failed to demonstrate 90% iodine removal efficiency Gaused by natural degradation EMDKER, C.B. Wisconsin Public Service Corp. 80/09/15 1p
- DOCKET 50-306 PRAIRIC ISLAND NUCLEAR STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8007240239 Forwards Health Physics Appraisal Repts 50-282/80-08 & 50-306/80-09 on 800509-15, notice of violation & significant appraisal findings KEPPLER.J G Region 3, Chicago, Office of the Director 80/08/12
- --8007240246 Notice of violation from health physics appraisal on 800905-15 # Region 3, Chicago, Office of the Director 80/08/11 1p
- --8009240255 Health Physics Appraisal Repts 50-282/80-08 & 50-304/80-09 on 800508-15 Noncompliance nated inadequate radiation survey instrument use in high radiation area & inadequate offshift chemistry & radiation protection coverage FISHER: W. Region 3. Chicago. Fuel Facility & Materials Safety Branch GRECER.LR. JANUSKA.A O Region 3. Chicago. Office of the Director 80/08/11 30pp
- 800B2002B2 Forwards final draft of upgraded emergency plan, consisting of corporate nuclear & plant emergency plans Delay in submittal due to incorporation of new 10CFR50 rules MAYER, L O Northern States Power Co 80/08/15 ip
- --8008200284 Final draft of upgraded emergency plan.consisting of corporate nuclear & plant emergency plans
 * Northern States Power Co 80/08/15 225pp
- 8009230305 Requests that all personnel be reminded of purpose of emergency motification sys & health physics network Sys installed for govt use during emergency KEPPLER.J Q Region 3. Chicago, Office of the Director 80/08/22

- 8009020072 Forwards "Evacuation Time Estimates From Areas Near Prairie Island Nuclear Generating Plant: Revision 1 MAYER.L D Northern States Power Co 80/08/25 1p
- --8009020076 "Evacuation Time Estimates From Areas Near Prairie Island Nuclear Generating Plant: "Revision i Northern States Power Co 80/08/31 18pp
- 8009100930 Transmits emergency planning info to be made available to public at LPDR in Minneapolis.MN W/o encl SOUDER, J L. Public Document Branch 80/09/04 ip
- 8009260016 Transmits emergency planning info to be made available to public at LPDR in Minneapolis, MN W/o encl SOUDER, J L Division of Rules and Records 80/09/11 1p

O Adjudicatory correspondence

- 8009030726 Motion to hold proceedings in abequance until 800923.when MN Pollution Control Agency will act on settlement Settlement if adopted would result in withdrawal of hearing request
 SENECHAL.M E . OLSON, J F . SPANNAUS, W Minnesota, State of 80/08/28 300
- --8009030728 Affidavit stating that proposed cettlement will be placed on next Mi Pollution Control Agency monthly meeting agenda or considered at special meeting for affirmative majority vote of board members URIEMHURST.L J Minnesota, State of 60/08/28 2pp
- 8009190295 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 80i101 CLARK.R A Operating Reactors Branch 3 80/08/27 299
- --8009190304 Order for mod of Licenses DPR-42 & DPR-60 to add info which Trivious Green for moe of Licenses by 12-2 & bra-out of audituity responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101 GISCNHUT, DO Division of Licensing 80/08/29 App
- 8009100429 Response in apposition to State of MN 800828 motion to hold spent fuel pool mod proceeding in abeyance pending MN Poliution Control Agency Board 800923 meeting Accepting settlement during meeting very remote M/Certificate of Svc SILBERGO J E , BERNSTEIN, D L Northern States Power Co SILBERO, J E Ghaw, Pittman, Potts & Trowbridge 80/09/04 7pp
- B009110023 Response in support of State of MV motion to defer ASLB action until B00923 Bettiement, if accepted during MN Pollution Control Agency B00923 meeting, would obviate proceeding Certificate of Svc encl BARTIS C A Hearing Branch 3 80/09/08 2pp
- 8009230625 Memorandum & order granting MN Pollution Control Agency 800828 motion in which deferral of action was requested pending Agency Board 800923 meeting Petitioner shall file reply to util objections by 801001 if settlement rejected LAZD,R M Atomic Safety and Licensing Board Panel 80/09/18 3pp
- 8009300039 Joint motion to terminate proceeding re CL amend application for spent fuel pool storage expansion Agreement incorporating certain language in OL amend has been reached between parties Contentions withdrawn SILBERG, J E Northern States Power Co OLSON, J F Minnesota, State of BARTH, C Hearing Branch 3 80/09/23 3pp
- P Operating license stage documents & correspondence
- B009020297 Submits interim criteria for shift staffing to all OL & CP licensess & applicants, per NRC B00507 itr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISSNHUT, D Q Division of Licensing B0/07/31 7pp
- 8009080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 enci H/o NUREO EISENHUT, D O Division of Licensing 80/08/01 119pp
- 8009230052 informs that exemption from fee re licensing action DOYACHURAC Informs that exemption from the re incoming active associated w/FMT-2 Lessons Learned is unjustified. Previous determination should be disregarded Requested submittal should include proposed class of amend CISENHUT, D 0 Division of Licensing 80/08/07 60pp

- 8009190794 Forwards revised Westinghouse 8T8 3 9 8 2.3 9 10 % Bases 3/4 9 8 % 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Mritten response required NDVAK.T M Assistant Director for Operating Reactors 80/08/15
- --B009190817 Revised Nestinghouse STS 3 9 9 2.3 9 10 & Bases 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Assistant Director for Operating Reactors 80/06/23 21pp
- 8009190745 Discusses review of util 800611 response to NRC 800507 ltr identifying five new TMI-2 requirements Review based on HR Danton 800328 ltr re qualifications of reactor operators Item (I) A la does not satisfy criteria COLLINS.P F Operator Licensing Branch 80/08/25 2pp
- 8009170082 Forwards Amends 42 & 36 to Licenses DPR-42 & DPR-60, pectively.EIA & notice of issuance & availability RK.R A Operating Reactors Branch 3 80/08/27 3pp
- --8009170099 Amends 42 & 36 to Licenses DPR-42 & DPR-60, respectively. changing Tech Specs. App B. to permit addition of chlorination program for circulating water sys in order to destroy program for tirebain sys parasitic amoebain sys CLARK, R A Operating Reactors Branch 3 80/08/27
- --8009170089 EIA supporting Amends 42 & 36 to Licenses DPR-42 & DPR-60. respectively

 # Office of Nuclear Reactor Regulation, Director 80/08/27 4pp
- --8009170092 Notice of issuance & availability of Amends 42 & 36 to Licenses DPR-42 & DPR-60, respectively * Operating Reactors Branch 3 80/08/27 ip
- 8009290421 Advises that 79/109 response acceptable re ECCG evaluation models dealing w/fuel cladding swelling & incidence of rupture No further action necessary CLARK,R A Operating Reactors Branch 3 80/09/10 2pp
- 8009;70341 Submits further response to NRC 800805 inquiries re proposed fuel surveillance program for refueling outage Fabrication methods used for gadolinia-bearing rods were typical of production-type fuel Northern States Power Co 80/09/12 3pp.
- B009190481 Notifies of delay until B01114 for submittal of proposed Tech Specs for Lessons Learned Category A requirements, requested by NRC B00702 itr MAYER, L D Northern States Power Co B0/09/12 2pp
- 8009300334 Forwards JC Lehr 800826 memo documenting EIA re 800826 issuance of Amends 42 & 36 to Licenses DPR-42 & DPR-60, respectively MARIIN.R. Operating Reactors Branch 3 80/09/12 1p
- --8009300340 Forwards compilation of telcons re 800821 license amend request Correspondence w/MN Pollution Control Agency & MN Dept of Matl Resources enci.

 LERR, J C Assistant Director for Environmental Technology 80/08/24 7pp
- B009250244 Submits supplemental info to 800506 request for amend to Licenses DPR-42 & DPR-60 re SI actuation & power distribution limits Lists detailed responses to NRC questions MAYER,L O Northern States Power Co 80/09/19 3pp
- G Inspection reports, IE Bulletins & correspondence
- 8009150076 Advises that response to Item 6 of IE Bulletin 79-17.
 Revision 1, was satisfactorily completed on Unit 1 in Jul
 1980 No corrective actions necessary
 01LERTS.D E Northern States Power Co 80/08/14 Ip
- 8007:502:6 Responds to IE Bulletin 80-17 ra failure of mercury-watted matrix relays No relays of type described are used in reactor protection sys at facility OLLBERTS, DE Northern States Power Co 80/08/14 ip.
- 8009260263 Forwards IE Insp Repts 50-282/80-13 & 50-306/80-13 on 800601-0731 No noncompliance noted HEIBHMAN.R F Region 3. Chicago, Reactor Construction & Engineering Bupport Branch 80/08/14 2pp

11

- --B00926027) IE Insp Repts 50-282/B0-13 \$ 50-306/80-13 on 800601-0731
 No noncompliance noted Major areas inspected operation,
 maint surveillance, security & radiation protection
 FELERABEND, C D , BURGES, B L , LITTLE, W S Region 3, Chicago,
 Office of the Director 80/08/11 Gpp
- 8009030210 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER. J G Region 3, Chicago. Office of the Director 80/08, Region 3. Chicago. Office of the Director 80/08/15
- E009310539 Responds to IE Bulletin 80-18, "Possible Disconnect Mode 4 Automation Industries. Inc Model 200-008 Sealed Source & Pigtail Assembly " High injection pumps assured min cooling Ollerns. D E Northern States Power Co 80/08/15 ip
- 6009090019 Submits addl response to IE Bulletin 60-00. "Exam of Containment Liner Penetration Welds" Facility does have containment penetration connections of type doscribed Facility was built to ANSI B31 I. 1967 Summary ropt encl GILBERTS, D. E. Northern States Power Co. 80/08/21 19pp
- 8009170433 Forwards IE Circular 80-18. "10CFR90 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response KEPPLER, J C. Region 3, Chicago, Office of the Director 80/08/22
- BOG9170403 Responds to IE Bulletin 80~19 re possible loss of emergency notification sys wiloss of offsite power New sys will be testalled in Oct 1780 Test will be conducted upon completion of power supply sys Notification made on 800623 QILBERTS, D.E. Northern States Power Co. 80/08/28 2pp
- BOG9230066 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boyeri 480 Volt Tupe K-6005 & K-DDN 6008 Circuit Breakers " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/08/28
- 8009100500 Forwards Revision 5 to "ASME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ASME Code Section XI Requirements"

 KAYERL O Northern States Power Co 80/07/03 2pp
- --8009100505 Revision 5 to "ABME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ABME Code Section XI Requirements " * Northern States Power Co 80/09/03 10pp
- BO09240i12 Forwards IE Circular 80-21. 'Regulation of Refueling Crews " Ro written response required
 #EPFLERJ 0 Region 3. Chicago, Office of the Director 80/09/10
- A Periodic operating reports & related correspondence
- BOO9D90297 Forwards "Effluent & Waste Disposal Bemiannual Rept for Jan-June 1980 -MAYERL D Northern States Power Co 80/08/28 ip
- --8009090302 "Effluent & Waste Disposal Semiannual Rept for Jan-June Northern States Power Co 80/08/28 9pp
- 8009160277 Forwards monthly operating repts for Aug 1780 MAYER.L O Northern States Power Co 80/09/08 ip
- --8009160282 Monthly operating repts for Aug 1980 HUMSTAD A A Northern States Power Co 80/09/01 Spp
- S Reportable occurrences, LERs & related correspondence
- #GO90E0395 Forwards LER 80-022/03L-0
 #MAYER, L 0 Northern States Power Co 80/09/02 in.
- --B0090B0401 LER 80-022/O3L-0 on B00B05 during surveillance test, fan-coil unit dome damper 23 could not be positioned properly Caused by leating air supply line to damper actuator Air supply line replaced HUNSTAD. A A Northern States Power Co 80/09/02 1p
- 8009300551 Forwards updated LER 80-025/01T-1
 MAYER. L D Northern States Power Co 80/09/25 1p

- --8009390558 Updated LER 80-025/01T-1 on 800904.ultrasonic examination of steam generator support bolts revealed that most had crack indications Preliminary cause suggests environmentally assisted cracking HUNSTAD, A A Northern States Power Co 80/09/25 1s
- 8009300573 Environ Event Rept 80-03 on 800820 during special chlorination program, certain levels of chlorine found outside circulating water sys that exceeded concentration limits in Tech Specs 2 4 1 WARD.P C Northern States Power Co 80/09/25 4pp
- DOCKET 50-307 MAINE YANKEE ATOMIC POWER PLANT F Security, medical, emergency & fire protection plans
- 8007230178 Requests that all personnel be remitted of purpose of emergency notification sys 5 health physics network Sys installed for govt use during emergency ORIER.B H Region 1. Philadelphia, Office of the Director 80/08/22 Spp
- 8009170345 Requests assistance of D Orimes &/or T McKenna to meet w/ state nuclear advisory committee re emergency response plan during Oct 1980 BRENNAN, JE Maine, State of 80/09/09 2pp
- O Adjudicatory correspondence
- 8009020417 Order granting extension until 800905 for Commission to review ALAB-602 re spent fuel pool compaction CHILK-S J Office of the Secretary of the Commission 80/08/28
- 8009260602 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by B01101 CLARK, R A Operating Reactors Branch 3 80/08/29 2pp
- ----8009260607 Order for mod of License DPR-36 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101
 EISENHUT, D 0 Division of Licensing 80/08/27 App
- H General correspondence
- 8008120480 Requests info on status of Task A-2. Asymmetric Blowdown Loads on Reactor Primary Coolant Sys Also requests status of problem at ME Yankee GARRETTLE O Affiliation Unknown 80/06/07 lp
- B008120525 Requests info re status of Tash A-17 Also requests info re whether problem has been completely resolved at facility GARREIT, E Q Affiliation Unknown 80/06/07 lp
- 8008120534 Requests info on current status of Task A-40, "Seismic Design Criteria" Also requests knowing if problem at facility has been completely resolved OARRETT,E Q Affiliation Unknown 80/06/07 ip
- BOOB120549 Requests info on current status of Task A-ii. "Reactor Vessel Hatls Toughness " Also requests to be informed if problem at facility has been completely resolved GARRETTLE O Affillation Unknown BO/O6/O7 ip
- 8008120555 Requests info on status of Task A-1, Water Hammer, & resolution of problem at facility.

 GARRETTE O Affiliation Unknown BO/06/07 lp
- 800Bi2054B Ack receipt of 800724 telcon advising that task managers responses to inquiry re generic safety issues would be consolidated into single response Lists three questions applicable to plant Requests response prior to 800815 GARRETT, E. G. Affiliation Unknown 80/07/30 ip
- 8009220067 Responds to 800730 & 800607 itrs re Task Action Plans A-1, A-2, A-11, A-17 & A-40 which may concern facility NUREO-0647.
 "Task Action Plans for Unresolved Safety Issues Re Nuclear Power Plants," provides details of each task action NOVAK.T H Assistant Director for Operating Reactors 80/08/19
- 8009240137 Responds to 800609 ltr to President Carter expressing concerns re lack of evacuation plan & potential increase in spent fuel storage at facility NRC & FEMA are conducting emergency preparedness plan review EISENHUT.D & Division of Licensing 80/09/02 7pp

- 8009240093 Responds to 800703 ltr requesting lists of required improvements to assure that every reactor is safe Reactors operated u/concept of providing minimal risk to health 5 safety of public NOVAK.T M Assistant Director for Operating Reactors E0/09/04
- P Operating license stage documents & correspondence
- 8009020297 Submits interim criteria for shift staffing to all GL & CP licenses & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D O Division of Licensing 80/07/31 7pp
- 8009086080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl H/o NUREG EISEN/
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT. D G Division of Licensing 80/08/07 60pp
- 8009170264 Forwards Amend 49 to License DPR-36.safety evaluation & notice of issuance & availability
 CLARK.R A Operating Reactors Branch 3 80/08/14 2pp
- --8009170267 Amend 49 to License DPR-36, revising Fech Spec Figure 3 10-3 which specifies excore monitor symmetric offset alarm band for LOCA limiting conditions
 CLARK, R A Operating Reactors Branch 3 80/08/14 4pp
- --8009170273 Notice of issuance & availability of Amend 49 to License DRR-36 ENOLEL B Operating Reactors Branch 3 80/08/14 2pp
- 8007110696 Advises that 800520 application submitted as Proposed Change 76 requires Class II fee Requests that fee to remitted promptly MILLEGYN O License Fee Management Oranch 80/08/19 1p
- 8009100425 Forwards payment of license amend fees per NRC determination of options expressed in Footnote 2 to 10CFR170 22 Fee submitted under protest because proposed change consisted of NRC prescribed clarification GROCE, R H. Maine Yankee Atomic Power Co. 80/07/03 3pp
- 8009260197 Advises that util response re ECCS evaluation models, dealing w/fuel cladding swelling & incidence of rupture, is acceptable CLARK, R A Operating Reactors Branch 3 80/09/10 2pp.
- 8009170343 Forwards proposed Tech Spec Change 78 to App A of OL.per NRC B00702 itr to all PHR licensees Also requests amend to implement program to reduce leakage from sys outside containment & to determine airborne rodine concentrations JDHNSQN.W P Maine Yankee Atomic Power Co 80/09/11 4pp
- --8009170347 Proposed Tech Spec Change 78 revising Tech Spec Pages 3 3-1, 3 3-2,3 3-3,3 9-1,3 9-2,4 1-11,4 1-12,4 2-5 & adding new Table 3 9-3,Page 3 9-5 changes incorporate addi TMI-2 Lessons Learned Category A requirements * Haine Yankee Atomic Power Co 80/09/11 9pp
- BO09230584 Forwards revised operational QA program reflecting organizational changes Revised QA program supersedes QA program submitted w/800709 ltr
 THU9LQU,E W Maine Yankes Atomic Power Co 80/09/17 ip
- --8009230591 Operational GA grogram
 LAWTON,R R , FRIZZLE,C D , BANDAZZA,J B Maine Yankee Atomic Power
 Co 80/09/10 68pp .
- G Inspection reports. IE Bulletins & correspondence
- 8007050541 Forwards response to IE Bullettn 80-15 re potential misapplication of Rosemount pressure transmitters No corrective action required MOODY. D.E. Maine Yankee Atomic Power Co. 80/07/29 3pp

- 8009120275 Provides further details & justification for components which do not remain in emergency mode upon reset of engineered safety feature signal.per IE Bulletin 80-04 Circuits for Items 18.19 & 20 will not be modified MODDY.D E Maine Yankee Atomic Power Co 80/07/29 4pp
- 8009080528 Responds to IE Builetin 79-03A Util determined in all (ases pipe wall thickness is based on use of 85% of code allowable MODDY, D.E. Maine Yankee Atomic Power Co. 80/07/30 lp
- 8009120207 Responds to IE Bulletin 79-21 re erroneous level indications during accidents due to increase in temp Correction curves for steam generator & pressurizer level instruments developed Application of curves will be completed by 800901 MOODY.D E Maine Yankee Atomic Power Co 80/08/05 2pp
- 8007030095 Forwards Revision 1 to IE Bulletin 80-17, "Fallures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required ORIER.B H Region 1, Philadelphia, Office of the Director 80/08/15 ip
- 8009180015 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required. GRIER.O H Region 1. Philadelphia. Office of the Director BO/08/22 1p
- 8009120186 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DDN 6008 Circuit Breakers" No written response required CRIER, B H Region i, Philadelphia, Office of the Director 80/08/27. ip
- 8009090431 Responds to IE Builetin 80~15, "Possible Loss of Emergency Notification Sys W/Loss of Offsite Power " Direct insprevealed that emergency notification sys was powered from non-vital lighting circuit powered from onsite power.

 JOHNSOLLUP Maine Yankee Atomic Power Co 80/08/28 2pp
- B007240030 Forwards IE Circular 80-21, "Regulation of Refueling Craws" No written response required CRIER, B H Region 1. Philadelphia, Office of the Director 80/09/10 1p
- 8007240362 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matis " No written response required GRIER, B H Region i, Philadelphia, Office of the Director BO/09/12 Ip
- R Periodic operating reports 5 related correspondence
- 8009090468 Forwards "Effluent & Waste Disposal Semiannual Rept.Jan-Jure 1980" GROCE, R H Maine Yankee Atomic Power Co 80/08/29 ip
- --8009090477 "Effluent & Waste Disposal Somiannual Rept.Jan-June 1980" * Maine Yankee Atomic Power Co 80/08/29 7pp
- 8007160257 Forwards monthly operating rept for Aug 1980 MORDY, D E Maine Yankee Atomic Power Co 80/09/11 1;
- --B007i60257 Monthly operating rept for Aug 1780
 BEERS F C Malne Yankee Atomic Power Co B0/09/11 5pp
- 8007230455 Forwards util annual rept re average bay temps for Junt-Ass 1980 at mising zone buogs, submitted to ME Dept of Environ Protection Rept provided per util 800307 commitment OARRITY, J H Maine Yankee Atomic Power Co 80/09/12 3pp
- 8009300426 Forwards Aug 1980 discharge monitoring rept submitted to K Dept of Environ Protection GARRITY, J H Maine Yankee Atomic Power Co 80/09/25 1p
- --8009300430 "Discharge Munitoring Rept. Aug 1980 "
 FLANDERS.W L Maine Yankee Atomic Power Co 80/09/25 5pp
- S Reportable occurrences, LERs & related correspondence
- 8009300600 PND-1-80-129 on 800914.plant was shutdown when one of thris soals failed on three reactor coolant pump Shutdown expected to last until 800918 LAZARUS, W.J., MARTIN, T.T., BRUNNER, E.J., Region 1, Philadelphia. Defice of the Director 80/09/15 1p

- 8009240637 Forwards LER 80-017/03L-0
 H000.E C Mains Yankse Atomic Power Co 80/09/19 ip
- --B009260642 LER 80-017/03L-0 on B00922, boron sample taken at completion of addition to RWST indicated concentration below Tech Spec limit Caused by failure of technician to obtain sufficient sample prior to addition BRINKLER, J E Maine Yankee Atomic Power Co 80/09/19 2pp
- 8009260494 Forwards LER 80-018/03L-0 HGOD, E C Maine Yankee Atomic Power Co 80/09/22 1p
- --8009260503 LER 80-018/03L-0 on 800826, during steady state power operation, w/diesel generator, DO-18, being operated in surveillance mode, DO-18 auto tripped on overspeed Caused by loose overspeed trip switch actuating arm Arm tightened BRINKLER, J E Maine Yankee Atomic Power Co 80/09/22 2pp
- DOCKEY 50-311 BALEM NUCLEAR GENERATING STATION, UNIT 2 E NRC Safety Evaluation Report (SER), sugpls & correspondence
- 8009180170 Forwards Operator Licensing Branch input to SER for full power operation MGGRE,V.A Division of Human Factors Safety 80/09/11 1300
- F Security, medical, emergency & fire protection plans
- SOOB2B0311 Forwards add1 info re NUREG-0674 fire protection requirements that will not be met.as identified in util B00808 % 19 ltrs Add1 justification in support of Implementation schedule & oversized drawings encl MITTL:R L Public Service Electric & Oas Co of New Jersey B0/08/22 12pp
- --8007040374 "Containment Sump Level Transmitter, Installation Detail " Drawing Number 237086-8-9639-IR-IEC-0549-C2/0 * Public Service Electric & Cas Co of New Jersey 60/06/24 ip
- --8009040375 "Auxiliary Bldg.Reactor Containment & Fuel Handling Area. Elevation 100 Ft " Bheet 1 of 1 e Public Service Electric & Cas Co of New Jersey 78/09/01 1p
- -8009040378 "Auxiliary Bldg.Elevation 84 Ft.Reactor Containment 78 Ft & 81 Ft & Fuel Handling Area Elevation 85 Ft & 89 Ft 6 Inches " Sheet 1 of 1 # Public Service Electric & Oas Co of New Jersey 78/09/05 ip
- --B007040379 "Auxiliary Bldg & Reactor Containment Elevation 64 Ft "
- Public Service Electric & Gas Co of New Jersey 78/08/31 ip
- --8009040381 "Auxiliary Bidg & Reactor Containment Elevation 45 Ft & 55 Ft " Sheet 1 of 1 # Public Service Electric & Cas Co of New Jersey 78/08/31 1p
- ---8007040384 "Auxiliary Bidg & Reactor Containment Section A-A " Sheet 1
 - * Public Service Electric & Gas Co of New Jersey 77/01/26 1p
- --8009040385 "Auxiliary Bldg & Reactor Containment, Sections N-D & C-C " Sheet 1 of 1 * Public Service Electric & Gas Co of New Jersey 76/12/29 1p
- ---8009040388 "Reactor Containment Glab at Elevation 78 Ft & Elevation 81 Ft " Sheet 1 of 5 # Public Gervice Electric & Gas Co of New Jersey 75/06/23 1p.
- --8009040392 "Reactor Containment Slab at Elevation 78 Ft & 81 Ft, Sections " Sheet 4 of 5
 # Public Service Electric & Oas Co of New Jersey 70/12/01 1p
- ---8009040394 "Reactor Containment Internal Walls & Reactor Foundation Plan Elevation 90 Ft " Sheet 1 of 15 Public Service Electric & Gas Co of New Jersey 71/07/06 1
- ---8009040396 "Reactor Containment Internel Walls & Reactor Foundation Plan Elevation 94 Ft." as-built Sheet 2 of 15 # Public Service Electric & Gas Co of New Jersey 76/03/23 12
- ---8007040378 "Reactor Containment Internal Walls & Reactor Foundation Plan Elevation 104 Ft " Sheet 3 of 15 * Public Service Electric & Gas Co of New Jersey 74/08/08 1p

- ---B009040379 "Reactor Containment Internal Walls & Reactor Foundation, Sections," as-built Sheet & of 15 4 Public Service Electric & Gas Co of New Jersey 76/03/23 1p
- --BC07040402 "Reactor Containment Internal Walls & Reactor Foundation, Sections " Sheet 5 of 15 * Public Service Electric & Oag Co of New Jersey 75/06/24 1p
- --8009040403 "Reactor Containment, Reactor Pit " Sheet 1 of 2 * Public Service Electric & Gas Co of New Jersey 76/01/28 ip
- ---8009040405 "Reactor Containment,Reactor Pit." as-built Sheet 2 of 2 a Public Service Electric & Gas Co of New Jersey 74/01/29 i
- ---BC09040407 "Reactor Containment Internal Walls & Reactor Foundation. Spections " Sheet 7 of 15 * Public Bervice Electric & Gas Co of New Jersey 71/03/10 1p
- --8007040408 "Reactor Containment Internal Walls & Reactor Foundation, Reinforcement Plans & Sections," as-built Sheet 13 of 15 * Public Service Electric & Gas Co of New Jersey 76/03/22 1p
- ---8007040410 "Reactor Containment Internal Wells & Reactor Foundation. Reinforcement -- Plans & Sections " Sheet 14 of 15 * Public Service Electric & Gas Co or New Jersey 74/03/06 ip
- ---8009040411 "Reactor Containment Drain Trench Elevation 81 Ft & 78 Ft -Sump Pit Elevation 54 Ft & Inches & 72 Ft 7 Inches " Sheet 1 of 1
 - Public Service Electric & Gas Co of New Jersey 77/08/08 1p
- 8009230193 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network 8ys installed for govt use during emergency GRIER, B H Region 1. Philadelphia, Office or the Director 80/08/22 3pp
- 8009190213 Forwards revised implementation schedule for fire protection
- J Insurance & indemnity information
- 8009260460 Forwards Endorsement 2 to MAELU Policy X8-72 CORREA.M A Marsh & McLennan.inc . M & M Nuclear Consultants.inc Div 80/09/19 3pp
- P Operating license stage documents & correspondence
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities "Comments requested within 30 days Praposed implementation schedule for meeting criteria of NUPEO-0696 enci W/o (NUREO EISENNUT), DO Division of Licensing 80/08/01 119pp
- 8009110560 Responds to 800927 ltr re withdrawal of 800914 application for Tech Specs changes Controller will refund fee since application review not started MILLER. N O License Fee Hanagement Branch 80/08/12 lpp
- 8009110725 Notification of 800819 meeting w/util concerning Tech Spec KERRIGAN, J Operating Reactors Branch 3 80/08/19 3pp
- 8009150104 Forwards Amend 2 to License DPR-75, safety evaluation & NOTION TO INTEGRAL PRINCE & AVAILAbility
 DENION, N R Office of Nuclear Reactor Regulation, Director
 80/08/22 3pp
- --8009150109 Amend 2 to License DPR-75 permitting special low power test program to be conducted
 DENTON.HR Office of Nuclear Reactor Regulation, Director
 80/08/22 7pp
- --8009150111 Safety evaluation supporting Amend 2 to License DPR-75
 * Office of Nuclear Reactor Regulation, Director 80/08/22 25pp
- --8009150114 Notice of issuance & availability of Amend 2 to License SCHWENCER.A Licensing Branch 3 80/08/22 2pp

- 8009020237 Commits to installation of seismically & environmentally qualified valve position switches on two pressurizer power operated relief valves following completion of low power testing program SCHNCIDER, F W Public Service Electric & Oas Co of New Jersey 800/00/45
- 800912010B Forwards request for add1 info re salt content of long-term auxiliary feeduater source.per full power license review TEDESCO.R L Assistant Director for Licensing 80/08/26 3pp
- 8009120112 Forwards request for addl info re post-accident iodine sampling & analysis sys & health physics organization,per full power license review YEDESCO.R.L. Assistant Director for Licensing 80/08/26 3pp
- 8009120501 Forwards request for add1 info re RCS vents.por full power license review TEDESCOR L Assistant Director for Licensing 80/08/26 300
- B009190131 Forwards request for additinfoire auxiliary feedwater source to complete evaluation for full power license Util must show discussion presented in 800701 submitted is binding for compositions other than sadium chloride solutions YEBESCO.R L Assistant Director for Licensing 80/08/26 3pp
- 8007040352 Advises that due to internal communications problems, 800328 ltr responding to TMI-2 Lessons Learned Section 2 (Ja., errongeously advised that limit soutches on power operated relief valves were sotsmically & environmentally qualified MITIL, R L Public Service Electric & Oas Co of New Jersey 80/08/20 2pp
- 8007229050 Forwards request for add1 info re upgraded meteorological program turbine discs.containment boundary fracture toughness.cladding sweiling & rupture models relief & safety valve tost requirements & Q-List TEDESCO.R L. Assistant Director for Licensing 80/08/27 11pp
- 8009090332 Submits response to NRC concerns re effects of dissolved solids other than sodium chloride on steam generators as source of auxiliary feedwater HITELR L. Public Service Electric & Gas Co. of New Jersey 80/09/03
- 8009090312 Forwards listing of each regulation in 10CFR20.50 & 100 & description of compliance in license application MITL.R L. Public Bervice Electric & Oas Co. of New Jersey 80/09/03 92pp
- 6007160469 Forwards supplemental ECCS calculations in response to NRC 800829 itr re NUREO-0630 MITTL.R L Public Service Clectric & Oas Co. of New Jersey 80/09/09 3pp
- BOOP190192 Provides responses to NRC BOOR29 request re relief & safety valvo test requirements Util will monitor EPRI program to provide assurance that it is applicable to plant design & qualify RC9 relief & safety valves HITTL.R L Public Service Electric & Gas Co of New Jersey BO/07/05 2pp
- 8009190479 Forwards addl info re RCS vents.per NRC 800826 request MITTLR L Public Sorvice Electric & Gas Co of New Jersey 80/09/05 7pp
- 8009190515 Advises that Restinghouse reviewed facility emergency operating t gover ascension procedures Util incorporated appropriate comments into procedures
 MITTLAR L. Public Service Electric & Gas Co. of New Jersey
 80/09/05 lp
- BOO9160331 Forwards "Natural Circulation Tests " Detailed rept will be incorporated in startup rept following power range testing MIDURA, H J Public Service Electric & Gas Co of New Jersey 80/09/00 1p
- 8009190327 Forwards updated Q-list in response to verbal request & superseding Q-list submitted by 800825 ltr MITTL,R L Public Bervice Electric & Gas Co of New Jersey 80/09/08 5pp

- 8009150401 Requests that util response to NRC 800702 ltr be delayed 90 days after formal issuance of Unit 2 Tech Specs Tech Spec amends per TMI Lessons Learned Category A requirements for Unit i will be implemented after issuance of Unit 2 DL LIBRIZZI.F P Public Service Electric & Oas Co of New Jersey 80/09/09 ip
- 8009180413 Provides supplemental info re facility compliance w/NRC regulations Facility complies w/regulations Util design & review process. GA program & independent review by NRC & ACRS assures protection of public health & safety MITTL.R.L. Public Service Electric & Gas Co. of New Jersey E0/09/09 ip
- 8009;90466 Forwards add1 info re TMI Lessons Learned requirements on primary coolant sources outside containment & noble gas. radioiodine & particulate effluent monitoring Liquid radwaste sys not used to cool core MITTLR L Public Service Electric & Oas Co of New Jersey 80/09/09 6pp
- BOOPIBO45B Advises that util will respond to requirements re MUREQ-OSB3 specified during NRC 80090B-09 audit by 800919 Info will include classification of use by safety significance of items previously identified in util 800825 submittal MITTLE L. Public Service Electric & Qus Co of Naw Jersey 80/09/11 2pp
- 8009190536 Forwards supplemental info re fracture toughness for containment bldg Unit 2:in response to NRC request during review of conformance w/General Design Criterion 51 HITELR L Public Bervice Electric & Qus Co of New Jersey 80/09/11 22pp
- 8009300229 Requests addl info re review of facility for full power license Questions are encl re 800825 updated P-List.Item III D () of KUREO-O694. "TMI-Related Requirements for New OLs" & 800808 & 22 submittals on effluent monitoring sys TENESCO,R L. Assistant Director for Licensing 80/09/13 5pp
- 8005220266 Forwards add1 info to 800825 submittal re containment susp performance in response to NRC 800721 request Adequate guidance is provided to operators for monitoring ECCS Detailed insulation survey & drawings will be provided MITTL-R L Public Service Electric & Oas Co of New Jersey 80/99/17 4pp
- 8009220280 Forwards addl info re equipment qualification, in response to NRC 800908-09 audit request MITTL.R L. Public Service Electric & Oas Co. of New Jersey 80/09/18 86pp
- 8009300513 Notifies that Tech Spec changes recommended by NRC 600815
 1ty are being reviewed Changes will be incorporated upon
 issuance of full power OL Application for license amund will
 not be submitted
 LIBRIZZILF P Public Service Electric & Gas Co of New Jersey
 80/09/22 1p
- 8009290361 Bubmits description of alternative proposal for providing assurance that inadvottent failure of suction valve from auxiliary feedwater storage tank will not result in degraded condition of auxiliary feedwater sys MITTL.R.L. Public Bervice Electric & Oas Co. of New Jersey 80/09/23 Rpp
- B009300512 Ack receipt of 800826 ltr requesting add1 info re collection of loggerhead sea turtles & Kemp Ridley sea turtles Responses enci.
 LIBRIZZI,F P Public Sarvice Electric & Oas Co of New Jersey 80/09/24 1p
- --8009300318 Forwards list of questions re specimens of Atlantic loggerhead turtle & Kemp Ridley sea turtle Response requested within 30 days of roceipt of 1tr VAROA.8 A Operating Reactors Branch i 80/08/26 19pp
- G. Inspection reports. IE Bulletins & correspondence
- 80070805:10 Responds to IE Bulletin 80-05 Per 800606 response, subsequent investigation revealed two additanks which could be subjected to conditions that might cause inward buckling SCHWEIDER: FW. Public Service Electric & Gas Co of New Jersey 80/07/29 ip
- 8009090230 Forwards add1 response to IE Bulletin 79-27 re less or nonclass IE instrumentation Evaluation of feasibility of design mods completed & results encl SCHAEIDER, F # Public Service Electric & Gas Go of New Jersey 80/07/31 900

- 8:007030091 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Marcury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written vasponse required ORIER, B H Region i, Philadelphia, Office of the Director 80/08/15 ip
- 8009180042 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GAIER.8 H Region 1, Philadelphia, Office of the Director EO/08/22 ip
- 8009120206 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required GRIER.8 H Region 1. Philadelphia. Office of the Director 80/08/27 1p
- BOG9110357 Forwards proprietary & nonproprietary responses to IE info Notice 79-37. "Cracking in Low Pressure Turbine Discs " Toughness properties data includes fracture appearance transition temp & upper energy & temp MITLLR L Public Service Electric & Qas Co of New Jersey BD/09/02 46pp
- 8009190396 Advises that 800702 response to IE Bulletin 80-11, "Masonry Wall Design," for Unit 1 is applicable to Unit 2 Min 1 5 factor of safety was used in Item 3, based on prudent engineering judgment MITTL-R L Public Service Electric & Oas Co of New Jersey 80709/05 1p
- 8009240049 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required GRIER, B H Region i, Philadelphia, Office of the Director 80/09/10 ip
- BOO9180455 Forwards updated response to IE Bulletin 79-07. "Selsmic Stress Analysis of Safety-Related Piping " Encl includes summary of analysis & resultant mode Requirements of IE Bulletins 79-07 & 79-14 have been met MITTLER L. Public Service Electric & Gas Go of New Jersey BO/09/11 4pp
- BOD9240335 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Hatis " No written response required GRIER, B K Region 1, Philadelphia, Office of the Director 80/09/12 lp
- R Periodic operating reports & related correspondence
- 8009090313 Forwards monthly operating rept for May 1980 MIDURA: H J. Public Service Electric & Cas Co of New Jersey 80/09/27 1p
- --B009090320 Monthly operating rept for May 1980 HILLERL K. Public Service Electric & Oas Co. of New Jersey B0/08/29 3pp
- 8007180249 Forwards monthly operating rept for Aug 1980 M1DURA, H J. Public Service Electric & Gas Co of New Jersey B0/09/10 1p
- --9009180257 Honthly operating rept for Aug 1980 MILLER,L K Public Service Electric & Oas Co of New Jersey 80/09/10 5pp
- 8 Reportable occurrences, LERs & related correspondence
- BOO9180463 PND-I-80-110 pn 800725. IBEW Union went on strike Unit 1 operations are continuing w/licensed supervisory personnel All phone lines at facility have been disabled BRICOSL.. KEIMIG.R. BRUNNER.E J Region 1. Philadelphia. Office of the Director 80/07/25 ip
- BOC90303B5 Forwards LER 80-021/03L-0 LIBRIZZI.F P Public Service Electric & Gas Co. of New Jersey BO/08/28 2pp
- --8007030591 LER 80-021/03L-0 on 800729, during routine containment entry, latch for exterior would not close Caused by broken latch pin Pin repaired & door retested satisfactorily NEWMALR J Public Service Electric & Gas Co of New Jersey 80/08/28 ip

- 8009030613 Forwards LER 80-020/03L-0 LIBRIZZI,F P Public Service Electric & Gas Co of New Jersey 80/08/28 2pp
- ~-8007030620 LER 80-020/03L-0 on 800729, during routine operation, pressurizer pressure channel 3 would not respond to pressure changes in sys Caused by shorted wire on power supply Power supply repaired NEMMAN, R J Public Service Electric & Gas Co of New Jersey 80/08/28 ip
- 8009090447 Forwards LER 80-024/031-0 LIBR12Z1.F P Public Service Electric & Gas Co of New Jersey 80/08/28 2ps
- --B007670455 LER 80-024/03L-0 on 800801, while withdrawing rods in preparation for entering Mode 2, position indicator read 20 steps lower than bank demand position Caused by equipment failure Individual rod position indicator replaced NFWHAN.R U Public Bervice Electric & Gas Co of New Jersey 80/08/28 1p
- 8009090542 Forwards LER 80-023/03L-0 LIBRIZZI,F P Public Service Electric & Gas Co of New Jørsey 80/08/28 2pp
- --8009090550 LER 80-023/03L-0 on 800731; chemical analysis of refueling water storage tank revealed boron concentration at 1980 ppm Gaused by personnel error Action was taken to increase concentration above min of 2,000 ppm NEWMAN,R J Public Service Electric & Gas Co of New Jersey 80/08/28 lp
- 8009090554 Forwards LER 80-022/03L-0 LIBRIZZI.F P Public Service Electric & Gas Co of New Jersey 80/08/28 2pp
- --8009090558 LER 80-022/03L-0 on 800731, Jacket water heater developed leak which caused jacket water heater for 2A diesel to trip Caused by equipment failure Heater replaced Design change issued for different type heater N-MMAN,R J Public Service Electric & Oas Co of New Jersey 80/08/28 ip
- 8009090437 Forwards LER 80-025/01T-0 LIBRIZZI.F P Public Service Electric & Gas Co of New Jersey 80/09/04 2pp
- --8009090441 LER 80-025/01T-0 on 800822, during review of equipment qualification records, limit switches for power operated relief valves were determined seismically & environmentally unqualified Caused by internal communication problem MURPHY. M J Public Service Electric & Oas Co of New Jersey 80/09/04
- 8009150244 Forwards LER 80-024/03L-0 LIBRIZZI,F P Public Service Electric & Gas Co of New Jersey 80/09/09 Zpp
- --8009150267 LER 80-026/03L-0 on 800811, during review of records, determined that reactor was taken critical w/o performing functional test on source range instruments Caused by personnel error MURPHY, M J Public Service Electric & Oas Co of New Jersey 80/09/09 1p
- 8009160478 Forwards LER 80-027/03L-0 LIBRIZZI.F P Public Service Electric & Oas Co of New Jersey 80/09/11 2pp
- --B0091604B2 LER B0-027/03L-0 on B008I5 during routine operation, auxiliary feedwater storage tank fell below min 200.000 gailon level Caused by throttling inlet valve too far during makeup of steam generators Level restored HURPHYIM J Public Service Electric & Gas Co of New Jersey 80/09/11 1p
- 8009230578 Forwards LER 80-028/03L-0 LIBRIZZI.F P Public Service Electric & Gas Co of New Jersey 80/09/18 2pp
- ~8009230694 LER 80-028/03L-0 on 800820, during surveillance, level in refueling water storage tank found to be below min level Caused by falled hose on temporary demineralizer Storage tank was refilled to greater than min level RANDOLPH.JM Public Service Electric & Gas Co of New Jersey 80/09/18 1p
- # Duke Power Co #0/07/25 2pp

- 8009120669 Refers to 800801 discussion w/J Zupko & 800804 telcon w/F Schneider re training & qualification for position of shift technical advisor Qualifications for position documented in Suppl 4 to facility SER GRIER.B H Region 1. Philadelphia. Office of the Director SPANDOCOS.
- 8009180306 Summary of 800805 meeting w/applicant in Bethesda.MD re operator exam results KERRIGAN, J Licensing Branch 3 80/08/21 App
- 8009110323 Notifies that all reactor operators & senior reactor operators received low power test program training Lists operators not trained because unit talen to Mode 5 operation on 860805 due to control rod drive mechanism vent leakage ECKERT, R M Public Service Electric & Gas Co of New Jersey 80/09/05 lp
- 8009160393 Reconfirms intentions to provide degraded core training to notice of the second and the second second desired the second of the second sec
- 8009230368 Requests waiver of 6-month experience requirement for three interim shirt technical advisors Waiver will expedite licensed operator steffing plan Personnel info encl available in Central Files only LIBRIZZI.F P Public Service Electric & Gas Co. of New Jersey 80/09710 2pp
- DOCKET SO-312 RANCHO SECO NUCLEAR GENERATING STATION F Security, medical, emergency & fire protection plans
- 8009030318 Notifies of 800819.22 \$ 30 regional workshops re development of guidance for acceptable method for coping w/emergencies at facility Requests that representative be sent Subj areas to be discussed include function of facilities & location ENGELKEN.R H. Region 5. San Francisco, Office of the Director 80/08/12 2pp
- 8009020330 Forwards comments on safeguards contingency plan & requests response within 30 days Encl withheld (ref 10CFR2 790)
 NBYAK.T M Assistant Director for Operating Reactors 80/08/14
- 8009230344 Requests that all personnel be reminded of purpose of energency notification sys & health physics network Sys installed for govt use during emergency ENGELKERIAR M Region 5, San Francisco. Office of the Director 80/08/22 3pp
- 8009040400 Advises that guard supervisor position was imadvertently omitted from organizational chart in Attachment 4 of physical security plan 8 Encl 6-3 within security plan implementing procedure 6 WALURIDGE, W C Sacramento Municipal Utility District 80/09/26 Sacramento Municipal Utility District 80/08/26
- 800905023B Requests response to encl comments re facility 790816 guard training & qualification plan Encl withheld (ref 10CFR2 790) REID.R N Operating Reactors Branch 4 80/08/26 3pp
- 8009230765 Notification of 800910 meeting w/util in Silver Spring,MD to discuss security plan related info GARNER.D J Operating Reactors Branch 4 80/09/03 2pp

G Adjudicatory correspondence

- 8009190316 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of into by 80\$101 REID.R (I Operating Reactors Branch 4 80/08/29 3pp
- --BOOP190324 Order for mod of License DPR-54 to add info which fully responds to NRC request for info re environ qualification or safety-related electrical equipment Info should be submitted by BO(101 EISCNHUT,D © Division of Licensing 60/08/29 6pp Division of Licensing 60/08/29 6pp
- 8007070784 Memorandum of law in support of encl findings of fact & conclusions of law filed in response to CA Energy Commission BO0304 findings Urges issuance of order to show cause if revision of Commission 800507 order warranted BAYTER. TA Sacramento Municipal Utility District BAXTER. TA Shaw. Pittman. Potts & Trowbridge 80/07/05 App

- --8009090788 Proposed findings of fact & conclusions of law in response to CA Energy Commission 800804 findings Sufficient actions & mods implemented per Commission 790507 order sufficient Centificate of Svc encl Certificate of Svc encl BAXTER, T A . TRAVIESO-DIAZ Bacramento Municipal Utility District BAXTER, T A . Shaw, Pittman, Potts & Troubridge 80/09/05 58pp
- 8009180431 Order denying SMMD request that Appeal Court take judicial determed until ASLD issues final order Appeal Court retains Jurisdiction over Case 79-7311 U.S. Court of Appeals 9th Circuit 80/09/11 in

H General correspondence

- 8009100457 Ack receipt of 800705 ltr & forwards Friends of the Earth Class 9 petition & Director's decision on petition W/o encl SCHWENCER, A Licensing Branch 2 80/08/27 2pp
- --8009100463 Requests Director's decision on Friends of the Earth petition to consider Class 9 accidents in supplemental EIS FRIESEMA.H P Northwestern Univ 80/07/05 ip
- P Operating license stage documents & correspondence
- 8007190070 Responds to 800523 recommendations concerning lessons learned from 800226 transient at Crystal River Submits results of investigations re use of atmospheric dump valve at Ocanee Units 1-3,AR Unit 1,Davis-Besse Unit 1 & TMI-T DENION,HR Office of Nuclear Reactor Regulation, Director 80/07/21 2pp
- 8009020297 Bubmits interim criteria for shift staffing to all CL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D 0 Division of Licensing 80/07/31 7pp
- 8009020366 "Electrical Instrumentation & Control Aspects of Low Temp Overpressure Mitigating Sys." informal interim rept WEBER.D A EG&O, Inc FIN A-6256 8009020366 80/07/31 16pp
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl M/o NUREO EIEENHUT.D 0 Division of Licensing 80/08/01 119pp
- B009230092 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D G Division of Licensing B0/0B/07 60pp
- 8007050240 Application for Amend 70 to License DPR-54, changing flux-to-flow ratio within reactor core Info supporting proposed amend re thermal hydraulic design & accident & transient analysis encl Sacramento Municipal Utility District 80/08/11 WATTIKOE, J J
- ---8009050241 Proposed revision to Tech Specs, Section 2 re safety limits limiting safety sys settings → Sacramento Municipal Utility District 80/08/11 13pp
- B009030344 Forwards request for add1 info re bypass & reset of engineered safety features Development drawings for switches BLPB-1 & DLPB-2 & relays RPIV/OC & RPIV/RC should be provided NOVAK.T M Assistant Director for Operating Reactors BO/08/14
- B007080433 Forwards rept re results of analysis concerning addless instrumentation to monitor inadequate core cooling WALBRIDGE: W C Sacramento Municipal Utility District 80/08/28
- ---8009080439 "Evaluation of Instrumentation to Detect Inadequate Core Cooling, Prepared for 177 Owners Group " FROITH.D J. SONTRIL.J R., OANTHNER, R W. Babcock & Wilcox Co BO/0B/15 21pp
- 8009170243 Forwards NRC regional evaluation & supporting data re 80092& meeting at util ofcs Draws mgt attention to particular areas of concern re functional design mods. GA audits & training CREMS. J L Region 5. San Francisco, Reactor Operations Nuclear Support Branch 80/08/28 1p

- __E009170244 Advises of Regional Evaluation Review Board 800606
 evaluation of activities for 790605-800605 Urges special
 insp in functional design mods. QA audits & training
 Recommends decrease in functional surveillance testing
 FAULKENGERRY, B. CANTER, H. L. CARNER, D. J. Region S. Gan Francisco.
 Office of the Director 80/08/08 8pp
- 6009180176 Requests add1 info re adequacy of station electrical distribution sys voltage REID.R W Operating Reactors Branch 4 80/09/03 4pp
- BOOTISO540 Forwards response to 800701 request re fuel assembly holddown springs MATTIMOE, J J Sacramento Municipal Utility District 80/09/04 8pp
- 6009160388 Application to amend License DPR-54 Forwards proposed Tech Spec changes limiting outage duration for Inverters A or B not to exceed 48-h MATTHME,J J Bacramento Municipal Utility District 80/09/08 1p
- --8009160392 Proposed Tech Spec changes re limiting outage duration for Inverters A or B not to exceed 48-h • Sacramento Municipal Utility District 80/09/08 2pp
- g009260538 Informs that response to NRC 791109 ltr re portions of ECCS evaluation models dealing w/fuel ciadding sweiling & incidance of rupture is acceptable Util has adequately confirmed representations made by fuel supplier REID.R W Operating Reactors Branch 4 80/09/09 3pp
- BOO9170339 Ac3 receipt of 800801 ltr suggesting that Dept of Consarvation provide NRC w/comments on proposed program of study of impact of recent foothills fault sys DAVIS.JF California. State of 80/09/12 ip
- B309270353 Forwards response to NRC B00903 request for info re adequacy of station ejectrical distribution sys voitage WALBRIDGE,W C Bacramento Municipal Utility District 80/09/22 200
- --8009270356 "Bafety Evaluation & Statement of Staff Positions Relative to Emergency Power Bys for Operating Reactors "

 * Sacramento Municipal Utility District 80/09/22 3pp
- O Inspection reports, IE Bulletins & correspondence
- 8009030189 Responds to IE Builetin 79-02. Buppl 1 & Revision 2, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Bixty-nine supports did not meet required safety factors Mods finished MATTIMOE. J J Sarramento Municipal Utility District 80/06/24 200
- BGO9070512 Forwards revised response to IE Dulletin 80-ii, "Masonry Wall Design " Util 800707 ltr iacking proper jurat statement HALBRIDGE.W C Bacramento Municipal Utility District 60/07/i6 Io
- --8007070813 Revised itr forwarding response to IE Builetin 80-ii.
 "Masonry Rail Design " Ltr is notarized
 WALBRIDDE.W C Sacramento Municipal Utility District 80/07/i6
 32p
- GOO9180628 Confirms 770416 response to IE Bulletin 77-03A, Longitudinal Held Defects in ASME SA-312, Type 304 Stainless Steel Pipe "No SA-312 pipe used or planned for use in safety-related sys At facility MATTINGE, J J Sacramento Municipal Utility District 80/07/30 ip
- 8009260278 Forwards IE Info Notice 80-27, "Broken Studs on Terry Furbine Steam Inlet Flange" No written response required ENGELKEN R H. Region 5, San Francisco, Office of the Director 80/08/07 | Ip
- BOO9120487 Forwards IE Insp Rept 50-312/80-23 on 800701-31 No moncoaptiance moted CREWS,J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/08/14 2pp.
- -- 8009120490 IE lnsp Rept 50-312/80-23 on 800701-31 No noncompliance noted Major areas inspected monthly maintroutine safety operations request & review of plant operations FAULKENEERRY. Region 5. San Francisco, Reactor Operations Huclmar Support Branch CANTER. H. L. O'BRIEN, J. P. Region 5. San Francisco, Office of the Director 80/08/13 14pp

- 8007030287 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required ENGELKEN R M Region 5, San Francisco, Office of the Director BO/08/15 1p
- 8009290407 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs" ENGELKEN:R H Region 3, San Francisco. Office of the Director 80/08/18 4pp
- 8007150510 Forwards IE lnsp Rept 50-312/80-22 on 800727-31 No noncompliance noted Rept withhold (ref 10CFR2 790) NORDEPHAUO.L R Region 5. San Francisco, Safeguards Branch 80/08/20 2pp
- 8009160185 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required ENOELKEN.R H Region 5. San Francisco, Office of the Director 80/08/22 1p
- 8009120465 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 490 Volt Type K-6005 % K-DDN 6008 Circuit Breakers " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/08/27 ip
- 8009240378 Responds to IE Bulletin 80-15 Submits rept re "Possible Loss of Emergency Notification Sys (ENS) w/Loss of Offsite Powor " Sys telephone power supply tested 800715 & ENS functioned properly MALBRIDGE.W C Sacramento Municipal Utility District 80/08/27
- 8009300047 Forwards iE Insp Rept 50-312/80-25 on 800B11-15 No noncompliance noted SPENCER, G & Region 5, San Francisco. Reactor Construction & Engineering Support Branch 80/08/29 2pp
- --8009300054 IE Insp Rept 50-312/80-25 on 8008it-15 No noncompliance noted Major areas inspected activities performed in response to open items from previous inspections inservice inspector revieu NARBUT,PP Region 5, San Francisco. Office of the Director DDDDS,R T Region 5, San Francisco. Reactor Construction & Engineering Support Branch 80/08/26 opp
- R Periodic operating reports & related correspondence
- 800903039 Forwards "Effluent & Wasto Disposal Semiannual Environ Rept. Jan-June 1980 " Summary enci MATTIMOE, J. J. Sacramento Municipal Utility District 80/08/15 2pp
- --8009050344 "Effluent & Waste Disposai Semiannual Environ Rept, Jan-June 1980 "
 - * Sacramento Municipal Utility District 80/08/13 35pp
- 8009160295 Forwards monthly operating ropt for Aug 1980 RODR(GUEZ: R J Sacramento Municipal Utility District 80/09/03 ip
- --8009160297 Monthly operating rept for Aug 1980 CDL018B.R W Bacramento Municipal Utility District 80/09/03, 5pp
- 8009230677 Forwards monthly operating rept for Aug 1980 MOLLINGSMORTH Sacramento Municipal Utility District 80/09/16 20p
- S Reportable occurrences. LERs & related correspondence
- 8009150269 Forwards LER 80-039/01T-0 MATTINDE, J J Sacramento Municipal Utility District 80/09/02 2pp
- --8009150272 LER 80-039/01T-0 on 800813.while proceeding to cold shutdown, reactor protection sys was placed in shutdown bypass mode & nuclear overpower trip setpoint not reduced to less than 5% of rated power Caused by personnel error CCLOMBO.R W Sacramento Municipal Utility District 80/09/02
- 8009260472 Forwards LER 80-040/03L-0 BOSSENMAIER, W Sacramento Municipal Utility District 80/09/12

- --8009260476 LER 80-040/03L-0 on B00812 reactor protection sys channel D trup signal was received Caused by amplifier failure in electronic portion of transmitter Transmitter replaced, callbr, leak tested 8 returned to sec COLCMBO,R W Sacramento Municipal Utility District B0/09/11
- T Hearing transcripts on non-antitrust matters
- 8009260313 Submittal of prepared testimony for first hearing session No attempts made to provide complete answers to ASLG 800908 memorandum & order re physical separation of TM1 units Certificate of Svc encl Related correspondence TROWBRIDGE. G F Metropolitan Edison Co 80/09/i5 7pp
- --8009260366 "Small Break Operating Guidelines " Related correspondence # Babcock & Wilcox Co 69-1106091-00 79/11/30 48pp
- DOCKET 50-313 ARKANSAS NUCLEAR ONE, UNIT I
- F Security, medical, emergency & fire protection plans
- 8009020130 invites participation in 800822 workshop in Atlanta, 0A to solicit comment re proposed functional criteria for emergency response facilities in NURED-0696 Discussion to include location.size & staffing of emergency ctrs SEYFRIY, K. V. Region 4. Dallas, Office of the Director 80/08/12
- 8009090326 Notifies that security mys will be fully implemented on 801001 Any subsequent equipment failure will be compensated for by compensatory measures outlined in util industrial security plan & implementing procedures
 TRINDLE.D C Arkansas Power & Light Co 80/08/29 1p
- 8009170322 Forwards security personnel training & qualification plans Revision & Revision withheld (ref 100FR2 790) TRIMBLE.D C Arkansas Power & Light Co 80/09/09 ip
- O Adjudicatory correspondence
- 8009190306 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 80i101.

 REID.R N Operating Reactors Branch 4 80/08/29 2pp
- ---8009190310 Order for mod of License DPR-51 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101
 EISENRUT.D 0 Division of Licensing 80/08/27 App
- J Insurance & indemnity information
- 8009030537 Forwards Endorsements 40.41 & 42 to NECLA Policy NF-210 & Endorsements 36 & 37 to MAELU Policy MF-74
 TRIMDLE, D C Artansas Power & Light Co 80/08/29 App
- 8009030550 Forwards Endorsement 3 to ANI Binders EB-48 & EB-68 & MAELU Binders XB-48 & XD-68 TRIMBLE:D C Arkansas Power & Light Co 80/08/29 9pp
- p Operating license stage documents & correspondence
- 8007290040 Responds to memo re fuel adjustment clause provision that would permit passing 90% of cost of replacement sower on to rategayers NRC would present any into at formal hearing No investigation planned VOEGELIR J Office of the Executive Legal Director 80/07/18
- 8009150070 Responds to 800523 recommendations concerning lessons learned from 600226 transfert at Crystal River Submits results of investigations re use of atmospheric dump valve at Oconsec Units 1-3. AR Unit 1. Davis-Basse Unit 1 & TMI-1 DENION. H R Office of Nuclear Reactor Regulation, Director 60/07/21. 2pp
- 8007020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 70 days E(SENHUT,D O. Division of Licensing 80/07/3i. 7pp

- BOO7080080 Forwards draft NUREC-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D © Division of Licensing 80/08/07 AOpp
- 8009980483 Advises that Class III fee is due for 800204 application for proposed Tech Spec change re diverse reactor bldg isolation MILLER, W U License Fee Management Branch 80/08/14 ip
- 8009020042 Responds to 800523 ltr requesting info re interim reliability evaluation program TRIMBLE.D C Artansas Power & Light Co 80/08/15 3pp
- 8007020322 Submits schedule for first 5 months of interim reliability evaluation program annotated to highlight areas of potential NRC participation Anticipated start date scheduled for 800915 EISENHUT, D. 9 Division of Licensing 80/08/15 App
- 8009030248 Advises of fee determinations for 790424 & 0606 applications re PORV setpoint change & 790606 application re anticipatory reactor trip
 MILLER, W O License Fee Management Branch 80/08/19 ip
- 8009030393 Forwards evaluation of instrumentation for detection of inadequate core cooling to support 8007il ltr stating that no add1 instrumentation is needed to meet NUREO-0578 requirements

 TRIMBLE, D.C. Arkansas Power & Light Co. 80/08/26 22pp
- 8007120387 Responds to 800701 ltr re assembly holddown spring failures Video tapes of core from last refueling have been reviewed & spent fuel pool assemblies examined No damage to spring or assembly components noted TRIMBLE, D C Arkansas Power & Light Co 80/08/27 Spp
- 8009090482 Forwards proposed revision to radiological effluent Tech Bpecs for review & approval Requests that implementation of specs be delayed until B11231 CAVANAUGH.W. Arkansas Power & Light Co 80/09/05 3pp
- --B009090491 Proposed revision to radiological effluent Tech Specs. Sections 1.2.3.4 & 6 changing data analysis & reporting requirements * Ariansas Power & Light Co 80/09/05 50pp
- 8009160228 Forwards response to NRC 800623 request for info on waste gas sys Finalization of identified mods to correct problems that allow air in-leakage to sys expected in early 1981 TRIMBLE, D C Arkansas Power & Light Co 80/09/09 App
- 8009280428 Informs of acceptability of response to NRC 791109 ltr reportions of ECCB evaluation models dealing w/fuel cladding swelling & incidence of rupture
 REID,R W Operating Reactors Branch 4 80/09/09 2pp.
- 8009300145 Forwards Amends 46 & 15 to Licenses DPR-51 & NPF-6, respectively, safety evaluation & notice of issuance & availability REID.R W Operating Reactors Branch 4 80/09/16 2pp
- --8009300148 Amends 46 % is to Licenses DPR-S1 & NPF-6.respectively.
 revising ETS re design objective for radioactive gaseous
 releases & requirements for quarterly rept on radioactive
 gaseous releases
 REID.R W Operating Reactors Branch 4 80/09/16 17pp
- ---B009300153 Eafety evaluation supporting Amends 46 & 15 to Licenses

 DPR-51 & NPF-6, respectively.

 # Office of Nuclear Reactor Regulation, Director 80/09/16 4pp
- BOO9300278 Advises that util will submit changes to 790402 response by 801103 as necessary to meet requirements for reactor bldg purge TRIMBLE, p. C. Arkansas Power & Light Co. 80/09/18, 1p.

- 6009300173 Requests deadline extension until 801201 to rewrite model Tech Specs to accompdate existing AR-1 Tech Specs format, unit design & NUREO-0578 Category A mods TRIMBLE D C. Arkansas Power & Light Co 80/09/19 ip
- Q Inspection reports. IE Bulletins & correspondence
- 8009020224 Responds to IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Units utilize flued head design for containment penetrations flued head penetrations radiographed TRIMBLE.D C Arkansas Power & Light Co 80/06/27 11pp
- 8008280022 Submits partial response to IE Bulletin 80-09. "Hydramotur Actuators " Complete response expected by 800718 Six Augramotor actuators used in safety-related sys All six mfg using proper 5160 steel for spring matl
 TRIKBLE.D C Artansas Power & Light Co 80/07/08 Ip
- BOO9180145 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side Migh Energy Line Rupture " Written response required BEYFRIT, K V Region 4, Dallas, Office of the Director 80/07/24, Lp
- 8009020538 Forwards supplemental IE Info Notice 80-06, "Notification of Significant Events at Operating Power Reactor Facilities " No written response required SEYFRIT.X V Region 4. Dallas. Office of the Director 80/07/29
- BOG9180138 Forwards IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches " Written response required SEYFRIT.K V Region 4, Dalias. Office of the Director, 80/07/31 to
- 800918060 Forwards IE Bulletin 80-19, "Failure of Mercury-Wotted Matrix Relays in Reactor Protective Sys of Operating Nuclear Pawer Plants Designed by C-E " Written response required SEYFRIT,K V Ragion 4, Dallas, Office of the Director 80/07/3
- 8009260294 Forwards IE Info Notice 80-29, "Broken Studs on Torry Turbine Steam Injet Flange " No written response required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/09/07 io
- 8009180470 Forwards IE Insp Repts 50-313/80-11 & 50-368/80-11 on B00622-0721 & notices of violation & deviation One notice of violation & Attachment A to repts withheld (ref 100FR2 790). MADSEN.O L. Region 4. Dallas, Reactor Operations Nuclear Support Branch B0/08/08 2pp
- --8009180472 Notice of violation from insp on 800622-0721 * Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/08/07 ip
- ---8009160475 Notice of deviation from insp on 800622-0721
 * Region 4, Dallas, Reactor Operations Nuclear Support Branch
 80/08/07 16
- --BD09180481 IE Insp Repts 50-313/80-11 & 50-368/80-11 on 800622-0721
 Nancompliance moted 2T12 valve gallery in Unit 2 auxiliary
 bldg not posted as radiation area & no positive access
 control on Door 364 Attachment A withheld (ref 10CFR2 790)
 JOHNSCH, W D. CALLAN, L. J., HUNNICUTT, D. M. Region 4, Dallas, Office
 of the Director 60/08/07 13pp
- BOG9040039 Ack receipt of 800708 & 11 itrs informing NRC of steps taken to correct violations noted in IE Imap Repts 50-313/80-05 & 50-368/80-03 MABBENG L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/08/12 ip
- --8009040049 Responds to NRC 800416 ltr re violations noted in JE Insp Rept 30-368/80-05 Corrective actions Tech 8pec change request generated to clarify existing spec on diesel generator automatic sequence tipe delay relays TRIMBLE.D C. Arkansas Power & Light Co 80/07/08 ip
- BO09240735 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Hercury-Watted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required.

 SEYFRIT.X V Region 4, Dallas, Office of the Director 80/08/15 to.

- 8009170390 Forwards IE Circular 80-18 "10CFR50 59 Safety Evaluations For Changes to Radwaste Treatment Sys " No written response required SEYFRIT.K V Region 4. Pallas, Office of the Director 80/08/22
- 8009120420 Forwards LE Info Notice 80-31. 'Maloperation of Gould-Brown Bover1 480 Vait Type K-6005 & K-DON 6005 Circuit Breakers "No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/08/27
- 8009170173 Forwards IE Insp Repts 50-313/80-13 & 50-348/80-13 on 800721-25 W/o enci notice of violation KELLV.J A Region 4. Dailas, Office of the Director 80/08/29 200
- --B009170176 IE Insp Repts 50-313/80-13 & 50-368/80-13 on 800721-25 Noncompliance noted vital area door fastened shut w/ inadequate fastener.tamper alarm triggering mechanism taped in manner preventing alarm & intrusion alarms not tested CALDWELL, R A , KELLY, J A Region 4, Dallas, Office of the Director 80/08/27 2pp
- R Periodic Operating reports & related correspondence
- 8009020001 Forwards results of impingement data for Jul 1980 TRIMBLE, D C Arkansas Power & Light Co 80/08/27 12pp
- 8009090425 Forwards NPDES rept for Second Quarter 1980 re NPDES Permit ARODO1392 Util 1trs to EPA encl TRIMBLE,D C Arkansas Power & Light Co 80/08/29 8pp
- ---8009090432 NPDES rept for Second Quarter 1980 re NPDES Permit ARGO01392 4 Arkansas Power & Light Co 80/08/29 15pp
- 8009160251 Forwards semiannual radioactive effluent rept for first & second quarters 1980
 TRIMBLE,D C Arkansas Power & Light Co 80/09/08 ip
- --B009160256 Semiennual radioactive effluent rept for first & second quarters 1980 4 Artansas Power & Light Co B0/09/08 21pp
- 8009230697 Forwards monthly operating rept for Aug 1980 TRIMBLE, D.C. Arkansas Power & Light Co. 80/09/15 1g
- --8009230700 Monthly operating rept for Aug 1980 BRAMLETT.L S Arkansas Power & Light Co 80/09/15 Spp
- B Reportable occurrences, LERs & related correspondence
- BOOTIGO557 PND-IV-80-027A correcting info previously reported in PND-IV-027 dtd BOO822 re loss of all telephone communications Util has plans for installation of new communications sys which includes fiber optics & microwave JOHNSON, W D , HUNNICUTT, D H , HADSEN, O L Region 4, Dailas. Office of the Director 80/08/26 2pp
- 8009240106 Responds to 800810 memo re proposed AD classification re reactor coolant pump seal failure Event did not involve major reduction in degree of public safety & should not be considered AD DENIGN.H R Office of Nuclear Reactor Regulation, Director 80/08/29 3pp
- --8009240134 Forwards draft Commission Paper w/proposed FR notice refailure of reactor coolant pump seal at facility Event is under consideration as AU since it satisfies one example in AO policy statement Requests comment by 800822 HALLER, N M Office of Management and Program Analysis 80/08/18 Pan
- ---8007240145 Responds to request for input re proposed AB classification of reactor coolant pump seal failure at facility Incident more appropriately meets criterion of "Event of Interest "
 No major breakdown in level of public protection determined RIGGS,R Operating Experience Evaluation Branch 80/08/22 3pp
- --8007240158 Operating Reactor Event Mamo 80-10, forwarding list of LERs re events which result in containment floor flooding & diagram of RCS Water on containment floor is only significant during major LCGA EISENHUT, D & Division of Licensing 80/07/11 5pp

- ---B009240179 Repts findings re review of available LER data on reactor contant pump seal failures Typical failure modes include inadequate seal spring pressure design error, thermal shock, personnel error & debris 2UDANS. J Division of Engineering 80/05/02 3pp
- 8009090542 Forwards updated LER 80-011/03L-5 TRIMBLE.B C Arkansas Power & Light Co 80/09/03 2pp
- --8009090568 Updated LER 80-0i1/03L-5 on 80040i.IE Bulletin 79-14 review revealed 21 piping bangers importable Hangers Tepaired or modified within Tech Specs time limit BRAKLETT.L 8 Arkansas Power & Light Co 80/09/03 ip
- 8009190600 PNO-1V-80-030 on 800905 during full power operation steam generator tube leak occurred Leak was indicated by N-16 detector offgas monitor & main stack monitor Unit will be shut down approx two wks

 JOHNSON N D , HUNNICUTT, D M , MADSEN, O L Region 4, Dallas, Office of the Director 80/09/05 ip
- 8009230708 Forwards updated LER 80-011/03X-6 TRIMBLE.D C Arkameas Power & Light Co 80/09/15 lp
- --8009230715 Updated LER 80-011/03X-6 on 800401/32 piping hangers were declared inoperable Design change prepared to upgrade affected hangers to meet design requirements Review continuing BRAMLETY, L.S. Arkansas Power & Light Co. 80/09/15 2pp

- 8009050330 Submits info re mods to reactor operator training program in response to NRC 800328 ltr Course summaries for thermodynamics, fluid flow 5 heat transfer training & for mitigating core damage encl O'HANLON, J P Artansas Power & Light Co 80/08/04 9pp
- 8009i70241 Documents G008ii presentation of util position re nuclear training program Presentations re operator training, general employee training, training records, on-the-job training, fire brigade training & sys training encl CAVANAUGH, M. Arkansas Power & Light Co. 80/08/13 14pp
- DOCKET 50-315 DONALD C COOK NUCLEAR POWER PLANT. UNIT 1

 F Security, medical. emergency & fire protection plans
- 8009230284 Requests that all personnel be reminded of purpose of omergancy notification sys & health physics network Sys installed for govt use during emergency KEPPLER. J G Region 3, Chicago, Office of the Director 80/08/22 3pp

O Adjudicatory correspondence

- G009240509 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 80110; VAROA, B A Operating Reactors Branch 1 80/08/29 2pp
- P Operating license stage documents & correspondence
- 8009050460 Forwards Amend 38 to License DPR-S8, safety evaluation & notice of issuance & availability
 VARGA.S A Operating Reactors Branch 1 80/07/25 20p
- --8007050464 Amend 38 to License DPR-58, revising Tech Specs to allow operation of unit w/Exxon Nuclear Go power distribution control procedures
 VARGA:5 A Operating Reactors Branch 1 80/07/25 17pp
- --8007050470 Safety evaluation supporting Amend 38 to License DPR-58
 * Office of Nuclear Reactor Regulation, Birector 60/07/25 3pp
- --8009050471 Notice of issuance & availability of Amend 38 to License DPR-58 VARGALS A Operating Reactors Branch (80/07/25 2pp

- 8009120039 Forwards Amend 39 to License DPR-58, safety evaluation & notice of issuance 5 availability
 VAROA 8 A Operating Reactors Branch 1 80/07/25 2pp
- --B009120048 Amend 39 to License DPR-58, revising surveillance & monitoring requirements for degraded voltage function & surveillance requirements for onsite power source testing VARGALS A Operating Reactors Branch 1 80/07/25 12pp
- --8009120051 Bafety evaluation supporting Amend 37 to License DPR-58
 Draft technical evaluation rept enc!

 → Office of Nuclear Reactor Regulation. Director 80/07/25
 1400
- --8009120065 Notice of Issuance & availability of Amend 39 to License DPR-58 VAROA.8 A. Operating Reactors Branch i 80/07/25 2pp
- 8007020183 Forwards correspondence on problems identified at other facilities re personnel errors per 800702 commitment W/o encl
 HEISHMANN R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/07/30 lp
- 8009020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D O Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREC-0696. "Functional Criteria for Emergancy Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREC-0696 encl W/o NUREC EISENHUT.D O Division of Licensing 80/08/01 119pp
- BOO9230052 Informs that exemption from fee re licensing action associated w/TMI~2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D Q Division of Licensing 80/08/07 60pp
- 8009170228 Forwards review & assessment re control rod guide thimble wear in FNRs Issue resolved for Unit 2 Unit i review is in progress VARGA.S A Operating Reactors Branch 1 80/08/14 4pp
- B009190794 Forwards revised Westinghouse BTS 3 9 B 2.3 9 10 & Bases 3/4 9 B & 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required NOVAK, T M Assistant Director for Operating Reactors 80/08/i5 in
- --B007190B17 Revised Westinghouse BTS 3 9 B 2.3 9 10 & Bases 3/4 9 B & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control roos

 # Assistant Director for Operating Reactors 80/06/23 2ipp
- BOO9110579 Informs that review of Tech Specs requirements for rod position indication completed Determined that requirements in compliance w/control rod position indication sys at Histinghouse PMSS Forwards safety evaluation VAROA.8 A Operating Reactors Branch i 80/08/i8 2pp
- --8009110584 Bafety evaluation supporting Tech Specs requirements re control red gosition indication sys at Westinghouse PWRs * Office of Nuclear Reactor Regulation, Director 80/08/18 2pp
- 8009(10512 Forwards revised Page 3/4 3-26a to Tech Specs in Amend 39 to License DPR-58 Due to administrative error, incorrect page was issued VAROA,8 A Operating Reactors Branch 1 80/08/19 ip
- --8009110516 Revised Page 3/4 3-26a to Tech Specs submitted w/Amend 39 to License DPR-58.re engineered safety feature actuation sys instrumentation trip setpoints w Operating Reactors Branch i 80/08/19 2pp
- 8007040464 Forwards mather NRC review of ice condensor containment & hydrogen control measures for Sequeyah Nuclear Power Plant ACRS has scheduled meetings in Washington, DC on 800828, 0902 & 04 to discuss issue.

 TEDESCO
- BO09240078 Forwards Amends 40 & 23 to Licenses DPR-58 & DPR-74 respectively, safety evaluation & notice of (squance & availability VARGA:8 A Operating Reactors Branch 1 80/08/29 3pp

- --8009240084 Amends 40 & 23 to Licenses BPR-58 & DPR-74, respectively, revising Unit 1 Tech Specs re refueling water tank operating temp & discharge scour bed protection & Units 1 & 2 plume measurements of water discharge VARQA.B A Operating Reactors Branch 1 80/08/29 21pp
- --8009240089 Safety evaluation supporting Amends 40 & 23 to Licenses DPR-58 & DPR-74 respectively → Operating Reactors Branch 1 80/08/29 4pp
- --8009240097 Notice of issuance & availability of Amends 40 & 23 to Licenses DPR-58 & DPR-74 respectively MEIGHBORB, J D Operating Reactors Branch i 80/08/29 2pp
- 8009120639 "Technical Evaluation Rept on Degraded Orid Protection for Class IE Power Sys for DC Cook Nuclear Plant Unit 1," technical evaluation rept. Aug 1980 CLEVELAND. C J E000 Idaho, Inc FIN A-4256 8009120639 80/08/31
- 8009260520 "Effect of Containment Tamp on Liquid Level Measurements, DC Cock Nuclear Station," informal rept UDY, A C E0%0 Idaho, Inc FIN A-6256 8009260520 80/08/31 10pp
- BOCP260568 "Technical Evaluation Rept on Degraded Grid Protection for Class IE Power Sys for DC Cook Nuclear Plant,Unit 1," Revision 1 CLEVELAND,C J E000 Idaho, Inc FIN A-6256 8009260568 80/08/31
- 13pp
- E009240369 Requests extension to 801031 for submitting info re auxiliary feedwater sys flow design basis per NRC 791030 request Extension will permit in-house review Add1 info re condensate storage tank lovel indication sys enc1 HUNIER,R S Indiana & Michigan Electric Co 60/09/18 3pp
- Q Enspection reports, IE Builetins & correspondence
- 8007320227 Ack receipt of 800708 ltr informing NRC of steps taken to correct violations noted in 800610 ltr DAVIS.A 3 Region 3, Chicago, Fuei Facility & Materials Safety Beanth 80/08/08 tp
- 8009140195 Responds to IE Builetin 79-03A, "Longitudinal Weld Defects in ABME SA-312, Type 304 Stainless Steel Pipe " No sys of ilizing pipe are stressed to more than 85% of max allowable stress
 #WNICH,R 8 Indiana & Michigan Electric Co 80/08/08 ip
- 8009250365 Ack receipt of 800804 itr informing NRC of steps taken to correct violation noted in IE imap repts
 MEISHMAN.R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/08/14 ip
- --8009250373 Responds to NRC 800710 ltr re violations noted in IE insp repts Corrective action document reviews will be completed on 800815 HUNTER.R S Indiana & Michigan Power Co 80/08/04 2pp
- 8007030170 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by G-E " Written rasponse required KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/15
- B009250628 Forwards IE Insp Rept 50-315/80-12 on 800722-25 No noncompliance noted DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/08/21 2pp
- --8009280634 IE Insp Rept 30-315/80-12 on 800722-25 No noncompliance noted Major areas inspected operational radiation protection during refueling & maint, including organization & staffing, exposure control & matl control FIGHER, M. L. HUETER, J. Region 3, Chicago, Office of the Director. 80/08/18 12pp
- 8009170407 Forwards IE Circular 80-18, "IOCFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEFPLER, J G Region 3, Chicago, Office of the Director 80/08/22

- 8009230063 Forwards (E. Info Notice 80-31, 'Maloperation of Gould-Brown Boveri 480 Volt Type K-6005 & K-DON 6005 Circuit Breakers "
 No written response required KEPPLER. J. G. Region 3, Chicago, Office of the Director 80/08/28
- 8009240094 Forwards response to 1E Bulletin 80-15. "Possible Loss of Emergency Notification Sys (ENS) w/Loss or Offsite Power" Test verified operability of all sys MALONEY:0 P Indiana & Michigan Electric Co 80/09/04 4pp
- 8009240212 Responds to IE Bulletin 80-20, "Failure of Nestinghouse Type W-2 Spring Return to Neutral Control Sultches' Referenced switches are not used in safety-related sys at facility HUNIER,R S Indiana & Michigan Electric Co 80/09/08 1p
- 8009240107 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/10
- 8009290440 Ack receipt of 800804 itr informing NRC of steps taken to correct violations noted in 1E insp Repts 50-315/80-08 % 50-316/80-07 HEISHMAN,R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/09/10 ip
- --8009290444 Responds to NRC 800710 Ltr se violations noted in LE Insp Repts 50-315/80-08 \$ 50-316/80-07 Corrective actions events entered in required logbooks & responsible persons reminded of maintaining accurate logs HUNTER: R S Indiana & Michigan Electric Co 80/08/04 3pp
- R Periodic operating reports & related correspondence
- 8007110310 Advises that ulii will submit semiannual radioactive aefiluent release rept by 800724 Rept being prepared per Bection 5 4 i B of Tech Specs.App B MALONEY.G P Indiana & Michigan Electric Co 80/09/04 ip
- 8009160273 Forwards monthly operating rept for Aug 1980 SHALLER,D V Indiana & Michigan Electric Co 80/09/12 1p
- --8009160277 Monthly operating rept for Aug 1980 GILLETT, W T Indiana & Michigan Electric Co 80/09/05 10pp
- 8009190322 Forwards summaries of impinged fish for Apr & May 1980 in response to NRC request Also forwards related data & repts to aid in evaluation of ecological significance of event Encis available in Central Files only QAULKE,A E American Electric Power Co , Inc 80/09/16 3pp
- S Reportable occurrences. LERs & related correspondence
- 800-9090501 Forwards LER 80-017/03L-0 SHALLER, D V Indiana & Michigan Power Co 80/09/03 1p
- --8009090508 LER 80-017/03L-0 on 800804, during low power physics test after refueling, boron injection tank discovered to have boron concentration below required min Caused by Inadequate mixing due to low rectrculation flow CHADUELL: H M Indiana & Michigan Power Co 80/09/03 2pp
- 8009110326 Forwards LER 80-018/03L-Q SHALLER,D V Indiana & Michigan Electric Co 80/09/05 ip
- --8009110348 LER 80-018/03L-0 on 800805.during post-refueling startup.RCS average temp foil below 541 F contrary to Tech Spec 3 [] 5 Caused by unbalance between turbing load & reactor power Turbing load reduced CHADHELL, H M Indiano & Michigan Electric Co 80/09/05 2pp
- 8009150323 Forwards LER 80-019/03L-0 SHALLER,D V Indiana & Michigan Electric Co 80/09/10 1p
- --8009150328 LER 80-019/03L-0 on 800811, while performing surveillance re Tech Spec 3 8 2 1 requirements for inoperable diesel generator, requirement 4 8 1 1 ia uas not performed Caused by inadequate surveillance procedures CHADWELL, H M Indiana & Michigan Electric Co 80/09/10 1p
- 8009190503 Forwards LER 80-021/03L-0 BHALLER, D V Indiana 2 Michigan Power Co 80/09/12 1p

- --8009190509 LER 80-021/03L-0 on 800817 during insp. two intermediate deck doors were found frozen shut Caused by water from top deck divider beams Design change submitted to insulate divider beams to prevent condensation WIZNER.D 0 Indiana & Michigan Power Co 80/09/12 1p
- 8009300510 Forwards LER 80-020/03L-0 SHALLER, D. V. Indiana & Michigan Electric Co. 80/09/24 ip
- --B009300517 LER 80-020/03L-0 on 80083i, during normal operation, Unit trip & Train A safety injection & steam line isolation occurred Caused by shorted diode in CRID 4 inverter Ail diodes & diocillator boards replaced tested % returned to svc DELONG, S D Indiana & Michigan Electric Co 80/09/24 2pp

- 8009170350 Concurs w/NRC 800328 ltr re qualifications of reactor operators Changes necessary to upgrade operations personnel qualifications program have been adopted Revised program was sent on 800725 to NRC for review & approval HUNIER.R S Indiana & Michigan Ejectric Co 80/09/11 ip
- DOCKE: 50-316 DOMALD C COOK NUCLEAR POWER PLANT. UNIT 2

 F Security, medical, emergency & fire protection plans
- 8007230284 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys (instailed for govt use during emergency KEPPLER. J O Region 3. Chicago. Office of the Director 80/08/22

G Adjudicatory correspondence

- 8009260609 Forwards order requiring info supporting environ qualification or safety-related electrical equipment Requests submittal of info by 80ii01 VAROA. S A Operating Reactors Branch 1 80/08/29 2pp
- --B009260613 Order for mod of Licenses DPR-58 & DPR-74 to add info which tuliy responds to NRC request for info re environ qualification of safety-related electrical equipment info should be submitted by 801601
 EISENHULD O Division of Licensing 80/08/29 App

P Operating iscense stage documents & correspondence

- 8009020183 Forwards correspondence on problems identified at other facilities re personnel errors per 800702 commitment W/o enci HEISMMAN, F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/07/30 in
- 8009020297 Submits interam criteria for shift staffing to all OL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D 0 Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/O NUREG EISENHUT.D 0 Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated G/TML-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend.

 EISENHUT, D 9 Division of Licensing 80/08/07 60pp
- 8009170228 Forwards review & assessment re control rod guide thimble wear in PHRs Issue resolved for Unit 2 Unit 1 review is in progress
 VARQA.8 A Operating Reactors Branch 1 80/08/14 4pp
- 8009190794 Forwards revised Westinghouse STS 3 9 8 2,3 9 10 % Bases 3/4 9 8 % 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required MDVAK.T M Assistant Director for Operating Reactors 80/08/15

- --8009190817 Revised Westinghouse STS 3 9 8 2,3 9 10 & Bases 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure flange during movement of fuel assemblies or control rods
 * Assistant Director for Operating Reactors 80/06/23 21pp
- B009110579 Informs that review of Tech Specs requirements for rod position indication completed Determined that requirements in compliance w/control rod position indication sys at Hestinghouse PHRs Forwards safety evaluation VAROA.S A Operating Reactors Branch 1 80/08/18 2pp
- --8009110584 Safety evaluation supporting Tech Specs requirements re control rod position indication sys at Westinghouse PWRs * Office of Nuclear Reactor Regulation, Director 80/08/18 2pp
- 8009100106 Forwards corrected Page 1 to Amend 22 to License DPR-74 & corrected Tech Spec Page 3/4 3-25a
 VARGA.S A Operating Reactors Branch 1 80/08/19 2pp
- --8009100110 Corrected Page 1 to Amend 22 to License DPR-74 & corrected Tech Spec Page 3/4 3-25a * Operating Reactors Branch 1 80/08/19 2pp
- 8009040464 Forwards matter NRC review of the condenser containment & hydrogen control measures for Sequoyah Nuclear Power Plant ACRS has scheduled meetings in Washington, DC on 800828, 0902 & 04 to discuss issue TEDESCO.R L Assistant Director for Licensing 80/08/22 2pp
- 8009240078 Forwards Amends 40 & 23 to Licenses DPR-58 & DPR-74 respectively, safety evaluation & notice of issuance & availability VARQA.S A Operating Reactors Branch (80/08/29 3pp
- --8009240084 Amends 40 & 23 to Licenses DPR-58 & DPR-74, respectively, revising Unit i Tech Specs re refueiing water tank operating temp & discharge scour bed protection & Units i & 2 plume measurements of water discharge VARGA, S A Operating Reactors Branch i 80/08/29 2ipp
- ---B009240089 Bafety evaluation supporting Amends 40 & 23 to Licenses OPR-38 & DPR-74 respectively 4 Operating Reactors Branch 1 80/08/29 4pp
- --8009240097 Notice of issuance & availability of Amends 40 & 23 to Licenses DPR-58 & DPR-74 respectively NEICHBORS.J D Operating Reactors Branch i 80/08/29 2pp
- 8009260084 "Effect of Containment Temp on Liquid Levei Measurements.DC Cook Nuclear Station, Unit 2," interim rept UDY, A C E0&G Idaho, Inc FIN A-6256 8009260084 80/08/31 10pp
- 8009240369 Requests extension to 80103i for submitting info re auxiliary feedwater sys flow design basis per NRC 791030 request Extension will permit in-house review Addl info re condensate storage tank ievel indication sys enci HUNIER.R 8 Indiana & Michigan Electric Co 80/09/18 3pp
- Q Inspection reports, IE Bulletins & correspondence
- 8009260304 Forwards IE Imap Rept 90-316/80-10 on 800623-27 No noncompliance noted HEIBHKAN.R F Region 3, Chicago. Reactor Operations Nuclear Support Branch 80/08/07 2pp
- --8009260303 IE Insp Rept 50-316/80-10 on 600623-27 No noncompliance noted Major areas inspected program & documentation recontrol of centrifugal charging/safety injection pumps FOSTER.LE, SHAFER.W D Region 3, Chicago, Office of the Director 80/08/04 7pp
- GOO9020227 Ack receipt of 800708 ltr informing NRC of steps taken to correct violations noted in 800610 ltr DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Safaty Branch B0/08/08 ip
- --8009020232 Responds to NRC 800610 ltr re violations noted in lasp rept Corrective actions placard procedures now require boxes over ,640 cubic ft vol to have placards on each side & and HUNTER, R S Indiana & Michigan Electric Co 80/07/08 1p
- 8009160193 Responds to IE Bulletin 79-03A, "Longitudinal Held Dufects in ASME 8A-312, Type 304 Stainless Steel Pipe " No sys utilizing pipe are stressed to more than 83% of max allowable stress HUNTER:R 8 Indiana & Michigan Electric Co 80/08/08 ip

- 8009236365 Act receipt of 800804 ltr informing NRC of steps taken to correct violation noted in 1E insp repts
 HEISIMFAN.R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/08/14 ip
- --8039250373 Responds to NRC 800710 ltr re violations noted in 1E insprepts Corrective action document reviews will be completed on 800815 HUNTER R S Indiana & Michigan Power Co 80/08/04 2pp
- 8009030190 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E " Written response required XEFPLER. J G Region 3, Chicago, Office of the Director 80/08/15
- E007:70407 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER. J G Region 3. Chicago. Office of the Director 80/08/22
- E007230063 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Bayeri 480 Volt Type K-6005 & K-DON 6008 Circuit Breakers " No written response regulard MEPPLER.J O Region 3. Chicago. Office of the Director 80/08/28
- 8009260094 Forwards response to IE Bulletin 80-15. "Possible Loss of Eastgency Notification Bys (ENS) w/Loss of Offsite Power " Fast verified operabliity of all sys HALONEY, Q P Indiana & Michigan Electric Co 80/09/04 App
- 8009260212 Responds to IE Bulletin 80-20, "Failure of Westinghouse Type H-2 Spring Return to Neutral Control Switches" Referenced switches are not used in safety-related sys at facility MUNIER.R B Indiana & Michigan Electric Co 80/09/08 ip
- 8009240107 Forwards IE Circular 80-21, "Regulation of Refueling Crews"
 No written response required
 VEFPLER, J.O. Region 3, Chicago, Office of the Director 80/09/10
 19
- 8009290440 Ack receipt of 800804 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-315/80-08 & 50-315/80-07 HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/09/10 ip
- --B009290444 Responds to NRC 800710 ltr re violations noted in IE Insp Repts 50-315/80-08 & 50-316/80-07 Corrective actions events entered in required logbooks & responsible persons reminded of maintaining accurate logs HUNTER.R S Indiana & Michigan Electric Co 80/08/04 3pp
- R Periodic operating reports & related correspondence
- SOCIIO310 Advises that util will submit semiannual radioactive effluent release rept by SOCIE Rapt being prepared per Section 5 4 1 B of Tech Specs. App B MALDNEY. 0 P Indiana & Michigan Electric Co 80/09/04 ip
- 8009160280 Forwards monthly operating rept for Aug 1980 SHALLER.D V Indiana & Michigan Electric Co 80/09/12 ip
- --8009160283 Monthly operating rept for Aug 1980 GILLETT,W T. Indiana & Michigan Electric Co 80/09/05 App
- 8009190422 Forwards summaries of impinged fish for Apr & May 1980 in response to NRC request Also forwards related data & repts to aid in evaluation of ecological significance of event Encls available in Central Files only GAULKE.A E American Electric Power Co . Inc 80/09/16 Spp
- S Reportable occurrences, LERs & related correspondence
- 8009190517 Forwards LER 80-030/03L-0 SMALLER.B V Indiana & Michigan Electric Co 80/09/12 1p
- --8009190522 LER 80-030/03L-0 on 800814, during normal operation, radiation monitor R1f alarmed investigation showed R-11 & R-12 sample pumps seized Caused by wear Pump replaced & monitors returned to svc WIZMER, D 9 Indiana & Michigan Electric Co 80/09/12 ip

- V Operator Examinations
- 8009170350 Concurs w/NRC 800328 ltr re qualifications of reactor operators Changes necessary to upgrade operations personnel qualifications program have been adopted Revised program was sent on 800725 to NRC for review & approval HUNTER,R S Indiana & Michigan Electric Co 80/09/11 1p
- DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8009230165 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency ORIER, B H Region 1. Philadelphia, Office of the Director 80
- 8009080350 Forwards "Fire Stup Penetration Test on Fire Protection Sys," final rept re Slab 2 ABH.R F Baltimore Gas & Electric Co 80/09/02 1p
- --8009080352 "Fire Btop Penetration Tests on Fire Protection Sys," final rept re Slab 2 PISH,M D , POIRIER,L J , SCHRAEDER,A L Southwest Research Institute 80/08/15 182pp
- 8009300333 Submits status of fire protection mods & details of certain mods which cannot be comploted per original schedule List of items requiring extended schedules encl
 LUNDVALL.A E Baltimore Gas & Electric Co 80/09/26 App
- O Adjudicatory correspondence
- 8009260528 Forwards order requiring into supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 CLARK.R A Operating Reactors Branch 3 80/08/29 2pp
- --8009260532 Order for mod of Licenses DPR-53 & DPR-69 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101 EISERMUT.D 0 Division of Licensing 80/08/29 App
- J Insurance & indemnity information
- B009300438 Forwards Endorsement 29 to MAELU Policy MF-76 & Endorsements 30 & 35 to NELIA Policy NF-216 SHGEMAKER, C L Balt/more Oas & Electric Co B0/09/26 4pp
- P Operating license stage documents & correspondence
- BOO902027 Submits interim criteria for shift staffing to all GL & CP licensees & applicants, per NRC BOO507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D O Division of Licensing. B9/07/31 7pp
- 8009080080 Forwards draft NUREO-0496, "Functional Criteria for Emergency Response Facilities' Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0496 encl H/O NUREO EISENHUT, D. Q Division of Licensing 80/08/01 119pp
- 8009230032 Informs that exemption from few re licensing action associated w/THI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D O Division of Licensing 80/08/07 60pp
- 8009020327 Submits schedule for first 5 months of interim reliability evaluation program, annotated to highlight areas of potential NRC participation Anticipated start date scheduled for 800915 EISENHUT.D O Division of Licensing 80/08/15 5pp
- BD09020336 Forwards Corrected Tech Specs 4 5 1 f & 4 5 1 b re sampling locations forwarded w/Amends 44 & 27 to Licanses DPR-53 & DPR-69.respectively CLARK,R A Operating Reactors Branch 3 B0/08/15 2pp
- --8009020338 Corrected Tach Spacs 3/4 5 re min boron concentration values which were included in Amends 44 & 27 to Licenses DPR-53 & DPR-67, respectively

 * Operating Reactors Dranch 3 80/08/15 4pp

- G007150415 Informs that facility does not have two specific Event 5 waive configurations discussed in NRC 800223 ltr re-primary coolant sys pressure isolation valves NRC activities re-valve configurations have been finalized for facility CLARK.R A Operating Reactors Branch 3 80/08/15 2pp
- --8009150424 "Primary Cootant Sys Pressure Isolation Valves, Calvert Ciiffs Units 1 & 2," technical evaluation rept NOELL,P N. STILKELL,T C Franklin Institute/Franklin Research Center NRC-03-79-118 80/07/21 4pp
- 8009150390 Forwards Amends 45 & 28 to Licenses DPR-53 & DPR-69, respectively & notice of issuance & availability CLARK,R A Operating Reactors Branch 3 80/08/19 2pp
- --8009150356 Amends 45 % 28 to Licenses DPR-53 % DPR-69 respectively, adding requirement to maintain safeguards contingency plan, to be fully implemented within 30 days
 TRAMMELL,C M Operating Reactors Branch 3 80/08/19 4pp
- --B009150361 Notice of issuance & availability of Amends 45 & 28 to Licenses DPR-53 & DPR-69, respectively TRANMELL.C M Operating Reactors Branch 3 80/08/17 2pp
- 8009150034 Summary of 800717 meeting w/C-E & util in Bethesda.MD re iB month fuel cycles for facilities Main purpose of meeting to present overview of six documents submitted by util on 800626 was fulfilled LI.C Y Operating Reactors Branch 3 80/08/20 4pp Operating Reactors Branch 3 80/08/20 4pp
- 8009090553 Submits general program for calculating RCS leak rates for most reactors from PWR vendors Results indicate periodic independent calculation of RCS leak rates by inspectors is WOODRUFF.R W Division of Reactor Operations Inspections 80/08/21
- 8009020020 Forwards proprietary & nonproprietary versions of data sheets from Mestinghouse low pressure turbine disc insp.to replace corresponding pages in 800318 itr Proprietary version withheld (ref lOCFR2 790) LUNDVALL,A E Baltimore Gas & Electric Co 80/08/25 4pp
- 8009040301 Describes proposed design mods per NUREG-0576:Item 2 i 7a which requires implementation of safety-grade autostart of auxiliary feedwater by 810101 Drawing change notices encl. including one oversized drawing LUNDVALL.A E Baltimore Cas & Electric Co 80/08/27 13pp
- 8009150290 Forwards response to NRC 800717 questions re C-E topical repts & review of safety evaluation re Westinghouse methodology for statistically combining uncertainties in state & sys parameters LUNDVALL.A E Baltimo Baltimore Qas & Electric Co 80/09/10 17pp
- 8009300077 Forwards Amends 46 & 29 to Licenses DPR-53 & DPR-49, respectively, safety evaluation & notice of issuance & availability CLARK, R A Operating Reactors Branch 3 80/09/10 3pp
- --8009300080 Amends 46 & 29 to Licenses DPR-53 & DPR-69, respectively, changing App A Tech Specs for safety-related hydraulic snubbers & limiting conditions for operation of fire hose stations, shutdown & onsite power distribution sys CLARK, R A Operating Reactors Branch 3 80/09/10 20pp
- --B009300083 Safety evaluation supporting Amends 46 & 29 to Licenses DPR-33 & DPR-69, respectively * Operating Reactors Branch 3 80/09/10 App
- --B0093000B5 Notice of issuance & availability of Amends 46 & 27 to Licenses DPR-53 & DPR-69, respectively CLARK, R A Operating Reactors Branch 3 80/09/10 2pp
- 8009160453 Responds to NRC 800911 request for add1 info re spent fuel pool mods Poison matl is 84C powder in fiberglass matrix Irradiation data submitted to NRC on Haddam Neck & Millstone dockets in form of 680-N-78-299 dtd 781031 ASH.R F Baltimore &as & Electric Co 80/09/12 2pp
- 8009230634 Requests amend to change Tech Specs for License DPR-53 to allow operation for fifth cycle Proprietary & nonproprietary versions of CEN-138(B) enci Proprietary version withheld (ref 100FR2 790) LUNDVALL, A E Baltimore Cas & Electric Co 80/09/22 2pp
 - 3009230640 Application to amend Cycle 5 refueling license Marked-up Tech Specs encl * Baltimore Gas & Electric Co 80/09/22 200pp

- --8009230646 Nonproprietary version of "Description of PROTOTYPE Test Program in Calvert Cliffs (Cycle 5 " + Combustion Engineering, Inc. CEN-137(8) 80/08/27 8pp
- --8009230650 Nonproprietary version of "Description of Modified Assemblies in Calvert Cliffs 1 Cycle 5 " + Combustion Engineering, Inc. CEN-138(B) 80/09/22 App
- 8009240360 Forwards affidavit supporting proprietary designation, per 10CFR2 790, for Apps D % E of Cycle 5 reload license submittal SCHERER, A E C-E Power Systems 80/09/22
- O Inspection reports. 1E Builetins & correspondence
- 8009240259 Forwards 1E Insp Repts 50-317/80-10 & 50-318/80-09 on 900418-20 No noncompilance noted CARLSDUR T Region 1. Philadeiphia, Reactor Construction 원 Engineering Bupport Branch 80/07/23 2pp
- -8009240265 IE Insp Repts 50-317/80-10 & 50-318/80-09 on 800618-20 No noncompliance noted Major areas inspected qualification data for electrical equipment inside containment as defined in licensee response to IE Bulletin 79-01B EBNETER S D Region 1, Philadelphia, Reactor Construction & Engineering Support Brench FINKEL, & Region 1, Philadelphia, Office of the Director 80/07/14 16pp
- 8009160504 Responds to IE info Notice 80-06. Suppl 1, "Notification of Bignificant Events at Operating Power Reactor Facilities" Proposed criteria requires medical judgment be made onsite & should be reconsidered

 TIERNAN, J A Baltimore Gas & Electric Co 80/08/08 ip
- B007030107 Forwards Revision 1 to 1E Builetin 80-17.. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written GRIER.B H Region t. Phriadelphia. Office of the Director 80/08/15 lp
- B009180572 Forwards IE Circular 80-18, "100FR50 59 Safety Evaluations for Changes to Radwasto Treatment Sys " No written response required
 GRIER.B H Region 1. Philadelphia, Office of the Director
 Q8/08/22 Ip
- BOOP120169 Forwards IE Info Notice 80-3i, "Maloperation of Gould-Brown Bover(480 Voit Type K-400S & K-DDN 600S Circuit Breakers " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director BO/08/27 ip
- 8009230776 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required GRIER.B H Region 1. Philadeiphia, Office of the Director #20/07/10 ip
- 8009240285 Forwards IE Info Notice 80-32, "Ciarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matis "No written response required GRIER.B H Region i. Philadeiphia, Office of the Director BO/07/12 ip
- 8009250047 Ack receipt of payment of civil penalties in amount of \$21,000 proposed in NRC 800801 ltr t util 800821 itr readdle corrective actions taken Further action will be based on future inspection & Enfarcement, Office of the Director 80/09/17 2pp
- R Periodic operating reports & related correspondence
- 8009020034 Forwards "Semiannual Effluent Release Rept for Calvert Cliffs Nuclear Power Plant. Second Haif 1979 " Meteorological summary for first half of 1980 will be submitted at Jates LUNDVALL, A E Baltimore Gas & Electric Co 80/08/20 ip
- --B0090Z0035 "Semiannual Effluent Release Rept for Calvert Cliffs Nuclear Power Plant, Second Halt 1979 " * Baltimore Gas & Electric Co 80/08/20 17pp
- 8007270244 Forwards monthly operating repts for Aug 1780 MERSON, S D Baltimore Gas & Electric Co 80/09/15
- -8009290248 Monthly operating rapts for Aug 1980 MERSON,S D. Baltimore Cas & Clectric Co. 80/09/15 24pp

- S Reportable accurrences. LERs & related correspondence
- SCOCIODES RG 80-41 on 800812; instrument air compressor after cooler 16 im svc water sys failed causing air ingress in svc water subsys Restored to normal operation after isolation of instrument il Details will follow RUSSELL.L B Baltimore Gas & Electric Co 80/08/13 ip
- 8009030520 Forwards LER 80-038/03L-0 RUSSELL, L B Baltymore Gas & Electric Co 80/08/29 ip
- 8009120354 Forwards LER 80-042/03L-0 RUSSELL, L B Saltimore Gas & Electric Co 80/09/06 1p
- --8007120378 LER 80-042/03L-O on 800806 during normal operation.

 engineered actuation sys channel ZE was de-energized for corrective maint Caused by failure of actuation channel B isolation module within channel ZD ZD module replaced

 LAGIEWSKI, J S , RIZZO, P G Baltimore Gas & Electric Co 80/07/06
- BOO9120447 Forwards LER 80-040/03L-0 RUBSELL, L B Baltimore Gas & Electric Co 80/09/06 lp
- --B009120455 LER 80-040/03L-0 on 800806, during normal test of saltwater valve I-SN-5210-CV.SN-5749-CV opened causing 11 SW header to decrease 3 psig Cause not known Solenoid valve 1-SV-5149 tasted, found operable & robuilt as preventive measure DAVIS, 8 M , R1220.P 0 Baltimore Gas & Electric Co 80/09/06
- 8009120344 Forwards LER 80-043/03L-0 RUSSELL.L B Baitimore Oas & Electric Co 80/09/08 1p
- --8009120348 LER 80-043/03L-O on 800819, during normal operation while conducting routine maint on 500 kV BRKR 552-22, disconnect device 89-228 maifunctioned Caused by failure of horseshoe clip Disconnect device repaired & returned to svc WENDERLICH, R L Baltimore Gas & Electric Co 80/09/08 2pp
- 8009160315 Forwards LCR 80-044/03L-0 RUSSELL,L B Baltimore Gas & Electric Co 80/09/08 lp
- B009250311 RO B0-51 on 800911.during post-maint test.control room air conditioning Unit 11 failed to start Attempt to restart Unit 12 failed Cause not stated Arter corrective maint & repairs Units \$1 & 12 returned to svc RUSSELL.L B Baltimore Gas & Electric Co G0/09/12 3pp
- 8009230531 Forwards LER 80-039/03L-0 RUSSELL,L # Baltimore Oas & Electric Co 80/09/15 1p
- --8009230536 LER 80-039/03L-0 on 800815 during normal operation, control room 12 air conditioning compressor tripped twice Caused by high discharge pressure Unloader valve adjusted & sys design re-evaluated to increase cepacity & reliability LEAOIEMBKI.J S., PENCE, H.B. Baltimore Gas & Electric Co 80/09/15 10
- 9009230542 Forwards LER 80-046/03L-0 RUSSELL,L B Baltimore Cas & Electric Co 80/09/16 ip
- 1009230583 Forwards LER 80-048/017-0 RUSSELL,L B Baltimore Gas & Electric Co 80/09/17 1

- --8009230592 LER 80-048/OLT-0 on 800993 during maint for control room (2 air conditioner unit il compressor was not running & later tripped on overload Faulty reset suitch replaced & procedures revised to require check of air conditioner WENDERLICH, R L , PENCE, W B Baltimore Gas & Electric Co 80/09/17 ip
- 8009230688 Forwards LCR 80-045/03L-0 RUSSELL.L D Baltimore Gas & Electric Co 80/09/20 1p
- --8009230695 i.ER 80-049/O3L-O on 800820.computer indication failed except for control element assembly position indication Caused by ipose wire connectors at several edge connector pins for analog bus segmentation cards Connectors soldered in place DAVIS.6 M . RIZZO.P G Baltimore Cas & Electric Co 80/09/20 20s
- 800930044i Forwards followup LER 80-022/01(-1 RUSSELL,L B Baltimore Gas & Electric Co 80/09/22 ip
- --8009300450 Followup LER 80-022/01X-1 on 809415.util notified of possible deficiency in FGAR safety analysis Section 14 3 Analysis does not address possibility of RCS being drained to hot leg w/1% shutdown margin Procedures changed DAVIS.8 M Baltimore Gas % Electric Co 80/09/22 2pp
- 8007300464 Forwards LER 80-049/03L-0 RUSSELL, L B Baltimore Gas & Electric Co 80/09/26 1p
- --8009300470 LER 80-049/03L-0 on 800830, during normal operation, 12 control room air conditioning unit tripped ½ would not restart Caused by high discharge pressure 8gs being re-evaluated for permanent changes to increase capacity LAGIENSKI.J S . PENCE, W B Baitumore Gas & Electric Co 80/09/26
- POCKET 50-318 GALVERT CLIFFS NUCLEAR POWER PLANT. UNIT 2

 F Security, medical, emergency & fire protection plans
- 8007230165 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency GRIER.B H Region I, Philadelphia, Office of the Director BO/08/22 3pp
- 8007080350 Forwards "Fire Stop Penetration Test on Fire Protection Sys," final rept re Slab 2 ASH.R F Baltimore Gas & Electric Co 80/09/02 1p
- --B009080392 "Fire Stop Penetration Tests on Fire Protection Sys," final rept re 81ab 2 PISH.M D . POIRIER.L J , SCHRAEDER.A & Southwest Research Institute B0/08/15 182pp
- 8009300083 Submits status of fire protection mods & details of certain mods which cannot be completed per original schedule List of items requiring extended schedules encl LUNDVALL, A E Baltimore Gas & Electric Co 80/09/26 4pp
- O Adjudicatory correspondence
- 8007260528 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 CLARK.R A Operating Reactors Branch 3 80/08/29 2pp
- --8009260532 Order for mod of Licenses DPR-53 & DPR-69 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment info should be submitted by 801101
 EISENHUT, D O Division of Licensing 80/08/29 App
- J Insurance & indemnity information
- 8009300438 Forwards Endorsement 29 to MAELU Policy MF-76 & Endorsements 30 & 35 to NELIA Policy NF-216 SHOEMAKER.C L. Baltimore Gas & Ciectric Co. 60/09/26 4pp
- P Operating license stage documents & correspondence
- BO09020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emargency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D & Division of Licensing 80/07/31 7pp

- 8009080080 Forwards draft NUREQ-0095, "Functional Criteria for Energenty Response Facilities ' Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT.D O Division of Licensing 80/08/01 119pp
- 8009230352 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Cearned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of anend EISER#UT.D C Division of Licensing 80/08/07 60pp
- 8007020335 Forwards Corrected Tech Specs 4 5 1 7 & 4 5 1 b re sampling locations forwarded w/Amends 44 & 27 to Licenses DPR-53 & DPR-69, respectively CLARK.R A Operating Reactors Branch 3 80/08/15 2pp
- --8009020338 Corrected Tech Specs 3/4 5 re min boron concentration values which were included in Amends 44 & 27 to Licenses DPR-53 & DPR-69:respectively to Operating Reactors Branch 9 89/08/15 4pp
- B009150415 Informs that facility idea not have two specific Event 5 valve conrigorations discussed in NRC 800223 for re-primary coolant sys pressure isolation valves NRC activities revalve configurations have been finalized for facility CLARK.R A Operating Reactors Branch 3 80/08/15 2pp
- ~-8009150426 "Primary Coolant Sys Pressure Isolation Valves Calvert Cliffs Units 1 & 2." technical evaluation rept NGELL,P N. STILNELL,T G Franklin Institute/Franklin Research Center NRC-03-79-118 60/07/21 4pp
- 8007190350 Forwards Amends 45 & 28 to Licenses DPR-53 & DPR-69, respectively & notice of (squance & availability CLARK, R A Operating Reactors Branch 3 80/08/19 2pp
- --B009150J61 Notice of issuance & availability of Amends 45 & 28 to Licenses DPR-53 & DPR-69, respectively TRAMMELL.C M Operating Reactors Branch 3 60/08/19 2pp
- 8009150034 Bunmary of 800717 meeting w/C-E & util in Bethesda, MD re i8 month duel cycles for facilities Main purpose of meeting, to present overview of six documents submitted by util C m 800626, was fulfilled LI,C Y Operating Reactors Branch 3 80/08/20 4pp
- 8009090553 Submits general program for calculating RCB leak rates for most reactors from PNR vendors Results indicate periodic independent calculation of RCS leak rates by inspectors is recommended HODDRYFF,R W Division of Reactor Operations Inspections 80/08/21
- 8009020020 Forwards proprietary & nonproprietary versions of data sheets from Westinghouse low pressure turbine disc insp.to replace corresponding pages in 800318 ltr Proprietary version withheld (ref 100FR2 790) LUNDVALE.A E Baltimere Oas & Electric Co 80/08/25 App
- B009040301 Bescribas proposed design mods per NUREO-0578, Item 2 1 7a which requires implementation of safety-grade autostant of auxiliary feeduater by B10101 Drawing change notices encl. including one oversized drawing LUNDVALL.A E Baltimore Gas & Electric Co B0/08/27 13pp
- 8009190011 Provides instructions omitted from 800819 issuance of Amend 28 to License DPR-69 CLARK, A. Operating Reactors Branch 3 80/08/28 2pp
- 8007150250 Forwards response to NRC 800717 questions re C-E topical repts & review of safety evaluation re Westinghouse methodology for statistically combining uncertainties in state & sys parameters LUNOVALLIAE Baltimore Cas & Electric Co 80/09/10 17pp
- BOOP30G077 Forwards Amends 46 & 29 to Licenses DPR-53 & BPR-49, respectively, safety evaluation & notice of issuance & availability CLARK R A Operating Reactors Branch 3 BO/09/10 3pp

- --B00930080 Amends 46 & 27 to Licenses DPR-53 & DPR-69, respectively, changing App A Tech Specs for safety-related hydraulic snubbers & limiting conditions for operation of fire hose stations shutdown & onsite power distribution sys CLARK, R A Operating Reactors Branch 3 80/09/10 20pp
- --8009390083 Safety evaluation supporting Amends 46 & 29 to Licenses DPR-53 & DPR-69, respectively * Operating Reactors Branch 3 80/09/10 4pp
- --ROO9300085 Notice of issuance & availability of Amends 46 & 29 to Licenses DPR-53 & DPR-69: respectively CLARA.R A Operating Reactors Branch 3 80/09/10 2pp
- 8009160453 Responds to NRC 800911 request for add1 info re spent fuel pool mods Poison matl is 84C powder in fiberglass matrix irradiation data submitted to NRC on Haddam Neck & Millstone dockets in form of C80-M-79-299 dtd 781031 ASH.R F Baltimore Oas & Electric Co 80/09/12 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 6007240257 Farwards IE insp Regts 50-317/80-10 & 50-318/80-09 on 800518-20 No noncompliance nobed CARLSDMR T Region in Philadelphia, Reactor Construction & Engineering Support Branch 80/07/23 2pp
- --8009240269 IE Insp Repts 50-317/80-10 & 50-318/80-09 on 800618-20. No noncompitance noted Major areas inspected qualification data for electrical equipment inside containment as defined in licensee response to IE Builetin 79-018
 EBHETER.8 D Region 1. Philadelphia, Reactor Construction & Engineering Support Branch FINKELA E Region 1. Philadelphia, Office of the Director 80/07/14 16pp
- 8009160504 Responds to IE Info Notice 80-06, Suppl 1, "Notification of Significant Events at Operating Power Reactor Facilities" Proposed criteria requires medical judgment be made onsite & should be reconsidered TIERNAN, J A Saltimore Oas & Eiectric Co 80/08/08 1p
- 8009030i09 Forwards Revision I to IE Dulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER, D H Region 1, Philadelphia, Office of the Director BO/08/15 1p
- 8009180572 Forwards IE Circular 80-i8. "10CFR50 59 Bafety Evaluations for Changes to Radwasta Treatment Sys " No written response required ORIERS H Region 1. Philadelphia. Office of the Director OB/03/22 1p
- 8009120169 Forwards IE Info Notice 80-31. "Majoperation of Oduld-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required GRIER B H Region 1. Philadeiphia. Office of the Director 80/08/27 ip
- B009230776 Forwards IE Circular 80-21, "Regulation of Refueiing Crews" No written response required ORIER, B H Region 1. Philadelphia. Office of the Director 80/09/10 ip
- 8009240285 Forwards 1E Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matis " No written response required ORIER B H Region 1, Philadelphia, Office of the Director. 80/09/12 1p
- 8009250047 Ack receipt of payment of civil penalties in amount of \$21,000 proposed in NRC 800801 ltr & util 800821 ltr readdl corrective actions taken Further action will be based on future insps STELLO.V Office of Inspection & Enforcement, Office of the Director 80/09/17 2pp
- R Periodic operating reports & related correspondence
- 8009020034 Forwards "Semiannual Effluent Release Rept for Calvert Cliffs Nuclear Power Plant, Second Half 1979 " Meteorological summary for first half of 1980 will be submitted at later date LUNDVALL, A E Baltimore Gas & Electric Co 80/08/20 1p.
- --8009020035 "Semiannual Effluent Release Rept for Calvert Cliffs Nuclear Power Plant-Second Half 1979 " * Baltimore Gas & Electric Co 60/08/20 17pp

- 8009290246 Forwards monthly operating repts for Aug 1980 MERSON 6 D Baltimore Gas & Electric Co 80/09/15 in
- --8009290248 Monthly operating repts for Aug 1980
 MERSON:5 D Baitimore Cas & Electric Co 80/09/15 24pp
- S Reportable occurrences, LERs & related correspondence
- 8009030543 Forwards LER 80-036/03L-0 RUSSELL, L 8 Baltimore Qas & Electric Co 80/08/29 in
- --8007030549 LER 80-036/03L-0 on 800729, engineered safety features actuating sys channel ZE de-energized in three instances Channel ZE de-energized while troubleshooting Meter pointers to defective bistables oscillated DAVIS.5 M . RIZZO.P G Baitimore Gas & Electric Co 80/08/29
- B009250311 RO B0-51 on B00911.during post-maint test.control room air conditioning Unit 11 failed to start Attempt to restart Unit 12 failed Couse not state8 After corrective maint & repairs Units 11 & 12 returned to svc RUSSELL.L B Baltimore Gas & Electric Co 80/09/12 3pp
- 8009230520 Forwards LER 80-037/03L-0 RUSSELL.L B Baltimore Gas & Electric Co 80/09/18 ip
- --8009230527 LER 80-037/03L-0 on 800818.while reducing power due to saltwater leak-steam generator blowdown hydrogen ion concentrate fell below Tech Spec Limit Caused by failure to notice feed line from ammonia tank to manifold was shut off LAOIENSXI, J S. 8PECIALE, J R Baltimore Oas & Electric Co BO/09/18 2pr
- 8009300454 Forwards LER 80-037/03L-0 RUSSELLit B Baltimore Oas & Electric Co 80/09/26 ip
- --8009300450 LER 80-037/03L-0 on 800910 during normal operation, containment sump drain valves were open for 28 minutes & eusp level alarm sys was inoperable Caused by operator seror Control switch will be modified to spring shut MENDERLICH.R L Baltimore Gas & Electric Co. 80/09/26 2p
- DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2

 F. Security, medical, emergency & fire protection plans
- 8009230175 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Bys installed for govt use during emergency GRIER, B H Region 1. Philadelphia, Office of the Director 80/08/22 3pp

Adjudicatory correspondence

- SOCYCOTO337 Add1 response to FOIA request for TM1-2, "Startup Problem Rept" & intervenor Citizens Committee for Protection of Environ Proposed Findings of Fact & Conclusions of Law re Indian Point 2 Forwards intervenor filing FELTON, J M Division of Rules and Records 80/08/12 ip
- 8009030118 Response stating no opposition to NRC 800812 motion that Tech Specs proposed in Director of Ofc of Nuclear Reactor Regulation 800211 order be amended per 800811 mod Formal assend will await hearing outcome W/Certificate of Svc IROMBRIDGE, 0 F. RIDOMAY, D A Matropolitan Edison Co FROMERIDGE, 0 F. Shaw, Pittman, Potts & Trowbridge 80/08/27 5p
- 8009050425 Hotion for correction of record to include failures of instruments & equipment outside containment that contributed to IMI-2 accident Focuses on IMI-2 fuel pool which may endanger TMI-1 operation
 LEMIS.M I Affiliation Unknown 80/08/28 3pp
- 8009040239 Memorandum & order accepting WA Lochstet.8C Bholly & Environ Coalition on Nuclear Power as parties in proceeding Naw parties shall respond to NRC motion to conform proposed Tech Spacs per 800811 mod of order.by 800917
 HDLF.JF Atomic Bafety and Licensing Board Panel 80/08/29 2pp.
- 8009110779 Response in opposition to Environ Coalition on Nuclear Power B00922 request for free 800707 prehearing conference transcript Recommends that ruling on future transcripts be deferred pending consolidation Certificate of Svc encl SINGER, LN Hearing Branch 2 80/09/10 5pp

- BOOTIA0170 Response stating no objection to NRC BOORI2 motion to conform proposed Tech Specs w/Ofc of Nuclear Reactor Regulation BOORI1 mod of order Certificate at Bvc encl LOCHSTET.W A Affiliation Unknown BO/09/11 3pp
- 8009230628 Advises that York,PA LPPR will be closed on 800929 York TMI
 1 & 2 documents will be available at restart hearing NRC
 must be informed by 800924 if parties object to course of
 action
 SWARTZ,L L Antitrust Division 80/09/16 300
- 8009300011 Forwards util 800916 inter-oft memo organizing ABLB 801014 tour to facilities 8vc list encl Related correspondence BLAKE.E L Shaw, Pittman, Potts & Troubridge 80/09/22 7pp
- H General correspondence
- 8009020194 Informs that venting of krypton gas from TM1 constitutes genocide for US BJORKLUND, P.P. Affiliation Unknown 80/06/11 to
- 8009300246 Responds to 800415 ltr to President Carter re nuclear power plants Action plan developed to provide plan for actions now judged necessary by NRC to improve nuclear facility regulation & operation based on TM1 DENION, HR Office of Nuclear Reactor Regulation, Director 80/06/17 4pp
- 0007260205 Forwards N Ginder 800702 ltr expressing concerns re facility vanting t possible traces of krypton found in soil around area WALKER, R S House of Rep 80/07/09 2pp
- 8009110637 Responds to CP Cole B00214 ltm to President Carter expressing concerns me mate structure NRC has ordered that public hearings be conducted to determine whether facility should be operated REID.R U. Operating Reactors Branch 4 B0/07/25 4pp
- BOOPISO413 Responds to BOOP30 postcard recommonding licensing of nuclear plants that meet NRC stds TM1 accident precipitated NRC decision not to license new plants until safety criteria are implemented DENION.H R Office of Nuclear Reactor Regulation, Director BO/07/30 1p
- ---B009190416 Recommends licensing of nuclear power plants which comply w/URC stds
 RULEY,E Affiliation Unknown 80/0//23 2pp
- G009150240 Responds to 791024 ltr to President Carter re possible future operation of THI MRC will conduct meetings to determine under what conditions restart would take place & public will be given opportunity to raise questions GNYDER, B J TM1 Program Office G0/07/31 2pp
- --8009180241 Forwards S Kelley 791024 ltr misdirectod to dept for reply RATHKOPP.C L Energy. Dept of 80/01/22 App
- B007240107 Responds to 790829 ltr re focility accident Commission determined that accident does not most specific criteria for extraordinary nuclear occurrence as defined by Price-Anderson Act
 SNYDER, B J TMI Program Office 80/07/31 2pp
- --8009240121 Opposes NRC determination that facility accident was not extraordinary nuclear occurrence Decision Ignores possible long-term hazardous effects on workers subjected to continuous radiation exposure & on people offsite RICCITELLI, J Affiliation Unknown 79/08/29 lp
- B0090B033: Forwards NRC evaluation of info forwarded in 800616 ltr. order dunying motion for reconsideration of CLI-B0-25 & order for temporary mod of license Facility decontamination has been completed safely BENTON, HR Office of Nuclear Reactor Regulation, Director 80/08/05.
- 8007020151 Responds to 800422 ltr re K Meiman opposition to venting krypten from reactor bidg UCS concluded that direct radiation-induced physical health effects from purging would be absent Purging completed 800711 DIRCKS, W J Office of the Executive Director for Operations 80/08/06 2pp
- --8009020156 Forwards K Weimann comments on venting krypton from reactor bldg SCHULZE,R T House of Rep , Hays and Means 60/04/22 7pp

DOCKETED ITEMS

- 8007020166 Responds to 800523 ltm re concerns of FR Romano of Air & Mater Pollution Patrol about 800423 release of Kr-85 from facility
 DIRCKS-W J Office or the Esecutive Director for Operations
- --8009020168 Requests response to encl FR Romano 800512 ltr to NRC expressing concern about 800423 release of Kr-85 from facility SCHWEIKER, R S Senate 80/05/23 ip
- --8009020171 Comments on B00423 release of Kr-85 aircraft, pilots be passengers, utilizing airports in facility area, should have been notified of danger of lethal krypton, regardless of amount NRC acted irresponsibly by withholding info ROMANO, FR Air and Water Pollution Patrol B0/05/12 2pp
- 8007020172 Responds to 800221 ltr urging revocation of OL due to util inability to handle cleanup operations NRC will fully implement regulatory process in determining acceptability of cleanup operations
 SNYOER: B J TMI Program Office 80/08/11 2pp
- --E009020178 Favors revoking util CL due to incompetence & inability to handle cleanup operations CARPENTER.M. Affiliation Unknown 80/02/21 2pp
- 8009020315 Responds to 800401 ltr expressing appreciation for NRC efforts to repair damages resulting from accident Expresses gratitude for kind remarks.

 SNYDER. B. J. TMI Program Office 80/08/11 1p.
- --8009020317 Expresses appreciation for NRC efforts to repair damages resulting from accident DAILY,L , DAILY,H Affiliation Unknown 80/04/01 ip
- 8009020465 Responds to postcards re release of Kr-85 Potential public health impact from using any proposed strategies for removing Kr-85 is negligible Purging method is quickest & safest for workers to accomplish SNYDER,
- --8009020472 Expresses concern re release of Kr-85 from facility GL should be revoked Health of local people being damaged PETROSKY, J.A. Affiliation Uninoum 80/08/26 Zpp
- 8009030369 Responds to 800326 ltr expressing concerns re nuclear energy in Eight of facility (incident Specific plans have been made for portiding accurate info to public for serious accidents Lists RRC conclusions re disposal of krypton gas SNYDER, B J Till Program Office 80/08/11 3pp
- --8009030375 Expresses concerns to nuclear energy in light of facility incident Info re accident made available to public was confusing & inaccurate Alternate methods must be used to eliminate krypton gases from facility KROUT.N Q Affiliation Unknown 80/03/26 4pp
- B00903067B Responds to 800215 ltr urging revocation of util DL & permanent shutdown of facility Commission has ordered public hearing to determine if facility should be operated Forwards order outlining (ssues re-public health & safety M/o encl SNYDER, B J TMI Program Office 80/08/11 lp
- --8009030680 Urges revocation of util QL b permanent shutdown of facility due to threat posed to public health & safety ALTHQUSE, V Affiliation Unknown 80/02/15 1p
- 8009030681 Responds to 800215 ltr vrging revocation of util DL & permanent shutdown of facility Commission has ordered public hearing to determine facility operation Forwards order outlining issues re public health & safety W/o enci SNYDER, B J IMI Program Office 80/08/ti 1p
- --B009030683 Wrges revocation of util OL 2 permanent shutdown of facility due to threat posed to public health 2 safety
 SMEREY-A A Affiliation Unknown 80/02/15 3pp
- 8009050375 Responds to itr to President Carter re cleanup of contaminated water at facility EPICOR-II water treatment sys authorized for use in processing waste water in auxiliary bidg SNYDER B J TMI Program Office 80/08/11 2pp
- 8009100952 Responds to 791206 ltr re TM1 cteanup operations Commission issued order on 800612 for temporary mod of license, authorizing controlled purging of Kr-85 from reactor bldg atnosphere
 SNYDER, B J TM1 Program Office 80/08/11 2pp

- 8009170170 Responds to 800229 ltr re removal of Kr-85 from reactor bldg Forwards NUREG-0642,800610 order for temporary mod of license authorizing purging of Kr-85 & 800612 memo & order discussing retionale for decision to purge W/o encl SNYDER, B J TMI Program Office 80/08/11 2pp
- 8009170266 Responds to 800313 ltr re release of Kr-85 Potential physical health impact on public of using any proposed strategies for removing gas negligible Purging method is quickest & safest for workers to accomplish SN\DER,B J TM1 Program Office 80/08/11 2pp
- --B007170269 Expresses concorn re release of Krypton gas into atmosphera b dumping contaminated water into Susquehanna Rivor REINHART,M Affiliation Unknown 80/03/13 ip
- 8009170272 Responds to 800313 ltr re rolease of Kr-85 Potential physical health impact on public of using any proposed strategies for removing Kr-85 is nogligible Purging method is quickest & safest for workers to accomplish SNYDER, B J TMI Program Office 80/08/11 2pp
- ~~8009170275 Suggests method for venting Kr-85 into cryogenic processing or condense out radioactive gases in tank containing liquid helium All vent sys should pass through cyrogenics scrub TVILEMA'J S Affiliation Unknown 80/03/13 ip
- 8009020320 Responds to 800625 ltr re constituent Flick idea to solve rrypton gas problem at facility Krypton purging authorized by NRC on 800612 Authorization was based on detailed evaluation of alternatives DIRCKS/N J Office of the Executive Director for Operations 80/08/12 lp
- --8009020323 Requests response to encl R Flick ltr suggesting method to solve krypton gas problem at facility ATKINSON,E V House of Rep. 80/06/25 3pp
- 8009240100 Responds to 800630 ltr re identity of radionuclides in reactor bldg Km-89 was dominant radionuclide Concentrations of other isotopes were small SNYDER.B J THI Program Office 80/08/12 lp
- 8007020iiß Responds to 800702 ltr requesting into re BL Kelter inquiry about nuclear safety & energy alternatives Every effort being made to protect public health & safety at all nuclear plants Plants found unsafe are not allowed to operate DIRCKS W J Office of the Executive Director for Operations 80/08/13 25pp
- --9007020124 Requests response to encl BL Kelter inquiry about nuclear safety & energy alternatives WILLIAMS: H A Senate 80/07/02 2pp
- 8009020328 Responds to 800711 ltr re constituent concern that radioactive matls released during facility purging would pollute ME rainfail Low solubility of trypton & abundance of stable trypton limits sorption of Kr-35 in rainwater DIRCKS/N J Office of the Executive Director for Operations 80/08/13 30s
- --8009020332 Requests info re constituent contern that radioactive matts released during facility purging would pollute ME rainfail COHEN, W S Senate 60/07/11 ip
- 8009020293 Responds to 800212 telegram to President Carter requesting action to prevent major disaster at nuclear station Studies have resulted in addl licensee requirements
 SNYGER, B. J. TMI Program Office 80/08/14 3pp
- 8009020299 Responds to 800329 ltr expressing concerns re nuclear energy % opposing venting of radioactive gases & release of contaminated water Forwards summary of NUREO-0598.re population dose & health impact. % other matl W/o enci SNYDER, B J TM1 Program Office 80/08/14 4pp
- --8009020304 Expresses concerns re nuclear energy Opposes venting of radioactive gases & release of contaminated water ROGERS:L. Affiliation Unknown 80/03/29 3pp
- 8007020310 Responds to 800313 ltr re release of Kr-85 Potential public health impact from using any proposed strategies for removing Kr-85 is negligible Purging method is quickest & safest for workers to accomplish SNYDER, BJ TM1 Pragram Office. 80/08/14 2pp
- --8009020314 Expresses concern re release of Kr-85 from facility & affect on pregnancy. No releases should take place until alternative method found for cleanup BIALER, O Affiliation Unknown 80/03/13 2pp

- 8009090369 Responds to itr re release of radioactive matis into atmosphere from facility Based on evaluation of alternative trypton disposal methods 2 on public comment.NRC authorized controlled purging of reactor bldg ENYDER.B J TMI Program Office 80/08/14 4pp
- BO090503B6 Responds to 1tr re release of radioactive mat1 & urging permanent facility shutdown Public hearing ordered to determine whether facility should be operated & under what conditions restart would take place
 SNYDER.B J Office of Policy Evaluations BO/DB/14 3pp
- --8009050391 Requests that NRC prevent release of radioactive matis & contaminated water from facility RRNY. C. Affiliation Unknown 80/08/19 ip
- 8009050496 Responds to Hillside, NJ Board of Health 800410 ltr re release of radioactive gas from facility & health effects of radiation No significant environ impact would result from use of any disposal methods of krypton gases SMYDER, B J TMI Program Office 80/09/14 2pp
- --8009050498 Submits 800610 ltr to Governor Thornburg re release of radioactive gas from facility & health effects of radiation Venting of radioactive gas from facility will be dangerous to public health & safety

 BEYER.J M New Jersey. State of 80/06/10 ip
- 8009090350 Urgss that period for comment of EIS be extended for period not less than 90 days
 WALTERS.P W. WALTERS.H B Affiliation Unknown 80/08/14 1p
- 8009100068 Responds to 790816 Itr to President Carter re release of radioactive matl from facility Only low or nondetectible lavels currently permitted to be released Disposal of water processed by EPICOR-II to be discussed in programmatic EIS SNYDER.8 J TMI Program Office 80/08/14 3pp
- --8009100074 Forwards C Whitney 790816 ltr & newspaper article for proper handling RATHROFF, C. L. Energy, Dept of 79/09/21 4pp
- GC07170285 Responds to 770816 ltr re release of Kr-85 Potential physical health impact on public of using any proposed strategies for removing gas negligible Purging method is quickest & safest for workers to accomplish SNYDER.D.J TMI Program Office 80/08/14 2pp
- 8009:70362 Responds to 790818 ltr re release of Kr-85 Potential health impact on public of using any proposed strategies for removing gas negligible Purgling method is quickest & safest for workers to accomplish
 SNYDER.B J TMI Program Office 80/08/14 2pp
- --8009170365 Expresses concern re irresponsible util activities re release of radwaste into atmosphere Questions explanations for accidental release of radwaste Forwards newspaper clippings about accident MENEFEE, M B Affiliation Unknown 79/08/18 6pp
- 8009230760 Responds to 800316 ltr re release of contaminated water from facility Commission has authrolized use of EPICOR-II water treatment sys for waste water stored in auxiliary bldg tanks Discharge of EPICOR-II processed water not permitted SMYDER-8 J TMI Program Office 80/08/14 1p.
- --8009230764 Expression concern re newspaper article on accidental dumping of radwasts in Chesapeake Bay Dumping totally insecusable & will ruin bay HESI.J B Affiliation Unknown 80/03/16 2pp
- EODGOMO4B7 Responds to 800628 mailgram to J Collins re purging of krypton gases at facility Purging method was quickest & safest for workers at facility to accomplish disposal of trypton gases M/o encl orders & NVHEG-0662
 ENYDER.B J TMI Program Office 80/09/15 2pp
- ---8009020494 Protests purging of radipactive gases from facility Requests info re levels of radiation to which humans & crops were exposed during purging process YOUNO,R Affiliation Unknown 80/06/28 ip

- 8009020488 Responds to enci L Oetlys 800321 telegram to President Carter re health effects of radiation from TMI Team of investigators has concluded that health effects from TMI accident represents minimal risk to offsite population SNYDER.B J TMI Program Office 80/08/15 2pp
- 8009020502 Responds to B00324 ltr re specific ill effects suffered by family farm animals & pets Investigators concluded offsite collective dose from radioactive matl represents minimal health rists N/O encl summary of NUREO-0558 SNYDER.B J TM1 Program Office 80/08/15 2pp
- --8009020515 Piesents bill & claims for damages caused by effects of nuclear radiation & gas releases from racilities identifies specific damages & requests payment in full or settlement HOLOHKA, P Affiliation Uningum 80/03/24 4pp
- 8009050366 Responds to 900225 ltr +o First Lady re continuing operation of racilities Public hearing to be held to determine if racilities should be operated & conditions of restart W/o Commission 790909 order SNYDER, B J TMI Program Office 80/08/15 2pp
- 8009220049 Responds to encl 800505 ltr to President Carter urging revocation of facility OLs Public hearing will be held refuture operation of Unit 1 Licensee has not yet submitted proposal ror overall recovery of Unit 2 SNYDER, B J TMI Program Office 80/08/15 4pp
- 8009230233 Responds to mailgram & ltrs re release of radioactive gases & Water from facility Alternatives for disposal of krypton considered prior to purging decision Collective offsite dose from 790328 accident represents minimal risks SNYDER.B J TMI Program Office 80/08/15 3pp
- --8009230239 Comments on NRC 790814 announcement of possibility of venting radioactive gases into atmosphere over 30-day period venting should not take place DRA2, Z The Tribune Chronicle Warren.OH 79/08/14 lp
- --8009230242 Comments on NRC 790814 announcement of possibility of venting radioactive gases into atmosphere over 30-day period venting should not take place
 RRAZ.Z The Tribune Chronicie Warren. CH 79/08/14 lp
- --8009230245 Comments on NRC 790814 announcement of possibility of venting radioactive gases into atmosphere over 30-day period venting should not take place-NRC on record stating that no safe dose of radiation exists
 DRAZ, Z The Tribune Chronicle, Warren DH 79/08/14 lp
- --8009230247 Comments on NRC announcement of possibility of venting radioactive gases into atmosphere over 30-day period venting is immoral & should be stopped NRC findings state that no safe level of radiation exists DRAZ, Z The Tribune Chronicle, Warren, OH 79/08/14 19
- 8009030187 Responds to 800704 itr re cleanup activities at TMI Licensee has not submitted proposal for overall plant recovery SNYDER.B J TMI Program Office 80/08/18 2pp
- --8009030194 Supports venting Kr-85 from reactor bldg Federal govt should absorb portion of cleanup costs EENIGENBURG. J Affiliation Unknown 80/07/04 2pp
- 8009110268 Forwards response to 800528 ltr forwarding RC Gray questions on condition of reactor core & volnerability of equipment & instrumentation in facility reactor bldg DIRCKS, W. J. Office of the Executive Director for Operations 80/08/18 8pp
- 9009120736 Responds to 900220 ltr re handling of incident Ensures continued protection of public safety & health DENTON.H R Office of Nuclear Reactor Regulation. Director 80/08/19 1p
- 8009180548 Responds to 800714 ltr re solution for safe removal of gases in confined areas Gas compression method was considered but to procure, install, check out 5 proof test sys would take 2 to 4 yrs
 DENION.H R Office of Nuclear Reactor Regulation, Director 80/08/19 4pp
- --8009180560 Forwards F Rongstad 800714 ltr for review re suggestion for safe method for disposal of contaminated gases
 GLAUSEH, D H House of Rep 80/08/01 lp
- --8009180565 Forwards schematic diagram & explanation for safe removal of gasses in confined areas
 RDNGSTAD.F Affiliation Unknown 80/07/14 3pp

- 9009110501 Responds to 800423 ltr relenci 9 Trust concerns about health effects or 790328 accident % purging reactor bldg atmosphere Several of Trust concerns result from misunderstanding & misapplication of info DIRCKS:
- 8009110494 Responds to 800529 ltr re CW Eneric's concerns about releases of Kr-85 into atmosphere around facility Purging approved 800612 commenced 800628 % concluded 800711 Discusses studies on thyroid disorders
 DIRCHS.MJ Office of the Executive Director for Operations 80/08/22 6pp
- 8009150324 Responds to 790701 ltm to MRC me TM1 accident Commission has ordered public hearing to determine whether TM1-1 should be operated Communication difficulties attributed to impairment of info from control room to offsite groups SMYDER.B J TM1 Program Office 80/08/22 App
- --8009150327 Expresses concern re TMI accident Util deliberately deceived public in crucial days following accident & should not be allowed to reopen TKI-t RUDDLEY.SE Affiliation Unknown 79/07/01 4pp
- 8009150330 Responds to 800326 ltr re reopening of TMI Licensee has not submitted proposal for overall recovery of Unit 2 NRC 790702 order directed Unit 1 to remain in cold shutdown, pending outcome of restart hearing SN1DER. B J TMI Program Office 80/08/22 2pp
- --8009150336 Requests cleanup & reopening of TMI RABUCK.B Affiliation Unknown 89/03/26 4p
- 8009150343 Responds to Itr to NRC re reopening of THI facilities Public hearing will be beid re TMI-1 restart Licensee has not submitted proposal for everall recovery of IMI-2 SNYDER.B.J. THI Program Office 80/08/22 2pp
- --8007i50346 Expresses desire for TMI restart Util followed all notification procedures on 790328 NRC & util should be supported in cleanup operation SMITM.J & Affiliation Unknown 80/08/22 2pp
- 8009150441 Responds to 800609 itr expressing concern re radwaste ventslation 2 cleanup Potential physical health impact on public of using any proposed strategies for removal of Kr-85 is negligible BNYDER.B J TMI Program Office 80/08/22 2pp
- ~~BOO9150445 Expresses concern re radumsta ventifation & cleanup LOOX, J Affifiation Unknown BO/06/09 1p
- 8009:50452 Responds to encl People of the Earth ltr to President Carter expressing concern for release or Kr-85 from Unit 2 Potential physical health impact using any proposed strategies re Kr-85 removal is negligible SNYDER.B J THI Program Office 80/08/22 4pp
- G009160101 Responds to encl 791031 ltr to President Carter re actions taken at TMI Licensees of all operating plants utilizing PMRs have been instructed to take actions re status of equipment procedures & facility designs
 SNYDER.B J TMI Program Office 80/08/22 App.
- 8009:70297 Responds to 800216 Itr urging revocation of util DL NRC has ordered public hearing re THI-1 restart Util has not submitted proposal for overall recovery of Unit 2 SNYDER B J THI Program Office 80/08/22 lp
- --8009170263 Urges revocation of util OL for TMI CONHEY, J Affiliation Unknown 80/02/16 2pj
- 800917027i Responds to encl 800411 ltr to President Carter re safety of TMI vicinity NRC.EPA & HEW investigations have shown offsite dose associated w/rad/coactive mati released from 790328-0429 represents minimal risk SNYDER.B J TMI Program Office 80/08/22 3pp
- 8009230194 Responds to 1tr urging revocation of util OL.NRC has ordered public hearing to determine Unit 1 operation feasability & possible restart conditions Licensee has not submitted proposal for overall recovery of Unit 2 ENYDER. B J THI Program Office 80/08/22 ip
- --8009230202 Urges revocation of util CL BRISCOE.G A Affiliation Unknown 80/08/22 1p

- 8009230216 Responds to 790726 ltr re TMI accident & subsequent ventilation of radwaste Potential physical impact on public fram using any proposed method for removing Kr-85 is negligible StyDER.E J TMI Program Office 80/08/22 5pp
- --8009230222 Requests info re TMI accident & subsequent ventilation of raduate CLANTZ, C Affiliation Unknown 79/07/26 2pp
- 8007:00206 Responds to 800421 ltr to President Certer re operator training & public awareness re TMI accident Human errors due to incorrect interpretation of RCS instrumentation Centralized dissemination of NRC info planned SNYDER:8 J YMI Program Office 80/09/25 App
- 800915032: Responds to postcard re safe decommissioning of nuclear reactors & studies of reactor health effects Specific NRC actions include employment of full-time inspectors at TMI, licensee instruction & emergency preparedness planning SNYDER.B J TMI Program Office 80/08/25 2pp
- --8009150325 Requests safe decommissioning of ail commercial nuclear reactors & performance of health impact studies to determine effects of nuclear energy XELLY.K Affiliation Unknown 80/08/25 2pp
- 8009150351 Responds to 800403 ltr re rejease of Kr-85 at facility NRC evaluated alternative methods for venting Kr-85 to determine effect on personnel, public health & safety & environ Environ assessment issued for public comment SNYDER, B J TMI Program Office 80/08/25 2pp
- --8009:90355 Expresses concern ro venting Kr-85 at facility NRC attitude toward psychological stress may be major factor in venting delay BURGER.A C Affiliation Unknown 80/04/03 2pp
- 8009190750 Responds to enci 800424 itr to President Carter expressing concern re THI effects on environ Efforts made to ensure continued wetfare of public outlined SNYDER.B. J. THI Program Office 80/08/25 9pp
- 8009110280 Responds to 800728 itr requesting info re safety of Midland & Fermi plants Ali nuclear plants subj to enhanced safety requirements resulting from TMJ Lessons Learned Task Force recommendations Supporting documentation encl DIRCKS.W J Office of the Executive Director for Operations 80/08/26 24pp
- --8009110288 Requests consideration of encl MC Haight itr re safety of Midland & Fermi piants BROUNFIELD, M S House of Rep , Foreign Affairs 80/07/28 2pp
- B009110314 Responds to 800710 ltr re R Collins concerns about facility decontamination Prior to purging NRC examined several alternatives for decontamination Krypton exists normally as only one constituent of air breathed DIRCKS V J Office of the Executive Director for Operations. B0/08/26 2pp
- ~~8009110319 Forwards R Collins ltr inadvertently omitted from 800710 ltr W/o encl PICKLEJ J House of Rep , Nays and Means 80/07/23 lp.
- --8009110322 Requests comment on encl R Collins ltr questioning NRC decision to vent facility krypton gas PICKLEJ J House of Rep , Mays and Heens 80/07/10 3pp.
- 6009170004 Responds to 790810 itr re accident at TMI NRC has ordered public hearing to determine whether TMI-1 should be operated & under what conditions restart would take place Licensee has not yet submitted proposal for overall recovery SNYDER, B J TMI Program Office. 80/08/26 3pp
- --8009170911 Urges NRC to restore feeling of normalcy to community around TMI Recommends that NRC wait until all investigations are completed before reopening TMI-1 Any premature opening would suggest that economics come before public safety HEIVLY.B J Affiliation Unknown 79/08/10 3pp
- 80091702B3 Responds to 800Ri& ltr re release of Kr-85 Potential physical health impact on public of using any proposed strategies for removing gas negligible Purging method is quickest & safest for workers to accomplish SNYDER.B J TMS Program Office 80/08/27 2pp

- --8009\$70284 Expresses concern re release of radioactive matis into atmosphere Facility CL, should be revoked because of MetEd Lies & incompetence CLAY.R V Affiliation Unknown 80/02/16 2pp
- BOD9[10212 Responds to 800709 ltr re N Ginder telcon about radio rept on krypton found in soli following facility purging Krypton is noble gas which is chemically inert & does not concentrate in soil DIRCKS.H J Office of the Executive Director for Operations 80/08/28 2pp
- EOOP110218 Forwards response to 800728 ltr requesting assistance in answering constituent questions re nuclear power & effects of radiation DIRCKS,H J Office of the Executive Director for Operations 80/09/28 4pp
- 8009090502 Suppl change request for organization plan. Revision 1. which defines proposed new mgt organization Proposed change does not after licensee responsibility for operation MCYEV, G K Hetropolitan Edison Co 80/08/29 ip
- 8009090556 Forwards revised pages to 800812 submittal re organization plan. Peviston 14 MOYEY, O K Metropolitan Edison Co 80/08/29 Spp
- 6009160596 "Organization Plan" * Natropolitan Edison Co 80/08/29 ip
- E0091803B1 Opposes extension of 45-day period for public comment on MAREG-0283 Addl delay would seriously hamper operation of cleanup & cause economic hardship on area residents E0046,P A Affiliation Unknown B0709704 ip
- 6009090380 Urges NRC to survey socioeconomic composition of Cumberiand County re preliminary DES concerning TMI cleanup RYERS.J A , PUNT.N A Cumberiand County. PA 60/09/05 2pp
- 2009090571 Requests extension of public comment period re programmatic £18 NRC treatment of public & apposition ltrs during comment period re trapton venting lacked honesty & decency HOCKER,M M Affiliation Unknown 80/09/05 3pp
- B009150546 Requests copyright release for 15 articles re TMI accident gublished in the NY Times SNYDER/B J TMI Program Office B0/09/05 2pp
- BOOG150547 Requests copyright release for 19 articles published in Philadelphic Inquirier re TM1 accident SN/DER.B J TM1 Program Office BO/09/05 2pp
- 8009300801 Requests that encl copyright release form for listed article be signed & returned to NRC by 800917 Article was snadvertently printed in Vol 2 of "Final EiA for Decontactination of THI-2 Reactor Bidg Atmosphere "
 SMYDER. II J THI Program Office 80/09/05 2pp
- B009300610 Requests that encl copyright release form for listed articles be signed & returned to NRC by 800919 Articio was inadvertently printed in Voi 2 of "Final EIA for Decontamination of TMI-2 Reactor Bldg Atmosphere"
 SNYDER.B J TMI Program Office 80/09/05 2pp
- 8009300836 Requests that encl copyright release form for listed article be signed & returned to NRC by 800917 Article was inadvertently printed in Vol 2 of "Final EIA for Decontamination of TMI-2 Reactor Bldg Atmosphere "
- 6009300638 Requests that encl copyright release form for listed articles be signed & returned to NRC by 800919 Articles were inadvertently printed in Vol 2 of "Final EIA for Decontamination of TMI-2 Reactor 81dg Atmosphere "ENYDER.8 J TMI Program Office 80/09/05 2pp
- 8009180338 Supports view of nuclear power as unhealthy & counsels patience in search for alternative energy sources Supports 90-day pariod for public comments re EIS KATTENBACHER.F Affiliation Unknown 80/09/11 2pp.
- 8009220215 Requests 90-day extension for comments on EIS ERB-M B Affiliation Unknown 80/09/12 ip
- 8009270331 Discusses study re mutant plants as result of TMI accident Instruments may be able to detect radiation, but not genetic demage Nawspaper articles re study encl AREMART, T. Affiliation Unknown 80/09/12 3pp

- 8007230126 Informs that organization plan submitted in 800821 ltr & supplemented in 800829 ltrs re mgt ½ support of facility in current status has been approved COLLINS.J T THI Program Office 80/09/15 4pp
- 8009300159 Responds to 1tr re excessive electric bil) NRC does not set rates that utils charge for electricity Accident at Unit 2 also caused Unit 1 to be shut down Excerpt from DDE rept encl
 DENTON: H R Office of Nuclear Reactor Regulation, Director B0/09/15
- --8009300163 Expresses concern re high util bills People on fixed incomes cannot afford cost of energy FASIG.F Affiliation Unknown 80/09/15 ip
- 8009290148 Adds name.as Township Manager for Springettsbury Township. to distribution list for ducuments re TMI.as requisted in 800822 ltr SNYDER.B J TMI Program Office 80/09/16 tp

I Financial information

- 8009090602 Summary of 800814 meeting w/Met Ed & Deneral Public Utils (GPU) at NRC re GPU financing plan over next 10 yrs Basis for plan, "Financial Forecast Reflecting Revised Estimate of TMI-2 Clean-up & Recovery" encl SILVER.H Operating Reactors Branch 4 80/08/26 5pp
- --B009070600 "Financial Forecast Reflecting Revised Estimate of TMI-2 Clean-up & Recovery " Util B00808 press release enck # General Public Utilities -- GPU Service Corp B0/08/14 4ipp
- 8009180370 Forwards Citibank.N A 800905 ltr notifying General Public Utils Corp of reduction in util credit availability, per 800910 telcon request CARROLL.D General Public Utilities GPU Service Corp 80/09/11
- 8009160359 Forwards matis re General Public Utils Svc Corp economic measures SM Shanaman (PA Public Utils Commission) 800827 statement to PA Congressional delegation enci HDMSDN.T G General Public Utilities GPU Service Corp 80/09/12
- P Operating license stage documents & correspondence
- 8009020493 "Final Environ Assessment for Decontamination of TMi Unit 2 Reactor Bldg Atmosphere," Vol 1 of final NRC staff report # TMI Program Office NUREO/CR-1662 Vi 80/05/3i 96pp Available at NTIS
- 8008060358 Forwards errata sheets correcting errors in five add1 TMI-2 rolated requirements submitted by 800507 ltr Items involved are II K 3 25.11 K 29 & II K 3 48 Svc lists encl
 EISENHUT, D 6 Division of Licensing 80/04/09 49pp
- 8009110563 Responds to 1E comments re TMI-2 Lessons Learned Tech Specs Proposed addition is covered in currently existing Tech NGVAK, T M Assistant Director for Operating Reactors 80/06/10
- 8009950370 FOIA request for list of all isotopos found in facility containment bldg atmosphere samples for 800301-0412

 BALTER, J Public Interest Law Center of Philadelphia 60/06/12
- B007020152 Requests clear copies of util missing documents referenced in Rogdvin rept within 30 days of receipt of ltr Missing list of documents encl SNYDER.B J THI Program Office 80/07/02 5pp
- 8009090572 Forwards draft programmatic EIS re decontamination & disposal of radwastes resulting from 770328 accident at facility Request for public comments is being sent to Ofc of Federal Register Wio enc!
 SNYDER. B J THI Program Office 80/07/30 ip
- --8009090604 Notice of issuance & availability of draft programmatic EIS for decontamination of facility SNYDER:8 J TMI Program Office 80/08/11 2pp
- --8009090611 Forwards FR notice & draft programmatic EIS re decontamination & disposal of radwastes resulting from 790328 facility accident W/o encl SNYDER.3 J TMI Program Office 80/08/14 4pp

- B0090B00B0 Forwards draft NUREO-0696. "Functional Critaria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria or NUREO-0696 enci M/o NUREO EISENHUT, D @ Division of Licensing 80/08/01 119pp
- 8007070603 Responds to LE Roynolds 800715 request for proprietary classification of SDS polishing unit description Rept withheld (ref 10CFR2 790)
 COLLING.J T RC Three Mile Island Task Force 80/08/06 4pp
- B009110678 Responds to G Hovey 800725 ltr re pre-accident spent resin disposal Concurs w/disposal plan for matl generated prior to 790328 accident CULLINGS J T RAC Three Mile Island Task Force B0/08/06 App
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D G Division of Licensing 80/08/07 40pp
- 8009050367 Responds to FOIA request for list of all isotopes found in facility containment bldg atmosphere samples for 800301-0612 Forwards document Division of Rules and Records 80/08/08 1p
- --8007050376 Analyses of gaseous isotopes found in facility containment bldg atmosphere for 800301-0412 4 Netropolitan Edison Co 80/06/12 2pp
- 8009090783 Informs of NRC actions re NUREO-0683, "Programmatic E18 on Decontamination & Disposal of Radwaste Resulting from 790328 Accident at YMT-2" Lists findings & conclusions re environ impacts of cleanup W/o encl NUREO-0683 DENIONI HR Office of Nuclear Reactor Regulation, Director SECY-80-295A 80/08/11 4pp
- 8009190619 Advises that NRC considers TMI-2 reactor bidg atmosphere purge complete as of 600711 Effluent releases should again be conducted in accordance w/original App B Tech Specs SNYDER.B J TMI Program Office 80/08/19 3pp
- 8009090155 Forwards proposed outline for revising document draft. "Psychological Stress & Alternatives for Decontamination of IMI Nuclear Station.Unit 2" Restart or decommissioning of plant beyond scope of document REGAN.W H Siting Analysis Branch 60/08/18 5pp
- 8009020037 Responds to NRC 800806 ltr requesting commitment date for submittal of contingency plan for alternate storage of reactor bldg sump water Plan will be completed wt of 801013 & submitted by 801017 ARMOLD,R C Metropolitan Edison Co 80/08/22 ip
- 8009020075 Forwards ORNL Jul 1980 rept "Evaluation of Submerged Demineralizer Bys Flowsheet for Decontamination of High-Activity-Level Mater at THI-2: " per commitment to update 800613 response re column performance test results HOVEY, Q K Metropolitan Edison Co 80/08/22 1p
- --8009020080 "Evaluation of Submerged Damineralizer Sys Flowsheet for Decontamination of High-Activity-Level Water at TMI-2" CAMFDELL, D 0 . COLLINS, E D . KING, L J Oak Ridge National Laboratory ORNL/TM-744B 80/07/30 Slpp
- 8007030529 Forwards ORKL final rept "Evaluation of Submerged Demineralizer Sys (SDS) Flowsheet for Decontamination of High-Activity-Level Mater at TMI Unit 2 Nuclear Power HOVEY, G K Metropolitan Edison Co 80/08/22 2pp
- --8009030534 "Evaluation of Submerged Demineralizer 8gs (SD8) Flowsheet for Decontamination of High-Activity-Level Water at TM1 Unit 2 Nuclear Power Station " CAMPBELL-D O. COLLING-E D. KINO, L. J. Oak Ridge National Laboratory ORNL/IM-7448 80/07/31 84pp
- 8009120677 Forwards review.w/comments & questions.of EPJCOR II resin solidification test program CDLLINS, J T TMI Program Office 80/08/22 App
- 09t00145 Forwards responses to Ofc of Elecutive Director for Operations comments on NRC overview of 731-2 radiation protection program DENION,H R Office of Nuclear Reactor Regulation, Director BD/08/25 Jpp

- -8009100151 Forwards draft philosophy statement & alternate proposals for TMI Site Ofc.in response to 800228 request Info re radiation protection plan encl CREMS.J L Region 5. San Francisco, Reactor Operations Nuclear Support Branch 80/02/29 24pp Support Branch
- 8009030473 Forwards missing documents previously provided by util to NRC/TM1 Special Inquiry Group in response to 800718 request Provides listing of documents Documents are cross referenced to Rogavin rept M/o encls
 HDVEY.G K Metropolitan Edison Co 80/08/26 2pp
- 8009i60394 Notifies of reversal of util 800324 plan re relocation of EPICOR-I Bys to Unit 2 side of fence Sys is mostly used to process TMI-I wastowater Relatively small amounts of Unit 2 wastewater treated by sys HOVCY, G K Metropolitan Edison Co 80/08/26 3pp
- B009030421 Requests 45-day extension to comment period for programmatic E18 re TMI cleanup process Public hearing should be conducted prior to drafting of final version SHQLLYS C Three Mile Island Public Interest Resource Center B0/08/27 2pp
- 8009040412 Ack receipt of NUREO-0483 re decontamination & disposal of radwastes at TMI-2 NUREO does not address possibility that zirconium hydridos may be present in reactor core Presence of irconium may change procedures for removal & disposal QULBRANSEN.E A Pittsburgh, Univ of 80/08/27 2pp
- 8007120582 Responds to FOIA request for two documents concerning ECC8 in B&W reactors Forwards documents FELTON.J M Division of Rules and Records 80/08/28 1p
- --8009120589 Forwards results for TMI-2 severe overcooling transient w/
 upperhead connection includes geometry changes to better fit
 FBAR data, vent valves between upper plenum & downcomer & new
 steam generator secondary pressure table
 WILLCUTT, G J F Los Alamos Scientific Laboratory 80/06/25
- 8009030554 Requests extension of public commentary date for EIS beyond 801005 Stresses length complexity & importance of EIS EPSTEIN.E G Affiliation Unknown 80/08/29 2pg
- 8009090421 Comments on swetions of draft programmatic EIS re psychological atress issue Rept implies that residents w/ misglyings about util & regulatory competence are unbalanced Rept lacks objectivity & empathy WALSH.E J Affiliation Unknown 80/09/03 1p
- 8007160382 Responds to 800718 request for comments re evaluation of EPICOR 11 wastes Evaluation will not be completed until end of Sopt 1980 due to Epicor. Inc proprietary restrictions on release or info Forwards waste staging drawings W/o encl HOVEY, O K Metropolitan Edison Co 80/09/04 Spp
- B009140395 Forwards Attachments 2 % 5 to util B00904 ltr re evaluation of EPICOR-II wastos Attachments withheld (ref 10CFR2 790) HOVEY, C K Metropolitan Edison Co 80/09/04 ip
- 8009180371 Requests extension period to study TMI DES Public needs more time to understand study WATT.C H Affiliation Unknown 80/09/05 1p
- 8009R60050 Requests that encl copyright release form for listed article to signed & returned to NRC by 800919 Article was inadvertently printed in Vol 2 of "Final EIA for Decontamination of TMI-2 Reactor Bldg Atmosphere "
- 8007240083 Requests that oncl copyright release form for listed article be signed & returned to NRC by 800717 Article was inadvertently printed in Vol 2 of "Final EIA for Decontamination of TMI-2 Reactor Bldg Atmosphere "
- 8009240093 Requests that encl copyright release form for listed article be signed & returned to NRC by 800919 Article was inadvertently printed in Vol 2 of "Final EIA for Decontamination of TMI-2 Reactor Bldg Atmosphers."

 SNYDER, B J TMI Program Office 80/09/05 2pp.
- 8009120494 Discusses "primary method of decay heat removal" interpretation & provides insight re util intended method of decay heat removal Requests that MDHR sys recovery operations plan change request be approved as written HDVEY, O X Metropolitan Edison Co 80/09/08 3pp

- BOO7:50432 Submits addl info requested by NRC re 480 volt buses 2-38 & 2-49 per MDMR Tech Spec change request Buses are no longer required, due to supplementary ventilation sys being taken out of svc.
 HDVEY.Q K. Hetropolitan Edison Co. 80/09/08 1p
- --B009130435 *480 V USS 2-38,2-48 & Distribution Panel PDP-5A,58 Dne Line Diagram "

 * Burns & Roe Co 79/08/31 10
- 8009150554 Responds to NRC concerns re util 800731 request for Tech Spacs & recovery operations plan changes required for MDHR sys Change establishes criteria for selection of lower standby pressure control sodium bank pressure MOVEY.O K. Matropolitan Edison Co. 80/09/08 1p
- BOO9160331 Forwards Attachments 2 & 5 to util BOO904 ltr re drawings of waste staging facility per requests for comments on evaluation of EPICOR II wastes Info withheld iref IOCFR2 790)
 BOVEY, O K Metropolitan Edison Co 80/07/08 4pp
- BD09170316 Forwards "Freimmary Sys Description Task Ts-27, Mini Decay Heat Removal Sys." Revision 3 HOVEY.O K Metropolitan Edison Co 80/09/08 lp
- --B009170317 "Preliminary Bys Description Task Ts-27.Mini Decay Heat Removal Bys." Revision 3 BROWNEHELL, R P Burns & Ros Co 80/08/18 62pp
- BOO9170377 Requests approval for shipment of several EPICOR II rosin liners which have been expended during course of processing auxiliary bidg waters Dates of proposed shipments not established HOVEY.O K Metropolitan Edison Co 80/09/OB ip
- BOD7180359 Requests extension of 45-day comment period for facility EIS to 90 days
 SCHALDRIS 1. Affiliation Unknown 80/09/08 1p
- PO09290235 Ack acceptance of invitation to study health & safety cansequences associated w/disposition of decontaminated accident generated waste water Draft preliminary EIS & radionuclide distribution tables encl
 DENTORIER Office of Nuclear Reactor Regulation, Director 80/09/00 5pp.
- 8009110328 Forwards "TMI-2 Recovery Program Estimate "
 CHIN,H Y Ceneral Public Utilities OPU Service Corp B0/09/09
 19
- --B009110330 "TM1-2 Recovery Program Estimate "
 * General Public Utilities GPU Service Corp 80/08/01 69pp
- 8009120416 Forwards draft Tech Spec 3 3 1 1 re neutron monitoring instrumentation in response to 800822 ltr Radiation level fata for containment entries will be provided by licensee FSSR & other matl available in LPDR GDLD
- 8009(8039) Requests extension of period for comment on E18, NUREG-0683, to 90 days KNOUFF.Q Affiliation Unknown 80/09/10 1p
- 8009220277 Forwards color photo negatives from second entry into containment bldg W/o enc!
 HDVEY.O K Metropolitan Edison Co 80/09/11 1p
- 8009220342 Urges NRC to extend deadline from 45 days to 60, for study & comment on 618
 PETERSON. J M Affiliation Unknown 80/09/11 ip
- 8009160359 Forwards matts re General Public Utils Syc Corp economic measures EM Shanaman (PA Public Utils Commission) 800827 statement to PA Congressional delegation encl HCMSON. T G General Public Utilities GPU Service Corp 80/09/12 279p
- --B009160961 Discusses actions taken by owners re TMI-2 cleanup plans DIECKAMP.H General Public Utilities - GPU Service Corp E0/09/12 3pp
- BOC9170255 Advises that util will not rely on regulatory guidance or definition of criteria or approval to proceed W/major cleanup activities until completion of final programmatic EIS

 DIECKAMP, H Ogneral Public Utilities GPU Service Corp 80/09/12.

- 8009220346 Requests extension of 45-day period for public comment on EIS to 90 days Cites public concern that NRC favors util stockholder interest over public safety BI(LER.E Affiliation Unknown 80/09/12 ip
- 8009220129 Submits info re personnel training for submerged demineralizer sys Multiphased approach includes classroom training re sys operation; theory & practical factors training NRC participation welcomed MOVEY.G K Metropolitan Edison Co 80/09/15 ip
- BOO9250440 Ack receipt of BOO626 ltr re operation & location of EPICORl Requests indication of what measures are available to assure that sys will not be operated by Unit : Procedure 1104-27% COLLINS, J T TMI Program Office BO/09/15 2pp
- 8009240541 Forwards tritium monitoring results from TMI groundwater & soil samples Tritium level analysis in Observation Wells ON-138.0N-14 & DM-17 enci
 RIETHLE.W E General Public Utilities GPU Service Corp 80/09/16
- 8007220276 Responds to NRC 800805 ltr submitting recommendations re TMI worker registry for use in potential studies of radiation effects Proposed definition of worker would be impractical, due to number of visitors receiving little or no radiation HGVEY, G K Metropolitan Edison Co 80/09/30 2pp
- 8009300387 Submits clarification of & interpretation re definition of primary method of decay heat removal % intended method of docay heat removal HGGEY, GK Metropolitan Edison Co 80/07/30 4pp
- G Inspection reports, IE Bulletins & correspondence
- 8009030044 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required ORIER.B H Region 1, Philadelphia, Office of the Director
- 8009020241 Responds to IE Bulletin 79-23 Review of emergency diesel generators revealed that no connection exists between generator neutrals & primary winding of exciter power transformer Operational tests failed to show subj condition HOVEY, O K. Metropolitan Edison Co. 80/08/22 2pp
- B009030372 Responds to IE Bulletin 80-05 Review indicates that 28 of 30 tanks are adequately protocted from Nacuum condition resulting in tank buckling Supporting documentation encl HOVE7.0 K Metropolitan Edison Co 80/08/22 4pp
- 8007180013 Forwards IE Circular 80-18, "10CFR50 57 Safety Evaluations for Changes to Radwasto Treatment Sys " No written response required GRIER, D H Region 1, Philadelphia, Office of the Director 80/09/22 1p
- 8007120184 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boyeri 480 Volt Type K-6008 & K-DON 6005 Circuit Breakers " No written response required ORIER B H Region I, Philadelphia, Office of the Director 80/08/27 ip
- 8009170334 Notifies that response to findings of NRC special insp. identified in Stello 800807 ltr to Arnold, will be submitted by 800909 HDVEY, 0 K Metropolitan Edison Co 80/09/05 lp
- 8009300014 Responds to NRC 800807 ltr re violations noted in lE Insp Repts 50-320/80-10 t 50-320/80-14 Containers for liquid radwaste now meet code requirements Containment vessels proven leak resistant Payment for civil penalties encl ARNOLD, R C Metropolitan Edison Co 80/09/08 4pp
- 8007230770 Forwards IE Carcular 80-21, "Regulation of Refueling Crews" No written response required CRIER.8 H Region 1, Philadelphia, Office of the Director 80/07/10 1p
- 8009240316 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required GRIER.D H Region i, Philadelphia. Office of the Director 80/09/12 Ip

R Portodic operating reports & related correspondence

- 8009020135 Forwards weekly status rept for 800803-09 CCLLINS, J T THI Program Office 80/08/11 App
- GOO9070796 Forwards status rept for whof BOOB10-16 COLLINS.J T TMI Program Office BO/08/18 App
- 8009100375 Forwards TMI Program Ofc status rept for wk of 800817-23 COLLINS.J T TM1 Program Office 80/08/25 5pp
- 8009190539 Forwards weekly status rept for wk ending 800823 COLLING, J T TMI Program Office 80/08/25 5pp
- G009150532 Forwards weekly status rept for wk ending 800829 COLLINS.J T TMI Program Office G0/08/29 4pp
- 8009110316 Forwards supplemental info to "Effluent & Haste Disposal Semiannual Rept, Jan-June 1980." for TMI-1 & 2 & EPICOR-II & supplemental info to "Effluent & Waste Semiannual Rept, 791015-1231." for EPICOR-II HERBEIN.J G Metrapolitan Edison Co 80/09/05 1p
- --8007110333 Supplemental info to "Effluent & Waste Disposal Semiannual Rept. Jan-June 1980" " Ketropolitan Edison Co 80/09/05 24pp
- --8009110340 Supplemental info to "Effluent & Waste Disposal Semiannual Rept. Jan-June 1780." for EPICOR-11 * Metropolitan Edison Co 80/09/05 8pp
- ~-8009110344 Supplemental info to "Effluent & Waste Disposal Semiannual Rept.for 791015-1231" re EPICOR-II 4 Metropolitan Edison Co 80/09/05 Spp
- 8007180204 TMI Program Ofc weekly status rept for wk of 800830-0706 CQLLINS, J T TMI Program Office 80/07/08 App
- 8009190490 Forwards info re 1979 annual rept of aquatic ecological studies of TMI in response to NRC 800805 request HOVEY,O K Metropolitan Edison Co GO/09/12 9pp
- 8009270481 Forwards weekly status rept for wk of 800907-13 COLLINS, J T TMI Program Office 80/09/15 4pp
- 8009300550 Forwards tritium results from TMI groundwater & soil samples obtained on 800530,0707,18 & 25 Results of analyses performed on soil samples from OM-130,0W-14 & OM-17 Loc budged RIETHIE. II E General Public Utilities - GPU Service Corp 80/09/16
- 8009300399 Forwards "Executive Summary, THI Units 1 & 2 Liquid & Gaseous Releases for Jul 1980, addl data for biquid discharges Busquehanna River for 1980 / explanation of Mil effluent assessment group monthly summary ER,S W Porter-Gertz Consultants, Inc 80/09/19 2pp PORTER, S W
- --8009300401 "Executive Summary, TMT Units 1 & 2 Liquid & Gaseous Releases for Jul 1980 " Tables providing add1 data for liquid discharge to Susquehanna River encl 4 Porter-Gertz Consultants. Inc 80/09/19 13pp
- S Reportable occurrences. LERs & related correspondence
- 8009020378 Ferwards LER 80-030/01L-0 Metropolitan Edison Co 80/08/20 16
- --8009920387 LER 80-030/01L-Q on 800717, following first reactor bldg normal since Mar 1979 accident foor seal leakage detected in excess of Tech Spec limit Apparently caused by some foreign matl renaining on seal after cleaning CHAPLINS D Ketropolitan Edison Co 80/08/18 2pp
- 8009030349 Forwards LER 80-034/03L-0 HOVEY, Q K Hetropolitan Edison Co 80/08/25 1p
- ---8009030361 LER 80-034/03L-0 on 800725, during recovery mode, use of hot water hydrolasing set off fire alarm in fuel handling bldg Ventilation automatically shut down & was not returned to sve for 5-h Caused by operator response to fire alarm CHAPLIN.S D Metropolitan Edison Co 80/08/25 3pp

- 8009050243 Informs that LERs 79-013,79-019,80-017 & 80-021 have been cancelled PERKINS,M A Office of Inspection > Enforcement, Office of the 80/09/02 Director
- --8007050245 LER 80-017 has been cancelled * Metropolitan Edison Co 80/09/02
- --8009050246 LER 79-013 has been cancelled * Motogoolitan Edison Co = 80/09/02
- --8009050247 LER 79-019 has been cancelled * Metropolytan Edison Co 80/09/02
- --8009050249 LER 80-021 has been cancelled * Metropolitan Edison Co 80/09/02
- 8009180415 Forwards LER 80-036/011-0 HOVEY, O K Metropolitan Edison Co 80/09/05 1p
- --8009180426 LER 80-036/01L-0 on 800808, failed to perform RCS coclant dissolved baron & hydrogen analyses Cause by contamination of B&W R&D facility Util in process of establishing onsite capabilities for performing RCS coolant analyses CHAPLIII, S D Hetropolitan Edison Co 80/09/05 3pp
- 8009120002 Forwards LER 80-035/03L-0 HOVEY, G K Metropolitan Edison Co 80/09/08 1p
- ---B009120406 LER 80-035/03L-0 on B00731 during recovery mode operation. trouble alarm received in control room Caused by Pailed flame detectors within balance of plant diesel generator Detector replaced Diesel generators removed from specs. CHAPLIM B D Metropolitan Edison CO 80/09/05 3pp
- 8009120450 Forwards LER 80-033/01L-0 HOVEY. G K. Metropolitan Edison Co. 80/09/08 ip
- --8007120452 LER 80-033/01L-0 on 800730.Gould-ITE reported possible failure of relay pneumatic timing device.Model J2013 Caused by age & doterioration.coupled w/kwo failures of timers & ezressive need for recalibr Failed timers replaced CMAPLIN.8 D Metropolitan Edison Co 80/09/08 Spp
- 8009180404 Forwards LER 80~037/01L-0 HGVEY, G K. Netropolitan Edison Co. 80/09/09 ip
- --8009180408 LER 80-037/01L-0 on 800808, leak rate testing of reactor bldg personnel air lock door 2 showed excessive leakage Caused by failure to equalize pressure inside & outside airlock resulting in door suddenly opening & striking wall CHAPLIN.8 D Metropolitan Edison Co 80/09/08 3pp
- T Hearing transcripts on non-antitrust matters
- 8009260313 Submittal of prepared testimony for first hearing session No attempts made to provide complete answers to ASLB 800908 momorandum & older re physical separation of TMI units Certificate of Svc entl Related correspondence TROWDRIDGE.9 F Metropolitan Edison Co 80/09/13 7pp
- ---B009260366 "Small Break Operating Guidelines " Related correspondence # Babcock & Wilcox Co 69-1106001-00 79/11/30 48pp
- U Congressional/Executive Coirespondence
- 8007020476 Provides Subcommittee on Nuclear Regulation w/NRC rept.
 "NRC Plan for Cleanup Operations at TMI-2 "Portions of plan
 subj to change as cleanup work & related investigations
 continue W/o encl
 DIRCKS.W J Office of the Executive Director for Operations
 80/03/15 1p
- 8009020492 Provides Subcommittee on Energy & Powor w/NRC rept. "NRC Plan for Cleanup Operations at TMI-2 " Portions of plan subj to change as cleanup work & related investigations continue W/o enci DIRCHS W J Office of the Executive Director for Operations 80/08/15 1p
- 8009020489 Provides Subcommittee on Environ.Energy & Natural Resources w/RRC rept, "NRC Plan for Cleanup Operations at TMI-2" Partions of rept subj to change as cleanup work & related investigations continue W/o encl DIRCKS, W J Office of the Executive Director for Operations 80/08/15 ip

- 6009020496 Provides Subcommittee on Energy & Environ w/NRC rept. "NRC Plan for Cleanup Operations at TMI-2" Portions of plan subject to change as cleanup work & related investigations continue W/o enci DIRCKS, N J Office of the Executive Director for Operations 80/08/15 1p
- BOO9110486 Responds to 800703 ltr requesting comments on P Hontague statement to Editor of NY Times on cessum content of spent resins from EPICOR-II processing sys Wastes are considered suitable for burial at commercial low level disposal site DIRCKS.M J Office of the Executive Director for Operations 80/09/23 2pp
- --B009i10491 Requests comments on encl statement by P Montague of Nati Campaign for Radwaste Bafety, to Editor of NY Times on cesium content of spent resins from EPICOR-II processing sys GTTINOER,R L House of Rep 80/07/03 2pp
- BOO7070570 Opposes any decision to dispose of facility radwaste at any DDE facility & specifically at Savannah River facility Waste should be disposed w/other commercial waste rather than w/defense waste DERRICK-B House of Rep 80/08/28 ip

- 8009030464 Forwards Administrative Procedure 1006.operator requalification program & status of requalification program for Unit II operators Replacement operator training program will be submitted upon completion HERBEIN.
- --8007030467 "Administrative Procedure 1006, Revision 3," operator requalification program Status of requalification program for Unit 11 operators enci

 * Hetropolitan Edison Co 80/07/31 42pp
- 5009080240 Forwards operator requalification program per 800328 ltr HERBEIN.J G Metropolitan Edison Co 80/08/08 2pp
- COCKET 59-321 EDHIN 1 HATCH NUCLEAR PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8009236245 Requests that ail personnal be reminded of purpose of emergency notification sys & health physics network Bys installed for govt use during emergency O'REHLLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22 lp
- 8009030484 Notifies that final version of upgraded emergency pian will be submitted by 810102 HIDNER, H A Georgia Power Co 80/08/28 ip
- 8009140448 Informs of util concept of physical means for algoriting & providing clear instructions to populace within plume exposure energency planning zone Dasign concept is to provide tone alert receivers for all establishments in zone HIDNER, N A Georgia Power Co 80/09/12 3pp
- @ Adjudicatory correspondence
- 8009240597 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 REID:R W Operating Reactors Branch 4 80/08/29 2pp
- P. Operating license stage documents & correspondence
- 6009110354 Supple NRC 800707 request for proposed Tech Specs changes restread discharge vol yent & drain valves. & reactor prefection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISEMBUTD 0 Division of Licensing 60/07/22 22pp
- BOG9020297 Bubmits interim criteria for shift staffing to all DL & CP licansess & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EIGERBUT.D & Division of Licensing 80/07/31 7pp

- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Focilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl 4/o KUREG EISENHUT, D G Division of Licensing 80/08/01 119pp
- BOO7230052 Informs that exemption From fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D.G. Division of Licensing 80/08/07 60pp
- 8009230763 Forwards "Mark 1 Containment Long-Torm Program SER, Resolution of Generic Technical Activity A-7," NUREO-0661 W/u encl REID.R N Operating Reactors Branch 4 80/08/20 2pp
- 8007180549 Advises that reply has not been received for 770405 request for addl info re 750303 application for Tech Spec change Application considered withdrawn NOVAK.T H Assistant Director for Operating Reactors 80/08/25
- 8009250421 Informs of acceptability of response to NRC 791109 ltr re portions of ECCS evaluation models dealing w/fual cladding swelling & incidence of rupture REID.R W Operating Reactors Branch 4 80/09/09 2pp
- 8009190423 Application for amend to Licenses DPR-57 & NPF-5 consisting of changes to Tech Specs WIDNER,W A Georgia Power Co 80/09/15 App
- --8007170428 Proposed changes to Tech Specs Tables 3 2-11,4 2-11 & 6 2 2-1 & Tech Specs & 3 for unit staff qualifications.6 4 for training & 6 5 for review & audit 9 Georgia Power Co 80/07/13 ápp
- --8009190432 Proposed changes to Tech Specs Tables 3 3 6 4-1.4 3 6 4-1 & 6 2 2-1 & Tech Specs 6 3 for unit staff qualifications.6 4 for training & 6 5 for review & audit 4 Georgia Power Co 80/09/15 5pp
- Q inspection reports, IE Bulletins & correspondence
- 8009090097 Forwards IE Bulletin 80-07. Suppl 1, "BUR Jet Pump Assembly Failure" No response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/13
- 8009150332 Forwards IE insp Repts 30-321/80-26 & 30-366/80-26 on 800625-26 No noncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/23 2pp
- --B009150370 IE Insp Repts 50-321/B0-26 & 50-366/B0-26 on 800625-26

 No noncompliance noted Major areas inspected settling of structural backfill around RHR & plant svc water intake structure & piping

 HARRIS, JR Region 2. Atlanta, Office of the Director CONLON.TE Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/22 3pp
- 8009220265 Forwards IE insp Repts 50-321/80-24 & 50-366/80-24 on 800513-0609 & notice of violation LENIG-R C Region 2. Attanta, Reactor Operations Nuclear Support Branch 80/07/25 2pp
- --8007220337 Notice of violation from Insp on 800513-0607 LEWIB.R C Region 2, Atlanta. Reactor Operations Nuclear Support Branck 80/07/25 1p
- --8009220341 IE Insp Repts 50-321/80-24 & 50-366/80-24 on 800513-0609 Noncompliance noted motor bearing cooling water inlet valves were found amproperly shut on RHR svc water pumps DANCE.H C Region 2. Atlanta, Reactor Operations Nuclear Support Branch ROGERS.R F Region 2. Atlanta, Office of the Director 80/07/25 78p
- 8009050076 Forwards partial response to IE Rulletin 80-08. "Exam of Containment Liner Penetration Welds " Seven welds failed nondestructive examination Unit 1 containment & Unit 2 torus penetration info forthcoming WIDNER.W A Georgia Power Co 80/08/05 8pp
- 8007020287 Submits response to IE Bulletin 80-17, Suppl 1 Procedures have been established to assure operability of scram discharge vol WIDNER, M A Georgia Power Co 80/08/07 2pp

- 8009030154 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Unitten O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/15
- 8009020180 Responds to Suppl i of IE Bulletin 80-17 re failure of control rods to insert during scram at BUR Existing design of facility meets requirement for continuous monitoring of water level in scram discharge vols WIDNER, U.A. Georgia Power Co. 80/08/19 2pp
- 8009020393 Submits status of recent util efforts towards compliance w/ IE Bulletin 79-01B. "Environ Qualification of Class IE Equipment" Util has joined BWR owners group effort on hollstin WIDNER, W.A. Georgia Power Co. 80/98/19 200
- 8009160037 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE DWR Facilities " No specific action or response requested O'REILLY, J P. Region 2, Atlanta, Office of the Director 80/08/19
- 8009230105 Submits response to IE Bulletin 79-018 Expects to complete qualification test program & component replacement by 820439 WIENER, W A Georgia Power Co 80/09/19 2pp
- 8009110671 Responds to IE Bulletin 79-01B Forwards 90-day repts re environ qualification of Class IE equipment summary of outstanding items 8 summary of equipment w/less than 40-yr aging qualification W/o encls HIBNER.U A Georgia Power Co 60/08/22 2pp
- 8009120077 Forwards Suppl 3 to IE Bulletin 80-17. "Failure of Control Rods to Insert During Scram at BWR " Written response required.
 O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/22 1 p
- 8009160147 Forwards IE Circular 80-18, "10CFR30 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required
 O'REILLY.J P Region 2: Atlanta, Office of the Director 80/08/22
- 8009110824 Ack receipt of 800731 ltr informing NRC of steps taken to correct deviations noted in IE Insp Repts 50-321/80-02 & 50-366/80-02 MURPHYC E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/08/25 ip
- --B009110828 Responds to NRC 800208 ltr re violations noted in IE Insp Repts 50-321/80-02 & 50-364/80-02 Corrective actions relocation of fire pump controller & installation of tamper alarms for fire valves to be completed Aug 1980 HIDMER.W A Georgia Power Co 80/07/31 tp
- 9009120311 Forwards IE Info Notice 80-31. "Maloperation of Oould-Brown Bover! 480 Volt Type K-6003 & K-DON 6008 Circult Breakers "No written response required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/08/27.
- 8009110576 Responds to IE Bulletin 80-15 Emergency notification sys powered by telephone company To ensure sys extensions operate independently of plant phones: testing was conducted on 800815 All extensions operable during power trip MIDNER.W A Georgia Power Co 80/08/29 ip
- 8009150162 Responds to IE Bulketin 80-19, Revision & Mercury-wetted matrix relays are not used in reactor protection sys WIDNER, W A Georgia Power Co 80/08/29 ip
- 8009230204 Forwards IE Insp Repts 50-321/80-34 t 50-366/80-34 on 800313-14 No noncompliance noted KENNA.W B Region 2. Atlanta, Safeguards Branch 80/08/29 1p
- --8009230210 IE Insp Repts 50-321/80-34 \$ 50-366/80-34 on 800813-14 No noncompliance noted Major areas inspected licensee implementation of contingency strike plan Details withheld 10CFR2 770) MCOUTRE, D R REGUIRE D R Region 2- Atlanta, Safeguards Branch, TOBIN.W J Region 2- Atlanta, Office of the Director, 80/08/29 1p

- 8009230525 Forwards Revision 1 to IE Bulletin 79-26, "Boron Loss From BWR Control Blades" Written response required O'REJLLY, J.P. Region 2. Atlanta, Office of the Director 80/08/29
- BO09240367 Responds to IE Bulletin BO-17, Suppl 3 Gutlines procedures in effect re loss of instrument air, loss of control rod driveline, rod drift 2 undrained scram discharge vol Function test of switches required prior to startup WIDNER, W A Georgia Power Co 80/08/29 2pp
- 8009290282 Forwards IE Circular 80-21, "Regulation of Refueling Creus" No written response required D'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/09/10
- 8009300104 Submits response to IE Bulletin 80-20 No Westinghouse Type W-2 control switches used in safety-related applications WIDNER,W A Georgia Power Co 80/09/12 1p
- R Periodic operating reports & related correspondence
- 8009030415 Forwards "Bemiannual Radioactive Effluent Release Rept." Jan-June 1980 HANRY,M Georgia Power Co 80/08/30 1p
- -- 8007030419 "Samiannual Radioactive Effluent Release Rept." Jan-June * Georgia Power Co 80/08/30 44pp
- 8009180199 Forwards monthly operating rept for Aug 1980 MANRY.M Georgia Power Co 80/09/10 ip
- --8009180208 Monthly operating rept for Aug 1980 UNDERWOOD, P. R. Georgia Power Co. 80/09/10 7pp
- S Reportable occurrences, LERs & related correspondence
- 8009020436 Forwards LER 80-084/03L-0 MAKRY, M Georgia Power Co 80/08/26 ip
- --8009020444 LER BO-084/03L-O on BOOB07, while performing HNP-1-3167, RMR svc water flow indication for RHR svc water loop B observed sulnging excessively Caused by faulty amplifier Amplifier replaced & transmitter recallibr
 NIX,R T Georgia Power Co 80/08/26 2pp
- 8007020437 Forwards LER 80-075/03L-0 MAPRY, M Georgia Power Co 80/08, 80/08/26 1p
- --8009020444 LER 80-095/03L-0 on 800808, w/reactor at steady state of power-during RHR valve operability surveillance on RHR A loop w/B loop out of svc. inboard injection valve IEII-F013A failed to open Caused by burned motor windings & rator. RIX.R T Georgia Power Co 80/03/26 2pp
- 8009020461 Forwards LER 80-099/03L-0 MANRY, M Georgia Power Co 80/08 80/08/28 1p
- --8009020469 LER 80-099/03L-0 on 800817, while performing normal operation of unit radwaste. door to empty drum conveyor room discovered unlacked Caused by evening shift personnel not locking door when exiting Lock changed to self locking type.

 BAXLEY, S X Georgia Power Co 80/08/28 2pp
- 8009020404 Forwards LER 80-092/03L-0. MANRY, M Georgia Power Co 60/08/ 80/08/29 lp
- ---B009020414 LER B0-092/03L-O on B00731.while at steady state power, cooling water to LPCI inverter room cooler was isolated resulting in high ambient temp in inverter room Caused by high ambient temp causing B loop of RHR to be inoperable C000IN.C L Georgia Power Co B0/08/29, 2pp
- 8009090469 Forwards LER 80-098/03L-0 MANRY, M Georgia Power Co 80/09/02 1p
- --8009090480 LER BD-098/03L-0: on 800816, during HNP-1-3957, torus to drywell vacuum breaker operability test closed indication lights on valve ITAB-F323H failed to extinguish w/valve in full open position Causa not known liIX.R T Georgia Power Co 80/07/02 2pp
- BOD7070443 Forwards LER 80-097/03L-0 MANRY, M Georgia Power Co 80/07 80/09/04 tp

--B009090460 LER 80-097/03L-0 on B00Bj5, during reactor operations at 2370 MAt.bldg vent radiation monitor sample pump failed Caused by moisture swelling pump carbon vanes Pumps rotated daily to revent recurrence

Georgia Power Co 80/09/04 2pp

6009150295 Forwards LER 80-100/01T-0 MANRY, M Georgia Power Co 80/09/05 1p

--B009150298 LER 80-100/01T-0 on 800822.vt(i notified by Bechtel that seismic piping support was not installed Apparently caused by goor communication w/designer re addition of support to original analysis Support Installed COGOIN.C L. Georgia Power Co 80/09/05 2pp Georgia Power Co 80/09/05 2pp

8009150281 Forwards LER 80-101/03L-0 MANRY, M Georgia Power Co 80/09/09 ip

B009150291 Forwards LER 80-102/03L-0 MANRY.M Georgia Power Co 80/09/09 ip

--god9150294 LER 80--102/03L-0 on B00821.while at steady state power.B LPCI inverter tripped making B loop of RKR inoperable Caused by high ambient temp Temporary cooling is being used until installation of permanent chillers is complete CO301M.C L Georgia Power Co 80/09/09 2pp

B009150392 Forwards LER 80-103/03L-0 MANRY, M Georgia Power Co B0/09/09 1p

--8009150385 LER 80-i03/03L-0 on 800822 during operation at 97% power, plant svc water flow was restricted Caused by tripped drive mechanism & coupling failure of strainers 1941-Di03A & 1941-Di03B Breaker reset & coupling repaired #MIX.R T Georgia Power Co 80/09/09 2pp

8009150384 Forwards LER 80-104/03L-0
HANRY,M Opengia Power Ca 80/09/09 1p

--8009150385 LER 80-i04/03L-0 on 800826 during annual surveillance & operability testing, five snubbers did not meet acceptance criteria Caused by seal leakage as snubbers were low on fluid Two snubbers were reconditioned & others replaced NIX.R T Georgia Power Co 80/09/09 2pp

8009300497 Forwards LER 80-096/03L-0 MANRY, M Ocorgia Power Co 80/09/23 1p

--8009300502 LER 80-096/03L-0 on 800902.all points of IT47-R612 Drywell & Torus temp recorder read i7 degrees F higher than redundant recorder 1747-R611 Caused by calibr drift Instrument recalibr & returned to syc Instrument recalibr & returned to svc NIX.R T Georgia Power Co 80/07/23 2pp

V Operator Examinations

800905029(Forwards excerpt from new training outline re criteria for operator training & licensing Current policy requires instructors attend annual simulator training & retraining lectures as part of approved requalification program MANRY.H Georgia Power Co 80/08/12 7pp

DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION

A Application/construction stage documents & correspondence

8007080080 Forwards draft NUREG-0676, "Functional Criteria for EISEMBUT D Division of Licensing 80/08/01 119pp

8007090631 Notification of cancellation of 800827 meeting w/DWR licensing review group to discuss concensus positions on TMI lasues (NNREO-0644) Assistant Director for Licensing 80/08/04 10pp

8009090631 Natification of cancellation of 800827 meeting w/BWR licensing review group to discuss concensus positions on TMI issues (NUREG-0694) WILSON, J N Assistant Director for Licensing 80/08/04 10pp 8009020425 Responds to NRC 800711 request for util confirmation of const completion date 2 fuel load schedule Fuel load forecast is 820601-0901 Station will be physically ready to load fuel before conclusion of CL proceeding NOVAPRO, J P Long Island Lighting Co BO/08/21 3pp

BOO7030437 Forwards commitments to meet requirements outlined in NUREO-0578 "TMI-2 Lessons Learned Task Force Status Rept & Short-Term Recommendations," per NRC 770927 & 1109 ltrs Requests concurrence & comments on submittai Long Island Lighting Co 80/08/29 80pp

8009110742 Notification of 800904-05 meeting w/Mark II owners group to discuss plants chugging C/O & lateral load specs ANDERSON, C Containment Systems Branch 80/08/29 14pp

8009120395 Forwards missing page to be inserted in section entitled "Containment Hydrogen Concentration," contained in "Shoreham huciear Power Station Responses to NUREG-0578, Short-Term Leasons Learned Requirements "
CUAQUIL, L. Long Island Lighting Co. 80/09/05 2pp

8009260091 Notifies of 801007 proposed date to review whether OBE & SRV responses should be considered separately or combined during ASME code fatigue calculations GE selected samples to emphasize highly fatigued components
WILSON.J N Assistant Director for Licensing 80/09/15 7pp

8009230590 Comments on NUREG-0696 in relation to "Design Criteria & Description, Technical Support Ctr for Ehoreham Nuclear Power Station." SNRC-486 Emphasizes importance of receiving evaluation of design criteria as early as Sept 1780 NOVARRO. J P Commonwealth Edison Co 80/09/16 3pp

F Security, medical, emergency & fire protection plans

8008280053 Natification of 800819.20 & 22 workshops in Valley Forge,PA, Chicago, IL & Atlanta, GA, respectively, to solicit public comment re NURED-0.6954, "Functional Criteria for Emergency Response Facilities"

GRIER, B H Region 1, Philadelphia, Office of the Director 80/08/11 2pp

G Adjudicatory correspondence

8009120550 Forwards NRC insp repts of fabrication of facility reactor pressure vessel per request during 800519 health committee public hearing W/o anci ORIER, B H Region i, Philadelphia, Office of the Director 80/08/04 2pp

80090204ik Responds to 800822 ltr Documents will be sent to Shoreham Opponents Coalition & MHB Technical Associates if spare copies are available Other intervenors or consultants must be contacted if spare copies are not located BORDENICK, B M Hearing Branch 4 80/08/28 ip

8009040248 Forwards recently promulgated amends to emergency planning regulations W/o encis BORDENICK: B M Hearing Branch 4 BO/09/02

BOD9170231 Forwards contractor repts NUREO/CR-0742 NUREO/CR-0744, in response to BOOB21 request delivered at BOOB29 meeting W/o enc! BORDEHICK, B M Hearing Branch 4 80/09/08 2pp

8009300001 Forwards DD Vassallo 790927 & 1009 itrs re TM1-2 followup actions & discussions of Lessons Learned Short-Term Requirements Remaining documents will be provided whon available BORDENICK, B M Hearing Branch 4 80/09/26 2pp

M Antitrust correspondence

80091904i5 Re-requests update of Jan 1976 submission of antitrust info in accordance w/AEC Reg Guide 9 3 SALTZMAN. J Utility Finance Branch 80/09/16 ip

O Inspection reports, 1E Builetins & correspondence

8007090085 Forwards iE Bulletin 80-07, Suppl i. "BWR Jet Pump Assembly Failure " No response required ORIER.B H Region i. Philadelphia. Office of the Director 80/05/13 ip

- 8009150159 Forwards IE Insp Rept 50-322/80-13 on 800601-0706 No noncompliance noted BRU'4'ER.E J. Region I. Philadelphia. Peactor Operations Nuclear Support Branch 80/07/24 2pp
- --8007150161 IE Insp Rept 50-322/80-11 on 800601-0706 No noncompliance noted Major areas inspected tours of facilities, test witnessing, review of fire protection measures & QA review HIGGINS.J C . LINVILLE.J C Region 1. Philadelphia. Office of the Director KISTER.H B Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 80/07/21 7pp
- BOO9120234 Responds to IE Bulletin 79-03A re longitudinal weld defects in BA-312. Type 304 stainless steel pipe BA-312 piping used at facility satisties criteria Sys pressure-temp values louer than reduced allowable code NGVARRG. J P Long Island Lighting Co BO/08/04 2pp
- 8009030087 Forwards Revision 1 to IE Bulletin 80-17, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER.8 H Region I. Philadelphia. Office of the Director 80/08/15 1p
- 8009030433 Forwards empty binder for increased vol of preservice insp plan inserts to cover will be sent at later date Suggests Section O be placed in second binder due to size Requests that NRC ack receipt of binder NDVARRG, J P Long Island Lighting Co 80/08/15 tp
- 8009120088 Forwards Suppl 3 to IE Bujletin 80-17, "Fallure of Control Rods to Insert During Scram at DNR " No written response required ORIER.B M Region I, Philadelphia, Office of the Director 80/08/22 1p
- 8009180009 Forwards IE Circular 80-18, "10CFR30 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GRIER.O H Region 1. Philadelphia. Office of the Director 80/08/22 19
- 8009120180 Forwards IE Info Notice 80-31, "Maloperation of Quild-Brown Boveri 480 Voit Type K-6009 & K-EON 6008 Circuit Breakers " No written response required ORIER B H Region I, Philadelphia, Office of the Director 80/08/27 ip
- 8009230786 Forwards 1E Circular 80-21, 'Regulation of Refueling Crews " No written response required GRIER, BH Region I. Philadelphia. Office of the Director 80/09/10 ip
- 009240315 Forwards IE Info Notice 80-32, "Ciarification of Certain Requirements for Exclusive-Use Shipments of Radioactive fatls " No written response required falls." If Region 1. Philadeiphia, Office of the Director 10/09/12 19
-)9250003 Forwards relevant portions of IE insp Repts 50-322/78-01. 10-322/78-17 & 50-322/79-12 in response to 800731 itr IQRDENICK.B M Hearing Branch 4 80/09/23 5pp
- Reportable occurrences, LERs & related correspondence
- 009120120 Ack receipt of 800724 interim deficiency rept re power supply failure CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/01 1p
- --8009120123 Interim deficiency rept re 24-voit dc power supplies w/ Bailey Controls Co electronic analog instrumentation Followup rept will be submitted within 90 days MVARRO.J P Long Island Lighting Co 80/07/24 2pp
 - KET 50-323 DIABLO CANYON NUCLEAR POHER PLANT, UNIT 2
 Application/construction stage documents & correspondence
 - GOSOOSO Forwards draft NUREG-0676, "Functional Criteria for ergency Response Facilities" Comments requested within 30 is Proposed implementation schedule for meeting criteria NUREG-0676 ent 1470 NUREG 688UT. D G Division of Licensing 80/08/01 119pp

- 8009020263 Forwards response to questions re Category i concreta masonry walls, sample calculation 5 pertinent location drawings, in response to NRC 800421 ltr CRANE.P A Pacific Gas 8 Electric Co 80/08/27 32pp
- --B009020265 "Plan Area A Elevation 107 Ft "
 * Pacific Oas & Electric Co 79/12/11 ip
- --8009020268 "Plan Area H Elevation 100 Ft " * Pacific Oas & Electric Co 78/02/24 ip
- --8009020269 "Plan Area A Elevation 119 Ft " * Pacific Gas & Electric Co 80/07/15 1
- --8009020270 "Plan Area H Elevation 115 Ft "
 * Pacific Gas & Electric Co 79/09/22 1
- --8007020272 "Pian Area H Elevation 128 Ft "
 Pacific Oas & Electric Co 78/10/30 1
- ---8007020274 "Plan Area K Elevation 185 Ft "
 # Pacific Gas & Electric Co 79/11/01 fp
- --- 8009020275 "Finish Schedule & Interior Details"

 Pacific Gas & Electric Co 79/12/12 ip
- --8009020277 "Miscelianeous Concrete Block Details "
 # Pacific Gas & Electric Co 78/09/27 ip
- B009110707 Forwards request for additinfo to continue review & evaluation for full power OL Info should be provided to low power turbine discs & rotore & evaluation of turbine missiles
 SCHMENGER. A Licensing Branch 3 80/08/27 7pp
- B009090344 Advises that habitability aspects of facility control room comply w/requirements of Reg Guides 1 78 & 1 95 & SRP.
 Bections 2 2 1-3 & 6 4 as specified in NUREC-0660.per NRC B00507 request Conclusion confirmed in Suppl 9 to BER GRANE.P A Pacific Gas & Eiectric CO B0/09/03 1p
- 8009180486 Forwards Revision 4 to "Description of Sys Interaction Program for Seismically-Induced Events " Requests that receipt of rept be ack GRANE.P A Pacific Gas & Electric Co 80/09/16 ip
- --8009180493 "Description of Sys Interaction Program for Gaismically-Induced Events." Revision 4 * Pacific Gas & Eiectric Co 80/08/29 92pp
- 8009250289 Forwards response to NRC 800606 itr requesting addi info re shielding review.containment monitors & iodine sampling at facilities Monitors are mutually redundant using separate power supplies from separate vital instrument busses GRANE.P A Pacific Oas & Electric CO 80/09/22 App
- E NRC 84fety Evaluation Report (BER), supple & correspondence
- BO09090195 Forwards Suppl 10 to facility SER covering TMI-2-related matters N/o encl
 BCHMEMCER: A Licensing Branch 3 80/08/15 5pp
- F Security, medical, emergency & fire protection plans
- 8007030337 Notifies of 800819,22 & 30 regional workshops re development of guidance for acceptable method for coping w/emergencies at facility Requests that representative be sent 8003 areas to be discussed include function of facilities & location ENGELKEN.R N. Region 5. San Francisco, Office of the Director 80/08/12 200
- 8009230337 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network, Bys installed for govt use during emergency ERVELKERIAR H Region 5, San Francisco, Office of the Director EO/OE/22 3pp
- 8009150565 Requests addl info & commitments re NRC evaluation of amergency preparadness program for conformance w/NUREO-0654 TEDESCO.R L. Assistant Director for Licensing 80/08/28 9pp.
- BOD7090612 Requests clarification of apparent omission of itr of agreement between util & Field Ranch on Page 5-6 of Feb 1980 Emergency Plan, Revision 2, App 7 SCHWENCER, A Licensing Branch 3 80/08/30 3pp

- BO09290049 Forwards 8 Schwencer BO0910 memo to HR Denton re alleged inaccuracios in emergency plan text Requests assistance in determination of substantiation of alleged inaccuracies TEDESCO:R L Division of Licensing BO/09/11 1p
- 8009230220 Forwards lighting maps of protected area of facility in response to NRC request Maps withheld (ref 100FR2 790) ROSE,D O Los Alamos Scientific Laboratory 80/09/17 ip

O Adjudicatory correspondence

- 8009220213 Confirms 800702 teleon re arrangements for mailing & delivery of security matts per ALAB-600 order Advises that mailing arrangements re sensitive info between Intervenor San Luis Oblaya Mothers for Peace & util are necessary NDRTOM. B Bruce Norton 80/07/17 2pp
- 8009030157 Executed amended affidavit of nondisclosure protecting licensee physical security plan Certificate of Svc encl LEWIS.W L Affiliation Unknown 80/08/20 6pp
- BOO9030489 Response in opposition to Governor of CA motion for revision of mandisclosure affidavit to security plan Takes exception to Governor of CA BOOB14 & 19 ltrs submitted in response to ASLAB order Certificate of Svc encl MORTON B , GERRA C , FURBUSH M H Pacific Gas & Electric Co 80/08/21 7pp
- ROG9020071 Motion for JE Luco & MD Trifunac to provide testimony by 800905 instead of 800902 Sacretarial help unavailable HORDLINGER,M S Office of the General Counsel 80/08/27 ip
- 8009030112 Order scheduling Bopt-Nov 1780 security plan hearings Parties may move for supplemental evidence re issues Teopened in seismic ALAB-578.by 800919 State of CA motion to ravise nondisciosure affidavit denied BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/08/28 16pp
- 8007030597 Response to ASLB 800814 order re util motion to load fuel & for low power tests Covernor of CA & joint interveners' replies should be stricken as failures to make substantive responses Certificate of Syc enci
 CRANE, F A . OCHR. A C . NORTON, B Pacific Gas & Electric Co
 BQ/08/28 7pp
- BOOTII0019 Request for BOO725 site insp visit Security plan w/maps, diagrams & safeguards contingency plan must be available for review by HH Brown, LC Lanpher. LO Gluffrida. RE White & DR Sievers who will undertake visit BROWN, R H , GEORGIOU, B S , LANPHER, L C California, State of SO/09/08. 2pp
- BOO9150404 Response to ASLB BOOB14 order re util BOOB04 motion for low power tests Urges summary dismissal of motion Security & seismic issues not yet resolved & are needed for low power testing BROWN, H H, LANPHER, L C, California, State of BROWN, H H Hill Christopher & Phillips BO/097/11 4pp
- BOO9140234 Response to ASLB 800814 order re util motion for low power testing. Urgas dismissal of motion due to reopening of record on security plan & seismic design Late discovery of Hosgri fault warrants consideration of Class 9 accidents FLEISCHAKER, D San Luis Obispo Mothers for Peace FLEISCHAKER, D Fleischaker, D S 80/09/11 5pp
- 8009150360 Forwards JF Devine & RF Yerkes combined testimony w/latter prof qualifications.ger ASLB 800819 memorandum & order Explains svc process re repts mentioned in testimony METCHEN.E. O Hearing Branch 4 80/09/12 2pp
- --8009160363 Combined testimony in response to ASLB 800819 memorandum & order on Question 9 re geology & selsmology repts New data & conclusions re LNQ repts have no Impact on USOS position RF Yerkes prof qualifications encil DEVINE, JF, YERKES, RF Interior, Dept of, Geological Survey 80/09/12 6pp
- 8009193035 Forwards 800819 FR notice re upgraded emergency plan regulations RAVIS.L D Hearing Branch 4 80/09/15 19pp
- 8009220406 Response in opposition to util & NRC objections re State of CA 800902 statement of security plan issues upon which participation is requested. Challenged subject are responsive to ASLB 800808 fourth prehearing conference order BROWN.H.H. LANPHER, L. C., GEORGIQU, B. G. California, State of 80/09/15 4pp

- 8007220262 Forwards plaintiff, San Luis Obispo Mothers for Peace, complaint for declaratory judgement injunctive relief & mandamus, disqualifying JM Mendrie from further participation in OL proceedings FLEISCHAKER, D Fleischater, D S FLEISCHAKER, D San Luis Obispo Mothers for Peace 80/09/16 20pp
- BO07230616 Correction to State of CA BO0708 interrogatories directed to NRC re security plan proceeding Certificate of Svc encl Related correspondence BROWN, H H . LANPHER, L C . GEORGIOU, B S California, State of BO/09/16 4pp
- 8009240544 Forwards RB Hubbard affidavit re need for Class 9 accident analysis to accompany joint intervenois' reply to ASLD 800814 order Related correspondence FLEISCHAKER.D Fleischaker.D S 80/09/19 lp
- --8009240546 Affidavit to need for Class 9 accident & sys reliability analyses of facility by util Analysis needed due to effect of reactor contamination on economic cost & health risks CEO 800320 ltr encl Related correspondence HUBBARD.R B MHB Technical Associates 80/09/17 18pp
- --8009240550 Submits conclusion of study on NRC regulations & policy re environ analysis of possible nuclear accidents under NEPA Typical EIB does not consider or analyse possibility of major accident in Class 9 category GPETH, O Council on Environmental Quality 80/03/20 4pp
- 8009260467 Notice of 801020 evidentiary hearings in San Luis Obispo.CA re ASLAB 800624 decision.ALAB-598.which reopened solumic issues
 BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/09/23

H Concral correspondence

- 8009090534 Urges use of influence for speedy & successful approval of facility industrial & agricultural production could be jeopardized SLOTT, N Affiliation Unknown 80/07/23 fp
- 8009110382 Urges opening of facility as necessary enterprise in area Newspaper articles enti BRADBURY,V A Affillation Unknown 60/08/05 4pp
- 8009170200 Responds to 800326 itr to Prosident Carter re delays in licensing process Delays attributed to seismic re-evaluation of facility, lessons learned from TM1 accident & public hearings re safety & security SCINENCER.A Licensing Branch 3 80/08/22 5pp
- B009030581 Requests that facilities be certified for startup operations & plans for RYB1-B2 be devioped w/o delay.CA could face serious power shortages Electronics industry & economy could be adversely affected QARCIA.H California, State of 80/08/25 ip
- 8009050342 Urges domal of licensing Diablo Nuclear power plant & any other plants
 SCHUMACHER, J. Affiliation Unknown 80/08/27 ip
- 8009100457 Ack receipt of 800705 itr & forwards Friends of the Earth Class 9 petition & Diractor's decision on petition W/o encl ECHMENCER.A Licensing Branch 2 80/08/27 2pp
- --8009100463 Requests Director's decision on Friends of the Earth petition to consider Class 9 accidents in supplemental EIS FRIESEMA.H P Northwestern Unly 80/07/05 1p
- 8009220042 Responds to 800319 ltr opposing licensing of facilities NRC has reacted positively in light of TMI accident to improve safety at all nuclear plants in operation & under const SCHMENCER.A Licensing Branch 3 80/09/03 lp
- 8009180248 Responds to 600422 ltr to President Cater re potential radiological risks at facility NRC has re-examined plant for conformance to fuel loading & low power testing requirements
 SCHWENCER.A Licensing Branch 3 80/09/09 3pp
- 8009290094 Forwards 800830 ltr to util requested by C Neiburger of Telegram Tribune on 800909 re alleged inaccuracies in emergency plan test Matter must be resolved prior to issuance of full power OL EIEENHUT, D. O Division of Licensing 80/09/10 ipp

- 8009300295 Responds to 790920 ltr to President Carter re concern over offect of low level radiation storage & transportation of high level radwaste & ability of plant to withstand seismic acitivity Fact sheets addressing concerns encl HIRAOLIA, F Licensing Branch 3 80/09/19 6pp
- --8009300306 Forwards misdirected T Gome: 790920 lti to President Carter re effects of low lovel radiation Requests response RATHKOPF,C L Energy: Dept of 80/01/22 3pp
- K Utility Final Safety Analysis Report (FSAR) % amende
- 8009090514 Forwards Amend 85 to QL application, including matl for Chapters 4,13,14 & 17 of FSAR GRANE.P A Pacific Gas & Electric Co 80/09/03 2pp
- ~-8007090520 Amend 85 to OL application, including matl for FSAR Chapters 4,13,14 & 17 SCHUYLER.J & Pacific Cas & Electric Co 80/08/28 7pp
- 9 Inspection reports, IE Builetins & correspondence
- 8009260299 Forwards IE Info Natice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange " No written response required ENDELKEN,R H Region 9, San Francisco, Diffice of the Director 80/08/07 lp
- 8007030278 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Piants Designed by C-E " Written response required ENGELKECK, R K Region 5. San Francisco, Office of the Director 80/08/15 1p
- 8007270305 Forwards 1E Info Notice 80-27, "Degradation of Reactor Coolant Pump Stude " No written response required ENGELKELY, R H Region 5, San Francisco, Office of the Director 80/08/18 4pp
- 8009160181 Forwards (E Circular 80-18, "10CFR50 59 Gafety Evaluations for Changes to Radwaste Treatment Sys " No written response required ENGCLKEN.R H Region 5. San Francisco. Office of the Director 80/08/22 ip
- 8009120458 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Bovert 480 Volt Type K-6008 & K-80N 6008 Circuit Breakers "
 No written response required ENGELKELIAR H Region 5. San Francisco. Office of the Director 80/08/27 lp
- T Hearing transcripts on non-antitrust matters
- 8009070779 Testimony in response to ASLAB 800807 order.ALAB-604 LUCG.E . NORDLINGER.M S Luco.J E 80/09/04 7ipp
- 8009090652 Testimony in response to ASLAB 800807 order.ALAB-604 TRIFURAC, M Bouthern California, Univ of NORDLINGER, M 8 Office of the General Counsel 80/09/05 182pp
- 8009140360 Forwards JF Davine & RF Yerkes combined testimony w/iatter prof qualifications.par ASLB 800Bl9 memorandum & order Explains ave process re repts mentioned in testimony, KETCHEN,E Q Hearing Branch 4 80/09/12 2pp
- ~-8009160363 Combined testimony in response to ABL9 800819 memorandum & order.on Question 9 re gooloty & seismology repts New data & conclusions re LNG repts have no impact on USOS position RF Yerkes prof qualifications encl
 DEVINE,J F Interior.Dept of, Geological Survey 80/09/12 App
- U Congressional/Executive Correspondence
- 8009110514 Responds to 800530 ltr re facility licensing status Major const completion delays result of seismic re-evaluation & of TMI-2 Lessons Learned Task Force recommendations Facility will not be authorized to load fuel until approx 1981 DIRCKS.U J Office of the Executive Director for Operations 80/09/21 2pp

- --8009110520 Urges prompt campletian of necessary requirements for granting facility license Delays result in increase in constituent util bills Requests licensing status SHUKWAY,N D House of Rep 80/05/30 ip
- 8009220255 Provides status of NRC efforts re final licensing of facility Further actions will be required by ASLAB, ABLB & Commission DIRCKS, M J Office of the Executive Director for Operations 80/09/17 2pp
- DOCKET 50-324 BRUNSHICK STEAM ELECTRIC PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8009230252 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/22
- 8009090402 Submits revised schedule for submittal of revised emergancy plan as specified by 800819 final rule revising lOCFR50 & 70
 UTLEY.E E Cardina Power & Light Co 80/09/02 ig
- G Adjudicatory correspondence
- 8009220120 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 IPPOLITO, T A Operating Reactors Branch 2 80/08/29 2pp
- --8009220122 Order for mod of Licenses DPR-62 & DPR-71 to add info which fully responds to NRC request for info re onviron qualification of safety-related electrical equipment, info should be submitted by 801101

 EISENHUT, D O Division of Licensing 80/08/29 6pp
- H Coneral correspondence
- BOO9120437 Advises of BWR owners group organizational changes & that future correspondence be forwarded to DB Waters Future requests for util action should be addressed to individual licensees & applicants
 WATERS,D B Carolina Power & Light Co BO/09/09 2pp
- P Operating license stage documents & correspondence
- 8009110554 Suppls NRC 800707 request for proposed Tech Specs changes re scram discharge vol vent & drain valves. & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISEIMUT.D O Division of Licensing 80/07/22 22pp
- 8009020277 Submits interim criteria for shift staffing to all OL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for energency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D O Division of Licensing 80/07/31 7pp
- 8009080080 forwards draft NUREC-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREC-0696 encl M/o NUREC EISENHUT, D O Division of Licensing 80/08/01 119pp
- 8007230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENMUT, D O Division of Licensing 80/08/07 60pp
- 8007040307 Advises that two specific Event 5 valve configurations do not exist at facility per review of response to 800223 ltr "Primary Coolant Bys Pressure Isolation Valves," technical evaluation rept encl
 IPPOLITO, T A Operating Reactors Branch 2 80/08/08 3pp
- --8009040315 "Primary Coolant Sys Pressure Isolation Valves," technical evaluation rept
 NOELL,P N. STILWELL,T C Franklin Institute/Franklin Research
 Center NRC-03-79-118 80/07/21 5pp

DOCKETED ITEMS

- 8009190678 Forwards NUREG-0661, "Mark I Containment Long-Term Program SER Resolution of Ceneric Technical Activity A-7" Rept discusses generic suppression pool hydrodynamic load derinition W/o encl IPPOLITO, T A Operating Reactors Branch 2 80/08/20 2pp
- 8009230772 Notification of 800905 meeting w/util in Bethesda. ND to discuss procedure for amending CLs to add addl owners MILEGALJR Licensing Branch 1 80/08/29 4pp
- 8009090448 Forwards updated outage schedule re Mary I containment program mode Containment mode to conclude in May 1982 Plant unique analysis scheduled to be completed in June 1981 UTLEY.E E Carolina Power & Light Co 80/09/02 2pp
- BD09190047 Advises of acceptability of 791227 response to NRC 791109 ltr re ECCE evaluation models dealing w/fuel cladding swelling & incidence of rupture IPPOLITO, T A Decrating Reactors Branch 2 80/09/03 2pp
- 8009170186 Forwards "Recovery of Radioactive Hati from Brunswick County Landfill near Southport.NC." final rept FURR.B J Carolina Power & Light Co 80/09/05 Ip
- --8009170191 "Recovery of Radioactive Matl from Brunswick County Landfill Near Southport NC," final rept + Carolina Power & Light Co 80/09/05 38pp
- --8009170197 "Radiation Control & Test Procedure 3280, Radioactive Matl Recovery Procedure " * Caroline Power & Light Co 80/05/01 8pp
- 8009160376 Forwards results of review of ECCS equipment availability w/dc power supply failure
 UTLEY.E E Carolina Power & Light Co 80/09/11 4pp
- BOO9170400 Summary of BOO905 meeting w/CP&L & NC Municipal Power Agency 3 in BethesdaMD re procedure for DL & CP amends WILEON.V N Licensing Branch i BO/097/12 7pp
- 800723043B Forwards proposed revisions to Tech Specs, implementing changes requested by NRC 800702 ltr re TML Lessons Learned requirements Proposed License conditions encl
 UTLEY, E E Garolina Power & Light Co 80/09/16 4pp
- --8009230439 Proposed revisions to Tech Specs, Pages 3/4 3-51 & 52, B 3/4 3-3.6-5.6-6 re post-accident monitoring instrumentation & min shift crew composition 4 Carolina Power & Light Co 80/09/16 10pp
- Q Inspection reports, IE Bulletins & correspondence
- 8009090055 Forwards IE Bulletin 80-07.Suppl 1, "BWR Jet Pump Assembly Failure" No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/13
- 8009150329 Forwards IE Insp Repts 50-324/80-26 \$ 50-325/80-29 on 800401-39 No noncompliance noted LEMIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/07/24 2pp
- --8009150375 IE Insp Repts 50-324/80-26 & 50-325/80-29 on 800601-30
 No noncompliance noted Major areas inspected control room
 observations.Unit I refueling operations.review of plant
 logs.tour of vital areas & physical security
 OUZTG.JE Region 2. Atlanta. Office of the Director
 KELLOGO,P J. Region 2. Atlanta. Reactor Operations Nuclear Support
 Branch 80/07/23 3pp
- 8007240273 Forwards IE Insp Repts 50-324/80-23 & 50-325/80-26 on 800602-06 No noncompliance noted LONO.F J Region 2, Atlanta, Office of the Director 80/08/04.
- --8009240284 IE Insp Repts 50-324/80-23 & 50-325/80-26 on 800602-06 No noncompliance noted Major areas inspected site environ monitoring & circumstances surrounding 800222 radiaactive mati release from auxiliary boiler sys LONO, F J . MARSH, R J Region 2. Atlanta, Office of the Director HARDIN, A K Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/08/04 13pp
- 8007020199 Submits response to IE Bulletin 80-17. Suppl 1 No design deficiencies have been noted which would preclude scram discharge vol from perfaming required functions FURR. B J Carolina Power & Light Co 80708/07 200

- B009030163 Forwards Revision 1 to IE Bulletin 80-19, 'Failures of Mercury-Watted Matrix Relays in Reactor Protective 89s of Operating Nuclear Power Plants Designed by C-E ' Unitten response required O'REILLY J P Re Region 2. Atlanta. Office of the Director 80/08/13
- 8009160040 Forwards IE Into Notice 80-30. 'Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Asi at Certain GE UWR Facilities "No specific action or response requested O'REILLY, J.P. Region 2. Atlanta, Orfice of the Director 80/08/19
- 8009230059 Submits response to 1E Bulletin 80-20 Westinghouse Type W-2 control switches not used in safety-related applications FURR.B J Carolina Power & Light Co 80/08/19 tp
- 8009230080 Submits response to IE Sulletin 80-19 Hercury-wetted relays re not used in reactor protection sys URR.B J Carolina Power & Light Co 60/08/19
- 8009230085 Submits add) info to ltem 3 of IE Bullotin 80-02 Feedwator spargers were evaluated & do not require essential equipment classification Carolina Power & Light Co 80/08/19 2pp
- B007070638 Ack receipt of BJ Furr 800703 Itr identifying corrective measures for noncompliance noted in 800611 itr & payment of proposed civil penalties
 STELLO, Office of Inspection & Enforcement, Office of the Director 80/08/20 ip
- 8007120072 Forwards Suppl 3 to IE Bulletin 89-17. "Failure of Control Rods to Insert During Scram at BUR " Wiltten response required required O'REILLY, J.P. Region 2 Atlanta, Office of the Director 80/00/22
- 8009160124 Forwards IE Circular 80-10. "10CFR90 59 Bafety Evaluations for Changes to Radwaste Troatment Bys " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/00/22
- 8009020321 Responds to 800801 notice of proposed imposition of civil penalty re improper disposal of radioactive matl Corrective action taken new procedure implemented to remove radioactive matl Penalty fee encl
 JDNES.J A Carolina Power & Light Co (80/09/27 7pp)
- 8009110027 Responds to NRC 800801 1tr re violations noted in If insp repts Corrective actions radiation protection program improved & offsite disposal of potentially contaminated mat1 terminated Carelina Power & Light Co 80/08/2/ 17pp
- 8009120290 Forwards IE info Notice 89-31, "Maloperation of Oould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Brenkers" No written response required .0'REILLY.J P Region 2, Atlanta, Orfice of the Director 80/08/27
- 8009240370 Responds to 10 Dulletin 80-15 Emergency notification syspowered from Generator 2 during loss of offsite power powered from Generator 2 during loss of offsite power Diasel generator actual load test is schoduled for Fall of 1980 FURRAR J Carolina Power & Light Co 80/08/27
- 8009110662 Responds to IE Bulletin 80-17. Suppl 3, re failure of 76 of 189 control rods to fully insert during scram at BUR Item 1 not applicable Periodic Test 1 1 2P revised FURR B J Garolina Power & Light Co BO/08/28 lp
- 8009230526 Forwards Revision 1 to 1E Bulletin 79-26. "Boron Loss From BUR Control Blades " Written response required O'REFLLY, J.P. Region 2. Atlanta. Office of the Director 80/08/29
- 8009240329 Ack receipt of 800711 \$ 0811 ltrs informing NRC or steps taken to correct violations noted in IE imap Repts 30-324/80-20 \$ 50-325/80-23, MURPHY.C E Region 2, Atlanta. Reactor Construction & Engineering Support Branch 80/07/03 ip
- --8009240340 Responds to NRC 800517 Itr re violations noted in If Insp Repts 50-324/80-20 & 50-325/80-23 Corrective actions procedures established us site empineering, QA/QC acceptance of surveillance data & inservice insp TOLLISON, A C Carolina Power & Light Co 80/0B/11 App

- --8009240356 Responds to NRC 800611 ltr re violations noted in IE Insp. Repts 50-324/80-20 & 50-325/80-23 Corrective actions reorganization of inservice insp. will mate future submittals more complete TOLLIBON A C Carolina Power & Light Co. 80/07/11 4pp
- --8009240363 Forwards IE lnsp Repts 90-324/80-20 & 50-325/80-23 on 800527-30 & notice of violation MJRPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 60/06/17 2pp
- --8009240368 Notice of violation from (1159 on 800527-30 a Region 2, Atlanta: Office of the Director 80/06/16 ip
- --8009240374 IE Insp Repts 50-324/80-20 th 50-325/80-23 on 800527-30 Noncomplainte noted inservice insp program incomplete to surveillance activity procedures not established or implemented HEROT. A.R. Region 2. Atlanta, Reactor Construction & Engineering Support Branch BLAKE. J.J. Region 2. Atlanta, Office of the Otrector 80/06/16 Spp
- 8009290287 Forwards IE Circular 80-21, "Regulation of Refueling Grews"
 No written response required
 O'REILLY, J.P. Region 2. Atlanta, Orfice of the Director 80/09/10
 550
- 8007:B0365 Responds to 800827 Itr re-notice of violation concerning improper disposal of radioactively contaminated math & problems in implementation & mot of radiation protection program Related correspondence JONES, J A Carolina Power & Light Co 80/09/12 ip
- 8009300042 Ack receipt of payment of civil penalties & util 800827 ltr re measures taken to correct items of nancompliance Measures will be reviewed during subsequent insps to determine effectiveness in preventing add1 noncompliance STELLO.V Office of Inspection & Enforcement, Office of the Director 80/09/12 lp
- 8009230693 Forwards 90-day response to IE Bulletin 79-01B, re environ qualification of electrical equipment Add1 qualification data will be submitted upon availability Response available in Central Files only UTLEY, E € Carolina Power % Light Co 80/09/19 ip
- R Periodic operating reports & related correspondence
- 8009160260 Forwards monthly operating repts for Aug 1980 TOLLISON, A.C. Carolina Power & Light Co. 80/09/09 ip
- --8009160263 Monthly operating repts for Aug 1980 WILLIS.E Carolina Power & Light Co 80/09/03 10pp
- S Reportable occurrences, LERs & related correspondence
- 8009020380 Forwards LER 60-057/031-0
 TOLLISOM A C Carolina Power & Light Co 80/08/26 ip
- --8009020391 LER 80-057/03L-0 on 800728 during calibr & functional check performance, low level switch 2-821-LIS-ND31C-3, Yarway Model 4418c, actuated at 133 50 inches water applied Caused by instrument drift Switch recalibr & returned to svc TOLLISON, A C Carolina Power & Light Co 80/08/26 1p
- 8009150168 Part 21 rept re leats in heat exchanger tubes of calandria type radicaste evaporator at facility Cause attributed to corrosive attack Evaporator unit out of svc pending repair of leats in tubes & sholl
 BENNETT
- B009100433 Submits special rept re 800808 total loss of power to Emergency Dus E-3 Caused by improperly grounded welding machine Welding cables rerouted TOLLISON.A C Carolina Power & Light Co 80/09/04 2pp
- 8009180570 RD 80-062 on 800907, during reactor core isolation cooling flow rate test at 150 psig pressure. RCIC turbine tripped on high exhaust pressure Caused by manually operated stop check in exhaust to torus found in locked closed position TOLLISON. A C Carolina Power & Light Co GD/09/08 3pp
- 8009230719 Forwards LER 80-050/03L-0 TOLLISON, A C Carolina Power & Light Co 80/09/10 ip

- --8009230727 LER 80-050/03L-0 on 800821, switch 2 of 2-821-F18-MOZIB Barton Model 288 found out of calibr Probably caused by accidental bumping by personnel during refueling outage Switch & instrument recalibr & returned to svc TOLLISON.A C Carolina Power & Light Co 80/09/10 2pp
- 8009230459 RO on 800819, fire support group tripped fire protection deluge valve on 50-ft elevation of diesel generator bldg in ventilation intake fan room Valve actuator arm facing seat found or tacked & actuator solenoid relay misadjusted FOLLISON, A C Carolina Power & Light Co 60/09/15 ip
- 8009250265 Special rept while performing insp to determine fire dc.r operability, dotermined that three doors inoperative Caused by door closers in need of adjustment Closers readjusted & returned to operability
 TOLLISON, A C Carolina Power & Light Co 80/09/16 ip
- 8009260635 Forwards LER 80-066/01T-0 FURR.B J Carolina Power & Light Co 80/09/19 tp
- --8009260638 LER 80-066/01T-0 on 800907, reactor core isolation codist turbine tripped on high turbine exhaust pressure Caused by improper valve positioning apparently due to personnel error TOLLISON, A C Carolina Power & Light Co 80/09/19 6pp
- 8009290288 Forwards updated LCR 80-033/03L-1 TOLLIBON, A C Carolina Power & Light Co 80/09/19 ip
- --8009290309 Updated LER 80-033/03L-1 on 800215, while attempting to 11; in 2A RMR room cooler, cooler blower motor tripped on magnetic; Caused by low breaker magnetics setting Breaker magnetics respt 3 breaker satisfacturily tested TOLLISON, A C Carolina Power & Light Co 80/09/19 Ip
- --8009300479 Updated LER 80-062/01T-i on 800907.during unit 2 reactor core isolation cooling flow rate testimeactor core isolation cooling turbine tripped on high turbine exhaust pressure Caused by personnel error TULLISON.A C Carolina Power & Light Co 80/09/24 App
- DOCKET 50-329 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- BO07230252 Requests that all personnel be reminded of purpose of emergency notification sys 5 health physics network Sys installed for govt use during emergency O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22
- E009990402 Bubmits revised schedule for submittal of revised energancy plan, as specified by 800819 final rule revising lOCFR50 & 70 UTLEY, E E Carolina Power & Light Co 80/09/02 ip
- O Adjudicatory correspondence
- B009270120 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by B01101 IPPOLITO.TA Operating Reactors Branch 2 80/08/29 2pp
- ---B009220122 Order for mod of Licenses DPR-62 & DPR-71 to add infostfully responds to NRC request for info re environ qualification of safety-related electrical equipment Infoshould be submitted by B01101
 EISENHUT, D O Division of Licensing 80/08/29 App
- H General correspondence
- 8009120437 Advises of BWR owners group organizational changes & that future correspondence be forwarded to DB Naters Future requests for util action should be addressed to individual , licensees & applicants WATERS.D B Carolina Power & Light Co 80/09/09 2pp

- P Operating license stage documents : correspondence
- 8009110554 Suppls NRC 800707 request for proposed Tech Specs changes rescram discharge vol vent & drain valves. 5 reactor protection sys 5 control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISEMUT.D 0 Division of Licensing 80/07/22 22pp
- 8009020297 Submits interim criteria for shift staffing to all DL & CP licensess & applicants per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENMUT.D G Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities' Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl M/o NUREG EISENHUT, D G Division of Liconsing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lussons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT. D G Division of Licensing 80/08/07 AOPP
- B009040307 Advises that two specific Event 5 valve configurations do not exist at facility per review of response to 800223 ltr "Primary Coolant Sys Pressuro Isolation Valves," technical evaluation rept encl IPPDL1TO.T A Operating Reactors Branch 2 80/08/08 3pp
- --80090403i5 "Primary Cooiant Eys Pressure Isolation Valves." technical evaluation rept NGELL,P N . STILMELL,T C Frankiin institute/Franklin Research Center NRC-03-79-118 80/07/21 5pp
- 8009190678 Forwards NUREC-0661, "Mark I Containment Long-Term Program SER Resolution of Generic Technical Activity A-7 " Rept discusses generic suppression pool hydrodynamic load definition W/o encl iPPOL170.T A Operating Reactors Branch 2 80/08/20 2pp
- 8009230772 Notification of 800905 meeting w/utii in Bethesda,MD to discuss procedure for amending OLs to add addl owners HJLBUN. J N Licensing Branch i 80/08/29 4pp
- 8007070448 Forwards updated outage schedule re Mark I containment program mode Containment mode to conclude in May 1982 Plent unique analysis scheduled to be completed in June 1981 UTLEY, E E Carolina Power & Light Co 80/09/02 2pp
- 8009190047 Advises of acceptablility of 791227 response to NRC 791109 itr re ECCS evaluation models dealing w/fuel cladding sweiling & incidence of rupture IPPOLITO, T A Operating Reactors Dranch 2 80/09/03 2pp
- 8009170186 Forwards "Recovery of Radioactive Mati from Brunswick County Landfili near Southport, NC, ' final rept FURR, B J Carolina Power & Light Co 80/09/05 ip
- --8009i70191 "Recovery of Radioactive Matl from Brunswick County Landfiil Near Southport,NC," final rept > Carolina Power & Light Co 80/09/05 38pp
- --8009170197 "Radiation Control & Test Procedure 3280, Radioactive Matl Recovery Procedure " # Carolina Power & Light Co 80/05/01 8pp
- 8009160374 Forwards results of review of ECCS equipment availability w/dc power supply fallure
 UTLEY.E E Carolina Power & Light Co 80/09/11 4pp
- 8009170400 Summary of 800905 meeting w/CPDL & NC Municipal Power Agency 3 in Bethesda.MD re procedure for OL & GP amends NILSON.J N Licensing Branch i 80/09/12 7pp
- BO09190425 Application to amend License DPR-71 to revise Tech Specs by changing temporary spec issued W/Amend 29 re safety relief valve settings Effective and date of spec will be extended until completion of T-quencher mod WTLEY.E E Carolina Power & Light Co 80/09/15 2pp
- --8009190429 Proposed Tech Spec change for Page 9/4 4-4 re sefety relief valve settings End date of temporary spec issued w/Amend 29 will be extended until completion of T-quencher mod « Carolina Pouer & Light Co 80/09/19 ip

- 800923043B Forwards proposed revisions to Tech Specs, implementing changes requested by NRC 800702 ltr re TMI Lessons Learned requirements Proposed license conditions encl
 UTLEY.E E Carolina Power & Light Co 80/09/16 4pp
- ~-800923043? Proposed revisions to Tech Specs.Pages 3/4 3-5i & 92. B 3/4 3-3.6-5.6-6 re post-accident monitoring instrumentation & min shift crew composition & Carolina Power 3 Light Co 80/09/14 10pp
- G inspection reports. IF Bulletins 3 correspondence
- 8009090055 Forwards IE Bulletin 80-07, Suppl 1, "BUR Jet Pump Assembly Failure" No response required O'REILLY, J P Region 2, Atlanta, Drice of the Director 80/05/13 lp
- 8009190329 Forwards IE Insp Repts 50-324/80-26 & 50-325/80-29 on 800601-30 No noncompliance noted LENIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/07/24 2pp
- ---8009190379 IE Insp Repts 50-324/80-26 % 90-325/80-29 on 800601-30
 No noncompliance noted Major areas inspected control room
 observations, Unit 1 refueling operations, review of plant
 logs, tour of vital areas & physical security
 OUZTS. J.E. Region 2. Atlanta, Office of the Director
 KELLOGG, P.J. Region 2. Atlanta, Reactor Operations Nuclear Support
 Branch 80/07/23 3pp
- 8009240273 Forwards iE Insp Repts 50-324/80-23 & 50-325/80-26 on B00602-06 No noncompliance nated LDNQ.F J Region 2. Atjanta, Office of the Director B0/08/04
- --8009240284 IE Insp Repts 50-324/80-23 & 50-325/80-26 on 800602-06 No noncompliance noted Major areas inspected site environ monitoring 8 circumstances surrounding 800222 radioactive matl release from auxiliary bolier sys LONO.F J. MARSH.R J. Region 2. Atlanta, Office of the Director HARDHIA Region 2. Atlanta, Construction & Engineering Support Branch 80/08/04 15pp
- 8009020199 Bubmits response to iE Bulletin 80-17, Suppl I No design deficiencies have been noted which would preclude scram discharge vol from performing required functions FURR: B J Carolina Power & Light Co 80/08/07 2pp
- 8007030163 Forwards Revision 1 to IE Bulletin 80-17, "Fallures of Mercury-Hetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Uritten response required O'REILLY, J P Region 2, Atlanta. Office of the Director 80/08/15 in
- 8009160040 Forwards IE Info Notice 80-3D, "Potential for Unacceptable interaction Between Control Rod Drive Scram Function & Nonessantial Control Air at Certain GE BNR Facilities "No specific action or response requested G'REILLY. J P Region 2. Atlanta. Office of the Director 80/08/19
- 8009230059 Submits response to iE Builetin 80-20 Nestinghouse Type N-2 control switches not used in safety-related applications FURR.B J Carolina Power & Light Ca BO/08/19 1p
- 8009230080 Submits response to IF Bulletin 80-19 Mercury-wetted relays are not used in reactor protection sys FURR, B J Carolina Power & Light Co 80/08/19 1p
- BO04230085 Submits add1 info re Item 3 of IE Dulletin 60-02 Feedwater spargers were evaluated & do not require essential equipment classification FORR.B J Carolina Power & Light Co BO/08/19 2pp
- 8007070638 Ack receipt of BJ Furr 800703 ltr identifying corrective measures for noncompliance noted in 800611 ltr & payment of proposed civil penalties
 STELLO, U Office of Inspection & Enforcement, Office of the Director 80/08/20 lp
- 8009120072 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR" Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22

- 8009160124 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY.J P Region 2. Atlanta, Orfice of the Director 80/08/22
- 8009020321 Responds to 800801 notice of proposed imposition of civil penalty re improper disposal of radioactive matl Corrective action taken new procedure implemented to remove radioactive matl Penalty fee encl
 JONES, JA Carolina Power & Light CO 80/08/27 7pp
- BOO9110027 Responds to NRC 900801 ltr re violations noted in IE insp repts Corrective actions radiation protection program improved & offsite disposal of potentially contaminated matl terminated JOI-S.J.A. Carolina Power & Light Co. 80/08/27 17pp
- 8009120290 Forwards IE Info Notice 80-31. "Haloperation of Gould-Brown Bovers 483 Voit Type K-6005 & K-DDN 6003 Circuit Breakers " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/27
- 8009240370 Responds to 1E Bulletin 80-15 Emergency notification syspowered from Generator 2 during loss of offsite power Diesel generator actual load test is scheduled for Fall of 1980 FURR.B J Carolina Power & Light Co 80/08/27 2pp
- 8009110662 Responds to 1E Bulletin 80-17.Suppl 3.re failure of 76 of 185 control rods to fully insert during scram at BNR Item l not applicable Periodic Test 1 1 2P revised FURR B J Carolina Power & Light Co 80/09/28 lp
- 8007230526 Forwards Revision I to IE Bulletin 79-26. "Boron Loss From BHR Control Blades " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/29 to
- 8007240329 Ack receipt of 800711 & 0811 ltrs informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-324/80-20 & 50-325/80-23 MURPHY.CE Region 2. Atlanta Reactor Construction & Engineering Support Branch 80/09/03 lp
- --8009240340 Responds to NRC 800617 ltr re violations noted in IE lnsp Repts 50-324/80-20 & 50-325/80-23 Corrective actions procedures established re site engineering, OA/GC acceptance of surveillance data & Inservice insp TOLE.ISON.A C Carolina Power & Light Co 80/08/11 2pp
- --809240356 Responds to NRC 800-11 litr reviolations noted in IE Insp Repts 50-224/80-20 & 50-325/80-23 Corrective actions reorganization of inservice insp will make future submittals core complete TOLLISONA C Carolina Power & Light Co 80/07/11 4pp
- --8007240363 Forwards IE Insp Repts 50-324/80-20 & 50-325/60-23 on 800527-30 & notice of violation HURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/80/17 2pp
- --8009240368 Notice of violation from insp on 800527-30 * Region 2. Atlanta, Office of the Director 80/06/16 ip
- --8009240374 IE Insp Repts 50-324/80-20 & 50-325/80-23 on 800527-30 Noncappliance noted inservice insp program incomplete & surveillance activity procedures not established or implemented HCROT.A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch BLAKE J J Region 2, Atlanta, Office of the Director 80/06/16 Spp
- 8009270287 Forwards IE Circular 80-21. "Regulation of Refueling Crews "
 No written response required
 O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/09/10
 509
- E0091803A5 Responds to 800827 Itr re notice of violation concerning improper disposal of radioactively contaminated matl & problems in implementation b mgt or radiation protection program Related correspondence

 JOMPS, J A Carolina Power & Light Co 80/09/12 1p
- BOO9300042 Act receipt of payment of civil penalties & util BOO927 ltr
 re measures taken to correct items of noncompliance Measures
 will be reviewed during subsequent insps to determine
 effectiveness in preventing addl noncompliance
 STELLO. V Office of Inspection & Envorcement. Office of the
 Diractor 80/09/12 by

- 8009230193 Forwards 90-day response to IE Bulletin 79-018, re environ qualification of electrical equipment Addl qualification data will be submitted upon availability Response available in Central Files only
 UTLEY.E E Carolina Power & Light Co 80/09/19 1p
- R Periodic operating reports & related correspondence
- 8009160260 Forwards monthly operating repts for Aug 1980 TOLL150N.A C Carolina Power & Light Co 80/09/09 IP
- --8009160263 Monthly aperating repts for Aug 1980 HILLIS.E Carolina Power & Light Co 80/09/03 10pp
- S Reportable occurrences. LERs & related correspondence
- 8009150168 Part 21 rept re leaks in heat exchanger tubes of calandria type radwaste evaporator at facility Cause attributed to corrosive attack Evaporator unit out of svc pending repair of leaks in tubes & shell BENNETT.R C Whiting Corp 80/09/09 3pp
- 8009100433 Submits special rept re 800808 total loss of power to Emergency Bus E-3 Caused by improperly grounded welding machine Welding cables rerouted TOLLISON, A C Garolina Power & Light Co 80/09/04 2pp
- 8009120366 Farwards LER 80-055/03L-0 FURR B J Carelina Power & Light Co 80/09/05 lp
- --8009120371 LER 80-055/03L-0 on BOOS12 during startup preparations, reactor vessel conductivity measured excessively high Caused by organics breakdown in reactor vessel Beries of condunsate makeup & reject operations performed using charcoal filters YOLLISON, A C Carolina Power & Light Co 90/09/04 1p
- 8009180570 RO 80-062 on 800907, during reactor core isolation cooling flow rate test at 150 psig pressure, RCIC turbine tripped on high exhaust pressure Caused by manually operated stop check in exhaust to torus found in locked closed position TOLL180%, A C Carolina Power & Light Co 80/09/08 3pp
- 8009230624 Forwards updated LER 80-012/03L-i TOLL150N.A C Carolina Power & Light Co 80/09/10 1p
- --8007230635 Updated LER 80-012/03L-1 on 800224, during normal surveillance, RIP valves X206D-C, variable leg isolation for torus level transmitter GAC-LT-2606 & switch E41-LEH-N013B, shut & failed to reopen Gaused by leaking switch diaphragm TOLLISON, A C Carolina Power & Light Co 80/09/10 2pp
- 8009230725 Forwards updated LER 80-024/03L-1 TOLLISON.A C Carolina Power & Light Co 80/09/10 lp
- --8009230735 Updated LER 80-024/03L-1 on 800405, drywell equipment drain integrator observed indicating flow w/both pumps secured & common isolation valve shut Caused by accumulation of rust & corrosion around valve seat of vacuum breaker TOLLISON,A C Carolina Power & Light Co 80/09/10 2pp
- 8009230736 Forwards LER 80-066/03L-0 TOLLISON A C Carolina Power & Light Co 80/09/12 1p
- --8009230740 LER 80-066/03L-0 on 800824 during normal surveillance, containment atmospheric menitor oxygen analyzer, I-CAC-ATH-1259-2: was observed indicating upacale Caused by loss of sample flow due to condensate in analyzer air dryer TOLLISON,A C Carolina Power & Light Co 80/09/12 2pp
- 8007230457 RO on 800817, fire support group tripped fire protection deluge valve on 50-ft elevation of diesel generator bldg in ventilation intake fan room Valve actuator arm facing smal found cracked & actuator solenoid relay misadjusted TOLLISON.A C Carolina Power & Light Co 80/09/15 ip
- 8009230670 Forwards LER 80-065/03L-0 TOLLISON-A C Carolina Power & Light Co 80/09/16 1p
- 8009230709 Forwards LER 80-067/03L-0 TOLLISON, A C Carolina Power & Light Co 80/09/16 lp

- --2309230717 LER 80-067/02L-0 on 800822. while withdrawing control rods during startup, erroneous rod blocks were received from rod worth minimizer Also plant process computer printed notch errors thile none existed Cause not determined 10LLISONAC Carolina Power 5 Light Co 80/09/16 2pp
- E039230718 Forwards LER 80-063/03L-0 TO:L150N.A C Carolina Power 3 Light Co 80/09/16 ip
- --8009230745 LER 80-063/03L-0 on 800826, during testing of reactor flow bias, three average power range monitors were actuating out of spec Caused by instrument drift Monitor4 recalibr % returned to svc
 TOLLISCHA C Carolina Power % Light Co 80/09/16 Ip
- EC09250265 Special rept while performing insp to determine fire door operability.determined that three doors inoperative Caused by door closers in need of adjustment Closers readjusted & returned to operability TOLLISOW. A C Carolina Power & Light Co 80/09/16 ip
- 8009270286 Forwards LER 80-058/03L-0 TOLLISON A C Carolina Power & Light Co 80/07/19 (p
- --B009290311 LER 80-058/03L-0 on 800822, during normal survexliance, drywell flow integrator failed to change while sump pump was running Caused by blown fuse in drywell floor drain flow transmitter power supply Fuse replaced FOLLISON.A C Carolina Power & Light Co 80/09/19 2pp
- 3009303489 Forwards LER 80-069/03L-0
 TOLLISON A C Carolina Power 8 Light Co 80/09/23 1p
- --Bop9300509 LER 80-069/03L-0 on 800827.during normal surveillance.RHR flow indicator on remote shutdown panel demonstrated erratic indications w/ays shutdown Caused by mechanical faiture of meter movement Movement calibr & returned to svc TOLLISOW.A C Carolina Power & Light Co 80/09/23 2pp
- 8009300559 Forwards LER 80-070/03L-0 TCLLISCH A C Carolina Power 3 Light Co 80/09/24 lp
- --8007300568 LER 80-070/03L-0 on 800828 during normal operation, several alarms received from Diesel Generator I Cause not determined Alarm relays reset generator tosted & returned to svc Update rept to be submitted upon discovery of cause TOLLISCV.A C Carolina Power & Light Co 80/09/24 Ip
- ECICKET 50-326 UNIV OF CALIFORNIA AT IRVINE RES REACTOR

 G Inspection reports. IE Bulletins & correspondence
- 6009120459 Ack receipt of 800821 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-326/80-01 CRENS.J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/09/04 ip
- --8009120466 Responds to NRC 800812 ltr re violations noted in 1E Imap Rept 50-326/80-01 Corrective actions operating procedure revised to include annual review of reactor operational records MCGAUGH.J L California, Univ of, Irvine 80/08/21 3pp
- --Bod9120470 Ack receipt of B00724 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-326/80-01 NRC concluded that licensee actions are not sufficient to avoid further violations

 CREKS.J L Region 5. San Francisco. Reactor Operations Nuclear Support Branch 80/08/12 lp
- -8009120471 Responds to NRC 800703 ltr re violations noted in IE lnsp Rept 50-326/80-01 Corrective actions reactor operations committee will establish regular schedule for review of facility operations & schedule quarterly committee meetings MCGAVOH. J. California, Univ or, Irvine 80/07/24 2pp
- -8009120474 Forwards IE Imap Rept 50-326/80-01 on 800519-21 & notice of violation CREMS.J L Region 5. San Francisco. Reactor Operations Muclear Support Branch 80/07/03 2pp
- -8009120476 Notice of violation from insp on 800519-21 * Region 5, San Francisco, Office of the Director 80/07/03 lp

- --8007120478 IE Insp Rept 50-326/80-01 on 800517-21 Noncompliance noted failure of reactor operations committee to meet & conduct quartorly reviews at required frequency FAULKENBERRY, B Region 5, San Francisco, Reactor Operations Nuclear Support Branch ZVETZIO.0 B, CHAFFEE, A E Region 5, Gan Francisco, Office of the Director 60/07/03 5pp
- DOCKET 50-027 GEGUOYAH NUCLEAR PLANT, UNIT 1
- E NRG Safety Evaluation Report (SFR), supple & correspondence
- 8007080419 Forwards Suppl 2 to SER (NUREO-0011) SCHNENCER, A Licensing Branch 2 80/09/04 2pp
- --8007680423 SER for facility
 # Office of Nuclear Reactor Regulation, Director NUREO-0011 82
 80/08/31 179pp Available at NTIS \$5.50
- BO09260254 Forwards Buppl 3 to SER for Pocility SCHWENCER, A Licensing Branch 2 80/07/16 2pp
- --8009260258 SER for facility, Suppl 3

 * Office of Nuclear Reactor Regulation, Disector NUREO-0011 83
 60709730 62pp Available at NTES \$4 00
- F Security, medical, emergency & fire protection plans
- BOO9230267 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Bys installed for govt use during emergency D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22, in
- 8009030536 Notifies of 800922 final implementation of radiological emergency plan as revised by 800/21 to 0815 ltrs MILLG.L M Tennossee Valley Authority 80/08/29 lp
- 8009230333 Forwards physical security plan.Revision 6A Revision withheld (ref 10CTR2 770)
 MILLS.L M Tennossee Valley Authority 89/09/17 1p
- Q Adjudicatory correspondence
- 8009220427 Order authorizing issuance of OL DRR-77 CHILK:S J Office of the Secretary of the Commission (80/09/10
- H General correspondence
- BOO71103B7 Commends Commissioners for denying facility full-power license until hydrogen buildup issue has been resolved beyond any doubt No compromise too expensive for prevention of another near-devastating event such as TMI CALDNELLM A Affiliation Unknown NO/09/00 10
- 8009120301 Responds to 800703 ltr requesting NRC comment on & Bpallons 800619 ltr re-potential impact of dan failure of Pand Hill Reservoir which util is considering for future const FEB scheduled for completion in Dec 1780 DIRCKS.W J. Office of the Executive Director for Operations 80709708 | 10
- ---B009120317 Requests NRC response to encl K Spallone 800619 ltr repetential impacts of Pond Hill Reservoir const & operation within 2 wks of receipt of request SCHWEIACR, R S Senste 80/07/03 2pp
- I financial information
- BOO9090543 Forwards Annual Financial Rept 1979. CROBS. J L Tennesses Valley Authority 60/09/04 lp
- --8009090969 Annual Financial Rept 1979 * Tennessee Valley Authority 60/09/04 44pp
- J Insurance & indomnity information
- 8009030374 Forwards Endorsement 1 to NELIA Binder EB-66 FIELPER, J. Marsh & McLeonan, inc., M & M Nuclear Consultants, Inc Div. 80/08/29 2pp

- A Utility Final Sarety Analysis Report (FBAR) & amends
- 8009030560 Forwards affidavit certifying that Amends 66 & 67 to FSAR were mailed to D Hoore. JR Hagan & BA Osborne on 800826 MILLS.L M Tennessee Valley Authority 80/08/26 2pp
- D. Advisory Committee on Reactor Safeguards reports & correspondence
- 8009190528 Notice of ACRS 800710-12 neeting in Washington, DC to discuss rept on NRC screty research budget for FN82 & operation of Sequeyah Unit 1
 HOYLE, J.C. Assistant Director for Esport/Import & International Safeguards 80/06/19 App
- 2009190766 Discusses 243rd ACRS meeting on 800710-12 to Sequoyah review & research program Fr82 budget PLESSET.M S ACRS - Advisory Committee on Reactor Safeguards 80/07/18 358
- 8007160093 Notice of ACRS Subcommittee on Structural Engineering 800702 meeting in Mashington DC to establish mar internal pressure Sequeyah Containment can withstand HOYLE J C Office of the Secretary of the Commission 80/08/13 200
- 8009050394 Transcript of ACRS Subcommittee on Structural Engineering 800902 hearing in Washington.DI re establishing max external pressure temp that Sequovah containment structure can withstand & ACRS Advisory Committee on Reactor Safeguards 80/09/02 182pp
- 8009180172 Forwards agendas for ACRS 800902 subcommittee meeting & 800904 full committee meeting re facilities TEDESCO.R L. Assistant Director for Licensing 80/09/02 4pp
- BG0915023B Responds to request for comments on questions contained in V Gilinsky B00B07 ltr re facility ice condenser containments Facility is capable of sustaining pressure of at least 45 psig w/o structural failure PLEBSCT. H B ACRS Advisory Committee on Reactor Safeguards B0/09/04 3pp
- 8009300329 Forwards ACRS E00908 itr to J Ahearne re ice condenser containments SCHMENCER: A Licensing Branch 2 80/09/18 2pp .
- P Operating license stage documents & correspondence
- 80091:0604 Requests review of R&D Associates rept, "Sequoyah Containment Analysis " Comments due by 80080 TEDESCO.R L Assistant Director for Licensing 80/07/29 2pp
- BOO9080080 Forwards draft NURES-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 enci W/o NURES EISENHUT, D O Division of Licensing 80/08/01 119pp
- 8008210618 Discusses preliminary assessment of use of igniters as method of hydrogen control at facilities Assessment based on present understanding of util-proposed igniter scheme Exclusiva use of igniters may not be grudent BARI.R A Brookhoven National Laboratory 80/08/08 3pp
- 8009120578 Responds to request for comments to Sequovah containment Forwards info re stringer & skin interaction Concludes NRC calculations overestimated beneficial effect of stringers MUBBARD.H W R & D Associates 80/08/18
- 8009110332 Forwards full-power UL, stide presentation entitled, "NRC Staff Review of Sequoyah for Full Power Operation Commission Briefing, 800821, " transcript of NRC 800821 public meeting & draft Suppl 2 to SER, NUREQ-0011 DENION, HR Office of Nuclear Reactor Regulation, Director, 80/08/20 14pp
- --8009110341 Transcript of Commission 800821 public meeting in Washington, DC to discuss facility full-power license Pp I-89 * Cormission 80/08/21 91pp
- ---8009110343 Draft Suppl 2 to SER * Office of Nuclear Reactor Regulation, Director NURE9-0011 92 80/08/15 150pp

- 8009040434 Forwards mati re NRC review of ice condenser containment to hydrogen control measures for Sequevah Nuclear Power Plant ACRS has scheduled meetings in Mashington DC on 800828.0702 to 4 to discuss issue TEDESCO.
- --8009040443 "Hydrogen Control for Sequoyah Nuclear Plant.Units (12 + Office of Nuclear Reactor Regulation, Director 80/08/13 Sipp
- --B009040450 Transcript of 800821 discussion of Sequoyah full power license in Washington, DC Pp 48-89 + Connission B0/08/21 47pp
- 8009150527 Forwards requests for add! info in response to util 800814 1tr re safety analysis of interim distributed ignition sys SCHWENCER, A Licensing Branch 2 80/08/28 3pp
- 8009030A36 Forwards Procedure IP-18. "Plant Release Rate Calculations" & graphs of containment activity as function of monitor reading, in fulfillment of 800Bil commitment to provide correlation procedure MILLS.E. II Tennessee Valley Authority 80/08/29 3pp
- --8009630438 "Plant Release Rate Calculations "
 ZOBEL.W , KITTS,R J , DILL.J Tennessee Valley Authority
 80/08/21 48pp
- 8009240560 Forwards preliminary staff assessment re use of halon as hydrogen combustion control measure Items addressed include selection 8 design of halon delivery sys, chemical stability requirements, reactivity 5 consequences of halon injection DENTON, H R Defice of Nuclear Reactor Regulation, Director 80/08/29 9pp
- --8009240564 Staff requirements memo re Commission 800814 meeting CHILK.S J Office of the Secretary of the Commission 80/08/18
- 8009030662 Forwards "Core Degradation Program.Vol 1 Hydrogen Study*t
 "Core Degradation Program Vol 2 Rept on Safety Evaluation of
 Interim Distributed Ignition Sys." in response to NRC 800828
 1tr Cross ref of NRC questions & util answers encl
 MILLS.L M Tennessee Valley Authority 80/09/02 3pp
- --8009030664 "Core Degradation Program, Vol 1 Hydrogen Study " 4 Tennessee Valley Authority 80/09/02 100pp
- G009030237 Forwards status rept on licensing items requiring completion before exceeding 5% power operation identified in B00820 draft full power license Procedures required as resolution to IE Builetin 79-27 will be approved by B00905 CR088.J L. Tennesses Valley Authority B0/09/03 2pp
- 6009110349 Farwards proposed full-power QL. Supple 2 & 3 to SER & "Discussion of Environ Effects of U Fuel Cycle " Tests & safety review of proposal for distributed ignition sys espected to be completed by Jan 1981 DENIGH.H R Office of Nuclear Reactor Regulation, Director 80/09/03 18pp
- --8009110355 Draft Suppl 3 to SER

 * Office of Nuclear Reactor Regulation, Director NUREQ-001153
 80/09/30 75pp
- --8009110398 "Discussion of Environ Effects of U Fuel Cycle" * Office of Nuclear Reactor Regulation, Director 80/09/30 92pp
- ---8009110060 Suppl 2 to SER

 * Office of Nuclear Reactor Regulation, Director NURE9-0011 87
 RD/08/31 180pp Available at OPO X5 50
- 8009250243 Forwards consultant ltr on possible fire risk in its condensors w/foam insulation Response requested by 800904 for discussion at ACRS meeting TEDESCO.R L Assistant Director for Licensing 80/09/03 2pp
- --8009250247 Expresses concern re possible fire risk in ice condensets u/foam insulation
 MACDOUGALL. E. A. Brookhaven National Laboratory 80/08/18 | 9

- 8007080299 Forwards description of facility ice condenser insulation matls & containment wall insulation structural design & insulation flammability review results CROSS.J L Tennessee Vailey Authority 80/09/04 11pp
- B009090370 Forwards addl info on temp control for main steam valve rooms, in response to NRC request lnfo revises util 800729 itr
 - CROSS.J L Tennessee Valley Authority 80/09/04 2pp
- 8009120389 Provides info re polyurethane foam insulation in ice condenser Auto ignition temp is 1,000 F & ignition temp is 400 to 500 F Decomposition starts at 300 F CRESS.J L Tennessee Vailey Authority 80/09/05 lp
- 8009300294 Forward Chilk 800818 memo to Dircks re briefing on hydrogen control in Sequoyah containment DENTON-H R Office of Nuclear Reactor Regulation, Director 80/09/10 lp
- 8009190476 Forwards info re matl test repts for critical section of containment steel Mill test rept on critical section will be submitted by 800915
 MILLS.L M Tennessee Valley Authority 80/09/12 4pp
- 8009170297 Forwards mill test rept re critical section of containment sterl in facility Matl suppis 800912 submittal which surearizes assessments of containment to withstand internal pressures Oversize drawings available in Central Files only, MILLS, L M Tennessee Valley Authority 80/09/15 10pp
- 8009230549 Proposes alternate replacement schedule for turbocharger drive geer assemblies mfg by General Motors Util will limit turbocharger operation to less than 200-h MILLS.L M Tennessee Valley Authority 80/09/17 2pp
- E009290333 Forwards Revision 3 of response to NUREO-0878.TMI-2 Lessons Learned Yask Force status rept & short-term recommendations, Items 2 1 & Revision 3 changes procedures description for reducing & quantifying leakage from liquid sys MILLS.L M Tennessee Valley Authority 80/09/22 ip
- 8009300226 Requests changes to facility Tech Specs to permit plant startup includes revisions to surveillance requirements. Leakage limit for valves FCV-74-1 & FCV-74-2 & leakage testing on valves after automatic or manual action MILLS.L & Tennessee Valley Authority 80/09/23 2pp
- 8007300400 Forwards technical questions re implementation of interim policy on 10CR450 & 5i
 MILLS.L.M Tennesses Valley Authority 80/09/23 3pp
- 8009290262 Application for amend of License DPR-77, changing Tech Specs 3 4 6 2,4,4 6 I \$ 3 4-1 to permit leak testing of valves in Hode 3 MiLLG.L M Tennessee Valley Authority 80/09/24 1p
- --9009270280 Proposed Tech Specs 3 4 6 2,4 4 6 1 & 3 4-1, permitting look testing of valves in Mode 3 & allowing util 30 days to accumulate data at rated sys pressure to establish baseline leakage limits for RHR sys supply line valves # Tennessee Valley Authority 60/09/24 5pp
- G Inspection reports, IE Bulletins & correspondence
- 8009040317 Forwards IE Insp Rept 50-327/80-23 on 800616 No noncompliance noted BTGHR.J.P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/07/14 2pp
- --8009040330 IE Insp Rept 50-327/80-23 on 600616 No noncompliance noted Major areas inspected emergency exercise between TVA & offsite support organizations

 JENKINS, Θ R Region 2, Atlanta, Fuel Facility & Materials Safety Branch OIBSON,Θ T. COTTLE,W Region 2, Atlanta, Office of the Director 60/07/15 Δρρ
- 8009100051 Forwards IE Bullatin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Failowing Secondary Side High Energy Line Rupture " Written response required d'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/07/24
- BOQ9020214 Forwards response to IE Bulletin 79-03A No 8A-312 & A-312, Type 300 series fusion walded pipe used or planned for use in safety-related sys at greater than 85% design stress except Watts Bar Mati under investigation at Watts Bar Millets Authority 80/08/05 2pp

- 8009090802 Responds to IE Bulletin 79-03A "Longitudinal Weid Defects in ASME SA-312. Type 30: Stainless Steel Pipe " Use of matis still under investigation for sys supplied by MSSS vendor MILLS. L II Tennessee Valley Authority 80/08/05 2pp
- 8009020303 Forwards IE Insp Repts 50-327/80-24.50-328/80-15, 50-390/80-20, 50-391/80-14, 50-438/80-13 50-439/80-13, 30-518/80-11, 50-518/80-11, 50-5518/80-11, 50-553/80-11, 50-553/80-11, 50-553/80-11, 50-554/80-10, 50-56/80-10 & 50-567/80-10 O'REILLY, J P Region 2, Atlanta, Orfice of the Director 80/08/06 200
- --8009020312 Notice of violation from insp on 800707-11
 * Region 2, Atlanta, Office of the Director 80/08/04 4pp
- --8009020337 IE Insp Repts 50-327/80-24,50-328/80-15,50-390/80-20,50-391/80-14,50-438/80-13,50-439/80-13,50-518/80-11,50-5518/80-11,50-5518/80-11,50-5518/80-11,50-554/80-11,50-554/80-11,50-554/80-10,5
- 8007030146 Forwards Revision 1 to IE Bulletin 83-19, "Failures of Mercury-Hetted Matrix Relays in Reactor Protective 84s of Operating Nuclear Power Plants Designed by C-E " Uritten response required O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/08/15 to
- 8009020104 Forwards table listing all components identified by drawing review which do not remain in emergency made after reset of an engineered safety features signal No items require mod to comply w/intent of it Bulletin 80-06 MILLS.L N Tennessee Valley Authority 80/08/18 App
- 8007160153 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/08/22 lp
- 8009110118 Ack receipt of 800820 Itr informing NRC of steps taken to correct violations noted in 1E Imag Rept 50-327/80-26 KENNA,W 8 Region 2, Atlanta, Safeguards Branch 60/08/27 1p
- --8009110181 Responds to NRC 800728 ltr re violations noted in IE lasp Rept 50-327/80-26 Corrective actions withheld (ref 10CFR2 790) MILLS:L M Tennessee Valley Authority 80/08/20 lp
- --8009110188 Forwards IE insp Rept 50-327/80-26 on 800708-09 & notice of violation Notice of violation withheld (ref 100FR2 790) KENNA-W B Region 2, Atlanta, Safeguards Branch 80/07/28 2pp
- --8009110191 IF Insp Rept 50-327/80-24 on 800708-09 Noncompliance noted testing alarms once every seven days Details withheld (ref 100FR2 790)
 TOBIN: U J Region 2. Atlanta, Office of the Director OILLESPIE.F P Region 2. Atlanta, Safeguards Branch 80/07/28
- 8009120340 Forwards 1E Info Notice 80-31. 'Maloperation of Gould-Brown Boyeri 480 Volt Type K-6005 & K-DON 6005 Circuit Breakers "No written response required O'REILLY, J P Region 2, Atlanta. Office of the Director 80/08/27 in
- 8009120679 Responds to IF Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Relays identified are not used in facility Forty manhours expended for review MILLS:L (1 Tennessee Valley Authority 80/09/04 ip
- 8009250480 Forwards response to IE Bulletin 80-15. "Possible Loss of Emergency Notification Sys (EUS) w/Loss of Offsite Power " ENS at facility is supplied power from onsite power source Mod to ENS power supply will be implemented CROBS, J L Tennessee Valley Authority 80/09/05 2pp
- 8009260375 Forwards IE Circular 80-2i, "Regulation of Refueling Crews " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/10 Son
- 8009300195 Submits response to iE Builetin 80-06 re engineered safety features resut controls Pressurizer backup heater bank has been found to return to normal status Operating instructions & operator training will provide guidance MILLG.L II Tennessee Valley Authority 80/09/15 2pp

R Periodic operating reports & related correspondence

- 8009030397 Discharge monitoring rept for 800501-0601 EL-ASHRY, N 1 , STEINER.C R Tennessee Valley Authority 80/08/08 87an
- 8089090414 Forwards "Radiological Impact Assessment, Sequoyah Nuclear Plant, Jan-June 1980 " MILLS, L. H. Tennessee Valley Authority 80/08/29 ip
- --8009070418 "Radiological Impact Assessment, Sequoyah Nuclear Plant, Jan-June 1980 " 3 Tennessee Valley Authority RH-80-4-801 80/08/29 23pp
- 8009170261 Forwards monthly operating rept for Aug 1980 BALLENTINE, J M Tennessee Valley Authority 80/09/09 1p
- --8009170262 Monthly operating rept for Aug 1980
 BALLENTINE.J M . HUBER.J M . Tennessee Valley Authority 80/09/02
- S. Reportable occurrences. LERs & related currespondence
- B009100537 Final deficiency rept re control rod drop events Operating procedures to be revised per Nestinghouse instructions. Procedural change will be made prior to greater than 90% power level ascension 3 will prevent power overshoot MILLS.L B. Fennessee Valley Authority B0/08/05 2pp
- 8009020201 Final deficiency rept re sarety injection pump breaker lockout Seal-in contact of IX relays to be removed from circuit breakers in 6,900-volt shutdown boards by 801103 MILLS.L II Tennessee Valley Authority 80/08/25 2pp
- 8009030367 Forwards RD 80-3 CALKOUN.J R Tennessee Valley Authority 80/08/27 1s
- ~~8009030373 RG 80-3 with reactor on Mode 4.both centrifugal charging pumps automatically started injecting 535 gallons of 20,000 ppm borated water at 193 F into RGS Gaused by incorrect softch manipulation during test performance
 4 Tennessee Valley Authority 80/08/27 lp
- 8009030517 Forwards LER 80-094/03L-0 CALHOUN.J R Tennessee Valley Authority 80/08/27 lp
- --8009030523 LER 80-094/03L-0 on 800620, w/unit in Modes 3.4 or 5. May 1980 evaluation for tritium was not performed Caused by inadequate description in procedure SI-415 for taking monthly samples while unit is in different modes GRIP EY. C.F. Tennessee Valley Authority 80/08/27 1p
- 8009070547 Forwards LER 80~060/03L-0 CALHOUN, J R Tennessee Valley Authority 80/08/28 lp
- --8007070590 LER 80-040/03L-0 on 800521, ERCW liquid effluent radiation monators were declared inoperable due to continuous, sporadic spiking Caused by contactor chattering on R-B emergency gas treatment sys room coular fan motor HEREFORD. J B Tennessee Valley Authority 80/08/28 ip
- BO09080354 Forwards EER 80-138/03L-0 CALHOUN, J R Tennessee Valley Authority 80/08/29 1p
- --B009090355 LTR B0-138/03L-0 on 80080i, during heavy thunderstorm cooling tower blowdown line effluent monitor declared snoperable Caused by nearby lightning strike or power line surge Damagad parts being repaired 2 bactup channel installed BMITHSON. J D. Tennessee Valley Authority 80/08/29 ip
- 8009090360 Forwards LCR 80-142/03L-0 CALHOUN, J R Fennessee Valley Authority 80/08/29 1p
- --8007080367 LER 80-142/03L-0 on 800/18, during testing w/unit in Mode 3, ice bed temp exceeded Tach Spec limit of 27 F Caused by insufficient recovery time between personnel entries & exits Work halted & temp reduced to 27 F.19 5-h later KIRK, OB Tennessee Valley Authority 80/09/02 1p
- 8009080373 Forwards LER 80-140/03L-0 CALHOUR, J R Tennessee Valley Authority 80/08/29 ip

- --8009080380 LER 80-140/03L-O on 800809, during preoperational test.dieselgenerator 86LOR relay zoils burned out following blackout initiation Caused by 86LOR relay being reset before blackout relays Coils replaced & relays reset ROMINE.D Tennessee Valley Authority 80/08/29 2pp
- 8009080382 Forwards LER 80-129/03L-0 CALKQUK, J R Tennessee Valley Authority 80/09/02 1p
- --8009080391 LER 80-129/03L-O on 800808, while operating in Mode 2 at 3 5% power, diesel generator 1A-A failed to start during simulated loss of power to 2A-A 6 9-kV shutdown board Caused by 437 (L) suitch being left in test position from previous test RECORD, D J Tennessee Valley Authority 80/09/02 2pp
- CALHOUN, J R Tennessee Valley Authority 80/09/02 1p
- --8009090583 LER 80-064/03X-1 on 80050B.w/reactor in Mode 4, all zones on ice condense engaged open door alarms Caused primarily by ineffective design of control rod missile shield seals Seals were redesigned fabricated & installed KIRA.9 B Tennessee Valley Authority 80/09/02 3pp
- 8009070531 Forwards LER 80-143/03L-0 CALHOUN, J R Tennessee Valley Authority 80/07/03 ip
- ~~8009070589 LER 80~143/03(_-0 on 800731.during preoperational test TVA 56.relay K609 was manually picked up & diesel operators 18-3.2A-A & 28-8 failed to start Cause unknown Generators were ratested & subsequently started on 800801 ROMINE Tennesses Valley Authority 80/09/03 lp
- E009120411 Forwards LER 80-149/03L-0 CALHOUN.J R Tennessee Valley Authority 80/09/04 ip
- ---8009120443 LER 80-149/03L-0 on 800807, during preoperational tests, turbine driven feedwater pump failed to maintain rated rpm Caused by overheated automatic governor Ventilation damper linkage repaired & governor controls replaced GELSTON, A H Tennossee Valley Authority 80/09/04 3pp
- 8009120412 Forwards LER 80-139/03L-0 CALHOUN, J R Tennessee Valley Authority 80/09/04 tp
- ---8007120440 LER 80-137/03L on 800807.during operation in Mode 2.8 train transfer switch for component cooling water pump supply tripped on three occasions Caused by thermal overload assembly Switches modified by defeating overload features KIRK.O B Tonnessee Valley Authority 80/09/04 2pp
- B009160325 Forwards LER 80-147/03L-0 CALHOUN, J R Tennessee Valley Authority 80/09/04 1p
- ~-8009160327 LER 80~147/03L-0 on 800807, during support & hanger insp.addl hanger not required by design analysis was found installed on containment spray giping Hanger was temporary & inadvertently left in place Hanger was removed SNEARINDEN.J D Tennessee Valley Authority 80/09/04 lp
- 800716G375 Forwards LER 80-145/03L-0 CALHOUN, J R Tennessee Valley Authority 80/09/04 1p
- --8009160380 LER 80-145/03L-0 on 800807, in mode 2 operation, cell 5t in diesel generator battery 18-0 shorted & failed, w/three addl cells already strapped out Cause not stated Diesel generator cells restored w/cells from diesel generator 28-8 ROMINE.D Tennessee Valley Authority 80/09/04 1p
- 8007160372 Second revised final deficiency rept re possible structural fallure of spent fuel pool gate during seismic event Problem to be corrected by administratively requiring gate to remain in storage location during normal plant aperations
 MILLS.L (1 Tennessee Valley Authority 80/09/08 Spp
- 8009160421 Forwards LER 80-146/03L-0 CALHOUN, J R Tennesses Valley Authority 80/09/08 1p
- --8009160425 LER 80-146/03L-0 on 800617, following post-maint testing of safety injection pump 18-8, one step of venting instructions not signed Caused by lack of immediate followup action to determine cause before entering mode 3 MILSON, G Tennessee Valley Authority 80/09/08 2pp
- 8009160390 Forwards LER 60-151/03L-0 CALHOUR: J R Tennessee Valley Authority 80/09/10 lp

- --E009160398 LER B0-151/03L-0 on 800811, turbine driven auxiliary faedwater pump failed to start after loss of both main feedwater pumps Caused by torque switch failure, causing valve FCV-1-51 motor operator to short GELSTON, A M. Tennessee Valley Authority 80/09/10 3pp
- 6009160406 Forwards LER 80-155/03L-0
 GALHOUNIJ R Tennessee Valley Authority 80/09/11 1p
- --8009160412 LER 80-155/03L-0 on 800813, w/unit in mode 3, remote shutdown manitoring channel L-68-312c was found inoperable Caused by flaw in plant operating procedures & unsealed transmitter leg was drained KIRK.O B Tennessee Valley Authority 80/09/11 ip
- BOO9160463 Forwards LER BO-152/03L-O CALMOUN J R Tennessee Valley Authority BO/09/11 ip
- --8009160468 LER 80-152/03L-0 on 800812 diesel generator battery IB-B cells 49-51 were found in discharged condition Caused by inadequate procedure Procedure has been changed & personnel reinstructed GELSTON, A.H. Tennessee Valley Authority 80/09/11 3pp
- 8009190471 Forwards LER 80-141/01T-0 CALHOUN, J R Tennessee Valley Authority 80/09/11 lp
- --80091905ti LER 80-141/01T-0 on 800829, while in Mode 5, pinhote leak was discovered in rod travel-housing latch housing interface seal weld on control rod drive mechanism C-11 Cause not stated Fault to be ground out & weld repaired WILLIAMS, W O Tennessee Valley Authority 80/09/11 ip
- 8009190540 Forwards LER 80-154/03L-0 CALHOUM R Tennessee Vallay Authority 80/09/12 ip
- --B009190547 LER 80-154/03L-0 on B00B15.auxiliary bidg vent radiation monitor B-RM-90-1018 did not respond to check source Caused by short in 24-volt power supply & detector preamplifier HEREFORD, J.M. Tennessee Valley Authority B0/09/12 1p
- BOC9230524 Special Rept 80-4 on 800623, unit received safety injection signal from high steam flow & lo-to Tave signal or lo steam generator pressure Approx 540 gallons borated water injected into RCS at 190 F Originally reported as 5,400 gallons * Tennessee Valley Authority 80/07/17 App
- BOO9230587 Forwards LER 80-084/01X-1 CALHOUN, J. R. Tennessee Valley Authority 80/09/18 1p
- --8007230574 LER 80-084/01X-1 on 800623 control room integrity breached Caused by removal of door C-49 & removal of tape used from door C-37 & C-50 in control room Door reinstalled Personnel reinstructed to insure doors are not removed KIRK, 0 B Tennessee Vailey Authority 80/09/18 2pp
- 8009230730 Forwards LER 80-077/03X-1 GALHQVM J P Tennessee Valley Authority 80/09/19 ip
- --8009230734 LER 80-077/03X-1 on 800525, during Mode 4.RHR containment sump recirculation valve FCV-63-73 would not open due to failure of FCV-74-21 to actuate limit switch Maint request made to adjust limit switch MiRK, 0 B Tennessee Valley Authority 80/09/19 2pp
- GOO9300451 Special Rept 80-5 on BOO804, fire detector XB-13-29F found to have thermal detector in place of ionization detector Caused by installation of wrong type of detector Correct detector installed Sys declared operable on BOO805 CALHOUNLY Representations of CALHOUNLY Representations of Representation of CALHOUNLY Representations of Representations of Representations of Representation of Representati
- T Hearing transcripts on non-antitrust matters
- 8DO9110332 Forwards full-power DL.slide presentation entitled, "NRC Staff Review of Sequoyah for Full Power Operation Commission Briefing.800821," transcript of NRC 800821 public matting & draft Suppl 2 to SER.NUREO-0011
 DENION.H R Office of Nuclear Reactor Regulation, Director 80/08/20 14pp
- --9009110341 Transcript of Commission 800821 public meating in Harbington,DC to discuss facility full-power license Pp 1-89 Commission 80/08/21 91pp

- 8009290021 Transcript of 800916 public meeting in Washington,DC rediscussion & vote on Commission program to review CL applications. AM session Pp 1-62
 AHEARNE, J F , GILINSKY, V , BRADFORD, P A Commission 80/09/16
- --8009290023 Forwards proposed modified license condition re hydrogen control measures
 AMEARKE, J. F. Commission 80/09/11 2pp
- --8009290026 Forwards proposed modified license candition re hydrogen control measures, as alternative to H Deaton 800903 proposal Hatter should be reviewed in early 1982 AUSTIN, J H Commission 83/09/09 2pp
- --B009250030 Forwards TVA summary sheets ie mill certification data pertaining to containment DENTON, H R Office of Nuclear Reactor Regulation, Director 80/07/15 20pp

- 8009120261 Submits info on degraded core training for operating employees, per NRC request Training completed for licensed reactor & senior reactor operators Presently conducting training for shift technical advisors CROSS, J.L. Tennessee Valley Authority 80/09/05 1p
- POCKET 50-328 SEQUDYAH NUCLEAR PLANT, UNIT 2

 Application/construction stage documents & correspondence
- 8009i10604 Requests review of R&D Associates rept. "Sequoyah Containment Analysis " Comments due by 80001 TEDESCO.R L Assistant Director for Licensing 80/07/29 2pp
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl M/o NUREO EISENHUT, D.G. Division of Licensing 80/08/01 119pp
- 8008210618 Discusses preliminary assessment of use of igniters as method of hydrogen control at facilities Assessment based on present understanding of util-proposed igniter scheme Exclusive use of igniters may not be prudent GARI,R A Brookhaven National Laboratory 80/08/08 3pp
- 8007120578 Responds to request for comments to Sequoyah containment Forwards info re stringer & skin interaction Concludes NRC calculations overestimated beneficial effect of stringers HU88ARD.H W R & D Associates 80/09/18 8pp
- BOG9040434 Forwards math re NRC review of ice condenser containment & hydrogen control measures for Sequoyah Nuclear Power Plant ACRS has scheduled meetings in Washington, DC on BOOB28, 0902 & 04 to discuss issue TEDEBCO
- --8009040443 "Hydrogen Control for Sequoyah Nuclear Plant, Units 1 & 2 "

 « Office of Nuclear Reactor Regulation, Director 80/08/13
 Bloa
- ---B009040450 Transcript of B00821 discussion of Bequoyah full power license in Washington, BC Pp 48-B9 4 Commission B0/08/21 47pp
- 8009150527 Forwards requests for addition on response to util 800814 1tr re safety analysis of interim distributed ignition sys SCHWENCER, A Licensing Branch 2 60/08/28 3pp
- 8009030436 Forwards Procedure IP-18. 'Plant Release Rate Calculations' & graphs of containment activity as function of monitor reading, in fulfillment of 800811 commitment to provide correlation procedure
 MILLS.L. M Tennessee Valley Authority 80/08/29 3pp
- --8009030438 "Plant Release Rate Calculations " ZOBEL.N. KITTS:R J , DILL,J Tennessee Valley Authority 80/08/21 48pp
- 8009240560 Forwards preliminary staff assessment re use of halon as hydrogen combustion control measure Items addressed include selection & design of halon delivery sys, chemical stability requirements reactivity & consequences of halon injection DENIGN.H R Office of Nuclear Reactor Regulation, Director 80/08/29 9pp

- --8009240564 Staff requirements meno re Commission 800814 meeting CHILK:S J Office of the Secretary of the Commission 80/08/18 1p
- 8009110349 Forwards proposed full-power OL. Supple 2 % 3 to SER & "Discussion of Environ Effects of U Fuel Cycle " Tests & safety review of proposal for distributed ignition sys expected to be completed by Jan 1981 DENION. H R Office of Nuclear Reactor Regulation, Director 80/09/03 18pp
- --B009110355 Draft Suppl 3 to SER

 # Dffice of Nuclear Reactor Pegulation, Director NURE0-0011 63
 60/09/30 75pp
- --8009110358 "Discussion of Environ Effects of U Fuel Cycle "

 Office of Nuclear Reactor Regulation, Director 80/09/30
 9200
- --8009110360 Suppl 2 to SER + Office of Nuclear Reactor Regulation, Director NUREO-0011 92 89/08/31 180pp Available at CPO 75 50
- 8009080259 Forwards description of facility ice condenser insulation matte & containment wall insulation structural design & insulation flammability review results

 CROSS.J L. Tennessee Valley Authority 80/09/04 llpp
- 8009090370 Forwards additinfo on temp control for main steam valve rooms in response to NRC request Info revises util 800729 ltr
- CROSS.J & Tennessee Valley Authority 80/09/04 2pp
- 8009300294 Forward Chilk 800818 memo to Dircks re briefing on hydrogen control in Sequoyah containment DENTON, H R Office of Nuclear Reactor Regulation, Birector 80/09/10 1p
- 8009190476 Forwards info re matl test repts for critical section of containment steel Mill test rept on critical section will be submitted by 800915
 MILLS.L M Tennessee Valley Authority 80/09/12 4pp
- 8009170297 Forwards mill test rept re critical section of containment steel in facility Matl suppls 800912 submittal which summarizes assessments of containment to withstand internal pressures Oversize drawings available in Central Files only MILLS, L. M. Tannessee Valley Authorsty 80/09/15 10pp
- 8009290333 Forwards Revision 3 of response to NUREO-0578.TM1-2 Lessons Learned Task Force status repl & short-term recommendations, Items 2 1 6a Revision 3 changes procedures description for reducing & quantifying leakage from liquid sys MILLS.L M Fennessee Valley Authority 80/09/22 lp
- 8009300400 Forwards technical questions re implementation of interim policy on IOCFR50 & 51 MILLS.L. M Fernessee Valley Authority 80/09/23 3pp
- E NRC Safety Evaluation Report (SER), supplie & correspondence
- 80090804(9 Forwards Suppl 2 to SER (NUREG-0011) 8CHWENCER,A Licensing Branch 2 80/09/04 2pg
- --8009080423 SER for facility

 » Office of Nuclear Reactor Regulation, Director NUREO-0011 S2
 80/98/31 175pp Available at RFIS \$9.50
- 8009260254 Forwards Suppl 3 to SER for facility SCHMENCER, A Licensing Branch 2 80/09/16 2pp
- --8009260258 SER for facility.Suppl 3
 * Office of Nuclear Reactor Regulation. Director NURE0-0011 83
 80/09/30 82pp Available at NTJS \$4 00
- F Security, medical, emergency & fire protection plans
- 8009230267 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Bys installed for govt use during emergency O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/22 in
- 8009230333 Forwards physical security plan.Revision 6A Revision withhald (ref 100FR2 790) MILLS.L M Tennessee Vailey Authority 60/09/17 ip

- H General correspondence
- 8009ii0387 Commends Commissioners for denying facility full-power license until hydrogen buildup issue has been resolved beyond any doubt No compromise too expensive for prevention of another near-devastating event such as TMI CALDWELL,M A Affiliation Unknown 80/09/08 ip
- 8009120301 Responds to 800703 ltr requesting NRC comment on K Spailone 800619 ltr re-potential impact of dam failure of Pond Hiii Reservoir which util is considering for future const FES scheduled for completion in Dec 1980 DIRCKS.WJ Office of the Executive Director for Operations 80/09/08 ip
- --8009120317 Requests NRC response to encl K Spailone 800619 ltr repotential impacts of Pond Hill Reservoir const & operation within 2 wks of receipt of request SCHMEIKERIR 8 Senate 80/07/03 2pp
- I Financial information
- 8009090543 Forwards Annual Financial Rept 1979 CROSS.J L Tennessee Valley Authority 80/09/04 1p
- --8009090563 Annual Financial Rept 1979
 * Tennessee Valley Authority 80/09/04 44pp
- K Utility Final Bafety Analysis Report (FSAR) & amonds
- 8007030560 Forwards affidavit certifying that Amends 66 & 67 to FSAR were mailed to D Hoore, JE Hagan & BA Osborne on 800826 MILLS, L K Tennessee Valley Authority 80/08/26 2pp
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8009190766 Discusses 243rd ACRS meeting on 800710-12 re Sequoyah review & research program FYB2 budget PLEBSET,M S ACRS - Advisory Committee on Reactor Bafeguards 80/07/18 3pp
- BOD91600B3 Natice of ACRS Subcommittee on Structural Engineering G00902 meeting in Washington.DC to establish max internal pressure Bequoyah containment can withstand HOYLE, J C Office of the Secretary of the Commission B0/08/13
- 8009030394 Transcript of ACRS Subcommittee on Structural Engineering 800902 hearing in Washington.DC re establishing max external pressure temp that Sequoyah containment structure can withstand

 * ACRS Advisory Committee on Reactor Safeguards 80/09/02 18200
- BOOP180172 Forwards agendas for ACRS 800902 subcommittee meeting & 800904 full committee meeting re facilities TEDESCO,R L. Assistant Director for Licensing 80/09/02 4pp
- BO0915023B Responds to request for comments on questions contained in V 011insty BO0B07 Itr re facility ice condenser containments Facility is capable of sustaining pressure of at least 45 paig w/o structural failure PLESSET.H B ACRS Advisory Committee on Reactor Safeguards B0/09/08 3pp
- 8009300329 Forwards ACRS 800908 itr to J Ahearne re ice condenser containments BCHMENCER.A Licensing Branch 2 80/09/18 2pp
- P Operating license stage documents & correspondence
- 8007230547 Proposes alternate replacement schedule for turbocharger drive gear assemblies mfg by General Motors Util will limit turbocharger operation to less than 200-h MILLS,L it Tennessee Valley Authority 80/07/17 2pp
- Q Inspection reports, iE Bulletine & correspondence
- 8009100063 Forwards IE Builetin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Escondary Side High Energy Line Rupture " No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director. 80/07/24

- 8009020214 Forwards response to IE Bulletin 79-03A No SA-312 & A-312. Type 300 series fuslon welded pipe used or planned for use in safety-pelated sys at greater than 85% dealgn stress except Matts Bar Matl under Investigation at Matts Bar HittS.L M Tennessee Valley Authority 80/08/05 2pp
- 8007090802 Responds to IE Builetin 79-03A, "Longitudinal Weld Defects in ASKE 8A-312. Type 304 Stainless Steel Pipe" Use of matls still under investigation for sys supplied by NSSS vendor MILLS.L II Tennessee Valley Authority 80/08/05 2pp
- 8009020303 Forwards IE lnsp Repts 50-327/80-24,50-328/80-15, 50-390/80-20,50-391/80-14,50-438/80-13,50-439/80-13, 50-518/80-11,50-519/80-11,50-550-11,50-521/80-11, 50-553/80-11,80-554/80-10,50-566/80-10 & 50-567/80-10 0'REILLY,J P Reglon 2, Atlanta, Office of the Director 80/08/08 200
- ---B009020312 Notice of violation from insp on 800707-11 * Region 2. Atlanta: Office of the Director 80/00 80/08/06 4pp
- --8007020337 IE Insp Repts 50-327/80-24,50-328/80-15,50-390/80-20, 50-371/80-14,50-438/80-13,50-437/80-13,30-318/80-11, 50-517/80-11,50-522/80-11,50-553/80-11,50-554/80-10,50-564/80-10,50-564/80-10,50-564/80-10 & 50-567/80-10 on 800707-11 BROWNLEE,V L , MODENUS,L Region 2, Atlanta, Office of the Director CUNLON,T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/06 24pp
- 8009170161 Forwards IE Insp Rept 50-328/80-14 on 800708-11 No noncompliance noted MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 60/08/06 2pp
- --8009170163 IE insp Rept 50-328/80-14 on 800708-11 No noncompliance noted Major areas inspected preservice & inservice insp program HERDY.A R , ZAJAC.L D Region 2, Atlanta, Office of the Director 80/08/04 4pp
- 8009030146 Forwards Revision 1 to IE Bulletin 80-19, "Fallures of Mercury-Wetted Matrix Relays In Reactor Protective Sys of Operating Muclear Power Plants Designed by C-E " Written response required O'REJLLY, J P Region 2, Atlanta, Office of the Director 80/08/15
- 8009660193 Forwards IE Circular 80-18, "10CFR30 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/08/22
- BOO9120340 Forwards IE Info Notice BO-31, "Maloperation of Gould-Brown Boveri 480 Volt Typo K-6005 ? K-DON 6005 Circuit Breakers " No written response regulated O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/27
- 8009240454 Forwards response to 16 Bulletin 80-16 re potential disapplication of Rosemount pressure transmitters No corrective action required due to results of evaluation that indicated impossibility of anomaious output MILLS.L & Tennessee Valley Authority 80/08/29 2pp
- 8009120379 Responds to IE Bulletin 80-19 re failures of marcury-wetted matrix relays in reactor protective sys Relays identified are not used in facility Forty manhours expended for review MILLEL M Tennesses Valley Authority 80/09/94 ip
- 8009260375 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required
 O'REILLY, J P Region 2, Atlanta, Office of the Director 60/09/10
- A Periodic operating reports & related correspondence
- BOO9030397 Discharge monitoring rept for 800501-0601 EL-ASKRY, M T , STEINER, G R Tennessee Valley Authority BO/08/08 B7pp
- S Reportable occurrences, LERs & related correspondence
- 8009040486 Becond interia deficiency rept re defective reactor vessel upper internals guide tube support pins TVA & Westinghouse replacing pins. Next rept will be submitted by 8009fi HILLS, L M Tennessee Valley Authority 80/07/24 ip.

- 8009100537 Final deficiency rept re control rod drop events Operating procedures to be revised per Westinghouse instructions Procedural change will be made prior to greater than 90% power level ascension & will prevent power overshoot MILLS.L M Tennessee Valley Authority 80/08/05 2pp
- 8009100236 First interim deficiency rept re evaluation of sensing line connections to process piping Reanalysis of process piping will be completed by end of Sept Next rept will be submitted by 801017 MILLS, L M Tennessee Valley Authority 80/08/07 2pp
- 8007100284 Final interim deficiency rept re spray header attachment lug re-evaluation Lug attachments for containment spray be RMM sys headers not properly evaluated when supports reanalysed for steel containment vessel dynamic movements MILLS.L B Tennessee Valley Authority 80/08/07 2pp
- 8008190463 Final deficiency rept re hydrogen detection sys integrity Util has ordered mod kits & anticipates that installation will be completed by 801205 MILLS.L K Tennessee Valley Authorlty 80/08/13 2pp
- 8007100576 Final deficiency rept re hydrogen detection sys integrity
 Pump diaphragm rupture could result in sys integrity breach,
 affecting plant safety Sample pump field mod kit being
 provided by Comsip. Inc installation anticipated by 801205
 MILLS,L M Tennessee Valley Authority 80/08/13 2pp
- 8009100496 Revised final deficiency rept re incorrect valve weights in upper head injection sys Addi valves w/erroneous weights ilsted Piping sys load analyses were rerun using correct weights
 MILLS,L M Tennessee Valley Authority 80/09/02 3pp
- 6009100459 Final rept re deficiencies in installed plpe hangers & discharge piping in essential raw cooling water pumping station Gaused by errors in design drawings & embedded pipes extending past location requirements
 MILLS.L M Tennessee Valley Authority 80/07/04 2pp
- 8009110320 Second interim deficiency rept re design criteria for secondary side pipe breaks Util completed analysis of pipe rupture interaction Protective devices will be added or piping will be rerouted Will submit next rept by 801028 MILLS.L M Tennessee Valley Authority 80/09/04 lp
- 8009160372 Becond revised final deficiency rept re possible structural fallure of spent fuel pool gate during seismic event Problem to be corrected by administratively requiring gate to remain in storage location during normal plant operations
 MILLB.L M Tennassee Valley Authority 80/09/08 3pp
- 8009160326 Third interim deficiency rept re defective reactor vessel upper internals guide tube support pins Hestinghouse evaluation of guide tube pins being reviewed Replacement of pins underway Next rept will be submitted by 801215 MILLS-L M Tonnessee Valley Authority 80/09/10 lp
- 8009160328 Third interim deficiency rept re unviron qualification of Class IC Instruments in valve room Six steam generator pressure transmitters replaced Pressure suitches for flow to Auxiliary feed pump repaired MILLS.L M Tennessee Valley Authority 80/09/12
- 8009290332 Third Interim deficiency rept re environ qualification of Class IE equipment Status of MCRs encl Environmentally qualified switches were installed Soleroid valves will be replaced Next rept will be submitted by 801121 KILLS.L M. Tennessee Valley Authority 80/09/19 2pp
- B009290350 First interim deficiency rept re safety Injection systrain B flow defect flow tests continuing Similar defect reported at Matts Bar i Watts Bar flow test rescheduled for B01031 Next rept will be submitted by 801023 MILLS, L M Tennessee Valley Authority 80/09/22 2pp
- 8009300395 Fourth interim deficiency rept re upper head injection hydraulic isolation valve accomplator weighing sys Util will delay design changes proposed by Westinghouse until further testing completed MILLS, L M Tennessee Valley Authority 80/09/25 lp Tennessee Valley Authority 80/09/25 lp
- G007300467 Final deficiency rept re seismic qualification of auxiliary feedwater pump recirculation line Caused by use of Improper design category Line to be reclassified & required seismic supports added prior to Unit 2 fuel load MILLS, L N Tennessee Valley Authority 80/09/25 2pp

T Hearing transcripts on non-antitrust matters

- GOOGROOD Trenstript of 600916 public meeting in Washington.DC rediscussion & vote on Commission program to review OL applications.AM session Pp 1-62
 AMEARNE.JF. GILINSKY.V. BRADFORD.PA Commission 60/09/16-65pp
- --8009290023 Forwards proposed modified license condition re hydrogen control measures
 AMEARNE.J F Commission 80/09/11 2pp
- --8009270026 Forwards proposed modified license condition re hydrogen control measures, as altornative to H Denton 800903 proposal flator should be reviewed in early 1982 AUSTIN J H Commission 80/09/09 2pp

V Operator Examinations

B009120261 Submits info on degraded core training for operating employees, por NRC request Training completed for licensed reactor & senior reactor operators Presently conducting training for shift technical advisors CROSS.J L Tannessee Valley Authority 80/09/05 1p

DOCKET 50-329 MIDLAND PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities! Corments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/o NUREO EISENHUT.D C Division of Licensing 80/08/01 119pp
- 8009020173 Provides satisfactory review of enci Army Corps of Engineers Itr rept re geotechnical engineering review Requests rept be submitted to util for response LEAR: 0 Hydrologic & Contechnical Engineering Branch 80/08/05
- GOO9020179 Gobwits ltr rept re completion of Subtask 1 re geotechnical engineering review Identifies unresolved issues & suggests course of action Guppl encl MCCALLIGIER.P Army.Dept of. Office of Surgeon General 80/07/07
- 8007020165 Ack receipt of 800724 ltr from UH Cook transmitting rept on reactor pressure vessel support mod FIGRELLIG Region 3. Chicago. Reactor Construction & Engineering Support Branch 80708/11 ip
- 8009100005 Notification to B00822 meeting u/util in Bethesda. MD to clarify & suppl info to const completion schedule H00D, B Operating Reacturs Branch 3 80/08/21 5pp
- 8007120199 Requests add1 info re permanent devatering sys proposed for site per Hydrologic & Geotochnical Engineering Branch review TEDESCOUR L Assistant Director for Licensing 80/08/27 lipp
- 8009090397 Forwards response to ARC 800421 info request re Category (masoury ualls Oversize drawings available in Central Files only CDGK, J W. Consumers Power Co. 80/09/03 lipp
- BOOTOTOTO Forwards description of nuclear operations & facility mgt organizational changes Revisions will be submitted to incorporate changes to OA program policies MOFFRAN. O P Consumers Power Co BO/09/05 4pp
- ---8007070511 "Nuclear Svcs Dept." & "GA Nuclear Operations "

 * Consumers Power Co 80/09/05 2pp
- 8009:70259 Amend Bi to application for CPs & DLs.including discussion of applicants position on need for add1 borings, settlement update & Revision 9 to response to NRC requests re plant fill. originally referenced by Amend 72 CDCK, J W Consumers Power Co 80/09/82 230pp
 - 0727036B Forwards B&W Rept 86-1120839-00, "Evaluation of Instrumentation to Detect Inadequate Core Cooling Prepared For 17/ Dwners Group " 'OCH.J W Consumers Power Co 80/07/12 lp

- --8009290373 "Evaluation of Instrumentation to Detect Inadequate Core Cooling Prepared For 177 Owners Group " FROTH D J Babouck & Wilcox Co 86-1120838-00 90/08/15 22pp
- 8009220238 Forwards response to NRC 781011 & 1222 ltrs requesting add1 info for review of application for DLs COOK.J R Consumers Power Ca 80/09/19 1p
- --8009220242 "Rept of Archaeological Matagation & Avoidance on CPC Right-of-Way in Saginaw & Midland Counties MI " OZKER.D., TAGGART.D.W. Machigan, Univ. of 80/02/18 200pp
- --8009220247 "Terrestrial Ecological Survey for Midland Nuclear Plant Tittabauassee Substation to Gary Road Substation 345 kV Transmission Right-of-May," final rept * Apteck Engineering Services 79/11/30 200pp
- 8009230550 Forwards Amend 82 to CP & OL application & Revision 11 to environ rept COURT, W Consumers Power Co. 80/09/15 in
- --8007230559 Amend 82 to application for OLs & CPs * Consumers Power Co. 80/07/15 ip
- --8009230552 Revision II to environ rept
 * Consumers Power Co. 80/09/30 100cc
- 8009230707 Submits corrections to 8007il ltr re cracked steam generator manway studs at Oconee 3 TAYLORJ H Babcock & Wilcox Co 80/09/15 lp
- 8009300332 Summary of 800825 meeting w/util in Bethesda,MD re potential timing & methods for resuming formal docket review of DL application HODD-D S Licensing Branch 3 80/07/16 App
- 8009300309 Requests addl info re reactor pressure vassel support mods TEDESCO.R L Assistant Director for Licensing 80/09/19 3pp
- 8009300507 Forwards affidavit acknowledging distribution of Amend 82 to CP & CL application.Revision 11 to environ rept CQCK.J W Consumers Power Co 80/09/22 4pp
- C Utility Environmental Report (ER), amends & correspondence
- 8009230550 Forwards Amend 82 to CP & QL application & Revision 11 to environ rept CODK. J W Consumers Power Co 80/09/15 lp
- 8009300507 Forwards affidavit acknowledging distribution of Amend 62 to CP & OL application.Revision 11 to environ rept COOK.J W Consumers Power Co 80/09/22 App
- F Security, medical, emergency & fire protection plans
- 8008080797 Forwards "Evacuation Clear-Time Estimates for Areas Near Midland.MI Nuclear Power Plant," in response to NRC 791226 & 800702 ltrs COOK.J N Consumers Power Co 80/07/31 2pp
- ---G0080B0302 "Evacuation Clear-Time Estimates for Areas Near Midland.HI Nuclear Power Plant " Oversize drawings encl * HMM Associates.Inc 80-059 80/07/31 112pp
- 8009100924 Transmits emergency planning info to be made available to public at LPDR in Midland.MI W/o encl SQUOER.J L Public Document Branch 80/08/27 lp
- G Adjudicatory correspondence
- BCO9050354 Advises of withdrawal as atty for WH Marshall Requests that firm name be removed from roster % that all parties be notified MERRITT. O J Thompson, Nielson, KlaverKamp & James 80/08/13 299
- 8009050423 Contention alleging that Class 9 accident will cause massive flow of radioactive matis into Saginaw Bay river which-provides drinking water to area Urges full disclosure per NEPA MARSHALL, W.H. Mapleton Intervenors 80/08/27 2pp

- E007020429 Response in support of B Stamiris amended petition to intrivene re Contention 4 on OA Urges amend of Contentions 1.2.3 & 6 Contentions 5 re differential soil settlement must not be accepted w/o amend W/Certificate of Svc PATON.U D Hearing Branch 4 80/08/29 iipp
- BO07020440 Response in support of SK Warren BO0B14 amended petition to intervene re Contentions 1 & 3 on fill soil composition & dewatering procedures Contentions 2 & 4 re seepage & preloading should be amended Certificate of Svc encl JOMES.8 W Hearing Branch 2 80/08/29 9pp
- 8007030718 Response to SK Warren 800814 suppl & B Stamiris amend to patitions to intervene Opposes Warren Contentions 2 & Stamiris Contentions 1.2.3 & 5 Urges rephrasing of Stamiris Contention 4 re QA Certificate of Svc encl FARNELL.A B Consumers Power Co FARNELL.A S Isham, Lincoin & Seale 80/08/30 ilpp
- BO092A0C01 Suppl to SK Warren patition to intervene & amended suppl to B Stamuris petition to intervene Alleges inadequacy of germanent dewatering procedures & CPC financial pressures adversely affecting resolution of soil settlement issues WARREN, S K, STAMIRIS, B Affiliation Unknown 80/09/09 8pp
- BOO9160397 Forwards util answer to notice of hearing W/o encl FARNELL, A S Isham. Lincoln & Beale 80/09/ii ip
- 6009190420 Notice of appearance in proceeding Certificate of Svc encl BRUNNER, J E Consumers Power Co 80/09/11 3pp
- 8009250034 Notice of reconstitution of ASLB due to IW Smith schedule conflict C Beckhoefer appointed chairman LAZO.R H Atomic Safety and Licensing Board Panel 80/09/19 ip
- 8009300023 Notice of 801007-09 depositions of D Hood, L Helier & J Kame of NRC & 801013,15 & 16 depositions of JW Simpson, W Lawhead & R Erickson of Corps of Engineers:re Stamiris & Warren contentions Certificate of Byc enci FARMELL, A S Consumers Pawer Co FARMELL, A S Isham, Lincoin & Bale 80/09/22 9pp
- ©009250004 Advises that, in response to 800920 mailgram, future transcripts will be mailed to 8 Gadler PATON, H D Hearing Branch 4 80/09/23 ip
- 8009290039 Responds to GA Linenberger 800910 inquiry re NRC conclusion on Page 3 of 790906 order modifying CPs Bafety issues in question are associated w/remedial action correcting soil deficienties Hearing Branch 4 80/09/24 3pp PATON, W. D.

H General correspondence

- 8007110280 Responds to 800728 ltr requesting info re safety of Midland & Fermi plants All nuclear plants subj to enhanced safety requirements resulting from TMI Lessons Learned Task Force recommendations Supporting documentation encl DIRCKS.W J Office of the Executive Director for Operations 80/08/26 24pp
- --8007110288 Requests consideration of encl MC Haight ltr re safety of Kidland & Fermi plants ERDOMFIELD.W S House of Rep , Foreign Affairs 80/07/28 2pp
- BOG9070040 Responds to 800507 itr to President Cartor re safety, cost & need for facilities NRC issued order on 791206 prohibiting soil const activities pending CP amend Bludy shows two-unit plant will provide electric power at lowest cost EISENHUT, D 0 Division of Licensing 80/08/27 10pp.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- BOO919021B Forwards portion of Amend 8i to FSAR. "Discussion of Applicant Position on Need for Addl Borings for Midland Plant Units i & 2 " Discussion attempts to document presentations & new math introduced at 800829 meeting w/NRC GOOK, J H Consumers Power Co 80/09/16 Spp

- --8009190221 Portion of Amend 84 to FSAR entitled. "Discussion of Applicant Position on Need for Addl Borings for Midland Plant Units : 5 2 "
 Consumers Power Co 80/09/14 44pp
- G Inspection reports: IE Bulletins & correspondence
- 8009150194 Forwards IE Insp Repts 50-329/80-20 & 50-330/80-21 on 800708-10 & notice of violation FIGRELLI.6 Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/07/18 2pp Support Branch
- --8009;50197 Notice of violation from insp on 800708-10 4 Region 3, Chicago, Office of the Director 80/0 80/07/18 io
- --8009150203 IE Insp Repts 50-329/80-20 & 50-330/80-21 on 800708-10 Noncompliance noted failure to specify applicable code in purchase order DANIELSON,D H Region 3, Chicago, Reacter Construction & Engineering Support Branch LCE,E W K Region 3, Chicago, Office of the Director 80/07/18 App
- 8009180231 Forwards IE Insp Repts 50-329/80-22 & 50-339/80-23 on 800701-31 No noncompliance moted FIGRELLI.0 Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/08/07 2pp
- --8009180240 IE Insp Repts 50-329/80-22 & 50-330/80-23 on 800/01 31 No noncompliance noted Major areas inspected detensioning of reactor hold down bolts, const activities of Zack Co & caseload forecasting KNDP.R C . CODK.R J Region 3. Chicago, Office of the Director 80/08/05 5pp
- 8009230:10 Responds to IF Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Circumstances addressed not considered problematical because NDE performed required by applicable codes COOK, J W Consumers Power Co 80/08/14 11pp
- 8009030226 Forwards Revision i to 1E Bulletin 80-17. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER, J O Reg Region 3. Chicago, Office of the Director 80/08/15
- 8009260410 Forward+ IE Insp Repts 50-327/80-13 & 50-330/80-14 on 800227-29,0305-06,0312-13 & 20.0418 & 0502 & natice of WEPPLER, J O Region 3, Chicago, Office of the Director (00/08/18)
- --809260413 Notice of violation from insp on 800227-29,0309-06,0312-13 t 20.0418 t 0502 * Region 3, Chicago, Office of the Director 80/08/1J 3pp
- --8009260415 IE Insp Regts 30-327/80-13 & 50-330/80-14 on 800227-29, 0305-06, 0312-13 & 20,0418 & 0502 Noncompliance noted inadequate procurement document control special processes control & purchase math.equipment & svc control FOSTER, J E , ERB.C M , NORELIUS.C E Region 3, Chicago, Office of the Director 80/08/13 23pp
- 8009170418 Forwards IE Circular 80-10, "10CFRSO 99 Bafety Evaluations for Changes to Radwaste Treatment Bys " No written response required

 KEPPLER. J O Region 3. Chicago, Office of the Director RO/08/22
- 8009160248 Forwards IE Insp Repts 50-327/80-17 & 50-330/80-18 on 800617-18 & 0722 & 0812-13 No noncompliance noted FIGRELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/27 2pp
- --8009160249 lE Insp Repts 50-329/80-17 & 50-330/80-18 on 800617-18,0722 & 0812-13 No noncompliance noted Major areas inspected preservice inspected preservice inspectations, work activities, nondestructive examination, personnel certification & data WARD.K D Region 3, Chicago. Office of the Director DANIELSON.D H Region 3, Chicago. Reactor Construction & Engineering Support Dranch 80/08/25, App
- 8009230071 Forwards 1E Info Notice 80-3i, "Malaperation of Could-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers" No written response required KEPPLER. J G Region 3. Chicago, Office of the Director 80/08/28

- 8009170227 Forwards NRC positions & requests for add1 info to IE Bulletins 79-21 & 80-06 re temp effects on level measurements & engineered safety feature reset controls Info needed for NRC review of OL applications TEDESCO,R L Assistant Director for Licensing 80/09/04 i2pp
- 6009240129 Forwards IE Circular 80-21. "Regulation of Refueling Crews " Na written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 60/09/10
- 8009290472 Ack receipt of 800825 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-329/80-20 & 50-330/80-21 FIORELLIO Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/10 ip
- --8009290475 Responds to NRC 800710 ltr re violations noted in iE insp Repts 59-329/80-20 & 50-330/80-21 Corrective actions audit of weld filler matis procurement initiated & fabrication conditions qualified COOK, J N Consumers Power Co 80/08/25 App
- R Periodic operating reports & related correspondence
- 8009040295 Forwards Bechtel nonconformance repts & log sheets.Bechtei quality action requests.B&W nonconformity repts.B&W inservice insp nonconformance repts.util nonconformance, audit finding & correction repts COOK.J W Consumers Power Co 80/08/21 300pp
- S Reportable occurrences, LERs & related correspondence
- 800Bi906D5 Interim deficiency rept re inconsistent cross-referencing between B&W & Bechtei numbering sys affecting instrument sys Instrument index & electrical schemes under revision for application of appropriate cross-reds CDOX.J W Consumers Power Co 80/08/i3 3pp
- 8007030654 Ack receipt of 800731 interim deficiency rept re safe shutdown boration capability FIGRELLIO Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/08/14 Ip
- 8009030657 Ack receipt of 800801 interim deficiency rept re reactor vessel broken anchor bolt FIDRELLI.O Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/08/14 ip
- 8009:00264 Ack receipt of 800813 interim rapt re NSSS component nvisure⇔ ack receipt of BOUBI3 interim rept re NSSS component identification FIORELLI,O Region 3, Chicago, Reactor Construction & Engineering Support Branch BO/08/28 ip
- 8009230275 interim rept re containment internal structures coating deficiency Substantial progress made in isolating factors contributing to delamination condition k in formulating corrective action program Next rept by 801103 CODK.J N Consumers Power Co 80/09/09 1p.
- 8009250268 Interim Deficiency Rept 9 re component quelification test decumentation Nonconformance Repts 1789,1795,1796,2659 & 2664 have been dispositioned & quality test review for mati requisition has been closed Next rept issued by 801205 CBGK, J W Consumers Power Co E0/09/19 64pp
- 8009250284 Deficiency rept we HELBA restraint design Steady state rather than peak thrust forces were used in design of G-listed pape whip restraints investigation & identification of root cause recommended Another rept due by 801201 COOK. J. N Consumers Power Go 60/09/19 App
- 8009290360 Deficiency rept re high energy line break analysis of pipe whip restraint designs Caused by misinterpretation of BN-TOP-2 Affected restraints re-evaluated Next rept by 801121 COOK, J W Consumers Power Co 80/09/19, App.
- T Hearing transcripts on non-antitrust matters
- 8009160499 Transcript of 800910 prehearing conference in Midland.MI Pp 234-408

 A Atomic Safety and Licensing Board Panel ISSVANCES OL 80/09/10
- 176pp

- DOCKET 50-330 MIDLAND PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- BOOQOBO'30 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl M/a NUREG EISENHUT,D O Division of Licensing 80/08/01 119pp
- B009020173 Provides satisfactory review of encl Army Corps of Engineers ltr rept re geotechnical engineering review Requests rept be submitted to util for response LEAR,0 Hydrologic & Geotechnical Engineering Brench B0/08/05
- 8009020179 Submits ltr rept re completion of Subtask 1 re geotechnical engineering review Identifies unresolved issues & suggests course of action Suppl enc!

 MCCALLISTER:P Army, Dept of, Office of Burgeon General 80/07/07
- 8007020i65 Ack receipt of 800724 itr from JW Cook transmitting rapt on reactor pressure vessel support mod FIORELLIO Region 3. Chicago Reactor Construction & Engineering Support Branch 80/08/11 ip
- 8009100005 Natification fo 800822 meeting w/util in Bethesda.MD to clarify & suppl info re const completion schedule HDDD,D Operating Roactors Branch 3 80/08/21 5pp
- 8007i20i77 Requests addi info re permanent dewatering sys proposed for site per Hydrologic & Oeotechnical Engineering Branch review TEDEBCD.R L Assistant Director for Licensing 80/08/27 lipp
- B007090397 Forwards response to NRC 800421 info request re Category I masonry walls Oversize drawings evaluable in Central Files only COCK.J W Consumers Power Co E0/07/03 11pp
- 8007070500 Forwards description of nuclear operations & facility mgt organizational changes Revisions will be submitted to incorporate changes to QA program policies HQFFMAN-Q P Consumers Power Co 80/09/05 4pp
- --B0090905ii "Nuclear Sycs Dopt," & "GA Nuclear Operations "
 # Consumers Power Co 80/09/05 2pp
- 8009:70299 Amend Bi to application for CPs & DLs.including discussion of applicants position on need for addl borings, settlement update & Revision 9 to response to NRC requests re plant fill.originally referenced by Amend 72 COOK.J W Consumers Power Co 80/09/12 230pp
- 8007270368 Forwards B&N Rept 86-1120838-00, "Evaluation of Instrumentation to Detect Inadequate Core Gooling Prepared For 177 Cuners Oroup " CODK,J W Consumers Power Co 80/07/12 ip
- ---8009290373 "Evaluation of Instrumentation to Detact Inadequate Core Cooling Prepared For 177 Owners Group " FROTH:D J Babcock & Wilcox Co 86-1120838-00 80/08/15 22pp
- 8009220238 Farwards response to NRC 78:011 & 1222 ltrs requesting addi info for review of application for QLs COOK.J W Consumers Power Co 80/09/15 1p
- --8009220242 "Rept of Archaeological Mitigation & Avoidance on CPC Right-of-Way in Saginaw & Midland Counties,MI " OZKER,D , TAGGART,D W Michigan, Univ of 80/02/18 200pp.
- --8009220247 "Terrostrial Ecological Survey for Midland Nuclear Plant Tittabawasses Substation to Gary Road Substation 345 kV Transmission Right-of-Way." final rept 4 Aptoch Engineering Services 79/11/30 200pp
- 8009230550 Forwards Amend 82 to CP \$ OL application & Revision 11 to environ rept
 COOK, J H Consumers Power Co 80/09/15 ip
- --8009230559 Amend 82 to application for OLs & GPs + Consumers Power Co 80/09/i5 1p
- 8009230707 Submits corrections to 800711 ltr re cracked steam generator manway study at Ocones 3 TAYLOR, J H Babcock & Wilcox Co 80/09/15 1p

- goo9300332 Summary of B00825 meeting w/util in Bethesda MD re potential timing & methods for resuming formal docket review of OL application MOOD D S Licensing Branch 3 80/09/16 6pp
- 8009300307 Requests addl info re reactor pressure vessel support mods TEDESCO.R L. Assistant Director for Licensing 80/09/17 3pp
- 8009300507 Forwards affidavit acknowledging distribution of Amend 82 to CP & CL application, Revision 11 to environ rept COCK. J H Consumers Power Co 80/09/22 4pp
- C Utility Environmental Report (ER), amends & correspondence
- 8309230550 Forwards Amend 82 to CP & CL application & Revision ii to environ rept CDG&J W Consumers Power Co 80/09/15 ip
- --8009230542 Revision 11 to environ rept * Consumers Power Co 80/09/30 100pp
- F Security, medical, emergency & fire protection plans
- BOOBOB0297 Forwards "Evacuation Clear-Time Estimates for Areas Near Midland, MI Nuclear Power Plant." in response to NRC 791226 & BOO702 ltrs CODM.J W Consumers Power Co 80/07/31 2pp
- --8009080302 "Evacuation Clear-Time Estimates for Areas Near Midland.MI Nuclear Power Plant " Oversize drawings succi # HMM Associates, Inc. 80-059 80/07/31 112pp
- 8009100724 Transmits emergency planning info to be made available to public at LPDR in Midland,MI W/o encl SOUDER,J L Public Document Branch 80/08/27 ip
- 9. Adjudicatory correspondence
- BOOTO70304 Advises of withdrawal as atty for NH Marshall Requests that firm name be removed from roster & that all parties be notified HERRITT.O J Thompson, Nielson, KlaverKamp & James BO/08/13 2pp
- 8009090423 Contention alleging that Class 9 accident will cause massive flow of radioactive matls into Saginaw Bay river which provides drinking water to area Urges full disclosure per NEPA MARSHALL.U H Mapleton Intervenors 80/08/27 2pp
- 60C9020429 Response in support of B Staminis amended petition to intervene re Contention 4 on QA Urges amend of Contentions 1.2.3 & 6 Contentions 5 re differential soil settlement must not be accepted w/o amend W/Certificate of Svc PATON.W D Rearing Branch 4 60/08/29 11pp.
- ECOPO20440 Response in support of SK Marren 800814 amended petition to intervene re Contentions 1 & 3 on fill soil composition & devatering procedures Contentions 2 & 4 re seepage & preloading should be amended Certificate of Svc encl. JUNES.8 W Hearing Branch 2 80/08/29 7pp
- 8009030718 Response to SK Warren 800814 suppl & 8 Stamiris amend to petitions to intervene Opposes Warren Contentions 2 & Stamiris Contentions 1, 2, 3 & 5 Urges rephrasing of Stamiris Contention 4 re 0A Certificate of Svc encl FARNELL.A S Consumers Power Co FARNELL.A S Isham, Lincoln & Beale 80/09/30 lipp
- 8009260001 Suppl to SK Warren petition to intervene & amended suppl to S Stamiris petition to intervene Alleges inadequacy of permanent dewatering procedures & CPC financial pressures adversely affecting resolution of soil settlement issues WARREN. B K , STAMIRIS. B Affiliation Unknown 80/09/09 Bpp
- --8009240002 Statement asserting NRC & CPC positions re SK Warren & B Stamaris revised contentions No objections stated by NRC Partial objections stated by CPC re circulating water lines & other irrelevant issues Certificate of Svc encl HILLER, M I. Consumers Power Co. MILLER, M I. Isham, Lincoln & Beals 60709/18 4pp
- 8009160397 Forwards util answer to notice of hearing W/o encl FARNELL, A S Isham, Lincoln & Beale 80/09/11 1p
- BOC9190420 Notice of appearance in proceeding Certificate of Sys encl BRUNNER, J. E. Gonsumers Power Co. 80/09/11 3pp

- 8009250034 Notice of reconstitution of ASLS due to 1W Smith schedule conflict C Beckhoefer appointed chairman LAZO,R M Atomic Safety and Licensing Board Panel 80/09/19 Ip
- BOO9300023 Notice of B01007-09 depositions of D Hood, L Heller & J Kane of NRC & B01013,15 & 16 depositions of JN Simpson, W Lawhead & R Erickson of Corps of Engineers, re Stamiris & Warren contentions Certificate of Svc encl FARNELL, A S Consumers Power Co FARNELL, A S Isham, Lincoln & Beale 80/09/22 9pp
- 8009250004 Advises that, in response to 800920 mailgram, future transcripts will be mailed to 5 Oadler PATON.W D Hearing Branch 4 80/09/23 ip
- 8009290039 Responds to GA Linenberger 800910 inquiry re NRC conclusion on Page 3 of 790906 order modifying CPs Safety issues in question are associated w/iemedial action correcting soil deficiencies

 PATON.W D Hearing Branch 4 80/09/24 3pp
- H General correspondence
- 8007110280 Responds to 800728 ltr requesting info re safety of Midland & Fermi plants All nuclear plants subj to enhanced tafety requirements resulting from TMI Lessons Learned Task Force recommendations Supporting documentation and DIRCKG.WJ Office of the Executive Director for Operations 800/08/26 24pp
- --B00911028B Requests consideration of encl MC Haight ltr re safety of Midland & Fermi plants BROOMFIELD.W S House of Rep , Foreign Affairs 80/07/28 2pp
- 6009090040 Responds to 800507 ltr to President Carter re safety, cost & need for facilities NRC issued order on 791206 prohibiting soil const activities pending CP amend Study shows two-unit plant will provide electric power at lowest cost EISE(#NUT, D & Division of Licensing 80/08/27 (Opp
- K Utllity Fina) Bafety Analysis Report (FSAR) & amends
- 8009190218 Forwards portion of Amend 81 to FSAR, "Discussion of Applicant Position on Need for Addl Borings for Midland Plant Units I & 2 " Discussion attempts to document presentations & new mat! introduced at 800929 meeting w/NRC COOK, J W Consumers Power Co 80/09/16 3pp
- --8009170221 Portion of Amend 81 to FBAR entitled, "Discussion of Applicant Position on Need for Addl Borings for Midland Plant Units 1 3 2" * Consumers Power Co 80/09/14 41pp
- G Inspection reports, IC Bulletins & correspondence
- 8007190194 Forwards IE Insp Repts 50-329/80-20 % 50-330/80-21 on 800708-10 & notice of violation FIGRELLI, C Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/07/18 2pp
- --8007150197 Notice of violation from insp on 800708-10
 * Region 3, Chicago, Office of the Director 80/07/18 ip
- --8009180203 IE Insp Repts 50-329/80-20 A 50-330/80-21 on 800708-10 Noncompliance noted failure to specify applicable code in purchase order BANIELSON. D.H. Region G. Chicago, Reactor Construction & Engineering Support Branch LEE.E W.K. Region G. Chicago, Office of the Director 60/07/18 dpp
- B009180231 Forwards IE Insp Repts 50-329/80-22 & 50-330/80-23 on B00701-31 No noncompliance noted FIDRELLI,O Region 3, Chicago, Reactor Construction & Engineering Support Branch B0/08/07 2pp
- --8007180240 IE insp Repts 50-329/80-22 & 50-330/80-23 on 800701-31
 No noncompliance noted Major areas inspected detensioning of reactor hold down bolts.const activities of Zack Co & caseload forocasting KNOP.R C . COOX.R J Region G. Chicago, Office of the Director 80/08/05 Spp
- 8009230110 Responds to IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Circumstances Addressed not considered problematical because NDE performed required by applicable codes CODA, J W Consumers Power Co 80/08/14 11pp

- 8009030226 Forwards Revision 1 to IE Bulletin 80-17, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER, J G Regi Region 3. Chicago, Office or the Director 80/08/15
- 8009260410 Forwards IE Insp Repts 50-329/80-13 & 50-330/80-14 on 800227-29,0305-04,0312-13 % 20,0418 % 0502 & notice of violation
 KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/18
- .--8009260413 Notice of violation from insp on 800227-29,0305-06:0312-13 & 20.0418 & 0502 + Region 3, Chicago. Office of the Director 80/08/13 3pp
- --8009260415 IE lnsp Repts 50-329/80-13 ; 50-330/80-14 on 800227-29, 0305-06, 0312-13 & 20.0418 & 0502 Noncompliance noted inadequate procurement document control special processes control b purchase mattered purposent & svc control purchase mattered by the Control of the Director 80/08/13 23pp
- 800917041B Forwards IE Circular 80-18, "10CFRSO 57 Safety Evaluations for Changes to Radwasto Treatment Sys " No written response KEPPLER, J C Region 3, Chicago, Office of the Director 80/08/22
- 8009160249 Forwards IE lnsp Repts 50-329/80-17 & 50-330/80-18 on 800617-18 & 0722 & CB12-13 No noncompliance noted FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/27 2pp
- --8009160249 1E Insp Repts 50-329/80-17 % 50-330/80-18 on 800617-18,0722 DUVIOURY IE INSPONDED SOME SOME SOME SOME SOME INSPECTED OF BOOK OF THE PROPERTY OF THE PROPER
- 8009230071 Forwards IE Info Notice 8D-31. "Maloperation of Gould-Brown Bovert 480 Volt Type K-600S & K-DON 600S Circuit Breakers " No written response required KEPPLER.J Q Region 3. Chicago, Orfice of the Director BO/08/28
- 8009170227 Forwards NRC positions & requests for add1 info to IE Bulletins 79-21 & 80-06 re temp effects on level measurements & engineered safety feature reset controls Info needed for NRC review of OL applications
 TED25CO,R L Assistant Director for Licensing 80/09/04 12pp
- 8009240129 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/10
- 8009290472 Ack receipt of 800825 ltr informing NRC of steps taken to correct violations noted in IE lasp Repts 50-329780-20 & 50-330780-21 FIGRELIT, G. Region 3. Chicago, Reactor Construction & Engineering Support Branch
- --8009290475 Responds to NRC 800710 ltr re violations noted in IE Insp Repts 50-329780-20 \$ 50-330780-21 Corrective actions audit of weld filler matis procurement initiated & fabrication conditions qualified CODK.J W Consumers Power Co 80708725 App
- R Periodic operating reports & related correspondence
- 8007040295 Forwards Bechtel nonconformance repts & log sheets.Bechtel quality action requests.8%W nonconformity repts.B&W inservice insp nonconformance repts.util nonconformance, audit finding & corrective action repts COCK.J W Consumers Power Co 80/09/21 300pp
- S Reportable occurrences. LERs & related correspondence
- 8009030654 Ack receipt of 800731 interim deficiency rept re safe shutdown boration capability FIORELL1.0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/14 lp

- 8009030657 Ack receipt of 800801 interim deficiency rept re reactor vessel broken anchor bolk FIDRELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/08/14 ip
- BOO9100664 Ack receipt of 800813 interim rept re NSSS companent identification FIORELLI, G. Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/08/28 1p
- 8009230275 Interim rept re containment internal structures coating deficiency Substantial progress made in isolating factors contributing to delamination condition & in formulating corrective action program Nest rept by 801103 COOK, J W Consumers Power Co 80/09/09 ip
- 8009250268 Interim Deficiency Rept 9 re component qualification test documentation Nonconformance Repts i789,1795,1796,2659 & 2664 have been dispositioned & quality test review for matl requisition has been closed Next rept issued by 801205 CDGk, J & Consumers Power Co 80/09/19 64pp
- 8009250284 Deficiency rept re HELBA restraint design Steady state rather than peak thrust forces were used in design of G-listed pipe whip restraints investigation & identification of root cause recommended Another rept due by 801201 COOK, J W Consumers Power Ca 80/09/19 dpp
- 8009290360 Deficiency rept re high energy line break analysis of pipe whip restraint designs Caused by misinterpretation of BN-TOP-2 Affected restraints re-evaluated Next rept by 801121 COOK, J W Consumers Power Co 80/09/19 6pp
- T Hearing transcripts on non-antitrust matters
- 8009160499 Transcript of 800910 prehearing conference in Midland, MI Pp 234-408
 * Atomic Safety and Licensing Board Panel ISSUANCES DL 80/09/10
- DOCKET 50-331 DUANE ARNOLD ENERGY CENTER F Security, medical, emergency & fire protection plans
- 8009230302 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency KEPPLER.J O Region 3. Chicago, Office of the Director 80/08/22
- 8009180389 Forwards revised safeguards contingency plan to modified amended security plan Revision withheld (ref 10CFR2 790) ROOT.L D lowe Electric Light & Power Co 80/09/15 ip
- Q Adjudicatory correspondence
- 8009220109 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 1990LITO.T A Operating Reactors Branch 2 80/08/29 2pp.
- --8009220112 Order for mod of License DPR-47 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment info should be submitted by 801101 EISENHUT.D & Division of Licensing 80/08/29 App
- P Operating license stage documents & correspondence
- 8009110354 Supple NRC 800707 request for proposed Tech Specs changes rescram discharge vol yent & drain valves, & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT.D @ Division of Licensing, 80/07/22 22pp
- 8007020297 Submits interim criteria for shift staffing to all GL & CP licensess & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D G Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for DOYSUBD FORWARDS STATE WARES-LOOPS, TOWNSHINE CHILDREN, S. Emergency Response Facilities "Comments requested within 30 days Proposed implementation schedule for meeting criteria of NURES-0676 encl W/o NURES.

 EISENHUT, D 0 Division of Licensing 80/08/01 119pp

- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal thould include proposed class of amend EISENHUT, D O Division of Licensing 80/08/07 60pp
- 8009020144 Confirms that two specific Event 5 valve configurations do not exist at facility NRC activities re valve configurations finalized for facility Franklin Research Ctr-Primary Coolant Sys Pressure Isolation Valves: encl IPPOLITO, T A Operating Reactors Branch 2 80/08/08 3pp
- --8009020148 "Primary Coolant Sys Pressure Isolation Valves," technical evaluation rept NOELL,? N . STILWELL.T C Franklin Institute/Franklin Research Canter 80/07/21 Spp
- SCO9180206 Forwards NUREO-0661, "Mark I Containment Long-Term Program SER Resolution of Generic Technical Activity A-7 " Rept describes NRC requirements re generic suppression pool Audrodynamic load W/o encl IFPOLITO.T A Operating Reactors Branch 2 80/08/20 2bb
- 8009090777 Advises that util response to NRC 791109 ltr re portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture is acceptable No further action necessary 1PPOLITO.T A Operating Reactors Branch 2 80/08/22 2pp
- 8009020289 Forwards facility Mark | project schedule re long-term program plant mods Bchedule offered as addl clarification & update of initial schedule previously submitted Util plans to install all major torus-related mods prior to Dec 1980 ROOT.L D lowa Electric Light & Power Co 80/08/20 2pp
- BOGGITOOD1 Advises that commitments to NRC 771023 "Interim Position on Containment Purging & Venting Pending Resolution of Isolation Valve Operability," are acceptable & remain in effect pending completion of NRC long-term review IPPOLITO, T A Operating Reactors Branch 2 80/09/03 2pp
- BOO9170331 Advises that comments on NUREG-0696. "Functional Criteria for Exergency Response Facilities," will be incorporated into AIF comments Applauds NRC shift of philosophy re location of emergency operations facility ROOT, LD Iowa Electric Light & Power Co 80/09/05 ip
- 8009190533 Application to amend License DPR-49 modifying Tech Specs to reflect TMI-2 Lessons Learned Category 111 amend fee encl RODT.L D Iowa Electric Light & Power Co 80/09/10 Ip
- EO09230284 forwards fee payment for application to amend App A Tech Spect RDOT.L D Iowa Electric Light & Power Co 80/09/12 2pp
- 8009190541 Proposed Tech Spec changes supporting amend to License DPR-49 by changing Tables 3 2-A, 3 2-H, 4 2-H, Sections 6 2, 6, 3 & 6 B & deleting Note 8 on Page 3 2-7 to reflect TM1-2 Lessons Learned 4 Jowa Electric Light & Power Co 80/09/10 16pp
- 9 Inspection reports. IE Bulletins & correspondence
- 9009090042 Forwards IE Bulletin 80-07, Suppl 1, "BWR Jet Pump Assembly Failure" No response required MEPPLER, J.O. Region 3, Chicago, Office of the Director 80/05/14
- BOO9100154 Forwards IE Insp Rept 30-331/80-10 on 800402-30 & notice of violation MEJSIMAN:R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/07/24 2pp
- --8009100196 Notice of yielation from insp on 800602-30

 Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/07/23 ip
- --8007100161 IE Insp Rept 50-331/80-10 on 800602-30 Noncompliance noted failure to lock closed valve in standby liquid control sys LITTLE, H B , CHRISTIANSON, F , CLARDY, L Region 3, Chicago, Office of the Director 80/07/23 4pp
- 8009020170 Responds to 1E Bulletin 80-15 re Rosemount, inc transmitter misapplication Rosemount pressure transmitters not installed nor planned to be installed at facility RDOT, L D lowe Electric Light & Power Go 80/07/28 ip

- B009170961 Responds to NRC request for add1 info re control rod driveline sys Response includes info reviewed per IE Bulletins 79-02 & 79-14 No reanalysis of safety-related piping sys personned R007.L D Towa Electric Light & Power Co B0/08/11 3pp
- 8009030202 Forwards Revision 1 to IE Bulletin 80-19. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER.J © Region 3. Chicago: Office of the Director 80/08/15
- 8009090026 Responds to Item B of IE Bulletin 80-17. Suppl 1. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR "
 Operating procedures will be revised to require surveillance testing of switches
 ROOT.L D Town Electric Light & Power Co 80/08/15 4pp
- GOO9150459 Forwards IE Info Notice BO-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE BWR Facilities " No specific action or response requested KEPPLER.J G Region 3, Chicago, Office of the Director GO/08/20
- 8009120050 Forwards Suppl 3 to LE Bulletin 80-17. "Failure of Control Rods to Insert During Scram at BWR " Written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/08/22 fp
- 8009170428 Forwards 1E Gircular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER.J & Region 3. Chicago. Office of the Director 80/08/22 is
- 8009040424 Responds to IE Bulletin 80-i7. Suppl 3 Action Item i does not apply since scram discharge vol headers connect directly to instrument vol rather than through 2-inch pipe Revised procedures evallable at site for review ROOT.L D Town Electric Light & Power Co 80/08/27 2pp
- 8009230082 Forwards IE Info Notice 80-31, "Maloperation of Could-Brown Noveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers" No written response required KEPPLER.J G Region 3. Chicago, Ofrice of the Director 80/08/28
- 8009120555 Responds to 1E Bulletin 80-19 re failures of mercury-wetted metrix relays in reactor protective sys Relays and not used in facility Twenty-four manhours expended for review ROUT, L D lows Electric Light & Power Co 80/08/29 in
- 8009170409 Responds to IE Bulletin 80-20 re failures of Hestinghouse Type W-2 spring return to normal control switches identified suitches are not used in safety-related areas Twenty-four manhours expended on review ROOT.L D lowa Electric Light & Power Co 80/08/29 ip
- 8009170427 Supple 800505 response to 1E Bulletin 79-01B re environ qualification of Class IE equipment Vendor contact established re outstanding items Reviews underway Final response will be submitted by 801101 ROOT.L D Jowa Electric Light & Power Co 80/08/29 ip
- B009230484 Forwards Revision 1 to IE Bulletin 79-26, "Boron Loss From BUR Control Blades " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director B0/08/29 1p
- 8009240103 Forwards IE Circular 80-21. "Regulation of Refueling Crews"
 No written response required
 KEPPLER, J. G. Regian 3. Chicago: Office or the Director 80/09/10
 1p
- R Periodic operating reports & related correspondence
- 8009190499 Forwards monthly operating rept for Aug 1980 MINECK.D L lowa Electric Light & Power Co 80/09/12 ip
- --8009190504 Monthly operating rept for Aug 1980
 VAN SICKEL, J Towa Electric Light & Power Co 80/09/15 8pp

- S Reportable occurrences, LERs & related correspondence
- 8009030466 Forwards LER 80-038/03L-0 MINFCK.D L lowa Electric Light & Power Co 80/08/29 1p
- --8009030471 LER 80-038/03L-0 on 800801, during normal power operation, both drywell particulate recorders found downscalo Caused by high moisture content on particulate radiation detectors due to MSIV packing leak Leak repaired RAGER, M loua Electric Light & Power Co 80/08/29 pp
- 8009170315 Forwards LFR 80-039/93L-0 MINFCK.D L Ioua Electric Light & Power Co 80/09/10 lp
- 8009170324 Forwards LER 80-040/03L-0 MINFCK.D L lowa Electric Light & Power Co 80/09/10 lp
- --8009170328 LER 80-040/03L-0 on 800812. river water supply toop A removed to facilitate interchange of pump motors 1P-117A & 1P-117C as IP-117A replaced IP-117C on 791131 to maintain operation iP-117C returned to svc after original motor installed RAGER, M Towa Electric Light & Power Co 80/09/10 19
- 8009170348 Forwards LER 80-041/03L-0 MINECK, D L lowa Electric Light & Power Co 80/09/10 1p.
- --8009170352 LER 80-041/031-0 on 800820, control bidg isolation damper fV-A0-31A would not close, compromising operability of A control bidg standby filter unit Caused by shaft-operated connector bolt failing out of linkage RAGER, H lowa Electric Light & Power Co 80/09/10 ip
- 8009170355 Forwards LER 80~042/03L-0 MINECK.D L lowa Electric Light & Power Co 80/09/10 ip
- --B009170360 LER B0-042/03L-0 on B00B13.during surveillance testing, containment spray permissive PS 43110 tripped at 2 3 psig. above max allowable Caused by instrument drift Instrument recalls recalls recall to the spray of t
- 8009170363 Forwards LER 80-043/03L-0 HENECK.D L. Towa Electric Light & Power Co. 80/09/10 1p
- --8009170367 LER 80-043/03L-0 on 800813, reactor core isolation cooling turbine trip throttle vaive would not open during surveillance testing resulting an limiting condition for operation Caused by improperly positioned latching pin RAGER, K S lowe Ejectric Light & Power Co 80/09/10 ip
- BO09300493 Forwards LER BO-044/03L-0 MINECK D L | IDWA Electric Light & Power Co | B0/09/23 | 19
- --8009300501 LER 80-014/03L-0 on 800824, during power ascension Rod Block
 Monitor B indicated downscale for any rod selected resulting
 in continuous rod withdrawal block Caused by improperly set
 pin connector Pin seated, panel tested & returned to svc
 RAGER, M S fowa Electric Light & Power Co 80/09/23 ip

DOCKET 50-332 BARNWELL REPROCESSING PLANT

- G Wq Indicatord correspondence
- 8009170366 Comments on rulemaking 50-5 re mixed oxide fuel.0ESMO & other recycle-related licensing proceedings should continue Positive affirmative action to approve licenses recommended KIRK, W.F. William F. Kirs. 80/08/28 4pp.
- 8009140224 Requests GESMO re fusis be completed Info is needed for future decisions re reprocessing of spent nuclear fuel VILLEMY. G. R. Affiliation Unknown 80/09/08 fp
- 8009160420 Comments on rulepaking 50-5 GEBMO proceedings should be reopened to provide early procedural framework for subsequent licensing RICHARDS.R.B General Electric Co 80/09/08 2pp

- 6009300525 Forwards Comments in response to Commission 600807 order raterminated CESMO proceedings Reopening would be inimical to matt security & defense & at odds w/nonproliferation objectives

 BIALIK.E I New York, State of 80/09/23 7pp
- 8009300514 Expresses concern re-reopening of GESMO & other related licensing proceedings for reprocessing sites FEIQ.D Affiliation Unknown 80/09/13 ip
- 8009220224 Comments on rulemaking 50-5 GESMO proceedings should be reopened Technical economic & safaty issues must be addressed in order for decisions to be made re use of mited-oxide fuels
 WEITZBERG, A Affiliation Unknown 80/09/j5 1p
- 8007260641 Urges resumption of OESMO hearings BOLONA & Affiliation Unknown 80/09/16 1p
- ~-8009260652 Urges reopening GESMO & recycle-related proceedings & consideration of expanding scope to include recycle of LMR fuel in breeder reactors MCCORMACK.M House of Rep. 80/09/22 2pp
- 8009300540 Comments on reopening of SESMO proceedings Addl use of nuclear generated electricity should be paced to preserva significant quantities of hydrocarbon reserves for use as raw matis in future chemical mfg BURRIS,L American Institute of Chemical Engineers 60/09/23 2pp
- 800730D549 Request extension of time for comment on Commission 800007 order re reopening GESMO proceeding HOLDEN:R B Allied General Nuclear Services 80/09/23 1p
- 8009300561 Supports reopening of GESMO & other recycling license proceedings
 PRICE. J E Affiliation Unknown 80/09/23 1p
- Q Inspection reports, IE Builetins & correspondence
- 8009080231 Ack receipt of IE Insp Rept 50-332/80-02 an 800708-11 No proprietary info HOLDEN,R 9 Allied General Nuclear Services 80/08/08 ip
- --8009080233 Forwards IE Insp Rept 50-332/80-02 on 800708-11 No noncompliance noted KEMMAN B Region 2: Atlanta, Safeguards Branch 80/07/28, 10
- --B009080838 IS Insp Rept 50-332/B0-02 on 800708-11 No noncompliance noted Major areas inspected safety committee, interpal review & audits, IOCFR21 implementation to IE info notices CORYELL, o P. Region 2, Atlanta, Office of the Director KAHLE, J.B. Region 2, Atlanta, Safeguards Branch 80/07/08 4pp
- 8007230400 Forwards IE Circular 80~20, "Changes in Bafe-Blab Tank Dimensions" No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/08/21 4pp
- DOCKET 50-333 JAMES A FITZPATRICK NUCLEAR POWER PLANT
 F Security, medical, emergency & fire protection plans
- 8009230188 Requests that all personnel be reminded of purpose of emergenty motification sys & health physics network. Bys installed for govt use during emergency GRIER, B H Region 1. Philadelphia. Office of the Director 80/08/22 Opp
- O Adjudicatory correspondence
- 8009220104 Forwards order requiring info supporting environ qualification of safety-related electrical equipment flequests submittal of info by 801101
 IPPOLITORY A Operating Reactors Branch 2 80/08/29 2pp
- --8009220107 Order for mod of License DPR-59 to add info which fully responds to NRC request for 10fo re environ qualification of safety-related electrical equipment 10fo should be submitted by 801101
 EISENHUT,D Q Division of Licensing, 80/08/29 App

1 Financial information

- 8009120396 Forwards estimated cash flow 2 audited financial statements for 1979 EERFY.G T Power Authority of the State of New York 80/09/03
- P Operating license stage documents & correspondence
- E009110554 Suppls NRC 800707 request for proposed Tech Specs changes re scram discharge vol vent & drain valves. & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT.D O Division of Licensing 80/07/22 22pp
- 8009020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days ERECHMUID G Division of Licensing 80/07/3i 7pp
- BOOTOBOOBO Forwards draft NUREQ-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUPEQ-0696 enci W/o NUREO EISENHUT.D O Division of Licensing 80/08/01 119pp
- EOG9230052 Informs that exemption from fee re ilcensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed clast of amend EISENHUT.D 0 Division of Licensing 80/08/07 60pp
- 8009170255 Advises that two specific Event 5 valve configurations do not exist at Pacifity per review of response to NRC 800223 ltr "Primary Coolant Sys Pressure Isolation Valves," technical evaluation rept enc!

 JPPOLITO.T A Operating Reactors Branch 2 80/08/08 Spp
- --8007i70260 "Primary Coplant Sys Pressure Isolation Valves." technical evaluation rept NDELL.P N . STILWELL.T C Franklin Institute/Franklin Research Center NRC-03-79-ii8 80/07/21 5pp
- 8009230237 Forwards NUREO-0661, "Mark I Containment Long-Term Program SER.Resolution of Generic Technical Activity A-7 " Rept dascribas NRC review results re generic suppression pool bydrodynamic load definition W/o encl
- E009930505 Forwards DE comments re facility reload SER ODYN use for rapid pressurization transient analyses re future reloads appropriate Transition to ODYN should not unduly perturb reload licensing cycle or penalize plant operation EHERKOOD.6 G Deneral Electric Co , Nuclear Energy Products Div E0/08/22 5pp
- 8009090778 Informs that no relief will be granted for 20-month Inservice insp/inservice testing test cycle due to three major differences of position NRC position on issues encl IPPOLITO.T A Operating Reactors Granch 2 80/08/27 4pp
- 8007180554 Advises that response to NRC 791109 ltr re ECCS evaluation models dealing w/fuel cladding swelling ½ incidence of rupture is acceptable No further action necessary IPPOLITO TA Operating Reactors Branch 2 80/09/03 2pp
- 8007290437 Fdrwards Amends 32 % 50 to Licenses DPR-64 & DPR-59, respectively safety evaluation & notice of issuance & availability VARQA.8 A Operating Reactors Branch 1 80/09/05 3pp
- --B009270446 Amends 32 & 50 to Licenses DPR-64 & DPR-59, respectively, changing organization charts & position titles & increasing manbership of safety review committee for both units VAROA, S A Operating Reactors Branch 1 80/09/05 26pp
- --800927045: Safety evaluation supporting Amends 32 & 50 to Licenses
 DPR-64 & DPR-59, respectively
 # Office of Nuclear Reactor Regulation, Director 80/09/05 3pp
- --8009290454 Notice of issuance & availability of Amends 32 & 50 to Licenses DPR-64 & DPR-59, respectively VARGA, S A Operating Reactors Branch 1 80/09/05 3pp

- 8009(20362 Provides update of Mark I containment program mod schedule previously submitted on 790629 t 0921 Installation of vent header deflectors t saddle supports under torus complete Other mods planned for completion during Fall 1931 BAYNE. J P Power Authority of the State of New York 80/09/09
- 8009260446 Requests extension until 80(013 for submitting Tech Spec changes re TMI-2 Lessons Learned Category A items due to completion of refueling outage restart of plant, fire protection / TMI related mods

 BANNE.J P Power Authority of the State of New York 80/09/23 ip
- O Inspection reports, IC Builetins & correspondence
- 8009090106 Forwards IE Builetin 80-07, Suppl 1, "BHR Jet Pump Assembly Failure" Response required GRIER, BH Region I, Philadelphia, Office of the Director 80/05/13 ip
- 8009190936 Advises that response to 1E Bulletin 80-14 will be consolidated w/reply to 1E Bulletin 80-17 due to similarity of action items
 PASTERNAK, R J Power Authority of the State of New York 80/07/28 ip
- BOO9020115 Responds to IE Bulletin 79-03A. "Longitudinal Weid Defects in ASME SA-012. Type 304 Stainless Steel Pipes" No SA-012 or A-012. Type 300 series fusion welded pipe in use or planned for use in safety-related sys PASTERNAN. R J Power Authority of the State of New York 80/07/29 1p
- 8009110257 Ack receipt of 800607 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-333/80-05 GRIER.B H Region 1. Philadelphia. Office of the Director 80/08/07 2pp
- --8009110278 Responds to NRC 800516 itr re violations nated in IE Insp. Rept 50-233/80-05 Corrective actions personnel training session to be conducted & instrument maint procedure revised PASTERNAK, J. Power Authority of the State of New York 80/06/07 700
- --8009i10301 Forwards 1E Insp Rept 50-333/80-05 on 800407-11 & notice of violation BRONNER,E J Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/05/14 2pp
- --8007110393 Notice of violation from insp on 800407-i1
 * Region i, Philadelphia, Office of the Director 80/05/07 3pp
- --B009ii0306 IE Insp Rept 50-333/80-05 on 800407-11 Noncompliance noted failure to perform periodic procedure review & failure to impiement calibr program for sefety-related instruments QREENMAN. E Region i. Philadelphia. Reactor Operations Nuclear Support Branch BLUMBERO, N J Region 1. Philadelphia. Office of the Director 80/05/09 15pc
- 8009090014 Responds to IE Bulletin 80-19. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Mercury-wetted relays not used in sys at facility PASTERNAK, R J Power Authority of the State of New York 80/08/12 is
- 8009100117 Responds to IE Builetin 80-20. "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches " No Type W-2 switches used in safety-related sys PASTERNAK.R J Power Authority of the State of New York 80/08/12 to
- 8009030074 Forwards Revision i to IE Builetin 80-19. "Failures of Mercury-Hetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Nritten response required GRIER B H Region i. Philadelphia. Office of the Director 80/08/15 ip
- 8009080266 Discusses lE insp on 800414-18 & 23-25 & forwards proprietary version of notice of violation & notice of proposed imposition of civil penalty Proprietary notice withheld (ref 10CFR2 790)
 STELLO, V Office of Inspection & Enforcement, Office of the Director, 80/08/18 2pp

- --8009080270 Notice of proposed imposition of civil penalty in amount or \$18 000 for item or nancompliance noted in IE imap on of \$18 000 for item of noncompliance noted in IE insp on 800414-18 & 23-25 + Orice of Inspection & Enforcement. Office of the Director
 - 80/08/18
- 8009120100 Faruards Suppl 3 to IE Bulletin 80-17. "Failure of Control Rods to Insert During Scram at BUR' Written response required
 - GRIER, B H Region i. Philadelphia. Office of the Director
- 8009180038 Forwards 1E Circular 80-18, "IOCFR50 99 Safety Evaluations for Changes to Radwaste Treatment Sys ' No written response
- Region i. Philadelphia. Office of the Director 80/08/22 10
- D09120233 Forwards 1E Info Notice 80-31 "Maloperation of Gould-Brown Bover: 480 Voit Type X-2005 & X-DDN 6005 Circuit Breakers" No written response required GRIER. B H Region 1: Philadelphia, Office of the Director 80/08/27 ip 8009120233 Forwards IE Info Notice 80-31
- 8009230499 Forwards Revision 1 to IE Bulletin 79-26. "Boron Loss From BNR Control Blades " Written response required GRIER.B H. Region 1. Philadelphia. Office of the Director 80/88/29 ip
- 8009240635 Forwards (E Circular 80-21, 'Regulation of Refueling Crews " No written response required GRIER.B H Region I. Philadelphia. Office of the Director 80/09710 ip
- 8009240324 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Ma+ls ' No written response required GRIER, B H Region I, Philadelphia, Office or the Director 80/09/12 tp
- R Periodic operating reports & related correspondence
- 8009100268 Forwards "Effluent & Wasto Disposal Semiannual Rept. Jan-June PASTERNAN, R J Power Authority of the State of New York 80/08/26
- -8009100275 "Effluent & Waste Disposal Semiannual Rept.Jan-June 1980 "

 4 Power Authority of the State or New York 80/08/26 84pp
- 8007070303 Forwards monthly operating rept for Aug 1780 PASTERNAX.R J Power Authority of the State of New York 80/09/05
- -8009090308 Monthly operating rept for Aug 1980 * Power Authority of the State of New York 80/09/05 16pg
- S Reportable occurrences, LERs 3 related correspondence
- 8009040591 EN-80-037 on 800818, notice of violation & notice of DOYOUSSI EN-BU-US on SOURIS, notice of violation & notice of proposed imposition of civil penalties of 480,000 to be issued Action is based on items of noncompliance associated w/implementation of physical security plan BROCYETITY W. THOMPSOU, D. Orfice of Inspection & Enforcement. Orfice of the Director BO/03/14 ip
- 8009030405 Forwards LER 80-063/03T-0 PASTERNAK,R J Power Authority of the State of New York 80/08/27
- --B009030414 LER 80-065/03T-0 on 800B14, during normal operations, while inerting primary containment standby gas treatment sys AFB round inoperable Caused by blocked drain line allowing water to accumulate in line until fams could not discharge CHILDS N V Powel Authority of the State of New York 80/08/27 200
- 8009030418 Forwards LER 80-066/03L-0 PASTERNAAR J Power Authority of the State of New York 80/08/28
- -8009030423 LER B0-066/03L-0 on 800805.during normal shutdown.conducting surveillance procedure F-15P-8.cors spray mys pipe break detection switches 14-DP18-43A & 43B found set greater than limit Caused by Instrument drift instruments recalled CHILDS.W V Power Authority of the State of New York 80/08/29

- 8009020354 Forwards LER 80-067/03L-0 PASTERNAA, R J Power Authority of the State of New York 80/08/29
- --8009020359 LER 80-067/03L-0 on 800805.while conducting instrument surveillance check, steam line low pressure switches found set higher than 100 psig limit Caused by instrument drift instruments calibit & returned to svC CHILDS.W V Power Authority of the State of New York 80/08/25 60/08/29
- 8009020394 Forwards LER 80-068/03L-0
 PASTERNAK, R J Power Authority of the State of New York 80/08/29
- --8009020403 LER 80-068/03L-0 on 800805 during normal cold shutdown, conducting instrument surveillance F-ISP-15 drywell drain sump pump flow transmitter found out of talerance Caused by instrument drift Instrument recallibr CHILDS.W V Power Authority of the State of New York 80/08/29
- 8007020409 Forwards LER 80-069/03L-0 PASTERNAK, R J Power Authority of the State of New York 80/08/29
- --8007020422 LER 80-069/03L-0 on 800807, during normal shutdown, while conducting survelllance test F-ST-22A, auto depressurization sys timer found set below limit Caused by setpoint drift Timer adjusted & returned to syc CHILDS. W V Power Authority of the State of New York 80/08/27
- 8009090359 Forwards LER 80-037/03X-1 PASTERNAK.R J Power Authority of the State of New York 80/09/03
- --B009090361 LER B0-037/03X-1 on B0041B during normal operation & surveillance testing, feedwater control sys level transmitter O6-LT-32A found out of callbr Caused by seat leak on instrument bypass (equaliting) valve instrument recalibr CHILDS,W V Power Authority of the State of New York B0/09. 80/09/03
- 8009120410 Forwards LER 80-070/03L-0
 PASTERNAK.R J Power Authority of the State of New York 80/09/08
- --8009120415 LER 80-070/03L-0 on 800807-15, intermediate range monitor sys problems encountered during plant shutdown, startup & normal operations Cause under speculation Followup rept to be submitted CHILDS.N V Power Authority of the State of New York 80/09/08
- 8009120359 Forwards LER 80-071/03L-0 PASTERNAX,R J Power Authority of the State of New York 80/09/09
- --8009120365 LER 80-071/03L-0 on 800810, during plant startup at less than 150 gslg.reactor core isolation cooling turbine speed would not control in manual during surveillance test Bys flow also did not control in automatic Cause not determined CHILDS. W V Power Authority of the State of New York 80/09/09
- 8009140445 Forwards LER 80-072/03L-0 PASTERNAN.R J Power Authority of the State of New York 80/09/11
- --8909160447 LER 80-072/03L-0 on 800812.during plant startup & operation, low pressure coolant injection inverter tripped Caused by electronic control failure Following repair, inverter became CHILDS. W V Power Authority of the State of New York 80/09/11
- B00916045B Forwards LER 80-066/03X-1
 PASTERNAK, R J Power Authority of the State of New York 80/09/11
- --8009160476 LER 80-066/03x-1 on 800805, during instrument surveillance procedure F-ISP-8, core spray sys pipe break detection switches 14-DPIS-A9A 3 A9B found set above max allowable Gaused by instrument drift Switch recalibr CHILDS.N V Power Authority of the State of New York 80/09/ll

- 8909190489 Forwards LER 80-073/03L-0
 PASTERNAA,R J Power Authority of the State of New York 80/09/12
- --8009190496 LER 80-073/03L-0 on 800815 during surveillance, offgas radiation monitor B found out of calibr Caused by instrument drift & detoctor aging Adjusted & restored monitor to operable status 3 days after discovery * Power Authority of the State of New York 80/09/12 ip
- DCCKET 80-334 BEAVER VALLEY POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8009230172 Requests that all personnel be reminded of purpose of energency notification sys & health physics network Sys installed for govt use during emergency GRIER, B H Region i. Philadelphia. Office of the Director 80/08/22 Spp
- @ Adjudicatory correspondence
- 8009220093 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 VAROA.5 A Operating Reactors Branch 1 80/08/29 3pp
- --800922009& Order for mod of Licenso DPR-66 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101
 EISENHUTID 9 Division of Licensing 80/08/27 App
- P Operating license stage documents & correspondence
- 8009020297 Submits interim criteria for shift staffing to all QL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D O Division of Licensing 80/07/31 7pp
- 800903Di67 Requests written justification of long-term operability of long head safety injection pumps on basis of mods made as results of tests run at facility & slsewhere VARGA.S A Operating Reactors Branch | 80/07/31 | 2pp
- BOD9080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EIBENHUT.D G Division of Licensing 80/08/01 119pp
- BCOP230052 Informs that exemption from fee re licensing action associated w/THI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D O Division of Licensing 80/08/07 60pp
- 8009190794 Forwards revised Westinghouse STS 3 9 8 2,3 9 10 & Bases 3/4 9 8 & 3/4 9 10 to require 23 ft of water over top of reactor pressure Vessel flange during movement of fuel assemblies or control rods Written response required NOVAK.T M Assistant Director for Operating Reactors 80/08/15
- --8009190817 Revised Westinghouse STS 3 9 8 2,3 9 10 t Bases 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods

 * Assistant Director for Operating Reactors 80/06/23 21pp
- 8009180525 Ack receipt of 800514 application for amend of license re Tach Spec changes Review determined to require Class II fee DIGOS.R M License Fee Management Branch 80/08/21 ip
- 8009190589 Forwards Amend 28 to License DPR-66, safety evaluation & notice of issuance & availability EISENHUT, D G Division of Licensing 80/08/27 2pp
- --8009190596 Amend 28 to License DPR-66, revising Tech Specs to reflect mods made to alleviate NPSH problems w/low head safety injection & recirculation spray pumps VAROA, S A Operating Reactors Branch 1 80/08/27 12pp
- --8009190402 Safety evaluation supporting Amend 28 to License DPR-66 4 Office of Nuclear Reactor Regulation, Director G0/08/27 18pp

- --9009190697 Notice of issuance & availability of Amend 28 to License DR-66 GROTE/HUIS, M. Operating Reactors Branch 1 80/08/27 2pp
- 8009150219 Forwards Amend 29 to License DPR-66, safety evaluation & notice of issuance & availability VARGA: 8 A Operating Reactors Branch 1 80/08/29 3pp
- --8009190244 Amend 29 to License DPR-66, revising Tech Specs to eliminate use of reactor coolant pump position trip above setpoint P-8 VARCA, S.A. Operating Reactors Branch 1 80/08/29 4pp
- --8009150246 Safety evaluation supporting Amend 29 to License DPR-66 * Office of Nuclear Reactor Regulation, Director 80/08/29 2
- ~~8009150248 Notice of (squance & availability of Amend 29 to License DPR-66 NEIOHBORS, J D Operating Reactors Branch 1 80/08/29 2pp
- B009090405 Forwards "Low Head Safety Injection Pumps Presently Installed at Beaver Valley Power Station, Unit 1." in response to NRC B00731 | Itr Rept describes mode 5 testing conducted to assure long-term operability of pumps DUNN, C (4 Duquesne Light Co 80/09/04 | 19
- --8009090412 "Low Head Safety Injection Pumps Presently Installed at Beaver Power Btation.Unit 1 "
 IRELAND.R N , SIEBER.J D , CAREY.J J Duquesne Light Co B0/09/04 4pp
- 8007100609 Forwards Class II fee to suppl Class IV fee submitted in 800514 application for amend of License DPR~66 MODRE.G W Duquesne Light Co 80/09/04 1p
- --8009100417 Forwards check for Class 11 fee D1998,R M License Fee Management Branch 80/09/08 1p
- 8007260166 Forwards Amend 30 to License DPR-66, safety evaluation & notice of issuance & availability
 VARGA:8 A Operating Reactors Branch 1 80/09/10 3pp
- --8009260181 Amend 30 to Liconse DPR-65 revising radiological Tech Specs to reflect new streamline break protection sys VARBALSA Operating Reactors Branch 1 80/09/10 30pp
- ---8009260186 Safety Evaluation supporting Amend 30 to License PPR-66
 * Operating Reactors Branch 1 80/09/10 28ap
- --8009260192 Notice of issuance & availability of Amend 30 to License DRR-66 VARGA.S A Operating Reactors Branch t 80/09/10 2pp
- 800723060: Confirms 800715 teleon re qualification of chlorine detection sys per Reg Guide 1 75 Detection sys qualified for all expected environs & severe environs that could lead to chlorine release SIEBER, J D Duquesne Light Co 80/09/16 3pp
- BO07230711 Confirms B00909 telcon re basis for selecting assential sys regarding clarification of NUREG-0578 Item 2 1 4 SIEBER. J D Duquesne Light Co B0/09/16 lp
- 8009230263 Application to amend License DPR-66, changing Tech Specs Bections 3 3,3 4,3 11,4 3,4 4 4 4 11 to add auxiliary feedwater to engineered safety feature sys instrumentation & ravising accident monitoring instrumentation requirements DUNN.C N Duquesne Light Co 80/09/17 2pp
- ---B009230269 Proposed Tech Specs 3 3.3 4.3 11.4 3.4 4 & 4 11 re engineered safety feature instrumentation, accident manitoring instrumentation, surveillance requirements, RCS pressurizer & min shift crew composition # Duquesne Light Co B0/09/17 31pp
- 8009230454 Confirms 800904 telcon re compliance w/NUREO-0578, Item 2 1 3 b concerning wide range pressure inputs & resistance temp detector uncertainty Util will upgrade nonsafety-grade input to safety grade during second refueling SIEGER, J D Duquesne Light Co 80/09/17 lp
- 8009230593 Confirms 800919 telcon re clarification of util position w/respect to NRC questions concerning 800628 submittal on THI Short-Term Lessons learned requirements SIEBER, J. D. Duquesne Light Co. 80/09/17 8pp

- B009300359 Responds to NRC B00819 ltm re revisions to Tech Specs Revisions will be provided in Oct 1980 Tech Spec changes are not immediately necessary Min of 23 ft or water over top of reactor vessel flange during movement of fuel assemblies DUNN,C N Duquesne Light Co 80/09/26 2pp
- Q Inspection reports. IE Bulletins & correspondence
- 8009180001 Forwards IE Insp Rept 50-334/80-14 on 890519-23 No noncompliance noted BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/07/18 2pp
- --8009180005 IE Insp Rept S0-334/80-14 on 800519-23 No moncompliance noted Major areas inspected design change mod control, QA/QC surveillance, audits 2 followup on previously identified items
 GREENMAN, E Region 1. Philadelphia, Reactor Operations Nuclear Support Branch NAPUDA, G. SIMONETTI, G. Region 1. Philadelphia, Diffice of the Director 80/07/14 8pp
- 8009160244 Forwards IE Insp Rept 50-334/60-19 on 800627-28 No noncompliance noted MARTIN.U 0 Region 1. Philadelphia, Safeguards Branch 80/07/24 2pp
- --B009160246 IE Insp Rept 50-934/80-19 on B00627-28 No noncompliance noted Major areas inspected licenses actions taken in response to possible intrusion into protected area Details withheld (ref 10CFR2 790)
 SMITH.O C Region I. Philadelphia. Safeguards Branch DELVIN.J Region 1, Philadelphia. Office of the Director 80/07/24 ip
- 8009/10047 Forwards 1E Insp Rept 50-334/80-12 on 800420-0531 No noncompliance noted BRUNNER,E J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/07/25 2pp
- --8009110050 IE Insp Rept 50-334/80-12 on 800420-0591 No noncompliance noted Major areas inspected plant operations, apparent gaseous waste tank release & potential recirculation spray heat exchange integrity problem BECKMAM.D A , HEGNER.J D Region i, Philadelphia, Office of the Director MCGABE, E C Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/07/23 20pp
- 8009100384 Ack receipt of 800417 Itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-334/80-05 BRUMMER,E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/08/11 2pp
- --8009100389 Responds to NRC 800329 itr re violations noted in IE Insp Rept 50-334/80-03 Corrective actions refueling water storage tank level indicators rearranged & meteorological calibr procedures altered DUNN.C N Duquesne Light Co 80/04/17 App
- --8009100392 Forwards (E Insp Rept 50-334/80-05 on 800205-08 & 12-13 & notice of violation BRUHHER,E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/03/25 2pp
- --8007100375 Notice of violation from Insp on 800205-08 & 12-13 * Region i, Philadelphia, Office of the Biroctor 80/03/24 3pp
- ---8009100399 IE Insp Rept 50-334/80-05 on 800205-08 & 12-13 Noncompliance noted failure to post temporary changes & revisions, failure to use approved procedure to perform Tech Spec calibr & failure to document calibr BAUNACK & Region I. Philadelphia. Reactor Operations Nuclear Support Branch BLUMBERO.N Region 1. Philadelphia. Office of the Director 80/03/24 [5pp
- E009150430 Forwards Performance Appraisal Branch insp planning data to facilitate 600818-22 insp Insp will examine problems identified de/Pacific Pumps RRUNNER.E J. Region J. Philadelphia. Reactor Operations Nuclear Support Branch 60/08/E1 Spp
- 8007070116 Forwards responses to IE Bullstin 77-14 & Suppls 1 & 2, "Seismic Analysis for As-Built Safety-Related Piping Sys "
 W/completion of mods.all piping sys will be able to perform required safety functions during seismic event WODLEVER.E J . SENCHYSHYN.J B Duquesne Light Co 80/08/14 8pp
- --8009090119 "Response to IE Bulletin 79-14 " Util schedule for completion of response ancl * Stone & Webster Engineering Corp 80/08/14 10pp

- 8009030070 Forwards Revision i to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required ORIER.8 H Region I. Philadelphia, Office of the Director 80/08/15 1p
- 8009:80478 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required ORIER B H Region 1, Philadelphia. Office of the Director 80/08/22 19
- 80070907Bi Forwards evaluation of util 790430,0514,17 & 0712 responses to 1E Bulletin 79-06A Appropriate actions taken to meet bulletin requirements Further actions may be required VAROA.S A Operating Reactors Branch I 80/08/27 16pp
- 8009120176 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Bover1 480 Volt Type K-600S 3 K-BON 600S Circuit Breakers" No written response required GRIER, B H Region I, Philadelphia, Office of the Director 80/08/27 Ip
- 8007080307 Forwards response to NRC 800801 notice of violation in IE Insp Rept 50-334/80-15 Corrective action calibr procedures will be revised by 801031 DUNN.C N Duquesne Light Co 80/09/02 3pp
- 8009090374 Responds to NRC 800B18 itr re violations noted in IE Insp Rept 50-334/80-22 Corrective action personnel responsible for preparing Radcon form 4 9 instructed to promptly update form upon receipt of required info DUNN.C N Duquesne Light Co 80/09/03 3pp
- B009230780 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required GRIER.B H Region I, Philadelphia, Office of the Director B0/09/10 Ip
- BO09160374 Responds to IE Bulletin 79-14. "Seismic Analysis for As-Bullt Safety-Related Piping Sys " Long-term evaluation of any as-bullt discrepancies will be based on appropriate loading combination for design 8 operation DUNN.G N Commonwealth Edison Co 80/09/11 2pp
- 8007240307 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matts " No written response required ORIER.B H Region 1, Philadelphia, Office of the Director 80/07/12 1p
- A Periodic operating reports & related correspondence
- 8809030390 Forwards NFDES discharge monitoring repts for Jul 1980 MDDRE, G W Duquesne Light Co 80/08/29 2pp
- --8009030395 NPDES discharge monitoring repts for Jul 1980 MODRE, O W Duquesne Light Co 80/08/29 13pp
- 8009180189 Forwards monthly operating rept for Aug 1980 DUNN: C N Duquesne Light Co 80/09/15 ip
- --8007180174 Monthly operating rept for Aug 1980 TIMAO.D R Duquesne Light Co 80/09/03 4pp
- 8009190446 Notifies that additime is needed to complete semiannual affluent rept for first six months of 1980 Rept will be submitted by 800930 Dose astimation data will be forwarded by 801030 DURN, C N Duquesne Light Co 80/09/15 2pp
- S Reportable occurrences. LERs & related correspondence
- 8009050250 Forwards LER 80-060/03L-0 WERLING, J A Duquesne Light Co 80/08/28 2pp
- --803905D254 LER 80-060/03L-0 on 800827, discovered that damage to ECCS charging pumps may occur following secondary side high energy line break Caused by excessive back pressure preventing sufficient flow to prevent damage to pumps LACEY.W B Duquesne Light Co 80/08/28 2pp
- 8009120377 Forwards LER 80-047/03L-0 WERLING.J A Duquesne Light Co 80/09/04 2pp

- --B0091203B4 LER 80-047/03L-O on 800805, during exercise mode, emergency diesel generator output circuit breaker failed to close Caused by relay latch inoperability, due to dirty contacts After replacing contact block, diesel tested satisfactorily LACEY, W B Duquesne Light Co 80/09/04 2pp
- BOO9150393 RO evaluation & reanalysis required by IE Bulistin 79-14 revealed that certain pipling & supports have less conservatism than assumed for safety analysis Cause unstated Pipe support will be added prior to startup HERLING. J A Duquesne Light Co 80/09/08 2pp
- 8009250251 RDs 80-062/01P & 80-063/01P on 800908 during evaluation & reanalysis required by IE Bulletin 79-14, overstressed conditions found on boron injection tank & charging pump 10 discharge lines MERLING.J A Duquesne Light Co 80/09/08 ip
- 8009160309 Forwards LERs 80-062/0iT-0 & 80-063/0iT-0 WERLING.J A Duquesne Light Co 80/09/09 3pp
- --B009160311 LER B0-062/01Y-O on 800908 overstress condition found to exist on boron injection tank discharge line during seismic event Cause unknown Pipe support mods will be completed before startup LACEY.H S. Duquesne Light Co B0/09/09, 2pp
- 8007160444 Forwards LER 80-059/01T-0 WERLING. J A Duquesne Light Co 80/09/09 2pp
- --8009160451 LER 80-059/017-0 on 800823, during diesel restart on low pressure following shutdown from surveillance run, starter motor burned up Caused by open field winding Starter was replaced tACEY.W 8 Duquesne Light Cp 80/09/09 2pp
- 8009160470 Forwards LER 80-064/03L-0 HERLING, J.A. Duquesne Light Co. 80/09/10 2pp
- --8009160472 LER 80-064/03L-0 on 800825, chemist failed to analyze reactor coolant for chloride % fluoride % did not analyze until 800827. Caused by personnel error Chemists were reinstructed in sampling requirements

 LACEY, H B, Duquesne Light Co 80/09/10 ip
- 8009160409 Forwards LER 80-008/01T-1 MERLING, J A Dequesne Light Co 80/09/11 2pp
- --B009160411 LER 80-00B/01T-1 on B00225, during in-plant insp. potential overstress condition of cable spreading room floor indicated due to postulated seismic loading Caused by utilizing underside of floor to higher degree than original design LACEY.W S Duquesne Light Co. B0/09/11 3pp
- BOOT170500 RO evaluation & analysis required by 1E Bulletin 79-14 revealed piping & supports have less conservatism during spisofic events Mods will be made prior to startup MERLING, J A Duquesne Light Co 80/09/15 2pp
- BO07240450 Forwards LERs 80-065/01T-0,80-066/01T-0 & 80-067/01T-0 WERLING, J A Duquesne Light Co 80/09/17 2pp
- --8009240456 LER 80-065/01T-0 on 800912, determined that both river water supply lines will be subj to overstress during seizmic event Caused by dead weight & DBE loading factors Corrective actions underway

 LACEY.W 8 Duquesne Light Co 80/09/17 2pp
- -- SCGY240458 LER BO-Obb/OlT-O on BOO912, determined that "A" steam generator steam outlet pipe hangers will be subj to overstress during seismic event Caused by dead weight & DRE loading factors Hanger mods completed LACEY, W S Dryuesne Light Co 80/09/17 2pp
- --BOO9240461 LER BO-067/017-O on BOO912, determined that branch line of 24-inch reactor plant component cooling water header will be tub; to overstress during selsmic event Caused by dead waight & DSE loading factors
 LACEY,W S Duquesne Light Co 80/09/17 2pp
- 1009290251 Forwards LER 80-052/01T-0 WERLING.J. A Duquesne Light Co 80/09/19 2pp

- ---8009290257 LER 80-052/0iT-0 an 800726 diesel fire pump was running below rated RPM & pressure Caused by clogged fuel oil filter Filter replaced LACEY,W S Duquesne Light Co 80/07/19 2pp
- 8009300412 RO 80-070/OIP on 800922.born dilution discovered during RCS initial fill b vent, causing unglanned reactivity insertion to exceed Tech Specs limits Caused by procedural deficiency Boric acid blender total flow setpoint changed WERLING, J A Duquesne Light Co 80/09/23 2pp
- 8009300543 LER 80-021 has been cancelied * Duke Power Co 80/09/25 1p
- DOCKET 50-335 ST LUCIE PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8007270624 Forwards proposed revision to emergency plan Apps will be forwarded under separate cover Complete implementation will depend on availability of essential resources UHRIO.RE Florida Fower & Light Co 80/07/23 ip
- ~-8007290625 Draft emergency plan ~ Fiorida Power & Light Co 80/07/15 140pp
- 8009230261 Requests that all personnel be reminded of purpose of emergency motification sys 3 health physics network Sys installed for govt use during emergency O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/22 in
- 8007100722 Transmits emergency planning info to be made available to public at LPDR.Fort Pierce.FL W/o encl SQUDER.J L. Public Document Branch 80/08/27 (p
- 9 Adjudicatory correspondence
- 8009190297 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 CLARK,R A Operating Reactors Branch 3 80/08/29 2pp
- ~~8009190302 Order for mod of License DPR-67 to add info which fully responds to NRC request for info re environ qualification of safety-related ejectrical equipment Info should be submitted by 801[0]

 KISENHUT, D 0 Division of Licensing 80/08/29 App
- M Antitrust correspondence
- 8009196091 Motion before US Court of Appeals for DC Circuit, for expedited consideration of petition for review re consolidation of Civil Action 80-1099 w/administrative proceeding M/Certificate of Svc Related correspondence JABLON, RA: LANDSMAN, RM Fiorida Cities JABLON, RA Spiegel & McDiarmid 80/09/15 5pp
- 8009300476 Response before US Court of Appeals for DC Circuit, in opposition to petitioners' motion for expedited consideration of Civil Action 80~1097 Certificate of Sycenci Related correspondence DYM, H, BOUKNIOHT. J A Florida Power & Light Co DYM, H Covington & Burling 80/09/25 5pp
- P Operating license stage documents & correspondence
- 8007020277 Bubmits interim criteria for shift staffing to all GL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D O Division of Licensing 80/07/31 7pp
- 8007080080 Forwards draft NUREO-0474, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0474 encl N/o NUREO EISENHUT.D & Division of Licensing 80/08/01 119pp
- 8007230052 Informs that exemption from fee re licensing action associated w/TMI~2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT,D 0 Division of Licensing 80/08/07 40pp

- E009040490 Responds to NRC 800728 ltr requesting opinion & advice re potential void rormation in vessel head Phenomena is unaffected by relatively small differences in fuel design Company would not analyze event unless asked by customer OMSLEY, 0 F Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 80/08/26 lp
- 6009110325 informs that util has contracted C-E for technical support to consultation in order to respond to questions re aspects of 800911 natural circulation cooldown at facility Responds to MRC 800912 ltr requesting technical opinion & advice SCHERER, A E Combustion Engineering, Inc. 80/09/05 2pp
- 8009150251 Forwards info re auxiliary feedwater sys in response to NRC 800502 request includes info re emergency operating procedure re alternate sources of auxiliary feedwater.pump area cordunatations & redundant condensate tank UHRIG.R E Florida Power & Light Co 80/09/10 3pp
- 8009140200 Forwards revised plans for monitoring noble gases which might be released from iteam plantiper TMI Lessons Learned Task Force short-term requirements UHRIO.R E Florida Power & Light Co 80/09/11 2pp
- 8009160378 Responds to NRC 800702 ltr re TMInrelated Tech Specs Proposed specs have been drafted & forwarded to onsite & offsite review committees for review & approval UHRIG.R E Florida Power & Light Co 80/09/12 lp
- 8009180444 Forwards response to NRC 800721 request for add1 info re adequacy of station electric distribution sys voltages UHRIO.R E Florida Power & Light Co 80/09/12 4pp
- 8009230306 Forwards updated response re natural circulation cooldown Emergency Operating Procedure 0120040 revised to address recognition of potential for upper head steam formation a cooldown rate necessary to prevent void formation UHRIG.R E Florida Power & Light Co 80/09/16 3pp
- Q Inspection reports. IE dulletins & correspondence
- 8009220182 Forwards IE Insp Rept 50-335/80-19 on 800609-10. No noncompliance noted STCHR.J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/06/26 2pp
- ---8009220184 IE Insp Rept 50-335/80-19 on 800609-10 No nencompliance noted Major areas inspected previous insp findings & IE Bulletin 79-18
 JERMINS.OR Region 2. Atlanta. Fuel Facility & Materials Safety Branch PERROTTI.D J Region 2. Atlanta. Defice of the Director 80/05/26 3pp
- 8009100049 Forwards IE Bulletin 80-18, "Maint of Adaquate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Written response required O'REILLY. J P Region 2, Atlanta, Office of the Director 80/07/24 Ip
- 8009030320 Suppls response to IE Bulletin 80-04, "Analysis of PNR Main Stream Line Break w/continued Feedwater Addition" Complete analysis of automatic auraliary feedwater initiation, supports installation of automatic sys UHR10, R E Garolina Power & Light Co 80/08/04 ip
- 8007240066 Forwards IE Insp Repts 50-335/80-23 % 50-389/80-09 on B00715-18 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/08/05 2pp
- ---8009240071 lE Insp Repts 50-335/80-23 & 50-389/80-09 on 800715-18
 No honcompliance noted Major areas inspected records
 associated w/work performance during outage in areas of
 installation welding, weld not control & core drilling
 VANDGORN.P K Region 2. Atlanta. Office of the Director
 HERDT.A R Region 2. Atlanta. Reactor Construction & Engineering
 Support Branch 80/08/04 6pp
- 8009020192 Submits response to IE Bulletin 79-03A Facility has no fusion welded SA-312 Type 304 stainless steel pipe in use or planned for use in safety-related sys

 UNR10,R E Florida Power & Light Co 80/08/06 ip
- 8009020306 Informs of visual & ultrasonic examinations on representative samples of circumferential welds in syscontaining stagnant oxygenated & borated water, per IE Bulletin 79-17 No stress corrosion in welds UHRIG, R E Florida Power & Light Co 80/08/14. lp

- 8007030158 Forwards Revision 1 to IE Bulletin 80-17. "Failures of Mercury-Wetted Matric Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REICLY. J P Region 2. Atlanta, Office of the Director 80/08/15 to
- 8009170374 Forwards corrected page for licensee 800804 response to lE Bulletin 80-05 re engineered safety feature reset controls UHRIO.R E Florida Power & Light Co 80/08/19 2pp
- 8009160143 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment 8ys " No written response required D'REILLY.JP Region 2. Atlanta. Office of the Director 80/08/22 is
- 8009120308 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Bovers 480 Volt Type K-6009 & K-DON 6009 Circuit Breakers "No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 50/08/27 lp
- 8009190137 Responds to 1E Bulletin 80-15 Fourteen manhours expended preparing rept & 434 manhours expended on corrective action UHRIG,R E Fiorida Power & Light Co 80/09/02 3pp
- B009290277 Forwards 1E Circular 80-21, "Regulation of Refueling Crews' No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/10 5pp
- 8009300152 Submits response to IE Bulletin 80-20 Westinghouse Type N-2 switches are used in safety-related 4160-volt switchgear Switches used do not use neutral function which caused problem referenced in bulletin UHRIO.R E Florida Power & Light Co 80/09/12 1p
- 8009300372 Forwards response to IE Bulletin 79-14, "Saismic Analysis for As-Built Safety-Related Piping Sys " UHRIQ.R E Florida Power & Light Co 80/09/19 609pp
- R Periodic operating reports & related correspondence
- 8009170279 Forwards monthly operating ropts for Aug 1980 SCHMIDT.A D Florida Power & Light Co 80/09/06 ip
- --800917028| Monthly operating repts for Aug 1980 CHILBON:V T Florida Power & Light Co 80/09/06 15pp
- S Reportable occurrences, LERs & related correspondence
- B009020365 Forwards LER 80-033/03L-0 SCHMIDT:A D Florida Power & Light Co 80/08/25 1p
- --B009020372 LER B0-033/03L-0 on B00724,while at 100% power, control element assembly 63 dropped to fully inserted position Caused by technician accidently shorting output of 15-volt power supply while taking routine voltage measurements PACE.P L Florida Power & Light Co B0/08/25 lp
- --8009120316 LER 80-034/03L-0 on 800818, during full power aperation. control element assembly (CEA) 41 dropped to full insertion Caused by failure of CEA 41 core power programmer 15-volt power supply Power supply replaced PACE, P L Florida Power & Light Co 80/09/02 1p
- 8009120307 Forwards LER 80-035/03L-0 SCHMIDT.A D Florida Power & Light Co 80/09/03 1p
- ~-8009120318 LER 80~035/03L-0 on 800804, during full power operation, control element assembly (CEA) 16 dropped to full insertion Caused by failure of CEA 16 core power programmer 15-volt power supply Power supply replaced PACE.P L Florida Power & Light Co 80/09/03 lp
- 8009150288 Forwards LER 80-036/03L-0 8CHMIDT.A D Florida Power & Light Co 80/07/03 lp
- --8009150290 LER 80-036/03L-0 on 800805, during full power operation. control element assembly 23 dropped to full Insertion Caused by failure In core element assembly core power programmer 15-volt power supply Power supply replaced PACE, P L Florida Power & Light Co 80/09/03 1p

- 8009300482 Forwards LER 80-040/03L-0 SCHMIDI, A D Fiorida Power & Light Co 80/09/15 1p
- --8009390485 LER 80-040/03L-0 on 800815, during startup node, control alement assembly 30 dropped into fully inserted position Cause Undetermined No corrective action necessary PACE.P L Florida Power & Light Co 80/09/15 1p
- DOCKET 50-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2
 F. Security, medical, emergency & fire protection plans
- BOOREDIBO Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency GRIER BH Region 1. Philadeiphia. Office of the Director BO/08/22 Spp
- Q. Adjudicatory correspondence
- 8007190322 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 CLAXX,R A Operating Reactors Branch 3 80/08/29 2pp
- --8009190328 Order for mod of License DPR-65 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 800101
 EISENRUT.D O Division of Licensing 80/08/27 6pp
- P Operating license stage documents & correspondence
- BOO9020297 Submits interim criteria for shift staffing to all QL & CP dicensees & applicants.per NRC 800507 ltr Discusses addinistrative provisions for emergency & overtime work Divelopment & implementation to be reviewed within 90 days EISENBUT, D O Division of Licensing 80/07/31 7pp
- BOO9180309 "Safety Evaluation of Inservice Testing Program for Pumps & Valves: "Interim rept 770426-801025 FEMRINGER.J M. ROCKHOLD.H C E000 Idaho, Inc FIN A-6258 8009180309 80/07/31 32pp
- OCOTOSOORO Forwards draft NUREG-0576, "Functional Criteria for Energency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0576 encl W/o NUREG EISENAUT.D 0 Division of Licensing 80/08/01 119pp
- BOO9120709 Forwards agenda of BOO921 meeting at util ofcs to discuss assessment of regulatory performance GRIER, B 2t Region 1, Philadelphia, Office of the Director BO/08/04 2pp
- BOOTE10553 Forwards add1 info requests re thermal hydraulics & accident & transient analysis sections of basic safety rept. & Cycle 4 reload safety analysis Requests add1 inforrequested on BOOTIO.18 & 27.by BOORIS to meet review schedule MOVAK.T.K Assistant Director for Operating Reactors 80/08/06 & 550
- BOO9230052 Informs that exemption from fee re licensing action associated w/IMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISEMMUT.D © Division of Licensing 80/08/07 60pp
- \$009180213 Confirms that two specific Event 5 valve configurations do not exist at facility Franklin Research Ctr Technical Evaluation Rept. "Primary Coolant Sys Pressure Isolation Valves:" encl CLARKR A Operating Reactors Branch 3 80/08/15 2pp
- -8009180219 "Primary Coolant Sys Pressure Isolation Valves." technical evaluation rept ROELLP N. STILWELL.T C Franklin Institute/Franklin Research Center. NRC-03-79-118 80/07/21 4pp
- QC993004B Forwards Amend 60 to License DPR-65, safety evaluation & notice of issuance & availability
 CLARK.R A Operating Reactors Branch 3 80/08/19 2pp
- -8009030054 Amend 60 to License DPR-65, changing Tech Specs to ailow containment electrical penetrations module replacement concurrent w/fuel movement TRAMMELL.C Operating Reactors Branch 3 80/08/19 7pp

- ---8009030058 Safety evaluation supporting Amend 60 to License DPR-65 # Orfice of Nuclear Reactor Regulation, Director 80/08/19 3p
- --B009630062 Notice of issuance & availability of Amend 60 to License DPR-65 TRAMMELL.C M Operating Reactors Branch 3 80/08/19 2pp
- 8009100454 Advises that mgt morting w/NRC in Berlin.CT has been rescheduled for 800911 Agenda encl GRIER.B H Region 1, Philadeiphia, Office of the Director 80/08/20 2pp
- B009050195 Forwards addl info on Cycle 4 relead to thermal-hydraulics, transient & accident analyses, & reactor physics & fuols, in response to NRC 800806 ltr CDUNSIL,W 6 Northeast Nuclear Energy Co (subs of Northeast Utilities) 80708725 26pp
- B009150247 Forwards addi info requested by NRC re design mod to Cycle 4 fuel assemblies & QA program in offect during design of Cycle 4 reload fuel COUNSIL, W G. FEE. W F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/08/27 App.
- B007030378 Advises that util will not meet deadline for implementation of NUPEG-057B requirements re emergency procedures & retraining for accidents & transcents NRC feedback needed COUNSIL, U G Couns
- B009050103 Application for amend to License DPR-65, incorporating proposed revisions to Tech Specs required to support plant operation Suring Cycle 4 reload CGU/911L,U G Northeast Nuclear Energy Co (subs of Northeast Utilities) B0/08/29 3pp
- --B009050105 Proposed revisions to Tech Specs required to support plant operation during Cycle 4 reload

 * Northeast Nuclear Energy Co (subs of Northeast Utilities)
 B0/09/29 28pp
- BO09190662 Requests Class (II fee for review of B00920 application for proposed Tech Spec changes re automatic initiation of auxillary feedwater sys Application involves consideration of single safety issue MILLER. W O License For Management Branch B0/09/02 ip
- B0091i0371 Requests that encl supporting document be docketed under Milistone KAPO.P S Assistant Disector for Core & Containment Systems 80/09/09 1p
- 8009180445 Advises that C-E owners group 800215,0630 & 0731 ltrs reasymmetric LOCA loads are applicable to Millstone Unit 2 & should be reparded as util response to NRC 780125 request COUNSIL.N G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/09/10 2ρρ
- BOO91BO357 Forwards implementation status of Catogory B TMI-2 lessons Learned requirements for each facility Echedules specifically identify items where requirement cannot be met or schedule is not foasible GOUNSIL. If G Connecticut Yankee Atomic Power Co CDUNGIL, If G Northeast Nuclear Energy Co (subs of Northeast Utilities) BO/09/15 43pp
- 8007290351 Application for amend to Licenses DPR-61.DPR-21 & DPR-65. incorporating revisions to Tech Specs for RGS per TMI-related requirements Fee encl COUNSIL.N G Connecticut Vankee Atomic Power Co COUNSIL.N G Northeast Utilities 80/09/16 App
- --B009290372 Proposed revisions to Tech Specs 3/4 4 3 for limiting condition for operation of RCS relief sys
 * Connecticut Yankee Atomic Power Co 78/12/00 3pp
- --8007270377 Proposed revisions to Tech Spect 1/4 4-34 re limiting conditions for operation of RCS relief valves-operating * Connecticut Yankee Atomic Power Co 80/07/30 ip
- --8007290381 Proposed revisions to Tech Specs 3/4 4 4 for limiting canditions for operation of RCS pressurizer
 * Connecticut Yankee Atomic Power Co 80/09/30 2pp
- --8009290384 Proposed revisions to Tech Specs 3/4 4 5 for RCS steam generators * Connecticut Yankee Atomic Power Co 80/09/30 ip

- --8009250397 Proposed revisions to Tech Specs 6 0 for administrative controls
 - Connecticut Yankes Atomic Power Co 80/09/30 3pp
- 8009300179 Forwards nonproprietary & proprietary repts, "Guide Thimble Inset Dasign " Hithholding application & affidavit encl Proprietary version withhold (ref 10CFR2 790) CGUISIL N O Northeast Utilities 80/09/18 16pp
- --8009300183 "Guide Thimble Inset Design," nonproprietary version * Northeast Utilities 80/09/30 15pp
- BOO930291 Corrects typographical error in Tech Spec Table 3 9-1 of Amend 60 to License EPR-65 Doors 252 & 297, listed as servicing solidification sys area, should be 292 & 207 COURBLA 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) BO/09/22 ip
- G Inspection reports. IE Bulletins & correspondence
- 6009150032 Forwards IE Insp Repts 50-245/80-10 & 50-336/80-07 on 800501-0705 No noncompliance noted BRUMNER,E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 60/07/14 2pp
- --BG09150928 IE Insp Repts 50-245/B0-10 & 50-336/B0-07 on 800601-0705
 No noncompliance noted Major areas inspected control room.
 accessible portions of Unit 1 reactor & intale bldgs. Unit 2
 encl & condensate polishing facility
 KEIMIO.R R Region 1, Philadelphia, Reactor Operations Nuclear
 Support Branch SHEDLOSKY, J T , ZIMMERMAN, R P Region 1,
 Philadelphia, Office of the Director 80/07/11 7pp
- 8009:10482 Responds to IE Bulletin 80-16 re Rosemount.Inc pressure transmitters Model 1151 or 1152 Util does not plan to install sub; transmitters at facility COUNSIL.N G Northeast Utilities 80/07/31 1p
- 8009150465 Discusses 800805 meeting w/util re physical protection program insp findings & forwards outline of corrective actions Encl withheld (ref 100FR2 790) ORIER-8 H Region 1. Philadelphia. Office of the Director 80/08/07 lp
- 8009100109 Updates 800716 response to IE Bulletin 79-02. Revision 2. "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Boits." by forwarding revised list of seismic Category 1 supports on block calls using subj bolts CDUNSIL.U Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/08/11 &pp
- 8007030031 Forwards Revision I to 1E Builetin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER.8 H Region I, Philadelphia, Office of the Director 80/08/15 Ip
- 8009180017 Forwards IE Circular 80-18, "100FR50 59 Bafety Evaluations for Changes to Radwaste Treatment Sys " No written response
- 8009120190 Forwards IE Info Notice 80-31: "Maloperation of Gould-Brown Bover: 480 Volt Type K-6005 & K-DON 6005 Circuit Breakers" No written response required CRIER.8 H Region), Philadelphia, Dffice of the Director 80/03/27 Ip
- 8007230791 Forwards IE Circular 80-21. 'Regulation of Refueling Crews " No written response required CRIER.8 H Region 1. Philadelphia, Office or the Director 80/09/10 ip
- 6009240319 Forwards IE Info Notice BO-32, "Clarification of Cartain Requirements for Euclusive-Use Shipments of Radioactive Hatls "No written response required GRIER-BH Region 1. Philadelphia, Office of the Director 80/09/12 ip
- A Periodic operating reports & related correspondence
- 8009020283 "Semiannual Radioactive Effluents Release Rept.Jan-June, Northeast Fluclear Energy Co (subs of Northeast Utilities) 80/08/29 100pp

- 8009230345 Forwards monthly operating rept for Aug 1980 MRDCZKA,E J Northeast Utilities 80/09/18 lp
- --8099230347 Monthly operating rept for Aug 1980 HOWLETT, G H Northeast Utilities 80/09/03
- S Reportable occurrences, LERs & related correspondence
- B009020284 Forwards LER 80-027/03L-0 MRGCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Utilities) B0/08/25 ip
- --8009020285 LER BO-027/03L-O on 800729, during steady state power operation, leak from failed wocket weld found on fitting in 1-inch safety injection tank recirculation line Caused by crack due to long-term fatigue attributed to vibration. HARRIS.J 8 Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/08/25 2pp
- 8009160457 Forwards LERs 80-028/03L-0.80-029/03L-0 & 80-030/03L-0 MR0CZMA.E J Northeast Utilities 80/09/08 lp
- --8009160461 LER 80-028/03L-0 on 800811.at 100X power, control element assembly 41 dropped from 180 to zero steps Caused by faulty jumper cable from refuel disconnect panel to reactor head Power reduced & assembly reallgned Replacement planned MARRIS.J 8 Northeast Utilities 80/09/08 19
- ---B009160464 LER 80-029/03L-0 on 800812, during surveillance test on 12 U diesel, 125 VDC ground alarm received Caused by frayed ansulation on wire in Bondix connector allowing contact between bare wire & connector shell Wire recovered HARRIS, J S Northeast Utilities 80/09/08 lp
- --B009160469 LER B0-030/OSL-0 on B00812 during routine operation, containment air temp exceeded 120 F Caused by svc water temp control valve to reactor bidg closed cooling water heat exchangers being set too high Valve readjusted HARRIS. J S Northeast Utilities 80/09/08 1p
- 8009190460 Forwards LERs 80-028/03L-0,80-029/03L-0 & 80-030/03L-0 MRDCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Ut(11ties) 80/09/08 ip
- --B009190531 LER 80-028/03L-0 on B00B11 during steady state 100% power operation control element assembly 41 dropped to zero steps from 180 steps Apparently caused by faulty jumper cable from refuel disconnect panel to reactor head HARRISJ S Northeast Nuclear Energy Co (subs of Northeast Utilities) B0/09/08 ip
- --8009190537 LER 80-029/03L-0 on 800812, during 120 diesel surveillance testing, 125 VDC (Bus 201A) ground alarm was received Caused by frayed insulation on one wire in Bendix connector Frayed HARRIS, J S Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/09/08 ip
- --B009190543 LER BD-030/O3L-0 on 800B12 during routine power aperation, containment air temp found in excess of 120 F limit Caused by svc water temp control valve to reactor bidg closed cooling water heat exchangers set too high Valve readjusted HARRIS. J S Northeast Nuclear Energy Co (subs of Mortheast Utilities) B0/09/OB Ip
- B009260649 Forwards LER 80-031/03L-0 MRDCZKA, E J Northeast Utilities 80/09/12 1p
- --B009260654 LER B0-031/03L-0 on B00817.one of two mln channels of wide range neutron flux instrumentation required for Mode 5 failed Caused by defective preamplifier Component replaced HARRIS.J S Northeast Utilities B0/09/12 1p
- DOCKET 50-338 NORTH ANNA POWER STATION, UNIT 1
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 8009150523 FES for facility * Office of Nuclear Reactor Regulation, Director NUREG-0134 ADD 2 80/08/31 53pp Available at NTIS \$3 25

- F Security, medical, emergency & fire protection plans
- 8009230273 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency O'REILLY, J P Region 2. Atlanta, Ornice of the Director 80/08/22
- 6009230320 Forwards revised nuclear security personnel training & qualification program Program withheld (ref 10CFR2 790)
 SYLVIA:B R Virginia Electric & Power Co 80/09/19 1p
- 8009260182 Requests extension of 30 days to respond to 800804 request that emergency plan be revised Request is based on scope of revision % internal review required SYLVIA, B R Varginia Electric % Power Co 80/09/22 ip

G Adjudicatory correspondence

- 8009260615 Forwards order requiring inro supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 CLARK.R A Operating Realtors Branch 3 80/08/29 2pp
- --8009260624 Order for mad of License NPF-4 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment info should be submitted 801101 by BOITOI EISENNUT.DG Division of Licensing 60/08/29 App
- 8009230629 Advises of changes to Station Settlement Procedure 1-PT-;11 per ALAB-578 Settlement monitoring Points i1.12.13 & 14 & all reference to Units 3 & 4 svc water pump house have been SYLVIA.B R Virginia Electric & Power Co 80/09/19 1p

H General correspondence

- operations. DENTON. H R O
- J Insurance & indemnity information
- 8009090384 Forwards Endorsement 1 to NEL1A Binder EB-70 ANDREMS,C L Marsh & McLennan inc . M & M Nuclear Consultants,inc Dis 80/09/03 2pp
- P Operating license stage documents & correspondence
- E009110610 Forwards request for add1 info re bypass & reset of engineered safety features per review of 790113 & 1220 submittals Requests response within 30 days CLARK.R A Operating Reactors Branch 3 80/07/10 4pp
- BO09020297 Submits interim criteria for shift staffing to all OL & CP licensues & applicants.per NRC 800507 itr Discusses administrative provisions for omergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D C Division of Licensing 80/07/31 7pp
- 8009050080 Forwards draft NUREG-0496, "Functional Criteria for Considered Financial Order Notice-Order, Foliational Criteria Foliation Response Facilities "Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREQ-0696 encl W/o NUREQ EISEKAUT.D Q Division of Licensing 80/08/01 119pp
- BOOT230052 laforms that exemption from fee re licensing action associated av/IMI-2 Lessons Learned is unjustified Previous determination should be disregarded Roquested submittal should include proposed class of amend EISENHUT.D & Division of Licensing 80/08/07 60pp
- EQ09190794 Forwards revised Westinghouse STS 3 9 B 2,3 9 10 & Bases 3/4 9 8 2/4 9 10 to require 23 ft of water over top of reactor pressure yeasel flange during movement of fuel assembles or control road Written response required MOVAK.T H Assistant Director for Operating Reactors 80/08/15
- --8007190317 Revised Westinghouse STS 3 9 8 2.3 9 10 b Daxes 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods

 * Assistant Director for Operating Reactors 80/06/23 2ipp

- 8009090881 Advises that Class II fee is required for review associated w/issuance of Amend iB on 800519
 MILLER,W O License Fee Management Brench 80/08/22 ip
- BO07030426 Requests amend to OLs consisting of changes to Tech Specs & to ETS Proposed changes encl FERGUSDN, J H Virginia Electric & Power Co 80/08/28 4pp
- ---8009030428 Proposed Tech Spec & ETS changes transferring independent review responsibility from existing Sigs Nuclear Safety Operating Committee to Safety Evaluation & Control staff # Virginia Electric & Power Co 80/08/28 44pp
- 8009090344 Application to amend Licenses NPF-4 & NPF-7.transferring independent review responsibility from sys nuclear safety & operating committee to safety evaluation & control staff & audit responsibility to GA dept Received w/o encl theck FERGUSON.J H Virginia Electric & Power Co 80/08/28 4pp
- --8009090347 Proposed Tach Spec changes to Section 6 transferring independent review responsibility from sys safety & operating committee to safety evaluation & control staff & audit responsibility to GA dept

 4 Virginia Electric & Power Co 80/08/28 35pp
- --8009090352 Proposed ETS change to Section 5 transferring independent review responsibility from sys safety & operating committee to safety evaluation & control staff % audit responsibility to 0A dept

 # Virginia Electric & Power Co 80/08/28 9pp
- 8009110431 Forwards FPRI repts on resin intiusions into boilers & steam generators per NRC request Concurs w/EPRI conclusions,which are applicable, in part, to facility SYLVIA.B R Virginia Electric & Power Co 80/09/08 ip
- --8009110433 EPRI Repts RP-623-3, first & second progress repts.Apr & Jun.
 1979, respectively, RP-623-1, fourth progress rept, Jul 1979 &
 RP-1563-2, first progress rept, June 1980 Repts concern resin
 intrusions into boilers & steam generators
 Electric Power Research Institute 80/09/08 600pp
- 8009160429 Forwards for in response to NRC 800822 request for payment re issuance of Amend 18 to License NPF-4
 BAUM.E A Virginia Electric & Power Co 80/09/11 1p
- --8009160423 Submits info re util 800911 fee payment D1898.R M License Fee Management Branch 80/09/15 ip
- 8009260829 Requests analysis of precision obtainable from direct measurement sys for svc water pipe expansion joints as compared w/existing indirect sys & cost estimate for implementation NOVAK. T H Assistant Director for Operating Reactors 80/09/12
- 8097190525 Bubmits info re maintaining min of 23 ft of water over reactor vessel flange during fuel movement, in response to NRC 800815 ftr Changes to Tech Specs to include RHR sys requirements identified in NRC 800611 ltr being reviewed SYLVIA,B R Virginia Electric & Power Co 80/09/16 2pp
- 8009230287 Bubmits update re secondary chemistry program Facility maintains secondary chemistry in compliance w/Westinghouse all volatite treatment guidelines Until evaluation is completed,Unit i Powder units will operate in bygass mode Virginia Electric & Power Co 80/09/17
- 8009220134 Forwards comments on NUREQ-0696 in response to NRC 800801 request Implementation of requirements according to time schedula not considered feasible Requests meeting to discuss preliminary plan re effective emergency response facilities FEROUSDN.J H Virginia Electric & Power Co 80/09/18 16pp
- 8007230272 Notifies of delay until Oct 1780 of responses to NRC 800710 & 25 requests for addi info re bypass & reset engineered safety feature actuation signals
 SYLVIA:BR Virginia Electric & Power Co 80/07/18 ip
- 8009290349 Provides addl info re electrical distribution sys voltages Designs enci SYLVIA.B R Virginia Electric & Power Co 80/09/24 23pp.
- 8009300249 Forwards addl info re multiple structure amplified response spectra evaluation of piping sys design, per NRC BO0725 request Table 1, identifying status of each problem 2 basis for acceptability under Phase I affort.encl
 BYLVIA.B R Virginia Electric & Power Co 70/09/24 9pp

- @ Inspection reports. IE Builetins & correspondence
- 8009100056 Forwards (E Bulletin 80-18, "Maint of Adequate Min Flow Through Centrirugal Charging Pumps Following Secondary Bide High Energy Line Rupture " Written response required O'REILLI, J P Region 2, Atlanta, Orrice of the Director 80/07/24
- 8009020242 Submits response to IE Bulletin 79-03A For North Anna, no SA-312 or A-312. Type 300 series fosion welded pipe in Use at greater than 85% design stress For Surry, eight fittings determined in eicess of 85% design stress SYLVIA.8 R Virginia Electric & Power Co 80%08/08 2pp
- 800903014) Forwards Revision I to 1E Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY. J P Region 2. Atlanta, Office of the Director 80/09/15
- 8009230097 Submits supplemental response to IE Bulletén 79-18 Design change to provide visual evacuation signal in diesel generator rooms will be completed by 800920 SYLVIA.B R Virginia Electric & Power Co 80/08/21 lp
- 8009160172 Forwards IE Circular 80~18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required D'REILLY, J P Region 2 Atlanta, Office of the Director 80/08/22
- 8009120031 Responds to IE Bulletin 80-19 Surry Units 1 & 2 do not use mercury-wetted relays in reactor protection sys No response for North Anna Units 1 & 2
 SYLVIA.B R Virginia Electric & Power Co 80/08/27 2pp
- E009(20314 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-600S 1 X-DON 600S Circuit Breakers "No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 60/08/27 is
- 8009240399 Forwards response to IE Builetin 80-15 re possible loss of emergency notification sys w/loss of offsite power Design change initiated to change power supply to vital bus Administrative Procedure 27 & revised Affidavit encl SYLVIA.B R Virginia Electric & Power Co 80/09/05 3pp
- 8009260517 Forwards IE Circular 80-21, 'Regualtion of Refueling Crews " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/10 Son
- 8009150237 Forwards response to NRC 800920 ltr re violations noted in IE Insp Repts 50-338/80-29 & 50-339/80-28 Corrective actions specific instructions given to control room operators re when to place channel in tripped condition SYLVIA.B R Virginia Electric & Power Co 80/09/12 4pp
- 800730D116 Forwards response to IE Bulletin 80-20 Hestinghouse Type W-2 control switch applications found Sub; switches have been tested satisfactorily SYLVIA:8 R Virginia Electric & Power Co 80/09/15 App
- 8009300255 Summarizes results of extensive steam generator insp performed during refueling outage Intention to install steam generator insp ports should be reconsidered until after more insps are performed SYLVIA.BR Virginia Electric & Power Co 80/09/26 4pp
- R Pariodic operating reports & related correspondence
- 8009050329 Forwards "Radioactive Effluent Release Rept for North Anna Power Station," Jan - June 1980 SYLVIA.B R Virginia Electric & Power Co 80/09/02 12p
- ---8009050335 "Radioactive Effluent Release Rept for North Anna Power Station," Jan-June 1980 OILDERT, J D. HOPPER, D M. CARTHRIGHT, W.R. Virginia Electric & Power Co. 80/09/02 229pp
- 8009290319 Forwards monthly operating repts for Aug 1980 SYLVIA.B R Virginia Electric 9 Power Co 80/09/15 1
- ~~8009290321 Monthly operating repts for Aug 1980 WOODSHALL, W A . NEUFER, A G Virginia Electric & Power Co 80/09/09 9po

- 8007230356 Forwards corrections to monthly operating repts for Aug 1980 SYLVIA.8 R Virginia Electric & Power Co 80/09/17 [p
- --8009230360 Corrected operating repts for Aug 1980 NEUFER, A G Virginia Electric & Power Co 80/09/09 2pp
- S Reportable occurrences. LERs & related correspondence
- 8007050026 Disagrees w/util plan to shut off recirculation flow as interim fix re low flow from auxiliary feed pump 1-FM-P-3D discussed in LER 80-061/017-0 Recirculation flow path should be retained to protect pump CHECK.P 8 Assistant Director for Plant Systems 80/08/04 ip
- 8009120702 Part 21 rept re potential nonconservatism in indicated feedwater flow due to fouling of feedwater venturi Detailed engineering evaluation is being performed SYLVIA, 8 R Virginia Electric & Power Co 80/08/15 3pp
- 8009030555 Forwards LER 80-068/03L-0 CARTWRIGHT.W R Virginia Electric & Power Co 80/08/27 19
- --8009030561 LER 80-068/03L-0 on 800801.during full power.electrical load discovered as having boen added to 1H emergency bus w/o approved jumper Caused by improper administrative controls Load isolated from emergency bus & personnel reinstructed CARTWRIGHT, W R Virginia Electric & Power Co 80/08/27 2pp
- 8009030606 Forwards LER 80-061/01X-1 CARTWRIGHT.W R Virginia Electric & Power Co 80/08/27 1p
- --BCO9030A14 LER 80-041/01X-1 on BO070B. StW review indicated that under accident conditions.auxiliary feedwater pump 1-FW-P-3B may not be able to function as designed Cause unknown Testing on pump will be conducted to determine pump flow capacity CARTWRIGHT.W R Virginia Electric & Power Co 80/08/27 2pp
- B009030627 Forwards LER 80-069/03L-0
 CARTWRIGHT, W R. Virginia Electric & Power Co B0/08/27 19
- --8007030632 LER 80-069/03L-0 on 800801, while operating in Mode 1 at 160X power, sample analysis indicated boron concentrations in success of Tech Spec limit Caused by stratification of boric aced in either accumulator or makeup source (RNST) CARTWRIGHT, W R Virginia Electric & Power Co 80/08/27 2pp
- 8009033442 Forwards LER 80-072/03L-0 CARTWRIGHT.W R Virginia Electric & Power Co 80/08/27 ip
- --8009030649 LER 80-072/03L-0 on 800808 containment bulk average temp exceeded Tech Spec limit Caused by operation during period of high outside temp Temp returned to 105 F within 4-h No corrective action necessary CARTHRIGHT, WR Virginia Electric & Power Co 80/08/27 2pp
- 8009030653 Forwards LER 80-070/03L-0 GARTWRIGHT, W R Virginia Electric & Power Co 80/08/27 lp.
- ---B009030658 LER B0--070/03L-O on 800814, containment air particulete high flow alarm was actuated Caused by dislocated high flow relay suitch Soutch replaced & loose relay socket tightened CARTWRIGHT, W R Virginia Electric & Power Co 80/08/27 2pp
- 8009030512 Forwards LER 80-071/017-0 CARTHRIGHT.W R Virginia Electric & Power Co 80/08/29. Ip
- ---B009030623 LER 80-071/017-0 on 800818, review per IE Bulistin 79-018 indicated info inadequate to demonstrate environ qualification of signal processors Operators alerted to possible erroneous indication from processors CARTWRIGHT, W R Virginia Electric & Power Co 80/08/29 20p
- 8009090499 Forwards LER 80-074/03L-0 CARTWRIGHT.W R Virginia Electric & Power Co 80/09/03 is
- --8009090512 LER 80-074/03L-0 on B00810.w/unit in Mode 1.axial flux difference deviated greater than 5% from target & quadrant power tilt ratio exceeded 1 02 Caused by xenon transient during & after load reduction CARTWRIGHT.W R Virginia Electric & Power Co 80/09/03 2pp
- E009090541 Forwards LER 80-065/03L-0
 GARTHRIGHT.W R Virginia Electric & Power Co 60/09/05 lp.

- --8309090584 LER 80-065/03L-0 on 800807-09, w/unit at 100% power aperation, control room operator reported pressuriier protection channel III level indication approx 6/ higher than indications on channels I & II CARTWRIGHT, W R Virginia Electric & Power Co 80/09/05 2pp
- 8009220243 Forwards LER 80-067/03X-1 CARTWRIGHT, W R Virginia Electric & Power Co B0/09/16 ip
- E009220251 Forwards LER 80-073/03L-0 CARTWRIGHT.W R Virginia Electric & Power Co 80/09/16 ip
- --8009220306 LER 80-073/03L-0 on 800818, operability of one low head safaty injection sys was compromised when MOV-1863A valve was demensized Caused by need to rework weld on leaking drain valve Held reworked & tested satisfactority CARTWRIGHT, W R Virginia Electric & Power Co 80/09/16 2pp
- 8009220369 Forwards LER 80-076/03L-0 GARTW91GHT.W R Virginia Electric & Power Co 80/09/16 ip
- --B009220373 LER 80-076/OSL-0 on 800820 w/unit in Mode 1. discovered that casing cooling pump 1-R8-P-3A test had not met acceptance criteria Caused by personnel failure to notice that differential pressure was above acceptable limits CARTHRIGHT, W R Virginia Electric & Power Co 80/09/i6 2pp
- 8309230605 Forwards LER 80~075/03L-0 CARTHRIGHT, WR Virginia Electric & Power Co 80/09/18 ig
- --GOD9230619 LER BO-079/03L-O on BO0904, in Mode I at 100% power, sample analysis of SI accumulator 1B revealed excessive boron concentration Caused by stratification of stagnant solution in accumulator Concentration diluted
 GARTMRIGHT, W R Virginia Electric & Power Co 80/09/18 2pp
- 8009230622 Forwards LER 80-077/03L-0 CARTWRIGHT,W R. Virginia Electric & Power Co 80/09/18 ip
- --8009230634 LER 80-077/03L-0 on 80082i.performing ECCS valve position verification, incorrect valve alignment affecting both LHSi pump min flow recirculation paths discovered Cause relates to change in RHAT flow path alignment to reduce temp CARTHRIGHT.W R Virginia Electric & Power Co 80/09/18 2pp
- DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2
- D #RC Draft/Final Environmental Statements, suppls & correspondence
- 8009150923 FES for facility + Office of Nuclear Reactor Regulation, Director NUREG-0134 ADD 2 80/08/31 53pp Available at NTIS \$3 25
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- B009110505 EER for facility, Suppl 12
 # Office of Nuclear Reactor Regulation, Director NUREG-0053 S12,
 B0/08/31 9pp Available at NTIS \$1.75
- 8009240636 Forwards Suppl 12 to SER, addressing issue of emergency preparedness W/o enci YOUNGBLOOD, B J Licensing Branch 1 80/09/00 3pp
- F Security, medical, emergency & fire protection plans
- BC09230273 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency O'REILLY, J P Region 2, Atlanta, Office of the Director BO/08/22
- EOO9300056 Summary of 800812 meeting w/util. State of VA & FEMA in Bythesda. MD re discussion of joint emergency plan exercise at plant site DRDMERICK, A w Licensing Branch 1 80/09/12 4pp
- 8007230320 Forwards revised nuclear security personnel training qualification program Program withheld (ref 100FR2 790)

 BYLVIA,B R, Virginia Electric & Power Co 80/09/19 1p

- 8009260182 Requests extension of 30 days to respond to 800804 request that emergency plan be revised Request is based on scope of revision & internal review required SYLVIA.B R Virginia Electric & Power Co 80/09/22 ip
- G Adjudicatory correspondence
- 8007£30629 Advises of changes to Station Settlement Procedure 1-PT-iii per ALAB-578 Settlement monitoring Points i1, i2, i3 % i4 % ail reference to Units 3 % 4 svc water pump house have been deleted
 SYLVIA, R R Virginia Electric & Power Co 80/07/19 ip
- H General correspondence
- 8009220033 Responds to 800805 request to reconsider decision to delay startup of facility NRC has not decided to delay issuance of full power OL License will be issued upon completion & FEMA approval of emergancy preparedness scorcise
 INGRAM, F Office of Public Affairs 80/08/13 ip
- --8009220037 Urges reconsideration of decision to delay facility startup Danger of nuclear accident extremely small Alternatives present greater risk BANDORTH.C 8 Affiliation Unknown 80/08/05 ip
- 8009090436 Responds to encl Hotetourt County Chamber of Commerce 800626 request to FERC for info re when facilities will be operational Lists status of plant operating schedules DENION.H R Office of Nuclear Reactor Regulation. Director 80/09/05 300
- J Insurance & indemnity information
- 8009090384 Forwards Endorsement 1 to MtLIA Binder E8-70 ANDREMS.C L Marsh & MtLennan: Inc . M & M Nuclear Consultants, Inc Div 80/09/03 2pp
- P Operating licenso stage documents & correspondence
- 800908008D Forwards draft NUREC-0676, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREC-0676 enci W/o NURECO EISENHUT. D C Division of Licensing 80/08/01 119pp
- BD09090330 Responds to B00802 talcon re Commission decision to defer issuance of full power license Review of SER found emergency preparedness matters not completed License & Tech Specs were still being modified for review AMEARNE. J F Commission B0/08/08 2pp
- --8009090333 Requests that Commission reconsider NRC staff recommendation that util be permitted to operate facility Test of emergency evacuation procedures scheduled for 900816 DALTON-JN Virginia, State of 80/08/02 2pp
- 8009090346 Responds to 80080; teicon re Commission decision to defer issuance of full power license Review of SER found emergency preparedness matter not completed License & Tech Specs were still being modified for review AHEARKE, J. F. Commission 80/08/08 2pp
- --8009090349 Requests that Commission reconsider 800731 action denying util permission to begin commercial operation of facility NALSKE.C. Atomic Industrial Forum 80/08/01 1p
- 8009050192 Forwards Amend 2 to License NPF-7, safety evaluation & notice of issuance & availability YOUNGBLOOD, B. J. Licensing Branch 1 80/08/18 3pp
- --8009050196 Amend 2 to License NPF-7 permitting conduct of water hammer domanstration test YOUNGBLOOD. 8 J Licensing Branch 1 80/08/18 2pp
- --8009050201 Bafety evaluation supporting Amend 2 to License NPF-7

 # Office of Nuclear Reactor Regulation, Director 80/08/18 3pp
- --8009050204 Notice of issuance & availability of Amend 2 to License RPF-7 YOUNGELOOD, B. J. Licensing Branch 1 80/08/18 2pp
- 8009160656 Forwards License NPF-7 w/App A to Tech Specs,FR notice & NUREO-0664 EISENBUT, D 0 Division of Licensing 80/08/21 3pp

- -- 8009160657 License NPF-7 for facility authorizing operation at 1007 DENTO(), H R Office of Nuclear Reactor Regulation, Director
- --B009160659 Natice of issuance of License NPF-7 for operation at 100% power YOUNGSLOOD.B J Licensing Branch 1 80/08/21 2pp
- --8009160661 Revision 1 to facility Tech Specs.App A to License NPF-7

 * Assistant Director for Operating Reactors NUREO-0664 R1
 80/08/31 420pp Available at GPO \$9.00
- --8009160663 ETS (radiological & nonradiological). App A to License NPF-7 * Assistant Director for Operating Reactors NUREG-0664 Rt 80/08/31 59pp
- 8009090863 Advises that util met NRC requirements by completion of Condition 2 C (5) to License NPF-7.dtd 800828 Matter EISENHUT, D.G. Division of Licensing 80/08/22 3pp
- 8009030426 Requests amend to OLs consisting of changes to Tech Specs & FERGUSON. J H Virginia Electric & Power Co 80/09/28 4pp
- --B009030428 Proposed Tech Spac & ETS changes transferring independent review responsibility from existing Sys Nuclear Safety Operating Committee to Safety Evaluation & Control staff * Virginia Electric & Power Co 80/08/28 44pp
- 8009090344 Application to amend Licenses NPF-4 & NPF-7, transferring independent review responsibility from sys nuclear safety & operating committee to safety evaluation & control staff & audit responsibility to GA dept Received w/o encl check FERGUSON, J H Virginia Electric & Power Co 60/08/20 4pp
- ~~8009090347 Proposed Tech Spec changes to Section 6 transferring independent review responsibility from sys safety & operating committee to safety evaluation & control staff & audit responsibility to GA dept

 # Virginia Electric & Power Co 80/08/28 35pp
- ~~8009090352 Proposed ETS change to Section 5, transferring independent review responsibility from sys safety & operating committee to safety evaluation & control staff & audit responsibility to QA dept ◀ Virginia Electric & Power Co 80/08/28 9pp
- 8009190658 Notification of rescheduled 800909-10 meeting w/util at site to discuss pump & valve inservice testing Meeting originally scheduled 800826-27 DROMERICK, A W Licensing Branch 1 80/08/20 4pp
- 8009110868 "North Anna Power Station Unit 2 Tech Specs.App A to License NPR-7 "
 * Commission NUREO-0664 Ri 80/08/31 250pp
- 8009090394 Forwards 38 detailed support drawings for pipe supports installed on low head safety injection discharge piping shown on 12050-MSK-104B-5, for use in performing independent verification of SXN pipe stress analysis
 SYLVIA, B.R. Virginia Electric & Power Co. 80/09/02 39pp
- 8009090640 Forwards questions & comments re pumps & valves inservice testing program to be used as basis for 800909-10 meeting agenda
 Agenda
 TEDESCO.R L Assistant Director for Licensing 80/09/05 18pp
- B009150319 Notifies that facility is operating at 30% power Neutron shield test completed b levels are lower than expected Plant will be operating at 50% power by 800911 YOUROBLOOD, B J Licensing Branch | 8009911 | 1p
- 8009260529 Requests analysis of precision obtainable from direct measurement sys for syc water pape expansion joints as compared w/existing indirect sys & cost estimate for implementation MOVAK. TM Assistant Director for Operating Reactors 80/09/1 Assistant Director for Operating Reactors 80/09/12
- 8009190525 Submits info re maintaining min of 23 ft of water over reactor vessel france during fuel movement, in response to NRC 800815 ltr Changes to Tech Specs to include RHR sqs requirements identified in NRC 800611 ltr being reviewed. SYLVIA, B R Virginia Electric & Power Co 80/09/16 2pp

- 8009223134 Forwards comments on NUREC-0496 in response to NRC 800801 request Emplementation of requirements according to time schedule not considered feasible Requests meeting to discuss preliminary plan re effective emergency response facilities FERGUSON, J H Virginia Electric & Power Co 80/09/18 1app
- 8009290490 Forwards Pages 3/4 4-4 & 3/4 4-5 of Tech Specs to substitute sections incorrectly numbered YOUNG, B J Licensing Branch 1 80/09/19 2pp
- -8009290496 Currected pages incorporting corrected Sections 3 4 1 4.4 4 1 3 1-4.3 4 1 5.3 4 2 & 4 4 2 of Tech Specs reboren concentrations Licensing Branch i 80/09/19 4pp
- G Inspection reports, 1E Bulletins & correspondence
- 8007100056 Forwards IE Bulletin 80-18. "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Bide High Energy Line Rupture" "Written response required O'REILLY, J F Region 2. Atlanta, Office of the Director 80/07/24
- 8007020242 Submits response to IE Bulletin 79-03A For North Anna no SA-312 of A-312. Type 300 series fusion welded pipe in use at greater than 857 design stress For Surry, eight fittings determined in excess of 85% design stress SYLVIA.B R Virginia Electric & Power Co 80/08/08 2pp
- 8009030141 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Morcury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J.P. Reg Region 2, Atlanta, Office of the Director 80/08/15
- 8009160172 Forwards IE Circular 80-18, "10CFRSO 59 Bafety Evaluations for Changes to Radwaste Treatment Sys " No written response required
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22
- B009120031 Responds to IE Bulletin 80-19 Surry Units 1 & 2 do not use mercury-wested relays in reactor protection sys No response for North Anna Units 1 & 2 SYLVIA, B R. Virginia Electric & Power Co. 80/08/27 2pp
- 8009120314 Forwards IE Info Notice 80-31, "Maloperation of Could-Brown No written response required
 O'REILLY, J P Region 2. Atlants, Office of the Director 80/08/27
- B009240399 Forwards response to IE Bulletin B0-15 re possible loss of emergency notification sys w/loss of offsite power Design change initiated to change power supply to vital bus Administrative Procedure 29.6 revised Affidavit encl SYLVIA, B R Virginia Electric & Power Co 80/09/05 3pp
- 8009260517 Forwards IE Circular 80-21, "Requaltion of Refueling Crews " No written response required O'REILLY,J P Region 2, Atlanta, Office of the Director 80/09/10
- 8009190257 Forwards response to NRC 800820 ltr re violations noted in IE lnsp Repts 90-338/80-27 & 50-339/80-28 Corrective actions specific instructions given to control room operators re when to place channel in tripped condition SYLVIA.B R Virginia Electric & Power Co 80/09/12
- 8009300114 Forwards response to IE Bulletin 80-20 Westinghouse Type M-2 control switch applications found Subj switches have been tested satisfactorily BYLVIA.B R Virginia Electric & Power Co 80/09/15 3pp
- R Periodic operating reports & related correspondence
- B007050329 Forwards "Redioactive Effluent Release Rept for North Anna Power Station:" Jan June 1980 SYLVIA:8 R Virginia Electric & Power Co 80/09/02 12p
- ---B009050333 "Radioactive Effluent Release Rept for North Anna Power Station: "Jan-June 1980 GILBERT.J D. HOPPER.D M., CARTHRIGHT.W R Virginia Electric & Power Co 80/09/02 225pp
- BO09290317 Forwards monthly operating repts for Aug 1780 BYLVIA: B R Virginia Electric & Power Co 80/09/15

- --8007270321 Monthly operating repts for Aug 1980
 WIGDSMALL.W A . NEVFER, A G Virginia Electric & Power Co
 80/09/09 9pp
- 8009230356 Forwards corrections to monthly operating repts for Aug 1980 54LVIA, B R Virginia Electric & Power Co 80/09/17 1p
- --8009230360 Corrected operating repts for Aug 1980 NEUFER, A 0 Virginia Electric & Power Co 80/09/09 2pp
- S Reportable occurrences. LERs & related correspondence
- BOO9030567 Forwards LER 80-043/03L-0 CARTURIGHT.W R Virginia Electric & Power Co 80/08/27 1p
- --8009030571 LER 80-043/03L-O on 800814 during Hode 5 operation, pressurizer power relief valve declared inoperable when nitrogen gas supply required for overpressure protection dropped below 1.775 psig Caused by low nitrogen pressure CARTURIOHT.W R Virginia Electric & Power Ca 80/08/27 2pp
- E009030576 Forwards LER 80-044/03L-0 CARTHRIGHT,W R Virginia Electric & Power Co 80/08/27 ip
- --8009030586 LER 80-044/031-0 on 800730 during Mode 2 generation at 3% power bypass feedwater regulator valve failed open causing high water level in steam generator A Caused by valve openator failure possibly caused by water in air line CARTHRIGHT.W R Virginia Electric & Power Co 80/08/27 2pp
- 89099030593 Forwards LER 80-046/03L-0 CARTHRIGHT,N R Virginia Electric & Power Co 80/08/27 1p
- --800903060B LER 80-046/03L-0 on 800818, while heating in Mode 3 operation, position indication for control rod 0-9 greater than 12 steps from demand position Caused by voltage drift in signal conditioning card Recallbr & functional test done CARTHRIGHT.W R Virginia Electric & Power Co 80/08/27 2pp
- 8009030615 Forwards LER 80-045/03L-0 CARTURIGHT, UR Virginia Electric & Power Co 80/08/27. 1p
- --8009030619 LER 80-045/03L-O on 800803 during RCS cooldown control room operator observed greater than 12 step deviation between rod indicator & demand indicator Caused by instrument drift Rod position indicator recali
- 8009090538 Forwards LER 80-037/03L-0 CARTHRIGHT, W R Virginia Electric & Power Co 80/09/05 1p
- --2009090584 LER 80-037/03L-0 on 800807, during Mode 3 operation, sample analysis indicated high boron concentration in SI accumulators A & C Gaused by stratification of boric acid in maleup source or accumulators CARTHROOHT.W R Virginia Electric & Power Co 80/09/05 2pp
- 8007180412 Forwards LER 80-052/03L-0
 GARTWRIGHT, W R Virginia Electric & Power Co 80/09/12 tp
- --8009180417 LER 80-052/03L-0 on 800823, w/unit at 4% power. C main steam trip valve would not fully close using train A close pushbutton Caused by solenoid operated valve in instrument air line to trip valve stuck in open position CARTWRIGHT. W R Virginia Electric & Power Co 80/09/12 3pp
- EOO9220239 Forwards LER 80-049/03L-0 CARTWRIGHT, W R Virginia Electric & Power Co. 80/09/16 ip
- --B009220319 LER 80-049/03L-0 on 800822, operating in Mode 2 at 3% power, loops A & C channel tour steam/flow bistables were tripped to allow mod to condensate pots Upon return to svc, A failed high Caused by instrument drift & improper valve lineup CARTWRICHT, W R Virginia Electric & Power Co 80/09/16 2pp.
- BOO9220241 Forwards LER 60-051/03L-0 CARTURIGHT,W R Virginia Electric & Power Co 80/09/16 1p
- --8009220315 LER 80-051/03L-0 on 800821, w/unit in Mode 2, C feedline containment isolation check valve 2-FW-126 did not meet post maint valve cycling test requirements Caused by failure of valve to shut completely due to burr on pivot pin bushing + Virginia Electric 5 Power Co 80/09/16 3pp

- 8009220355 Forwards LER 80-053/03L-0 CARTWRIGHT, W. R. Virginia Electric & Power Co. 80/09/16 1:
- --8009220360 LER 80-053/03L-O on 800825 during Mode 1 operation. C steam line flow Channel 4 indicated low 2 channel placed in trip condition Caused by instrument drift Channel recallor & returned to syc CARRWIGHT. W R Virginia Fisctric & Power Co. 80/09/16 2pp
- 8009230589 Forwards LER 80 048/03L-0 CARTHR10HF, W R Virginia Electric & Power Co 80/09/16 1p
- --8009230600 LER 80-048/03L-0 on BOOGEB, performing inspitechnicians discovered feed flow square root comparator card out of calibr Cause undetermined Card recalibr & seturned to svc CARTHRIGHT. W R Virginia Electric & Power Co 80/09/16 2pp
- BOO9230594 Forwards LER 80-047/03L-0 CARTWR1GHT,W R Virginia Electric & Power Co BO/09/18 1p
- --8009230577 LER 80-047/03L-0 on 800819.in Mode 2 at 3% power steam flow indications on toops A.B & C gave erroneous readings Caused by design deficiency in prossure sensing sys of venturi in main steam line Engineering study & design and carried out CARTWRIGHT.W R Virginia Electric & Power Co 80/09/18 2pp
- T Hearing transcripts on non-antitrust matters
- 8009:100101 Transcript of 800820 meeting in Washington DC to discuss full power license Pp 1-30 W/supporting documentation & Commission 80/08/20 57pp
- U Congressional/Executive Correspondence
- 8009070338 Responds to 800809 ltr re Commission decision to defer issuance of full power license Review of BER found emergency preparedness matters not completed License & Tech Brecs were still being modified for review AMEARNE, J. F. Commission 80008/11 2pp
- DOCKET 50-340 BEADROOK NUCLEAR STATION, WHIT I
- A Application/construction stage documents & correspondence
- 80090B00R0 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NURCO-0696 enci W/o NUREO EIEENHUT.D O Division of Licensing 80/08/01 119pp
- DOCKET 50-341 ENRICO FERMI ATOMIC POHER PLANT, UNIT 2
- A Application/construction stage documents ? correspondence
- 8009080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Focilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl H7a NUREO EISENHUT, D O Division of Licensing 80/08/01 | 119pp
- 8009120690 Forwards "Mark I Containment Long-Term Program SER, Resolution of Generic Technical Activity A-7." HUREO-0661 W/o encl SCHWENCER, A Licensing Dranch 2 80/08/20 2pp
- 8007030402 Submits response to 800711 ltr requesting estimate for const completion date Util currently estimates latest fuel load date for plant to be Nov 1982 Roview of plant 1974 CL application should resume W/publishing of SFR by Har 1981 TAUSER. H Detroit Edison Co 80/08/26 2pp
- B007250091 Notifies of B01007 proposed date to review whether CBL & BRV responses should be considered separately or combined during ASME code fatigue calculations OE selected samples to amphasize highly fatigued components
 WILEON, J N Assistant Director for Licensing B0/09/15 9pp
- 8007240502 Forwards Amend 30 to application for licenses & Amend 30 to FBAR, including drawings & calculations requested by NRC THOMABLE B LeBosuf, Lamb, Leiby & MacRae 80/09/22 jp

- --8009240507 Amend 30 to application for license for purpose of transmitting addl info requested by NRC
 HEIDEL.C M Detroit Edison Co 80/07/18 2pp
- --8039240509 Amend 30 to FSAR * Defroit Edison Co 80/09/30 50pp
- --8009240513 Drawings & calculations requested by RRC submitted in conjunction w/Amend 30 to FSAR * Detroit Edison Co 80/09/22 275pp
- H General correspondence
- 8009110280 Responds to 800728 ltr requesting info re safety of Midland & Fermi plants All nuclear plants subj to enhanced safety requirements resulting from TMI Lessons Learned Task Force recommendations Supporting documentation encl DIRCKS U.J. Office of the Elecutive Director for Operations 80/08/26 24pp
- --8007110283 Requests consideration of encl MC Haight ltr re safety of Midland & Fermi plants BRG04F1ELD.W S House or Rep . Foreign Affairs 80/07/28 2pp
-) Financial information
- 8009220013 Discusses impact of licensing re merging of two cooperatives that together num 20% of facility Action will have no significant impact on licensing procedure KIRINER.L Licensing Branch 2 80/08/25 1p
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8009240502 Forwards Amend 30 to application for licenses & Amend 30 to FSAR.including drawings & calculations requested by NRC THOMAS, E. LeBoeuf, Lemb, Leiby & MacRae 80/09/22 Ip
- --8009240507 Amend 30 to FSAR
 * Detroit Edison Co 80/07/30 50pp
- --8007240513 Drawings & calculations requested by NRC, submitted in conjunction w/Amend 30 to FSAR

 Detroit Edison Co 80/09/22 275pp
- M Antitrust correspondence
- E009240058 Forwards notice of receipt of OL application & request for antitrust info SCHMENCER, A Licensing Branch 2 80/08/27 2pp
- --8009260063 Notice of receipt of OL application & request for antitrust info SCHMENCER: A Licensing Branch 2 80/08/27 2pp
- @ Inspection reports. IE Bulletins ; correspondence
- 8007090027 Forwards IE Bulletin 80-07. Suppl 1. "BHR Jet Pump Assembly Failure' No response required KEPPLER. J G Region 3. Chicago, Office of the Director 80/03/14 to
- 8009030198 Forwards Revision I to IE Bulletin 80-17. "Failures of Hercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/08/15 ip
- 8009180477 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Numessential Control Air at Certain OE BHR Facilities " No specific action or response requested KEPPLER.J G Region 3. Chicago. Office of the Director 80/08/20 ap
- 8009120046 Forwards Suppl 3 to IE Sulletin BO-17, "Failure of Control Rods to Insert During Scram at BNR " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director BO/08/22
- 3009170425 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required EPPLER, J G Region 3. Chicago, Office of the Director 80/08/22

- BO09180016 Responds to IE Bulletin 79-03A re longitudinal weld defects in ASME BA-312 Type 304 stainless steel pipe spools Manufacturer review, util results L description of corrective action will be submitted by 800915
- 8009180029 Requests extension until 801001 to respond to IE Bulletin 80-16 re potential misapplication of Rosemount pressure transmitters Required analysis complex & extensive HINES.E Detroit Edison Co 80/08/26 ip
- 8009230072 Forwards IE Info Notice 80-31, 'Maloperation of Gould-Brewn Bover(480 Volt Type K-600S & K-DON 600S Circuit Breakers " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/28
- 8009090417 Submits revision to 800513 ltr which responded to 1E Sulletin 80-02. "Inadequate QA for Nuclear Supplied Equipment " Provides reasons for accepting statements re GA/GC program as basis for judging equipment integrity HINES,E Detroit Edison Co. 80/09/04 3pp
- 8009230446 Revises 800513 response to 1E Bulletin 80-02, "Inadequate OA for Nuclear Supplied Equipment" Thermal feedwater sleeves were fabricated under properly controlled OA program HINFS, E Detroit Edison Co 80/09/04 3pp
- 8009240101 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/09/10
- S Reportable occurrences, LERs & related correspondence
- 8009040455 Interim deficiency rept re Agostat relay bases Different model relay mounting base has been ordered Evaluation of GE proposal to modify relay bases is continuing Final rept will be submitted by 801004 FAHRNER.W J Detroit Edison Co 80/08/05 2pp
- BOD9160417 Followup to final deficiency rept re design inadequacy of CA relief valves \(\alpha \) insufficient capacity to limit pressure in event of reducing valve failure \(\beta \) discharge blockage Cause not stated Design mods underway to replace valves FAHRNER, II \(\extstyle \) Detroit Edison Ca \(\textstyle \) BOV09705 \(\textstyle \) 3pp
- 6009290065 Ack receipt of 800805 interim deficiency rept re Agastat relay base problem Final rept awaited for review FIGRELLI, @ Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/10 ip
- DOCKET 50-944 TROJAN NUCLEAR PLANT, PORTLAND GENERAL ELECTRIC F Security, medical, emergency & fire protection plans
- 8009110616 Requests participation in study of people-related problems in nuclear safeguards Study involves collection of data on licensee security forces & practices EISENHUT, D G Division of Licensing 80/07/25 2pp
- 8009030327 Notifies of 800819,22 & 30 regional workshops re development of guidance for acceptable method for coping w/smergencies Requests that representative be sent Discussion will include function of facilities & location EdGELKEUR H Region 5. San Francisco. Office of the Director GO/08/12 2pp
- 8009230337 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network. Sys installed for govt use during emergency ENGELKEN.R H. Region 5. San Francisco, Office of the Director. 80/08/22 3pp
- 8009100509 Forwards safeguards info re security plan Info withheld (ref 10CFR2 790) GUODNIN,C Portland General Electric Co 80/09/04 ip
- Q Adjudicatory correspondence
- B007020054 Order clarifying ASLB B00711 initial decision recontrol bldg mods Provisions of POE-1020 through Revision 4 & F0&E Exhibit 27 will be solely imposed as license conditions All other mati will become part of amended FSAR MILLER, ME Atomic Bafety and Licensing Board Panel 80/08/27 Bpp

- 8009040263 Order granting extension until 800909 for Commission to review Director's decision under 100FR2 206 CHILK-S J Office of the Secretary of the Commission 80/08/29
- E007i70308 Forwards order requiring into supporting environ qualification of safety-related electrical equipment Requests submittal of info 801101 CLARK,R A Operating Reactors Branch 3 80/08/27 2pp
- --8009190311 Order for mod of License NPF-1 to add info which fully responds to NRC request for info re environ qualification of safety-rolated electrical equipment Info should be submitted by 801101
 EISENHUT,D 0 Division of Licensing 80/08/29 6pp
- 80091800iO Order adhering to ASLB 8007il initial decision which rejected State of OR proposed license conditions re accelerated reporting MILLER, M E Atomic Bafety and Licensing Board Panel 80/09/04
- 8009090252 Advises that NRC will not file exceptions to ASLB 8007ii initial decision.per ASLB 800827 clarifying order GRAY.J R Hearing Branch i 80/09/05 ip
- 8009i100il Certifies svc of LER 80-0i7/03L-0 w/related correspondence. upon parties in proceeding on 800905 MCCARREL.8 F Portland General Electric Co 80/09/05 2pp
- B009:20244 Order granting extension until 800930 for Commission to review Director's decision under 10CFR2 206.DD-80-26 CHILK.S J Office of the Secretary of the Commission 80/09/09
- 80091901B9 Order extending until 800929 time for State of OR to either withdraw exceptions to ASLB 800711 decision, amend exceptions in light of ruling or notify ABLAB of intent to proceed w/appeal on basis of exceptions as now formulated BISHOP, C J Atomic Safety and Licensing Appeal Panel 80/09/15 200
- 8009290452 Informs Commission of Director's denial re suspension of plant operations in light of volcanıc activity at Mount St Helens Recommends effects of activity on evacuation be considered in conjunction w/required onergency planning MALSCH.H G Office of the General Counsel SECY-A-80-138 80/09/15 44pp
- 9009300566 Amended exceptions to initial decision re license conditions & to ASLB order re State of OR motion for reconsideration Accelerated reporting of design changes & completion of soismic evaluation must be imposed Certificate of Syc encl OSTRANDER.F W Oregon, State of 80/09/23 5pp

H General correspondence

- BOO9iiO389 Requests that facility be closed & defueled Eruptions from Mount Baint Helens would make moving out of area impossible if nuclear accident should occur SNOW.C A Affiliation Unknown 80/07/29 ip
- J Insurance & indemnity information
- BOD9190501 Forwards Endorsements 41 & 34 to AN1 & MAELU Policies NF-225 & MF-85-respectively HILBON.F R Portland Ceneral Electric Co 80/08/04 3pp
- P Operating license stage documents & correspondence
- 8009020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants, per NRC 800507 ltm Discusses administrative provisions for emergency & overtime work, Development & implementation to be reviewed within 90 days EISENHUT, D G. Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/o NUREO EISEMHUT.D O Division of Licensing 80/09/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENBUT. D G Division of Licensing 80/08/07 60pp

- 8009190794 Forwards revised Westinghouse STS 3 9 8 2,3 9 10 & Bases 3/4 9 8 & 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Whitten response required NDVAK.T M Assistant Director for Operating Reactors 80/08/15
- --8009190817 Revised Westinghouse STS 3 9 8 2.3 9 10 & Bases 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods # Assistant Director for Operating Reactors 80/06/23 21pp
- 8007020037 Advises that finite element analyses performed by Bechtel have been completed Refined displacement multiplication factors are at or below 800628 criteria Summary of results encl
 BROEHL D J Portland General Electric Co 80/08/20 3pp
- 8009090823 Summary of 800825 meeting u/util in Portland.DR re effect of volcanic activity at Mount St Hølens on plant TRAMMELL.C M Operating Reactors Branch 3 80/08/25 34pp
- 8009150385 Responds to NRC 800815 ltr ro making revisions to Tech Specs assuring water level requirements during Mode 6 Current procedures require min of 10 ft of water above fuel assembly during transfer GOODMIN.C Forti
- 8007260032 Advises that util response re ECCS evaluation models, dealing w/fuel ciadding swelling & incidence of rupture, is acceptable CLARK,R A Operating Reactors Branch 3 80/09/10 2pp
- 8009180468 Advises that license change application re implementation of TMI-2 Lessons Learned requirements will be submitted by 801103 GODDUIN.C Portland General Electric Co. 80/09/12 io
- 8009220363 Provides add1 info in response to NRC 800723 ltr re relationship of recent volcanic activity at Mount St Helens to facility Info addresses NRC Questions 361 t.2 & 3 Encl maps available in Central Files unly GODDWIN.C Fortland General Electric Co 80/09/15 13pp
- 8009290117 Notification of 800925 meeting w/util & Westinghouse in Bathesda.MB to discuss hab examination results of steam generator U-bend samples TRAMMELL, C.M. Operating Reactors Branch 3 80/09/16 2pp
- Q Inspection reports. IE Bulletins & correspondence
- 8007020244 Forwards IE lnsp Rept 50-344/80-44 on 800602-30 No noncompliance noted CREMB, J.L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/07/22 2pp
- --8009020251 IE Insp Rept 90-344/80-14 on 800402-30 No noncompliance noted Major areas inspected plant operations, maint, emergency surveillance testing, physical security, pracurement, emergency preparedness & LER follows MALMROS, M H , JOHNSTON, G W Region 5, San Francisco, Office of the Director STERNBERO, D M Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/07/22 5pp
- 8009260300 Forwards IE info Notice 80-27, "Broken Studs on Terry Turbine Steam inlet Flange " No written response required ENGELKEN.R H Region S. San Francisco. Office of the Director 80/08/07 1p
- 8009i40620 Responds to IE Bulleton 79-00A. "Longitudinal Neld Defects in ABME SA-312. Type 304 Stainless Steel Pipe " No subj pipe at faculity subjected to design stress greater than 85% of code allowable stress COUDMIN.C Portland Ceneral Electric Co 80/08/08 2pp
- 8009130009 Updates 800603 response to 1E Bulletin 80-08 re containment penetration welds Still unable to locate documentation for 11 welds Independent checks indicate proper radiography procedures followed Welds to be reradiographed Spring 1981 GOODWIN.C Portland General Electric Co 60/08/14 1p
- 8009150059 Suppls response to IE Bulletin 80-05 re vacuum protection measures for all sys that contain primary water Licensee 800609 ltr outlined commitment to provide locking & warning on values w/o redundant sys Tanks have redundant protection 60000WIN.C Fortland General Electric Co 80/08/14 2pp

- 8009250337 Responds to IE Bulletin 80-15 re possible loss of emergency notification sys(ENB) w/loss of offsite power Sys powered from telephone company Emergency power supplies consist of set of battories 5 dc diesel generator GOODWIN.C Portland Ceneral Electric Co 80/08/14 3pp
- 8007030270 Forwards Revision i to IE Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Hritten response required ENGELKEN, R H Region 5, San Francisco. Office of the Director 80/08/15 ip
- 8007270404 Forwards IE Info Notice 80-27. 'Degradation of Reactor Coulant Pump Stude " ENGELKEN,R H Region S. San Francisco. Office of the Director 80/08/18 4pp
- 8009140183 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required ENGELKEI, R H Region S, San Francisco, Office of the Director 80/08/29 18
- 8009240375 Updates 800702 response to IE Bulletin 80-08, re containment liner penetration welds Documentation found for welds identified in Table 1 as Items 1.51 2.74 Unable to locate documentation for 11 welds 000DWIN.C Portland General Electric Co 80/08/25 ip
- 8009120460 Forwards IE Info Notice BO-31. "Maloperation of Gould-Brown Bover! 480 Voit Type K-6008 & K-DON 6008 Circuit Breakers " No written response required ENGELKEN, R H Region 5. San Francisco. Office of the Director 80/08/27 to
- 8009110308 Forwards, "Environ Qualification of Electrical Equipment, Master List," Revision K per 800114 IE Bulletin 77-01B réquirements & 800827 order for license mod Encl available in Central Files only OOQDHIN,C Portland General Electric Co 80/09/05 2pp
- 8007300312 Ack receipt of 800822 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-344/80-17 800%.HE Region 5, San Francisco, Fuel Facility & Materials Safety Branch 80/07/12 ip
- --8009300314 Responds to NRC 800806 itr re violations noted in IE Insp Rept 50-344/80-17 Corrective actions procedure implemented requiring checklist be used during insp of drums prior to shipment to verify proper labeling GOODHIM.C Portland General Electric Co 80/08/22 3pp
- ---B009300318 Forwards IE Insp Rept 50-344/80-17 on 800619 & notice of violation BOOK.H E Region 5. San Francisco: Fuel Facility & Materials Safety Branch 60/08/06 2pp
- --8009300319 Notice of violation from insp on 800619 * Region 5, San Francisco, Office of the Director 80/08/05
- --8009300324 IE Insp Rept 50-344/80-17 on 800619 Noncompliance noted failure to mark two drums "Radioactive-LSA" & one container appeared to fail requirement of strong tight package FONO.T. WENSLAMSKI.F A Region 5. San Francisco. Office of the Director BOOK.H E Region 5. San Francisco. Fuel Facility & Materials Safety Branch 80/08/05 7pp
- R Pariodic operating reports & related correspondence
- 8009030575 Forwards "Effluent & Waste Disposal Semiannual Rept.Jan-June 1980 " QUODMIN.C Portland General Electric Co 80/08/28 1p
- E009100239 Forwards monthly operating rept for Aug 1980, YUNDT. C.P., Portland General Electric Co 80/09/02 ip
- --B007100242 Monthly operating rept for Aug 1980 BAIR-9 0 Portland General Electric Co. B0/07/02 3pp

- S Reportable occurrences, LERs & related correspondence
- 8009090410 RD on 800721, during Mode 1 monthly functional testing, found seismic monitoring sensor ST 6336 in cable spreading room not responding acceptably Caused by malfunction of seismic triaxial accelerometer ST 6336 Channel repaired YUNDT, C P Portland General Electric Co 80/08/28 2pp
- 800913047i Forwards RD re seismic monitoring instrument being inoperable for period exceeding 30 days
 YUNDT, C P Portland General Electric Co 80/08/28 ip
- --8009150475 RO on 800731, during monthly functional testing, seismic monitoring sensor ST 6336 did not respond acceptably Caused by seismic triaxial accelerometer in cable spreading room failure to functionally test Channel was repaired * Portland General Electric Co 80/08/28 ip
- 8009260506 Forwards updated LER 80-005/01T-1 YUNDT, C.P. Portiand General Electric Co. 80/08/29 1p
- --8007260510 Updated LER 80-005/01T-1 on 800411.main steam isolation valves did not fully close as required Caused by component failure immediately froed up stems b cycle valves Permanent corrective action is under investigation PERRY.J C Portland General Electric Co 80/08/29 3pp
- E009170309 RO during 800910-1201, cable spreading room sprinkler fire suppression sys L will be inoperable during mod to three zoned deluge ays 20.21 & 22 Backup fire protection measures will be employed YUNOT.C P Portland General Electric Co 80/09/04 1p
- E009100449 Forwards LER 80~017/03L~0 BRDEHL, D J Portland General Electric Co 80/09/05 1p
- --B009100453 Forwards RO-17 re inoperable containment spray pump room fan YUNDT.C P Portland Omneral Electric Co B0/08/29 2pp
- --8009100461 RD 80-17 on 800803 one-inch conduit A8-4596, supplying power to HV252A fan for west containment spray pump room damaged by concrete core drilling Drilling procedure changed to include voice communication between driller & observer * Portland General Electric Co 80/08/29 ip
- --B009100467 LER B0-017/03L-O on B00803, during concrete care drilling, conduit damaged which supplied power to west containment spray pump room fan Fan rendered inoperable Caused by core drilling crew error Certificate of Bvc encl
 PERRY, J C Portland General Electric Co B0/08/29 4pp.
- B009180379 Describes evaluations & followup actions re LERs 80-005/017-0,80-009/03L-0 & 80-010/03L-0,in response to 800729 ltr COCOMMIN.C Portland General Electric Co 80/09/05 6pp
- 8007300471 RO followup to CP Yundt 800724 rept to M Malmros re high steam flow bistable trip setpoints incorrectly set but within limits of Toch Spect Occurrence will be reported to NRC as LER YUNDT, C P Portiand General Electric Co 80/09/25 ip
- DOCKET 50-346 DAVIS-BESSE NUCLEAR POWER SYATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- B009230309 Requests that ail personnel be reminded of purpose of emergency notification sys & health physics network Bys installed for govt use during emergency KEPPLER, J G Region 3, Chicago, Office of the Director 90/08/22 3pp
- 8009120430 Forwards update re current status of fire protection upgrades at facility CROUBE.R P Toledo Edison Co 80/09/05 5pp
- @ Adjudicatory correspondence
- B009i90572 Forwards order requiring info supporting environ qualification of safety-related ejectrical equipment Requests submittal of info by B0i10i REID.R W Operating Reactors Branch 4 80/08/29 2pp

- --BOO9190581 Order for mod of License NPF-3 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment info should be submitted by BO3101
 EISCHHUI, D O Division of Licensing 80/08/29 dep
- P Operating license stage documents & correspondence
- QCO9150070 Responds to 800523 recommendations concerning lessons learned from 800226 transient at Crystal River Submits results of investigations je use of atmospheric dump valve at Oconee Units 1-3:AR Unit i.Davis-Besse Unit 1 ½ TMI-1 DENYOULH R Office of Nuclear Reactor Regulation. Director 80/07/21 20s
- 800Y020297 Submits interim criteria for shift staffing to all CL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Devalopment & implementation to be reviewed within 7D days EISENNUT, D O Division of Licensing 80/07/31 7pp
- 8009080090 Forwards draft NUREO-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 #ays Proposed implementation schedule for meeting criteria of NUREG-0696 enci W/o NUREG EISE/RBJT, D O Division of Licensing 80/08/01 119pp
- 8009200052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous datermination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D O Division of Cicensing 80/08/07 40pp
- BOOPOGOA77 Informs of Class 3 fee requirement for review of fish impingement study
 HILLER.H O License Fee Management Branch 80/08/14 Ip
- BOOTOTO645 Requests Class [1] fee for Ofc of Nuclear Reactor Regulation review of util 800721 & 0804 submittals re RCS flow indication DIGOSIR M License Fee Management Branch 80/08/25 ip
- 8009300046 Forwards Amend 30 to License NPF-3, safety evaluation & notice of issuance & availability REID.R W Operating Reactors Branch 4 60/08/27 2pp
- --8009300052 Amend 30 to License NPF-3, deleting License Condition 2 C (3)(r) re-submittal of seismic reanalysis REID:R W Operating Reactors Branch 4 80/08/27 2pp
- --8009300053 Safety evaluation supporting Amend 30 to License NPF-3 • Office of Nuclear Reactor Regulation, Director 80/08/27 3pp
- --8009300057 Notice of issuance & availability of Amend 30 to License RFF-3 REID,R W Operating Reactors Branch 4 80/08/27 2pp
- BOOR190145 Forwards corrected Tech Spec Page 3/4 5-4 issued on 800725 w/Amend 28 to DL AEEO, N Operating Reactors Branch 4 80/09/04 2pp
- --B009190148 Corrected Tech Spec Page 3/4 5~4, originally issued 800725 # Operating Reactors Branch 4 80/09/04 2pp
- 8009100172 Forwards BBW rept. "Evaluation of Instrumentation to Detect Inadequate Core Cooling Prepared for 177 Dwners Group" CROUSE:R P Toledo Edison Co 80/09/08 ip
- --B009100176 "Evaluation of Instrumentation to Detect Inadequate Core Cooling Prepared for 177 Owners Oroup " FROTH D J Babcock & Wilcox Co 80-1120838-00 80/08/15 2ipp
- 8009240346 Forwards Amend 31 to License NPF-3, safety evaluation & notice of issuance & availability
 REID.R H Operating Reactors Branch 4 80/09/08 2pp
- -8009260353 Amend 31 to License NPF-3/modifying containment purge & exhaust isolation valves & allowing plant in cold shutdowns to heat up & operate at power w/valves inoperable.

 REID.R W Operating Reactors Branch 4 80/09/08 7pp
- -- 8009260358 Safety evaluation supporting Amond 31 to License NPF-3.

 # Operating Reactors Branch 4 80/09/08 2pp

- --B009260364 Notice of issuance & availability of Amend 31 to License NPT-3 REID.R W Operating Reactors Branch 4 80/09/08 2pp
- 8009250491 Informs of acceptability of response to NRC 791109 ltr reportions of ECGS evaluation models dealing w/fuel cladding swelling & incidence of rupture
 REID.R W Operating Reactors Branch 4 80/09/09 2pp
- B007220297 Forwards application for amend of License NPF-3, consisting of proposed Tech Spec changes in response to NRC G00702 ltr re TMI Lessons Learned Category A requirements CROJSE, R P Toledo Edison Co B0/09716 Ip
- --8009220301 Application for amend of License NPF-3 consisting of proposed Tech Spec changes supporting actions to satisfy THI Lessons Learned Category A requirements CROUSE, R P Toledo Edison Co 80/09/16 1p
- --8009220313 Proposed Tech Specs 1 2.3 3-3.3 3-11.4 3-2.3 3-10.4 3-10.3 4 11.6 3 6 5.6 2-1.3/4 4 4.3/4 4 5.3/4 4 10 % 3 4 4 11 re safety features actuation sys instrumentation Made in response to TMI Lessons Learner, Category A requirements 4 Totedo Edison Ca 80/09/14 14pp
- G Inspection reports, IE Sulletins & correspondence
- 8009290019 Forwards IE Insp Rept 50-346/80-17 on 800604 No noncompliance noted KEPPLER, J G Region 3, Chicago, Office of the Director 80/07/10 2no
- ~-8009290020 IE Insp Rept 50-346/80-17 on 800604 No noncompliance soted Major areas inspected assessments of security (nsp findings & enforcement actions to 800430 pyrsonnel averapposure TAMBLINO T M Region 3. Chicago. Office of the Birector HEISHMAN.R F Region 3. Chicago. Reactor Operations Nuclear Support Branch 80/07/09 12pp
- 8009150504 Forwards IE Insp Rept 50-346/80-21 on 800708-09 No noncompliance noted FIGRELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/07/28 2pp
- --8009150508 IE Insp Rept 50-346/60-21 on 800708-09 No nuncompliance noted Major areas inspected QA/QC program.implementing procedures, work activities & IE Bulletin 79-17 & IE Bulletin 80-09 activities WARD, K D Region 3, Chicago, Office of the Director DANIELSON, D M Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/25 App
- 800930023B Forwards IE Insp Rept 50-346/80-i9 on 8006i6-20,23-27 & 30 & O701-03 & 07-11 & notice of violation HEIGHHAN,R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/08/12 2pp
- ---8009300240 Natice of violation from sasp on 800620.23-27 & 30 & 0701-03 & 07-11 * Region 3. Chicago, Office of the Director 80/08/31 2pp
- --8009300243 (E Insp Rept 50-346/80-19 on 800620,23-27 & 30 & 0701-03 & 07-11 Noncompliance noted failure to keep log of events & to properly log locked valve position REVESI. A . MARMICK.R F Region 3. Chicago. Office of the Director 80/08/11 lipp
- 8009150067 Forwards Revision i to 800403 response to tE Bulletin 79-018 Revision I supercedes initial response & provides addl evaluation work sheets re components subj to increased radiation from recirculating fluid following LOCA W/o encl CROUSE.R P Toledo Edison Co 80/08/14 3pp
- 8007030214 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/09/15
- 8009220176 Bubmits additinfore IE Bulletin 79-14, "Seismic Analysis for As-Built Bafety-Related Piping Sys " Stress calculation on main steam line outside containment was calculated using proposed mod support sys instead of as-built configuration CROUSE.R P Toledo Edison Co 80/09/18 2pp
- 8009290097 Forwards IE Insp Rept 50-346/80-22 on 800722-24 No noncompilance noted FIORELLI, @ Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/17 2pp

- --8009290101 IE insp Rept 50-346/80-22 on 800722-24 No nuncompliance noted Kajor areas inspected pipe whip restraint mod at hot leg risers, snubber installations, accessible area piping & procedure review VIII. 1 T. BRICKLY, R H. DANIELSON, D H. Region 3. Chicago, Office of the Director 80/08/18 7pp
- 8009260659 Forwards IE Insp Rept 50-346/80-24 on 800721-25 & notice of visiation DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/08/20 200
- ~-8009260451 Notice of violation from insp on 800721-25 * Region 3. Chicago. Office of the Director HO/08/18 1p
- --8009260665 IE Insp Rept 50-346/80-24 on 800721-25 Noncompliance noted failure to report exceeding Tech Spec limiting operating condition & to perform sulfate monitoring at required interval PHILLIPS.M P. (DESTHANN.M J., ESSIG.T H. Region 3, Chicago, Office of the Director 80/08/18 10pp
- 8009110504 Forwards response to IE Bulletin 80-15. "Possible Loss of Emergency Notification Sys (ENS) w/Loss of Offsite Power" Adequacy of emergency notification sys verified in 800625 util insp w/appropriate telephone company representative CRGUSE.R P Toledo Edison Co 80/08/22 3pp
- 8009170437 Forwards IE Circuiar 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER.J G Region 3, Chicago. Office of the Director 80/08/22
- 8009260097 Forwards 30-day response to Item i of IE Bulletin 80-19. Revision 1. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E "No soby relays used CROUSE,R P Toledo Edison Co 80/08/26 2pp
- 8009230058 Forwards IE info Notice 80-31, "Maloperation of Quild-Brown Boveri 480 Volt Type K-6005 & K-DON 6005 Circuit Breakers " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/08/28
- 8009240118 Forwards IE Circular 80-21. "Regulation of Refueiing Crews " No written response required KEPPLER, J G Region 3. Chizago. Office of the Director 80/09/10
- R Periodic operating reports & related correspondence
- 8009080317 Forwards "Semiannual Radioactive Liquid & Caseous Release Rept.Jan-June 1980 " MURRAY.T D Toledo Edison Co 80/08/21 ip
- --8009080319 "Semiannual Radioactive Liquid & Gaseous Release Rept Jan-June 1980 " * Totado Edison Co 80/08/21 870s
- 109150274 Forwards monthly operating rept for Aug 1980 MURRAY.T D Toiedo Edison Co 80/09/09 1p
- -8009150277 Monthly operating rept for Aug 1980-SARSOUR.B Toledo Edison Co 80/09/09 [App
- 3 Reportable occurrences, LERs & related correspondence
- 3009020333 Forwards LERs 80-095/03L-0,80-056/03L-0,80-057/03L-0 & 80-058/01T-0 MURRAY.T D Toledo Edison Co 80/08/22 19
- --8009020376 LER 80-038/03L-0 on B00724,ioss of decay heat flow caused by DH12 going shut was observed DH11 closed while attempting to restore BFAS CH4 cabinet to normal DH11 closed on B00803 while removing bistable BA413 Caused by gersannel error FROHMER Toiedo Edison Co 80/08/07 ip
- 8009020057 Forwards LER 80-060/01T-0 MURRAY.T D Toledo Edison Co 80/03/26 ip
- --800902006(LER 90-060/01T-0 on 800813 during resetting of trip point, decay heat isolation valve DH il began closing Caused by personnel error DH il reopened DH pump i-2 started & flow re-established Tech Specs amended ISLEY.T Toledo Edison Co 80/08/26 3pp

- 8009160391 Forwards LER 80-012/03L-1 MURRAY, T D Toledo Edison Co 80/09/09 in
- --8007160379 LER 80-012/03L-1 on 800201, reactor operator noticed control room position indication was lost for letdown cooler isolation valve MUZA Caused by const personnel bumping into disconnect switch breaker Switch repositioned STDTZ, J C Toledo Edison Co 80/02/28 3pp
- 8009120351 Forwards LER 80-061/03L-0 MURRAY, F D Toledo Edison Co 80/09/10 1p
- --8009120356 LER 90-061/03L-0 on B00812.during calibr & maint records check, personnel found valve 8V5005 installed 760826 for temporary use was not replaced Caused by inadequate administrative control Replacement for SV5005 requested ISLEY.T Toledo Edison Co 80/09/10 3pp
- 8009230682 Forwards LER 80-062/03L-0 MURRAY, T D Tolado Edison Co 80/09/18 1p
- ----8009230686 LER B0--062/03L-O on 800903.while performing waikdown par IE Bulletin 80--11.discovered that protective curbs had not been provided around one of pipe chases in mechanical room 3 & A Causad by AE error Curbs will be added KURRAY.T D Toiede Edison Co 80/09/18 3pp
- 8009230690 Forwards LER 80-063/03L-0 MURRAY, T D Toledo Edison Co 60/09/18 ip
- --8009230692 LER 80-063/03L-O on 800823 control room operator discovered that indicating lights on safety features actuation sys indication panel for damper CV5442 were out Caused by random failure of fuse in control circuit Fuse replaced THDMP69N,T Toledo Edison Co 80/09/18 2pp
- B00923067i Forwards LER B0-064/03L-0 MURRAY, T D Toledo Edison Co 80/09/19 1p
- --8007230680 LER 80-064/03L-O on 800822, station experienced ioss of essential instrument ac panel Y2 Caused by failure of YV-2 inverter output fuse No cause determined for fuse failure Failed fuse replaced ISLEY,T Toledo Edison Co 80/09/18 3pp
- 8009290363 Forwards LER 80-065/03L-0
 Toiedo Edison Co 80/09/23 ip
- --8009290370 LER 80-065/03L-0 on 800826.loss of position indication light caused ioss of control power to breakers rendering amergency diesel generator i-i inoperable Caused by human error Switch reclosed & breaker position indication returned MATHENY.D Toledo Edison Co 80/09/23 3pp
- DOCKET 50-348 JOSEPH M FARLEY NUCLEAR PLANT, UNIT i

 F Security, medical, emorgency & fire protection plans
- 8007230247 Requests that all personnel be reminded of purpose of emorgoncy notification sys & health physics network Sys installed for goot use during emorgency D'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/22 tp
- 8009090585 Forwards summary of 800821 working session re installation of fire barriers for cable trays & conduits Util concludes that all commitments & requirements have been fulfilled CLAYTON: F.L. Aiabama Power Co 80/09/02 2pp
- O Adjudicatory correspondence
- 8009230115 Forwards order requiring info supporting environ qualification of safety-related electrical equipment, Requests submittal of info by 801101 VAR96.6 A Operating Reactors Branch 1 80/08/27 2pp
- --8007230117 Order for mod of License NFP-2 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101
 EISENHUT, D G Division of Licensing 80/09/29 App

- 8009380407 Informs of M Farrar resignation from full-time ASLAP position Name should be deleted from svc list for all but Farlay antitrust proceeding Svc list for all other dockets need contain only two ASLAB members ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel 80/09/25
- # General correspondence
- E009300435 Requests that distribution list be revised to reflect recent mgt-level reorganization WD Whitt has assumed responsibilities formerly assigned to AR Barton CLAYION,F L Alabama Power Co 80/09/23 lp
- J Insurance & indomnity information
- 8009020278 Forwards ANI Secondary Financial Protection Binder EB-73 • Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div 80/08/26 6pp
- M Utility Final Safety Analysis Report (FSAR) & amends
- 6009150259 Forwards Amend 74 to FSAR for Unit 1 & to application for OL for Unit 2 Certificate of 8vc encl CLAYTON:F L. Alabama Power Co 80/09/12 2pp
- ---B009150260 Amend 74 to application for OL for Unit 2 & to FSAR for Unit 1 CLAYTON,F L Alabama Power Co 80/09/12 1p
- A Antitrust correspondence
- 8009090339 Motion for issuance of decision at earliest convenience Proceeding pending since 790308 Certificate of Svc encl Granted by ASLAB on 800908 BLUME.H & Antitrust Division 80/09/05 3pp
- 8009260662 Response in support of NRC 800905 motion for issuance of dacision issues, if resolved, will affect future power supply & development of supply planning Injury may occur if delayed Certificate of Svc encl HJELHFELT, D C Humicipal Electric Utility Association, Alabama HJELHFELT, D C Hjelmfelt, D C 80/09/23 3pp
- P Operating license stage documents & correspondence
- 8009380274 Forwards "Setpoint Study for Farley 1 & 2," proprietary (MCAP-B313) & nonproprietary (MCAP-9768) versions, Application & affidavit for withholding encl AMDZREGN.TM Westinghouse Electric Corp 80/07/25 13pp
- ---8009080299 "Setpoint Study for Farley 1 & 2," nonproprietary version KD.M Westinghouse Electric Corp ORTCNBERG,L I : ROSSI,C E Westinghouse Electric Corp : Nuclear Energy Systems WCAP-9768 74/05/31 216pp
- BOO9D20297 Bubmits interim criteria for shift staffing to all OL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D O Division of Licensing 80/07/31 7pp
- 8009080380 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREO EIGENBUT.D & Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated &/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D Q Division of Licensing 80/08/07 60pp
- 8009110030 Forwards Amend 15 to License NPF-2, safety evaluation & notice of issuance & availability VARGA.8 A Operating Reactors Branch 1. 80/08/14 2pp
- ---8009110031 Amend 15 to License NPF-2, revising low-low steam generator water level reactor trip setpoint to compensate for high containment pressure following postulated high energy line break VAROA, S.A. Operating Reactors Branch 1 80/08/14 6pp

- --8009/10033 Safety evaluation supporting Amend 15 to License (IPF-2 * Office of Nuclear Reactor Regulation, Director 80/08/14 3pp
- --8009110035 Notice of issuance & availability of Amend 15 to License NAF-2 VARGAIS A Operating Reactors Branch 1 80/09/14 2pp
- 8009190794 Forwards revised Westinghouse 8TS 3 9 8 2.3 9 10 & Bases 3/4 9 8 2 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required NOVAK.TM Assistant Director for Operating Reactors 80/08/15
- --8009190817 Revised Westinghouse SIS 3 9 8 2.3 9 10 2 Bases 3/4 9 8 2 3/4 9 10 requiring 23 ft of water over top of reactor pressure flange during movement of fuel assemblies or control rods 4 Assistant Director for Operating Reactors 80/06/23 21pp
- 8009080387 Forwards summary & results of 800819 working session w/NRC re hot shutdown panel, per 800014 telcon w/NRC CLAYTON,F L. Alabama Power Co. 80/00/28 2pp
- 8009090566 Requests that radiological ETS for Unit 2.NRC approved during wt of 800825.be implemented for Unit 1 on 810101 to assure consistent implementation for both units CLAYTON.F L. Alabama Power Co. 80/09/02 Ip
- 8009120425 Requests that Tech Specs re exposure of fuel assemblies & control rods remain unchanged until after receipt of Unit 2 full power OL CLAYTOH.F L. Alabama Power Co 80/09/03 tp
- 8009110371 Requests that encl supporting document be docketed under Millstone KAPD.P S Assistant Director for Cord & Containment Bystems 80/09/09 Ip
- 8009160358 Requests that RHR Tech Specs, as agreed for Unit 2 be implemented for Unit 1 after receipt of Unit 2 full power OL to assure consistent implementation for both units CLANTON F L Alabama Power Co 80/09/10 tp
- 8009300381 Forwards summary of results achieved at 800918 meeting re isolation of hot shutdown panel & main control board instrumentation mods, resulting from NRC 800915 request for addI info CLAYTON.F L Alabama Power Co
- 8009300424 Bupports EPRI & Westinghouse comments on NUREO-0577,τe alternate approach for demonstrating nuclear support structure adequacy.per 800702 commitment CLAYTON F L Alabama Power Co, 80/09/26 Ip
- G Inspection reports, IE Bulletins & correspondence
- 8009110258 Forwards response to IE Bulletin 79-018. Items 1.2 & 3 re environ qualification of electrical equipment includes master list for each sys or subsystem w/electrical equipment items within scope of bulletin CLAYTOM: L Alabama Power Co 80/04/29 350pp
- 8009020466 Forwards 1E Insp Repts 50-348/80-18 \$ 50-364/80-18 on 800623-26 No noncompliance noted STOHR, J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/07/14 2pp
- ---8009020477 IE Insp Repts 50-348/80-15 & 50-344/80-18 on 800623-26 No noncompliance noted Major areas inspected radwaste mgt OIBSDN,A F Region 2. Atlanta. Fuel Facility & Materials Safety Branch WRAY,J R Region 2. Atlanta. Office of the Director 80/07/11 App
- 8009100040 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/07/24 lp
- 8009110102 Forwards IE Insp Repts 50-348/80-17 & 50-344/80-23 on 800602 -30 No noncompliance noted LEWIS.R C Region 2, Atlanta. Reactor Operations Nuclear Support Branch 80/07/27 2pp

- --8009110202 IE Insp Repts 50-348/80-19 t 50-364/80-23 on 800602-30 No nancompliance noted Hajor areas inspected sys integrity outside containment monitoring instrumentation, radiation controls, fluid leads, piping vibration & rire hazards BRADFORD, W H . MARTIN.R D Region 2. Atlanta, Diffice of the Director 80/07/28 7pp
- 8009050052 Responds to JE Builetin 79-03A. "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " No 300 series fusion welded pipe used in safety-related sys sub) to stresses greater than 85% of max allowable stresses CLAYTO4.F.L. Alabama Power Co. 80/08/01 2pp
- BO07020271 Forwards response to IE Bulletin BO-15 Emergency notification sys verified as powered offsite w/backup battery packs CLAYTON.F. L. Alabama Power Co. 80/08/06 5pp
- 8009120045 Forwards IE Insp Repts 50-349/80-14 & 50-364/80-16 on 800509-13 & 16-20 & notice of violation LEHIS.R C Ragion 2, Atlanta, Reactor Operations Nuclear Support Branch 60/09/08 2pp
- --8009120052 Notice of violation from insp on 800609-13 & 16-20 * Region 2, Atlanta, Office of the Director 80/08/06 2pp
- --B039120071 IE losp Repts 50-348/80-14 & 50-344/80-16 on 800609-13 & 16-20 Noncompliance noted failure to provide definitive corrective action for identified matI storage inadequacies & failure to control consumables in safety-related sys BELISLE, G A , FORD, E J Region 2, Atlanta, Office of the Director UPRIGHT, C M Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/08/06 35pp
- 8009030123 Forwards Revision 1 to IE Builetin 80-19, "Failures of Marcurg-Watted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY. J P Region 2, Atlanta, Office of the Director 80/08/15 to
- 3009160110 Forwards IE Circular 80-18. "100FR50 59 Bafety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REJLLY.J P Region 2. Atlanta. Office of the Director 80/08/22
- 8009120251 Forwards IC Info Notice 80-31, "Maloperation of Gould-Brown Bover: 480 Volt Type X-6008 & K-DON 6008 Circuit Breakers " No written response required GREILLY.J P Region 2, Atlanta, Office of the Director 80/08/27
- 80091f0597 Responds to IE Builetin 80-17 Mercury-wetted relays not utilized in reactor protection sys in either facility CLAYTON,F.L. Alabama Power Co. 80/08/29 1p
- 8009190576 Ack receipt of 800812 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-348/80-16 & 50-364/80-19 MURPNY-C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 60/09/03 2pp
- --8009190583 Responds to NRC 800723 ltr re violations noted in IE lnsp Repts 50-348/80-16 & 50-364/80-19 Corrective actions testing & analysis initiated to determine probable error introduced through improper use of torque multipliers CLAYTON:F L Alabama Power Co 80/08/12 5pp
- --8009190588 Forwards 1E Insp Regts 50-348/80-16 \$ 50-364/80-19 on BBO617-20 & notice of violation r/JRPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/07/23 2pp
- --8039190593 Notice of violation from insp on 800517-20
 ** Region 2. Atlanta. Reactor Construction & Engineering Support
 Branch 80/07/21 2pp
- -8009190609 IE Insp Repts 50-348/80-16 & 50-364/80-19 on B00617-20 Noncompliance noted torque wrench multiplier used for IE Bulletin 79-02 testing not controlled or calibr & inadequate instruction for mod & insp of support A/G.W.P. Region 2. Atlanta. Diffice of the Director HERDT, A Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/07/21 499
- 19290276 Forwards IE Circular 80-21, "Regulation of Refueling Grews" o written response required 'REILLY, J P Region 2. Atlanta: Office of the Director 80/07/10

- 8009303534 Responds to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment " Responses submitted on 800429 & 0730 completely addressed bulletin requirements No further action required CLAYTON,F L Alabama Power Co 80/09/22 1p
- R Periodic operating reports & related correspondence
- 8009030491 Forwards "Semiannual Radioactive Effluent Release Rept. Jan-June 1980 " CLAYTON.F L. Alabama Power Co. 80/08/28 ip
- --8007030475 "Semiannual Radioactive Effluent Release Rept.Jan-Juna 1780 " * Alabama Power Co 80/08/28 55pp
- 8009160268 Forwards monthly operating rept for Aug 1980 CLAYTON: F L Alabama Power Co 80/09/11 2pp
- --8009160270 Monthly operating rept for Aug 1980 MAIRSTON,W G Alabama Power Co 80/09/01 Spp
- 8009230566 Forwards corrections to printout Pages 1.3, 4 & 7 of draft summary of effluent & waste disposal semiannual rept for 1978 in response to NRC 800825 ltr Corrected pages available in Central Files only CLAYTON.F L Alabama Power Co 80/09/15 lpp
- S Reportable occurrences, LERs & related correspondence
- 8009020062 Forwards LER 80-044/03L-0 CLAYTON F L Alabama Power Co 80/08/22 1p
- ---8009020068 LER 80-044/03L-0 on 800723, during surveillance test.dissel generator iC failed to reach rated speed & voltage & was declared inoperable Cause under continued investigation HAIRSTUN.W G Alabama Power Co 80/08/22 2pp
- 8007030427 Forwards LER 80-045/03L-0 CLAYTON F L Alabama Power Co 80/08/26 1p
- --8009030429 LER 80-045/03L-0 on 800727, vacuum pump tripped on low flow causing containment atmosphere radioactivity monitoring sys Ris & Ris to be declared inoperable Caused by fouled filter paper in vacuum pump Paper replaced HAIRSTCN-W O Alabama Power Co 80/08/26 ip
- 8009160320 Forwards LER 80-046/03L-0 CLAYTON F L. Alabama Power Co 80/09/08 1p
- --B009160323 LER B0-046/03L-0 on B00813, steam flow channel associated w/ flow transmitte: 475 failed low Caused by defective loop power supply cord Cord replaced & channel returned to svc HAIRSTON, W O Alabama Power Co B0/09/00 ip
- 8009160307 Forwards LER 80-047/03L-0 CLAYTON.F L Alabama Power Co 80/09/11 1p
- --8009160308 LER 80-047/03L-0 on 800812, evc water bldg 8 train battery sys declared inoperable due to low specific gravity of battery cell No cause found Battery placed on equalize & gravity returned to normal HAIRSTON: W G Alabama Power Co 80/09/11 1p
- 8009230722 Forwards LER 80-049/03L-0 CLAYTON: F L Alabama Power Co 80/09/16 Ip
- --8009230729 LER 80-048/03L-0 on 800817, containment atmoshpere gaseous & particulate radioactivity monitoring sys were declared inoperable due to pump failure & pump trip on low flow Caused by pump burnout & sys flow maladjustment H41RSTON, W C Alabama Power Co 80/07/16 lp
- 8009230710 Forwards LER 80-049/03L-0 CLAYTON.F L Alabama Power Co 80/09/18 ip
- --8009230737 LER 80-049/03L-0 on 800820, reactor trip instrumentation channel associated w/RCS loop flow transmitter 434 inoperable due to loss of flow indication Caused by defective transistors on card C1-242 HAIRSTON, H O Alabama Power Co 80/09/18 Ip
- 8009300572 Forwards LER 80-050/03L-0 CLAYTOM F L Alabama Power Co 80/09/24 (p

.= 0.09300577 LER 80-050/03L-0 on 800825, svc water train B dc distribution was declared inoperable when no output indication from battery charger 4 was observed Caused by actuation of high voltage shutdown relay Reset & returned to svc HAIRSTON. W 9 Alabams Power Co 80/09/24 1p

09300523 Forwards LER 80-051/03L-0 CLAYTON F L Alabama Power Co 80/09/25 1p

GOOGGOST LER 80-051/03L-0 on 800626.diesel generator iC failed to reach speed within specified limits Apparent cause was leaking check valve in fuel oil sys Valve replaced & diesel generator returned to svc
HAIRSTON W O Alabams Power Co 80/09/25 2pp

09300511 Forwards LER 80-052/03L-0 CELAYTON:F L Alabama Power Co 80/09/26 1p

9009300515 LER 80-052/03L-0 on 800827 electronic switching sys 81H sequencer falled to meet time requirement for steps 2 & 3 Caused by setpoint drift Agastat timers satisfactorily reset

MAIRSTON.# O Alabama Power Co 80/09/26 lp

Operator Examinations

:9100318 Forwards revised operating shift manning & training schedule gr 800804 exam results & 800904 verbal request LAYTON:F L. Alabama Power Co 80/09/08 6pp

KET 50-352 LIMERICK GENERATING STATION, UNIT 1 Application/construction stage documents & correspondence

POBOODO Forwards draft NUREO-0696, "Functional Criteria for margency Response Facilities" Comments requested within 30 ays Proposed implementation schedule for meeting criteria NUREO-0696 enci 4/o NUREO SENSUR. 0 Division of Licensing 80/08/01 119pp

₹110742 Notification of 800904~05 meeting w/Mark II owners group to Lscuss plants chugging C/O & lateral load specs 4DERSON.C Containment Systems Branch 80/08/29 14pp

#290378 Forwards Amend 24 to application for OL & revised Pages to FAR. Sugmary description of amend revision encl
#ADLEY.E J Philadelphia Electric Co 80/09/24 4pp

OP290380 Amend 24 to application for OL Revises PBAR Pages 5 12-13 & 5.2-16 Certificate of Svc enci BOYER.V S Philadelphia Electric Co 80/09/24 4pp

OF2903B2 Amend 24 to PBAR, revising Pages 5 2-13 & 5 2-16 ⇒ Philadelphia Electric Co BO/07/24 3pp

tility Preliminary Safety Analysis Report, amends

R90378 Forwards Amend 24 to application for OL & revised Pages to AR. Summary description of Amend revision enci ADLEY, E. J. Philadelphia Electric Co. 80/09/24 4pp

19290380 Amend 24 to application for OL Revises PBAR Pages 5 12-13 & 3. 2-14 Certificate of Svc encl IOYER.V.S Philadelphia Electric Co 80/09/24 4pp

'9290382 Amend 24 to PSAR, revising Pages 5 2-13 t 5 2-16 Philadelphia Electric Co 80/09/24 3pp

curity, medical, emergency & fire protection plans

70332 Forwards "Limerick Nuclear Generating Station Preliminary Countion Time Estimates" Rept withheld (ref 10CFR2 790) KLEY.J NUS Corp 80/08/22 1p

Termi correspondence

30448 Responds to 800317 ltr requesting public debate re issues repriate to evacuation of large population ctrs near lts.
TON.H R. Office of Nuclear Reactor Regulation, Director 34/21 3pp

~~8009180462 Requests public debate re issues appropriate to evacuation of large population ctrs near plants Expresses Confidence in attempts by Commissioners to represent public concerns EMOR*/A Affiliation Unerdan 60/03/19 Ip

8007220078 Responds to 800837 ltr expressing opposition to c-rat of facilities Util application for CLs will be subjected to devailed safety & environ reviews by IRC 5 may be subj of public hearing if application is contested INGRAM, F. Office of Public Arfairs 63/08/13 ip

--B009220031 Expresses concern re const of racilities Forwards neutpaper article re dangers of nuclear plants
MAYER, P Affiliation Unknown ED/CO/OP Zpp

B009150316 Responds to E60718 ltr to President Carter transmitting Borough of Phoenitville:PA resolution apposing const of nuclear reactors Facility is not undergoing review Util studies he executation time estimates have been submitted DENTON H R Office of Auclear Reactor Regulation. Director B0/08/25 2pg

--8009150318 Forwards Borough of Phoens::111s.PA 800718 1tr to Fresident Carter: transmitting Resolution 80-10 opposing const of nuclear reactors Requests response SEAL.M H President of US % Executive Offices 80/07/25 Epp

O Inspection reports, IE Bulletins & correspondence

8009090089 Forwards 16 Bulletin 80-07. Suppl 1. "EWR Jet Pump Assembly Failure" No response required ORIER B Region 1. Philadelphia, Office of the Director 80/05/13

8009100981 Forwards IE Insp Repts 30-352/60-13 & 50-353/80-11 on 800602-13 No noncompliance noted CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/07/21 2pp

~~8009100884 IE Insp Repts 50-352/80-13 & 50-353/80-11 on 800602-13 No moncompliance noted Hajor areas inspected Unit 1. installation & welding of safety-related piping & supports. Unit 2. tour of facility conducted HATTIA. J C Region 1. Philadelphia. Office of the Director McGAUGHY.R W Region 1 Philadelphia. Reactor Construction & Engineering Support Branch 60/07/16 App

8009090222 Ack receipt of 800710 ltr informing NRC of steps taten to correct violations noted in IE lnsp Repts 50-352/80-04 & 50-353/80-04 CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/08/05 Ip

--8009090226 Responds to NAC 800olo ltr re violations noted in IE Imap Repts 50-352/80-04 & 50-353/80-04 Corrective actions concrete strength will be based on 90-day Compressive strength tests KEMPER.J S Philadelphia Electric Co 80/07/10 4pp

--B009070229 Forwards 1E Insp Repts 50-352/80-04 & 50-353/80-04 en B00319-21 & 0402-04 No noncompliance metad GARLSON, R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/10 2pp

--BOQ7090232 IE Insp Repts 50-352/80-04 & 50-353/80-04 on BO0319-21 0402-04 No noncompliance noted One deviation noted failure to meet FSAR commitment for concrete strength in 20-day compression tests
ERMETER, S D Region 1. Philadelphia. Reactor Construction & Engineering Support Branch CHAUDHARY, S K Region 1. Philadelphia. Office of the Director B0/06/06 7pp

8009100022 Ack receipt of 800717 ltr informing NRC of steps taten to correct violations noted in IE insp Repts 50-352/80-05 & 50-353/80-05 CARLSON-R T Region i. Philadelphia. Reactor Construction & Engineering Support Branch 80/08/05 ip

--8009100025 Forwards IE insp Repts 50-352/80-05 & 50-353/80-05 or -0430 & notice of violation CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/19 2pp

--8007100028 Notice of violation from insp on 800026-0430
** Region i. Philadelphia, Office of the Director 80/06/13

- --8009100030 IE Insp Repts 90-352/80-05 & 50-333/80-05 on 800326-0430 Honcompliance noted failure to repair weld cavity properly for pape restraint MCGAUGHY,R W Region 1. Philadelphia. Reactor Construction & Engineering Support Branch MATTIA: J C Region 1. Philadelphia, Office of the Director 80/06/13 19pp
- 8009190044 Ack receipt of 800804 ltr informing NRC of steps taken to Currect indiations noted in IE Insp Repts 50-352/80-09 & 50-353/80-08 SMITH, G H

of Region 1, Philadelphia, Fuel Facility & Materials Safety 80/08/14 ip

- -8009190048 Responds to NRC 800714 ltr re violations noted in IE Insp Repts 50-352/80-09 & 50-353/80-08 Corrective actions sewage pumped on continuous batch basis from holding tanks to treatrent plant KEMPER. J S Philadelphia Electric Co 80/08/04 3pp
- --8007190049 Forwards IE (nsp Repts 50-352/80-09 & 50-353/80-08 on 800522-27 & notice of violation SMITH/S H Region I. Philadelphia. Fuel Facility & Materials Safety Branch 80/07/14 2pp
- --8009190053 Netice of violation from insp on 800522-27

 * Region i, Philadelphia, Fuel Facility & Materials Safety Branch 80/07/07 ip
- --8009190056 IE Insp Repts S0-352/80-09 & 50-353/80-08 on 800522-27
 Noncompliance noted failure to control untreated wastewater
 & discharge from site
 BORES, RJ Region i, Philadeiphia, Fuel Facility & Haterials
 Safety Branch JACKSON.T J Region I, Philadelphia, Office of the
 Director 80/07/07 9pp
- 80090300B3 Forwards Revision i to IE Bulletin 80-i9. "Failures of Marcurq-Vetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Hritten response required GRIER, B M. Region i, Philadelphia, Office of the Director 80/08/15 19
- 8009120105 Forwards Suppl 3 to IE Builetin BO-17, "Failure of Control Rods to Insert During Scram at BWR " No written rasponse required GRIER B H Region (, Philadelphia, Office of the Director BO/08/22 1p
- 8009180035 Forwards IE Circular 80-18, "10CFR50 39 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required
 GRIER, B M Region 1, Philadelphia, Office of the Director
 BO/06/22 ip
 - 8009120200 Forwards IE info Notice 80-31, "Maloperation of Oguid-Brown Bover: 480 Volt Type K-600S & K-DON 6008 Circuit Breakers " No written response required CRIER: B H Region 1, Philadelphia, Office of the Director 80/09/27 lp
 - B009230794 Forwards IE Carcular 60-21, "Regulation of Refuelang Craws " NA written response required
 ORIER B H Region I. Philadelphia, Office of the Director
 80/09/10 ip
- 8009240353 Forwards IE Info Notice 80-32. "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matis " No written response required ORIER.O If Region i. Philadeiphia. Office of the Director 80/09/12 ip
- S Reportable occurrences, LERs & related correspondence
- 8009040425 Advises of completion of investigation of engineering documents re Fairbanks Horse Model 381D8-1/8 powered generator sets wistacked heat erchangers Potential for situation similar to Limerick does not exist MORIARTY. J M Colt Industries. Inc., Fairbanks Morse Engine Div 80/08/27 1p
- U Congressional/Executive Correspondence
- BOO9100073 Discusses 800527 testimony by V Boyar, util senior vice president, re emergency planning NRC met w/Boyar on BO0630 Boyer has committed to assuring that all util mgt lovels have sincere commitment to effective emergency measures AHEARNE, J.F. Commission BO/08/20 Ip

- --8009100078 Discusses 800527 testimony by V Boyer, util senior vice president, re emergency planning NRC met w/Boyer on 800630 Boyer has committed to assuring that all util mgt levels have sincere commitment to effective emergency measures AMEARNE, JF Commission 80/08/20 lp
- DUCKET 50-353 LIMERICK GENERATING STATION, UNIT 2 A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl H/o NUREO EISENHUT, D & Division of Licensing 80/08/01 119pp
- B009110742 Notification of 800904-05 meeting w/Mark II owners group to discuss plants chugging C/D & lateral load specs ANDERSON C Containment Systems Branch 80/08/29 14pp
- B Utility Preliminary Safety Analysis Report, amends
- 8009290378 Forwards Amend 24 to application for OL & revised Pages to PSAR Summary description of amend revision encl BRADLEY, C J Philadelphia Electric Co 80/09/24 4pp
- --8009290380 Amend 24 to application for QL Revises PSAR Pages 5 12-13 to 5 2-16, Certificate of Svc encl GOYER, V S Philadelphia Electric Co 80/09/24 4pp
- --8009290382 Amend 24 to PSAR, revising Pages 5 2-13 & 5 2-16.
 * Philadelphia Eiectric Co 80/09/24 3pp
- F Security, medical, emergency & fire protection plans
- 8009170332 Forwards "Limerick Muclear Generating Station Preliminary Evacuation Time Estimates " Rept withheld (ref (OCFR2 790) BERNLEY, J NUS Corp 80/08/22 ip
- H General correspondence
- 8007180448 Responds to 800319 itr requesting public debate re issues appropriate to evacuation of large population ctrs mear plants
 DENION.HR Office of Nuclear Reactor Regulation, Director 80/04/21 Spp
- --8009180462 Requests public debate re issues appropriate to evacuation of large population ctrs near plants Expresses confidence in attempts by Commissioners to represent public concerns EMORY, K. Affiliation Unknown 80/03/19 Ip
- 8009220078 Responds to 800809 itr expressing opposition to const of facilities Util application for OLs will be subjected to detailed safety & environ reviews by NRC & may be subj of public haaring if application is contested INORAM.F. Office of Public Affairs 80/08/13 ip
- --8009220081 Expresses concern re const of facilities Forwards newspaper article re dangers of nuclear plants MayER.P Affiliation Unknown 80/08/09 2pp
- 80091503i6 Responds to 8007i8 ltr to Prosident Carter transmitting Borough of Phoenixville.PA resolution opposing const of nuclear reactors Facility is not undergoing review Util studies re evacuation time ostimates have been submitted DENTON.H R Office of Nuclear Reactor Regulation, Director 80/08/25 2pp
- --8007150318 Forwards Borough of Phoenixville,PA 800718 ltr to President Carter,transmitting Resolution 80-10 opposing const of nuclear reactors Requests response SEAL.M M President of US & Executive Offices 80/07/25 Opp
- O Inspection reports, IE Bulletins & correspondence
- 8007070087 Forwards IE Bulletin 80-07. Suppl 1, "BWR Jet Pump Assembly Failure" No response required GRIER.8 H Region I, Philadelphia. Office of the Director 80/05/13 1p
- 8009100881 Forwards IE Inap Rapts 50-352/80-13 & 50-353/80-11 on 800502-13 No noncompliance noted CARLSON.R T Region i Philadelphia, Reactor Construction & Engineering Support Branch 80/07/21 2pp

- --8009(00884 iE Insp Repts S0-392/80-13 & 50-353/80-11 on 800602-13 No noncompliance noted Major areas inspected Unit 1, installation & welding of sarety-related piping & supports; Unit 2, tour of facility conducted MATTIA, J C Region 1, Philadelphia, Office of the Director MCCAUGHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/16 6pp
- 8009090222 Ack receipt of 8007i0 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-352/80-04 & 30-352/80-04 CARLEON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/05 ip
- --8009090226 Responds to NRC 800610 itr re violations noted in IE Insp Repts 50-352/80-04 & 30-353/80-04 Corrective actions concrete strength will be based on 90-day compressive strength tests KEMPER.J S Philadeiphia Electric Co 80/07/10 4pp
- --8007070227 Forwards IE Insp Repts 50-352/80-04 & 50-353/80-04 on 800319-21 & 0402-04 No noncompliance noted CARLSOM,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/10 2pp
- -- 8009090232 IE Insp Repts 50-352/80-04 & 50-353/80-04 on 800319-21 & 0402-04 No noncompliance noted flat deviation noted failure to meet PSAR commitment for concrete strength in 28-day compression tests

 EBNETER, S D Region 1, Philadelphia, Reactor Construction & Engineering Support Branch CHAUDHARY, S K Region 1, Philadelphia, Office of the Director 80/06/06 7pp
- BGG910G022 Ack receipt of B00717 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-352/80-05 & 50-353/80-05 CARLSON-R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch B0/08/05 1p
- --8009100026 Responds to NRC 800619 itr re violations noted in IE lusp Repts 90-352/80-05 & 50-393/80-05 Corrective actions weld cavity repaired for pipe restraint KEMPER, J S Philadelphia Electric Co 80/07/17 3pp
- --8007100025 Forwards IE Insp Repts 50-392/80-05 & 50-353/80-05 on 800326 -0430 & natice of violation CARLSON,R T Region 1, Philadeiphia, Reactor Construction & Engineering Support Branch 80/06/17 2pp
- --8009100028 Notice of violation from insp on 800326-0430
 # Region 1, Philadeiphia, Office of the Director 80/04/13 1;
- --8007100030 IE Insp Repts 50-352/80-05 % 50-353/80-05 on 800326-0430 Moncompliance noted failure to repair weld cavity properly for pipe restraint MCGAUGHYR W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch MATTIA.J C Region 1, Philadelphia, Office of the Director 80/06/13 19pp
- 8009190044 Ack receipt of 800804 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-352/80-09 & 50-353/80-08 SMITH.Q H Region i, Philadeiphia, Fuel Facility & Materials Safety Branch 80/08/14 ip
- --8009190048 Responds to NRC 800714 ltr re violations noted in IE Insp Repts 50-352/80-09 \$ 50-353/80-08 Corrective actions sewage gumped on continuous batch basis from holding tanks to treatment plant KFNPER.J S Philadeiphia Eiectric Co 80/08/04 3pp
- --B009190049 Forwards IE Insp Repts 50-392/80-09 & 50-393/80-08 on 800522-27 & natice of violation SMITH,0 H Region i. Philadelphia. Fuel Facility & Materials Bafety Branch 80/07/14 2pp
- --8007190053 Notice of violation from insp on 800522-27. « Region i. Philadeiphia, Fuel Facility & Materials Safety Branch 50/07/07 ip
- --BOO9190056 IE Insp Repts 50-352/80-09 & 50-353/80-08 on 800522-27
 Noncompliance noted failure to control untreated wastewater
 & discharge from site
 BORES,R.J. Region 1, Philadelphia, Fuel Facility & Materials
 Safety Branch JACKSON,T J Region 1, Philadelphia, Office of the
 Director 80/07/07 9pp

- 8009030083 Forwards Revision 1 to LE Bulletin 80-19. "Failures of Mercury-Wettod Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by CrE " Uritten response required ORIER B H Region 1, Philadelphia, Office of the Director 80/09/15 Ip
- 8009120106 Forwards Supp) 3 to 1E Builetin 80-17, "Failure of Control Rads to Insert During Scram at BWR 'No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/08/22 1p
- 8007180035 Forwards IE Circular 80-18, "10CFRSD 57 Safety Evaluations for Changes to Radwasto Treatment Sys " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/08/22 1p
- 8009120200 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover(480 Volt Type K-6005 & K-DDN 6005 Circuit Breakers " No written response required ORIER B H Region (, Philadeiphia, Office of the Director 80/08/27 ip
- 8009230794 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required GRIER, B H Region i. Philadelphia. Office of the Director 80/99710 ip
- 8009240353 Forwards IE info Notice 80-32 "Ciarification of Certain Requirements for Exclusive-Use Shipments of Redioactive Matis " No written response required GRIERS H Region 1. Philadelphia. Office of the Director 80/09/t2 1p
- S Reportable occurrences, LERs & related correspondence
- 8009040425 Advises of completion of investigation of engineering documents re Fairbanks Korse Model 38TU8-1/8 powered generator sets w/stacked heat exchangers Potential for situation similar to Limerick does not exist MORIARTY, J M Colt Industries, Inc., Fairbanks Morse Engine Div 80/08/27 io
- U Congressional/Erecutive Correspondence
- 8009100073 Discusses 800927 testimony by V Boyer util senior vice president, re emergency pianning NRC met w/Boyer on 800630 Boyer has committed to assuring that all util mgt levels have sincere commitment to effective emergency measures AHEARNE, J F Commission 80/08/20 ip
- --8009190078 Discusses 800527 testimong by V Boyer, util senior vice president, re emergency pianning NRC met w/Boyer on 800630 Boyer has committed to assuring that all util mgt levels have sincere commitment to effective emergency measures AMEARNE, J F Commission 80/08/20 ip
- DOCKET SO-354 HOPE CREEK NUCLEAR STATION, UNIT I
- A Application/construction stage documents & correspondence
- 8007080080 Forwards draft NUREQ-0676, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0676 ent NO NUREO EISENHUT. D
- Q007180168 Forwards NUREG-0661, "Mark I Containment Long-Term Program SER Resolution of Generic Technical Activity A-7 " Rept describes requirements re generic suppression good hydrodynamic load M/o enc! SCHMENGER, A Licensing Branch 3 80/08/20 2pp
- @ Inspection reports, IE Bulletins & correspondence
- 8009090096 Forwards IE Bulletin 80-07.Suppl [, "BWR Jet Pump Assembly Failure " No response required GRIER.O H Region i, Philadelphia, Office of the Director 80/05/13 |p
- B0091501B7 Forwards IE Insp Repts 50-354/80-09 % 50-355/80-09 on 800602-27 No noncompliance nated CARLSON.R T Region 1. Philadelphia, Reactor Construction % Engineering Support Branch 80/07/25 2pp

- --8009190190 IE Insp Repts 50-354/80-07 & 50-355/80-09 on 800402-27 No noncompliance noted Major areas inspected PDN vent line belious repair, backfilling 3 compaction testing structural steel installation & welding activities inside containment BATEMAN,N H , MCGAUCHY,R W Region 1, Philadelphia, Office of the Director 80/07/24 8pp
- 8009110472 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASKE SA-012.Type 304 Stainless Steel Pige" No ASKE SA-012.Type 304 Stainless Steel Pige" No ASKE SA-012 or ASKM A-012 Type 300 series fusion-welded piping products use greater than 85% of allowable stresses MARTIM T J Public Service Electric & Gas Co of New Jersey 80/07/30 2pp
- 8009190203 Ack receipt of 800721 ltr informing NRC of staps taken to correct violations noted in 1E Insp Repts 50-354/80-04 & 50-355/80-04 CARLSON:R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/08/06 ip
- --8009190210 Responds to NRC 800518 itr re violations noted in IE Insp Rapts 50-354/80-04 \$ 50-355/80-04 Corrective actions review of concrete specs & procedures & training for all civil GC examiners increased MARTIN.T J Public Service Electric & Gas Co of New Jersey 80/07/21 3pp
- --B009190214 Forwards IE insp Repts 50-354/80-04 & 50-355/80-04 on 800331 -0430 & notice of violation CARLSOLAR T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/18 2pp
- --8009190216 Notice of violation from insp on 800331-0430 * Region 1, Philadelphia, Office of the Director 80/06/17 1p
- --8009190223 IE Insp Repts 50-354/80-04 & 50-355/80-04 on 800331-0420 Noncompliance noted failure to follow procedures designed to prevent segregation of concrete during placement & failure of QC to take action to stop improper placement MCCAUGHY.R W. BATEMAN.H H. Regson I. Philadelphia. Office of the Director 90/06/17 13pp
- 8009030060 Forwards Revision 1 to IE Bulletin BO-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E" Written response required GRIER.8 H Region i, Philadelphia, Office of the Director 80/08/15 ip
- 8009:20110 Forwards Suppl 3 to 1E Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR" No written response required GRIER,8 H Region 1, Philadelphia, Dffice of the Director 80/08/22 ip
- 8009180044 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required ORIER B H Region 1, Philadelphia, Office of the Director 80/08/22 lp
- 8007070557 Responds to 1E Bulletin 80-16 re potential misapplication of Rosemount Models 1151 & 1152. Investigation should be completed by 801110 Awaiting response from Bechtel & AE MARTINIT J Public Service Electric & Gas Co of New Jersey
- 8009120239 Forwards 1E info Notice 80-31, "Maloperation of Qould-Brown Boveri ABO Volt Type K-6008 & K-DON 6008 Circuit Breakers" No written response required ORIER, B R Region 1, Philadelphia, Office of the Director BO/08/27 1p
- -8009230795 Forwards 1E Circular BD-21, "Regulation of Refueling Crews" No written response required ORIER.B H Region 1, Philadelphia, Office of the Director 80/09/10 1p
- 8009240330 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Erclusive-Use Shipments of Radioactive Matls " No written response required ORIER.B H Region 1, Philadelphia, Office of the Director 80/09/12 1p

- S Reportable occurrences, LERs & related correspondence
- B009120218 Part 21 rept re epoxy surface sys whose qualification is indeterminable due to conflicting data in qualification test repts b data not supported by actual test results investigation is continuing MARTIN.T J Public Service Electric & Gas Co of New Jersey 80/08/12 2pp
- 8009190037 Ack receipt of interim rept re potential significant deficiency of biological shield supplied by PX Engineering Co CARLSUN, A T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/20 1p
- --8009150043 Interim rept re potential significant deficiency of biological shield supplied by PX Engineering Co Bechtel currently conducting investigation of documentation & effecting re-examination where appropriate MARTIN.T J. Public Service Electric & Gas Co. of New Jersey 80/08/07.
- B007160650 Part 21 rept re Con/Chem upoxy surfacer sys Suppls B00812 itr re sub; item reported by Bechtel Power Corp Will advise of schedule dates of completion when Bechtel engineering studies finalized MARTIN.TJ Public Service Electric & Qas Co of New Jersey 80/09/02 2pp
- DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days. Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT, D O Division of Licensing 80/08/01 119pp
- BO0918016B Forwards NUREO-0661. "Mark 1 Containment Long-Term Program SER Resolution of Generic Technical Activity A-7 " Rept describes requirements re generic suppression pool hydrodynamic load M/a encl SCHMENCER, A Licensing Branch 3 80/08/20 2pp
- 9 Inspection reports, IE Bulletins & correspondence
- 8009090094 Forwards IE Bulletin 80-07. Suppl 1, "BNR Jet Pump Assembly Failurs" No response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/05/13 1p
- 8009190187 Forwards lE lnsp Repts 50-354/80-09 & 50-355/80-09 on 800602-27 No noncompliance noted CARLSON.R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/07/25 2pp
- ~-8009150190 IE lnsp Repts 50-354/80-09 & 50-355/80-09 on 800602-27 No noncompliance noted Major areas inspected PDM vent line bellows repair backfilling & compaction testing, structural steel installation & welding activities inside containment BATEMANN W H. MCGAUGHY, R W Region 1, Philadelphia, Office of the Director 80/07/24 Spp
- 8009110472 Responds to IE Bulletin 79-03A, "Longitudinal Weld Defects in ABME SA-312. Type 304 Stainless Steel Pipe " No ABME SA-312 or ASTM A-312 Type 300 series fusion-walded piping products use greater than 85% of allowable stresses MARTIN.T J Public Service Electric & Gas Co of New Jarsey E0/07/30 2pp
- 8007190203 Ack receipt of 800721 ltr informing NRC of steps taken to correct violations noted in IE Insp Rapts 50-354/80-04 & 50-355/80-04 CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/06 1p
- --8009190210 Responds to NRC 800618 ltr re violations noted in IE Insp. Repts 50-35480-04 & 50-355/80-04 Corrective actions review of concrete specs & procedures & training for all civil GC examiners increased MARTINIT J Public Service Electric & Gas Co. of New Jersey 80/07/21 3pp
- --8007190214 Forwards IE Insp Repts 50-354/80-04 & 50-355/80-04 on 800331 -0430 & notice of violation. CARLSGULR T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/18 2pp

- --B009190223 IE Insp Repts 50-354/80-04 & 50-355/80-04 on B00331-0430 Noncompliance noted failure to follow procedures designed to prevent segregation of concrete during placement & failure of QC to take action to stop improper placement MCGAUOHY, R W. BATEMAN, W H. Region 1, Philadelphia, Office of the Director B0/08/17 i3pp
- BOCPO30060 Forwards Revision 1 to 1E Sulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Pients Designed by C-E " Written response required GRIER, 8 H Region 1, Philadelphia, Office of the Director 80/08/15 19
- 8009;20;10 Forwards Suppi 3 to 1E Builetin 80-17, "Failure of Control Rods to Insert During Scram at BWR " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/08/22 1p
- B0091B0044 Forwards IE Circular 80-18, "10CFR30 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GRIER.B H Region 1. Philadelphia, Office of the Director 80/08/22 ip
- 8007090559 Responds to IE Bulletin 80-16 re potential misapplication of Rosemount Models 1551 & 1152 Investigation should be completed by 801110 Awaiting response from Bechtel & AE MARTIN,T J. Public Service Electric & Oas Co. of New Jersey 80/09/27 1p
- 8009120239 Forwards (E Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6005 & K-DON 6008 Circuit Breakers" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/08/27 1p
- 6009230795 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required ORIER.B H Region 1. Philadelphia, Office of the Director 80/09/10 1p
- 8009240330 Forwards IE Info Notice 80-32. "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Hatls " No written response required QRIER, B.H. Region I. Philadelphia. Office of the Director 80/09/12 1p
- DOCKET 50-356 UNIV OF ILLINOIS LOPRA RESEARCH REACTOR

 Reproduct operating reports & related correspondence
- BOOGISC456 Forwards "Annual Rept.Aug 1979-Aug 1980.IL LOPRA Reactor " BECK.G P , CHILTON.A B Illinois, Univ of Urbana-Champaign BO/09/05 1p
- --8009150461 "Annual Rept. Aug 1979-Aug 1980, IL LOPRA Reactor "
 11linois, Univ of, Urbana-Champaign 80/09/05 ip
- DOCKET 50-358 WILLIAM H ZIMMER NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8009020617 Confirms 800724 telcon arranging NRC 800730 & 31 meeting M/several BHR license Forwards sample ltr w/meeting schedule HEISHMAN.R F Region 3, Chicago, Reactor Operations Nuclear Support 8ranch 80/07/24 1p'
- 8009080080 Forwards draft NUREO-0676, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0676 encl W/o NUREO EISERHUT, D O Division of Licensing 80/08/01 119pp
- 8009070631 Notification of cancellation of 800827 mosting w/BWR licensing review group to discuss concensus positions on TMI 1stues (NURED-0694) WILSON,J N Assistant Director for Licensing 80/08/04 10pp
- 8009110255 Requests that util advise NRC on number of lines exempted on main steem.nuclear boiler, residual heat removal, coolant injection, reactor recirculation & standby liquid control sys re permitted exemptions under ASME Code. Section XI, iHB-1220 ECHMENCER. A Licensing Branch 2 80/08/21, 4pp

- BOO9110742 Notification of GOO904-05 meeting w/Mark II owners group to discuss plants chugging C/O & lateral load specs ANDERSON.C Containment Systems Branch BO/OB/29 14pp
- 800926067: Forwards request for additinfo re Category I masonry wall design
 TEDESCO.R L Assistant Director for Licensing 80/09/10 5pp
- BO09290086 Forwards positions re degraded grid voltage & protection of reactor containment electrical penetrations, developed during review of FSAR Requests date or response TEDESCO.R L. Assistant Director for Licensing 80/09/12 App
- 8009260091 Notifies of 801007 proposed date to review whether OBE & SRV responses should be considered separatrly or combined during ASNE code fatigus calculations GE selected samples to emphasize highly fatigued components WILSON, J N Assistant Director for Licensing 80/09/15 9pp
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8007250267 Requests add1 info re containment pressure boundary fracture toughness for final SER completion
 TEDESCO.R L. Assistant Director for Licensing 80/09/10 3pp
- F Security, medical, emergency & fire protection plans
- 8009030588 Forwards Revision 16 to "Fire Protection Evaluation Rept "
 DDRGMANN, E A Cincinnati Gas & Electric Co 80/08/29 1p
- --8009030590 Revision 16 to "Fire Protection Evaluation Rept "
 * Cincinnati Gas & Electric Co BO/08/31 2pp
- 8009080333 Comments on util 800818 preliminary evacuation time study & requests NRC insure that City of Mentor has integral role in facility emergency planning Study has serious flaws that must be examined & corrected REDER.M Mentor,KY 80/09/02 2pp
- BOO9280490 Immediate action itr re potentially deficient fire stop mat1 mfg by Tech-Bil, inc Lists products found to be in nonconformance w/project & NRC requirements & actions to be completed before leaded elastomer installation is continued KEPPLER, J. Ø Region 3. Chicago. Office of the Director 80/09/04
- O Adjudicatory correspondence
- 8007030693 Response to parties' comments on Contention 5 per ASLB 800714 order re-potential hazards of irradiated fuel transportation Urges same degree of protection for residents of nonurban areas Certificate of Svc & address change enci FANKHAUSER, D Frankhauser, D D WOLIVER, J Woliver, J D 80/08/26
- 8009020445 Forwards Commission 800819 amend to emergency planning rules N/o encl
 BARTH, C A. Hearing Branch 3 80/08/29 Ip
- 8009050272 Responds to ASLB 800804 memorandum on behalf of utiline util k NRC plans for analyzing & evaluating safety significance of 800727 earthquake Util has concluded that event had no safety significance for facility CONNER.T B Conner. Moore & Corber CONNER.T B Gincinnati Qas & Electric Co 80/09/02 2pp
- B009100595 Response in apposition to applicants' motion for summary disposition of Contention 5.per ABLB B00714 order inviting comments in light of physical protection final rule Burden of proof not sustained Certificate of 5vc encl MARTIN.D K , BESHEAR, S L Kentucky, State of 80/09/04 10pp
- 8009220413 Memorandum advising MRC to provide ASLB w/best estimate for issuance of BER suppline unresolved generic issues Urgas NRC to evaluate applicants financial ability relitems mandated by TMI accident & various contingencies
 BECHHOEFER, C Atomic Safety and Licensing Board Panel 80/09/17
 40n
- B009300D16 Response in opposition to State of KY B00904 objection to summary disposition of Contention 5 Concurs w/ASLB B00714 memorandum & order Challenge to spent fuel casks design is barred as matter of law Certificate of Svc encl CONNER, T B , NETTERHAHN, M J Cincinnati Oas & Electric Ce CONNER, J B Conner, Moore & Corber B0/09/23 7pp

a inspection reports, IE Bulletins & correspondence

- 8009040531 Forwards IE Bulietin 80-07, Suppl 1. "BWR Jet Pump Assembly Failure " Response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/14 to
- 8009110655 Forwards IE insp Rept 50-358/80-15 on 800623-27 & notice of violation FIDRELLI.6 Region 3. Chicago, Reactor Construction & Engineering Support Brench 80/07/25 2pp
- --8009110656 Notice of violation from insp on 800623-27

 d Region 3. Chicago, Office of the Director 80/07/25 ip
- ~-8009110661 IE Insp. Rept 50-358/80-15 on 800623-27 Noncompliance noted failure to establish controls to assure that structural design changes are implemented in field & verified by GC KNOP, R.C., BARRETT, P.A. Region 3, Chicago, Office of the Director 80/07/25 4pp
- 8009160509 Forwards IE Insp Rept 50-358/80-14 on 800602-06,09-10.16-20 & 23-26 & notice of violation HEISHMAN R F Region 3, Chicago. Reactor Operations Nuclear Support Stanch 80/07/31 2pp
- --8009160512 Notice of violation from insp on 800602-06.09-10.16-20 t 23-26
 - * Region 3, Chicago, Office of the Director 80/07/30 2pp
- --8009160314 IE Insp Rept 90-358/80-14 on 800602-06,09-10,16-20 & 23-26 Noncompliance noted inadequate corrective action to control weld rod & inadequate corrective action taken on audit findings WARNICK, R.F., DANIELS, F.T. Region 3, Chicago, Office of the Director 80/07/30 7pp
- 8009030192 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER. J O Region 3. Chicago, Office of the Director 80/08/15
- 8009150473 Forwards IE Info Notice 80-30. "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE BNR Facilities " No specific action or response requested MERPLER.J Q Region 3. Chicago, Office of the Director 80/08/20 is
- 8009120032 Forwards Suppl 3 to IE Bulletin 80-17. "Failure of Control Rods to Insert During Screm at BNR " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/08/22 to
- 8007170408 Forwards IE Circular 80-18, "IOCFR50 57 Safe.y Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER.J Q Region 3, Chicago, Office of the Director 80/08/22 to
- 8009230081 Forwards IE info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6005 & K-DDN 6005 Circuit Breakers " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/08/28
- 8009250223 Ack receipt of 800804 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-358/80-09 KEPPLER.J O Region 3, Chicago. Office of the Director 80/08/30 to
- --8009250227 Responds to NRC 800702 ltr re violations noted in IE Insp Rept 50-358/80-09 Corrective actions HJ Raiser procedure re control of nonconforming matls will be revised BURGMANN.E A Cintinnati Gas & Electric Co 80/08/04 2pp
- 709170422 Responds to IE Bulletin 80-19 & Revision 1 re failures of mercury-wetted matris relays in reactor protective sysdentified relays are not used in facility Four manhours spended for investigation

 OROMANNIE A Cincinnati Oas & Electric Co 80/09/02 ip
 - 9170427 Responds to 1E Bulletin 80-20 re failures of Westinghouse pe N-2 spring return to neutral control switches are not used in safety-related areas mandays expended for investigation MANN. E A Cincinnati Gas 4 Electric Co 80/09/02 1p

- 8009260137 Responds to IE Bulletin 80-17 & Ravision 1, "Failures of Mercury-Netted Matrix Ralays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Relays not utilized in reactor protective sys of facility BORGMANN.E A Cincinnati Gas & Electric Co 80/09/03 1p
- 8009240090 Forwards IE Circular 80-21, "Regulation of Refueling Creus" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/10 15
- 8009250146 Forwards request for info re turbine disc for NRC review of inservice insp program TEDESCOR L Assistant Director for Licensing 80/09/10 4pp
- 8007290448 Ack receipt of 800821 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/80-15 FIORELLI,O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/09/10 ip
- --B009290460 Responds to NRC ltr re violations noted in IE Insp Rept 50-358/80-15 Corrective actions procedure establishing method to verify field activities will be issued BCRSMANN.E A Cincinnati Gas & Electric Co 80/08/21 2pp
- 8 Reportable occurrences, LERs & related correspondence
- 8007150062 Part 21 rept re power plant noncomplying valves Reanalysis 90% complete Corrective action involves design changes & review by customer engineering & field personnel High priority on valves which must meet increased loading.
 NIEHAUS; P W William Powell Co 80/08/03 2pp
- 8009100620 Ack receipt of 800804 ltr informing NRC of actions taken to correct deficiency re Ruskin fire dampers FIORELLI.G Region 3, Chicago: Reactor Construction & Engineering Support Branch 80/08/25 ip
- 8009250490 Immediate action ltr re potentially deficient fire stop mati mfg by Tech-8il, Inc Lists products found to be in nonconformance w/project & NRC requirements & actions to be completed before leaded elastomer installation is continued KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/04
- DOCKET 90-361 BAN DNOFRE NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8009120505 Notification of contract execution, Mod 5 to "Bimulation of Earthquake Ground Motions for San Onofre " Contractor K Aki MCNULTY.A Administrative Contracts Branch FIN B-6531 80/04/01 to
- --8009120514 Mod 5, extending period of performance & adding add1 funds to "81mulation of Ground Motions for San Onofre" AKI.K Massachusetts Institute of Technology PERLMAN, J Administrative Contracts Branch FIN B-6531
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 enci W/o NUREG EISENHUT, D & Division of Licensing 80/08/01 119pp
- 8007020006 Forwards addendum to June 1980 response to Guestion 361 63, re origin of Polds & fauits offshore & south of facility.per NRC request during 800814 geosciences meeting Addendum will be included in Amend 21 to FSAR, to be submitted in Oct 1980 BASKIN.K P Southern California Edison Co 80/08/22 2pp
- --8007020007 Addendum to June 1780 response to Guestion 361 63 re origin of folds & faults.offshore & south of facility Four composite geologic cross-sections encl * Southern California Edison Co 60/08/22 23pp
- ~~8007020010 "Offshore Geologic Structure," Plate 2. Sheet 12 * Southern California Edison Co 80/08/31 ip.
- 8009100417 Bummary of 800724 meeting w/applicants to discuss analysis of Imperial Valley earthquake of Oct 1979 ROOD.H Licensing Branch 3 80/08/27 16pp
- 8009150420 Notification of contract execution "Followon to Simulation of Earthquake Oround Motions for San Onofre Nuclear Generating Station." awarded to E Luco LITLE, M Administrative Contracts Branch FIN B-6898-0 80/08/27 in

- 8009180227 Notification of 800909-10 meeting w/util to conduct caseload forecast panel site visit ROOD.M Licensing Branch 3 80/08/27 4pp
- BOO9140252 Summary of 800812-15 meeting w/Southern CA Edison Co.C-E.
 Bechtel & San Diego Ges & Electric Co in Bethesda,MD to
 discuss non-TMI related open items
 EDGD.H Licensing Branch 3 80/08/27 lipp
- 8009240622 Notification of 800909-il meeting w/util in San Clemente.CA to conduct electrical site visit 8000.H Licensing Branch 3 80/08/27 3pp
- BOO9240052 Notification of contract execution "Foilowon to Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station " Contractor R Hermann LITILE. K Administrative Contracts Branch FIN B-6898-0 80/08/28
- --8009240057 Contract "Followon to Simulation of Earthquake Ground Hotions for San Onofre Nuclear Generating Station," awarded to R Hermann HERMARN, R 5t Louis Univ PERLMAN, J Administrative Contracts Branth FIN 8-6898-0
- BOOPOSO302 Forwards responses to NRC BOOB23 to O616 ltrs.proprietary & monpreprietary versions of CEN-135(s), "CPC/CEAC Boftware Mads for San Onefre Unit 2," in response to NRC question 221 IS listhholding affidavit encl BASKIN.K.P. Bouthern California Edison Co 80/09/03 77pp
- --8009030308 "CPC/CEAC Software Mods for San Onofre Unit 2 " Proprietary version withheld (ref 10CFR2 790)

 2 Combustion Engineering, Inc. CEN-135(S)-NP 80/08/31 79pp
- B007510547 Nobification of 800910 meeting w/util & C-E in Bethesda, MD to discuss NRC questions re CEMPD-178
 ROOD-H Licensing Brench 3 80/09/04 3pp
- 8009(20273 Notification of 800909 meeting w/util & C-E in Windsor,CT to discuss audit of CENPD-17B analysis methods
 RCOD.H Licensing Branch 3 80/09/04 3pp
- S009380330 Forwards questions to Executive Order 11988 Flood Plain Mgt Response requested by 800912 TEDESCO.R L. Assistant Director for Licensing 80/09/04 App
- 8009290143 Natification of 800926 meeting w/utils & Kerr-McGee Chemical Corp in Bethesda, MD to discuss review & recommendations for site specific ground response spectra & program plans for reismic functional qualification of Class IE equipment ALLISON, D. P. Systematic Evaluation Program Branch 80/09/08 3pp
- BOO9170913 Notification of BOO923 meeting w/util.USOS & CDMO in Menio Part.CA to discuss seismology & geology re facilities.
 RDOD,H Licensing Branch 3 BO/09/09 3pp
- 900918042! Forwards response to hydraulic engineering questions re flood plain mgt, per NRC 800904 request Sito does not fail within floodplain as defined by Executive Order 11988 BASKIN.K P Southern California Edison Co 80/09/10 4pp
- --8009180429 "Preconst Ficodplains, Units 2 & 3 "
 # Southern California Eduson Co 80/09/10 1p
- --8009:80433 "Post-Const Floodplains. Units 2 & 3 "

 ** Southern California Edison Co 80/09/10 ip
- BOG9250190 Approves of util 800115 plans to terminate preoperational monitoring program
 SCHWENCER, A Licensing Branch 3, 80/09/11 3pp
- 3009250451 Forwards proposed memorandum of agreement for San Onofre transmission lines & two ltrs from State of CA, Dept of Parks & Recreation, per 800909 teleon Formal request for concurrence will follow shortly SCALETTE.D. 2 Licensing Branch 3 80/09/13, 9pp
- ~8009250456 informs of assuming H Bass responsibilities Requests informal meeting w/NRC to discuss directions of mutual interests in preserving cultural resources BELL.D A. California, State of B0/04/18 ip

- F Security, medical, emergency & fire protection plans
- 8007030358 Notifies of 800819,22 % 30 regional workshops re development of guidance for acceptable method for coping w/emergencies at facility Requests that representative be sent Subj areas to be discussed include function of facilities & location E/GELKEN,R H Region 5. San Francisco. Office of the Director 80/08/12 2pp
- 8008270278 Forwards Jul 1980 revised emergency plantin response to NRC 791031 request for addl info Licensee is assisting local govt in devising emergency response procedures BASKIN:K P Southern California Edison Co 80/09/18 2pp
- 8009030387 Forwards revised safeguards contingency plan per NRC 791211 & 800324 requests Plan withheld (ref 100FR2 790) BASKIN;K & Southern California Edison Co 80/08/28 2pp
- 8009050286 Forwards Revision 1 to security force training 5 qualification plan Plan withheld (ref 10CFR2 790) BASKIN.K P Southern Callfornia Edison Co 80/09/03 lp
- 8009240347 Forwards emergency planning info for placement in focal PDR SQUOER, J L Division of Rules and Records 80/09/04 lp
- G Adjudicatory correspondence
- 8009020057 Order establishing discovery schedule Discovery re geology, seismology & emergency planning shall end 30 days following NRC safety evaluation & svc of emergency plan Depositions shall be completed 40 days after such svcs SMITH, I W Atomic Safety and Licensing Hoard Panel 80/08/27 5pp
- 8007160339 Forwards NUREC-75/111.NUREC-0654 & NUREC-0696 in response to 800811 tolcon re emergency planning into U/o encis DAVIS.L D Hearing Branch 4 80708/27 is
- 8009110396 Forwards stipulation to extend time within which Southern CA Edison Co will answer intervenor Friends of The Earth 800811 interrogatories PIGOTT,D R Chickering & Gregory 80/09/03 [p
- --8007110377 Stipulation between parties allowing Bouthern CA Edison Coestension until 800915 to respond to intervenor Friends of The Earth 800811 interrogatories Approved by ABLB on 8009708 PIGOTT, D.R. Southern California Edison Co. PIGOTT, D.R. San Diego Gas & Electric Co. PIGOTT, D.R. Chickering & Gregory 80/09/27
- BOO9:00406 Interrogatories directed to NRC re Cristianitos fault.
 Newport-Inglewood-Rose Canyon-San Miguel fault ione & other
 seismic-related issues Certificate of Svc enct
 HHARTON,R J. POGALIES, J K. Friends of the Eurth HHARTON,R J
 Hharton & Pogalies 80/09/04 17pp
- 8009190299 Responds to FDIA request for 15 documents listed in bibliography of NUREO-0625. "Rept of Biting Policy Task Force" Documents 6-8 & 13 are available in PDR Forwards remaining documents FELTOR: J M Division of Rules and Records 80/09/04 1p
- --Bog91905B7 Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants, for determination of site acceptability & adequacy of engineered safety features MINGOUE, R II Office of Standards Development, Director SECY-79-362 79/06/04 7pp
- --8009190630 Requests that enci. "Differences in Procedures for Estimating Atmospheric Dispersion Conditions at Inland & Coastal Bites." be sent to appropriate Boards SCINTOLY Hearings Division 79/04/04 16pp
- 8007070774 Forwards 800817 FR notice re final rules upgrading emergency planning regulations, effective 801103 CHANGLER, L. J. Hearing Branch 1 80/09/05 17pp
- 8009160341 Advises that NUREC-75/111, NUREC-0654 > NUREC-0696 were mailed on 800827 per 800828 inquiry about emergency planning into Discovery requests should be made through counsel Wharton DAVIS.L. D. Hearing Branch 4 80/09/11 1p

- 8009190083 Response to Intervenor Friends of The Earth 800811 fourth set of interrogatories Objects to portions requesting production of documents Certificate of Svc encl PIGOTT. DR. CASEY, S.B., KOCHER, C.R. Southern California Edison Co 80/09/15 46pp
- H General correspondence
- 8009050339 Urges NRC not to issue low power fuel loading license for Unit 2 LITFIN.K Affiliation Unknown 80/08/28 lp
- 8009120448 Upposes licensing of facility for low level fuel loading due to undue risks posed to public health & safety Requests to be informed of NRC actions & future public hearings HARRIB, J F Affiliation Unknown 80/08/28 ip
- 8009110395 Opposes licensing of facility KLEIN.S Affiliation Unknown 80/08/29 ip
- 8009110398 Opposes low lovel testing & licensing of facility, since no evacuation plan possible MARTINEZ P R Affiliation Unknown 80/08/29 lp
- 8009120183 Opposes licensing of facility for low power testing allowing bypass of new TM1 mods & evacuation laws Requests notification of public hearings on issue & any procedural change COH#N.E Affiliation Unknown 80/08/29 Ip
- 8009120441 Opposes licensing of facility for low level testing due to undus risks posed to health & safety of public & environ BRCWN,P Affiliation Unknown 80/08/29 ip
- 8009050350 Expresses apposition to nuclear energy & licensing of Unit 2 COMEN.P Affiliation Unknown 80/09/93 to
- 8009110430 Oppuses granting low power loading license to avoid evacuation plan requirements PULIDO.11 Affiliation Unknown 80/09/03 lp
- 8009100448 Forwards updated 10CFR2 50.51 b 100 W/o encl CHANDLER,L J Hearing Branch 1 80/09/05 1p
- 8009120108 Opposes granting low-power fuel loading license,or any license, to Unit 2 Requests any info re new developments concerning facility operation PAULSDN.K Affiliation Unknown 80/07/05 1p
- 8009120435 Opposes licensing of facility Muman needs should be placed before monetary gains POLLACM.S Affiliation Unknown 80/09/05 ip
- B00912043B Expresses concern re law power fuel loading license for plant & requests info re public hearings SIGUR-S R Affiliation Unknown 80/09/05 ip
- 8009120439 Opposes licensing of facility due to undue risks posed to public & future health & safety BEMECOUR.C Affiliation Unknown 80/69/05 lp
- 8009120442 Opposes licensing of facility for low level testing due to undue risks posed to public & environ health & safety Nuclear power is unnecessary POLLETTIR Affiliation Unknown 80/09/05 ip
- 8009230637 Protests plant licensing even ir authorization is only for operation at 5% capacity Expresses concern that conversion to safe nonnuclear fuels will consequently be more difficult MARTIN.8 Affiliation Unknown 80/09/14 ip
- 8009230633 Forwards transcript of 800814 public meeting in Bethesda, MD re-seismic issues Similar documents usually available at LPDR W/o encl DAVIS-L D Hearing Branch 4 80/09/18 jp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8009190338 Forwards Amend 20 to FSAR Amend contains responses to NUREQ-0560 & NUREQ-0594, "TM1-Related Requirements for New OLs " DIETCH.R Southern California Edison Co 80/09/12 is

- --8007190344 Application for amend to facility license applications, incorporating Amend 20 to FEAR Amend consists of responses to NUREG-0694 % NUREG-0660, "TMI-Related Requirements for New Olls "

 * Southern California Edison Co GILLMAN, D W Ban Diego Gas & Electric Co 80/07/12 3pp
- --B009190351 Amend 20 to FSAR, including responses to NUREG-0694 & MUREG-0660. "TMI-Related Requirements for New OLs "

 Southern California Edison Co " San Diego Gas & Electric Co B0/08/31 225pp
- P Operating license stage documents & correspondence
- 8009260022 Notification of second rescheduling until 801003 for meeting w/SEP owners group & KMC. Inc. to discuss NRC initial review of site-specific ground response spectra & util program for seismic functional qualification of Class IE equipment ALLISON.D P Systematic Evaluation Program Branch 80/09/10 3pp
- G Inspection reports. IE Bulletins & correspondence
- 8007020258 Forwards IE Insp Repts 50-361/80-09 & 50-362/80-06 on B00428-0301 No noncompliance noted SPENCER, 0 & Region S. San Francisco. Reactor Construction & Engineering Support Branch 80/07/10 2pp
- --8007020267 IE Insp Repts 50-361/80-07 & 50-362/80-06 on 800428-0506 No noncompliance noted Major areas inspected const activities including previous open items & equipment storage & maint ECKHARDT, J H. ELIN, J O Region 5. Ban Francisco. Office of the Director HAYNES, R C. Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/07/10 6pp
- 8009160626 Responds to IE Bulletin 79-03A, "Longitudinal Weld Defects in ASKE 8A-312. Type 304 Stainless Steel Pipe " Unly piping components subjected to design stresses greater than 85% of allowable stresses listed in encl
 BASKIN. K P Southern California Edison Co 80/08/01 7pp
- 8009260297 Forwards IE info Notice BO-29, "Broken Studs on Terry Turbine Steam inlot Flango " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/08/07 Lp
- 8009120475 Forwards IE Insp Rept 50-361/80-11 on 800615-0717 No noncompliance noted CREMS, J L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/08/12 2pp
- ~-8009120479 lE Insp Rept 50~361/80-11 on 800615-0717 No noncompliance noted Major areas inspected preoperational test program & procedures & independent insp program FAULKENGERRY, B Region 5, San Francisco, Reactor Operations Nuclear Support Branch JCHNSON.A D , PATE, R J Region 5, San Francisco, Office of the Director 80/08/11 4pp
- 8009030280 Forwards Revision 1 to IE Bulletin 80-17, "Failures of Mercury-Natted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required ENGELKEIJR H Region 5, San Francisco, Office of the Director 80/08/15 ip
- 8009290437 Forwards IE Info Notice 80~27, "Degradation of Reactor Coolant Pump Stude " ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/08/18 4pp
- 8009160184 Forwards IE Circular 80-18, "10CFR50 57 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/08/22 ip
- BOO9300017 Submits response to IE Bulletin 80-16 Rosemount Models 1151 & 1152 pressure transmitters are not planned for use in safety-related applications
 BASKIN.K P Southern California Edison Co 80/Q8/26 2pp.
- 8009120463 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DDN 6008 Circuit Breakers" No written response required ENSELKFINR H Region 9, San Francisco, Office of the Director 80/08/27 Ip

- S Reportable occurrences, LERs > related correspondence
- 8009090470 Final deficiency rept re lubricated armature bumpers on some NEMA Bize 3 starters & contactors még by Square D Co All 30 suspect starters will be inspected during Sept 1980 Starter bumpers containing lubricant will be replaced PAPAY, L T Southern California Edison Co 80/09/03 3pp
- 8009300431 Final deficiency mept me excessive bypass flow for high pressure safety injection pumps Orifice assembly design has been modified by manufacturem & will be installed by 801015 PAPAY, L T Southern California Edison Co 80/09/25 3pp
- T Hearing transcripts on non-antitrust matters
- 8007100021 Summary of 800814 meeting w/util & USGS in Bethesda.MD reoffshore exploration results Transcript encl ROOD.H Licensing Branch 3 80/08/21 4pp
- --8009100024 Transcript of 800814 public meeting w/util & USGS in Bethesda.HD re offshore exploration results Pp 1-76 + Licensing Branch 3 80/08/14 65pp
- COCKET 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3
- A Application/construction stage documents t correspondence
- 8007120305 Notification of contract execution, Mod S to "Bimulation of Earthquake Ground Motions for San Onofre " Contractor K Aki KORULTY, A Administrative Contracts Branch FIN 8-6331 80/04/01
- --8009120514 Mod 5, extending period of performance & adding addi funds to *Simulation of Ground Motions for San Onofre " AKI.K Massachusetts Institute of Technology FIN B-6531 80/04/Oi ip
- BOOY0800BO Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISEKHUT, D O Division of Licensing 80/08/01 i19pp
- BC07020006 Forwards addendum to June 1980 response to Question 361 63, re origin of foids & faults.offshoro & south of facility, per NRC request during 800814 geosciences meoting Addendum will be included in Amend 21 to FGAR, to be submitted in Oct 1980 EASKIN, K P Southern California Edison Co 80/08/22 2pp
- --B009020007 Addendum to June 1980 response to Question 361 63 re origin of folds & fauits.offshore & south of facility Four composite geologic cross-sections encl
 # Bouthern California Edison Co B0/08/22 23pp
- --8007020010 "Offshore Geologic Structure," Plate 2, Sheet i2 * Southern California Edison Co 80/08/31 Ip
- 8009100417 Summary of G00724 meeting w/applicants to discuss analysis of Imperial Valley earthquake of Oct 1979
 R00D/H Licensing Branch 3 80/08/27 16pp
- 8009150420 Notification of contract execution "Followen to Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station." awarded to E Luco
 LITLE.M. Administrative Contracts Branch FIN D-6898-0 80/08/27
- --8009150424 Contract "Followon to Bimulation of Earthquake Oround Kotions for San Onofre Nuclear Generating Station," awarded to E Luco LUCO.J E Luco, J E FIN 8-6898-0 80/08/27 5pp
- 8009(60227 Notification of 800909-10 meeting w/util to conduct caseload forecast panel site visit
 RDGD:H Licensing Branch 3 80/08/27 4pp
- GCO9160252 Summary of GO0312-15 meeting w/Southern CA Edison Co.C-E, Bightel & Ban Diego Cas & Electric Co in Bethesde, MD to discuss non-TMI related open items RDDD-H Licensing Branch S 80/08/27 lipp
- 8009240622 Natification of 800909-11 meeting w/util in Ban Clemente, GA to conduct electrical site visit ROQD, H Licensing Branch 3 80/08/27 3pp

- 8009240052 Notification of contract execution "Followon to Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station "Contractor R Hermann LITTLE.M Administrative Contracts Branch FIN B-6898-0 80/08/28
- ~~8009240057 Contract "Followon to Simulation of Earthquake Ground Hotions for San Onofre Nuclear Generating Station," awarded to R Hermann HERMANN.R St Louis Univ FIN 8-6898-0 80/08/28 5pp
- 8007050302 Forwards responses to NRC 800923 & 0616 ltrs.proprjetary & nonproprietary versions of CEN-135(s), "CPC/CEAC Software Mods for San Dnofre Unit 2." in response to NRC question 221 18 Withholding affidavit enc! BASKIN.K P Sauthern California Edison Co 80/09/03 77pp
- ~-8009050308 "CPC/CEAC Software Mods for San Onofre Unit 2 " Proprietary version withheld (ref 10CFR2 770) * Combustion Engineering, Inc. CEN~135(5)-NP 80/08/31 79pp
- 8009110547 Notification of 800910 meeting w/utii & C-E in Bethesda.MD to discuss NRC questions re CEMPD-178
 ROOD,H Licensing Branch 3 80/09/04 3pp
- 8009120273 Notification of 800909 meeting w/util & C-E in Windsor.CT to discuss audit of CEND-178 analysis methods RODD-H & Licensing Branch 3 80/09/04 3pp
- 8009180330 Forwards questions re Executive Order (1988 Flood Piain Mgt Response requested by 800912 TEDESCO.R L Assistant Director for Licensing 80/09/04 4pp
- 8009290143 Notification of 800926 meeting w/utils & Kerr-KcGee Chemical Corp in Bothesda.MD to discuss review & recommendations for site specific ground response spectra & program plans for seismic functional qualification of Class IE equipment ALLISON.D P Systematic Evaluation Program Branch 80/09/08 3pp
- 8009190913 Notification of 800923 meeting w/utii.USOS & CBMG in Menlo Park,CA to discuss seismology & geology re facilities ROOD,H Licensing Branch 3 80/09/09 3pp
- BOO918042i forwards response to hydraulic engineering questions re flood piain mgt. per NRC 800904 request Site does not fail within floodpiain as defined by Executive Order 11988 BASKIN.K P Southern California Edison Co 80/09/10 4pp
- --8007180427 "Preconst Fioudpiains, Units 2 & 3 "
 * Southern Caiffornia Edison Co 80/07/10 tp
- --8009180433 "Post-Const Fioodplains. Units 2 & 3 " * Southern California Edison Co 80/09/io 1
- GOO9250190 Approves of util 800115 plans to terminate preoperational monitoring program
 SCHMENCER:A Licensing Branch 3 BO/09/11 3pp
- 8009250451 Forwards proposed memorandum of agreement for San Unoffe transmission lines & two ltrs from State of CA.Dept of Parks & Recreation.per 800909 telcon Formal requost for concurrence will follow shortly SCALEITI.D C Licensing Branch 3 80/09/13 9pp
- --8009250456 Informs of assuming H Dass responsibilities Requests informal meeting w/RRC to discuss directions of mutual interests in preserving cultural resources
 BELL.D A California, State of 80/04/18 tp
- F Security, medical, emergency % fire protection plans
- 8009030358 Notifies of 800819.22 & 30 regional workshops re development of guidance for acceptable method for coping w/emergencies at facility Requests that representative be sent Subj areas to be discussed include function of facilities & location ENGELKEN.R H Region 5. San Francisco. Office of the Director 80/08/12 2pp
- B00B27027B Forwards Jul 1980 revised emergency plan, in response to NRC 791031 request for addl info Licensee is assisting local govt in devising emergency response procedures
 UASKIN,K P Bouthern California Edison Co 80/08/18 2pp

- 80090303B7 Forwards revised safeguards contingency plan per NRC 791211 & 800324 requests Plan withheld (ref 10CFR2 790) BASKIN.K P Southern California Edison Co 80/08/28 2pp
- 8007050286 Forwards Revision 1 to security force training \$
 qualification plan Plan withheld (rev 100FR2 770)
 BASKIN,K P Southern California Edison Co 80/07/03 ip
- 8009240347 Forwards emergency planning into for placement in local PDR SOUDER, J L Division of Rules and Records 80/09/04 ip
- G Adjudicatory correspondence
- 8009020059 Order astablishing discovery schedule Discovery re geology, seismology 5 emergency planning shall end 3D days following NRC safety evaluation & svc of emergency plan Depositions shall be completed 40 days after such svcs BMITH, I W Atomic Safety and Licensing Board Panel 80/08/27 5pp
- 80091A0339 Forwards NUREG-75/111.NUREG-0654 & NUREG-0696 in response to 860811 telcon re emergency planning info W/o encls DAVIS/L D Hearing Branch 4 80/05/27 ip
- 8009110376 Forwards stipulation to extend time within which Southern CA Edison Co will answer intervenor Friends of The Earth 800811 interrogatories PIGDTT, D.R. Chickering & Gregory 80/09/03 1p
- --8007i10377 Stipulation between parties, allowing Southern CA Edison Co extension until 800715 to respond to intervenor Friends of The Earth 8008i1 interrogatories Approved by ASLB on 800708 PIGGTT, D. R. Southern California Edison Co. P100TT.D R. San Diego Gas & Electric Co. P160TT.D R. Chickering & Oregory 80/08/27 20n
- 8009100406 Interrogatories directed to NRC re Cristianitos fault, Newport-Inglewood-Rose Canyon-San Miguel fault ione & other seismic-related issues Certificate of Svc encl MHARTON; R J . POGALIES. J K Friends of the Earth WHARTON; R J Wharton & Pogalies 80/09/04 17pp
- 8009170299 Responds to FOIA request for 15 documents listed in bibliography fo NUREG-0625, "Rept of Siting Policy Task Force " Documents 6-8 % 13 are available in PDR Forwards remaining documents FELTON-J M Division of Rules and Records 80/09/04 lp
- --BOD7170587 Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants, for determination of site acceptability & adequacy of engineered safety features
 MINOQUE, R B Office of Standards Development, Director 5ECY-79-362 79706/04 7pp
- --B009190630 Requests that encl. "Differences in Procedures for Estimating Atmospheric Dispersion Conditions at Inland & Coastal Sites." be sent to appropriate Boards BCIMTD. J F Hearings Division 79/04/04 lépp
- 8007090774 Forwards 800819 FR notice re final rules upgrading emergency planning regulations, effective 801103 CHANDLER, L. J. Hearing Branch 1 80/09/05 19pp
- 8009160341 Advises that NUREG-75/llf.NUREG-0654 & NUREO-0696 were mailed on 800827 per 800828 inquiry about emergency planning info Discovery requests should be made through counsel Wharton DAVIS.L D Hearing Branch 4 80/09/ll 1p
- 8009190083 Response to Intervenor Friends of The Earth 800811 fourth sot of interrogatories Objects to portions requesting production of documents Certificate of Svc encl PIODTILD R. CASEY.S B. KOCHER.C R. Southern California Edison Co 80/09/15 46pp
- H General correspondence
- 8009050357 Urgs NRC nat to issue low power fuel loading license for Unit 2 LITFIN.K Affiliation Unknown 80/08/28 Ip
- BOO9:1037B Opposes low level testing / licensing of facility, since no evacuation plan possible MARTINEZ.P R Affiliation Uninown GD/08/29 ip
- 8009120444 Opposes licensing of facility for low level testing due to undue risks posed to health & safety of public & environ BROWN.P Affiliation Unknown 80/08/27 ip

- 8009050390 Expresses opposition to nuclear energy & licensing of Unit 2 COMEN, P Affiliation Unknown 80/09/03 1p
- B009110430 Opposes granting low power loading license to avoid avacuation plan requirements
 PULIDA 4 Affiliation Unknown 80/09/03 1p
- 8009100448 Forwards updated 10CFR2.50.51 & 100 W/o encl CHANDLER.L J Hearing Branch 1 80/09/05 1p
- 8009120188 Opposes granting low-power fuel loading license, or any license, to Unit 2 Requests any info re new developments concerning facility operation PAULSON-X Affiliation Unknown 80/09/05 1p
- 8009230637 Protests plant licensing even if authorization is only for operation at 5% capacity Expresses concern that conversion to safe nonnuclear fuels will consequently be more difficult
 MARTIN. # Affiliation Unknown 80/09/14 ip
- 8009230633 Forwards transcript of 800814 public meeting in Bethesda. MD re seismic issues Similar documents usually available at LFDR W/o encl DAVIS.L D Hearing Branch 4 80/09/18 ip
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8009190338 Forwards Amend 20 to FSAR Amend contains responses to NUREG-0660 & NUREG-0694, "TMI-Related Requirements for New OLs " DIEICH, R Southern California Edison Co 80/09/12 19
- ---B009190344 Application for amend to facility license applications, incorporating Amend 20 to FSAR Amend consists of responses to NUREG-0694 & NUREG-0660, "TMI-Related Requirements for New OLs"

 * Southern California Edison Co GILLMAN,D W San Diego Gas & Electric Co 80/09/12 3pp
- --8009190391 Amend 20 to FSAR, including responses to NUREG-0494 & NUREG-0460, "TMI-Related Requirements for New ULs " * Southern California Edison Co * San Diego Gas & Electric Co 80/08/31 225pp
- Q Inspection reports, IE Bulletins & correspondence
- B00902025B Forwards IE Insp Repts 30-361/B0-09 & 50-362/B0-06 on B0042B-0301 No noncompliance noted SPENCER,O & Region 5. San Francisco, Reactor Construction & Engineering Support Branch B0/07/10 2pp
- ---B009020267 lE insp Repts 50-361/80-09 & 50-362/80-06 on 800428-0501
 No noncompliance noted Major areas inspected const
 activities including previous open items & equipment storage
 & maint
 ECKHARDTJ H , ELIN, J O Region 5, San Francisco. Office of the
 Director HAYNES, R C Region 5, Ban Francisco, Reactor
 Construction & Engineering Support Branch 80/07/10 App
- 8009160626 Responds to 1E Bulletin 79-03A, "Longitudinal Weld Defects in ASME 8A-312, Type 304 Stainless Steel Pipe " Only piping components subjected to design stresses greater than 85% of allowable stresses listed in enc!

 BASKIN,K P Southern California Edison Co 80/08/01 7pp
- 8009260297 Forwards 1E Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange" No written response required EMOELKEUR H Region S. Ban Francisco, Office of the Director 80/88/07 Ip
- BO09030280 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Watted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required, ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/08/15 lp
- 8009290457 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " ENGELKEH,R H Region 5, San Francisco, Office of the Director 80/08/18 4pp
- 8009160184 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required EMGELKEHAR R Region 5. Sen Francisco. Office of the Director 80/02/22 lp

- BOOP300017 Submits response to 1E Bulletin 80-16 Resemblint Hodels 1151 2 1152 pressure transmitters are not planned for use in safety-related applications BASKINN P Southern California Edizon Co 80/08/26 2pp
- EOO9320463 Forwards IE Info Notice 80-31. "Maloperation of Could-Brown Boseri 450 Volt Type K-6005 & K-DDN 6005 Circuit Breakers " No written response required ENGELKEN,R H Region 5. San Francisco, Office of the Director 80/08/27 ip
- S Reportable occurrences, LERs & related correspondence
- B009390470 Final deficiency rept re lubricated armature bumpers on some NEMA Bize 3 starters & contactors mfg by Square D Co Ail 30 suspect starters will be inspected during Sapt 1980 Starter bumpers containing lubricant will be replaced PAPAY.L T Southern Caisfornia Edison Co B0/09/03 3pp
- E009300431 Final deficiency rept re excessive bypass flow for high pressure safety injection pumps Orifice assembly design has been modified by manufacturer & will be installed by 801015 PAPAY.L. T. Southern California Edison Co. 80/09/25 3pp
- T Hearing transcripts on non-antitrust matters
- BOSP100021 Summary of 800914 meeting w/util & USGS in Bethesda, MD re offshore exploration results Transcript encl RCGD, H Licensing Branch 3 80/08/21 4pp
- --8009100024 Transcript of B00B14 public meeting w/util * USGS in Bethesda: MD re offshore exploration results Pp 1-76
 Licensing Branch 3 80/08/14 85pp
- DOCKET 50-363 FORKED RIVER NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of MUREG-0696 enci W/o NUREG EISENHUT, D G Division of Licensing 80/08/01 i19pp
- G Inspection reports, IE Bulletins & correspondence
- 8009030042 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required CRIER, B H Region i, Philadeiphia, Office of the Director 80/08/15 1p
- 80C91BC004 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwasto Treatment Sys " No written response for Changes to nauwasso in comment. Cy-required GRIER.B H Region i. Philadelphia. Office of the Director
- 8009120177 Forwards IE Info Notice 80-31. "Maloperation of Couid-Brown Eoveri 480 Volt Type K-6008 t K-DON 6008 Circuit Breakers " No written response required CRIER.B H Region i, Philadelphia, Office of the Director 30/08/27 ip
- 8009240032 Forwards IE Circular 80-21. "Regulation of Refueling Crews " Ro written response required
 GRIER, B H Region i, Philadelphia, Office of the Director
 80/09/10 ip
- 8009240311 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required ORIER, B H Region I, Philadelphia, Office of the Director 80/09/12 1p
- DOCKET 50-364 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 2 A Application/construction stage documents & correspondence
- E007080274 Forwards "Setpoint Study for Farley 1 ½ 2." proprietary (WCAP-B313) & monproprietary (WCAP-9758) versions Application & affidavit for withholding encl ANDERSOW. TM Westinghouse Electric Corp 80/07/25 13pp

- --8007080297 "Setpoint Study for Farley 1 & 2," nonproprietary version KO.M Westinghouse Electric Corp ORTENBERG,L I , ROSSI,C E Westinghouse Electric Corp , Nuclear Energy Systems WCAP-9768 74/05/31 216pp
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities 'Comments requested within 30 days Proposed implementation schedule for meeting criteria or NUREG-0696 enci M/o NUREG EISEIMUT.D G Division of Licensing 80/08/01 119pp
- 8007020030 Forwards util position on licensing issues re shift manning, low power test procedures high range radiation detection, fire protection / security plan CLAYTON, F.L. Alabama Power Co. 80/08/19 4pp
- 8009020045 Forwards info re TM1-2 action plan per 800716 request CLAYTON:F L Alabama Power Co 80/08/20 3pp
- 8007020938 Provides addi info re shirt supervisor functions in response to NRC 800819 request One of two shirt supervisors will be designated as supervisor in charge & will hold Unit 1 & Unit 2 license CLAYTON, F.L. Alebama Power Co. 80/08/22 lb
- 8009090128 Forwards request for addi info to RCS vents.RHR sys % bypass, override & reset circuits of engineered safety features
 TEDESCO.R L. Assistant Director for Licensing 80/08/25 18pp
- 8009170174 Informs that facility will be ready for fuel loading & low power testing license by 800919 Submits info to assist in obtaining proper fee for license SCHMENCER: A Licensing Branch 2 80/08/27 2pp
- 8007030492 Submits add1 info requested by NRC 800124 itr re qualification of Barton Lot 2 transmitters Review of differential pressure transmitters proved acceptable for respective functions CLAYTON, F L Alabama Power Co 80/08/28
- 8009080387 Forwards summary & results of 800819 working session w/NRC re hot shutdown panel.per 800814 telcon w/NRC CLAYTON:F L Alabama Power Co 80/08/28 2pp
- 8009110541 Notification of 800905 meeting w/wtil & Westinghouse in Bethosda.MD to discuss Westinghouse proposed response to staff questions re WCAP-9292 XINTMER.L L. Licensing Granch 2 80/08/29 3pp
- B009190409 Informs of 800903 meeting w/Commission re DL for facility Draft SER Suppl 4.iicense & Tech Specs.addendum to FES & licensee B00829 itr demonstrating compliance w/Commission regulations enci W/o encis DENION.H R Office of Nuclear Reactor Regulation. Director 80/08/29 ip
- 8009230767 Notification of 800902-03 meeting w/util in Zion.IL to run selected transients & accidents on simulator & to evaluate emergency operating procedures KINTHER.L. L ticensing Branch 2 80/08/29 2pp
- 8009040246 Submits response to NRC request resulting from 800821-28 meeting re App A Tech Specs 3 3 3 8. 'Accident Monitoring instrumentation" \$ 3 7 9. "Snubbers " Info should be considered in development of final App A Tech Specs CLAYTON.F L Alabama Power Co 80/09/02 5pp
- --8009040251 Proposed Tech Specs 3 3 3 8 % 4 3 3 8 re accident monitoring instrumentation ilmiting condition for operation & surveillance requirements, respectively # Alabama Power Co 80/09/02 3pp
- 8009040386 Forwards "Special Low Power Tests Safety Evaluation." & draft startup test procedures. "Cooldown Capability of Charging & Letdown Sys,' "Natural Circulation." & "Porced Circulation Cooldown" CLAYTON.F L Alabama Power Co 80/09/02 7pp
- --8009040387 "Special Low Power Tests Safety Evaluation "
 * Alabama Power Co 80/08/31 47pp
- --8009040389 Draft Phase III Test Procedure 501-7-001. "Cooldown Capability of Charging & Latdown Sys " * Alabama Power Co 80/07/26 idpp
- --8009040390 Draft Phase III Test Procedure 501-7-002. "Natural Circulation " * Alabama Power Co 80/07/24 48pp

DOCKETED ITEMS

- ---8009040071 Draft Phase III Yest Procedure 501-7-003, "Forced Circulation Cooldown "

 * Alabama Power Co 80/08/10 41pp
- --8007040353 Draft Phase III Test Procedure 501-7-003, "Natural Circulation W/Simulated Loss of Power Conditions" * Alabama Power Co 80/07/28 41pp
- --8009040395 Draft Phase III Test Procedure 501-7-004. "Effect of S/Q Secondary Side Isolation on Natural Circulation " Alabama Power Co 80/07/29 42pp
- 8007080293 Forwards info or Category 1 masonry walls.per NRC 800421 request Oversize drawings available in Central Files only CLAYTON, F.L. Alabama Power Co. 80/07/02 App
- 8009090566 Requests that radiological ETS for Unit 2.NRC approved during wk of 800825,be implemented for Unit 1 on 810101 to assure consistent implementation for both units CLAYTON,F L. Alabama Power Co. 80/09/02 1p
- 8009120425 Requests that Tech Specs re exposure of fuel assemblies & control rods remain unchanged until after receipt of Unit 2 full power Di.

 CLAYTON,F L Alabama Power Co 80/09/03 ip
- 8007150484 Forwards proposed mod to auxiliary feedwater flow control solenged valves per NRC license requirement for fuel loading 1 lower power testing CLAYYON.F L. Alabama Power Co. 80/09/08 4pp
- 8007160415 Forwards response to NRC request for add1 info re Reactor Sys Branch Question 210 1.1tem 3 re cavitation & air CLAYTON F L Alabama Power Co 80/09/08 3pp
- 8009240551 Forwards request for add] info & Power Sys & Mechanical Engineering Branch positions re overload protection design & RCPD safety sys respectively TEDESCO.R.L. Assistant Director for Licensing 80/09/10 9pp
- 8009170353 Forwards Phase III Test Procedure 501-7-003, "Natural Circulation W/Bimulated Loss of Offsite AC Power." & Phase III Test Procedure 501-7-006, "Coming W/Simulated Loss of Power Conditions" CLAYION, F. L. Alabama Power Co. 80/09/11 4pp
- --8009170356 Phase Iff Test Procedure 501-7-006, "Cooling W/Simulated Loss of Power Conditions" 4 Alabama Power Co 80/09/08 25pp
- 8009300051 Notification of 800918 meeting w/otil in Bethesda.MD to discuss review of incense application KINTNER.L Licensing Branch 2 80/09/11 3pp
- 8009300288 Notification of 800918 meeting w/util in Bethesda.MD to review containment purge requirements.RCS yents & leakage tests for RCS valves KININER.L. Licensing Branch 2 80/09/11 2pp
- 8009190259 Forwards Amend 74 to FSAR for Unit 1 & to application for OL for Unit 2 Certificate of Svc encl CLAYTON F L Alabama Power Co 80/09/12 2pp
- -- 8009150260 Amend 74 to application for OL for Unit 2 % to FSAR for Unit CLAYTON, F.L. Alabama Power Co. 80/09/12 10
- --8009150263 Amend 74 to FSAR * Alabama Power Co 80/0 80/09/12 9pp
- 8007170214 Forwards "Environ Qualification of Class IE Equipment," response to NURES-0588 Response withheld (ref 100FR2 790) CLAYTON,F L Alabama Power Co 80/09/12 9pp
- 8009230465 Forwards add1 info re potential design deficiencies in bypass.override L reset circuits of engineered safety features, in response to NRC 800825 ltr CLAYTOWF L Alabama Power Co 80/09/12 App
- 800923044B Forwards add1 into re turbine trip w/o reactor trip below 50% power in response to Item C 3 10 of II K 3 in NUREG-0694 CLAYTON:F L Alabama Power Co 80/09/16 14pp

- 8009290329 Notifies of incorporation of addi documents into license application NPF-8. Item 2 C 6. per App 0 10CFR50 Westinghouse Topical Rept. NCAP-9292 & responses to NRC 790725 request for info filed W/NRC CLAYTON, F L Alabama Power Co BO/07/22 2pp
- 8009300391 Forwards summary of results achieved at 800918 meeting re isolation of hot shutdown panel & main control board instrumentation mods.resulting from NRC 800915 request for addi info CLAYTON F L Alabama Power Co 80/09/22 2pp
- 8009290391 Forwards response to NRC Power Sys Branch Guestions 040 1-040 14 rs diesel generators CLAYTON:F t. Alabama Power Co 80/09/24 24pp
- F Security, medical, emergency & fire protection plans
- 8009100324 Summarizes 800812 meeting & 800815 telcon re completion of fire protection sys & equipment installation Mods are scheduled for completion in late Oct 1780 CLAYTON-F L. Alabama Power Co. 80708/18 2pp
- 8009020030 Forwards util position on licensing issues re shift manning. low power test procedures high range radiation detection, fire protection & security plan CLAYTON, F L Alabama Power Co 80/08/19 6pp
- 8007230249 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency O'REILLY, J P Region 2, Atlanta. Office of the Director 80/08/22
- asmobnoqearus yrotesibutby 0
- B009090415 Authorizes Director of Ofc of Nuclear Reactor Regulation to issue License NPF-8 for fuel loading & low power testing HOYLE.J C Office of the Secretary of the Commission 80/09/05
- 8009220226 Comments on rulemaking 90-5 GESMO proceedings should be reopened Technical economic & safety issues must be addressed in order for decisions to be made re use of misedoxide fuels WEITZBERG. A Affiliation Unknown 80/09/15 lp
- 8009300407 Informs of M Farrer resignation from full-time ASLAP position Name should be deleted from avoidist for all but Farrey antitrust proceeding 8vc list for all other dockets need contain only two ASLAB members ROSENTHALA & Atomic Safety and Licensing Appeal Panel 80/09/25
- H General correspondence
- BOO9300435 Requests that distribution list be revised to reflect recent mgt-level reorganization WO Whitt has assumed responsibilities formerly assigned to AR Barton CLAYYON.F L. Alabama Power Co. 80/09/23 p
- M Antitrust correspondence
- 8007070339 Motion for issuance of decision at earliest convenience Proceeding pending since 770308 Certificate of Sv¢ encl Granted by AELAB on 800708 BLUME: M B Antitrust Division 80/07/05 3pp
- 8009260662 Response in support of NRC 800705 motion for issuance of decision issues; if resolved, will affect future power supply b devalopment of supply planning Injury may occur if delayed Certificate of Svc encl HJELMFELT, D C Municipal Electric Utility Association, Alabama HJELMFELT, D C Hjelmfelt, D C 80/09/23 3pp
- G Inspection reports: IE Bulletins & correspondence
- B009020466 Forwards IE insp Repts 50-349/80-15 & 50-364/80-19 on B00623-26 No noncompliance noted BTOHR, J P Region 2. Atlanta. Fuel Facility & Materials Safety Branch B0/07/14 2pp
- --8009020477 IE Insp Repts 50-348/80-15 & 50-364/80-16 on 800423-26 No honcompliance noted Major areas inspected radwaste mgt OIBSOUA A F Region 2. Atlanta, Fuel Facility & Materials Safety Branch WRAY, J R Region 2. Atlanta, Office of the Director 80/07/11 6pp

- 8009100040 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Written response required D'RECLLY, J P Region 2. Atlanta, Office of the Director BO/07/24
- 8007090415 Forwards IE Insp Rept 50-364/80-20 on 800630-0702 No noncompliance noted MAPHY,C E Region 2, Atlanta Reactor Construction & Engineering Support Branch 80/07/25 2pp
- --8009050421 IE Insp Rept 50-364/80-20 on 800630-0702 No noncompliance noted Major areas inspected preservice insp activities CROWLEY.B R Region 2. Atlanta, Office of the Director HERDT, A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/25 Spp
- BO09110102 Forwards IE Insp Repts 50-348/80-19 & 50-364/80-23 on 800602 -30 Mo noncompliance noted LEMIGR C Region 2 Atlanta, Reactor Operations Nuclear Support Branch B0/07/29 2pp
- --8009110202 IE insp Repts 50-348/80-19 \$ 50-344/80-23 on 800602-30 No noncompliance noted Major areas inspected sys integrity outside containment, monitoring instrumentation, radiation controls, fluid leaks, piping vibration & fire hazards BRADFORD, W H , MARTIA, R D Region 2. Atlanta, Office of the Director 80/07/28 7pp
- 8009050032 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " No 300 series fusion welded pipe used in safety-related sys subj to stresses greater than 85% of max allowable stresses CLAYTON.F.L. Alabama Power Co. 80/08/01 2pp
- 8009120045 Forwards 1E Insp Repts 50-348/80-14 % 50-364/80-16 on 800409-13 % 16-20 / notice of violation LEMIS.R C Region 2, Atlanta. Reactor Operations Nuclear Support Branch 80/08/08 2pp
- --8009120052 Notice of violation from Insp on 800609-13 & 16-20
 # Region 2, Atlanta, Office of the Director 80/08/06 2p
- --8009120071 IE Insp Repts 50-348/80-14 & 50-364/80-16 on 800609-13 & 16-20 Noncompliance noted failure to provide definitive corrective action for identified mati storage inadequacies & failure to control consumables in safety-related sys BELISLE: 0 A . FURD. J Region 2. Atlanta. Office of the Director UPRIONI,C M Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/08/06 35pp
- BOO9020301 Forwards revisions to BOO107 response re IE Bulletin 79-02, "Plps Support Base Plate Dusigns Using Concrete Expansion Anchor Bollts," Revision 2. Item 7 & BOO115 response to IE Bulletin 79-14 re as-bullt safety-related plping sys CLAYJON, F L Alabama Power Co BO/OB/19 7pp
- 8009030123 Forwards Revision [to IE Bulletin 80-19, "Failures of Marcury-Hatted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/15 tp
- 8009100237 Ack receipt of IE Insp Rept 50-364/80-24 on 800708-11 No proprietary info CLAYTON.F L Alabama Power Co 80/08/22 lp
- --8007100330 Forwards IE Insp Rept 50-364/80-24 on 800708-11 No noncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/01 2pp
- --8009100307 IE insp Rept 50-364/80-24 on 800708-11 No noncompliance noted Major areas inspected, instrumentation components & sys work & work activities & Instrumentation cables & terminations work & work activities CONLON.TE Region 2. Atlanta, Reactor Construction & Engineering Support Branch OIBBOINS,T D. MERRIMEATHER,N Region 2. Atlanta, Office of the Director 80/08/01 4pp
- 8009160110 Forwards IE Circular 80-18, "10CFR30 39 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/08/22

- 8009120251 Forwards IE Info Notice 80-31, 'thatoperation of Gould-Brown Boseri 480 Volt Type K-6008 ? K-BON 6008 Circuit Breakers "No written response required O'REILLY, J P. Region 2. Atlanta, Orfice of the Director 80/08/27 lp
- 8009110687 Responds to IE Bulletin 80-19 Mercury-wetted relays not utilized in reactor protection sys in either facility CLAYTON.F L. Alabama Power Co. 80/08/29 lp
- 8009190576 Ack receipt of 800812 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/80-16 t 50-364/80-19 MURPHY.C E Region 2. Atlanta. Reactor Construction t Engineering Support Branch 80/09/03 2pp
- --8009190583 Responds to NRC 800723 ltr re violations noted in 1E Insp Repts 50-348/80-16 \$ 50-344/80-19 Corrective actions testing & analysis initiated to determine probable error introduced through improper use of torque multipliers CLAYIC4,F L Alabama Power Co 83/08/12 5pp
- --8007190588 Forwards IE Insp Repts 50-348/80-16 & 50-364/80-19 pn 830617-20 & notice of violation MURPHY, C.C. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/23 2pp
- --8009190593 Notice of violation from insp on 800617-20 * Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/07/21 2pp
- --8009190609 IE Insp Repts 50-348/80-16 5 50-364/80-19 on 800617-20 Noncompliance noted torque wrench multiplier used for IE Bulletin 79-02 testing not controlled or calibr & inadequate instruction for mod & insp of support ANO, W P Region 2. Atlanta, Office of the Director HERDT, A Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/21 4pp
- 8009290976 Forwards IE Circular 80-21. "Regulation of Refueling Crews" No written response required O'REILLY, J.P. Region 2, Atlanta, Orrice of the Director 80/09/10
- S Reportable occurrences, LERs & related correspondence
- 8009100363 Deficiency evaluation rept re Westinghouse centrifugal charging pump operation following secondary side high energy line rupture Design change implemented to remove safety injection initiation closure signal from isolation valves CLAYION:F L Alabama Power Co 80/08/20 4pp
- T Hearing transcripts on non-antitrust matters
- 8009180222 Transcript of 800904 meeting in Washington, DC to low power OL Pp 1-9 * Commission 80/09/04 12pp
- V Operator Exeminations
- 8009100318 Forwards revised operating shift manning & training schedule per 800804 exam results & 800904 verbal request C&AYTON.F L Alabama Power Co 80/09/08 opp
- 8009300498 Advises that training program for mitigating core damage is scheduled to commence on 800929 & to be completed by mld Nov 1980 Training program will tocome part of requalification program CLAYTD.4:F L. Alabama Power Co. 80/09/24 1p
- 8009300463 Revises commitments submitted 800924 re training for miltigating core damage Selected personnel will receive pertinent training in areas where assistance would be expected in event of sovere core damage CLAYTON,F L. Alabama Power Co. 80/09/25 1p
- DOCKET 50-366 EDMIN I HATCH NUCLEAR PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8009230265 Requests that all personnel be reminded of purpose of emergancy notification sys & health physics network Sys installed for govt use during emergency D'REILLY, J P Region 2. Atlanta. Office of the Director 80/08/22 to

- 8009030484 Notafies that final version of upgraded emergency plan will be submitted by 810102 WIDNER, W.A. Georgia Power Co. 80/08/28 1p
- BOO9140448 Informs of util concept of physical means for alerting & providing clear instructions to populate within plume exposure emergency planning ione Design concept is to provide tone alert receivers for all astablishments in ione WIDNER, N.A. Georgia Power Co. 80/09/12 3pp

@ Adjudicatory correspondence

- 8009240597 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 REID.R W Operating Reactors Branch 4 80/08/29 2pp
- --8009240603 Order for mod of Licenses DPR-57 & NPF-5 to add info which fully responds to NRC request for into re environ qualification of safety-related electrical equipment info should be submitted by 801101 EISENHUT, D & Division of Licensing 80/08/29 App
- P Operating license stage documents & correspondence
- 8009110554 Suppls NRC 800707 request for proposed Tech Specs Changes re scram discharge vol vent & drain valves. & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISEMHUT.D G Division of Licensing 80/07/22 22pp
- BOO9020297 Submits (interim criteria for shift staffing to all OL & CP livensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISEKHUT.D C Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT, D G Division of Licensing 80/08/01 119pp
- 8007230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D.O. Division of Licensing 80/08/07 60pp
- 8009230763 Forwards "Mark 1 Containment Long-Term Program SER, Resolution of Generic Technical Activity A-7," NUREG-0661 W/o encl REID, R N Operating Reactors Branch 4 80/08/20 2pp
- 8007180163 Lists issues to be addressed re restart of unit Items identified should be resolved prior to Cycle 2 operation & do not include anticipated submittals of Fech Spec changes Requests response advising of submittal date for each item VERRELLI,D M Operating Reactors Branch 4 80/08/26 3pp
- 8009190423 Application for amend to Licenses DPR-57 & NPF-5 consisting of changes to Tech Specs WIDNER, N. A. Georgia Power Co. 80/09/15 App
- --8009190432 Proposed changes to Tech Specs Tables 3 3 6 4-1.4 3 6 4-1 & 6 2 2-1 & Tech Specs 6 3 for whit staff qualifications.6 4 for training & 6 5 for review & audit + Georgia Power Co 80/09/15 5pp
- Q Inspection reports, IE Bulletins & correspondence
- 8009090057 Forwards IE Bulletin 80-07. Suppl 1, "BHR Jet Pump Assembly Failure" No response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/13 to
- 8007150332 Forwards 1E Insp Repts 50-321/80-26 & 50-364/80-26 on 800625-26 No noncompliance nated MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/23 2pp
- --8009150370 IE Insp Repts 50-321/80-26 & 50-366/80-26 on 800625-26
 No noncompliance noted Major areas inspected settling of structural backfil around RHR & plant svc water intake structure & piping HARRIS.JR Region 2. Atlanta. Office of the Director CONLOUILT E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/07/22 3pp

- 8009220265 Forwards IE Insp Repts 50-321/80-24 & 90-366/80-24 on 800513-0609 / notice of violation LEWIS.R C Region 2. Atlanta Reactor Operations Nuclear Support Branch 80/07/25 2pp
- ~~8009220337 Notice of violation from insp on 800513~0609 LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 60/07/25 1p
- --8009220341 IE Insp Repts 50-321/80-24 & 50-366/80-24 on 600513-0607 Noncompliance noted motor bearing cooling water inlet valves were found improperly shut on RMR svc water pumps DANCE.H C Region 2. Atlanta, Reactor Operations Nuclear Support Branch ROCERS, F Region 2. Atlanta, Office of the Director 80/07/25 9pp
- 8009050076 Forwards partial response to 1E Bulletin 80-0B, "Exam of Containment Liner Penetration Nelds " Seven welds failed hondestructive examination Unit 1 containment & Unit 2 torus penetration info forthcoming WIDNER, N & Georgia Power Co 80/08/05 Bpp
- 8009020287 Submits response to IE Bulletin 80-17, Suppl 1 Procedures have been established to assure operability of scram discharge vol WIDNER, W.A. Occupia Power Co. 80/08/07 2pp
- 8009030154 Forwards Revision 1 to 1E Bulletin 80-19. "Failures of Marcury-Wetted Matrix Relays in Reactor Protective Sys of Operating Muclear Power Plants Designed by C-E " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/15
- B009020180 Responds to Suppl 1 of IE Bulletin B0-17 re failure of control rods to insert during scram at DNR Existing design of facility meets requirement for continuous monitoring of water level in scram discharge vols WIDNER, WAA Georgia Power Co 80/08/19 2pp
- 8009020393 Submits status of recent util efforts towards compliance w/ 1E Bulletin 79-010. "Environ Qualification of Class IE Equipment " Util has joined BMR owners group effort on bulletin WIDNER, H A Georgia Power Co 80/09/19 2pp
- 8009160039 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain OE BWR Facilities " No specific action or response requested O'REILLY.J P Region 2, Atlanta, Office of the Director 80/08/19
- 8009230105 Submits response to IE Bulletin 79-018 Expects to complete qualification test program & component replacement by 820630 MIDNER, N A Georgia Power Co 80/08/19 2pp
- 8009110671 Responds to IE Bulletin 79-01B Forwards 90-day repts re environ qualification of Class IE equipment, summary of outstanding items & summary of equipment w/iess than 40-yr aging qualification W/o encls WIDNER, W A Georgia Power Co 80/08/22 2pp
- 8009120077 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22
- 8009160147 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GREILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22
- 8007110824 Ack receipt of 800731 ltr informing NRC of steps taten to correct deviations noted in 16 lnsp Repts 50-321/80-02 & 50-366/80-02 MRRPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/08/25 lp
- --8009110828 Responds to NRC 800208 ltr re violations noted in \$E Insp Repts 50-321/80-02 & 50-364/80-02 Corrective actions relocation of fire pump controller & installation of tamper alarms for fire valves to be completed Aug 1780 WIDNER.W A Georgia Power Co 80/07/31 ip

```
8009120311 Forwards IE Into Natice 80-31, "Maloperation of Gould-Brown
Bovers 480 Volt Type K-600S & K-DON 600S Circuit Breakers "
No written response required
O'REILLVy P Region 2. Atlanta, Office of the Director 80/08/27
 8009110676 Responds to 1E Bulletin 80-15 Emergency notification sys
powered by telephone company To ensure sys extensions
operate independently of plant phones, testing was conducted
on 800815 All extensions operable during power trip
HIDMER, W.A. Georgia Power Co. 80/08/29 ip
  8009230204 Forwards 1E Insp Repts 50-321/80-34 & 50-366/80-34 on
      800813-14 No noncompliance noted
KENNA, W B Region 2, Atlanta Safeguards Branch 80/08/29 ip
  --8009230210 IE Insp Repts 50-321/80-34 $ 50-366/80-34 on 800813-14 No
          noncompliance noted Major areas inspected licenses implementation of contingency strike plan Details withheld (ref loCFR2 790)
MCGUIRE D R Region 2, Atlanta, Safeguards Branch TOBIN,
          MCGUIRE.D R. Region 2, Atlanta, Safeguards Branch TOBIN, W J. Region 2, Atlanta, Office of the Director 80/08/27 ip
 8009230525 Forwards Revision 1 to IE Bulletin 79-26, "Boron Loss From BMR Control Diades" Written response required O'REFLLY, J.P. Rogion 2, Atlanta, Office of the Director 80/08/29
 8009240367 Responds to IE Bulletin 80-17. Suppl 3 Outlines procedures in effect re loss of instrument air.loss of control rod driveline. rod drift by undrained scram discharge vol Function test of switches required prior to startup HID: HER. If A Georgia Power Co 80/08/29 2pp
 8009290282 Forwards IE Circular 80-21, "Regulation of Refueling Crews "
      No written response required
O'REILLY.J P Region 2. Atlanta. Office of the Director B0/09/10
 8007300104 Submits response to IF Bulletin 80-20 No Westinghouse Type
H-2 control switches used in safety-related applications
WIDNER, W A Georgia Power Co 80/07/12 ip
 R Pariodic operating reports & related correspondence
 8007030465 Forwards "Semiannual Radioactive Efficient Release Rept."
      Jan-June 1980
MAPHY, M Oso
                          Georgia Power Co 80/08/30 1p
 -- 8009030419 "Bemiannual Radioactive Effluent Release Rept." Jan-June
                Georgia Power Co 80/08/30 44pp
 8009180498 Forwards monthly operating rept for Aug 1980
MAXMY.M Georgia Power Co 80/09/10 ip
--8009180235 Monthly operating rept for Aug 1980
UNDERNDOD, P R Georgia Power Co 80/09/10 9pp
 S Reportable occurrences, LERs & related correspondence
8007030451 Forwards LER 80-113/03L-0
                                                                 80/08/25 in
     HALRY, H
                          Oporgia Power Co
--BC09030461 LER 80-113/03L-0 on 800726, w/reactor in shutdown mode following performance of manual scram per 1E Bulletin 80-17, scram discharge vol hi level switches 2C11-N013A & D found inoperable Caused by crushod floats Rept update to follow CQGOIN, C L Georgia Power Co 80/08/25 2pp
8007020369 Forwards LER 80-109/03L-0
MANRY, M Georgia Power Co 80/08/26 ip
--8009020374 LER 80-109/03L-0 on 800809, while performing HPC1 valve operability, HPC1 suppression chamber suction valve 2E41-F041 failed when cycled to check for battery ground Caused by motor winding failure due to high temp Motor repaired WIX.R T Georgia Power Co 80/08/26 2pp
8009020400 Forwards LER 80-122/03L-0
MARRY.M Georgia Power Co 80/08/26 lp
---8009020405 LER 80-122/03L-0 on 800811, during steady state operation at full power, while performing HNP-2-3001, reactor high pressure instrument tests witch 2021-N023C actuated at 1,068 psig Caused by setpaint drift Switch recallibr NIX,R T Georgia Power Co. 80/08/26 lp
```

```
8009030442 Forwards LER 80-106/03L-0
MA/RY, M Georgia Power Co 80/08.
--8009030447 LER 80-106/03L-O on 80072B;w/reactor in cold shutdown, potassium sulfate; matural ascanite & potassium hydrogen sulfite deposits discovered around spams on sacrificial shield Cause undottermined Update rept uil be submitted CDGGIN,C L Georgia Power Co 80/08/26 2pp
800902036R Forwards LER 80-119/02L-0
MANRY.M Georgia Power Co 80/08/27 1p
--8009020267 LER 80-119/02L-0 on 800805,during QA audit surveillance, fire barrier penetration seal through rloor of control room was found breached Caused by failure to reseal following cable removal Seal repaired 800820 Fire watch established COOGIN.C L Georgia Power Co 80/08/29 2pp
8009020419 Forwards LER 80-123/03L-0
MANKY, M Georgia Power Co 80/08.
                                                                                                                           80/08/29 to
~-8009020433 LER 80-129/03L-0 on 800812, during normal operation, while performing reactor core isolation cooling steam line pressure instrument functional test outboard isolation valve failed to fully close Caused by derective torque switch NIX.R T Georgia Power Co 80/08/29 2pp
 60090904성당 Forwards updated LER 80-032/01术-1
MANRY.M Georgia Power Co 60/09/04 ip
 --8009070438 Updated LER 80-032/01X-1 on 800327.during simulated loss of
                sys pressure surveillance test:2D plant syc water pump sequenced improperly Cause not found Siys tested & pump tied to bus within required limits Test continued w/no problems COGOIN.C L Georgia Power Co 80/09/04 2pp
8007090486 Forwards LER 80-124/03L-0
MANRY, M Georgia Power Co 80/09/04 tp
--8009090495 LER 80-124/03L-0 on 800813, during surveillance of torus drywell vacuum breakers, 2748-F323J valve failed to give proper light indication On 800827, 2748-F323I failed in similar manner Cause not known Nix,R T Georgia Power Co 80/09/04 2pp
8009150331 Forwards LER 80-124/03L-0
MAKRY,M Georgia Power Co 80/09
                                                                                                                           B0/09/09 1a
--8009150335 LER 80-126/03C-0 on 800824, during steady state operation at 1540 MW 2P33-P001A, primary containment hydrogen & oxygen analyser became inoperable Caused by faulty design of regent gas flowmeter Design change requested R1X.R T Georgia Power Co 80/09/09 2pp
8009160285 Forwards LER 80-125/03L-0
MANRY, M Georgia Power Co 80/09/11 1p
 --8009160306 LER 80-125/03L-0 on 800824, during control room panel check,
                DETRIBUTION OF THE PROPERTY OF
8009230316 RO on 800908, following reactor scram, HPCI auto initiated beinjected due to low reactor water level Caused by MSIV closure, which caused reactor scram, loss of RFPT & increased reactor pressure HPCI returned water level to normal MARRY, M. Georgia Power Cd. 80/09/15. 2pp
8009290278 Forwards LER 80-105/03L-0
MANNY,M Ocorgia Power Co 80/09/18 1p
--8009290281 LER 80-105/03L-O on 800821, mitrogen pressure was lost to
both standby liquid control sys accumulators Caused by
"A" test valve leak % "B" test valve being broken while
installing test gaupe Test valves replaced
NIX,R T Georgia Power Co 80/09/18 2pp
8009300519 Forwards LER 80-128/03L-0
MANRY,M Georgia Power Co 80/09
                                                                                                                            B0/09/23 Lp
 --- B009300524 LER B0-128/03L-0 on 800905, reactor high pressure instruments
                  ORSONOZA LA ACTUATED Above Tech Breck Caused by setpoint
drift Editches recalltr & tested successfully
NIX.R T Georgia Power Co 80/09/23 2pp
```

V Operator Examinations

8009050291 Forwards excerpt from new training outline re criteria for operator training & licensing Current policy requires instructors attend annual simulator training & retraining lectures as part of approved requalification program MANRY. M Georgia Power Co 60/09/12 7pp

POCKET 50-967 BAILLY GENERATING STATION

- A Application/construction stage documents & correspondence
- 8007080080 Forwards draft NUREC-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed (mplementation schedule for meeting criteria of NUREG-0696 enci N/O NUREG EISERHUT, D.G. Division of Licensing 80/08/01 119pp
- 8009110742 Notification of 800904-05 meeting w/Mark 11 pwmers group to discuss plants chugging C/O & lateral load specs ANDERSON. C Containment Systems Branch 80/08/29 14pp
- 8009300419 Forwards "Pretiminary Review.Soil Parameters Used in USOS Rept 78-138.Efrects of Seepage From Fly-Ash Settling Ponds & Const Dewatering on Groundwater Levels in Cowles Unit. IN Dunes Natl Lakeshore: IN," in response to 800131 meeting BOHN: R J Northern Indiana Public Service Co 80/09/26 lp
- --8009300421 "Preliminary Review.Soil Parameters Used in USOS Rept 78-138,Effects of Seepage From Fly-Ash Settling Ponds & Const Dewatering on Oroundwater Levels in Cowles Unit, IN Dunes Hatl Lakeshore, IN " 4 Northern Indiana Public Service Co 80/05/31 34pp

O Adjudicatory correspondence

- 8009030552 Forwards appeal re denial of appropriateness of contentions in hearings on CP renewal Workable evacuation plan should be formalized & made operable before GL stage SCHULT2.0 Affiliation Unknown 80/08/26 1p
- B009020048 Response to ASLB 800807 special prehearing conference order re short pilings as issue in proceeding Issue should not be deferred due to new method of installation & serious safety questions that may arise Certificate of Svc encl EEKULER.S N . FAHNER.T C . MURRAY, H J Illinois. State of 80/08/25 9pp
- 8009090621 Ack receipt of 800605 request to join State of IL petition for suspension or revocation of CP Consideration of request delayed panding outcome of risk assessment study DENTON.H R Office of Nuclear Reactor Regulation, Director 80/08/25 in
- --8009070627 Requests under 10CFR2 206.submitted on behalf of intervenors City of Gary. IN. United Steelworkers of America Local 6787. Bailly Altiance. Save the Dunes Council & Critical Mass Energy Project. to join State of IL petition to suspend CP CORN. D G Gary. IN CORN. D 8 Public Citizen Litigation Group BO/06/05 7pp
- ~-B009090833 Petition to intervene & request for hearing submitted on behalf of City of Gary, IN. United Steelworkers of America Local 6787, Basily Alliance, Save the Dunes Council & Critical Mass Energy Project COMM, D B . BCMULTZ, N D Cary, IN COMM, D B Public Citizen Litigation Group B0706/05 7pp
- --8007070635 Response, submitted on behalf of City of Gary, IN.United Steelworkers of America Local 6787, Bailly Alliance, Save the Dunes Council % Critical Mass Energy Project to NRC & util opposition to petition to intervene Draft affidavits encl CONG, B & GENULTZ, W B Oary, IN CONN, D B Public Citizen Litigation Group 80/02/26 20pp
- 8007020884 Motion to compel NRC to determine whether to issue supplemental or new EIS per MEPA due to changes in circumstances occurring since EIS was issued Certificate of Svc & supporting documentation encl MURRAY, M J. FAHNER, T C. SEMULER, S N Illinois, State of 80/08/26 15pp
 - 09090972 Requests limited appearance at forthcoming ASLB hearing re CP amend for facility /DHNSON,L Affiliation Unknown 80/08/27 [p

- 8007020402 Order granting extension until 800711 for State of IL to respond to ASLB 800807 order re contentions incorporated by ref Replies to IL response will be extended accordingly GROSSMAN, H Atomic Safety and Licensing Board Panel 80/08/28 1p
- 8009030703 Notice for R Bohn B00930 deposition in Chicago, IL re late const completion & Joint intervenors' contentions admitted per ASLB 800807 order Certificate of Svc encl Related correspondence VOLLEN, R J. OBANN, E W. Izaak Walton League of America, Porter County Chapter VOLLEN, R J. B0/08/28 4pp
- 8009030710 Arguments in support of intervenors' 800630 reworded contentions filed in response to ASLB special prehearing conference provisional order Discusses Class 9 accident % spent fuel storage W/Certificate of Svc VOLLENR J . OSANNE W Izaak Walton League of America. Porter County Chapter VOLLENR J Voilen, R J 80/08/28 9pp
- 8009040281 Response in opposition to State of IL & Porter County Chapter 1979-80 contentions to Apalth & safety issues Contentions do not relate to couse of delay in const Does not address environ contentions Certificate of Svc encl BHEALK H. EICHHORNIN H. Northern Indiana Public Service Co SHEALK H. Lowenstein, Newman, Reis, Axeirad & Toll 80/08/28 15pp
- B009030[49 Notice of appeal from ASLB B0080B order denying intervention COHN, D.B., SCHULTI, W.B. Gary, IN COHN, D.B. Cohn, D.B. 80/08/29 la
- --8009030152 Brief in form of pleading supporting 800827 notice of appeal from ASLB 800808 order denying intervention Asserts interest & restates relevancy Urges application of 1973 ALAB-129 test Documentation & Certificate of Svc encl COHN.D M . SCHULTZ.W B Gary.IN COHN.D B Cohn, D B 80/08/29 25on
- 8009050432 Memorandum advising parties that oral argument will be heard on 801002 if decided Date must be reserved BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/09/02 ip
- 8009080509 Notion for extension until 800915 to respond to City of Oary, IN notice of appeal & supporting brisf Counsel contemporaneously involved in other pleadings Certificate of 8vc encl
 SHCA.K H. EICHHORN.H H. Northern Indiana Public Service Co SHCA.K H. Comenstein, Nowman, Reis, Axelrad & Toil 80/09/03 5pp
- 8009080511 Mution for consolidation of responses to Porter County Chapter 800828 & State of IL arguments re admission of Porter County new contentions Requests extension until 10 days after svc of State of IL filing W/Certificate of Svc SHEA.K H , EIGHHORN.W H Northern Indiana Public Service Co BHEA.K H Lowenstein.Newman.Reis,Arelrad & Toll 80/09/03 4pp
- 8009100515 Advises of limited appearance at ASLB hearing. TAIT.L Affiliation Unknown 80/09/03 1p
- 8009090420 Order granting extension until 801010 for parties to respond to submittals filed in response to revised contentions GROSSMAN.H Atomic Safety and Licensing Board Panel 80/09/03 fp
- 8009090791 Forwards util memorandum of law in response to State of IL motion to compel NRC determination re need for EIS SHEA.K H Lowenstein, Newman, Reis, Axeirad & Toll 80/09/05 2pp
- --8007070775 Memorandum of law in response to State of IL motion to compol NRC determination re need for EIS CEQ 800812 ltr upon which IL request was based/failed to demonstrate nexus between CP extension & CP developments

 Northern Indiana Public Service Co * Lowenstein, Newman, Reis, Axelrad & Toll 80/07/05 27pp
- 8009110783 Response in opposition to ABLB 800825 order denying State of IL Contentions 7D & 8 Issues presented raflect compelling matters of public interest & are within acope of proceeding Certificate of Svc anci FAHNER, T C . SEKULER, S N Illinois. State of 80/09/05 3pp

- 8009;10808 Response in opposition to Porter County Chapter & State of IL 800825 & 26 motions to compel NRC determination re need for EIS NRC should inform ASL8 & parties of schedule for completion of evaluation of util extension request SHEA,K H. EICHHORN,W H. Northern Indiana Public Service Co SHEA,K H. Lowenstein, Newman, Reis, Azelrad & Toll 80/09/05 3pp
- 8009120372 Response by Porter County Chapter Intervenors stating no objection to util 800703 request for reply consolidation Conditions position upon grant of extension until 800724 for intervenor to reply to util re revised contentions VDLLEN.R J Isaak Waiton Loague of America, Porter County Chapter VOLLEN.R J Volien, R J 80/09/08 ip
- --E007120445 Response by Porter County Chapter Intervenors in opposition to NRC 800822 position re new contentions & motion to consolidate Urges admission & consolidate to environ Issues arising after CP issuance Cartificate of Evc encl VOLLEN.R J Izaak Waiton League of America. Porter County Chapter VOLLEN.R J Volien, R J 80/09/08 6pp
- 8009150400 Response in opposition to NRC 800822 motion to consolldate contentions Consolidation premature Undistinguishable interests are impossible to be defined prior to progress of discovery Certificate of Syc encil SEXULER.S N. FAHNER.T C Illinois, State of 80/09/08 3pp
- 8009110018 Response to Porter County Chapter & State of IL 800825 & 26 motions, respectively NRC will determine whether EIS is resoured in Oct 1980 Due consideration will be given to CEQ 800912 itr Certificate of Svc enci
- 8009130463 Forwards revised Pages 21.22 & 24 of memorandum of iaw on need to prepare EIS rs CP extension, attached to 800705 ltr Section 9 103 of NRC regulations was overlooked Memorandum submitted w/800705 ltr SHEAR H Lowenstein, Newman, Reis, Axeirad & Toll 80/09/10 6pp
- SOOT160247 Memorandum in support of Porter County Chapter Contentiions R-8 1 R-i i5 previousiy adopted by State of IL Contentions fit within 1973 ALAB-129 definition in DC Cook proceeding rescope of hearing Certificate of Svc encl VAN VRANKEN.J., FAHNER.T C IIIInois, State of 80/09/i1 6pp
- 8009250057 Notice of change of address W/Cortificate of Svc LAUDIG.S Laudig, S 80/09/13 2pp
- 8009170147 Brief in opposition to City of Cary et al & O Schuit: appeal from ASLB 800807 special prehearing conference order Urges that denial of intervention & contention re emergency evacuation be upheld Certificate of Svc enci
 CDLOBERG, 8 C Hearing Branch 2 80/09/15 2ipp
- 8009190039 Brief in opposition to City of Gary, IN, et al & G Schultr appeal from ASLB 800807 special prehearing conference order Vrges that denial of intervention re emergency evacuation be affirmad & appeal dismissed Certificate of Svc encl SHEA.K H , FRANTZ.8 P , EICHHORN.W H Northern Indiana Public Service Co 80/09/15 36pp
- 8009220177 Brief in form of pleading supporting City of Cary, IN, et al & O Schultz appeal from ASLB 800808 special prehearing conference order Urges reversal of portion danying admissibility of evacuation issues Certificate of Syc enci SEKULER: N , FAHNER: T C , MURRAY: M J Illinois, State of SO/09/15 8pp
- 8009230008 Brief in form of pleading in support of City of Cary, IN et al & O Schultz appeal from ASLB 800808 special prehearing order denying intervention Urges reversal of order reevacuability as opposed to suitability W/Certificate of Svc VCLLEN.R J. OSANN.E W Izaak Walton League of America. Porter County Chapter VCLLEN.R J Vollen, R J 80/09/15 14pp
- 8009230035 Brief in form of pleading in opposition to City of Gary, IN et al & G Schultz appeal from ASLD 800807 special prehearing conference order denying intervention Contention does not relate to cause of delay Certificate of Svc enci SHEA, K H , FRANTZ, 8 P . EICHHORN, W H Northern Indiana Public Service Co 80/09/15 29pp
- 8009180259 Forwards portions of Northern IN Public Svc Co 800915 brief in opposition to appeals Cover sheet, table of contents, table of authorities & Centificate of Svc only enci BHEA,K H. Lowenstein, Neuman, Reis, Axelrad & Toll 80/09/16 10pp.

- 8009190419 Memorandum / order consolidating City of Oary, IN.et al & G Schultz eppeals from ASLB 800807 special prehearing conference order Appeal arguments will be heard on 801002 at NRC in Bethesda.mD Names must be submitted by 800928 BISHOP, C. J. Atomic Safety and Licensing Appeal Panel 80/09/17 30b
- 8009230382 First request for designation of NRC witnesses for 801018 deposition in Chicago, it re Contentions 1, 3, 4, 5, 7 & 8 admitted per ASLS 800807 special prehearing conference order Certificate of Svc enc1 VDLLEN, R J , 0SANJ, E W | Iraak Walton League of America, Porter County Chapter VDLLEN, R J Vollen, R J 80/09/17 4pp
- 8009230393 Notice for EA Schroer & HP Lyle B01021 & 28 deposition taking respectively in Chicago. IL re Contentions 1.3.4,5.7 & B admitted per ASLB 800807 special prehearing conference order Certificate of Svc encl Related correspondence VOLLEN.R J. DSANN.E W Isaak Walton League of America, Porter County Chapter VOLLEN.R J. Volien. R. J. 80/09/17 4pp
- 8009260011 First request for production of documents directed to NRC Addresses delay in construence bilization of contractors, installation of slurry wall & environ significance of amend Insp & copying will take place on 801014 in Chicago IL VOLLEN.R J. OSANN,E W. Iraak Walton League of America, Porter County Chapter VOLLEN.R J. Vollen, R J. 80/09/18 8pp
- 8009220173 Submission of Exhibit B erroncously omitted from State of IL 800915 brief filed in form of pleading in support of City of Gary, IN. et al % S Schultr appeal MURRAY.IN J Illinois. State of 80/09/19 4pp
- 8009230041 Advises that 80 Goldberg will present NRC oral argument in proceeding per ASLAB 800917 memorandum & order GOLDBERO,8 C Hearing Branch 2 80/09/19 ip
- 800930000A Response in opposition to util application for extension of CP which would constitute major federal action affecting environ if granted Urges issuance of revised EIS Extension cannot be based on 1973 FES KIMBALL, T. L. National Wildlife Federation SHELDON, K.P. Sierra Club COCHRAN, T.B. Natural Resources Defense Council 80/09/24 17pp
- B009300025 Advises that W/ Eichhorn will present 800917 oral argument on behalf of util per ASLAB 800917 memorandum & order Related correspondence EICHHORN W M Eichhorn, Eichhorn & Link 80/09/24 1p
- B00930005 Advises that contrary to B00B18 pleading, NRC safety evaluation of applicant pile installation proposal will be issued on B01015 OQLUDERG, SC Hearing Branch 2 80/09/26 Ip
- 800930033; Order denying State of It, motion to compel NRC determination whether EIB will be assued per NEPA NRC will decide need for EIB by early Oct 1980 Time frame reasonable GROSSMAN. H Atomic Safety and Lacensing Board Panel 80/09/26
- 8009300576 Response in opposition to State of iL 800911 memorandum & to Porter County Chapter arguments filed in support of County new contentions on safety matters issues held to be outside scope of proceeding Certificate of Svc encl SHEA,K H FRANTZ,B P , EICHHORN,W H Northern Indiana Public Service Co 80/09/26 ilpp
- H Qeneral correspondence
- BQQ91QQ511 Opposes const of facility * Affiliation Unknown BO/09/Oi 5pp
- 8009:80556 Responds to 800421 ltr expressing concerns re facility & NRC response to 800416 question re why plant should be completed before deciding whether or not it should operate Safety evaluation concluded piant may be safely built & operated YDUNGSLOUD, B J Licensing Branch ! 80/09/10 2pp
- G Inspection reports: IE Bulletins & correspondence
- 8009090047 Forwards IE Bulletin 80-07. Suppl 1, "BWR Jet Pump Assembly Failure," No response required KEPPLER, J D Region 3, Chicago, Office of the Director 80/05/14 to
- 8009100165 Responds to IE Sulletin 79~03A, "Longitudinal Held Defects in ASKE SA-312. Type 304 Stainless Steel Pipe" No plping as yet installed at facility SHORB.E M Northern Indiana Public Service Co 80/08/14 1p

- 8007110556 Responds to IE Bulletin SO-OB, "Eram of Containment Liner Penetration Welds" Due to delays in NRC completion of pile foundation reviews, const % engineering on plant halted for three yrs Will submit response by 820104 SMORBLE K Northern Indiana Public Service Co 80/08/14 [p
- 8009110569 Responds to 1E Bulletin 80-16. "Potential Misapplication of Rosemount, Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dubput Codes ' Will respond, following resumption of engineering & const, by 820104
 SHQRB.E M Northern Indiana Public Service Co 80/08/14 1p
- 8009030207 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written respinse required KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/15 in
- 8007190485 Forwards (E Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE BUR Facilities" No specific action or response requested MEPPLER, J G Region 3, Chicago, Office of the Director 80/08/20
- G009120055 Forwards Suppl 3 to 1E Bulletin 60-17, "Failure of Control Rods to Insert During Scien at BUR" No written response required KEPPLER.J G Region 3, Chicago. Office of the Director 80/08/22
- 8009170432 Forwards IE Circular 80-18, "iOCFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/08/22
- 8009230259 Responds to NRC 800805 request for supplemental info re IE Dulletin 80-07. "BWR Jet Pump Assembly Failure " No jet pumps have been installed at facility Util will adopt plan to prevent cracking in BWR jet pump hold down beams SMORBLE M Northern Indiana Public Service Co 80/08/27 2pp
- 8007230074 Forwards IE info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-600S & K-DON 600S Circuit Breakers " No written response required KEPPLER. J Q Region 3. Chicago, Office of the Director 80/08/28
- 8009240110 Forwards IE Circular 80-21, "Regulation of Refueling Crews"
 No written response required
 KEPPLER, J.O. Region 3, Chicago, Office of the Director 80/09/10
- 8009300365 Forwards IE Insp Meeting Rept 50-367/80-02 on 800724 FIORELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/09/19 ip
- ---8009300571 IE insp Meeting Rept 50-367/80-02 on 800724 No nancompliance nated Areas discussed coast status & general IE policies re coast FIGRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/18 2pp
- R Periodic operating reports & related correspondence
- 8007020005 Forwards well charts for 800730-0804. Bailly wells u/o recorders 5 pand levels for 800806, pneumatic pressure transducers & water meter readings for 800804, USOS wells for 800803 6 new USOS wells for 800727-0803 BOHN. R J Northern Indiana Public Service Cp 80/08/22 35pp
- 8009030434 Forwards "Quarterly Rept.Bailly Nuclear-1 Site." Apr-June 1980 PURCELL.J Northern Indians Public Service Co 80/08/22 1s
- 8009020091 Forwards well charts for 800804-12.pond levels for 800813 & Bailly walls w/o recorders, pneumatic pressure transducers, water meter readings & USOS wells for 800812 BOHNR U Northern Indiana Public Service Co. 80/08/25 33pp
- 8007090427 Forwards well charts for B00812-20.Bailly walls w/o recorders, pond lovels, pneumatic pressure transducers & water meter readings for 800820 t US33 walls for 800819 BOHN, R J Northern Indiana Public Service Co 80/08/27 33pp

- 8009090469 Forwards well charts for 800820-27 & Bailly wells w/o recorders, pond levels, pneumatic pressure transducers, water meter readings & VSGS wells for 800827 BDNH, R J Northern Indiana Public Service Co 80/09/05 35pp
- B009150474 Forwards well charts for 800827-0903.Bailly Wells w/o recorders.pond levels.pneumatic pressure transducers.water meter readings & USOS wells for 800903.rainfall data for 800901-0831 t Lake MI levels for 800515.0601 & 15 BDHN,R J Northern Indiana Public Service Co 80/09/11 36pp
- 8009250297 Forwards well charts for 800903-10.Bailly wells w/o recorders.pond levels.pneumable pressure transducers.water meter readings & USOS wells 800910 BDHN.R J Northern Indiana Public Service Co 80/09/19 34pp
- B009300446 Forwards well charts for 800910-17,8ailly walls w/o recorders,pond levels,pneuamtic pressure transducers,water meter readings 2 USOS wells for 800917 USOS has installed new Retl 9-4A next to Well 0-4 Hater level included B0!N,R J Northern Indiana Public Service Co 80/09/24, 33pp
- DOCKET 50-368 ARKANSAS NUCLEAR ONE, UNIT 2
- F Security, medical, emergency & fire protection plans
- BCCGG20130 Invites participation in BCCG22 workshop in Atlanta, GA to solicit comment re proposed functional criteria for emergency response facilities in NUREG-0696 Discussion to include location, size b staffing of emergency ctrs
 SEYFRIT, K V Region 4, Dallas, Office of the Director BC/08/12
- BO09090326 Notifies that security sys will be fully implemented on BD1001 Any subsequent equipment failure will be compensated for by compensatory measures outlined in util industrial security plan b implementing procedures
 TRIMBLE, D C Arkansas Power & Light Co 80/08/29 1p
- 8009170322 Forwards security personnel training & qualification plan Revision 1 Revision withheld (ref LOCFR2 790) TRIMBLE D C Arkansas Power & Light Co 80/07/09 ip
- G Adjudicatory correspondence
- 8009260535 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 CLARK, R.A. Operating Reactors Branch 3 80/08/27 2pp
- --8009260540 Order for mod of License NPF-6 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment info should be submitted by 801101
 EISENHUT, D O Division of Licensing 80/08/27 6pp
- U Insurance & indemmity information
- 8007030537 Forwards Endorsements 40,41 & 42 to NELIA Policy NF-210 & Endorsements 36 & 37 to MAELU Policy NF-74, TRIMBLE, D C Artansas Power & Light Co 80/08/29 6pp
- 8009030550 Forwards Enforsement 3 to ANI Binders EB-48 & EB-68 & MAELU Binders YB-48 & XB-69 TRIMBLE,D C Arkansas Power & Light Co 80/08/29 9pp
- P Operating license stage documents & correspondence
- 8009020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISECHUT, D & Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0496 entl W/o NUREG EISENHUT, D 0 Division of Licensing 80/08/01 119pp
- BOOT230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disreparted Requested submittal should include proposed class of amend EISENHUT, D O Division of Licensing 80/08/07 60pp

- GOOP:50287 Application to amend License NPF-6 changing Tech Spec 3 4 35 rs pressurizer code relief valves Class III fee encl GAVANAUOH.W Arkanses Power & Light Co 80/08/29 3pp
- --B009150292 Proposed Tech Spec 3 4 3 b re time extension for setting pressurizer code safety valves under ambient (hot) conditions

 * Arkansas Power & Light Co 80/09/29 ip
- BOO9110371 Requests that encl supporting document be docteted under Millistone MAPO.P 8 Assistant Director for Core & Containment Systems BO/09/09 1p
- BOO9180424 Application for amend to Licenso NPF-6, mafifying surveillance requirements of Toch Spec 4 6 2 3 to assure operability of containment sys Class III amend fee & supporting documentation enci CAVANAUGH, W Arkansas Power 8 Light Co 80/09/11 6pp
- --8009180427 Proposed mods to surveillance requirements of Tech Spec 4 & 2 3 to assure operability of containment sys * Arkansas Power & Light Co 80/09/11 lp
- 9009250126 Forwards Amend 14 to License NPF-6, safety evaluation & notice of issuance & availability CLARK,R A Operating Reactors Branch 3 80/09/12 2pp
- ---8009250130 Amend 14 to License NPF-6 revising App A Tech Specs to identify water flow rate requirements for operation mode allowed by Tech Spec 3 6 2 3 CLARK.R A Operating Reactors Branch 3 80/09/12 5pp
- ---8007250133 Safety evaluation supporting Amend 14 to License NPF-6 * Operating Reactors Branch 3 80/09/12 2pp
- --8009280137 Notice of issuance & availability of Amend 14 to License NFF-6 CLARK.R A Operating Reactors Branch 4 80/09/12 2pp
- 8009260453 Application for amend of License NPR-6, changing Tech Specs 3 6 2 3,4 6 2 3,3/4 6 3 & 3/4 6 4 Fee enci CAVANAUGH.H Arkansas Power & Light Co 80/09/16 9pp
- --8009260456 Proposed Tech Specs 3 6 2 3.3/4 6 3 & 3/4 6 4.permitting operation w/min of one containment cooling unit operable in each group & surveillance flow requirement of 1.250 gpm to each group 4 Arkansas Power & Light Co 80/09/16 3pp
- 8009300i45 Forwards Amends 46 % is to Licenses DPR-5; & NPF-6, respectively-safety evaluation & notice of issuance & availability
 REID.R W Operating Reactors Branch 4 80/09/i6 2pp
- --E009300148 Amends 46 to 15 to Licenses DPR-51 to NPF-6, respectively, revising ETS re design objective for radioactive gaseous releases to requirements for quarterly rept on radioactive gaseous releases
 REIO.R W. Operating Reactors Branch 4 80/09/16 19pp
- --8009300153 Safety evaluation supporting Amends 46 & i5 to Licenses DPR-51 & NPF-6, respectively * Office of Nuclear Reactor Regulation, Director 80/09/16 4pp
- --8007300155 Notice of issuance & availability of Amends 46 \$ 15 to Licenses DPR-51 & NPF-6, respectively REFD.R W Operating Reactors Branch 4 80/09/16 2pp
- BOOP300173 Requests deadline extension until 801201 to rewrite model Tech Specs to accomodate existing AR-1 Tech Specs format, unit design & NUREG-0578 Category A mods TRIMBLE, D.C. Artansas Power & Light Co. 80/09/19 ip
- BOG9300242 Confirms telcon commitments re removal of accumulation of Asian clams from containment cooling units In addition to physical cleaning, efforts include flushing w/high temp water to till any live clams remaining CAVANAUGH.W Arkansas Power & Light Co 80/09/22 2pp
- Q Inspection reports, IE Bulletins & correspondence
- EOO9020224 Responds to IE Bulletin 80-08, "Exam of Containment Liner Penatration Welds " Units utilize flued head design for containment penetrations Flued head penetrations radiographed TRIMBLE.D C Arkansas Power & Light Co 80/06/27 11pp

- 8009180145 Forwards IE Bulletin 80-18, "Maint of Adequate flin flow Through Centrirugal Charging Pumps Following Secondary Side High Energy Line Rupture " Written response required SEYFRIT. K V Region 4. Dailas. Office of the Director 80/07/24 1p
- 800902053B Forwards supplemental LE Info Notice 80-06. "Notification of Significant Events at Operating Power Reactor Facilities "No written response required SEYFRIT, K V Region 4. Dallas. Office of the Director 80/07/29 is
- 8009180138 Forwards IE Bulletin 80-20. "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches" Nritten response required SEYFRIY.X V Region 4. Dallas. Office of the Director 60/07/31 in
- 8009480160 Forwards IE Builetin 80-19. "Failure of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E" Written response required SEYFRIT. & V Region 4. Dallas. Office of the Director 80/07/31 in
- 8009260294 Forwards iE Info Notice 80-29, "Broken Studs on Terry Turbing Steam inlet Flange " No written response required SEYFRIT.K V Region 4. Dalias. Office of the Director 80/08/07
- 8009180470 Forwards IE Insp.Repts 50-313/80-11 & 50-368/80-11 on 800622-0721 & notices of violation & deviation One notice of violation & Attachmont A to repts withheld (ref 10CFR2 790) MADSEN-0 L Region 4, Dalias, Reactor Operations Nuclear Support Branch 80/08/08 2pp
- --8009180472 Notice of violation from insp on 600622-0721 * Region 4, Dalias, Reactor Operations Nuclear Support Branch 80/08/07 ip
- --8009180476 Notice of deviation from insp on 800622-0721 * Region 4, Dailas, Reactor Operations Nuclear Support Branch 80/08/07 lp
- --8009180481 IE Insp Repts 50-313/80-il & 50-368/80-il on 800622-0721
 Noncompliance noted 2712 valve gailery in Unit 2 auxiliary
 bldg not posted as radiation area & no positive access
 control on Door 364 Attachment A withheld (ref 100FR2 790)
 JOHNSON D CALLANI J, HURNICUIT, D M Region 4, Dallas, Office
 of the Director 80/08/07 i3pp
- 8009040039 Ack receipt of 800708 & 11 itrs informing NRG of steps taken to correct violations noted in IE lnsp Repts 50-313/80-05 & 50-369/80-05 MADSEN,G L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/08/12 ip
- --B009040049 Responds to NRC B00416 ltr re_violations noted in IE Insp Rept 50-368/80-05 Corrective actions Tech Spec change request generated to clarify existing spec on diesel generator automatic sequence time delay relays TRIMBLE.D C Arkansas Power & Light Go 80/07/08 lp
- 8009240735 Forwards Revision i to IE Builetin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required EEYRRIT.X V Region 4. Dalias, Office of the Director 80/08/15
- 8007170390 Forwards IE Circular 80-18. "10CFR50 99 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/08/22
- 8007120420 Ferwards IE Info Notice 80-31, "Maioporation of Gould-Brown Boveri 480 Voit Type K-600S & K-DCN 600S Circuit Breakers " No written response required SEYFRIT.K V Region 4, Dallas, Dffice of the Director 80/08/27
- 8009170173 Forwards IE lnsp Repts 50-313/80-13 \$ 59-348/80-13 on 800721-25 W/o encl notice of violation KELLY, J A Region 4. Dallas, Office of the Director 80/08/29 200

- --B009170176 IE Insp Repts 50-313/E0-13 & 50-368/80-13 on 800721-25
 Noncompliance noted vital area door fastened shut u/
 inadequate fastener, tamper alarm triggering mechanism taped
 in manner preventing alarm & intrusion alarms not tested
 CALDMELL, R A , KELLY, J A Region 4, Dailas, Office of the
 Director 80/08/27 2pp
- R Periodic operating reports & related correspondence
- E009090425 Forwards NPDES rept for Second Quarter 1980 re NPDES Permit AROSO1392 Ut;1 ltrs to EPA enci TRIMBLE.D C Arkansas Power & Light Co 80/08/29 8pp
- --8009090432 NPDES rept for Second Quarter 1980 re NPDES Permit AR0301392 + Ariansas Power & Light Co 80/08/29 15pp
- 8009160951 Forwards semiannual radioactive effluent rept for first & second quarters 1980
 TRIMBLE:D C Arkansas Power & Light Co 80/09/08 1p
- --8009160256 Semiannual radioactive effluent rept for first & second
- quarters 1750 * Artansas Power & Light Co 80/09/08 21pp
- 8009230407 Forwards monthly operating rept for Aug 1980 TRIMBLE.D C Arkansas Power & Light Co 80/09/15 ip
- --8009230410 Monthly operating rept for Aug 1980 PENGERGRAFT, R Artansas Power & Light Co 80/09/15 6pp
- S Reportable occurrences, LERs & related correspondence
- 8009020449 Forwards LER 80-059/03L-0
 TRIMBLE, D.C. Arkansas Power & Light Co. 80/08/26 2pp
- --8009020458 LER 80-059/03L-0 on 800727.during Mode 1 operation,core operating limits supervisory sys plant computer program indicated power margin of -80% rather than expected 0% at rated power Probable cause intermittent hardware failure SHIVELY.C N , O'HAMLON.J P Arkansas Power & Light Co 80/08/24
- 8009160557 PNO-IV-80-027A correcting info previously reported in PNO-IV-027 dtd 800822 re loss of all telephone communications Util has plans for installation of new communications sys which includes fiber optics & microwave JOHNSON & D. KUNNICUTY D. M. MADSEN O. L. Region 4. Dailas, Office of the Director 80/08/26 Zpp
- 8009030422 Forwards updated LER 80-037/01X-I TRIMBLE.D C Arkansas Power & Light Co 80/08/27 1p
- --8009030425 Updated LER 80-D37/01X-1 on 800503. furing Mode 1 operation, safety injection tanks (SIT) C & D were found to have boron concentrations of 1711 ppm & 1620 ppm Probably caused by dilytion of SIT makeup path by reactor coolant SHIVELY.C N Arkansas Power & Light Co 80/08/27 4pp
- 8009030539 Forwards LER 80-061/03L-0 TRIMBLE.D C Arkansas Power & Light Co 80/08/27 ip
- --8009030546 LER 80-061/03L-0 on 80072B leakage discovered on C charging pump at eibow weld during Mode I operation Caused by vibration Defective pipe spool piece replaced b hanger installed to reduce vibration Pump operable after repairs PENDERGRAFT, R Arkansas Power t Light Co 80/08/27 Ip
- 8009030622 Forwards LER 80-060/03L-0 TRIMBLE,D C Arkensas Power & Light Co 80/08/28 1p
- --8007030428 LER 80-060/03L-0 on 800730.D core protection calculator failed during Mode I operation Cause unknown DNBR/LPD trips bypassed 0 sys reinitialized % failure indications returned to normal Bypasses removed Unit remained operable TRIMBLE.D C Arkansas Power & Light Co 80/08/20 2pp
- 8009030410 Forwards updated LER 80-050/03X-1 TRIMBLE.D C Arkansas Power & Light Co 80/08/27 ip
- ---B009030417 Updated LER 80-050/03X-1 on 800804 during Mode 1 operation, untile testing emergency feedwater pump (2P7A), overspeed trip occurred rendering 2P7A inoperable Cause not specified, but hydraulic control oil sys is suspected Vendor contacted PENDERGRAFT,R Arkansas Power & Light Co 80/08/29 ip

- 8009090378 Forwards LER 80-057/03L-0
 TRIMBLE, D C Arkansas Power & Light Co 80/09/03 1p
- --8009090385 LER 80-057/03L-0 on 800805 during Mode 1 operation.all control element assembly calculator 1 inputs to core protection calculators were placed on inoperable status as precautionary measure

 EHIVELY: C N Arkansas Power & Light Co 80/09/03 1p
- 8009180149 PNO-IV-80-028 on 800903, svc water flow to containment cooling coils failed to meet min flow rate required by Tach Specs Nhen compliance w/Tech Specs could not be demonstrated unit was shut down Licensee is investigating JOHNSON, W. D., HUNNICUTT, D. M., MADSEN, O. L. Region 4, Dalias, Office of the Director 80/09/04 2pp
- 8009190590 PNO-IV-80-031 on 800904, containment bidg purge was started w/a licensed operator in charge knowing when purge started Caused by operator in charge being involved in other work JUHNSON, W D. HUNNICUTT. D H. MADSEN, O L. Region 4. Dallas, Office of the Director 80/09/05 2pp
- 8009150293 Forwards LER 80-044/03L-0 TRIMBLE,D C Arkansas Power & Light Co 80/09/08 ip
- --8009150296 LER 80-064/03L=0 on 800810, during Mode 1 operation, plant protective sys channels A & D maifunctioned Caused by power supply failure Channels repaired & declared operable per Tech Specs
 SHIVELYIC N Arkansas Power & Light Co 80/09/08 1p
- 8009150258 Forwards LER 80-042/03L-0 TRIMBLE, D C Arkansas Power & Light Co 80/09/09 Ip
- --8009150261 LER 80-062/03L-0 on 800801 during startup test procedures review for RC8 calorimetric flow rate test, power uncertainty bias terms in core protection calculators revealed calibratelenance less constant than Tech Spec requirements EHIVELY:C N Arkansas Power & Light Co 80/09/09 ip
- 8009150268 Forwards LER 80-066/03L-0
 TRIMBLE, D G Arkansas Power & Light Co 80/09/09, ip
- --8009150271 LER 60-066/03L-O on 800811.during Mode 1 operation, hi-hi containment pressure trip was received on plant protective sys channel D Other channels reported normal pressures Caused by power supply failure on bistable cand PENDERORAFT. A Arkansas Power & Light Co 80/09/09 1p
- 8009150273 Forwards LER 80-065/03L-0 TRIMBLE, D C Arkansas Power & Light Co 80/09/09 1p
- --B009150275 LER B0-065/03L-O on B00BI2, while performing surveillance testing on containment spray & sump valves, containment sump recirculation valve failed Caused by valve operator overload breaker tripping due to foreign matl in switch contacts PENDERGRAFT.R Arkansas Power & Light Co B0/09/09 ip
- 8009230705 Forwards LER 60-068/03L-0 TRIMBLE, D C Arkansas Power & Light Co 80/09/16 ip
- --B009230712 LER 80-068/03L-0 on 800823 during Mode 1, leak was discovered on 8 charging pump, 2P368, discharge header at discharge relief valve pipe Apparent cause is vibration induced from positive displacement pumps Mods made to all three pumps SHIVELY, C N Arkansas Power & Light Co 80/09/16 1p
- 8009230744 Forwards LER 80-067/03L-0 TRIMBLE,D C Arkansas Power & Light Co 80/09/16 ip
- --8009230748 LER 80-067/03L-0 on 800823, during Mode 1 operation I-131 dose equivalent value of 3 & uCi was observed Caused by "CRUD" burst RCS letdown flow was increased \$\tilde{t}\$ I-131 decreased to 0 26 uCi PENDERGRAFT, Arkansas Power \$\tilde{t}\$ Light Co 80/09/16 5pp
- 8009240496 Forwards LER 80-072/017-0 TRIMBLE, D C Arkansas Power & Light Co 80/09/17 1p
- --B007240504 LER B0-072/01T-0 on B00903, during Mode i operation, discovered B00B20 surveillance indicated inadequate evolute from through containment bidg coalers Caused by buildup of Asian clams in svc water side of coolers GHIVELY, C H Arkansas Power & Light Co B0/09/17 4pp
- 8009300538 Forwards LER 80-063/03L-0 TRIMBLE, D C Arkansas Power & Light Co 80/09/18 ip

- --8007300546 LER 80-063/03L-0 on 800822.after unit trip at 90%, power A condensate storage tank level fell below Tech Spec min Caused by emergency feedwater sys Suction taken from tank after unit trip Procedures revised to prevent reoccurrence SHIVELY, C N Arkansas Power & Light Co 80/09/18 ip
- y Operator Examinations
- BO09050330 Submits info re mods to reactor operator training program in response to NRC 800328 ltr Course summaries for thermodynamics fluid flow & heat transfer training & for mitigating core damage encl BTHARLON, JP Arkansas Power & Light Co 80/08/04 9pp
- EOC9170241 Documents 800811 presentation of util position re nuclear training program Presentations re operator training, general engloyee training, training records, on-the-job training, fire brigade training & sys training enci CAVANAUCH.W Arkansas Power & Light Co 80/08/13 16pp
- GOCKET 50-369 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- B009110636 Forwards roquests for additinfo re raduaste mgt sys, per review of FBAR Revision 39 Comments on radiological ETS & offsite dose calculation manual enc!

 TEDESCO.R L Assistant Director for Licensing 80/07/29 Opp
- 8009080080 Forwards draft NUREG-0676, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 enci W/o NUREG ELEENHUI.D 0 Division of Licensing 80/08/01 119pp
- 8009020122 Forwards request for addi info re floodplain mgt per Esscutive Order 11988 Response requested by 800808 YEDESCO.R L Division of Licensing 80/08/06 5pp
- 8009030069 Notification of 800904 meeting w/util in Bethesda, MD to discuss standby shutdown facility BIRKEL.R A Licensing Branch 1 80/08/14 4pp
- 8009040434 Forwards mati re NRC review of ice condenser containment & hydrogen control measures for Sequoyah Nuclear Power Plant, ACRS has scheduled meetings in Washington, DC on 800828, 0902 & 04 to discuss issue

 TEDESCO.R L Assistant Director for Licensing 80/08/22 Spp
- --8009040443 "Hydrogen Control for Sequoyah Nuclear Plant,Units | \$2 "
 4 Office of Nuclear Reactor Regulation, Director 80/08/13
 8199
- ---8009040450 Transcript of 800821 discussion of Sequoyah full power ilcense in Washington DC Pp 48-87
 Commission B0/08/21 47pp
- BO0912Dii6 Requests addi info re containment pressure boundary fracture toughness by 800903 TEDESCO.R L Assistant Director for Licensing 80/08/22 3pp
- 8009090877 Forwards request for addl info re radiation protection Complete response should be provided by 800902 TEDE8CO.R L Assistant Director for Licensing 80/08/25 4pp
- 8009180489 Requires submittai of ATMS temergency operating procedure for ARC review by 800919 Generic analysis should confirm ATMS mitigation capability described in Voi 3 of NUREO-0460 Commission will determine required mods & schedules TEDESCO.R L Assistant Director for Licensing 80/08/25 App
- 8009120623 Forwards request for additinfor recontainment emergency sump performance under post-LOCA conditions Requests info by 800903

 YEDESCO.R L Assistant Director for Licensing 80/08/26 App
- SCO9020371 Provides documentation of activities & current work status re hydrogen control in ice condenser containments Facility will have ECCS Bys will not generate substantial amounts of hydrogen ECCS will prevent hydrogen problem PARKER, H O Buka Power Co 80/08/27 3pp
- BOO9160649 Requests info neaded by 800908, for review of application re low pressure turbine discs TEDESCO.R.L. Assistant Director for Licensing 80/08/27 3pp

- 8009150333 Forwards request for add1 info re Category i masonry wail design Requires response by 800919 TEDESCOR L Assistant Director for Licensing 80/08/29 5pp
- BD09100152 Requests info by B00919 to complete Final Tach Specs Required info includes proposed changes requiring technical justification & identification of FSAR revisions subsequent to issuance of SER requiring Tech Spec changes YDUNGBLGOD: B J Licensing Branch (80/09/02 3pp
- 8009190236 Forwards FR notice re-relocation of local PDR to Atkins Library,Univ of NC.Charlotte.NC FELTON.J M Division of Rules and Records 80/09/02 2pp
- --8009190242 Notice of relocation of local PDR to Atkins Library, Univ of NC. Charlotte, NC FELTON. J M Division of Rules and Records 80/09/02 2pp
- 800916026t Forwards proprietary & nonproprietary versions of Westinghouse computer printout data entitled "Low Prossure Turbine Disc Info," in response to NRC 800827 request Proprietary version withheld (ref 10CFR2 790) PARKER.N O Duke Power Ca 80/09/04 2pp
- 8009110345 Forwards updated responses to "Duke Power Co.McGuire Nuclear Station Response to TMI Concerns " Fuel loading for Unit i scheduled for Oct 1980 PARKER, W O Duke Power Co 80/09/08 34pp
- BOO9150439 Notifies that util BOO925 itr re ATMS requirements responds to NRC 790817 & BOO925 requests Ltr reflects current util intentions re interim ATMS procedures prior to OL issuance PARKER, W O Duke Power Co BO/09/09 ip
- 6009150548 Requests examption from mechanical snubber requirements until startup following first refueling outage Testing equipment necessary to comply w/NRC surveillance requirements is unavailable PARKER, N O Duke Pawer Co 60/09/08 ip
- 8009300644 Summary of B00904 meeting u/util in Bethosda,MD re final standby facility Connection u/station will occur subsequent to NRC review & approval Site visit considered for B00925-26 BIRKEL,R A Licensing Branch 1 80/09/09 Zee
- BOO9160600 Forwards response to RL Tadesco ROOB22 itr requesting info re containment pressure boundary fracture toughness Mails test data in storage at facility Oversize drawings available in Contral Files only PARKER, W O Duke Power Co BO/09/10 3pp
- 8009290001 Forwards request for additinfo concorning reactor sys re Branch Technical Position RSD 5-1 TEDESCO.R L Assistant Director for Licensing 80/09/11 Spp
- 8009180376 Forwards add1 info re ECCS ovaluations in response to RL Tedesco 800805 itr Provides results of supplemental calculations to demonstrate potential impact of using fuel rod models.per draft NNRG-0630, on LOCA analysis for Unit 1 PARKER.N D Duke Power Co 80/09/15 3pp
- 8009180322 Forwards draft emergency procedures for review including immediate actions & diagnostics for safety injection. LUCA & steam generator tube rupture Secondary line rupture & loss of feedwater will be provided by 800919 PARKER. W O Duke Power Co 80/09/16 1p
- --B009180327 Draft emergency procedures, including immediate actions & diagnostics for safety injection.LOCA & steam generator tube rupture

 4 Duke Power Co B0/09/16 50pp
- 8009190399 Responds to NRC 800520 ltr re NUREQ-0577. "Potential for Low Fracture Toughness & Lameliar Tearing on PNR Steam Generator & Reactor Cociant Pump Supports " No response needed, pending add1 NRC guidance PARKER, W D Duke Power Co 80/09/16 lp
- B009190506 Forwards Revision 1 to util 800702 response re info request on Category I masonry walls
 PARKER, W Q Buke Power Co 80/09/16 4pp
- BOO7240407 Responds to NRC 800731 Itr stating position re incore thermocouples Thermocouple readout has capability for printout within 5-6 minutes Thermocouples are capable of measuring in 2,000 F range PARKER, W O Duke Power Co 80/07/17 2pp

- 6009290169 Advises that auxiliary feedwater sys automatic initiation meets safety grade requirements re 7H1 Itam II E 1 2/NUREO-0578. Section 2 i 7 a Requests compliance demonstration.by 800929, re automatic removal of manual bypass YOUNG3LOOD.B J Licensing Branch (80/09/17 3pp
- 8009240489 Forwards response to Bulletins & Grders Task Force recommendations re auxiliary reedwater sys Response supplements info transmitted in 800813 1tr PARKERIN U Duke Power Co 80/09/18 7pp
- 8009290371 Advises that response to NAC 800827 request for info re draft Tech Specs has been sent PARKER,W O Dute Power Co 80/09/19 1p
- 8009290303 Forwards add1 info re Category I mesonry wall design per NRC 800829 request Also forwards revised Page 3 of 800916 response PARKER.N D Dute Power Co 80/09/23 12pp
- 8009300434 Responds to NRC B00826 request for info re containment emergency swep debris PARKER, N O Dube Power Co 80/09/24 App
- F Security, medical, emergency & fire protection plans
- 8009260527 Forwards comments re storage & in-transit security plan for SMM of low strategic significance Response requested within 30 days Comments withheld (ref 100FR2 790) MCCORKEE,O W Physical Security Licensing Branch
- 8009020029 Forwards facility emergency plan & rei±ted info PARKER.W O Duke Power Co 80/08/25 13pp
- --8009020033 Emergency plan for facility * Duke Power Co 80/08/25 200pp
- B009120592 Forwards emergency preparedness evaluation Current plan provides acceptable state of emergency preparedness for fuel load & low power testing GRIMES.B K Emergency Preparedness Program Office B0/09/04 4pp
- 8009290175 Advises that health physicist should report directly to station manager per Reg Guide 8 B & NUREO-0660 & NUREG-0694 re radiation protection organization Requests commitment to comply or explanation of alternate compliance u/criteria BIRKEL.R Licensing Branch I 80/09/17 3pp
- O Adjudicatory correspondence
- BC090500B6 Response in opposition to Carolina Environ Study Group B00509 & 0815 motions requesting reopening of hearing record New contentions re amergency planning & comparative containment design are impermissible attack on regulations MCGARRY, J M Debevoise & Liberman B0/09/03 22pp
- ---B0090500B7 Affidavit ra hydregen generation & control following postulated TM1-type accident Util action offectively procludes excess hydrogen generation Certificate of Svc encl CANADY-K 9 Dute Power Co 79/07/09 7pp
- 8009090241 Response urging deferral of ruling on Carolina Environ Study Group 800815 motion to reopen record re hydrogen generation issue arising from TMI accident Suggests 15 days for parties to file simultaneous reply W/Certificate of Svc KETCHEN.E G Hearing Branch 4 80/09/04 lipp
- 8009120252 Forwards 800819 FR notice amending emergency planning regulations KETCHEN, E. G. Hearing Branch 3 80/09/09 19pp
- 8009160343 Forwards FR notice of relocation of LPDR KETCHEN.E G Hearing Branch 4 80/09/12 1p
- --8009160347 Forwards notice of relocation of LPDR CHILK.S J Office of the Secretary of the Commission 80/09/05
- --8007i60352 Notice of relocation of LPDR to Attins Library. Univ of NC, Charlotte, UNCC Station, NC FELTON, J M Division of Rules and Records 80/09/02 ip
- 8009220425 Notice of appearance in proceeding Certificate of Syc enci CHATISS.J R Regulations Division 80/09/18 2pp

- 8009260010 Submittal updating applicant 800903 response in opposition to Carolina Environ Study Group motion to reopen OL record re hydrogen generation control issue arising from TMI accident Certificate of Svc encl PORTER, M. L. NCGARRY, J. M. Duke Power Co. MCGARRY, J. M. Debevoise & Liberman 80/09/19 App
- BO09260266 Response in opposition to N Kiefer 800911 itr sesting intervention if OL record reopened Petition deficient but limited appearance statement may be granted Certificate of Svc encl MCGARRY, J M , PORTER, W L Consumers Power Co MCGARRY, J M Debevoise & Liberman 80/09/23 4pp
- 8009260273 Response in apposition to JJ Scott 8009il ltr seaking intervention if OL record respond Petition deficient but limited appearance statement may be granted Certificate of Svc encil MCGARRY, J M. PORTER, W.L. Consumers Power Co. MCGARRY, J M. Debevoise & Liberman. 80/09/23 4pp
- H General correspondence
- 8009100103 Responds to 800729 request for public hearing re-effects of TMI-2 type accident on facility containment bidg Motions by util to terminate stay of ASLB 770418 decision 7 by intervenor to reopen proceedings are pending KETCHENLE Q Hearing Branch 4 80/08/20 2pp
- 8009180385 Expresses concern re-proximity of facilities to Charlotte. NC All safety factors should be considered prior to granting of OLs CONVEY.N H Affiliation Unknown 80/09/11 2pp
- --8009180480 Expresses concern re proximity of facilities to Charlotts. NC Licensing hearings should be respended due to problems w/low pressure containment bidg & danger of hydrogen explosion SCOTT. J J Affiliation Unknown 80/09/11 ip
- 8009230746 Requests licensing hearings be reopened to consider low pressure containment bldg inability to withstand more than 15 psi Balleves that TMI-2 pressure reached 28 psi KIEFER:N Affitiation Unknown 80/09/ii ip
- Q Inspection reports. IE Bulletins & correspondence
- 8009100058 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/07/24
- 8009030175 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/15
- B009030183 Ack receipt of 16 Insp Rept 50-369/80-13 on 800610-19 No proprietary info PARKER.# O Duke Power Co 80/08/15 lp
- --B009030168 Forwards IE Insp Rept 30-369/80-13 on B00610-19 No noncompliance noted LEWIS,R C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/07/28 2pp
- --8007030199 IE Insp Rept 50-367/80-13 on 800610-19 No noncompliance noted Major areas inspected preoperational testing, IE Bulletin 80-50 & previous insp findings UPRIGHT.C & Region 2. Atlanta, Reactor Operations Nuclear Support Branch JOHNSON, A H Region 2, Atlanta, Office of the Director 80/07/28 2pp
- 8009050545 Ack receipt of IE Insp Rept 50-369/80-15 on 800609,10.17 & 18 No proprietary info PARKER: W O Duke Power Co 80/08/15 ip
- ---8009050547 Forwards JE Insp Rept 50-369/80-15 on 800609.10.17 & 18 No noncompliance noted LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/07/28 2pp

- --8007050550 IE Insp Rept 50-369/80-15 on 800607.10.17 & 18 No noncompliance noted Major areas inspected hot functional testing preparation preoperational test witnessing & responses to bulletins & circulars MARTIN, R D Region 2. Atlanta, Reactor Operations Nuclear Support Branch DDNATT J Region 2. Atlanta, Office of the Director 80/07/28 Spp
- 8009140633 Responds to IE Bulletin 80-20 re failures of Wastinghouse M-2 spring return to neutral control switches Identified switches are not used or planned to be used in safety-related areas ThirteOn manhours expended for review PARKER,W O Duke Power Co 80/08/20 Ip
- 8009160137 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22
- 8009120343 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Bover(480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required C'REILLY, J P Region 2. Atlanta. Office of the Director 80/08/27
- 8007250191 Ack receipt of IE Insp Rept 50-369/80-21 on 800714-18 No proprietary info pARKER, O Dute Power Co 80/08/27 ip
- --8009250196 Forwards IE lnsp Rept 80-369/80-21 on 800714-18 No moncompliance noted STOHR, J.P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/08/07 2pp
- --8009250200 IE Insp Rept 50-369/80-21 on 800714-18 No noncompliance noted Major areas inspected radiation protection, nadwasts mgt & sys mods & preoperational testing results TROUP.0 L. Region 2. Atlanta, Office of the Director OIBSQN.A F Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/08/06 App
- 8009120598 Responds to IE Bulletin 80-19 Mercury-wetted matrix relays are not used or planned for use in reactor protection sys PARKER, W O Duke Power Co 80/08/28 ip
- 8009240201 Ack receipt of 800605,30 & 0718 itrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-369/80-04

 MURPHY.C © Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/08/29 1p
- --8009240206 Responds to NRC IE Insp Rept 50-369/80-04 Corrective actions completion of evaluation of addi hangers per 800630 ltr PARKER, N O Duke Power Co 80/07/18 2pp
- --8009240212 Responds to IE Insp Rept 50-369/80-04 Corrective actions performed reinsp of hangers PARKER.W 0 Dute Power Co 80/06/30 2pp
- --8009240220 Responds to NRC 800912 ltr re violations noted in IE Insp Rept 50-369/80-04 Corrective actions rept issued to record Items of noncompliance & evaluation performed to determine proper actions necessary to resolve problems PARKER, W O Duke Power Co 80/06/05 3pp
- --800924022B Forwards IE Insp Rept 50-369/80-04 on 800416-18 & notice of violation MURPHY C E Region 2, Atlanta. Reactor Construction & Engineering Support Branch 80/05/12 2pp
- --8009240232 Notice of violation from insp on 800416-18
 # Region 2. Atlanta, Office of the Director 80/05/08 ip
- --BOD7240241 IE Insp Rept 50-369/BO-04 on BOO416-18 Noncompliance noted insp data for support 1-MCA-ND-H265 not available Three of five selfdrill expansion anchor bolts of support 1-MCA-ND-H76 determined to be torqued less than CP-308 requirementa ANG.W P Rogion 2. Atlanta. Office of the Director HERDT.A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch BO/05/08 4pp
- 8007270277 Forwards IE Circular 80-21, "Regulation of Refueling Crows" No written response required D'REILLY. J P Region 2. Atlanta, Office of the Director 80/09/10 500

- 8009300157 Submits response to IE Bulletin 79-13.Revision 2 During radiograph testing, indication was found in auxiliary feedwater no.ile on steam generator A Indication is considered acceptable PARKER, W O Duke Power Co 80/09/11 1p
- S Reportable occurrences. LERs & related correspondence
- 8007040383 Significant deficiency rept re loose impeller cap & jam nuts on RHR Pump 1A Caused by inadequacy of IR recommendation re IE Circular 77-19 Util has informed I-R that recommendation will not resolve problem PARKER.W O Dute Power Co 80/08/28 2pp
- 8009240481 Significant Deficiency Rept SD 349/80-15 on 800917, pressurizer cavity exceeded design temp Caused by insufricient ventilation cooling flow & higher than design heat loads Permanent temp monitoring sys will be installed DOMAT.Y Duke Power Co 80/09/18 4pp

V Operator Examinations

- 8009240087 Requests detailed discussion & description of proposed licensed Operator staffing plan projected through Dec 1983 by 800912 TEDESCO.R L. Assistant Director for Licensing 80/09/03 3pp
- 8009240448 Discusses proposed biconsed operator staffing plan Marked-up Tech Specs Table & 2-1 re shift creu composition & breakdown of total licensees.Individuals in training & available min requirements for Sept 1980-Jul 1981 encl PARKER:W O Duka Power Co 80/09/18 6pp
- DUCKET 50-370 WILLIAM B MCGUIRE NUCLEAR STATION. UNIT 2

 Application/construction stage documents & correspondence
- 8009110636 Forwards requests for add1 info re radwaste mgt sys.per review of FSAR Revision 39 Comments on radiological ETS & offsite dose calculation manual enci TEDESCO.R L Assistant Director for Licensing 80/07/29 8pp
- 80090800B0 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities ' Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT, D G Division of Licensing 80/08/01 [19pp]
- 8009020122 Forwards request for addl info re floodplain mgt per Executive Order I1988 Response requested by 800808 TEDESCO.R L Division of Licensing 80/08/06 5pp
- 8009030069 Notification of 800904 meeting w/util in Bethesda.MD to discuss standby shutdown facility BIRKEL.R A Licensing Branch & 80/08/14 4pp
- 8009040434 Forwards mather NRC review of ice condenser containment & hydrogen control measures for Sequoyah Nuclear Power Plant ACRS has scheduled meetings in Washington, DC on 800828, 0702 to 4 to discuss issue TEDESCO, R L. Assistant Director for Licensing 80/08/22 5pp
- 8009120116 Requests addl info re containment pressure boundary fracture toughness by 800903
 TEDESCO,R L. Assistant Director for Licensing 80/08/22 3pp
- 8009090877 Forwards request for add3 info re radiation protection Complete response should be provided by 800902 TEDESCO,R L Assistant Director for Licensing 80/08/25 4pp
- 8009180489 Requires submittal of ATMS emergency operating procedure for NRC review by 800919 Generic analysis should confirm ATMS mitigation capability described in Vol 3 of NVREO-0460 Commission will decormane required mods & schedules TEOEBCO, R. L. Assistant Director for Licensing 80/08/25 4pp
- 8007120623 Forwards request for add) info re containment emergency sump performance under post-LOCA conditions Requests Info by 800703
 TEDESCO.R L Assistant Director for Licensing 80/08/26 App
- 8009020371 Provides documentation of activities & current work status re hydrogen control in Ice condenser containments Facility will have ECCS Bys will not generate substantial amounts of hydrogen ECCS will prevent hydrogen problem PARKER, W Q Duke Power Co 80/08/27 3pp

- 8009160649 Requests info needed by 800908, for review of application re low pressure furbine discs TEDESCO.R L Assistant Director for Licensing 80/08/27 3pp
- 8009150333 Forwards request for additinfo re Category I masonry wall design Requires response by 800919
 TEDESCO.R L. Assistant Director for Licensing 80/08/29 5pp
- 8009100152 Requests info by 800919 to complete final Tech Spece Required info includes proposed changes requiring technical justification & identification of FSAR revisions subsequent to issuance of SER requiring Tech Spec changes YOU.4GREGOD. B J Licensing Branch & 80/09/02 3pp
- 8009190236 Forwards FR notice re relocation of local PDR to Atkins Library, Univ of NC. Charlotte, NC FELTQM, J M Division of Rules and Records 80/09/02 2pp
- --8009190242 Notice of relocation of local PDR to Atkins Library,Univ of NC. Charlotte,NC FELYON.J M Division of Ruies and Records 80/09/02 2pp
- 8009110345 Forwards updated responses to "Duke Power Co.McGuire Nuclear Station Response to TMI Concerns " Fuel loading for Unit 1 scheduled for Oct 1980 PARMER:N D Duke Power Co 80/09/03 34pp
- 8009150439 Notifies that util 800925 ltr rø ATMS requirements responds to NRC 790817 & 800825 requests Ltr røflects current util intentions re interim ATMS procedures prior to DL issuance PARKER, N O Duke Power Co 80/09/09 ip
- 8009300644 Summary of 800904 meeting w/utll in Bethesda.MD re final standby Facility Connection w/station will occur subsequent to MRC review & approval Site visit considered for 800925-26
 BIRKEL.R A Licensing Branch 1 80/09/09 2pp
- 8009140600 Forwards response to RL Tedesco B00822 ltr requesting info re containment pressure boundary fracture toughness Matls test data in storage at facility Oversize drawings available in Central Files only PARKER.W Q Dute Power Co 80/07/10 3pp
- 8009290001 Forwards request for add1 info concerning reactor sys re Branch Technical Position RSB 5-1 TEDESCO.R L Assistant Director for Licensing 80/09/11 5pp
- 5009180375 Forwards add1 info re ECCS evaluations in response to RL Tedesco 800805 itr Provides results of supplemental calculations to demonstrate potential impact of using fuel rod models.psr draft RUREC-0530. on LCCA analysis for Unit 1 PARKER.W O Duke Power Co 80/09/15 5pp
- BO09180322 Forwards draft emergency procedures for review including immediate actions & diagnostics for safety injection. LOCA & steam generator tube rupture Secondary line rupture & loss of feedwater will be provided by BO0919 PARKER. W O Duke Power Co B0/09/16 10
- ---8009180327 Draft emergency procedures including immediate actions & diagnostics for safety injection, LOCA & steam generator tube rupture

 + Duke Power Co 80/09/16 50pp
- BOO9190399 Responds to NRC BOO520 Itr re NUREQ-0577. "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generation & Reactor Coolant Pump Supports "No response needed.pending add1 NRC guidance PARKER.W O Duke Power Co BO/09/14 1p
- S009190506 Forwards Revision 1 to util 800702 response re info request on Category 1 masonry walls PARKER.W 0 Dute Power Co 80/09/16 4pp
- 8009240407 Responds to NRC 800731 ltr stating position re incore thermocouples Thermocouple readout has capability for printout within 3-5 minutes Thermocouples are capable of measuring in 2,000 F range PARKER, N O Duke Power Co 80/09/17 2pp
- BOO9270169 Advises that auxiliary feedwater eys automatic initiation meets safety grade requirements re TMI Item II E 1 2,NUREO-0578,Section 2 1 7 a Requests compliance demonstration.by BOO929,re automatic removal of manual bypass YOUNG9LOOD,B J Licensing Branch 1 80/09/17 3pp

- 8009240487 Forwards response to Bulletins & Orders Task Force recommendations re auxiliary feedwater sys Response supplements info transmitted in 800019 1 br PARKER, U O Duke Power Co 60/09/18 7pp
- 8009270371 Advises that response to NRC 800827 request for info redraft Tech Specs has been sent PARKER. H O Duke Power Co 80/09/19 1p
- B009290303 Forwards add1 info re Category I masonry wal1 design per NRC B00829 request Also forwards revised Page 3 of B00916 response PARKER. W O Duke Power Co 80/09/23 12pp
- 8009300434 Responds to NRC 800824 request for info re containment energency sump debris PARKER, N D Duke Power Co 80/09/24 App
- F Security, medical, emergency & fire protection plans
- 8009020029 Forwards facility emergency plan & related info PARKER, N D Duke Power Co 80/08/25 13pp
- --8009020033 Emergency plan for facility * Duke Power Co 80/08/25 200pp
- 8009120592 Forwards emergency preparodness evaluation Current plan provides acceptable state of emorgency preparedness for fuel load & low power testing GRIMES.B K Emergency Preparedness Program Office 80/09/04 4pp
- 8009290175 Advises that health physicist should report directly to station manager per Reg Guide 8 & NUREG-0660 & NUREG-0694 re radiation protection organization Requests commitment to comply or explaination of alternate compliance w/criteria BIRKEL.R Licensing Branch 1 80/09/17 3pp
- G Adjudicatory correspondence
- 8009050086 Response in opposition to Carolina Environ Study Group 800867 & 0815 motions requesting reopening of hearing record New contentions re emergency planning & comparative containment design are impermissible attack on regulations MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman 80/09/03 23pp
- --8009050087 Affidavit re hydrogen generation & control following postulated TMI-type accident Util action effectively precludes excess hydrogon generation Certificate of Sycencl CANADY, K S Duke Power Co 79/07/09 7pp
- 8007070241 Response urging deferral of ruling on Carolina Environ Study Group 800815 motion to reopen record re hydrogen generation issue arising from TMI accident Suggests 15 days for parties to file simultaneous reply W/Certificate of Svc KETCHEN.E O Hearing Branch 4 80/07/04 lipp
- 8009120282 Forwards 800819 FR notice amending emergency planning regulations KETCHEN.E G Hearing Branch 3 80/09/08 19pp
- 8009160343 Forwards FR notice of relocation of LPDR KETCHEN, E 0 Hearing Branch 4 80/09/12 ip
- --8009160347 Forwards notice of relocation of LPDR
 CHILK.S J Office of the Secretary of the Commission 80/09/05
 1p
- --8009160952 Notice of relocation of LPDR to Atkins Library, Univ of NC, Charlotte, UNCC Station, NC FELTON, J M Division of Rules and Records 80/09/02 ip
- 8009220425 Notice of appearance in proceeding Certificate of Svc encl CURTISS, J.R. Regulations Division 80/09/18 2pp
- 8009260010 Bubmittal updating applicant 800903 response in opposition to Carolina Environ Study Group motion to reopen GL record re hydrogen generation control issue arising from TMI accident Cortificate of Syc encl PORTER,W L , MCGARRY,J M Duke Power Co MCGARRY,J M Debevoise & Liberman 80/09/19 App

- 8009260266 Response in opposition to N Kiefer 800931 ltr seeking intervention if OL record reopened Petition deficient, but limited appearance statement may be granted Certificate of Syc encl MCGARRY, J M. PORTER, W.L. Consumers Power Co. MCGARRY, J M. PORTER, W.L. Consumers Power Co. MCGARRY, J M. Roccardes & Liberman. 80/09/23 4pp
- E009250273 Response in opposition to JJ Scott 800911 its seeking intervention if OL record reopened Petition deficient, but limited appearance statement may be granted Certificate of Svc enci MCGARRY, J M , PORTER, W L Consumers Power Co MCGARRY, J M Debapoise & Liberman 80/09/23 4pp

H General correspondence

- 8009100103 Responds to 800729 request ror public hearing re effects of THI-2 type accident on facility containment bldg Motions by util to terminate stay of ABLS 790418 decision & by intervenor to reopen proceedings are pending XETCHEMIE 0 Hearing Branch & 80/08/20 2pp
- GOO9180385 Expresses concern re proximity of facilities to Charlotte, NC All safety factors should be considered prior to granting of OLs CONVEY, W. H. Affiliation Unknown BO/09/ii 2pp
- --SCOTIBO4BO Expresses concern re proximity of facilities to Charlotte, NC (Licensing hearings should be reopened due to problems whom pressure containment bldg & danger of hydrogen explosion SCOTY.J J Affiliation Unknown 80/09/11 1p
- 3009230746 Requests licensing hearings be reopened to consider low pressure containment bldg (nability to withstand more than 15 psi Belisves that TMI-2 pressure reached 28 psi KIEFER.N Affiliation Unknown 80/09/11 ip
- G Inspection reports, IE Bullatins & correspondence
- S009030175 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Hercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY.J P Region 2, Atlanta. Office of the Director 80/08/15 in
- 8009160633 Responds to IE Bulletin 80-20 re failures of Westinghouse W-2 spring return to neutral control switches Identified switches are not used or planned to be used in safety—related areas Thirteen manhours expended for review PARKER, H O Duke Power Co 80/08/20 ip
- 6009150366 Ack receipt of 800807 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-370/80-08 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/08/22 ip
- --8009150349 Forwards response to NRC 800718 ltr re violation noted in IE lnsg Rept 50-370/80-08 Corrective actions procedures reviewed & all refs to unapproved procedures deleted PARKER/U D Duke Power Co 80/08/07 2pp
- --P007150372 Forwards IE Insp Rept 50-370/80-08 on 800616-19 & notice of violation HJRPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/07/18 2pp
- --8009150374 Notice of violation from insp on 800414-19 a Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/07/18. ip:
- --8009180377 IE Insp Rept 50-370/80-08 on 800616-19 Noncompliance noted failure of ultrasonic procedures to complete instructions for performing & recording exams
 IAJAC.L D. Region 2, Atlanta, Office of the Director HERDI.A R
 Region 2, Atlanta, Reactor Construction & Engineering Support
 Branch 80/07/18 1p
- 8009160137 Forwards IE Circular 80-18, "100FR80 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22 to
- 309120262 Ack receipt of 1E Insp Rept 50-370/80-11 on 800707-09 No proprietary info PARKER, N. O. Duke Power Co. 80/08/27 ip

- ---8009120271 IE lnsp Rept 50-370/80-11 on 800707-07 No noncompliance noted Major areas inspected preoperational environ monitoring, const waste mgt. wastewater treatment sys & site erosion control JENKINS, 0 R. CUNNINGHAM, A L. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/08/07 3pp
- 8009;20343 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boyer: 480 Vott Type K-6005 & K-DON 6005 Circuit Breakers"

 No written response required G'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/27
- 8009120598 Responds to 1E Sulletin 80-19 Mercury-wested matrix relays are not used or planned for use in reactor protection sys PARKER,N D Duke Power Co 80/08/28 ip
- 8007240256 Ack receipt of 800822 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-370/80-09 MURPHY.C E Region 2. Atlanta Reactor Construction & Engineering Support Branch 80/03/27 ip
- --8009240262 Responds to NRC 800725 ltr re violations noted in IE Insp Rept 50-370/80-09 Corrective actions loose termination in referenced mator aperated valves corrected & inspected/new installation specs issued PARKER, W O Duke Power Co 80/08/22 3pp
- --8009240265 Forwards IE Insp Rept 50-370/80-09 on 800624-27 & notice of violation dWRPHY,C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/07/25 2pp
- --8009240270 Notice of violation from insp on 800624-27 * Region 2, Atlanta, Office of the Director 80/07/25 2pp
- --B009240276 IE Insp Rept 50-370/80-09 on 800624-27 Noncompliance noted inadequate procedures for insp of safety-related cable terminations GIBEQUEST D. Region 2. Atlanta. Reactor Construction & Engineering Support Branch MERRIWEATHER.N., CONLON.T E. Region 2. Atlanta. Office of the Director 80/07/25 App.
- 8009270297 Forwards IE Circular BO-21, 'Regulation of Refueling Grews"
 No written response required
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/10
- 8 Reportable occurrences. LERs & related correspondence
- 8007040383 Bignificant deficiency rept re toose impeller cap & jam nuts on RRR Pump IA Caused by inadequacy of IR recommendation re IE Circular 79-19 Util has informed I-R that recommendation will not resolve problem PARKER, W O Duke Power Co 80/08/28 2pp

V Operator Examinations

- 8009240087 Requests detailed discussion & description of proposed licensed operator staffing plan projected through Dec 1983 by 800912 TEDESCO, R.L. Assistant Director for Licensing 80/09/03 3pp
- 8009240448 Discusses proposed licensed operator staffing plan Marked-up Yech Specs Table 6 2-1 re shift crew composition & breakfoun of total licensees, individuals in training & available min requirements for Sept 1980-Jul 1981 enct PARKER.W O Duke Power Co 80/09/18 6pp

DOCKET 50-373 LASALLE COUNTY STATION, UNIT 1

- A Application/construction stage documents & correspondence
- 8007080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl N/o NUREG EIBENHUT, D & Division of Licensing 80/08/01 117pp
- B009020126 Forwards request for add1 info re floodplain mgt per Executive Order 11988 Requests response completion schedule TEDESCO.R L. Division of Licensing 80/08/05 4pp
- 8009090631 Notification of cancellation of 800827 meeting w/BWR licensing review group to discuss concensus positions on TM1 issues (NUREG-0674) WILSOID / N Assistant Director for Licensing 80/08/04 lOpp

- 6009110420 Notification of 800915-19 meeting u/wtil at site to review control room design & operation BOURNIA.A Licensing Branch 1 60/08/25 3pp
- 8009110742 Notification of 800904-05 meeting w/Mart II owners group to discuss plants chugging C/O & lateral load specs
 ANDERSON-C Containment Systems Branch 80/08/29 14pp
- 8009;10715 Notification of 800923 meeting w/util in Bethesda, MD to discuss soil properties utilized in soil interaction analyses
 BOU-NIA, A Licensing Branch (80/09/03 3pp
- 8009180540 Notification of 800924 meeting w/util in Bethesda.MD to provide status of facilities requalification program for seismic qualification review teet BOURMIA:A Licensing Branch 1 80/09/08 3pp
- 8009180515 Forwards request for add1 into to complete evaluation of FSAR TEDESCO.R L Assistant Director for Licensing 80/09/10 7pp
- 8009160595 Informs of revised facility position on NUREO-0694, Task [I D 3 3 re portable iodine Enstrumentation One SAM & five Ping-Eberline iodine monitor sys will be available at site Equipment meets NRC requirements DEL GEORGE. L O Commonwealth Edison Co 80/09/11 1p
- 8009180404 Forwards "Chugging Loads for Assessment of 4TCO Data." Revision 1.suppl to containment design assessment rept Revision uithheld (seef 10CFR2 779) DELOEORGE.L O Commonwealth Edison Co 80/09/12 2pp
- 800926091 Notifies of 801007 proposed date to review whether DBE & SRV responses should be considered separately or combined during ASKE code fatigue calculations GE selected samples to emphasize highly fatigued components
 WILSON, J & Assistant Director for Licensing 80/09/15 9pp
- BO09260511 Forwards errata to suppl to "Chugging Loads for Assessment of 47CO Data." Revision 1 Revision withheld (ref 10CFR2 790)
 DELGEORGE.L O Commonwealth Edison Co 80/09/23 2pp
- F Security, medical, emergency & fire protection plans
- 8007100378 Forwards review of util generating station amergency plan & draft ltr requesting addl info & cormitments from util PAGAMO.F C Emergency Praparedness Licensing Branch 80/08/28 Spp
- 8009110400 Advises of acceptance of safeguards contingency plan submitted by 800324 ltr YOUNOBLOOD,D J Licensing Branch | 60/09/02 2pp
- 8009250489 Immediate action ltr re potentially deficient fire stop matl mgg by Tech-Sil.inc Lists products round to be in nonconformance w/project & NRC requirements & actions to be completed before leaded elastomer installation is continued KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/04
- G Inspection reports: JE Bulletins & correspondence
- 8009040517 Forwards IE Bulletin 80-07, Suppl 1, "BNR Jet Pump Assembly Failure" Response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/14
- 8009150022 Forwards JE Insp Rept 50-373/80-25 on 800520-23,27-30,0603-06 & 10-13 % notice of violation HEISHMAIR F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/07/24 Zpp
- --8007150024 Notice of violation from insp on 800920-23,27-30,0403-06 & 10-13 * Region 3, Chicago, Office of the Director 80/07/23 3pp
- --8009150025 IE Insp Rept 50-373/80-25 on 800520-23.27-30.0603-06 & 10-13 Moncompliance noted failure to complete procedure changes required to ensure that drywell pneumatic air on nitrogen bottles manifold vented during ILRT GTREETER.J Region 3. Chicago, Reactor Operations Muclear Support Branch MAURA.F. MCGREODR.L Region 3. Chicago, Office of the Director 80/07/23 12pp

- 8009180266 Forwards IE Insp Repts 50-373/80-29 & 50-374/80-18 on B00708-10 No nencompliance noted F10RELLI.0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/07/28 2pp
- --B009180280 IE Insp Repts 50-373/80-29 & 50-374/80-18 on 800709-10 Ha noncompliance noted Major areas inspected observation of work inside Unit 2 reactor pressure vessel, licensee actions re 10CFR30 55p items & IE bulletins NILLIAMS,C C . ERB,C M . NEISLER,J H Region 3. Chicago, Office of the Director 80/07/25 App
- 8009020109 Responds to IE Bulletin 79-03A, "Longitudinal Held Orfects in ASME SA-312. Type 304 Stainless Steel Pipe " SA-312 pipe not present in operating plants Final confirmation from suppliers anticipated by 800915 re const plant piping sys NAUOHTON, W F Commonwealth Edison Co 80/08/07 2pp
- 8009290462 Forwards IE lnsp Rept 50-373/80-31 on 800729-30 No noncompliance noted FIGRELLI, 0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/14 2pp
- --8009270465 IE Insp Rept 50-373/80-31 on 800729-30 No noncompliance noted Major areas inspected suppression pool modifollowup insp on deficiency unresolved items & observation of instrumentation installation records
 NEISLER.J H. WILLIAMS: C C Region 3. Chicago, Office of the Director 80/08/13 App
- B009030231 Forwards Rovision 1 to IE Bulletin B0-19, "Failures of Morcurg-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER. J G Region 3. Chicago, Office of the Director B0/08/15
- 8009110545 Responds to 1E Bulletin 80-08. "Exam of Containment Liner Penetration Welds." supplementing 800709 response Corrects Zion response re rings used for field circumferential butt weld Reviews accuracy of other statements ABEL,J 8 Commonwealth Edison Co 80/08/15 4pp
- 8009160681 Submits supplementary response to IE Bulletin BO-08. "Examination of Containment Liner Penetration Helds." correcting statement made in DL Peoples 800709 ltr Further review not necessary ADEL, J B Commonwealth Edison Cg 80/08/15 4pp
- 8009120038 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR" No written response required KEPPLER: J G Region 3. Chicago. Office of the Director 80/09/22
- 8009180551 Forwards 1E Circular 80-18. "IOCFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER.J O Region 3. Chicago, Office of the Director 80/08/22
- BOO9120538 Advises that insp exemptions were probably made on 27 pipelines under ASME Code.Seciton XI.1H3-1120 Method of analysis for exemptions was correctibut input assumptions were in error Values based on assumptions encl YCUNOBLOOD.B J Licensing Branch i 80/08/25 5pp
- B009180040 Forwards IE Insp Repts 50-373/80-32 ½ 50-374/80-20 on B00808-08 ½ notice of violation KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/27
- --8009188047 Notice of violation from insp on 800806-08 * Region 3. Chicago, Office of the Director 80/08/25 3pp
- --8009180094 IE Insp Repts 80-373/80-32 % 50-374/80-20 on 800806-08
 Noncompliance noted inadequate document control inadequate
 QA audits & surveillance lack of approved work procedures &
 lack of training program for contract personnel
 DANIELSON.D H Region 3. Chicago, Reactor Construction &
 Engineering Support Branch YIN, I T Region 3. Chicago. Office of
 the Director 80/08/25 6pp
- 8009230094 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover! 480 Volt Type K-600S & K-DON 6008 Circuit Breakers " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/08/28

- E009180466 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Identified relays are not used in facility No action required Twenty-four manhours expended on review RAUSCH.T J Commonwealth Edison Co 80/08/29 ip
- 9009190607 Responds to IE Bulletin 80-16 re potential misapplication of Rosemount pressure transmitters identified transmitters are not used in Byron & Braidwood safety-related areas LaSalle will comply w/requirements by defining mods by 801001 RAUSCH.T J Commonwealth Edison Co 80/08/29 2pp
- 8009250468 Supplemental response to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies" Deficient springs in actuators w/ Hasoneslian valves for safety-related applications will be replaced prior to shipment to site RAUSCH.T J Commonwealth Edison Co 80/08/29 3pp
- B009240133 forwards IE Circular B0-21, "Regulation of Refueling Crews" No written response required XEPPLER, J G Region 3, Chicago, Office of the Director 80/09/10 in
- B009300200 Forwards response to IE Bulletin 80~20 No Westinghouse Type W-2 control switches are used in safety-related sys at Dresden. Guad Cities & LaSalle County Responses for Zlon & Byron are encl RAUSCH.T J Commonwealth Edison Co B0/09/15 &pp.
- S Reportable occurrences: LERs & related correspondence
- 8009040399 PNO-111-80-153 on 800814.Region 3 to issue immediate action ltr confirming util cessation of onsite design & installation activities involving small bone pipe hangars action result of deficiencies identified in 800807-08 insp. KEI8LER. J H. WILLIAMS.C C. Region 3. Chicago. Office of the Director FIGRELLI.G. Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/08/14 1p
- 8009250489 lamediate action ltr re potentially deficient fire stop matl adg by Tech-Sil. Inc Lists products found to be in nonconformance w/project & NRC requirements & actions to be completed before leaded elastoner installation is continued KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/04 2pp
- 8009270379 Final interim deficiency rept re MSIV leakage control sys E32 being installed E23 equipment cannot meet functional requirements to relieve steamline pressure Mods being implemented & will be completed prior to fuel load DELQEORQE, L O Commonwealth Edison Co 80/09/19 2pp
- V Operator Examinations
- 8009300287 Forwards preiiminary topical outlines of proposed modules on thermal hydraulics & core damage mitigation to be included in revised reactor operator training program per 800328 request NAVOHTON. W F Communwealth Edison Co 80/09/15 7pp
- DOCKET 50-374 LABALLE COUNTY STATION, UNIT 2
- A Application/construction stage documents & correspondence
- BOO9080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT. D @ Division of Licensing 80/08/01 119pp,
- 8009020126 Forwards request for add1 info re floodplain mgt per Executive Order 11988 Requests response completion schedule TEDESCO.R.L Division of Licensing 80/08/05 4pp
- 8009110420 Notification of 800915-19 meeting w/util at site to review control room design & operation ECURNIA, A Licensing Branch I 80/08/25 3pp
- 8009110715 Notification of 800923 meeting w/util in Bethesda, MD to discuss soil properties utilized in soil interaction analyses BOUSNIA, A Licensing Branch 1 80/09/03 3pp
- 8009180540 Notification of 800924 meeting w/util in Bethesda, MD to provide status of facilities requalification program for seismic qualification review team EDURNIA:A Licensing Branch 1 80/09/08 3pp

- 8009180915 Forwards request for add1 info to complete evaluation of FSAR
 TEDESCO.R L Assistant Director for Licensing 80/09/10 7pp
- 8009160585 Informs of revised facility position on NUREG-0694. Task II D 3 3 re portable lodine instrumentation One SAM & five Ping-Eberline rodine monitor sys will be available at site Equipment meets NRC requirements DEL GEORGE.L O Commonwealth Edison Co 80/09/11 ip
- 8009180406 Forwards "Chugging Loads for Assessment of 4TCD Data," Revision tisuppl to containment design assessment rept Revision withheld (ref 10CFR2 790) DELGCDROE, LO Commonwealth Edison Co 80/09/12 2pp
- 80092605)! Forwards errata to suppl to "Chugging Loads for Assessment of 4TCD Data." Revision | Revision Cithheld (ref 106FR2 790)
 DELOEDROE.L O Commonwealth Edison Co 80/09/23 2pp
- F Security, medical, emergency & fire protection plans
- BO0925048? Immodiate action itr re-potentially deficient fire stop mating by Tech~Sil, inc Lists products found to be in nonconformance w/project > NRC requirements > actions to be completed before leaded elastomer installation is continued KEPPLER, J G Region 3, Chicago, Office of the Director 60/09/04
- 6007100378 Forwards review of util generating station emergency plan & draft ltr requesting addl info & commitments from util PAGAKO.F Q Emergency Preparedness Licensing Dranch 80/08/28 500
- 8009110400 Advises of acceptance of safeguards contingency plan submitted by 800324 ltr YOUNGBLOOD:8 J Licensing Branch 1 80/09/02 2pp
- B009040517 Forwards IE Builetin 80-07, Suppl 1, "BWA Jot Pump Assembly Failure " Response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/05/14
- 8007180246 Forwards 1E losp Repts 50-373/80-29 & 50-374/80-18 on 800708-10 No noncompliance noted FIGRELLIG Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/28 2pp
- --8009180280 IE Insp Repts 50-3/3/80-29 % 50-374/83-18 on 800708-10 No noticengliance noted Major areas inspected observation of work this for Unit 2 reactor pressure vessel, licensee actions re IDCFR50 55e items & IE bulletins
 WILLIAMS.C C. ERB.C M. NEISLER.J H. Region 3. Chicago, Office of the Director 80/07/25 App
- 8009020109 Responds to 1E Bulletin 79-03A. "Longitudinal Weld Defects in ASME 8A-312. Type 304 Stainless Beel Pipe " 8A-312 pipe not present in operating plants Final confirmation from suppliers anticipated by 800915 re const plant piping sys NAUOHTOM, W F Commonwealth Edison Co 80/08/07 2pp
- 8009030331 Forwards Revision I to IE Sulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Pawer Plants Designed by C-E "Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/15 ip
- B009110345 Responds to IE Bulletin 80-08. "Exam of Containment Liner Penetration Wolds," supplementing 800709 response Corrects Zion response re rings used for field circumferential butt weld Reviews accuracy of other statements

 ABEL.JS Commonwealth Edison Co 80/08/15 App
- 8009160681 Submits supplementary response to IE Bulletin 80-08, "Examination of Containment Liner Penetration Helds." correcting statement made in DL Peoples 800709 ltr Further review not necessary ABELUS Commonwealth Edison Co 80/08/15 4pp
- 8009123038 Forwards Suppl 3 to IE Bulletin 80-17, "Fallure of Control Rods to Insert During Scram at BUR" No written response required KEPPLER, J. G. Region 3, Chicago, Orfice of the Director 80/08/22 in

- 8009180551 Forwards IE Circular 80-18, "100FR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/22
- 8007120558 Advises that inspleremptions were probably made on 27 pipslines under ASME Code. Seciton 11. INE-1120 Method of analysis for exemptions was correct, but input assumptions were in error Values based on assumptions encl YOUNGBLOOD, B. J. Licensing Branch 1 80/08/25 5pp
- 8009180040 Forwards IE Insp Repts 50-373/80-32 & 50-374/80-20 on 800806-08 & notice of violation KEPPLER. J G Region 3. Chicago. Office of the Director 80/08/27
- ---8097180047 Notice of violation from insp on 800806-08 * Region 3, Chicago, Office of the Director 80/08 80/08/25 3pp
- --8009180054 IE lnsp Repts 50-373/80-32 % 50-374/80-20 on 800806-08 Noncompliance noted inadequate document control inadequate GA audits & surveillance lack of approved work procedures & lack of training program for contract personnel BAHBELSCH.D H Region D. Chicago, Reactor Construction & Engineering Support Branch YIN.I T Region D. Chicago, Office of the Director 80/08/25 App
- 8009230094 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Bovers 480 Volt Type K-6005 & K-DQN 6008 Gircuit Breakers " No written response required KEPPLERJ G Region 3. Chicago, Office of the Director 80/08/28
- 8009180456 Responds to IE Builetin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Identified relays are not used in tacility No action required Twenty-four manbours expended on review RAUSCH.T J Commonwealth Edison Co 80/08/29 1p
- 8009190907 Responds to JE Bulletin 80-15 re potential misapplication of Rosemount pressure transmitters Identified transmitters are not used in Byron & Braifwood safety-related areas Laballe will comply w/requirements by defining mods by 801001 RAUSCH-F J Commonwealth Edison Co 80/08/29 2pp
- 8009250468 Supplemental response to 1E Bulletin 80-09, "Hydramotor Actuator Deficiencies " Deficient springs in actuators w/ Masonellian valves for safety-related applications will be replaced prior to shipment to site
 RAUSCH: T J Commonwealth Edison Co 80/08/29 3pp
- 8009240133 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/09/10
- 8009300200 Forwards response to JE Butletin 80-20 No Westinghouse Type M-2 control switches are used in safety-related sys at Dresdem Ouad Cities & LaSaile County Responses for Zion & Commonwealth Edison Co 80/09/15 App
- 5 Reportable occurrences. LERs & related correspondence
- 8009230497 Immediate action itr re-potentially deficient fire stop matl mfg by Tech-Sii, Inc Lists products round to be in nonconformance w/project & NRC requirements & actions to be completed before leaded elastomer installation is continued KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/04
- 8009290399 Final interim deficiency rept re MSIV leakage control sys E32 being installed E23 equipment cannot meet functional requirements to relieve steamline pressure Mods being implemented & will be completed prior to fuel load DELCEORGE.L O Commonwealth Edison Co 80/09/19 2pp
- V Operator Examinations
- 8009300587 Forwards preliminary topical outlines of proposed modules on thermal hydraulics & core damage mitigation to be included in revised reactor operator training program per 800326 request NAUGHTON, H F Commonwealth Edison Co 80/09/15 7pp

- DOCKET 50-376 NORTH COAST NUC PLANT G Adjudicatory correspondence
- 8009040225 Motion for clarification of scope of single Issue to be tried in ASLO 800819 order re intervenor 800430 petition on lack of intention to build Draws attention to util inaction & contradictory actions W/Certificate of Svc FERNOS.0 Citizens for the Conservation of Natural Resources, Inc 80/08/27 3pp
- 8009040233 Motion for ruling on intervenor 800718 submission seeking legal assistance during hearings plus round trip travel & lodging expenses for counsel Certificate of Svc encl FERNUS. C Cittiens for the Conservation of Natural Resources. Inc 80/08/27 3pp
- B009110010 Motion advising of temporary substitution of author Requests incorporation of T Morales on svc list in absence W/Gertificate of Svc FERNOS, C Litizens for the Conservation of Natural Resources, Inc B0/09/03 2pp
- 8009110055 Interrogatories & request for production of documents directed to applicant Questions applicant financial statement re past & future total Investment in project Certificate of Svc encl FERNOS @ Citizens for the Conservation of Natural Resources, Inc 80/09/03 Spp
- 8009090411 Order granting extension until 800919 for Commission to review ALAB-605
 HDYLE, J C Office of the Secretary of the Commission 80/09/05
- 8009110065 Order denying part of Citizens for Conservation of Natural Resources 800827 motion for legal assistance from FY80 appropriations Funds may or may not be appropriated in FY81 Intervenor 800827 motion re intention to build denied HGLFE,S J Atomic Safety and Licensing Board Panel 80/09/08 28 80/09/08 2pp
- 8009110021 Interrogatories & requests for production of documents directed to Puerto Rico Water Resources Authority Requests info re islote site development & latest iong-range forecast for energy & peak load demands W/Gertificate of 8vc HCGURREM, H J Hearing Branch I 80/09/09 8pp
- 800916014B Motion for withdrawal of application for CP AXELRAD.M Puerto Rico Electric Power Authority AXELRAD.M Lowenstein.Newman.Reis.Axelrad & Toll 80/09/11 1p .
- --8009150151 Motion for termination of proceeding due to encl withfraual of application Certificate of Svc enci AXELRAD.M Puerto Rico Electric Power Authority AXELRAD.M Lowenstein, Newman, Reis, Azelrad & Toll 80/09/11 3pp
- 8009180564 Requests Commission take no action re ALAB-605 Intervenor must present case to ASLB before Commission acts to review ALAR-605 Intervenor counsel in hose until after Commission action deadline of 800919 Certificate of Svc encl CARDINA.T M Citiens for the Conservation of Natural Resources.Inc 80/09/13 2pp
- 8009260670 Motion for direct certification requesting that CP application be dismissed w/prejudice rather than accepting applicant withdrawal terminating proceeding Certificate of Svc encl FERNOS, G 80/09/17 Citizens for the Conservation of Natural Resources, Enc
- --8009260681 Addendum to 800917 motion for direct certification which requested that CP application be dismissed u/prejudice Applicant withdrawal evading direct confrontation w/issues raised & litigated for 5 yrs is unfair M/Certificate of Svc FERINDS, 0 Citizens for the Conservation of Natural Resources, Inc 80/09/18 2pp
- --8009260684 Motion for stay of proceeding until Commission rules upon direct certification seeking dismissal of application w/ prejudice Certificate of Svc enci FERNOS, Q Citizens for the Conservation of Natural Resources, Inc 80/09/18 2pp
- 8007230049 Response stating no opposition to util 800912 motion for termination of proceeding & withdrawal of application Certificate of Svc encil MCOURREN, HJ Hearing Branch 1 80/09/19 3pp

- BOO9253007 Advises that NRC does not intend to respond to Citizens for Conservation of Natural Resources BOO903 motion of temporary change of address unless advised to contrary by ASLB MCOURREN.H J Heating Branch 1 80/09/23 Ip
- BOO9250022 Forwards NRC Rules of Practice in response to BOO903 ltr Arrangements will be made for temporary availability of NRC lssuances in LPDR N/o encl MCCURREN.H J Hearing Branch 1 BO/09/23 1p
- 8009300439 Advises that intervenor answer to 800911 withdrawal of application & motion for termination of proceeding on behalf of PR Electric Power Authority, has not been received Certificate of Svc encl MOLFE, S J , COLE, R F Lowenstein, Newman, Reis, Axelrad & Toll 80/09/25 4pp
- 8009300462 Advises that util will not respond to discovery requests due to 800918 withdrawal of application Reserves right to file objections or motion for protective order if attempts are made to pursue proceeding Cortificate of Svc encl AXELBAD, M Lowenstein, Newman, Reis, Axelrad & Toll 80/09/25 4pp

DOCKET 50-378 CAORSD NUCLEAR STATION

- A Application/construction stage documents & correspondence
- 8009110742 Notification of 800904-05 meeting w/Mark II owners group to discuss plants chugging C/O & lateral load specs ANDERBON, C Containment Systems Branch 80/08/29 14pp

DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3

- A Application/construction stage documents & correspondence
- BOO9110565 Notification of GOO813 meeting w/util in Bethesda MD to discuss facility review status KAME, M Licensing Branch 2 80/07/22 2pp
- 8009080080 Forwards draft NUREO-0696, "Functional Critaria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedulo for meeting criteria of NUREO-0696 encl W/o NUREO EISENHUT, D O Division of Licensing 80/08/01 119pp
- 8009190010 Summary of 800813 meeting w/util in Bothesda.MD to discuss status of application for OL & potential problem areas KANE.W F Licensing Branch 2 80/08/26 5pp
- BO07240569 Forwards Mechanical Engineering Branch & ORNL status review re FSAR through Amend 8 & request for add1 info Util should prepare meeting agenda re resolution of open issues TEDESCO.R L. Assistant Director for Licensing 80/09/04 33pp
- BOO9230437 Forwards 800901 revised PWR const milestone & activities itst Const is 83% completo MAURIN.L V Louisiana Power & Light Co 80/09/19 8pp

ii General correspondence

- 8009190491 Notifies of organizational changes in util LV Maurin has been named facility project director Forwards organization chart Press release enci ASWELL.D L. Louisiana Power & Light Co 80/09/16 2pp
- --8009190494 Util organization chart
 * Arkansas Power & Light Co 80/09/16 tp
- @ Inspection reports, IE Bulletins & correspondence
- BO0917036B Completes response to IE Bulletin BO-O5 re spent resin tank Vent valve to vent gas collection header locked open except during resin transfer to prevent excessive vacuum conditions ASMELL.D L Louisiana Power & Light Co 80/07/11 lp
- BOO9170168 Forwards IE Insp Rept 50-382/80-12 on 800623-27.No noncompliance noted. MADSEN/0 L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/07/31 2pp
- --8009170172 IE insp Rept 50-382/80-12 on 800623-27 No noncompliance noted Major areas inspected operational staffing & overall preoperational test program CONSTABLE 6 L . KESTERMAN T F Region 4, Dailas, Office of the Director 80/07/31 3pp

- 8009190158 Submits response to IE Bulletin 79-03A Two pieces Type 300 series fusion welded pipe installed in containment spray sys Both pieces removed Subj pipe in storage will be removed from site ASWELL, O. L. Louisiana Power & Light Co. 80/08/06. 2pp
- 8009190153 Submits response to IE Bulletin 80-19 Reactor protective sys does not use mercury-wetted relays ASWELL.D L Louisiana Power & Light Co 80/09/09 1p
- 8009190333 Forwards IE Insp Rept S0-382/80-18 on 800728-31 No noncompliance noted SEIDLE N C Region 4. Dallas. Reactor Construction & Engineering Support Branch 80/08/13 3pp
- --8009190340 1E Insp Rept 50-382/80-18 on 800728-31 No noncompliance noted Major areas inspected welding activities on RCPB & other safety-related piping & installation of electrical of electrical cable CROSSMAN, M A Region 4. Dallas. Reactor Construction & Engineering Support Branch MALL.R & . GLOBERT, L D Region 4. Dallas. Office of the Director 80/08/12 & pp
- B0093000B9 Forwards IE Insp Rept 50-382/80-16 on 800722-25 No noncompliance noted SEIDLE: N C Region 4. Dailas. Reactor Construction & Engineering Support Branch 80/08/14 2pp
- --8009300096 IE Insp Rept 50-382/80-16 on 800722-25 No noncompliance noted Major areas inspected follow-on review of immediate action itr & previously identified unresolved items STEWART.R C , CROSSMAN W A Region 4. Dallas, Office of the Director 80/08/13 4pp
- 8007030266 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Marcury-Metted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E "Unitten response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/08/15
- 8009170397 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/08/22
- 8007120427 Forwards IE Info Notice 80-3(, "Maloperation of Could-Brown Bover(480 Volt Type K-600S & K-DON 600S Circuit Breakers " No written response required SEYFRIT.K V Region 4, Dalles, Office of the Director 80/08/27
- B009300092 Submits response to 1E Bulletin 80-16 Investigation of subj bulletin is still in progress Expects to submit final rept by B01020 ASHELL, D L Louisiana Power & Light Co 80/08/27 ip
- 8009170180 Forwards 1E Insp Rept 50-382/80-19 on 800611 No noncompliance noted KELLY.J A Region 4, Dallas, Office of the Director 80/08/29 1p
- --8009170183 IE Insp Rapt 50-382/80-19 on 800611 No noncompliance noted Major areas inspected plans for security & independent inspected plans for security & independent inspector CALDNELL, R A. KELLY, J A. Region 4. Dalles, Office of the Director 80/08/27 is
- B009300212 Submits response to 1E Bulletin 80-09 ITT General Controls Series AH-90 & NH-90 hydramotor actuators will be used in safety-related sys Problems are being investigated & corrective actions are being taken ASWELL,D L Louisiana Fower & Light Co 80/08/29 2pp
- 8009300100 Submits response to IE Bulletin 80-20 re failures of Westinghouse Type W-2 switches Investigation of subjubiletin is still in progress Expects to submit final rept by 801003
 MAURIN.L V Lovisiana Power 4 Light Co 80/09/09 ip
- 8 Reportable occurrences. LERs & related correspondence
- 8009300342 Notifies that util response to Potential Const Deficienty 27 re IIT General Control actuators will be addressed in response to IE Bulletin 80-09, "Hydrameter Actuator Deficiencies " Response will be completed by 800929 ASHELL, D.L. Louisiana Pawer & Light Co. 80/08/15 lp

- 8009300338 Final rept re Significant Const Deficiency 10 re defective emergency generator roller pins Roller pin diameter redesigned to provide interference fit at assembly between pin % crosshead & reduce clearance between pin & collor ORNICH J. MILHISER, R. J. HART, J. Louisiana Power & Light Co. 80/09/18 3pp
- 8009290394 Forwards final repts of Significant Const Deficiency & re emergency diesel generator sharts & springs & Significant Const Deficiency 10 re defective emergency diesel generator roller pins M/o Rept of Const Deficiency 10 ASNoLL-D L Louisiana Power & Light Co 80/09/23 19
- --800929039& Final rept of Const Deficiency & re defective shafts & springs for Cooper-Designer emergency diesel generators
 Caused by addl length on splined and of shafts & cracks in spring base metal New shaft fabricated & spring reworked HARTHETI,R A , CRNICH, J , Milhiser,R J Louisiana Power & Light Co 80/09/18 Jpp
- --8009290398 Part 21 rept re shaft defects in two emergency diesel generator sets supplied to Ebasco Svrs. Inc for util Caused by addi length in splined driven end of shafts Replacement will be completed by 780930 BENDER.B Cooper Industries, Inc., Cooper - Bessemer Co Div 78/07/25 2pp
- ---8009290401 Part 21 rept re spring defect in six emergency diesel generator sets supplied by Cooper Energy Svcs to nuclear facilities Caused by cracks in base metal resulting from electrolytic plating Spring will be replaced by 780930 BENDER. B B Cooper Industries, Inc. Cooper Energy Services Div 78/07/25 2pp
- DOCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1

 A Application/construction stage documents % correspondence
- 8009030285 Responds to 800417 request for info re NRC involvement in archeological data recovery activities for FY79 Completed questionnaire encl
 DENION, HR Office of Nuclear Reactor Regulation, Director 80/06/11 7pp
- --8009030314 Requests info re KRC involvement in archeological data recovery activities for FY79 & forwards questionnaire DELAPORTE.C T Interior.Dept of 80/04/17 4pp
- E0070B0080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 and M/o KireG EISENHUT, D G Division of Licensing 80/08/01 117pp
- 8009090831 Notification of cancellation of 800827 maeting w/BWR incomsing review group to discuss concensus positions on TMI issues (NUREG-0694) WILSON JN Assistant Director for Licensing 80/08/04 109
- 8009150498 Summary of 800821 meetings w/Brchtel,util,GE & Savannah River Plant in Dethesda.MD re FSAR open review items STARK.R M Licensing Branch | 80/08/26 App
- BO09080364 Documents agreements reached % actions to result from 800714-16 meeting w/NRC re draft 800421 SER & open items in FSAR Sections 36 & through 3 10 CURTIS.N N Pennsylvania Power & Light Co 80/08/28 105pp
- 8009110742 Notification of 800904-05 meeting w/Mark II owners group to discuss plants chugging C/O & lateral load space ANDERSON, C Containment Systems Branch 80/08/29 14pp
- E009120651 Notification of 800926 meeting w/util in Bethesda MD to discuss fuel load date STARKR M Licensing Branch l 80/09/04 lp
- --B009120660 Responds to NRC 80071; ltr re request for estimate of fuel load dates Primary sys fill & flush or Unit 1 completed & hydro & reactor internal vibration test near completion H/ 65% of plant sys in startup.completion by B10601 is likely CURTIS,N W Pennsylvania Power & Light Co 80/08/19 4pp
- 8009100484 Forwards request for add1 info re accident evaluation, needed for review of OL applications RM Start principal contact TEDESCO,R L Assistant Director for Licensing 80/09/05 4pp
- 6009180464 Summary of 800821 meeting ω/util in Bethesda.MD re forecasted fuel load date STARX.R M. Licensing Branch 1 80/09/05 3pp

- 8009150470 Forwards complete response to 8A Varga 800421 request for into on Category 1 masonry wells employed by plants under CP & OL review CP & CLTS.N W Pennsylvania Power % Light Co 80/09/08 8pp
- 8009160310 Forwards document used to establish recommended instrument nominal trip setpoints & Tech Specs limits per 800821 request CURTIS:R R Pennsylvania Power & Light Co 80/09/10 19pp
- 8009170290 Forwards ASME Boilor & Pressure Vessel Code, Section 3 overpressure rept per FSAR Question 211 204 CURTIS.N W Pennsylvania Power & Light Co 80/09/12 25pp
- 8009260091 Notifies of B01007 proposed date to review whether OBE & SRV responses should be considered separately or combined during ASMF code fatigue calculations GE selected samples to emphasize highly fatigued components
 WELSON J N Assistant Director for Licensing 80/09/15 9pp
- D NRC Braft/Final Environmental Statements, supply & correspondence
- 8009100082 Responds to 800626 itr requesting comments on enci K Spailone itr re potential impact of Pond Hill Reservoir dam failure Dam safety not under NRC review IRIC is reviewing potential environ impact of dam const & operation DIRCKS.W J Office of the Executive Director for Operations 80/08/18 3pp
- F Security, medical, emergoncy & fire protection plans
- 8009300669 Notification of 801027 meeting w/will in Berwick,PA to view status & configuration of electrical sys w/respect to electrical separation & fire protection STARK,R M Licensing Branch | 80/07/10 4pp
- Q Adjudicatory correspondence
- 8009120295 Requests time to make limited appearance statement at licensing hearings Requests to be informed when & where hearings will be held OAMRYCH.M A Affiliation Unknown 80/09/02 is
- 8009110787 Advises that NRC will not respond to applicants' 800822 motion for partial summary disposition of Contention i7 re orone issue Commission regulations allow only opposing replies CUTCHIN.J M Hearing Branch 3 80/09/08 lp
- 8009110016 Response in opposition to Environ Coalition on Nuclear Power 800822 request for free prehearing conferences transcripts prior to 800729 Does not oppose grant of transcripts of future resisions Certificate of Svc encl CUTCHIN.J M Hearing Branch 3 80/09/09 Spp
- 8009180394 Motion in opposition to applicant request for summary disposition of Contention 17 rc ozone Issue is of public interest I requires hearing Motion grant would prevent full litigation of Contention 17 M/Certificate of 8vc HALLIGAN,T J Citizens Against Nuclear Dangers 80/09/10 2pp
- 8009160414 Requests to make limited appearance statement at ticensing hearing for facility 4DROGNE.A Affiliation Unknown 8D/09/12 lp
- 8007270043 Decision, ALAD-613, denying Environ Coalition on Nuclear Power 800315 petition referred to ASLAB on 800516, re alleged ASLAB refusal to stop applicants discovery harassments Supporting documentation encl BISHOP, C J Atomic Safety and Licensing Appeal Panel 80/09/23 127an
- Q inspection reports, IE Audiatins & correspondence
- 8007070094 Forwards IE Bulletin 80-07, Suppl 1, "BWR Jet Pump Assembly Failure" No response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/05/13 1p
- 8007250297 Forwards IE Insp Repts 50-397/80-13 \$ 50-398/80-09 on 800602-05 No noncompliance noted CARLSGIRT T Region 1. Pailadelphia, Reactor Construction & Engineering Support Branch 80/07/11 2pp

- --8009290302 IE Insp Repts 50-387/80-13 > 50-288/80-09 on 800602-05 No noncompliance noted Major areas inspected installation of water supply & distribution systemater & gaseous suppression systematics, specs > drawings & GA program
 EBNETERS D Region 1, Philadelphia, Reactor Construction & Engineering Support Branch & ROLTAY, P S Region 1, Philadelphia, Office of the Director 80/07/08 7pp
- B00919023: Forwards 1E Insp Repts 50-387/80-10 & 50-388/80-06 on B00421-0516 & 27-30 No noncompliance noted CARLSON, R T Region 1. Philadelphia. Reactor Construction & Engineering Support Brench B0/07/15 2pp
- --8009190241 IE Insp Repts 50-387/80-10 & 50-388/80-06 on 800421-0516 & 27-30 No noncompliance noted Major areas inspected installation & wolding of RCPB & other piping & installation of safety-related components

 MCGAUGHY, R W Region 1: Philadelphia. Reactor Construction & Engineering Support Branch GALLO, R M. RHOADS. 0 G Region 1: Philadelphia. Office of the Director 80/06/30 17pp
- POG9100889 Forwards IE Insp Repts 50-387/80-15 % 50-388/80-10 on BOG623-27 No mencompliance noted CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/21 2pp
- --8009100893 IE insp Repts 80-387/80-15 & 50-388/80-10 on 800623-27 No noncompliance noted Major areas inspected licensee corrective action on previous inspected licensee work in progress DURR. J P Replon 1, Philadelphia, Office of the Director MCGAUGHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/16 Spp
- 8009120142 Responds to 1E Bulletin 80-03 Insps will be performed & results reported when charcoal adsorber cells are returned from manufacturer CURTIS.N W Pennsylvania Power & Light Co 80/07/30 1p
- BOO9190756 Respands to IE Bulletin 80-02 No equipment supplied by Marvin Engineering Co CURTIS N H Pennsylvania Power & Light Co 80/07/30 1p
- 8009190247 Ack receipt of 800721 ltr informing NRC of staps taken to correct violations noted in IE lnsp Rept 50-387/80-09 CARLSON R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/01 lp
- --9007170250 Responds to NRC 860607 itr re violations noted in IE lnsp Rept 50-387/80-07 Corrective actions more detailed instructions provided to weld examinors SABDL.A R Pennsylvania Power & Light Co 80/07/21 2pp
- --8007190294 Forwards IE Insp Rept 50-387/80-09 on 800422 & 0508-09 & notice of violation CARLSON.R T Region 1, Phlladelphia, Reactor Construction & Engineering Support Branch 80/06/09 2pp
- --8099190257 Notice of violation from insp on 800422 & 0508-09 • Region 1, Phlladelphia, Office of the Director 80/06/02 lp
- --8009190239 IE Insp Rept 50-387/80-09 on 800422 & 0508-09 Noncompliance noted failure to follow approved procedure during ultrasonic examination of piping welds TRIPP.LE Region 1. Philadelphia, Reactor Construction & Engineering Support Branch MCDREARTY, R A Region 1. Philadelphia, Office of the Director 80/06/02 Spp
- 8009070516 Responds to IE Bullatin BO-08, "Examination of Containment Liner Penetration Welds " Flued head design utilized for piping penetrations illustrated in Figure NE-1120-1 Electrical penetration design is illustrated in encl CURTIS N W Pannsylvania Power & Light Co. 80/08/07 24pp
- 8009190264 Ack receipt of 800728 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/80-04 & 50-388/80-02 CARLSDN: R Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/11 ip
- --8009190271 Responds to NRC 800529 ltr re violations noted in IE Insp. Repts 50-387/80-04 & 50-388/80-02 Corrective actions all weld filler math certifications to be reviewed in accordance w/89AM BABOL.A R Pennsylvania Power & Light Co 80/07/28 3pp
- --B009190277 Forwards IE Insp Repts 50-387/80-04 \$ 50-388/80-02 on B00303-0312 & 0320-0418 \$ notice of violation CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/29 2pp

- --8009190282 Natice of violation from insp on 800303-0312 & 0320-0418 * Region i, Philadelphia, Office of the Director 80/05/28 ip
- ~~8009190288 IE Insp Repts 50-387/60-04 & 50-388/80-02 on 800303-0312 & 0320-0418 Noncompliance noted failure to document chemical analysis of weld filler mat!

 # Region), Philadelphia, Reactor Construction & Engineering Support Branch 80/05/28 H4pp
- 8009030086 Forwards Revision 1 to IE Bulletin 80-19. "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/08/15 1p
- 8009070036 Responds to [E Bulletin 79-036, "Longitudinal Neld Defects in ASME 86-312. Type 304 Stainless Steel Pipe " Pipe is not used in safety-related sys subjected to design stress greater than 894 CURTIS:N W Pennsylvania Power & Light Co 80/08/15 1p
- 8009120109 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insort During Scram at BUR" No written response required GRIER.B H Region 1, Philadelphia, Office of the Director BO/08/22 to
- 8009180037 Forwards IE Circular 80-18, "IOCFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GRIER, BH Region 1, Philadelphia. Office of the Director
- 8009120204 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-600S & K-DON 600S Circuit Breakers " No written response required GRIER.B H Region I. Philadelphia, Office of the Director 80/08/27 ip
- 8009240115 Forwards IE Circular 80-21, "Regulation of Refueling Crews " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/09/10 to
- 8009240328 Forwards lE info Notice 80-32. "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matis " No written response required GRIER.B H Region 1, Philadelphia. Office of the Director 80/09/12 ip
- S Reportable occurrences, LERs & related correspondence
- 8009090630 Ack receipt of 800703 interim rept re deficiency on Pacific check valves CARLSON.R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/09/01 Ip
- ---8009090454 Interim rept re deficiency on Pacific check valves Problems w/valve operation in Unit i core spray pump discharge vertical pipe run necessitate bonnet stops rework Final rept appected by Sept 1980 CURTIS:N W Pennsylvania Power & Light Co 80/07/03 2pp
- 8009110401 Ack receipt of 800721 final deficiency rept re improper sloping of GE piplng & tubing CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/01 lp
- ---B007110414 Final deficiency rept re Improper sloping of GE piping b tubing As-built drawings will be revised to include actual slope of Installed pipe CURTIS.N W Pennsylvania Power & Light Co B0/07/21 4pp
- 8009120128 Ack receipt of 800722 interim rept re deficiency in pipe support design drawing released for fabrication 2 installation CARLSON: T Region 1. Philadelphia, Reactor Construction & Englneering Support Branch 80/08/01 lp
- 8009120711 Ack receipt of 800723 interim deficiency rept re improper safety classification for solenoid valve CARLBOM,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branca 80/08/01 lp
- 8007120704 Ack receipt of 800707 Interim deficiency rept to cracks in Anchon-Darling valve yokes CARLSON,R T Region I. Philadelphia. Reactor Construction & Engineering Support Branch 80/08/04 lp

- 8009090472 Final deficiency rept re nonconforming ICO-Rally, Type SLV-1200 biaided riberglass sleeving used as barrier matl for electrical separation Caused by inadequacy of Bechtel recommendation authorizing field purchase CURTIS, N H Pennsylvania Power & Light Co 80/09/05 4pp
- DOCKET 50-388 SUSGUCHANNA STEAM ELECTRIC SYATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8009030285 Responds to 800417 request for info re NRC involvement in archeological data recovery activities for FY79 Completed questionnairs enci OENION, R Office of Nuclear Reactor Regulation, Director 80/06/11 7pp
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 enci N/o NUREG EISENHUT, D G Division of Licensing 80/08/01 L19pp
- 8009150498 Summary of 800821 meetings w/Gethtel.util.GE & Savannah River Plant in Bethesda.KD re FSAR open review items STARK.R M Licensing Branch 1 60/08/26 App
- 8007080364 Documents agreements reached & actions to result from 800714-16 meeting w/NRC re draft 800421 8ER & open items in FSAR Sections 3 6 through 3 10 CURTIS:N M Pennsylvania Power & Light Co 80/08/28 105pp
- 8009110742 Notification of 800904-05 meeting u/Mark il owners group to discuss plants chugging C/O & lateral load specs ANDERSOLL C Containment Systems Branch 80/08/29 14pp
- 8009120591 Notification of 800926 meeting w/util in Bethesda MD to discuss fuel load date STARK,R M Licensing Branch! 80/09/04 1p
- --E009120560 Responds to NRC E00711 ltr re request for estimate of fuel load dates Primary sys fill & flush of Unit 1 completed & hydro 3 reactor internal vibration test near completion W/65% of plant sys in startup.completion by E10501 is likely CURTIS,N W Pennsylvania Power & Light Co 20/08/19 4pp
- 8039100484 Forwards request for add1 info to accident evaluation, needed for review of OL applications RH Start principal contact TEDESCOR i Assistant Director for Licensing 80/09/05 4pp
- 8007180464 Summary of 800821 meeting w/otll in Bethesda. MD re forecasted fuel load date STARK R M Licensing Branch & 80/09/03 3pp
- 8009150470 Forwards complete response to SA Varga 800421 request for info on Category I masonry walls employed by plants under CP & OL review
 CUSTIS-N W Pennsylvania Power & Light Co 80/09/08 Epp
- 8009160310 Forwards document used to establish recommended instrument nominal trip setpaints? Tech Specs limits per 800821 request CURTIS.N W Pennsylvania Power & Light Co 80/09/10 19pp
- 8009170290 Forwards ASME Boiler & Pressure Vessel Code, Section 3 overpressure rept per FSAR Question 211 204 CURTIS. N W Pennsylvania Power & Light Co 80/09/(2 25pp
- F Security, medical, emergency & fire protection plans
- 8009300659 Notification of B01027 meeting w/util in Herwick, PA to view status 5 configuration of electrical sys w/respect to electrical separation & fire protection
 STARK.R is Licensing Branch 1 80/09/10 4pp
- G Adjudicatory correspondence
- 8009120275 Requests time to make limited appearance statement at licensing hearings Requests to be informed when & where hearings will be held GARMYCH, H A Affiliation Unknown 80/09/02 1p
- 8009110787 Advises that NRC will not respond to applicants' 800822 motion for partial summary disposition of Contention 17 records issue Commission regulations allow only opposing replies CUTCHIN. J K Hearing Branch 3 80/09/08 ip

- 8009110016 Response in opposition to Environ Coalition on Nuclear Power 800922 request for free prehearing conferences transcripts of prior to 800725 Does not oppose grant of transcripts of future sessions Certificate of Svc encl CUTCHIN-J K Hearing Branch 3 80/09/09 5pp
- 8009180394 Motion in opposition to applicant request for summary disposition of Contention 17 re of one Issue is of public interest & requires hearing Motion grant would prevent full litigation of Contention 17 W/Certificate of Svc HALLIGAN.T J Citizens Against Nuclear Dangers 80/09/10 2pp
- 8009160414 Requests to make limited appearance statement at licensing hearing for facility GURGONE. A Affiliation Unknown 80/09/12 ip
- 8009290043 Decision, ALAB-613, denying Environ Coalition on Nuclear Power 800315 petition referred to ASLAB on 800916, re alleged AELAB refusal to stop applicants discovery harassments Supporting documentation encl BISHOP, C J Atomic Safety and Licensing Appeal Panel 80/09/23 12700
- Q Inspection reports, IE Bulletins & correspondence
- 8009090094 Forwards IE Bulletin 80-07, Suppl 1, "BNR Jet Pump Assembly Failure " No response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/05/13 | 1p
- 8009250299 Forwards IE Insp Repts 50-387/80-13 % 50-388/80-09 on 800602-05 No noncompliance noted CARLSON,R T Region in Philadelphia, Reactor Construction & Engineering Support Branch 80/07/ii 2pp
- --8009250302 IE Insp Repts 50-387/80-13 & 30-388/80-09 on 800602-05 No moncompliance noted Major areas inspected installation of water supply & distribution sys,water & gaseous suppression sys, specs & drawings & GA program EDMETER. B D Region 1. Philadelphia, Reactor Construction & Engineering Support Branch KOLTAY,P B Region 1. Philadelphia, Office of the Director 80/07/08 7pp
- B007170231 Forwards IE Insp Repts 50-387/80-10 & 50-388/80-06 on B00421-0316 & 27-30 No noncompilance noted CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/15 2pp
- --B009190241 IE Insp Repts 50-397/80-10 % 50-359/80-06 on 800421-0316 & 27-30 No honcompliance noted Major areas inspected installation & welding of RCPB & other piping & installation of safety-related components MCGAUGHY.R W Region i. Philadelphia. Reactor Construction & Engineering Support Branch GALLO,R M , RMOADS.0 O Region 1. Philadelphia. Office of the Director 80/06/30 17pp
- 6007100889 Forwards IE Insp Repts 50-387/80-15 & 50-388/80-10 on BOO&23-27 No noncompliance noted CARLSON-R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/21 2pp
- --8009100893 IE Insp Repts 50-387/80-15 & 50-383/80-10 on 800623-27 No noncompliance noted Major areas inspected licensus corrective action on previous insp results. OC. equipment storage & work in progress DURR. J.P. Region I. Philadelphia. Office of the Director MCGAUGHYR W. Region I. Philadelphia. Reactor Construction & Engineering Support Branch 80/07/16 Spp
- 8009120142 Responds to IE Bulletin 60-03 Insps will be performed a results reported when charcoal adsorber cells are returned from manufacturer CURTIS.N W Pennsylvania Power & Light Co 80/07/30 lp
- 8009190956 Responds to IE Bulletin 80-02 No equipment supplied by Marvin Engineering Co CURTIS-N W Pennsylvania Power & Light Co 80/07/30 lp
- 8009090616 Responds to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds " Flued head design utilized for piping genetrations illustrated in Figure NS-Fi20-1 Electrical penetration design is illustrated in encl CURTIS.N N Pennsylvania Power & Light Co 80/08/07 24pp
- 8009190264 Ack receipt of 800728 itr informing NRC of steps taken to correct violations noted in IE inep Repts 30-387/80-04 & 30-368/80-02 CARLEON, R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/08/11 lp

- --8009190271 Responds to NRC 800529 itr re violations noted in 16 Imag Repts 50-387/80-04 & 50-388/80-02 Corrective actions all weld filler math certifications to be reviewed in accordance w/80AM SABOLLA R Pennsylvania Power & Light Co 80/07/28 3pp
- --8009190277 Forwards IE Insp Repts 50-387/80-04 & 50-388/80-02 on 800303-0312 & 0320-0418 & notice of violation CARLEON.R T Region J. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/29 2pp
- --8009190282 Notice of violation from inep on 800303-0312 & 0320-0418 * Region 1, Philadelphia: Office of the Director 80/05/28 1p
- --800919028B IE Insp Repts 50-387/80-04 & 50-388/80-02 on B00302-0312 & 0320-0418 Noncompliance noted failure to document chemical analysis of weld filler mati a Region 1, Philadelphia, Reactor Construction & Engineering Support Branch B0/05/28 14pp
- 8009030086 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Hercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER.8 H Region 1, Philadeiphia. Office of the Director 80/08/15 lp
- 8009090036 Responds to IE Bulietin 79-03A. "Longitudinal Weld Defects in ASME BA-312. Type 304 Stainless Steel Pipe " Pipe is not used in safety-related sys subjected to design stress greater than 85% CURTIS-N W Pennsylvania Power & Light Co 80/08/15 1p
- 9009120109 Forwards Suppl 3 to 1E Suiletin SO-17. "Failure of Control Rods to Insert During Scram at BWR " No written response required. GRIER.B H Region 1. Philadelphia. Office of the Director 60/08/22 ip
- 8009180037 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/08/22, 1p
- 6009120204 Forwards IE Info Notice 80-31, "Maloperation of Quald-Brown Bover: 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers "
 No written response required GRIER, B H Region 1. Philadelphia, Office of the Director 80/08/27, p
- 8009240115 Forwards IE Circular 80-21, "Regulation of Refueling Craws " No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/09/10
- 8009240328 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matis " No written response required GRIER BH Region I, Philadelphia, Office of the Director 80/09/12 1p
- S Reportable occurrences. LERs & related correspondence
- 6009090550 Ack receipt of 800703 interim rept re deficiency on Pacific check valves CARLEDNAR.T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/01 1p
- --BOOTO90454 Interim rept re deficiency on Pacific check valves Problems
 w/valve operation in Unit 1 core spray pump discharge
 vertical pipe run necessitate bonnet stops rework Final rept
 expected by Sept 1980
 CURFIS.N W Pennsylvania Power & Light Co 80/07/03 2pp
- 009110401 Ack receipt of 800721 final deficiency rept re leproper sloping of GE piping & tubing CARLSOM.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/08/01 1p
- -BOO9:10414 Final deficiency rapt re improper slaping of GE piping & tubing As-built drawings will be revised to include actual slape of installed pipe CURTIS.N & Pennsylvania Power & Light Co 80/07/21 4pp
- 009[20]28 Ack receipt of 800722 interim rept re deficiency in pipe support design drawing released for fabrication & installation CARLSON.R T. Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/01 ip

- 8009120711 Ack receipt of 800723 interim deficiency rept re improper safety classification for solenoid valve CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/01 1p
- 8009120704 Ack receipt of 800707 interim deficiency mept me cracks in Anchor-Darling valve yokes CARLSON,R T Region I. Philadelphia, Reactor Construction & Engineering Support Branch 80/08/04 19
- 8009090472 Final deficiency rept to noncontorming ICO-Raily, Type SLV-1200 braided fiberglass sleeving used as barrier motl for electrical separation Caused by inadequacy of Bechtel recommendation authorizing field purchase CURTIS.N W Pennsylvania Power & Light Co 80/09/05 4pp
- DOCKET 50-389 ST LUCIE PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8009080080 Forwards Graft NUREG-0696. "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl 4/o NUREG EISENHUT,D G Division of Licensing 80/08/01 119pp
- R009090842 Requires submittal of ATMS emergency operating procedure for NRC review by 80:019 Generic analysis should confirm ATMS mitigation capability described in NUREO-0460, Vol 3 Commission will determine required mode & schedules TEDESCO,R L Assistant Director for Licensing 80/08/25 3pp
- 8009090851 Requests that info on chemical formulation & quantity of NUKEM 750 to be used as expansive joint filler inside containment be provided by 800910
 TEDESCO.R L Assistant Director for Licensing 80/08/25 29p
- 8009030633 Submits info requested in NRC 800711 ltr re up-to-date const completion schedules Facility will be ready for fuel loading in Nov 1982 Three oversize photographs & supporting documentation encl
 UHRIGR E Florids Power & Light Co 80/08/26 15pp
- BOOTGDOO43 Notification of time change for BOOTIB meeting w/util in Bethesda.MD to discuss schodule & staff review of application Meeting will be hald at 11 00 AM BIRKEL.R A Licensing Branch 1 89/07/09 3pp
- B009300667 Notification of B00918 meeting w/util in Bethesda.MD to discuss schedule & NRC review of application BIRKEL,R A Licensing Branch 1 B0/09/09 3pp
- 8009150262 Responds to NRC 800825 ltr re use of NUKEM 750 as expansion joint filier inside containment Includes chemical formulation of NUKEM 750 & quantity used inside containment UHRIO.R E Florida Power & Light Co 80/09/10 ip
- BOO9300105 Forwards Amend 1 to CPPR-144, incorporating conditions to alleviate loss of ac power in event of station blactout Notice of issuance & availability of decision encl YOUN0BLOOD, B of Licensing Branch 1 80/09/18 2pp
- --8009300i08 Amend 1 to CPPR-144, incorporating conditions to alleviate loss of ac power in event of station blackout YGUNOBLDOD, 8 J Licensing Branch 1 80/09/18 ip
- F Security, medical, emergency & fire protection plans
- 8009230261 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network, Sys installed for got use during emergency O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/22
- G Adjudicatory correspondence
- 8007040355 Order granting extension until 800715 for Commission to review ALAB-603 CHILK.S J. Office of the Secretary of the Commission 80/08/27
- BOO9190279 Responds to FOIA request for 15 documents listed in bibliography fo NUREG-0625, "Rept of Siting Policy Task Force" Documents 6-8 t 13 are available in PDR Forwards remaining documents FELTON, J K Division of Rules and Records 80/09/04 ip

- --8007190537 Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants, nor determination or site acceptability & adequaty of engineered safery features HINDIVE R B Office of Standards Development, Director SEC:-77-342 79/06/04 7pp
- --8007190633 Requests that encl "Differences in Procedures for Estimating Atmospheric Dispersion Conditions at Injand & Coastal Sites," be sent to appropriate Boards SCINTO.JF Hearings Division 79704704 16pp
- BCO9180546 Order extending time until 800929 in which Commission may act to review ALAB-603 CHILKIS J Orrice of the Secretary of the Commission 80/09/15 1p
- 8509260459 Memorahdum to counsels disclosing past involvement as AEC Deputy Director of Technical Review Previous involvement w/ 5t Lucie Units 1 & 2 has not prejudiced objectivity Objections will be considered if filed by 801002 HEMURIE. J H Commission 80/09/19 2pp
- 8009260009 Forwards Amend I to CPPR-144 & notice of issuance & availability in reaponse to ALAB-603
 PATON W D Hearing Branch 4 E0/09/23 1p
- --8007260012 Amend 1 to CPPR-144 incorporating Paragraph 3 Hyre consideration of total loss of ac power as DBE YOURJECOOD B J Licensing Branch 1 80/69/18 1p
- --8009260013 Notice of issuance & availability of Amend I to CPPR-144 YOUNG8LOOD.B J Licensing Branch I 80/09/18 2pp
- 8009260463 Order granting extension until 801006 for Commission to elect whether to review ALAB-603 CHILK.S J. Office of the Secretary of the Commission 80/09/24

M Antitrust correspondence

- B009020131 Advises that Cormission has received add1 antitrust advice from Atty General re CP application No antitrust hearing necessary for proposed amend to CP SALTIMAN J Utility Finance Branch B0/08/05 2pp
- B009110013 Ack rereipt of FL Cities B00822 ltr re draft settlement reached by utilipUJ & NRC Final settlement addresses intervenor concerns SHAPARIM K Diffice of the Executive Legal Director B0/09/08 lp
- 8009220221 Forwards FL Cities comments be advice ltr concerning util Orlando settlement JABLDM:R A Spiegel & McDiarrid 80/09/10 1p
- --B00922022 Comments concerning util Orlando settlement FL Cities prepared to show by argument 5 evidence that grant of unconditioned license to util would create or maintain situation inconsistent w/antitrus+ laws

 JASLONAR A . ROTH.A J Florida Cities JABLONAR A Spiegel & McDiarrid 80/09/10 3pp
- --800922023 Comments concerning notice of withdraual of intervention by Orlando utils As procedural matter, motion would be necessary for Orlando to withdraw Certificate of Svt encl JABLON, R A Foliar A College Cartificate of Svt encl JABLON, R A Spiegel & McDiarmid B0/07/07 5pp
- 8009160033 Joint motion for approval & authorization to implement encl stipulation re license conditions Urges immediate effect w/o prejudice to different or addl conditions that day be imposed after hearing FL Cities must specify objections URBAN. J R Justice. Dapt of DEHEV, L S Antitrust Division DYM, H Florida Power i Light Co 80/09/12 3pp
- --BC07160041 Stipulation reflecting util consent to incorporate encl license conditions w/o prejudice to addi or different conditions that may be imposed after hearing Stipulation does not constitute admission of guilt H/Certificate of Svc URBAN.J R Justice. Dept of DEMEY.L S Antitrust Division DYM, H Florida Power & Light Co 80/07/12 35pp
- BOO7:70162 Motion supported by DOJ & RRC. For suspension of responses to interrogatories DOJ. NRC & util settlement may affect procedures Certicate of Svc encil JABLON.R A DYH, H Flortda Cities JABLON.R A Sprend & RCDiarmid BO/09/15 3pp

- B009190091 Motion before US Court of Appeals for DC Circuit, for especiated consideration of petition for review re consolidation of Civil Action B0-1099 w/administrative proceeding W/Certificate of Svc Related correspondence JABLON, R A. LANDEMAN, R M. Florida Cities JABLON, R A. Spiegel & McDiarmid B0/09/15 Spp
- 8009260653 Order granting FL Cities & Dts: 800915 joint motion to suspend interrogatory responses Request Unopposed by remaining parties
 SMITH.I W Abomic Safety and Licensing Board Panel 80/09/22 lp
- 8009300476 Response before US Court of Appeals for DC Circuit, in opposition to petitioners' motion for expedited cansideration of Civil Action 80-1099 Certificate of Svc encl Related correspondence DYM.H Florida Power & Light Co BDUKNIGHT, J A Lawenstein, Newman, Reis, Azelrad & Toll 80/09/25 5pp

P Operating license stage documents & correspondence

- B009040490 Responds to NRC B00728 ltr requesting opinion & advice repotential void formation in vessel head Phonomena is unaffected by relatively small differences in fuel design Company would not analyse event unless asked by customer ORSLEY.0 F Exxon Nuclear Co , Inc (subs of Exxon Corp) 80/08/26 1p
- O Inspection reports. IE Bulletins & correspondence
- 8009100130 Forwards 1E Insp Rept 50-387/80-08 on 800604-06 & notice of viglation MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/06/23 2pp
- --8007100146 Notice of violation from insp on 800604-06
 Region 2, Atlanta, Office of the Director 80/06/20 ip
- ~~8007100147 IE Insp Rept 50~389/80~08 on 800604-06. Noncompliance upted inadequate procedural controls on sand-cement fill CONLON.T E Region 2. Atlanta. Reactor Construction & Engineering Support Branch HARRIS.J R Region 2. Atlanta. Diffice of the Director 80/06/20 4pp
- 8009240066 Forwards IE Insp Repts 30-339/80-23 & 50-389/80-09 on 800715-18 No noncompilance noted MMRPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/08/05 2pp
- --8009240071 IE Insp Repts 30-335/80-23 & 50-389/80-07 on 800713-10 No noncompliance noted Major areas inspected records associated w/work performance during outage in areas of installation welding, weld red control & core drilling VANDOURN,P & Region 2, Atlanta, Office of the Director HERDT,A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/04 App
- 8009030158 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director E0/08/1:
- 8009160143 Forwards IE Circular 80-18, "IOCFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22
- 8009240174 Responds to IE Bulletin 80-16, "Potential Misapplication of Rosemount, Inc Models 1151 & 1152 Pressure Transmitters w/ Either A or D Dutput Codes " Transmitters are not installed in any safety-related applications
 UHRIG.R E Florida Power & Light Co 80/08/26 ip
- 8009120308 Forwards IE Info Notice 80-31, "Maloperation of Qould-Brown Boveri 480 Voit Type K-6003 \$ K-DON 6005 Circuit Breakers " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/27
- 8009110493 Responds to IR Bulletin 80-19 Mercury-webted relays not used in logic matrix of reactor protective sys UHRIGIR R Florida Power & Light Co 80/08/29 1p
- 8009290277 Forwards IE Circular 80-21. "Regulation of Refueling Craus" No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/09/10 Dap

- BOO9300040 Submits response to IE Bulletin 80-30 re Westinghouse W-2 control switches investigation is still in progress & complete response is expected by 901014
 URRIG:R E Florida Power & Light Co 80/09/15 ip
- S Reportable occurrences. LERs & related correspondence
- BOO9100585 Final deficiency rept re cracked & broken electrical penetration connections Caused by poor assembly techniques Supplier will develop repair procedures & repair & replace fractured ring tongue connectors

 UHRIGORE Florida Power & Light Co 89/08/06 4pp
- DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- 80090800B0 Forwards draft NUREC-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREC-0696 encl W/o NUREC EISENHUT, D G Division of Licensing 80/08/01 119pp
- 80D9040467 Forwards matl re NRC review of ice condenser containment & hydrogen control measures for Sequoyah Nuclear Power Plant ACRS has scheduled meetings in Washington, DC on 800828, 0902 & 04 to discuss issue
 TEDESCO,R L Assistant Director for Licensing 80/08/22 2pp
- 8009300400 Forwards technical questions re implementation of interim policy on 10CFR90 & 51 MILLS.L di Tennessee Valley Authority 80/09/23 3pp
- F Becurity, medical, emergency & fire protection plans
- BOO91204BB Forwards "Watts Bar Nuclear Plant Units 1 & 2 Fire Protection Submittal:" in response to NRC 79010B request for addl info MILLS.L M Tennessee Valley Authority 80/09/09 400pp
- J Financial Information
- 8009090543 Forwards Annual Financial Rept 1979 CROSS.J L Tennessee Valley Authority 80/09/04 ip
- M. Utility Final Safety Analysis Report (FSAR) & amends
- 8Q09020074 Forwards Amend 41 addendum to FSAR Enc1 matt imadvertently omitted from 800430 submittal MILLS.L M Tennessee Valley Authority 80/08/26 19
- --8009020097 Addendum to Amend 41 to FSAR
 * Tennessee Valley Authority 80/08/26 100pp
- 8009030574 Forwards affidavit cartifying that Amend 41 addendum to FSAR was mailed to BA Osborne, D Waid & JE Hagan on 800826 MILLS.L M Tennessee Valley Authority 80/08/26 2pp
- a inspection reports, IE Bulletins & correspondence
- 8009030032 Forwards IE Insp Repts 50-390/80-18 & 50-391/80-11 on 800625-27 No noncompliance noted MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/17 2pp
- --8007030040 IE Insp Repts 50-390/80-18 & 50-391/80-11 on 800625-27 No noncompliance noted Major areas inspected const activities, deficiency repts handling & storage of piping & GA audits CANTRELL, F S Region 2, Atlanta, Reactor Construction & Engineering Support Branch THOMAS, M Region 2, Atlanta, Office of the Director 80/07/16 4pp
- 8009100063 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/07/24 19
- 8009030257 Ack receipt of 800723 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-390/80-08 LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/08/04 ip

- --8009030260 Responds to NRC 800626 lfr re violation noted in IE Insp Rapt 50-370/80-08 Corrective actions craft supervision re-emphasized 5 addl craftsmen assigned to check work areas daily MILLS.L M. Tonnessee Valley Authority 80/07/23 2pp
- --8009030264 Act receipt of 8006;0 ltr informing NRC of steps taken to correct violation noted in 1E Insp Rept 50-390/80-08 Requests add1 info re piping sys cleanliness LEWIS.R C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/06/26 lg
- --8009030270 Forwards IE Insp Rept 50-390/80-08 on 800324-26 & notice of violation LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/03/02 2pp
- --8009030274 Notice of violation from insp on 800324-26

 # Region 2, Atlanta, Office of the Director 80/05/02 2pp
- --8007030251 IC Insp Rept 50-390/80-08 on 800324-26 Noncompliance noted failure to maintain adequate lubrication procedure to ensure valve lubrication prior to initial valve operation ASHENDEN, M.C. Region 2. Atlanta, Office of the Director DANCE, H.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/05/02 4pp
- 8009020214 Forwards response to IC Bulletin 79-03A No SA-312 & A-312, Type 300 series fusion welded pipe used or planned for use in safety-related sys at greater than 85% design stress except Natts 3ar Matl under investigation at Watts Bar MILLS, L M Tennessee Valley Authority 80/08/05 2pp
- 8007070802 Responds to IF Sulletin 77-03A. "Longitudinal Weld Defects in ASME 6A-312 Type 304 Stainless Steel Pipe " Use of matis still under investigation for sys supplied by NSSS vendor MILLS.L II Tennessee Valley Authority 80/08/05 2pp
- B009020303 Forwards IE Insp Repts 50-327/80-24.50-328/80-15, 50-390/80-20, 50-391/80-14.90-438/80-13.50-439/80-13, 50-9318/80-11, 50-518/80-11, 50-520/80-11, 50-521/80-11, 50-523/80-11, 50-523/80-11, 50-524/80-10, 50-566/80-10, 50-567/80-10
- ~-8009020312 Natice of violation from insp on 800707-(1 * Region 2: Atlanta, Dffice of the Director 80/08/06 App
- --8007020337 1C Insp Repts 50-327/80-24,50-328/80-15,50-390/80-20, 50-391/80-14,50-438/80-13,50-439/80-13,50-519/80-11, 50-519/80-11,50-519/80-11,50-553/80-11,50-554/80-10,50-564/80-10 & 50-567/80-10 an 800707-11 SROUNICE, V. MODENOS, L. Region 2, Atlanta, Diffice of the Director CUNLON, T.C. Region 2, Atlanta, Reactor Construction & Engineering Support Blanck 80/08/06 24pp
- 8009030146 Forwards Revision 1 to IE Bulletin 80~19, "Failures of Morcury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required D'REILLY, J.P. Region 2. Atlanta, Diffice of the Director 90/08/15
- 8009160153 Forwards IE Circular 80-18, "LOCFR50 59 Safety Evaluations for Changes to Radwaste Troatment Sys ' No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22 in
- 8009120340 Forwards IC Info Notice 80-31, "Majoperation of Gould-Brown Bovers 480 Volt Type K-6005 \$ K-00N 6008 Circuit Breakers " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/27
- 8009180087 Forwards response to IE Bulletin 80-16 Rosemount Models 1151 & 1152 pressure transmitters are not used or planned for use except at Bellefonte Huclear Plant where use will be evaluated MILLSIL N Tennessee Valley Authority 80/08/29 2pp
- 8009240454 Forwards response to IE Bulletin 80-14 re potential misapplication of Rosemount pressure transmitters he corrective action required due to results of evaluation that indicated impossibility of anomalous output MILLS.L M Tennessee Valley Authority 80/08/27 2pp
- 8009120679 Responds to 1F Bulletin 80-i9 re failures of nercury-wetted matrix relays in reactor protective sys Relays identified are not used in facility Forty manhours expended for review MILLS-L. M. Tennessee Valley Authority 80/09/04 ip

- 8009260375 Forwards IE Circular 80-21, "Regulation of Refueling Creus" No written response required O'REILLY, J.P. Region 2 Atlanta, Office of the Director 80/09/10
- 8009160410 Forwards response to items of noncompliance cited in IE Insp. Repts 50-390/80-21 & 50-391/80-15 Corrective actions incomplete work stems have been completed or placed on list Six high point vents have been routed to closed drain sys. MILLS.L. M. Tennessee Valley Authority 80/09/11 Epp.
- 8009160423 Forwards response to deficiencies noted in IE insp Repts 50-390/80-19 ½ 50-391/80-13 Corrective actions GC procedure to be revised to include requirement to inspect one inch on either side or weld MILLS.t. (1 Tennessee Valley Authority 80/09/11 5pp
- S Reportable occurrences. LERs & related correspondence
- 8007040486 Second interim deficiency rept re defective reactor vessel upper internals guide tube support pins TVA & Hestinghouse replacing pins Next rept will be submitted by 800711 MILLS.L M Tennessee Valley Authority 80/07/24 [p
- E009100597 Final deficiency rept re control rod drop events Operating procedures to be revised per Westinghouse instructions Procedural change unli be made prior to greater than 90% power level ascension & unli prevent power overshoot MILLS.L K Tennessee Valley Authority 80/08/05 2pp
- 8009040436 Notifies of inability to correct deficiency re qualification of cold foaming procedures in accordance w/800603 deadline Anticipated completion scheduled for 800908 MILLS, L if Tennessee Valley Authority 80/08/07 ip
- 6008150212 Third interim deficiency rept re faulty fillet welds & GC breakdown Reinsp of fillet welds begun Addl affected areas include cable tray supports conduit supports & steel Addl info will be provided by 401031 MILLS.L K Tennessee Valley Authority 80/08/08 ip
- 8009040401 Third interim deficiency rept re escessive output fluctuations of Foxboro instrumentation TVA & Hestinghouse have not yet arrived at permanent solution Addl into to be submitted by 810209 MILLS.L.M. Tennessee Valley Authority 80/08/08 1p
- 8008:30476 Submits third interim deficiency rept re UHI hydraulic isolation valve accumulator weighing sys Add1 info to be transmitted by 8009:19
 MILLS.L H Tennessee Valley Authority 80/08/08 1p
- 8009040430 Bubmits third interim deficiency rept re UHI hydraulic isolation valve accumulator weighing sys Addl info to be transmitted by 800919

 MILLS,L H Tennessee Valley Authority 80/08/08 1p
- 8008170458 Fourth interim deficiency rept re Penn Ventilator OA program Util still evaluating drawings & documents supplied by Penn Ventilator Will submit next rept by 80110 MILLS.L M Tennessee Valley Authority 80/08/13 (p
- 8009100576 Final deficiency rept re hydrogen detection sys integrity Pump diaphragm rupture could result in sys integrity breach, affecting plant safety Sample pump field mod kit being provided by Consip. Inc Installation anticipated by 801205 MILLS.L N Tennessee Valley Authority 80/08/13 2pp
- B009020046 Fourth interim deficiency rept re steam generator water level ref column error Util working w/Nastinghouse to evaluate interfacing problems in installing instrumentation for temp compensation of level transmitter output signal NILLS, L M Tennessee Valley Authority 80/08/22 ip
- 8009020056 Final deficiency rept re seismic supports for auxiliary feedwater control valves Support struts cannot be installed due to interference w/other equipment Interferences will be removed or new strut will be field fabricated MILLS.L II Tennassee Valley Authority 80/08/22 2pp
- 8009100293 Final deficiency rept or documentation tag & condust support tag removal Support Tag CS-A8-15,589 & condust support Tag CB-A8-15,190 located & attached to proper support. & removal documented Craft employees will be retrained MILLS.L M Fennessee Valley Authority 80/09/03 2pp
- 8009100443 Second interim deficiency rept re insufficient analysis of 3-inch fire protection lines Analysis has been done at Next rect will be a feet.

- 8009100283 Final deficiency rept re cutting of conduit supports w/o cutting release Cutting of conduit supports documented as required by Procedure WBNP-GCP-I 7 Craft personnel will be retrained in documentation procedures
 MILLS.L M Tennessee Valley Authority 80/09/04 2pp
- 8009150537 Final deficiency rept re pressurizing fams w/o automatic blade pitch control Util purchased inlet vame dampers which will control air flow into control blidg similar to manner provided by automatic pitch control blades MILLS:L M Tennessee Valley Authority 80/09/05 2pp
- 8009160019 Fifth interim deficiency rept re surface cracks in loop one steam generator Surface indications removed by grinding to max depth of 0 190 inches Necessity of nondestructive exams not decided Addl info will be submitted by 801028

 MILLS.L II Tennessee Valley Authority 80/09/09 ip
- 8009160326 Third interim deficiency rept re defective reactor vessel upper internals guide tube support pins Mestinghouse evaluation of guide tube pins being reviewed Replacement of pins underway Next rept will be submitted by 801215 MILLS.L K Tennessee Valley Authority 80/09/10 ip
- 8007230468 First interim deficiency rept re damage to upper head injection piping hanger which is located on underside of reactor cavity shield plug Caused by plug being lifted for gastot fitup w/o hangers being disconnected Insp underway MILLS.L II Tennessee Valley Authority 80/09/12 2pp
- 8009230611 First interim deficiency rept re discrepancy in two MK-71 embedded plates Existing dimension for MK-71 plate at 136 degrees discovered wiless than required anchor bolts Plates fabricated wionly one stud Addi info by 801121 MILLS.L M Tennessee Valley Authority 80/09/16 2pp
- 8009250273 Final deficiency rept re emergency gas treatment sys open head spray nozzles Open head spray nozzles will be replaced by closed head water spray nozzles to provent water from spraying charcoal beds in event of inadvertent initiation MILLS.L M Tennessee Valley Authority 80/09/17 2pp
- B007230540 First interim deficiency rept re deterioration of unused Kerotest Y-type globe valves discovered during disassembly & insp Maeting scheduled w/Kerotest to discuss short & longterm currective actions MILLGL M Tennessee Valley Authority 80/09/18 3pp
- 8007230610 Final deficiency rept re incorrect analysis of siping sys over operating temp range Cause not stated Piping sys reanatyzed w/no major changes required MiLLS.L.M Tennessee Valley Authority 80/09/18 2pp
- 8009290324 Third Interim deficiency rept re radiation dose inside containment erceeding cable qualification Computer codes suitable for analyses of beta radiation dose to cables inside containment obtained Completion will require months. HILLS.L M Tennessee Valley Authority 80/09/19 ip
- B009290327 Fourth interim deficiency rept re upper head injection isolation valve accumulator weighing sys Proposed Westinghouse design changes will be delayed until further testing completed Addl info will be provided by 801005 MILLS.L M Tennessee Valley Authority 80/09/19 ip
- B009270344 Final deficiency rept re 6,900 volt shutdown board breaker lockout Seal-in contact of IX relay will be removed from control circuits prior to fuel loading MILLS.L M Tennessee Valley Authority 80/09/19 2pp
- DOCKET 50-391 HATTS DAR NUCLEAR PLANT, UNIT &

 A Application/construction stage documents & correspondence
- 8009160547 Forwards Westinghouse 800222 & 0604 ltrs stating vendor will provide for in-transit physical protection for nuclear fuel MILLS.L M Tennessee Valley Authority 80/06/i3 3pp
- 8009090080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0694 encl W/o NUREG EISERMUT.D G Division of Licensing 80/08/01 119pp
- 8009040467 Forwards matl re NRC review of ice condenser containment & hydrogen control measures for Sequoyah Nuclear Fower Plant ACRS has scheduled meetings in Washington, DC on 800828, 0902 & 04 to discuss issue TEDESCO

- B009300400 Forwards technical questions re implementation of interim policy on 100FR50 & 51 MillS.L # Tennessee Vallay Authority 80/09/23 3pp
- F Security, medical, emergency & fire protection plans
- 8009150206 Forwards add1 comments re transportation portion of fuel storage physical security plan dtd 800516 Requests that response be consolidated w/responses to NRC 800716 ltr & be submitted within 30 days of receipt of ltr MCCORMLE, 0 W Physical Security Licensing Branch 80/08/11 ip
- 8009030548 Forwards amend to fuel storage physical security plan Plan withheld (ref 10CFR2 790) MILLS,L K Tennessem Valley Authority 80/08/27 1p
- 8009120488 Forwards "Watts Bar Nuclear Plant Units i & 2 Fire Protection Submittal." in response to NRC 790108 request for addl info MILLS.L M Tennessee Valley Authority 80/09/09 400pp
- I Financial information
- BO09090543 Forwards Annual Financial Rept 1979 CROSS.J L. Tennessee Valley Authority BO/09/04 lp
- --8009090963 Annual Financial Rept 1979
 * Tennessee Valley Authority 80/09/04 44pp
- * Utility Final Safety Analysis Report (FSAR) & amends
- BC09020094 Forwards Amend 41 addendum to FSAR Encl matl inadvertently amitted from 800430 submittal MILLS:L M Tennessee Valley Authority 80/08/26 ip
- 8009030574 Forwards affidavit certifying that Amend 41 addendum to FSAR was mailed to DA Osborne,D Wade & JE Hagan on 800826.

 KILLS.L M Tennessee Valley Authority 80/08/26 2pp
- O Inspection reports. IE Bulletins & correspondence
- B009030032 Forwards IE Insp Repts 50-390/80-18 & 50-391/80-11 on B00629-27 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/07/17 2pp
- --B009030040 IE Insp Repts 50-390/80-18 & 50-391/80-11 on 800625-27 No noncompliance noted Major areas inspected const activities, deficiency repts, handling & storage of piping & QA audits CANTRELL,F S Region 2. Atlanta, Reactor Construction & Engineering Support Branch THOMAS,M Region 2. Atlanta, Office of the Director 80/07/16 4pp
- 8007100063 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture," No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/07/24
- 8009020214 Forwards response to IE Bulletin 79-03A No 8A-312 & A-312, Type 300 series fusion welded pipe used or planned for use in safety-related sys at greater than 88% design stress except Watts Bar Matl under investigation at Watts Bar MILLS.L M Tennessee Valley Authority 80/08/05 2pp
- BO09090802 Responds to IE Bulletin 79-03A: "Longitudinal Held Defects in ASME BA-312. Type 304 Stainless Steel Pipe" Use of matls still under investigation for sys supplied by NBS8 vendor Hill&L H Tennessee Valley Authority 80/08/05 2pp
- BO09020303 Forwards IE Insp Repts 50-327/80-24, 50-328/80-15, 50-390/80-20, 50-391/80-14, 50-438/80-13, 50-439/80-13, 50-518/80-11, 50-518/80-11, 50-520/80-11, 50-521/80-11, 50-533/80-11, 80-554/80-10, 50-520/80-10, 50-567/80-10

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director B0/08/06 258

- --8009020337 IE Insp Repts 50-327/80-24, 50-328/80-15, 50-390/80-20, 50-391/80-14, 50-438/80-13, 50-439/80-13, 50-518/80-11, 50-519/80-11, 50-520/80-11, 50-521/80-11, 50-553/80-11, 50-554/80-10, 50-566/80-10 & 50-567/80-10 on 800707-11 BROWNLEE, V L Region 2, Atlanta, Office of the Director 80/08/04 74pp
- 8007030146 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Merculy-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E ' Written response required 0'REILLY, J P. Region 2, Atlanta. Office of the Director 80/08/15
- 8009160153 Forwards IE Circular 80-18, "IOCFRSO 59 Safety Evaluations for Changes to Raduaste Treatment Sys " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22 in
- 8009120340 Forwards IF Info Notice 80-31. "Maloperation of Goold-Brown Boveri 480 Voit Type K-6005 & K-DON 6005 Circuit Breakers" No written response requised O'REELLY, J. P. Region 2. Atlanta Office of the Director 80/08/27
- 8009120679 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Relays identified are not used in facility Forty menhours expended for review MILLS, L.M. Tennessee Valley Authority 80/07/04 ip
- 8009260375 Forwards 1E Circular 80-21, "Regulation of Refueling Crews"
 No written response required
 D'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/10
 Son
- 8009160418 Forwards response to items of noncompliance cited in IE Insp Repts 50-390/80-21 & 50-391/80-15 Corrective actions incomplete work items have been completed or placed on list Six high point vents have been routed to closed drain sys MILLS.L M Tennessee Valley Authority 80/09/11 8pp
- 8009160423 Forwards response to deficiencies noted in IE Insp Repts 50-390/80-19 & 50-391/80-13 Corrective actions QC procedure to be revised to include requirement to inspect one inch on either side of weld MIU.S.L M Tennessee Valley Authority 80/09/11 Spp
- S Reportable occurrences, LERs & related correspondence
- 8009040486 Becond interim deficiency rept re defective reactor vessel upper internals guide tube support pins TVA & Westinghouse replacing pins Next rept will be submitted by 800911 MiLLS.L. M. Tennessee Valley Authority 89/07/24 ig
- 8009100537 Final deficiency rept re control rad drap events Operating procedures to be revised per Nestinghouse instructions Procedural change will be made prior to greater than 90% power level ascension 8 will prevent power overshoot MILLS, L M Tennessee Valley Authority 80/08/05 2pp
- B007040436 Notifies of inability to correct deficiency re qualification of cold foaming procedures in accordance w/B00403 deadline Anticipated completion scheduled for 800708 MILLS, L M Tennessee Valley Authority B0/08/07 ip
- 8007040401 Third interim deficiency rept to excessive output fluctuations of Forboro instrumentation TVA & Westinghouse have not yet arrived at permanent solution Add1 into to be submitted by 810207 MILLS:L M Tennessee Valley Authority 80/08/08 ip
- 8009040430 Submits third interim deficiency rept re UHI hydraulic isolation valve accumulator weighing sys Add1 info to be transmitted by 800919 HILLS, L.M. Tennessee Valley Authority 80/08/08 ip
- 8009100576 Final deficiency rept re hydrogan detection sys integrity Pump diaphragm rupture could result in sys integrity breach, affecting plant safety Sample pump field mod kit being provided by Comsip. Inc Installation anticipated by 801205 MILLS, t. H. Tennesses Valley Authority 80/08/13 2pp
- 8009020046 Fourth interim deficiency rept re steam generator water level raf column error Util working u/Westinghouse to evaluate interfacing problems in installing instrumentation for temp compensation of level transmitter output signal MILLS.L M Tennessee Valley Authority 80/08/22 ip

- 8009020056 Final deficiency mept me seismic supports for auxiliary feaduater control valves Support struts cannot be installed due to interference widther equipment Interferences will be removed on new strut will be field rabricated HILLS:L M Tennessee Valley Authority 80/08/22 2pp
- 8009100293 Final deficiency rept re documentation tag & conduit support tag removal Support Tag CS-AB-15,589 & conduit support Tag CS-AB-15,190 located & attached to proper support. & removal documented Craft employees will be retrained MILLS.L M Tennessee Valley Authority 80/09/03 2pp
- 8009100443 Second interin deficiency rept re insufficient analysis of 3-inch fire protection lines Analysis has been delayed Nest rept will be submitted by 801125 MILLS, L.M. Tennessee Valley Authority 80/09/03 ip
- B009100283 Final deficiency rept re cutting of conduit supports w/o cutting release Cutting of conduit supports documented, as required by Procedure WBMP-06P-1 7 Craft personnel will be retrained in documentation procedures
 MILLS.L (§ Tennessee Valley Authority 90/09/04 2pp
- 8009150537 Final deficiency rept re pressurizing fans u/o automatic blade pitch control Util purchased inlet vane dampers which will control air rlow into control bldg similar to manner provided by automatic pitch control blades MILLS.L.M. Tennessee Valley Authority 80/09/05 2pp
- 8009160326 Third interim deficiency rept to defective reactor vessel upper internals guide tube support pins Hestinghouse evaluation of guide tube pins being reviewed Replacement of pins underway Next rept will be submitted by 801215 HILLS.L M Tennessee Valing Authority 80/09/10 [p
- 8009230468 First interim deficiency rept re damage to upper head injection piping hanger which is located on underside of reactor cavity shield plug Caused by plug being lifted for gasket fitup w/o hangers being disconnected Insp underway MILLS,L K Tennessee Valley Authority 80/09/12 2pp
- 8009230611 First interim deficiency rept re discrepancy in two MK-71 ambedded plates Existing dimension for MK-71 plate at 196 degrees discovered w/iess than required anchor boits flates fabricated w/only one stud Add info by 801121 MILLS.L M Tennessee Valley Authority 80/09/16 2pp
- 8009250273 Final deficiency rept re emergency gas treatment sys upen head spray noisles Open head spray noisles will be replaced by closed head water spray noisles to prevent water from spraying charcoal beds in event of inadvertent initiation MILLS.L (f Tennessee Valley Authority 80/09/17 2pp
- 8009230560 First interim deficiency rept re deterioration of Unused Kerotest Y-type globe valves discovered during disassembly & Insp Meeting Scheduled w/Kerotest to discuss short & longterr corrective actions MILLS.C M Tennessee Valiey Authority 80/09/18 3pp
- 8009230610 Final deficiency rept re incorrect analysis of piping sys over operating temp range Cause not stated Piping sys reanalyted w/no major changes required MILLS.L K Tennessee Valley Authority 80/09/18 2pp
- 8009270324 Third interim deficiency rept re radiation dose inside containment exceeding cable qualification Computer codes suitable for analyses of beta radiation dose to cables inside containment obtained Completion will require months MILLS.L M Tennessee Valley Authority 80/09/19 1p
 - 09290327 Fourth interim deficiency rept re upper head injection isolation valve accumulator weighing sys Proposed Westinghouse design changes will be delayed until further testing completed Add1 info will be provided by 801005 MILLS,L II Tennessee Vailey Authority 80/07/19 ip
 - 09290344 Final deficiency rept re 6,900 volt shutdown board breaker lockout Seal-in contact of IX relay uill be removed from antrol circuits prior to fuel loading 'LLS.& M Tennessee Valley Authority 80/09/19 2pp
 - IT 50-395 VIRGIL C SUMMER NUCLEAR STATION, UNIT 1

 **plication/construction stage documents & correspondence
 - 1000080 Forwards draft NUREQ-0696. "Functional Criteria for respency Response Facilities " Comments requested within 30 Mys Proposed implementation schedule for meeting criteria NUREG-0696 encl W/O NUREQ SERMUT.D G Division of Licensing 80/08/01 119pp

- 8009050418 "Seismic Activity Near VC Summer Nuclear Station." Oct-Dec 1978 TALMANI,P South Carolina. Univ of 79-4 80/08/07 32pp
- 8009030332 Forwards requests for addl info concerning qualification of electrical equipment in order to complete review of ten plant electrical items Response should be provided by 800912
 TEDESCO,R L Assistant Director for Licensing 80/08/12 App
- 8009090789 Forwards request for addl info re TMI-2 action plan concerns Clarification that steam dump/safety & containment hydrogen punge exhausts will be monitored by high range noble gas effluent monitors should be provided TEDESCO:R L Assistant Director for Licensing 80/08/15 3pp
- 8009090895 Forwards NRC position re-application of cladding swelling & rupture LOCA models Requests supplemental calculations TEDESCO.R.L Assistant Director for Licensing 80/08/26 Spp
- 8009030493 forwards responses to NRC 800807 questions re shielding of personnel after accident Responses are in FSAR change form to will be included in next FSAR amend NICHOLS:T C South Caralina Electric & Gas Co 80/08/27 16pp
- B009190776 Forwards request for add1 info re figodplain mpt Requests responses no later than 800926 TEDESCOR L Assistant Director for Licensing 80/08/28 4pp
- 8009180569 Forwards Geotechnical Review Branch requests for additinfor re-effects of settlement of pumphouse & svc water intake structure TEDESCO.R L. Assistant Director for Licensing 80/09/02 12pp
- 800913034i Requests attendance by representative at 800910 meeting in Bethes4a,MD to discuss schedule for resolution of remaining issues re licensing application TEDESCO.R L Assistant Director for Licensing 80/09/04 App
- 8007100320 Forwards responses to RE Jackson 800620 seismology questions Responses will be incorporated in FSAR by amend Requests meeting w/NRC re seismology NICHOLS.T C South Carolina Electric & Gas Co 80/09/05 103pp
- 8009110211 Forwards response to mpt review concerns identified at 800708-10 meeting w/NRC Point-by-point comparison w/document entitled "Criteria For Util Mpt & Technical Competence" will be submitted at later date NICHOLS
- 8009120347 Bubmits response pro so & on behalf of SC Public Svc Authority, to NRC 800908 questions re TM1 mods described in NUREO-0660 Anticipatory reactor trip upon turbine trip is interlocked w/P-7 setpoint NICHOLS,T C South Carolina Electric & Gas Co 80/09/09 2pp
- 8009170294 Forwards responses to questions from GA Branch Matl will be incorporated in next FSAR amend First three pages correct numbering problem w/NRC questions Last four pages provide info inadvertently omitted from last amend NICHOLS.T C South Carolina Electric & Gas Co 80/09/12 8pp
- 8009290159 Forwards request for additinfoing plant shielding & design & high range containment monitors contained in NUREO-0578 TEDESCO.R L Division of Licensing 80/09/16 App
- 8009230296 Responds to questions re preoperational test program for facility Test sequence error will be revised to have core loading instrumentation procedure performed as initial Phase III test Air operated valves will be checked NICHOLS, T.C. South Carolina Electric & Gas Co. 80/09/17 2pp
- 8009290337 Forwards responses to generic requests for add1 info re Executive Order 11988 on floodplain mgt requested in RL Tedesco 800828 ltr Structures & topographic changes do not effect Honticello Reservoir flood hydrology NICHOLS.T C South Carolina Electric & Gas Co 80/09/23 4pp
- 8009300168 Responds to NRC request re underclad cracking in reactor vessel nozzles Related mati encl NICHOLS:T C. South Carolina Electric & Gas Co 80/09/23 22pp
- 8009260316 Forwards nonproprietary & proprietary versions of "Environ Gualification, Safety-Related Electrical Equipment/NUREO-0588," in response to DF Ross 800221 ltr Proprietary version withheld (ref 10CFR2 790) Affidavit encl NICHQL5.T C South Carolina Electric & Qas Co 80/09/24 Ppp

- --8009260518 Nonproprietary version of "Environ Qualification, Safety-Related Electrical Equipment/NUREO-0588 " 4 South Carolina Electric & Gas Co 80/09/24 100pp
- E 1980 Safety Evaluation Report (SER), supplie & correspondence
- 8609160592 Forwards SER input & requests addl info re containment pressure boundary fracture toughness PARLICXI.S S Materials Engineering Branch 80/08/22 2pp
- F Security, medical, emergency & fire protection plans
- ECOP120119 Forwards request for addition radiation emergency pian Requests response by B00926 TEOESCO.R L. Assistant Director for Licensing 80/09/02 19pp
- BOOPI603BB Informs of actions initiated to assist BC & local govt in development of radiological omergency response plans consistent w/NRC-FEHA criteria
 HCCONNELL,JW Federal Emergency Management Agency BO/09/10 ip
- 8009230282 Forwards physical security plan, Amend 2 Plan withheld (raf 105FR2 790) NICHOLS,T C Bouth Carolina Electric & Gas Co 80/09/17 ip
- Q Adjudicatory correspondence
- 8009140337 Response before US District Court for Middie District of NG. Greensboro Div.in apposition to Util motion for protective ander re Civil Action C-77-3940 Affidavit & Certificate of Sec enc!

 BRAND, WE Brand & Hail 80/09/04 20pp
- 8009170282 Forwards 800819 FR notice re final rule upgrading Commission emergency planning regulations
 GDLDBERG S C Hearing Dranch 2 80/09/15 i3pp
- BOOT230027 Notice of withdrawai from proceeding re Commission 800430 mamorandum & order, CLI-80-28, on development of new info Certificate of Byc anci CGMMER, T 8 South Carolina Electric & Oas Co CONNER, T R , WETTERHAMM
- 8009300007 Notice of appearance in proceeding Certificate of Svc encl WNOTTS.JB South Caroina Electric & Cas Co KNOTTS.JB South Carolina Public Service Authority KNOTTS.JB Debevoise & Liberman 80/09/24 2pp
- * Utility Final Safety Analysis Report (FBAR) & amends
- BO09i50314 Forwards changes to FBAR Section 2 5.for subsequent incorporation into FBAR by Amend 21 Requests prompt scheduling of meeting to discuss any remaining concerns MZCHOLS. T C Southern California Edison Co 80/09/12 ip
- --8009150315 Amend 21 to FSAR • Southern Cailfornia Edison Co 80/10/31 29pp
- H Antitrust correspondence
- E009020065 Responds to Commission 800630 memorandum & order Updates info re changes in util proposed operations & competitive status Superisedes util 800728 ltr directed to F Chanania Supporting documentation encl
 NICHOLS
- 8009020459 Response to request for commonts on Commission 800630 memorandum & order Central Electric Power Cooperative is being availed increased power supply options from SC Electric & Gas & Santee Cooper Certificate of Svc encl CHANANIA,F D Antitrust Division 80/08/29 10pp
- --8007020462 Forwards SC Public Svc Authority info in response to 800708 tte WORRISON, M. P. Cahiii, Oordon & Reindel 80/07/28 ip
- --BO09020468 Responds to 800708 ltr directed to PT Allen by outlining status of negotiations between Central Electric Power Cooperative & applicants BRAND, N E Brend & Hall 80/08/05 7pp
- SOOTISODE Requests meeting w/Central Electric Power Cooperative, Inc & REA to discuss REA proposed agreement changes Changes under evaluation Some changes would cause difficulty if adopted.
 MESCHER, W.C. South Carolina Public Service Authority 80/09/10 to

- 8009190307 Advises Commission & parties that DDJ attorneys have returned to counsel For petitioner documents obtained by NC Electric Membership Corp through discovery in antitrust proceeding re-racility Motion enci BRAND.WE Brend 5 Hall 80/09/1t 15pp
- --E009150312 Affidavit re SC Electric & Gas Co filing for protective order or documents sought by NC Electric Membership Corp concerning antitrust proceeding Plaintiff argues protective order would unduly burden litigation proceedings BRAND. IJ E Brand & Hail B0/09/03 Spp
- 8009300002 Notice of appearance in proceeding Certificate of Svc encl KNDTTS, J B South Carolina Fiectric & Gas Co 80/09/24 4pp
- 8009300021 Requests extension until 891010 to respond to Commission 800620 memorandum & order Carerul Analysis & evaluation of issues required

 KAPLAN.D A Justice, Dept of 80/07/24 ip
- B007300560 Order granting extension until B01010 for DOJ to comment on Commission 800630 memorandum & order CHILKS J Office of the Secretary of the Commission 80/07/29 to
- P Operating license stage documents 3 correspondence
- 8009050383 Responds to FOIA request for documents re seismic activity at facility from 1978 to present Forwards Technicai Rept 79-4. "Seismic Activity Near VC Burner Nuclear Station," Oct-Dec 1979 8 std order for DOE wor's FELTON, J H Division of Ruies and Records 80/08/07 ip
- a inspection reports, IF Bulletins & correspondence
- 8009030138 Forwards IE tasp Rept 50-395/80-17 on 800624-27 No noncompliance noted MUXPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/17 2pp
- --8009030140 iE Insp Rept 50-395/80-17 on 800424-27 No noncompliance noted Major areas inspected previous inspecifications illustrated identified atoms & preservice inspector gram HERDT. A Region 2, Atlanta, Reactor Construction & Engineering Support Branch (GIRARD. E H Region 2, Atlanta, Office of the Director 80/07/17 5pp
- 80091i0107 Forwards IE Insp Ropt 50-375/80-19 on 800716-18 No noncompliance noted MURPHY.C E Region 2, Atlanta, Roactor Construction & Engineering Support Branch 80/07/29 2pp
- --8009110198 IE Insp Rept 50-395/80-19 on 800716-18 No noncompliance noted Major areas inspected pipo support baseplate designs using concrete expansion anchor balts & selsmic analysis for as-built safety-related piping sys

 ANO.N P Region 2. Attanta Office of the Director HERDT, A Region 2. Attanta Reactor Construction % Engineering Support Branch 80/07/28 4pp
- 8009030129 Forwards Revision i to 1E Builotin 80-19, "Failures of Mercury-Hetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J.P. Region 2, Atlanta. Office of the Director 00/08/15
- 8009030130 Forwards Revision i to IE Bulletin 80-19, "Failures of Morcury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Dosigned by C-E " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/15 tp
- B009180511 Advises that NRC Audit Rept 50-395/80-17 dtd 800717 contains no proprietary info
 NICHOLS.T C South Carolina Electric % Gas Co 80/08/18 1p
- 8009160118 Forwards IE Circular 80-18, "10CfR50 59 Safety Evaluations for Changes to Radwasta Treatment Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 60/08/22 ip
- 8007160120 Forwards IE Cercular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director NO/08/22 ip

- 8009020031 Final rept, per 10CFR21 & 1E Bulletin BD-16.re Rosemount Model 1152 pressure transmitter safety hazards Tuelve transmitters could have false instrument outputs caused by overrange condition instruments to be nodafied or replaced NICHOLS.T C Southern California Edison Ca 80/09/25 2pp
- 8007230072 Responds to IE Sulletin 80-16 Review of safety-related applications or Rosenount Model (152 pressure transmitters w/output codes A or D indicates none can be exposed to imput pressures which could result in anoralous output signals MICHOLS, T C South Carolina Electric & Gas Co 80/08/25 2pp
- 8009030460 Pesponds to IE Bulletin 80-19. "Failures of Mercury-Watted Matrix Relays in Reactor Protectiva Sys of Operating Nuclear Power Plants Designed by C-E Mercury-wetted relays in 7300 series are not used in matrix logic applications NECHOLS.T C South Carolina Electric & Gas Co 80/08/27 1p
- 8009110719 Ack receipt of 18 Insp Rept 50-395/80-19 on 800729 No proprietary info MICHOLST C South Carolina Electric & Gas Co 80/03/27 ip
- 8009120265 Forwards IF Info Notice 80-31. "Maloperation of Could-Brown Bovers 480 Volt Type K-6008 E K-DON 6008 Circuit Breakers " No written response required O'REILLY, J P Region 2. Atlanta, Orfice of the Director 80/08/27
- 8009120286 Forwards iE Info Notice 80-31, "Maioperation of Gould-Brown Bover: 480 Volt Type K-6005 S X-DON 6005 Circuit Breakers " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/27
- 8007180831 Act receipt of 800728 itr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-395/80-15 LEWIS.R C Region 2 Atlanta Reactor Operations Nuclear Support Branch 80/09/04 ip
- --8007160634 Responds to ARC ltr re violations moted IE lnsp Rept 50-395/ 80-15 Corrective actions Hydrostatic Test Procedure 80-15-Hi ravised to include appropriate tolerances for relief setting Shubber inspected 2 protective wrappings installed NICHOLS, T C South Carolina Electric & Gas Co 80/07/28 5pp
- --8009160537 Forwards IE Insp Rept 50-395/80-15 on 800501-31 & notice of violation LEMIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 60/07/07 2pp
- --8007160638 Notice of violation from insp on 800501-34
 Region 2. Atlanta, Office of the Director 80/07/03 ip
- --B007160640 IE Insp Rept 50-395/80-15 on 800501-31 Noncompliance noted failure to establish procurement document change program & failure to follow preoperational test procedures SKOLDS.J L Region 2. Atlanta. Office of the Director KELLOGG.R J Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/07/03 6pp
- 8009180129 Submits response to IE Bulletin 83-19, Revision 1 CP Ciare Model HG2X-1011 mercury-mettod relays are not used in reactor protective sys NICHOLS, T C South Carolina Eiectric & Oas Co 80/09/04 2pp
- 8007240510 Forwards requests for add1 info re preliminary preservice insp program TEDESCO.R L Assistant Director for Licensing 80/09/10 4pp
- B009260397 Forwards IE Circular 80-21, "Regulation of Refueling Crews"
 No written response required
 O'REILLY. J P Region 2, Atlanta, Office of the Director B0/09/10
- 8009300590 Submits response to IE Sulletin 80-20 No indications of use of Westinghouse Type W-2 control switches NICHOLS, T.C. South Carolina Electric & Gas Co. 80/09/11 1p
 - /9240552 Forwards preservice insp plan Plan includes programs for reld insps.hydrostatic tests, pump & valve insps & component .upport insps
 ICHGLS, T G South Carolina Electric & Cas Co 80/09/17 ip
- 8007240557 Preservice insp plan MOMROE, J D . SHITH, S J . COLLIER, L B South Carolina Electric & Gas Co 80/09/15 300pp

- S Reportable occurrences. LERs & related correspondence
- 8009100427 Interim deficiency rapt re Class 1 pipe installed w/o having required 4-way ultrasonic exam Piping not proporly examinad presented for shipment Gaused by failure to perform & comply u/procedures to verify matl acceptability NICHOLS.Y C South Carolina Electric & Gas Co 80/07/30 3pp
- 8009020031 Final rept,per 10CFR21 & 16 Bulletin 80-14,re Rossmount Model 1152 pressure transmitter safety hazards Twelve transmitters could have false instrument outputs caused by overrange condition Instruments to be modified or replaced NiCHOLS.T C Southern California Edison Co 80/08/25 2pp
- 8009030621 Interim deficiency rept to lack of full penetration welds for attachments to Class 1 pipe Attachment welds will be reworked providing full penetration Class II & III attachments will be evaluated & rept furnished NICHOLS.T C South Caroling Electric & Oas Co 80/08/29 2pp.
- 8009080337 Final deficiency rept re patential stress corrosion cracking problem of control rod guide tube support pins supplied by Maskinghouse Util will replace pins w/pins which have been solution heat treated in range of 1,950 to 2,000 F NICHOLS.Y C Southern California Edison Co 80/09/03 3pp
- DOCKET 50-397 WPPSS NUCLEAR PROJECT: UNIT 2
- A Application/construction stage documents & correspondence
- BO070B00B0 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl M/o NUREG EISE
- 8009030521 Forwards "SRV Loads Improved Definition & Application Methodology for Mark II Containments," prepared by Burns & Roe, Inc. Rept withheld (ref. 10CFR2 790)
 RENBERGER.D.L. Washington Public Power Supply System.
- 8009070631 Notification of cancellation of 800827 meeting w/BWR licensing review group to discuss concensus positions on THI 15sues (NUREQ-06/94)
 WILSON, J. N. Assistant Director for Licensing 80/08/04 109
- BOD703012: Notification of BO0815 meeting w/util in Dethesda. MD to discuss proposed structural replacement of plug waids in sacrificial shield LYNCH.M D Licensing Branch I 80/08/14 3pp.
- 8009ii0056 Add1 response to FOIA request for 36 categories of documents re facility Region 5 documents are available in PDR Forwards documents listed in App A
 FELTORLY IS Division of Rules and Records 80/08/26, 3pp
- --8009ii006: Discusses transfer of lead responsibility for repair to facility sacrificial shield wall Signatures of HD Thornburg & RH Volimer represent concurrence w/listed proposed actions
 THORNBURG.H D Division of Reactor Construction Inspection
 80/05/19 200
- --8009i10066 Transcript of 800206 brisfing in Bethesda.MD re review & evaluation of sacrificial shield wall, pipe whip restraints & related structures Pp 1-i26 4 Commission 80/02/06, i28pp
- 8009030403 Forwards proprietary version of "Safety Relief Valve Loads ~ Improved Definition & Application Methodology for Mark II Containments," technical rept Rept withheid (ref 100FR2 790)
 VERDERBER. J J Burns & Rog Co 80/08/27 2pp
- BOO9080321 Requests meeting on 800918 w/Instrumentation & Controls Sys Branch & Reactor Sys Branch to discuss concerns before contract expiration on 800930 RENBERGER.D L Washington Public Power Supply System 80/08/29 2pp
- 8009090103 Lists steps to be taken prior to OL issuance to further reduce risk from ATMS events during interim period before plant mods determined by Commission are completed ATMS emergency operating procedure must be submitted for review TEDESCU.R L Assistant Director for Licensing 80/08/29 Upp

- 8009090496 Forwards addl geologic into re time of latest movements of earth faults on Oable Mountain near ctr of reservation. No conclusions re significance have been reached & info is not considered reportable under IOCFR21 REINBERGER.D L. Washington Public Power Supply System. 80/09/02 350
- 8009260091 Notifies of 801007 proposed date to review whether OBE & SRY responses should be considered separately or combined during ASME code fatigue calculations GE selected samples to emphasize highly fatigued components WILSON, J N Assistant Director for Licensing 80/09/15 9pp
- 8009230392 Forwards "IEEE Reliability Qualification Rept." Revision A, "Machanical Design Rept." Revision A, "Dynamic Tasting Rept." & "Thermal Cycle Test Performanco" Repts available in Central Files only RENBERGER, D.L. Washington Public Power Supply System 80/09/16
- 8009230696 Forwards eath of affirmation inadvertently emitted from DL Renberger 800916 ltr to BJ Youngbiood RENBERGER, D L Washington Public Power Supply System 80/09/17
- 8009300352 Confirms 800930 & 1001 meeting schedules w/Reactor Sys Branch & Structural Engineering Branch, respectively, re sacrificial shield waii at facility RENBERGER, D. L. Washington Public Power Supply System 80/09/22
- F Security, medical, emergency & fire protection plans
- 9009030267 Notifies of 800819, 22 & 30 regional workshops re development of guidance for acceptable method for coping W/emergencies at facility Requests that ropresentative be sent Subj areas to be discussed include function of facilities & location ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/08/12 2pp
- x Utility Finai Safety Analysis Report (FSAR) & amends
- 6007D20043 Forwards revisions to electrical, instrumentation & control drawings listed in Section 1 7 of FSAR Amend 12 will reflect revisions W/o encl
 RENBERGER, D. L. Washington Public Power Supply System 80/07/3i
- 8009090680 Forwards Amend 10 to FSAR Affidavit of distribution will be furnished within 10 days of filing Affidavit & Burns & Ros greats sheet encl RENBERGER.D L. Washington Public Power Supply System 80/08/08
- --8009090319 Amend 10 to FSAR Seventy-three drawings encl
 * Washington Public Power Supply System 80/07/31 70pp
- ~-8009090322 Package of 73 drawings to be recalled at later date for microfilming Addl documentation included • Washington Public Power Supply Bystem 80/07/31 400pp
- 83091603i2 Forwards util 8009i0 transmittal itr & Certificate of Svc for Amend 10 to F5AR RENBERGER, D. L. Washington Public Power Supply System 80/09/10
- O Inspection reports. IE Bullatins & correspondence
- 8007070052 Forwards 1E Bulletin 80-07, Suppl 1, "BWR Jet Pump Assembly Faiture" No response, required EMGELKEN, R H Region 5, San Francisco, Office of the Director 80/05/14 1p
- 8009150326 Forwards IE Insp Rept 50-397/80-12 on 800530 No noncompilance noted ENSELVERIAR H Region 5, San Francisco, Office of the Director 80/06/17 2pp
- --2009150378 IE Insp Rept 50-397/80-12 on 800530 No noncompliance noted Major areas inspected mgt meeting re results of Region 5 Licensee performance evaluation for Apr 1979 through Apr 1980 ENGELKEN, R H . BISHOP, T W Region 5, San Francisco, Office of the Ofrector SPENCER, G S Region 5, San Francisco, Reactor Genstruction & Engineering Support Branch 80/06/17.

- 8009120467 Forwards IE Insp Rept 50-397/80-07 on 800527-30 No noncompliance noted SPENCER, G S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/07/07 2pp
- --8009120472 iE insp Rept 50-397/80-07 on 800527-30 No moncompliance noted Major areas inspected licensee actions in response to iE Circular 78-08 % review of dc electrical power distribution DODDS: RT Region 5. San Francisco. Reactor Construction & Engineering Support Branch ELIN. J G Region 5. San Francisco. Office of the Director 80/07/03 App
- 8007020233 Forwards IE Insp Rept 50-397/80-07 on 800618-20 No noncompilance noted CREMS,J L Region 5. San Francisco, Reactor Operations Nuclear Support Branch 80/07/14 2pp
- --B009020240 IE Insp Rept 50-397/80-09 on B00618-20 No nuncompliance noted Major areas inspected plant procedures, provisional acceptance packages, preoperational test procedures, & overall preoperational test program

 JOHNSON, P. H., CARLSON, J. D. Region 5, San Francisco, Office of the Director STERNBERO, D. M. Region 5, San Francisco, Reactor Operations Nuclear Support Dranch 80/07/19 3pp
- 8009260303 Forwards iE Info Notice 80-29, 'Broken Studs on Terry Turbine Steam Iniet Flange " No written response required ENCELKEU, R H Region 5, San Francisco, Office of the Director 80/08/07 1s
- 8009090023 Forwards updated response to IE Bulietin 79-02.Revision 2, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Boits ' W/o encl Final response will be issued in first quarter 1981 REMBERGER, D.L. Washington Public Power Supply System 80/08/08
- 800917038B Responds to TE Builetin 79-03A. "Longitudinal Weld Defects in ASKE SA-312. Type 304 Stainless Steel Pipe " Two contracts identified where math may be used Math hist requested from contractors
 RENUERGER. D. L. Washington Public Power Supply System 80/08/08
- 8009030292 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E "Written response required EMGELKEN, R H Region 5, San Francisco, Office of the Director 80/08/15 1p
- B007040472 Forwards iE Investigation Rept 50-397/80-08 on 800403-0725 & notice of violation EfGELKEN,R H Region 5, San Francisco. Office of the Director B0/08/15 2pp
- ---8009040474 Notice of violation from investigation on 800603-0729 * Region 5, San Francisco, Office of the Director 60/08/15 7pp
- --8009040482 IE Investigation Rept 50-397/80-08 on 800403-0725
 Noncompliance noted failure to maintain QA freedom, from cost & schedule to maintain survey document of vendor & failure to document insp findings.
 BODDS,R T Region 5, Sun Francisco, Reactor Construction & Engineering Support Branch BISHOP,T W, TOTH,A D Region 5, San Francisco, Office of the Director 80/08/15 67pp
- 8009290302 Forwards iE Info Notice 80-27 re degradation of reactor coolant pump studs ENOSLKEN.R H Region 5. San Francisco. Office of the Director 80/08/18 4pp
- 8009120030 Forwards Suppl 3 to [E Bulletin 80-17, "Failure of Control Rods to Insert During Scram at 8HR " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/08/22 1p
- B009150376 Forwards IC Insp Rept 50-397/80-11 on B00812 No noncompliance noted ENGELKEN,R H Region S. San Francisco. Office of the Director B0/08/22 2pp
- --8009150379 IE Insp Rept 50-397/80-il on 800812 No noncompliance noted Major areas inspected special corporate mpt meeting in San Francisco to present results of Region 5 evaluation of licensee performance for Apr 1979 through Jul 1980 TOTH, A D. ENDELKEN, R H. Region 5, San Francisco, Office of the Director 80/08/21 12pp

DOCKETED ITEMS

- 8009160189 Forwards IE Circular 80-18, "100FR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required ENGELKENIR M Region 5, San Francisco, Office of the Director 80/08/22 is
- 800912046B Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Voit Type R-600S & K-BDN 600S Circuit Breakers" No written response required EMGELKRIN R H. Region S. San Francisco, Office of the Director 80/08/27 lp
- 8009120568 Responds to 1E Bullatin 80-19 No mercury-wetted matrix relays used in reactor protective sys or any safety-related sys RENBERGER.D L. Washington Public Power Supply System 80/08/26
- 8009180134 Forwards Revision 1 to JE Bulletin 79-26, "Boron Loss From Bild Control Blades " No written response required ENGELKELIAR H Region 5, San Francisco. Office of the Director 80/08/29 ip
- S Reportable occurrences. LERs & related correspondence
- 8007240465 Deficiency rept to large diameter piping found to have less than ASME code required min wall thickness Caused by overgrinding while preparing weld profiles for ASME Section 11 inservice insp Contractors to revise procedures RENMERGER, D.L. Washington Public Power Supply System 80/07/16 2pp
- 8009240464 Deficiency rept re Power Piping Co beam attachment. HS-142, used in rigid sway brace assemblies supplied w/undersized welds Caused by bracist design deficiency Stop work order issued to all contractors installing sub, brackets RENBERGER. D L Washington Public Power Supply System 80/09/19 290
- 8009300415 Deficiency rept re primary containment pressure monitoring instrumentation sensing line routing to initiate ECGS PED 220-1-324 & -329 issued, reassigning instrumentation sensing lines to penetrations below instrument rack elevation RENUERGER, D. L. Washington Public Power Supply System 80/09/24 2nd
- E009300379 Deficiency rept re lack of installation documentation for Class IE cables in main control room raceways Evaluation revealed inadequate inspiciteria & OA program for installation of electrical cables Procedures being revised RENBERGER, D. L. Washington Public Power Supply System 80/09/26
- U Congressional/Executive Correspondence
- 8009110241 Forwards response to B00714 questions re financing guarantees provided to certain NRC licensees Also provides table of generating costs for nuclear plants DIRCKS, W J. Office of the Executive Director for Operations 80/08/08 11pp
- DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- BO09090080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT.D Q Division of Licensing 80/08/01 119pp
- 8009230772 Notification of 800905 meeting w/util in Bethesda,MD to discuss procedure for amending OLs to add addl owners WILSON. J N Licensing Branch i 80/08/29 4pp
- 30071704QO Summary of 800705 meeting w/CPSL 5 NC Municipal Power Agency 3 in BethesdarMD re procedure for QL & CP amends WILSQN.J N Licensing Branch 1 80/09/12 7pp
- 3009250141 Discusses interim steps needed prior to issuance of OL. pending final resolution of ATMS Emergency operating procedures should be developed in event of ATMS NRC avaluation may include site visit
 TEDESCO.R L Assistant Director for Licensing 80/09/12 3pp

H General correspondence

- 8009120437 Advises of BWR owners group organizational changes & that future correspondence be forwarded to DB Waters Future requests for util action should be addressed to individual licensees & applicants

 MATERS.D B Carolina Power & Light Co 80/09/02 2pp
- 6009260509 Forwards "Mgt Capability Rept" & Section 13 1 from FBAR remgt capability in support of preliminary NRC evaluation ordered 600417 Requests that preliminary evaluation begin immediately to expedite notice of oper
- @ Inspection reports, IE Bulletins & correspondence
- 8008280104 Forwards IE Insp Repts 50-400/80-15,50-401/80-13, 50-402/80-13 & 50-403/80-13 on 800614-20 & notice of violation MURPINC E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/25 2pp
- --8008280114 Notice of violation from insp on 800616-20
 * Region 2, Atlanta, Office of the Director 80/07/25 ip
- --8008280126 IE Insp Repts 50-400/80-15,50-401/80-13,50-402/80-13 & 50-403/80-13 on 600616-20 Noncompliance noted failure to follow reinforcing steel storage procedure HERDTA R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 60/07/25 Spp
- 8009020203 Submits response to IE Bulletin 79~03A No welded SA~312 or A~312. Type 300 series stainless steel has been used or is planned for use in safety-related piping sys MCDUFFIE.M A Caralina Power & Light Co 80/08/05 ip
- 8007030163 Forwards Revision 1 to IE Bulletin 80-17, "Failures of Mercury-Netted Matrix Relays in Reactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/15 1p
- 8009230067 Submits response to IE Suffetin 80-16 No Rosemount Inc Model 1151 or 1152 pressure transmitters installed or planned for use in safety-related functions MCDUFFIE.H A Carolina Power & Light Co 80/08/20 1p
- 8009100241 Ack receipt of IE Insp Repts 50-400/80-14, 50-401/80-14, 50-402/80-14 & 50-403/80-14 an 800623-27 No proprietary info HOME, P W Carolina Power & Light Co 80/08/22 Ip
- --8009100250 Forwards IE Insp Repts 50-400/80-14, 50-401/80-14, 50-402/80-14 & 50-409/80-14 on 800623-27 No noncompliance noted MURPHY,C,E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/13 2pp
- --8009100258 IE insp Repts 50-400/80-16.50-401/80-14.50-402/80-14 & 50-403/80-14 pn 800623-27 No noncompliance noted Major areas inspected containment structural concrete, safety-related cable raceway support & pump motors CONLON.TE Region 2, Atlanta, Reactor Construction & Engineering Support Branch MALTERS.D K Region 2, Atlanta, Office of the Director 80/08/12 App.
- 8009160124 Forwards IE Circular 80-18, "10CFR50 59 Bafety Evaluations for Changes to Radwasto Treatment Sys " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22, ip
- 8009120290 Forwards IE Info Notice 80-31, "Maioperation of Gould-Brown Boveri 480 Voit Type K-6008 & K-DON 6008 Circuit Breakers " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/27
- 8009120593 Responds to IE Bulletin 80-19 Initial review of design indicates no mercury-wetted matrix relays are used in reactor protection sys Addi reviews & inquires are required MCDUFFIE, MA Carolina Power & Light Co 80/08/29 IP
- 8009180450 Ack receipt of IE Insp Repts 50-400/80-20,50-401/80-18, 50-402/80-18 & 50-403/80-18 on 800721-31 No proprietary info HOME, P N Carolina Power & Light Cp 80/09/02 1p

- --8009180454 Forwards IE Insp Repts 50-400/80-20,50-401/80-18, 50-402/80-18 t 50-403/80-18 on 800721-31 No noncompliance noted KVRFHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/08/21 2pp
- --B0091B0459 IE Insp Repts S0-400/80-20, 50-401/80-18, 50-402/80-18 & 50-403/80-18 on B00721-31 No noncompliance noted Major areas inspected equipment storage, containment steel & concrete placement
 MAKKELL.G F Region 2, Atlanta, Office of the Director ERYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/19 Spp
- B009230347 Ack receipt of B00819 (fr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/80-15, 50-401/80-13, 50-402/80-13 & 50-403/80-13 MRRPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch B0/09/09 (p
- --8009250351 Responds to NRC 800725 ltr re violations noted in IE Insp Repts 50-400/80-15.50-401/80-13.50-402/80-13 & 50-403/80-13 Corrective actions undercut area on hanger 1-CT-H-7 has been rewelded HOME.P W Carolina Power & Light Co 80/08/19 3pp
- 8009290287 Forwards IE Circular 80-21. "Regulation of Refueling Crews"
 No written response required
 O'REILLY, J.P. Region 2 Atlanta, Office of the Director 80/09/10
- 8009300581 Submits response to IE Bulletin 80-20 Westinghouse Type W-2 control switches are not used in safety-related applications RCQUFFIE.M A Carolina Power & Light Co 80/09/12 ip
- BO092&0497 Submits changes in QA organization adding position of principal const specialist-insp.in response to follow-up item from IE insp on B00428-0502
 MCDUFFIE.H A Carolina Power & Light Co 80/09/19 4pp
- S Reportable occurrences, LERs & related correspondence
- BOOTIO0465 Deficiency rept re use of insufficient preheat in field welding of Seismic I hangers Item is still under investigation to determine reportability per IOCFRSO 35e Evaluation will be completed by 800705 tHIANGI.N J Caralina Power & Light Co 80/08/19 (p
- BC09080254 Interim deficiency rept re procurement fabrication & insp of engineered plates for concrote embedment & support of safety-related loads Corrective action on 22 remaining plates to be completed by 801(15) CHIANOI.N J Carolina Power & Light Co 80/08/29 ip
- DOCKET 50-401 GHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2
 A. Application/construction stage documents & correspondence
- E009080080 Forwards draft NUREO-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/o NUREO EISENRUY, D O Division of Licensing 80/08/01 119pp
- BOO9230772 Notification of 800905 meeting w/util in Bethesda, MD to discuss procedure for amending OLs to add addi owners NILSON, J N Licensing Branch i 80/08/29 4pp
- SOC9170400 Summary of GOO905 meeting w/CP&L & NC Municipal Power Agency 3 in Bethesda.MD re procedure for OL & CP amends MTLSONJJN Licensing Branch 1 80/09/12 7pp
- BGG9230141 Discusses interim steps needed prior to issuance of OL, pending final resolution of ATWS Emergency operating procedures should be developed in event of ATWS NRC availation may include site visit
 TEDESCO.R L Assistant Director for Licensing 80/09/12 3pp

H. Ganeral correspondence

8009120437 Advises of BWR owners group organizational changes & that future correspondence be forwarded to DB Waters Future requests for util action should be addressed to individual licensees & applicants WATERS.D B Carolina Power & Light Co 80/09/02 2pp

- 8009260509 Forwards "Mgt Capability Rept" & Section 13 1 from FSAR remgt capability, in support of preliminary NRC evaluation ordered 800417 Requests that preliminary evaluation begin immediately to expedite notice of opertunity for hearing UTLEY, E E Carolina Power & Light Co 80/09/22 210pp
- Q Inspection reports, IE Bulletins & correspondence
- 8009020203 Submits response to IE Bulletin 79-03A No welded SA-312 or A-312. Type 300 series stainless steel has been used or is planned for use in safety-related piping sys MCDUFFIE, N A Carolina Fower & Light Co B0/08/05 Ip
- 8009030163 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/08/15
- 8009230067 Submits response to IE Builetin 80-16 No Rosemount Inc Model 1151 or 1152 pressure transmitters installed or planned for use in safety-related functions MCDUFFIE.N A Carolina Power & Light Co 80/08/20 1p
- 800910024(Ack receipt of (E Insp Repts 50-400/80-(6,50-401/80-)4, 50-402/80-14 & 50-403/80-14 on 800623-27 No proprietary inro
 HDWE.P N Carolina Power & Light Co 80/08/22 1p
- --8009100250 Forwards IE Insp Repts 50-400/80-16,50-401/80-14, 50-402/80-14 % 50-403/80-14 on 800623-27 No noncompliance noted MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/13 2pp
- --8009100258 IE Insp Repts 50-400/80-16,50-401/80-14,50-402/80-14 & 50-403/80-14 on 800623-27 No noncompliance noted Major areas inspected containment structural concrete,safety-related cable raceway support & pump motors COILCOUTE Region 2. Atlanta, Reactor Construction & Engineering Support Branch MALTERS, DK Region 2, Atlanta, Office of the Director 80/08/12 App
- 8009160124 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/09/22 ip
- 8009120290 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover(480 Volt Type K-6005 & K-DDN 600S Circuit Breakers " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/27
- 8009120593 Responds to IE Builetin 80-19 Initial review of design indicates no mercury-wetted matrix relays are used in reactor protection sys Addi reviews & inquires are required MCDUFFIE, M A Carolina Power & Light Ca 80/08/29 ip
- 8009180450 Ack receipt of IE Insp Repts 50-400/80-20.50-401/80-18, 50-402/80-18 & 50-403/80-18 on 800721-31 No proprietary info HOWE, P K Carolina Power & Light Co 80/09/02 1p
- --8007180457 lE insp Repts 50-400/80-20.50-401/80-18.50-402/80-18 & 50-403/80-18 on 800721-31 No noncompliance noted Major areas inspected equipment storage, containment steel & concrete placement MAXMELL.O F Region 2. Atianta. Office of the Director IRYANT.J C Region 2. Atianta. Reactor Construction & Engineering Support Branch 80/08/17 Spp
- 8009250347 Act receipt of 800819 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/80-15. 50-401/80-13, 50-402/80-13 & 50-403/80-13 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/09/09 ip
- --8009250351 Responds to NRC 800725 ltr re violations noted in IE Insp. Repts 50-400/80-15, 50-401/80-13, 50-402/80-13 & 50-403/80-13 Corrective actions undercut area on hanger i-CT-H-7 has been reweited HGHE.P W Carolina Power & Light Co 80/08/19 3pp

- 8009290287 Forwards IE Circular 80-21. "Regulation of Refueling Crews" No written response required O'REJLL: J P Region 2. Atlanta, Orrice of the Director 80/09/10
- 8009300581 Submits response to IE Sulletin 80-20 Westinghouse Type W-2 control switches are not used in safety-related applications MCDUFFIE.II A Carolina Power & Light Co 83/09/12 lp
- 8009260497 Submits changes in QA organization.adding position of principal const specjalist-insp.in response to follow-up item from JE insp on 800428-0502 MCDUFFIE.H A Carolina Power & Light Co 80/09/19 4pp
- S Reportable occurrences, LERs & related correspondence
- 8009100465 Deficiency rept re use of insufficient preheat in field welding or Seismic I hangers liem is still under investigation to determine reportability per 10CFR50 55e Evaluation will be completed by 800705 CHIANGLIN J Carolina Power & Light Co 80/08/19
- 8009090254 Interim deficiency rept re procurement.fabrication & insp of engineered plates for concrete embedment & support of safety-related loads Corrective action on 22 renaining plates to be completed by 801115
 CHIANOL
- DUCKET 50-402 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 3 A Application/construction stage documents & correspondence
- B007080080 Forwards draft NUREO-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 enci H/o NUREO EISENYUT.D C Division of Licensing 80/08/01 119pp
- B009230772 Notification of B00905 meeting w/util in Bethesda.MD to discuss procedure for amending OLs to add addit numers WILSON, J.N. Licensing Branch 1 80/08/29 4pp
- 8009170400 Summary of 800903 meeting w/CP&L & NC Municipal Power Agency 3 in Bethesda.MD re procedure for DL & CP amends WILSON.J N Licensing Branch 1 80/09/12 7pp
- 8009250141 Discusses interim steps needed prior to issuance of CL, pending final resolution of ATMS Emergency operating procedures should be developed in event of ATMS MRC evaluation may include site visit TEDESCO.R L Assistant Director for Licensing 80/09/12 3pp
- If General correspondance
- 8009120437 Advises of BMR owners group organizational changes & that future correspondence be forwarded to DB Waters Future requests for util action should be addressed to individual litensees & applicants WATERS.D 8 Caroline Power & Light Co 89/09/02 2pp
- B009260569 Forwards "Mgt Capability Rept" & Section 13 f from FSAR remgt capability, in support of preliminary NRC evaluation ordered 800417 Requests that preliminary evaluation begin immediately to expedite notice af oportunity for hearing UTLEY.E E Carolina Power & Light Co 80/09/22 210pp.
- Q Inspection reports, IE Bulletins & correspondence
- 8009020203 Submits response to IE Bulletin 79-03A No welded SA-312 or A-312. Type 30D series steinless steel has been used or is planned for use in safety-related piping sys
 MCDUFFIE.M A Carelina Power & Light Co 80/08/05 ip
- 8007030163 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/15
- 8007230067 Submits response to IE Bulletin 80-16 No Rosemount Inc Model 1551 or 1552 pressure transmitters installed or planned for use in safety-related functions MCDUFF1E.N A Carolina Power & Light Co 60/08/20 1p

- 8009100241 Ack receipt of IE Insp Repts 50-400/80-16, 50-401/80-14, 50-402/80-14 & 50-403/80-14 on 800623-27 No proprietary HOWE.P W Carolina Power & Light Co 80/08/22 (p
- --8039100250 Forwards IE Insp Repts 50-400/80-16.50-401/80-14. 50-402/80-14 % 50-403/80-14 on 800623-27 No noncompliants Region 2. Atlanta. Reactor Construction & Engineering Support Granch
- --8009100258 IE Insp Repts 50-400/80-16.50-401/80-14.50-402/80-11 t 50-403/80-14 on 800623-27 No noncompliance noted Major areas inspected containment structural concrete, safety-related cable raceway support t pump motors CONLON.T E Region 2. Atlanta. Reactor Construction & Engineering Support Branch WALTERS, D K Region 2. Atlanta. Office of the Director 80/08/12 6pp
- 8009160124 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response o'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22
- 8009120290 Forwards IE Info Notice 80-31, "Naloperation of Could-Brem Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/21
- B009120593 Responds to IE Bulletin B0-19 Initial review of design indicates no mercury-wetted matrix relays are used in reactor protection sys Addl reviews & inquires are required ACDUFFIE.M A Carolina Power & Light Co B0/08/29 Ip.
- 8009180450 Ack receipt of IE Inap Repts 50-400/80-20,50-401/80-18. 50-402/80-18 & 50-403/80-18 on 800721-31 No proprietary HOWE, P K Carolina Power & Light Co 80/09/02 Ip
- --8009180454 Forwards IE Insp Repts 50-400/80-20:50-401/80-18:50-402/80-18 & 50-403/80-18 on 800721-31 No noncompliance noted notes MURPHY.C E. Region 2. Atjanta, Reactor Construction & Engineering Support Branch 80/08/21 200
- --8009180459 IE Insp Repts 50-400/80-20,50-401/80-18,50-402/80-18 & 50-403/80-18 on 800721-31 No noncompliance noted Major areas inspected equipment storage, containment steel & concrete inspected equipment storage containment steel & concrete placement MAXMELL.O F Region 2. Atlanta, Office of the Director BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch BD/08/19 Spp
- 8009280347 Ack receipt of 800819 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/80-15, 50-401/89-13, 50-402/80-13 & 50-403/80-13 MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/09 ip
- --8009250351 Responds to NRC 800725 1tr re violations noted in IE Ins Repts 50-400/80-15, 50-401/80-13, 50-402/80-13 & 50-403/80-13 Corrective actions undercut area on hanger 1-CT-H-7 has been HORE, P. W. Carolina Power & Light Co. 80/09/19 3pp
- 8009290287 Forwards IE Circular 80-21, "Regulation of Refueling Craus" No written response required G'RETLLY, J P Region 2, Atlanta, Office of the Director 80/09/10
- 800930059f Submits response to IE Bulletin 80-20 Westinghouse Type M-2 control suitches are not used in safety-related applications MCCUVFFIE.M A Carolina Power & Light Co 80/09/12 ip
- 8007260497 Submits changes in QA organization, adoing position of principal const specialist-insp.in response to follow-up item from IE insp on 800428-0502 MCDUFFIE.M A Carolina Power & Light Co 80/07/19 4pp
- S Reportable occurrences, LERs & related correspondence
- 8009100465 Deficiency rept re use of insufficient preheat in field, welding of Seismic I hangers. Item is still under investigation to determine reportability per 10CFR50 358 Evaluation will be completed by 800905 CHIANGI.

- 6009080254 Interim deficiency rept re procurement, fabrication & insp of engineered plates for concrete embedment & support of safety-related loads Corrective action on 22 remaining plates to be completed by 801115
 CHIANOI, II J Carolina Power & Light Co 80/08/29 1p
- EDCKET 50-403 SHEARON HARRIS NUCLEAR POHER PLANT, UNIT 4

 A Application/construction stage documents & correspondence
- 8007080080 Forwards draft NUREO-0694, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/o NUREO EISENHUT, D G Division of Licensing 80/08/01 119pp
- 8009230772 Notification of 800905 meeting w/util in Bethesda.MD to discuss procedure for amending OLs to add add1 guners WILSON.J N Licensing Branch : 80/08/29 4pp
- B009170400 Summary of B00905 meeting w/CP&L & NC Municipal Power Agency 3 in Bethesda.HO re procedure for OL & CP amends WILSDN.J N Licensing Branch 1 80/09/12 7pp
- 800925014i Discusses interim steps needed prior to issuance of OL, pending final resolution of ATMS Emergency operating procedures should be developed in event of ATMS NRC svaluation may include site visit
 TEDESCO.R L Assistant Director for Licensing 80/09/12 3pp
- H General correspondence
- 8009120437 Advises of BWR owners group organizational changes & that future correspondence be forwarded to DB Waters Future requests for util action should be addressed to individual licenses & applicants WATERS.D B Carolina Power & Light Co 80/09/02 2pp
- 8009260509 Forwards "Mgt Capability Rept" & Bection 13 1 from FSAR remgt capability in support of proliminary NRC evaluation ordered 800417 Requests that preliminary evaluation begin immediately to expedite notice of oportunity for hearing UTLEY,E E Carolina Power & Light Co 80/09/22 210pp
- O Inspection reports: IE Bulletins & correspondence
- 8007020203 Submits response to 1E Bulletin 79-03A No welded SA-312 or A-312. Type 300 series stainless steel has been used or is planned for use in safety-related pining sys HCDUFFIE.M A Carolina Power & Light Co 80/08/05
- 8009030163 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercusy-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Fower Plants Designed by C-E " Written response required O'REFILLY.J P Region 2, Atlanta, Office of the Director 80/08/15 to
- 8007230067 Bubmits response to IE Bulletin 80-16 No Rosemount Inc Mudel 1(5) or 1192 pressure transmitters installed or planned for use in safety-related functions MCDUFFIE.M A Carolina Power & Light Co 80/08/20 1p.
- 8007100241 Ack receipt of IE Insp Repts 50-400/80-14, 50-401/80-14, 50-402/80-14 & 50-403/80-14 on 800423-27 No proprietary info HDME:P W Carolina Power & Light Co 80/08/22 1p
- --8009100250 Forwards IE .Insp Repts 50-400/80-14,50-401/80-14, 50-402/80-14 \$ 50-403/80-14 on 800623-27 No noncompliance noted MWRPHY, C E Region 2, Atlanta, Reactor Construction \$ Engineering Support Branch. 80/08/13 2pp
- --8009100258 IE Insp Repts 50-400/80-14,50-401/80-14,50-402/80-14 & 50-403/80-14 on 800623-27 No noncompliance noted Major areas inspected containment structural concrete, safety-related cable raceway support & pump motors CONLON.T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/12 App
- 8009360124 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required 0'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/08/22 to

- 8009120290 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6005 % K-DDN 6008 Concust Breakers "No written response required O'REJLLY. J P Region 2 Atlanta, Orfice of the Director 80/08/27
- 8007120373 Responds to [E Bulletin 80-19 Initial review of design indicates no mercury-wetted matrix relays are used in reactor protection sys Addl reviews 5 inquires are required MCDUFFIE, M A Carolina Power 5 Light Co 80/08/29 1p
- 8009180450 Ack receipt of IE Insp Repts 50-400/80-20,50-401/80-18, 50-402/80-18 & 50-403/80-18 on 800721-31 No proprietary info HOME.P W Carolina Power & Light Co 80/09/02 1p
- --8009180454 Forwards 1E Insp Repts S0-400/80-20,50-401/80-18, 90-402/80-18 & 50-403/80-18 on 800721-31 No noncompliance noted KURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/21 2pp
- --8009180459 IC Insp Repts 50-400/80-20,50-401/80-18,50-402/80-18 & 50-403/80-18 on 800721-31 No noncompliance noted Major areas inspected equipment storage.containment step! & concrete placement MAXWELL.0 F Region 2, Atlanta, Office of the Director 80/08/19 550
- B009290347 Ack receipt of 800B19 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-400/80-13. 50-401/80-13. 50-402/80-13 & 50-403/80-13 MNRPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch B0/09/09 ip
- B009290287 Forwards 1E Circular 80-21, 'Regulation of Refueling Crews **
 No written response required
 O'REILLY.J P Region 2. Atlanta, Office of the Director B0/09/10
 Soo
- 8009300581 Submits response to 1E Bullet;n 80-20 Westinghouse Type W-2 control switches are not used in safety-related applications MCDUFILE.M A Carolina Power & Light Co 80709712 & sp
- 8009260497 Submits changes in QA organization, adding position of principal const specialist-insp, in response to follow-up item from IE insp on 800428-0502 MCDUFFIE.11 A Carolina Power & Light Co 80/09/19 4pp
- S Reportable occurrences. LERs & related correspondence
- 8007100465 Deficiency rept ro use of insufficient preheat in field welding of Seismic 1 hangers ltem is still under Investigation to determine reportability per 10CFRSO 35e Evaluation will be completed by 800705 CHIANGI
- B009080234 Interim deficiency rept re procurement fabrication & insp of engineered plates for concrete embedment & support of safety-related loads Corrective action on 22 remaining plates to be completed by 801115
 CHIANGI,N J Carolina Power & Light Co 80/08/29 ip
- DOCKET 50-404 NORTH ANNA POHER STATION, UNIT 3

 F Security, medical, emergency & fire protection plans
- 8009230273 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency D'REILLY, J.P. Region 2. Atlanta, Office of the Director BO/09/22 ip
- @ Inspection reports, IE Bulletins & correspondence
- 8009100065 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Bide High Energy Line Rupture " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/07/24 ip

- 800903014: Forwards Revision I to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required D'REILLY, J P Region 2. Atlanta, Orfice of the Director 80/08/15
- 8009160172 Forwards IE Circular 80-18, "IOCFR50 59 Safety Evaluations for Changes to Radwasto Treatment Sys " No written response required
 O'REILLY, J P Region 2, Atlanta, Orfice of the Director 80/08/22
- 8009020234 Advises that review of IE Bulletin 80-16 re potential misapplication of Rosemount 1151 & 1152 pressure transmitters has been suspended Resumption pending results or studies re-reasibility of operation as nuclear units 880WN.S C Virginia Electric & Power Co 80/08/27 Ip
- 8009020399 Responds to IE Bulletin 80-20, "Failures of Wastinghouse, Type W-2 Spring Return to Neutral Control Switches" Review suspended during feosibility study for facility Review will be resumed if study indicates continuance of nuclear units BRCWN.S C Virginia Electric > Power Co 80/09/27 ip
- 8009020416 Informs of suspending review of IE Dulletin 80-19 re failures of morcury-wetted matrix relays in reactor protective sys Feasibility study of units has curtailed activities in nuclear-related areas BRGWN-S C Virginia Efectric & Pecer Co 80/08/27 ip
- 8009120314 Forwards IE Info Notice 80-31, 'Maloperation of Gould-Brown Boveri 480 Volt Type K-6005 8 K-00N 6009 Circuit Breakers " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/27
- 8009250087 Responds to IE Bulletin 80-14 Feasibility study of unite currently being conducted Activities in nuclear-related areas stopped Review of Rosemount Models 1151 & 1152 transmitters misapplication suspended BRCMN-8 C Virginia Electric & Power Co 80/08/27 ip
- 8007250517 Forwards IE Carcular 80-21, "Regualtion of Refueling Crews " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director
- DOCKET 50-405 NORTH ANNA POWER STATION, UNIT 4 F Security, medical, emergency & fire protection plans
- B009230273 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22
- O Inspection reports, IE Bulletins & correspondence
- 8009100045 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Foilowing Secondary Bide High Energy Line Rupture " No written response required O'REILLY, J P Region 2. Atlanta, Orfice of the Director 80/07/24
- 8009030141 Forwards Revision i to IE Bulletin 80-19. "Failures of Mercury-Wetted Matilix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required
 D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/15
- 8007160172 Forwards IE Circular 80-18, "10CFR50 57 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/22
- 8007020236 Advises that review of IE Bulletin 80-i6 re potential misapplication of Rosemount 1151 & 1152 pressure transmitters has been suspended Resumption pending results of studies re feasibility of operation as nuclear units BROWN.8 C Virginia Electric & Power Co 80/09/27 lp
- 8009020399 Responds to 1E Bulletin 80-20, "Failures of Westinghouse. Type W-2 Spring Return to Neutral Control Switches of Westin Type W-2 Spring Return to Neutral Control Switches "Review suspended during feasibility study for facility Review will be resumed if study indicates continuence of nuclear units BRDAM S C Virginia Electric & Power Co. 80/08/27 ip

- 8009020416 Informs of suspending review of IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Feas(bility study of units has curtailed activities in nuclear-related areas SRGWN.S C Virginia Electric & Power Co 80/08/27 to
- 8009120314 Forwards IE Info Notice 80-31. "Maloperation of Gould-Break Bower1 480 Volt Type K-6005 & K-DON 6005 Circuit Breakers" No written response required O'REILLY, J.P. Region 2. Atlanta, Orfice of the Director 80/08/27
- 10
- B0092500B7 Respunds to 1E Bulletin B0-16 Feasibility study of units OFFECUOIS, Responds to its buffetin BO-To reasibility successions controlling successful being conducted Activities in nuclear-related areas stupped Review of Rosemount Modols 1151 & 1152 transmitters misapplication suspended BROAN, S.C. Virginia Electric & Power Co. 80/08/27 ip
- 8009260517 Forwards IE Circular 80-21, "Regualtion of Refueling Creat. No written response required G'REILLY, J.P. Region 2, Atlanta, Office of the Director 60/09/10
- DOCKET 50-409 LA CROSSE BOILING WATER REACTOR F Security, medical, emergency & fire protection plans
- 8009230300 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency KEPPLER.J G Region 3. Chicago. Office of the Director 80/08/22 Эрр
- 8007250475 Informs of upcoming onsite appreisal of health physics program & requests nonemployee no escort required, picture badges for personnel identified in encl KEPPLER. J & Region 3. Chicago. Office of the Director 60/07/07
- O Adjudicatory correspondence
- 8007020041 Response in opposition to Coulem Region Energy Coalition to FM Disen requests for hearing re 800225 order to show cause on site dewatering sys Hearing not required per Marble Hill std.CLI-80-10 Certificate of Syc encl HEISTAND.O S Dairyland Power Cooperative HEISTAND.O S Horian Lewis & Bockius 80/08/28 13pp
- BO07020426 Forwards documents re comparative health effects of coil in nuclear fuel cycles in response to ASLB Question 3 at prehearing conference W/o encls HDDDHEAD.C P Hearing Branch 3 80/08/29 1P
- 8009030096 Responds to ASLB 800619 second prehearing conference questions Addresses Table S-3 of FES, justification for using Reg Guide 1 109 offsite doses computation & decommissioning cost after 10 yes of operation Certificate of Svc enci SHCA. J. 1 Operating Reactors Branch 2 80/08/29. 12pp
- 8007030i34 Response urging denial of Coulee Region Energy Coalition in FA Disen requests for hearing resite dewatering systematics interest is adequately & sufficiently shown, Notices of appearances & Certificate of Secton Edward Council Edward C
- --8009030142 Forwards safety evaluation in support of licensee positive that design & installation of site dewatering sys not required
 DENTINH R Office of Nuclear Reactor Regulation, Director B0/08/29
- ---8009030147 Bafety evaluation in support of licensee position that design & installation of site decatoring sys not required Supporting documentation encl
 # Office of Nuclear Reactor Regulation, Director 80/08/29 1600
- --8009830150 Advises of Commissioner 800416 decision not to review Director's denial of enforcement action under iOCFR2 206 CHILK.S J Office of the Secretary of the Commission 80/04/1 BO/04/17
- E007090336 Response in opposition to FM Olsen of Coulee Region Energy Coalition motion to disqualify ASLB Unfavorable rulings not evidence of bias per 1974 ALAB-224 Notices of appearances & Certificate of Svc encl HIESTAND. O S . OALLEN.K P Dairyland Power Cooperative HIESTAND. O S . Morgan, Lewis & Bockius 80/09/05 Bpp.

- 8009230001 Response to NRC second round of interrogatories Questions ability to enforce stds for protection against radiation & provisions of domestic licensing Supporting documentation encl Related correspondence HORSE.A K . NYOGARD.O R Coulee Region Energy Coalition 80/09/10
- --9009230002 Response to NRC request for admissions Denies that LACBWR is in compilance w/regulations that offgas emissions are minimal & that radiological monitoring program is adequate KORSE.A K Coulee Region Energy Caalition 80/09/11 3pp
- --8009230004 Request for admissions directed to NRC re adverse effects of offgas emissions & of radiological monitoring program BURMASTER:M Coulee Region Energy Coalition 80/09/10 2pp
- BOO9260014 Response in opposition to NRC & applicant responses which objected to intervenor request to disqualify ASLB Board errors ignoring LACBUR cost factors in hearing focussing on plant economic aspects, are grounds for disqualification OLSEN, F M Affiliation Unknown 80/09/ii 3pp
- 6007180522 Order authorizing ASLB to perform review function re hearing on issues of 800225 order to show cause CMILK,S J Office of the Secretary of the Commission 80/09/12 to
- 8009260672 Request for postponement of fuil term OL hearing until completion of show cause proceeding Intervenor human & manetary resources are insufficient to continue w/two proceedings, simultaneously MDRSE, A K Coulee Region Energy Coalition 80/09/i5 2pp
- --8009260677 Erratum to intervenor filing in response to request for admission Last paragraph of answer to Request 10.Page 3,to be disregarded Certificate of Svc enci KORSE.A K Coulee Region Energy Coaistion 80/09/15 2pp
- B009250012 Memorandum & order denying FM (1)sen B00819 motion & B00822 amend for disqualification of ASLB & referring denial to ASLAB for review BECFHQEFER.C Atomic Safety and Licensing Board Panol 80/09/19
- 800925000t Certification to Commission re Coviee Region Energy Coalition B00916 request for free hearing transcripts Applicability of new rulo re free transcript does not govern show cause cases Requests that scope of rule be broadened ECCHHOEFER.C Atomic Safety and Licensing Board Panei 80/09/22
- 6009250032 Notice of constitution of ASLAB AB Rosenthal chairman & JH Buck & TS Moore,members BIGHOP,C J Atomic Safety and Licensing Appeal Panel 80/09/22 to
- 8009260449 Decision, ALAB-614, affirming ASLB 800919 order in which FM Disen 800819 motion for ASLB disqualification was denied. Bias not established BISHDP, C J Atomic Safety and Licensing Appeal Panel 80/09/24 5pp
- 8009300008 Response in support of Coulse Region Energy Coalition 800915 request for deferral of full-term OL Suspension appropriate until completion of liquefaction show cause proceeding Certificate of Byc encl HEISTAND.

H General correspondence

- BOO9ii04il Requests establishment of LPDR in Madison, WI, on behalf of WI Public Syc Commission State agency personnel will review replacement of steam generators at Point Beach Unit 1 in 1981 or 82 Related correspondence YORKAS, PARBONS, E.M., NUNNERY, W.J. Wisconsin, Btate of BO/OB/26
- P Operating license stage documents & correspondence
- 2007110554 Suppls NRC 800707 request for proposed Tech Epecs Changes re scram discharge voi vent & drain valves, & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT, D Q Division of Licensing 80/07/22 22pp
- 8009110612 Forwards request for addl info re anchorage & support of safety-related electrical equipment CRUTCHFIELD:D Operating Reactors Branch 5 80/07/28 5pp

- 8009020297 Submits interim criteria for shift staffing to all DL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D & Division of Licensing 80/07/31 7pp
- B0090B00B0 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 enci N/o NUREG EISENHUT.D 6 Division of Licensing E0/08/01 119pp
- 8007030237 Application to amend License DPR-45 re administrative control Tech Specs Amend reflects changes in facility mot structure & staff & incorporates STS Class II amend fee encl
 LINDER.F Dairyland Power Cooperative 80/08/06 3pp
- ~-8009030243 Proposed Tech Spacs Section 6 0 for administrative controls, reflecting changes in facility mgt structure & staff 9 incorporating STS # Dairyiand Power Cooperative 83/08/06 2ipp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should (include proposed class of amend EISENHUT.D O Division of Licensing 80/08/07 60pp
- 8009220394 Responds to util 800701 itr re insp fees by forwarding corrected invoice Bafety & safeguards Pees assessed for facility are flat fees established by regulation & are based on average cost M/o enci invoice & related mat!

 MILLER, W D License Fee Management Branch 80/08/22 2pp
- B009li0746 Notification of B009i6 meeting w/SEP vwners group to discuss NRC initial review & recommendations for site-specific ground response spectra & owners group program plans for seismic functional qualification of Class IE equipment LEVIN.H A Division of Engineering 80/08/26 Ep
- 8009150042 Notification of 800908-11 meetings at plant sites w/utils to discuss environ qualification of electrical equipment PAULSON.W A Operating Reactors Branch 5 80/08/27 2pp
- B009090529 Forwards answers to questions re TMI lessons learned scope & criteria for licensing exams Procedures for feedback of operating experiences to plant staff currently under review LINDER.F Dairyland Power Couperative B0/09/03 App
- 8009290i43 Notification of 800926 meeting w/wtils & Kerr-McGee Chemical Corp in Bothesda, MD to discuss review % recommendations for site specific ground response spectra & program plans for selemic functional qualification of Class IE equipment ALLISON, D P Systematic Evaluation Program Branch 80/09/08 3pp
- B009220i45 Responds to questions forwarded w/NRC 800728 ltr re presence of voids underneath turbine bldg mat lwo borings, DM-12 & DM-13, indicated existence of minor voids in vicinity of borings Voids exist only within turbine bldg area LINDER, F Dairyland Power Cooperative 80/09/09 App
- B009260022 Notification of second rescheduling until B01003 for meeting w/SEP owners group & KKC. Inc. to discuss NRC initial review of site-specific ground response spectra & util program for selsmic functional qualification of Class IE equipment ALLISON, D.P. Bystematic Evaluation Program Branch 80/09/10 3pp
- 8009240343 Forwards revised Tech Spec Table 6 2 2-i re min shift crew composition originally submitted in 800806 application for amend to License DPR-45
 LINDER:F Dairyland Power Cooperative 80/09/16 3pp
- ---8007240350 Revised Tech Spec Table 6 2 2-1 re min shift crew composition 4 Dairyland Power Cooperative 80/09/16 ip
- Q Inspection reports, IE Bulletins & correspondence
- 8007070028 Forwards IE Bulietin 80-07. Suppl 1, "BWR Jat Pump Assembly Failure " No response required KEPPLER, J C Region 3, Chicago, Office of the Director 80/05/14 ip
- 8009260418 Forwards 1E Insp Rept 50-409/80-04 during June 1980 No noncompliance noted HEISHMAN, R F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/07/10 2pp

- --8009260420 IE insp Rept 50-409/80-04 during June 1980 Nd noncompliance noted Major areas inspected operational safety, surveillance, maint & TMI short-term mods BAKERIA R. RIDCHAYIA R. Region 3, Chicago. Office of the Director 80/07/09 5pp
- 800909000B Responds to IE Bullatin 80-20, "Failures of Hestinghouse Type M-2 Spring Return to Neutral Control Switches" Switches are not used in safety-related applications at facility LINDER,F Dairyland Power Cooperative 80/09/09 ip
- 80070700(0 Responds IE Bulletin 80-19, 'failures of Hercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " C-E did not design facility Relays are not used in reactor protective sys LINDER, F Dairyland Power Cooperative 80/08/08 ip
- 8009030196 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Morcury-Netted Matrix Relays in Reactor Protective Bye of Operating Nuclear Power Plants Designed by C-E " Nritten response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/15 in
- 8009190455 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Detween Control Rod Drive Stram Function & Nonessential Control Air at Certain GE BWR Facilities "No specific action or response requested KEPPLER. J G Region 3. Chicago. Office of the Director 80/08/20
- 8009120044 Forwards Suppl 3 to IE Bulletin 80-17. "Failure of Control Rods to Insert During Scram at BWR " Written response required KEPPLER, J O Region 3, Chicago, Office of the Director 60/08/22
- 8009170419 Forwards IE Circular 80-18, "10CFRSO 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/08/22
- 8009230087 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Bover: 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required KEPPLERJ & Region J. Chicago. Office of the Director 80/08/28
- 209220497 Forwards Revision 1 to IE Bulletin 79-26, "Boron Loss From BUR Control Blades " Written response required KEPPLER, J O Region 3: Chicago, Office of the Director 80/08/29
- 209240157 Responds to IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) w/Loss of Offsite Power " Test conducted on B00702 w/all ENS extensions operating satisfactorily LIMOER.F Dairyland Power Cooperative 80/09/02 25pg
- 800924009B Forwards 1E Circular 80-21, "Regulation of Refueling Crews" No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/09/10 Ip
- A Periodic operating reports & related correspondence
 - 09160250 Forwards monthly operating rept for Aug 1980 ENDER.F Dairyland Power Cooperative 80/09/08 ip
 - D09160253 Monthly operating rept for Aug 1980 G00DHAN,L S Dairyland Power Cooperative 80/09/08 10pp
 - Reportable occurrences, LERs & related correspondence
 - 9030454 Forwards LFR 80-005/01T-0
 INDER:F Dairyland Power Cooperative 80/08/27 5pp
 - OO9030457 LER 80-005/01T-0 on 800806 during operation valve addition to shutdown condenser shell gauge tap found w/o design change Caused by personnel error Valve was removed Pipe cap was installed 5 tested w/acceptable results
 GUDDMAN,L S Dairyland Power Cooperative 80/08/18 1p
 - 1230648 Forwards LERs 80-004/03L-0 \$ 80-007/03L-0 | NOER-F Dairyland Power Cooperative 80/09/12 | 17pp

- --8009230657 LER 80-006/03L-0 on 800814, during reactor shutdown, indicated alpha activity of primary coolant sample exceeded Tech Specs Caused by degraded fuel cladding Primary purification sys operation reduced concentration to allowable value GODDMAN.L. S Dairyland Power Cooperative 80/09/12 lp
- --8009230664 LER 80-007/O3L-0 on 800816, during reactor shutdown, indicated alpha activity of primary coolant sample exceeded Tech Specs Caused by degraded fuel cladding Primary purification sys operation reduced concentration to allowable value GOODMAN, L. S. Dairyland Power Cooperative 80/09/12 1p
- 8009260630 Forwards LER 80-008/03L-0 LINDER, F Dairyland Power Cooperative 80/09/19 3pp
- --8009260436 LER 80-008/03L-0 800819,18 high pressure svc water diespidid not start on manual activation Diesel did start locally from battery banks Caused by bad cell in one 8 bank battery Battery replaced GOOMAN.L S Dairyland Power Cooperative 80/09/19 ip
- T Hearing transcripts on non-antitrust matters
- 8009190763 Transcript of 800911 prehearing conference re show cause order in La Crosse.WI Pp 1-67 * Atomic Safety and Licensing Board Panel, 80/09/11 68pp
- 8009260095 Transcript of B00911 Affirmation Session 80-40 in Washington.DC re delegation of review authority in LaCrosse proceedings Pp 1-4 * Commission 80709711 App
- DOCKET 50-410 NINE MILE POINT NUCLEAR STATION. UNIT 2

 A Application/construction stage decuments & correspondence
- BOO70BOO80 Forwards draft NURES-0696, "Functional Criteria for Emergency Response Facilities ' Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NURES EIBERHUT, D O Division of Licensing 80/08/01 119pp
- 8009020248 Responds to NRC 800728 request re latest const completion date Schedule & reasons for delay in completion of const will be submitted by 810131 RMDDE-6 K Niagara Hohawk Power Corp 80/08/27 1p
- 8009090035 Submits interim actions for plant operation, pending final resolution of ATWS Emergency operation procedural review may include NAC site visit prior to issuance of OL TEDESCO:R L Assistant Director for Licensing 80/08/29 3pp
- 8009:10742 Notification of B00904-05 meeting w/Mark II owners group to discuss plants chugging C/O & lateral load specs ANGERSON.C Containment Systems Branch B0/08/29 14pp
- 8009110633 Notification of 800903 trip to facility to investigate terrestrial ecology of site for cooling tower rept review KIPER.K L Licensing Branch 1 80/09/02 2pp
- 8009150551 Requests NRC review of Oulf & Western FBD-2538 re main steam valve Review is needed by 801231 to maintain current engineering & const schedule RHDDE: G K Niegara Mohawk Power Corp 80/09/08 1p.
- BOO9150560 Forwards requests for add1 info re proposed cooling tower for plant. TEDESCO.R L Assistant Director for Licensing 80/09/09. 4PP
- 800924033 Summary of 800814 meeting w/util,8&W & Dyckerhoff & Widmann. Inc in Bethesda.MD re application of the DywiDay Threadbar Bys on secondary containment structure KIPER.K L Licensing Branch I 80/09/09, 4pp
- G Inspection reports. IE Bulletins & correspondence
- 8009090087 Forwards IE Bulletin 80-07, Suppl 1, "BWR Jet Pump Assembly Failure" No response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/05/13 1p
- B0070504B2 Forwards IE Insp Rept 50-410/80-04 on 800512-15.No noncompliance noted CARLSON.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/10 2pp

- --8007050426 IE Insp Rept 50-410/80-04 on 800512-15 No noncompliance noted Major areas inspected repair activities associated u/biological shield wall TRIPPLE E Region i. Philadelphia, Reactor Construction & Engineering Support Branch MCBREARTY, R A . WALTON, G A Region i. Philadelphia, Office of the Director 80/07/08 6pp
- 8009150092 Forwards IE Insp Rept 50-410/80-05 on 800617-19 No noncompliance noted CARLSDN.R T Region i. Philadelphia, Reactor Construction & Engineering Support Branch 80/07/17 2pp
- --8009150097 IE Insp Rept 50-410/80-05 on 800617-19 No noncompliance noted Hajor areas inspected licensee action on previous findings & cadwelding on containment floor & uall MCGAUCHY.R W Region 1. Philadelphia, Reactor Construction & Engineering Support Branch Fell.R Region 1. Philadelphia, Office of the Director 80/07/16 Spp
- 8009230098 Responds to IE Bulletin 79-03A re use of SA-312 or A-312, Type 300 fusion welded pipe Analysis determined that identified piping will not be subj to stresses greater than code allowable No action required RHODE.O K Niagara Mohawk Power Corp 80/08/06 2pp
- ECOSOGO097 Forwards Revision 1 to 16 Bulletin 80-19. "Failures of Marcury-Weited Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-6 " Written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/08/15 1p
- 8009120095 Forwards Suppl 3 to 1E Bulletin BO-17, "Failure of Control Rods to Insert During Scram at BWR" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/08/22 1p
- 8009180023 Forwards IE Circular 80-18. "100FR50 59 Bafety Evaluations for Changes to Radwaste Treatment Sys " No written response required ORIER,8 H Region I, Philadelphia, Office of the Director 80/08/22 1p
- 8009120193 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover: 480 Volt Type K-6008 & K-DDN 6008 Circuit Broakers " No written response required CRIER, B H Region I. Philadelphia. Office of the Director 80/08/27 10
- 8009240033 Forwards IE Circular 80-21, "Regulation of Refueling Crews"
 No written response required
 GRIER, B H Region 1, Philadelphia, Office of the Director
 B0/09/10 1p
- 8009240323 Forwards IE Info Notice BO-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matis " No written response required CRIER.B H Region 1, Philadelphia, Office of the Director 80/09/12 ip
- S Reportable occurrences, LERs & related correspondence
- B009070839 Ack receipt of final deficiency rept re environ & seismic qualification of electrical equipment CARLEDN.R T Region 1. Philadelphia, Reactor Construction & Engineering Eupport Branch 80/08/20 1p
- 8007090844 Ack recupt of 800724 ltr re potential deficiency in radwasts bidg geologic feature CARLEON.R T Region 1, Philadelphia, Reactor Construction & Engipeering Support Branch 80/08/20 ip
- ---8009090848 Interim deficiency rept re potential deficiency in possible future movement of radwaste bldg geologic feature Forwards response to Ofc of Nuclear Reactor Regulation Geologic Info Request 00361 i Final rept will be submitted by 801231 RMODE.O K Niagara Mohawk Power Corp 80/07/24 11pp
- DOCKET 50-412 BEAVER VALLEY POHER STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 9007080080 Forwards draft NUREO-0496, "Functional Criteria for Emergency Response Facilities "Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/a NUREO EISEN-MY-TD 0 Division of Licensing 80/08/01 119pp

- I Financial information
- 8007230599 Apprises NRC of facts re proposed temporary transfer by OH Edison Co of ownership interest in facility Comership interest will be transferred to Const Trust which will not be involved in const & operation mafters or plant BYINGTON, J.H. Winthrop, Stimson, Putnam & Roberts 80/09/19 Spp
- Q Inspection reports, IE Bulletins & correspondence
- 8009100865 Forwards IE Insp Rept 50-412/80-07 on 800707-10 No noncompliance noted CARLSGN:R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/25 2pp
- --B009100B70 IE Insp Rept 50-412/B0-07 on B00707-10 No noncompliance noted Major areas inspected welding of structural angle clips to embedment plates, installation of snubber supports & unloading of steam generator supports MARROW.L. Region 1, Philadelphia, Office of the Director MCGAUGHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch B0/07/24 7pp
- 9007030075 Forwards Revision 1 to IE Bulletin 80-17. "Failures of Mercury-Watted Matrix Relays in Reactor Protective Sys of Operating Muclear Power Plants Designed by C-E " Written response required ORIER.3 H Region 1. Philadelphia. Office of the Director 80/08/15 1p
- B009180483 Forwards IE Circular 60-18 "10CFR50 57 Safety Evaluations for Changes to Raduaste Treatment Sys " No written response required GRIER.B H Region 1. Philadelphia. Office of the Director B0/09/22 to
- 8009120219 Forwards 1E info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Voit Type K-6008 & K-DOM 6008 Circuit Breakers " No written response required ORIER B H Region i. Philadelphia, Office of the Director 80/09/27 1p
- 8009240031 Forwards 1E Circular 80-21, "Regulation of Refueling Crews" No written response required GRIER, B H Region 1. Philadelphia. Office of the Director B0/09/10 lp
- 8009240342 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required GRIER, B H Region i, Philadelphia, Office of the Director 80/09/12 1p
- S Reportable occurrences, LERs & related correspondence
- BOO9090248 Final Significant Deficiency Rept 80-04 re misapplication of welding electrode E-309-(6 Increased emphasis placed on verification of mechanical contractor electrode control program by creating welding supervisor position WOOLEVER.E J Duquesne Light Co 80/09/04 6pp
- DOCKET 50-413 CATAMBA NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- BD09080080 Forwards draft NUREG-0676, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl W/o NUREG EISENHUT, D O Division of Licensing E0/08/01 119pp
- 8009040434 Forwards math re NRC review of ice condenser containment & hydrogen control measures for Sequeyah Nuclear Power Plant ACRB has scheduled meetings in Washington, DC on 800828, 0702 & 04 to discuss issue TEDESCO, R L Assistant Director for Licensing 80/08/22 5pp
- 8009190399 Responds to NRC 800520 ltr re NUREO-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PUR Steam Generator & Reactor Coolant Pump Supports " (to response needed.pending add1 NRC guidance PARKER.N O Duke Power Co 80/09/14 Lp
- O Inspection reports, IC Bulletins & correspondence
- 8009110423 Ack receipt of IE Imap Repts 50-413/80-13 & 50-414/80-13 on B00418-20 No proprietary info PARKER, U Duke Power Co 80/08/13 ip

- -8009110425 Forwards IE Insp Repts 50-413/80-13 & 50-414/80-13 on 800s18-20 No noncompliance noted MJRPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/23 2pp
- -8009110427 IE Insp Repts 50-413/80-13 & 50-414/80-13 on 800618-20 No noncompliance noted Major areas inspected field performance, drawings & work procedures, engineering, QC, matls & equipment. procurement, receiving & storage COM,ON.TE Region 2, Atlanta, Reactor Constructson & Engineering Support Branch BROWNLES,V L. BURDETTE,TE Region 2, Atlanta, Orfice of the Director 80/07/23 App Support Branch BROWNE
- 009030175 Forwards Revision I to IE Bulletin 60-17, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Reg Region 2. Atlanta. Office of the Director 80/08/15
- 309170371 Advises that final response to SE Bulletin 80-09 not submitted due to necessary info not available from vendors Final rept expected by 801201 PARKER,W O Dute Power Co 83/09/15 1p
- 109140642 Responds to 1E Bulletin 80-20 re failures of Westinghouse W-2 spring return to neutral control switches identified switches are not used or planned for use in safety-related areas Thirteen menhours expended for review PARKER, NO Consumers Power Co. 60/08/20 ip
- 09140137 Forwards 1E Circular 80-18. "IOCFR50 S9 Gafety Evaluations for Changes to Radwaste Treatment Sys " No written response required
 O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/22
- 09120343 Forwards 1E Info Natice 80-31, "Maloperation of Gould-Brown Bover: 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required O'REILLY.U P Region 2, Atlanta, Office of the Director 80/08/27
- 09120587 Responds to IE Bulletin 80-19 Mercury-wetted matrix relays are not used or planned for use in reactor protection sys PARKER.N 0 Duke Power Co 80/08/28 1p
- 19240202 Ack receipt of 800819 ltr informing NRC of steps taken to orrect violation noted in 1E Insp Repts 50-413/80-10 & 30-414/80-10 Wighth, C.E. Region 2. Atlanta Reactor Construction & Engineering Support Branch 80/09/02 1p
- 3009240290 Responds to NRC 600623 itr re violations noted in IE Imag Repts 50-413/80-10 & 50-414/80-10 Corrective actions util uill imag addl component support welds PARKER,U G Duke Power Co 80/08/19 ip
- 009240294 Act receipt of 600715 ltr informing NRC of steps taken to correct violation noted in 1E Insp Repts 50-413/80-10 & 50-414/80-10 Requests addi response MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/08/12 ip
- 007240298 Responds to NRC 600623 ltr re violations noted in IE Insp Repts 50-413/80-10 & 50-414/80-10 Corrective actions insp of component support welds initiated PARKER.W D Dute Power Co 80/07/15 2pp
- 009240302 Forwards IE insp Repts 50-413/80-10 & 50-414/80-10 on 800527-20 & notice of violation HVRPHY,0 E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/06/23 2pp
- 109240306 Notice of violation from insp on 800527-30 * Region 2, Atlanta, Office of the Director 80/0 80/06/20 1p
- 109240313 IE Insp Repts 50-413/80-10 \$ 50-414/80-10 on 800527-30 Noncompliance noted undersized fillet wold HERDT. A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch KLEINSORGE, W P. COLEY, J. L. Region 2, Atlanta, Office of the Director 80/06/20 10pp
- 240292 Ack receipt of 800919 ltr informing NRC of steps taken to rrect violations noted in IE lnsp Repts 50-413/80-15 t -414/80-15 RPHY, C E Region 2. Atlanta Reactor Construction & Engineering pport Branch 80/09/02 lp

- --8009240297 Responds to NRC 800725 ltr re violations noted in IE lnsp Repts 50-413/80-15 & 50-414/80-15 Corrective actions GC welding inspectors restrained in requirements of GA procedures M-19 & M-4 Emphasis placed on documentation PARKER,W O Duke Power Co 80/08/19 2pp
- --80092403)7 Forwards 1E Insp Repts 50-413/80-15 & 50-414/80-15 on 800530-0703 & notice of violation MURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/25 2pp
- --8009240314 Notice of violation from insp on 800630-0703
 * Region 2. Atlanta, Office of the Director 80/07/3
- --8007240320 IE lasp Repts 50-413/80-15 t 50-414/80-15 on 800630-0703 Nancompliance noted failure to document GC welding surveillance
 HERDI,A R Region 2, Atlanta, Reactor Construction & Engineering
 Support Branch VANDOORN,P K Region 2, Atlanta, Office of the
 Director 80/07/25 App
- 8009250339 Ack receipt of IE lnsp Repts 50-413/80-20 & 50-414/80-20 on 800804-05 No propiletary info PARAER. N O Dute Power Co 80/09/09 ip
- --800725034; Forwards JE lnsp Repts 50-413/80-20 & 50-414/80-20 on 800804-08 No noncompliance noted INRPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 60/08/25 2pp
- ---8009250343 IE Insp Repts 50-413/80-20 & 50-414/80-20 on 800804-09 No noncompliance noted Major areas inspected structural concrete storage & preventive maint & const progress HARRIS, J R Region 2. Atlanta, Office of the Director COLLON, T E. Region 2. Atlanta, Peactor Construction & Engineering Support Branch 80/08/22 3pp
- 8009290297 Forwards IE Circular 80-21. "Regulation of Refueling Crews " No written response required Q'REILLY, J P Region 2. Atlanta, Office of the Director 80/09/10
- S Reportable occurrences, LERs & related correspondence
- 8009080312 Significant Deficiency Rept 413-414/80-11 re nonseismically qualified battery racks supplied w/dissel generator unit batteries Causud by manufacturer error Three new racks will be fabricated in accordance w/proper drawings & specs PARKER, U.O. Duke Power Co. 80/08/28 3pp
- DOCKET 50-414 CATAWBA NUCLEAR STATION, UNIT 2 A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREO-0694, "Functional Criteria for ovrocoded rorwards eract NOMES-U-0070, "Punctional Uniterial for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria set NURGE-0-6376 encl M/o NUREO EISERHUT.D C Division of Licensing 80/08/01 119pp
- 8009040434 Forwards mati re NRC review of ice condenser containment & hydrogen cuntral measures for Sequoyah Nuclear Power Plant ACRS has scheduled meetings in Washington, DC on 800828, 0902 & 04 to discuss issue.

 TEDESCO.R L Assistant Director for Licensing 80/08/22 5pp
- 8009190397 Responds to NRC 800520 ltr re NUREO-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PNR Steam Conerator & Reactor Coolant Pump Supports " No response needed.pending add1 NRC guidance PARKER.N O Duke Power Co 80/09/16 ip
- Q Inspection reports. IE Bulletins & correspondence
- 8009110423 Ack receipt of IE Insp Repts 50-413/80-13 & 50-414/80-13 on 800618-20 No proprietary info PARKER, W O Duke Power Co 80/08/13 ip
- --8009110425 Forwards 1E Insp Repts 50-413/80-13 & 50-414/80-13 on 800618-20, No noncompliance noted MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/23 2pp

- --B009110427 IE Insp Repts 50-413/80-13 & 50-414/80-13 on 800618-20 No nancompliance noted Major areas inspected field performance, drawings & work procedures engineering GC, matls & equipment, procurement receiving & storage CONLON.T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch BROWNLEE.V L. BURDETTE.T E Region 2, Atlanta, Office of the Director 80/07/23 6pp
- BOO9030575 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/15
- 8009170371 Advises that final response to IE Bulletin 80-09 not submitted due to necessary info not available from vendors Final rept expected by 801201 FARKER.W O Duke Power Co 80/08/15 ip
- BO09160642 Responds to IE Bulletin 80-20 re failures of Heatinghouse M-2 spring return to neutral control switches Identified switches are not used or planned for use in safety-related areas Thirbeen manhours expended for review PARKER, N O Consumers Power Co 80/08/20 ip
- 8009160137 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Bys " No written response required
 D'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22
 19
- BOO9120343 Forwards IE Info Notice BO-31, "Maloperation of Oould-Brown Bovert 480 Voit Type K-6008 & K-DON 6008 Circuit Breakers " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director BD/08/27 10
- EOO9120587 Responds to IE Bulletin 80-19 Mercury-wetted matrix relays are not used or planned for use in reactor protection sys PARKER, IO Duke Power Co 80/08/28 1p
- BOO9240282 Ack receipt of BOO819 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-413/80-10 & 50-414/80-10 MURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering
- --8007240270 Responds to NRC 800623 ltr re violations noted in 1E Insp Repts 50-4(3/80-10 & 50-414/80-10 Corrective actions util util insp addl component support welds PARKER.H O Duke Power Co 80/08/19 ip
- --8009240274 Ack receipt of 800715 ltr informing NRC of steps taken to correct violation noted in IE insp Repts 50-413/80-10 & 50-414/80-10 Requests addl response MURPHY.C E Region 2, Atlanta, Roactor Construction & Engineering Support Branch 60/08/12 lp
- --B009240298 Responds to NRC 600623 itr re violations noted in 1E Insp Repts 50-413/80-10 & 50-413/80-10 Corrective actions insp of component support welds initiated PARKER.H O Duke Power Cd 80/07/15 2pp
- --8009240302 Forwards IE Insp Repts 50-413/80-10 & 50-414/80-10 on 800527-30 & notice of violation MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/06/23 2pp
- --BO09240306 Notice of violation from insp on 800527-30
 * Region 2, Atlanta, Office of the Director 80/06/20 ip
- --8009240313 IE Insp Repts 50-413/80-10 & 50-414/80-10 on 800527-30 Mancompliance noted undersized fillet weld HERDT, A.R. Region 2. Atlanta, Reactor Construction & Engineering Support Branch KLEINSORGE, N.P., GOLEY, J.L. Region 2. Atlanta, Office of the Director 80/06/20 10pp
- 8009240292 Ack receipt of 800919 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/80-15 & 50-414/80-15 MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/02 ip
- --8097240297 Responds to NRC 800728 itr re violations noted in 1E Insp Repts 50-413/80-15 & 50-414/80-15 Corrective actions GC welding inspectors restrained in requirements of GA procedures M-19 & M-4 Emphasis placed on documentation PARAER, H O Duke Power Co 80/08/19 2pp

- ~-E009240307 Forwards IE Insp Repts 50-413/80-15 & 50-414/80-15 on 800830-0703 & notace of violation MURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/25 2pp
- --8009240314 Notice of violation from insp on 800630-0703 * Region 2, Atlanta, Office of the Director 80/07/25 ip
- ~-8009240320 IE insp Repts 50-413/80-15 t 50-414/80-15 on 800630-0703 Noncompliance noted failure to document QC weiding surveillance HERDT,A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch VANDODRN,P K Director 80/07/25 6pp
- 8009250339 Ack receipt of IE Insp Repts 50-413/80-20 & 50-414/80-20 on 800804-08 Mo proprietary info PARKEN.N D Duke Power Co 80/09/09 1p
- --B009250341 Forwards IE Insp Repts 50-413/80-20 & 50-414/80-20 on 300804-08 No noncompliance noted MURPHY,C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch B0/08/25 Zpp
- --8009250343 IE Insp Repts 50-413/80-20 % 50-414/80-20 on 800804-08 No noncompliance noted Major areas inspected structural concrete, storage & preventive maint & const progress HAPRIS, J. R. Region 2, Atlanta, Office of the Director CONLON, T.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/22 3pp
- 8009296297 Forwards IE Circular 80-21, "Regulation of Refueling Crows" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/10 Soo
- S Reportable occurrences, LERs & related correspondence
- 8009080312 Significant Deficiency Rept 413-414/80-11 re nonseismically qualified battery racks supplied w/diesel generator unit batterios Caused by manufacturer error Three new racks will be fabricated in accordance w/proper drawings & specs PARKER, NO Duke Power Co 80/08/28 3pp
- DOCKET 50-414 GRAND OULF NUCLEAR STATION. UNIT I

 A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/o NUREO EISENNUT.D G Division of Licensing 80/08/01 119pp
- 8009020413 Forwards Amend 42 to application for OL, consisting of responses to NRC questions re FSAR 2. assorted matters & including miscelianeous refinements of design info Revised P&IDs encl
 RCGAVONIV, J P Mississippi Power & Light Co 80/08/29 ip
- --8009020419 Amend 42 to application for OL. consisting of responses to NRC questions re FSAR & assorted matters & including miscellaneous refinements of design info Mississippi Power & Light Co 80/08/29 2pp
- --8007020423 Amend to FSAR, constituting Amend 42 to application for OL Mississippi Power & Light Co 80/08/29 300pp
- --8009020427 "P\$ID Diagram Fuel Pool Cooling & Cleanup Sys, Unit 1 " * Decktel Corp 9645 80/06/26 1p
- ~~8009020430 "Public Address Sys Riser Diagram, Unit 1 & Common "
 * Bechtel Corp 9645 80/02/07 1p
- --8009020434 "Public Address Sys & Public Telephone Riser Diagram.Unit 1 Common" 4 Eechtel Corp 9645 60/01/02 1p
- --8009020438 "Public Address Sys Riser Diagram.Unit 2 " * Bechtel Corp 9645 78/12/21 1p
- B009050352 Forwards "Environ Protection Program Presperational Monitoring Rest " DALE, LF Mississippi Power & Light Co 80/08/29 1p

- --8009050356 "Environ Protection Program Preoperational Monitoring Rept "
 4 Mississippi Power » Light Co 80/08/29 23pp
- 8009:90099 Forwards request for add1 info resulting from FSAR review Outstanding items include assessment of degree of damage due to tornado generated missles & description of amplification factors used in plant design
 TEDESCO, R L Assistant Director for Licensing 80/08/29 17pp
- 8009110943 Notification of 800923-24 meetings w/ufil.Bechtel.GE & Savannah River Lab to review facility sys & discuss Reactor Sys Branch questions MARTORE J A Licensing Branch 3 80/09/04 2pp
- 8009230235 Notification of 800917 meeting w/util, CE & Savannah River Lab in Bethesda, MD to discuss applicant approach to HPCS Level 8 trip logic MARTURE, J.A. Licensing Branch 3 80/09/04 2pp
- BOO9150425 Expresses concern at meeting licensing schedule milestones, due to lack of NRC activity on second round questions Requests for addl info should be made immediately or questions should be replaced by draft SER for branches LUTKEN.D C Mississippi Power & Light Co 80/09/08 2pp
- BOO9150493 Endorses draft SER approach to formulating SER in comparing draft SER approach w/formal question method approx 225 manhours saved in mechanical engineering using draft SER approach

 LUTKEN.O C Mississippi Power & Light Co 60/09/00 2pp
- 8009260531 Forwards request for addl info re FSAR FSAR should be amended to reflect responses TEDESCORL Assistant Director for Licensing E0/09/09 9pp
- 8009230454 Confirms 800916 talcon re 800923 meeting to discuss resolution of GE supplied radiography problem at facilities MCGAUGHY, J.P. Mississippi Power & Light Co. 80/09/17 lp
- 8009300437 Forwards response to NRC Questions 031 56.031 71 % revised responses to Questions 031 38.031 54.031 60 & 031 75 Responses will be incorporated into Oct \$980 amend to FSAR DALE.L F Mississippi Power & Light Co 80/09/22 102pp
- F Socurity, medical, emergency & fire protection plans
- 8009180002 Summary of 800813 meeting w/otil & NVSAC in Bethesda.HD re physical security plan MARTORE, J.A. Licensing Branch 3 80/09/09 3pp
- (General correspondence
- 1009030804 Informs NRC of organizational changes which will be incorporated into Revision 2 of operational OA nanual scheduled for submittat in Dec 1980 REAVES.TE Mississippi Power & Light Co E0/08/27 lp
- Utility Final Safety Analysis Report (FSAR) & amends
- 009150489 Forwards affidavit of svc on distribution of Amend 42 to FGAR
 DALC.L F Mississippi Power & 1.1ght Co 80/09/08 2pp
- Inspection reports, IE Bulletins & correspondence
- H009090049 Forwards IE Bulletin 80~07. Suppl 1, "BWR Jet Pump Assembly Failure" No response required C'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/13 lp
- 8009120135 Forwards IE losp Repts 50-416/80-14 & 50-417/80-10 on 600603-06 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 60/07/21 2pp
- --8039120141 IE insp Repts 50-416/60-14 & 50-417/80-10 on 800603-06 No noncompliance noted Major areas inspected electrical equipment in-place storage & licensee actions on prior items MALYERS.D K Region 2. Atlanta. Office of the Director COULCULT E Region 2. Atlanta. Reactor Construction & Engineering Gupport Branch 80/07/21 5pp
- 8009120143 Forwards IE Insp Rept 50-416/80-15 on 800528-0627 No noncompliance noted LENIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/07/22 2pp

- --8009120240 IE Insp Rept 50-416/80-15 on 800528-0627 No noncompliance noted Major areas inspected preoperational test status, administrative QA & independent insp effort WAGNER,A G Region 2, Atlanta, Office of the Director KELLGOG,P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/07/22 3pp
- 8009020218 Submits response to IE Bulletin 79-03A No SA-312 Type 304 series piping used in any safety-related sys at greater than 85% design stress Requests extension until 800901 to complete review of bulletin DALE.L F Mississippi Power & Light Co 80/08/06 1p
- 8009020292 Requests extension until 800901 to complete investigation in response to 16 Bulletin 80-08, "Examination of Containment Liner Penetration Welds"

 DALE, F Mississippi Power & Light Co 80/08/15 lp
- 8009030\$20 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/15 to
- BO09160036 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Red Drive Scram Function & Nonessential Control Air at Certain GE BUR Facilities " No specific action or response requested O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/08/59 ip
- 8009230092 Forwards response to 1E Bulletin 80-09 Penetration closure details enc1 Radiography used for all full ponetration butt welds Final response espected by 801015 DALE.L F Mississippl Power & Light Co 80/08/21 14pp
- B009120080 Forwards Suppl 3 to 1E Builetin 80-17, "Failure of Control Rods to Insert During Scram at BWR" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director. 89/08/22
- tp
- 8009160115 Forwards IE Circular 80-18, "1007830 59 Safety Evaluations for Changes to Radwaste Treatment Bys " No written response required O'RE(LLY, J P Region 2, Atlanta, Office of the Director 80/08/22 to
- 8007110681 Responds to IE Bulletin 80-16 Ten Rosemount, Inc Model 1151A transmitters schoolled to be used in safety-related applications were purchased Transmitters will be replaced before fuel loading DALE.L F Kississippi Power & Light Co 80/08/27 2pp
- 8009120260 Forwards 1E Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Voit Type K-600S & K-DON 600S Circuit Breakers "
 No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/27
- 8009240318 Ack receipt of 800730 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-416/80-07 & 50-417/80-07 STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/08/28 ip
- --8009240331 Responds to NRC 800423 ltr re violations noted in IE Imap Repts 50-416/80-07 & 50-417/80-06 Corrective actions dredging operations will be completed by 800905 ICCOMUDITY, J. P. Massissippi Power & Light Co. 80/07/30 | 1p
- 8009080328 Responds to violation noted in IE Insp Repts 50-416/80-16 & 50-417/80-17 Corrective action constructor reinspected 513 ABMS socket welds to determine extent to which welds are undersized in safety-related applications (MCGAU3HY, J P Mississippl Power & Light Co 80/08/27 2pp
- 8009290271 Forwards IE Circular 80-21, "Regulation of Refueling Creus" No written response required O'RETILLY, J.P. Region 2. Atlanta, Office of the Director 80/09/10 San
- 8009300026 Ack receipt of 800829 % 0902 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 30-416/80-16 % 50-417/80-11 MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/11 ip

- --8009300029 Responds to NRC 800805 ltr re violations noted in IE Imap Rapts 50-416/80-16 & 50-417/80-11 Corrective actions constructor audit procedures revised to allow documentation of concerns found & corrected during audit MCGAUCHY, J P Mississippi Power & Light Co 80/09/02 2pp
- --8009300031 Forwards IE Insp Repts 50-416/80-16 & 50-417/80-11 on 800715-18 & notice of violation HURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/08/05 2pp
- --8009300034 Notice of violation from Insp on 800715-18
 * Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/08/05 Ip
- --B009300041 IE Insp Repts 50-416/80-16 & 50-417/80-11 on 800715-18
 Noncompliance noted acceptance of undersize socket welds &
 fallure to follow procedure for documentation of audit
 findings
 CROMLEY.8 R Region 2. Atlanta, Office of the Director
 HARDT, AR Region 2. Atlanta, Reactor Construction & Engineering
 Support Branch 80/08/05 App
- 8009230627 Final deficiency rept re design nomographs used in stiling & selection of hydramotor electrohydraulic actuators supplied by ITT General Controls Condition determined not reportable under 100FRSO 55(e) RCOAUGHY, J P Mississippi Power & Light Co 80/09/15 2pp
- --8009230642 Advises no other application determined for NH90 Series Andramotor actuators No further action planned per IE Bulletin 80-09 DALE, F. Mississippi Power & Light Co. 80/07/28 lp
- S Reportable occurrences, LERs & related correspondence
- E009100565 NO Status Rept 3 on 800129, hand switch CR-2940-US203E supplied by GE failed to operate Util AE & Bechtel Power Corp will evaluate switches Final rept to be submitted by 800918
 MCGAUSHY, J.P. Mississippi Power & Light Co. 80/06/18 2pp
- BOO6270284 Deficiency rept re radiographs supplied by contractors to NSSB vendors which failed to meet ASME code requirements Radiograph components analyzed Final rept & determination of reportability by Oct 1980 MCGAUGHY.J P Mississippi Power & Light Co BO/06/20 2pp
- 6009100335 Deficiency rept to radiographs supplied by contractors to NSSB vandors which failed to meet ASME code requirements Radiograph components boing analyzed Final rapt & determination of reportability by Oct 1980 MCGAUCHY. J P Mississippi Power & Light Co 80/06/20 2pp
- BOOTIO0436 Btatus Rept 2 re electrical cable insulation damaged during pulling process Damaged cable would not affect plant safety Final rept & determination of reportability by BioI31 MCGAUCHY, J. P Mississippi Power & Light Co 80/06/23 App
- 8009100558 RO Status Rept 2 on 800313 electrical cable insulation damaged during pulling process Caused by poly-propylene pulling rope damaging cabies Cablos replaced Training session initiated Final rept to be submitted by 810131 MCGAUGHY, J. P. Mississlppi Power & Light Co. 80/06/23 3pp
- 8009100519 Deficiency rept re Rosemount Model 510 DU trip/calibr units & Model \$152 pressure transmitters Final ropt re trip units will be submitted by 801022 Final rept re pressure transmitters encl
 MCGAUGHY, J P Mississippi Power & Light Co 80/06/24 5pp
- 8009100592 Final deficiency rept re design nomographs used in siring & selection of General Controls hydromotor electrohydraulic actuators Forwards 800616 response to IE Bulletin 80-09 Final rept to be submitted by 800915 KCGAUUHY, J P Mississippi Powor & Light Co 80/07/21 2pp
- B009040489 Status Rept 2 of deficiency re nonconforming calibr sycs provided by Computer Sciences Gorp Final rept by 800822 MCGAUGHY. J P Minnesota Power & Light Go 80/07/22 1p
- 8007150062 Part 21 rept re power plant noncomplying vaives Reanalysis 70% complete Corrective action involves design changes & review by customer engineering & field personnel High priority on vaives which must meet increased loading NIENAUS,P W William Powell Co 80/08/03 2pp

- BOO9100303 Final deficiency rept re incorrect bolt torquing on HPCS pump Deficiency could have caused pump degradation by subsequent failure Pumps disassembled & retorqued to Field Disposition Instruction 32-42382 MCGAUGHY. J P Mississippi Power & Light Co 80/0B/04 4pp
- 8009100347 Status rept re feedwater pipe bend below design min wall thickness Feedwater pipe supplier uill perform evaluation of pipe & bending process Unit 1 pipe will be ultrasonically tested final rept will be submitted by 801211 MCGAUCHY.JP Mississippi Power & Light Co 80/08/04 2pp
- 8009020064 Interim deficiency tept to calibr svcs provided by Computer Sciences Corp Evaluation of investigation results not completed Final rept to be submitted by 800930 MCGAUCHY, J.P. Mississipp: Power & Light Co. 80/08/21 2pp
- 8009080249 Second interim deficiency mept no incorrect pipe supplied by TK Pipe Bending Heavier wall of spool will not cause overstressed condition on pipe support sys in application final rept expected by 801010 KCCAUCHY, JP Kississippi Power & Light Co 80/08/29 1p
- B0090B0376 Interim deficiency rept re fractured actuator to damper shaft couplings in diesel generator bldg bay A Final evaluation to be completed by B01219 MCGAUGHY.J P Mississippi Power & Clight Co 80/08/29 Ip
- B009100486 Interim deficiency reptile installation of expansion anchors for conduit hangers, instrument process tubing & air supply supports w/o proper approval Procedures have been revised Final ropt will be submitted by 80illi MCGAUOHY. J P Mississippi Power & Light Co 80/09/03 lp
- 8009190301 Interim deficiency rept to inadequate control of supplier drawing revision notice program investigative action resulted in issuance of 34 nonconformance documents Procedure controlling notices revised final rept by 810122 MCOAUGHY, J.P. Mississippi Power & Light Co. 80/09/05 2pp
- 800916059: Interim deficiency rept re possibility of infloctive insulation in annular space between reactor vesse: & shield disindging during LOCA & thearing reactor pressure vesse: level sensing lines Final rept will be forwarded on 810515 MCGAUGHY, J.P. Mississippl Power & Light Co. 80/09/08 3pp
- 80092504i7 Part 21 rept re defects in diesel generator control panels mfg by Intl Control & Switchgear Co Equipment is being repaired per FDBR JBI-940 under supervision of Morrison-Knudsen Co MCOAUCHY, J.P. Mississippi Power & Light Co MO/09/08 3pp
- BO09260473 interim deficiency rept re failure of GE subcontractor 1%SE to establish & implement approved QA program for electrical work performed under GE field deviation requests & instructions Results of GE reinspection expected by Rj0131 MCGAUGHY.J P Mississipp: Power & Light Co 80/09/08 2pp
- 8009160387 Second interim deficiency rept re defective leak detection equipment used to qualify Farr Co NPP-2 carbon filters for use in control room standby air units Filters have been returned to vendor final rept will be submitted by 801125 MCGAUGHY. J P Mississippi Power & Light Co 80/09/09 2pp
- 8009230556 Interim deficiency rept, per iOCFR50 55(e) & Part 21 re Hiltl Fastening Sys, Inc. anchor bolt pull out strength Specific applications of one-inch diameter KUIK bolts are being investigated Final rept will be filed by 801104 MCOAUGHY, J P Mississippi Pawer & Light Co 80/09/12 lp
- 800923047: Interim deficiency rept re discrepancies in design documentation for Power Generation Control Complex panels & associated delivered hardware No deficiencies discovered that would adversely affect safety of operations MCGAUGHY, J P Mississippi Power & Light Co 80/09/15 2pp
- 8009230627 Final deficiency rept re design nomagraphs used in sizing & selection of hydramotor electrohydraulic actuators supplied by ITT General Controls Condition determined not reportable under 100FR50 55(s) MCGAU3HY, J P Mississippi Power 5 Light Co 80/09/15 2pp
- --B009230642 Advises no other application determined for NH70 Beries hydramotor actuators No further action planned per IE Bulletin B0-09 DALE,L F Mississippi Power & Light Co 80/07/28 1p

- 8009230595 Interin deficiency rept re unqualified cable insulation repairs in 680-volt cable supplied by Rockbestos Investigation continuing involving safety implications of deficiency Final rept by 801216 MCGAUGHY. J P Mississippi Power & Light Co 80/09/14 2pp
- 8009240438 Final deficiency rept re failure of handswitch CR2940-U5203E in nonsafety related area of plant svc water sys Investigation indicates that deficiency does not stist in safety related sys % is not reportable per 10CFRSO 55e MCGAUGHY.J P Hississippi Power & Light Co 80/09/16 2pp
- BOOS2404BO Final deficiency rept re incorrect translation of weld requirements from design drawings to field sketches Erroneous welding direction corrected Future field sketches will include instruction to rerer to design drawing MCGAUGHY. J P Mississippi Power & Light Co 80/09/16 Rpp
- DOCKET 50-417 CRAND GULF NUCLEAR STATION. UNIT 2
- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREO-0696. 'Functional Criteria for Emergency Response Facilities' Commants requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 enci M/o NUREO EISENMUT.D O Division of Licensing 80/08/01 119pp
- 8009020413 Forwards Amend 42 to application for DL, consisting of responsas to NRC questions re FSAR & assorted matters & including misceilaneous refinements of design info Revised P&1Ds enct MCGAUGHY.J P Mississippi Power & Light Co 80/08/29 1p
- --8009020458 Amend 42 to application for OL-consisting of responses to MRC questions re FSAR A assorted matters & including miscellaneous refinements of design info # Mississippi Power & Light CO 80/08/29 2pp
- ---8009020423 Amend to FSAR.constituting Amend 42 to application for OL + Mississippt Power & Light Co 80/08/27 300pp
- --8009020433 "Public Address Sys Riser Diagram.Unit 2 "
 * Bechtel Corp 9645 78/12/21 1p
- 8009050352 Forwards "Environ Protection Program Preoperational Monitoring Rept" DALE: Mississippi Power & Light Co 80/08/29 ip
- --8009050356 "Environ Protection Program Preoperational Monitoring Rept " # Mississippi Power > Light Co 80/08/29 23pp
- 8009190099 Forwards request for add1 info resulting from FBAR review Outstanding items include assessment of degree of damage due to tornado generated missles & description of amplification factors used in plant design
 TEDESCO, R. L. Assistant Director for Licensing 80/08/29 17pp
- 8009110543 Notification of 600923-24 meetings w/util.Bechtel.GE & Savannah River Lab to review facility sys & discuss Reactor Sys Branch questions MARTORE.J A Licensing Branch 3 80/09/04 2pp
- 8009230235 Notification of 800917 meeting w/util.GE & Savannah River Lab in Sethesda.MD to discuss applicant approach to HPCS Level 8 trip logic MARIORE, J.A. Licensing Branch 3 80/09/04 2pp
- BOO9i50425 Expresses concern at meeting licensing schedule milestones, due to lack of NRC activity on second round questions Requests for addlinfo should be made immediately or questions should be replaced by draft SER for branches LUTKEN.D C Mississippi Power & Light Co 80/09/08 2pp
- 8009150453 Endorses draft SER approach to formulating SER in comparing draft SER approach w/formal question method, approx 225 manhours saved in mechanical engineering using draft SER approach LUTKEN.D C Mississippi Power & Light Co 80/09/08 2pp
- 8009260331 Forwards request for add1 info re FSAR FSAR should be agended to reflect responses TEDESCO.R L Assistant Director for Licensing 80/09/09 9pp
- 8009230456 Confirms 800916 telcon re 800923 meeting to discuss resolution of GE supplied radiography problem at facilities MCGAUGHY, J P Mississippi Power & Light Co 80/09/17 ip

- B009300437 Forwards response to NRC Questions 031 56.031 71 & revised responses to Questions 031 38.031 54.031 60 & 031 75 Responses will be incorporated into Oct 1980 amend to FSAR DALE: L F Mississippi Power & Light Co 80/09/22 102pp
- F Security, medical, emergency & fire protection plans
- 8009180602 Summary of 800813 meeting w/util & NUSAC in Bethesda. MD rephysical security plan MARTORE, J A Licensing Branch 3 80/09/09 3pp
- H General correspondence
- 6009030504 Informs NRC of organizational changes which will be incorporated into Revision 2 of operational GA manual scheduled for submittal in Dec 1980 REAVES, T E Mississippi Power 8 Light Co 60/08/27 1p
- K Utility Final Safety Analysis Report (FSAR) & amends
- E007150489 Forwards affidavit of svc on distribution of Amend 42 to FSAR DALE.L F Mississippi Power & Light Co 60/09/08 2pp
- Q Inspection reports. IE Bulletins & correspondence
- 8D09090069 Forwards IE Bulletin 80-07, Buppl 1, "BWR Jet Pump Assembly Failure " No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/05/13
- 8009120135 Forwards IE Insp Repts 50-416/80-14 & 50-417/80-10 on 800603-04 No noncompliance noted MURPHY.C E Region 2: Atlanta, Reactor Construction & Engineering Support Branch 80/07/21 2pp
- --B007120141 IE Insp Repts 50-416/80-14 & 50-417/80-10 on 800603-06 No noncompliance noted Major areas inspected electrical equipment in-place storage & licenswe actions on prior items
 WALTERS,D K Region 2, Atlanta, Office of the Director CONLON,T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/21 Spp
- 8009020218 Submits response to IE Rulletin 79-03A No 8A-312 Type 304 series piping used in any safety-related sys at greater than 85% design stress Requests extension until 800901 to complete review of bulletin DALE.L F Mississippi Power & Light Co 80/08/06 1p
- 8007020292 Requests extension until 800701 to complete investigation in response to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds"

 DALE: L. F. Mississippi Power & Light Co. 80/08/15 ip
- 8009030128 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Marcury-Metted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Hritten response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/15 to
- 8009140036 Forwards 1E Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE BWR Facilities " No specific action or response requested O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/19 in
- B009230092 Forwards response to 1E Bulletin B0-09 Penetration closure details encl Radiography used for all full penetration butt welds final response expected by B01015 DALE/L F Mississippi Power & Light Co B0/08/21 14pp
- B009120080 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at SHR" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director B0/08/22
- B009160115 Forwards 1E Circular 80-18, "10CFR50 S9 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director SQ/08/22

- 8009ii0&Bi Responds to IE Bulletin 80-i& Ten Rosemount, Inc Model i151A transmitters scheduled to be used in safety-related applications were purchased Transmitters will be replaced before fuel loading DALE.L F Mississippi Power & Light Co 80/08/27 2pp
- 8009120260 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DQN 6008 Circuit Breakers" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/27
- 80092403iB Ack receipt of 800730 ltr informing NRC of steps taken to corract violation noted in IE Insp Repts 50-416/80-07 & 50-417/80-07 Region 2, Atlanta, Fuel Facility & Materials Safety Reanch 80/08/28 in
- --2009240331 Responds to NRC 900423 ltr re violations noted in 1E Insp Repts 50-416/80-07 & 50-417/80-06 Corrective actions dredging operations will be completed by 800905 RCOAUGHY, J P Mississippi Power & Light Co 80/07/30 1p
- 8009080328 Responds to violation noted in 1E Insp Repts 50-416/80-16 & 50-417/80-17 Corrective action constructor reinspected 513 ASME socket welds to determine extent to which welds are undersized in safety-related applications MCGAUCHY, J P Mississippi Power & Light Co 80/08/29 2pp
- BOO929027i Forwards IE Circular 80-2i, "Regulation of Refueling Crews"
 No written response required
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/10
 5ep
- BO04300026 Ack receipt of B00829 & 0902 ltrs informing NRC of steps taken to correct violations noted in IE lnsp Repts 90-416/80-16 & 50-417/80-11 MMRPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch B0/09/11 ip
- --8009300029 Responds to NRC 800805 ltr re violations noted in IE lnsp Repts SO-416/80-16 & 50-417/80-11 Corrective actions constructor audit procedures revised to allow documentation of concerns found & corrected during audit MCGAUGHY, J P Mississippi Power & Light Co 80/07/02 2pp
- --B009200031 Forwards IE Insp Repts 50-416/80-16 & 50-417/80-11 on B00715-18 & notice of violation HURPHY,C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/08/05 2pp
- --8009300034 Notice of violation from insp on 800715-18 * Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/08/05 1p
- --EOD936004; IE Insp Repts 50-416/80-16 & 50-417/80-11 on 800715-18
 Noncompliance noted acceptance of undersine socket welds &
 failure to follow procedure for documentation of audit
 findings
 CRCHLEY, B R Region 2, Atlanta, Office of the Director
 HARDTLAR Region 2, Atlanta, Reactor Construction & Engineering
 Support Branch 80/08/05 6pp
- BOC9230627 Final deficiency rept re design nomographs used in siring & selection of hydramotor electrohydraulic actuators supplied by ITT General Controls Condition determined not reportable under 10CFR50 55(e) HCGAUGHY.J P Mississippi Power & Light Co B0/09/15 2pp
- --8007230642 Advises no other application determined for NH70 Series hydramotor actuators No further action planned per IE Bulletin 80-09

 PALE, L F Mississippi Power & Light Co 80/07/28 lp
- S Reportable occurrences, LERs & related correspondence
- 8007100966 RU Status Rept 3 on 800125, hand switch CR-2740-U8203E supplied by QE failed to operate Util AE & Bechtel Power Corp will evaluate switches Final rept to be submitted by 800718 MCQAUQHY, J P Mississippl Power & Light Co. 80/06/18 Rpp
- 8009100335 Deficiency rept re radiographs supplied by contractors to RSSS vendors which failed to meet ASME code requirements Radiograph components being analyzed Final rept & determination of reportability by Oct 1980 MCGAUGHY.JP Mississippi Power & Light Co 80/06/RO 2pp

- 8009100436 Status Rept 2 re electrical cable insulation damaged during pulling process Damaged cable would not affect plant safety Final rept % determination of reportability by 810131 MCGAUGHY, J P Mississippi Power % Light Co 80/06/23 2pp
- 8009100558 RO Status Rept 2 on 800313, electrical cable insulation damaged during pulling process Caused by poly-propylene pulling rope damaging cables Cables replaced Training session initiated Final rept to be submitted by 810131 MCCAUGHY, J P Mississippi Power & Light Ca 80/06/23 3pp
- 8009100519 Deficiency rept re Rosemount Model 510 DU trip/calibr units & Model 1152 pressure transmitters final rept re trip units will be submitted by 801022 final rept re pressure transmitters encl MCGAUGHY. J P Mississippi Power & Light Co 80/06/24 Spp
- 8009100592 Final deficiency rept re design nomographs used in sizing & selection of General Controls hydromotor electrohydraulic actuators Forwards 800616 response to IE Bulletin 80-09 Final rept to be submitted by 800915 MCGAUGHY.J F Mississippi Power & Light Co 80/07/21 2pp
- 8009040489 Status Rept 2 of deficiency re nonconforming calibr svcs provided by Computer Sciences Corp Final rept by 800822 MCGAVGHY, J P Minnesota Power & Light Co 80/07/22 lp
- 8009150052 Part 21 rept re power plant noncomplying valves Reanalysis 90% complete Corrective action involves design changes % review by customer ongineering & field personnel High priority on valves which must meet increased loading NIEHAUS, P W William Powell Co 80/08/03 2pp
- 8009100303 Final defictency rept re incorrect bolt torquing on HPCS pump Deficiency could have caused pump degradation to subsequent failure Pumps disassembled & retorqued to Field Disposition Instruction 32-42382 MCGANGHY. J P Mississippi Pawer & Light Co 80/08/04 4pp
- 8009100347 Status rept re feedwater pipe bend below design min wall thickness Feedwater pipe supplier will perform evaluation of pipe & bending process Unit i pipe will be ultrasomically tested Final rept will be submitted by 801211 MCGAUGHY, J F Misslssippi Power & Light Co 80/08/04 2pp
- 8007020044 Interim deficiency rept re calibr aves provided by Computer Sciences Corp Evaluation or investigation results not completed Final rept to be submitted by 800930 MCGAUGHY.JP Mississippi Power & Light Co 80/08/21
- 8009080249 Second interim deficiency rept re incorrect pipe supplied by TX Pipe Bending Heavier wall of spool will not cause overstressed condition on pipe support sys in application Final rept expected by 801010 MCGAUGHY.J P Mississippi Power & Light Co 80/08/29 lp
- 8009080376 Intorim deficiency rept to fractured actuator to damper shaft couplings in diesel generator bldg bay A Final evaluation to be completed by 801219 MCGAUGHV, J.P. Mississippi Power & Light Co. 80/08/29 1p
- B009100486 Interim deficiency rept re installation of expansion anchors for conduit hangers, instrument process tubing & air supply supports w/o proper approval Procedures have been revised Final rept will be submitted by B01111 MCGAUGHY, J P Mississippi Power & Light Co 80/09/03 lp
- BO07190301 Interim deficiency rept re inadequate control of supplier drawing revision notice program Investigative action resulted in (assuance of 34 nonconformance documents Procedure controlling notices revised Final rept by 810122 MCGAUGHY, J.P. Mississippi Power & Light Co. 80/09/05 2pp
- 8009160391 Interim deficiency rept re possibility of inflective insulation in annular space between reactor vessel & shield dislodging during LOCA & shearing reactor pressure vessel level sensing lines Final rept will be forwarded on 810515 MCGAUGHY, J.P. Mississippi Power & Light Co. 80/09/08 Spp.
- 8009250417 Part 21 rept re defects in diesel generator control panels mfg by Intl Control & Switchgear Cq Equipment is being repaired per FDDR JB1-940 under supervision of Marrison-Knudsen Co MCGAUGHY, J P Mississippi Power & Light Co 80/09/08 3pp
- BOO9280473 Interim deficiency rept re failure of GE subcontractor 1&SE to establish & implement approved OA program for electrical work performed under GE field deviation requests & instructions Results of GE refinspection expected by 810131 MCGAUGHY. J P Mississ(ppi Power & Light Co 80/09/08 2pp

- 8009160387 Second interim deficiency mept me defective leak detection equipment used to qualify Farm Co NPP-2 cambon filters for use in control moom standby air units filters have been returned to vendom Final mept will be submitted by 801125 MCGAUCHY, J P Mississippi Power # Light Co 80/09/09 2pp
- 8009230956 Interim deficiency rept, per iOCFR50 55(e) & Part 21 re Hilts Fastening Sys. Inc. anchor boilt pull out strength Specific applications of one-inch diameter KUIK bolts are being investigated Final rept bill be filed by 801104 MCGAUGHY. J P Mississippi Power & Light Co 80/09/12 lp
- 6007230471 Interim deficiency rept re discrepancies in design documentation for Power Generation Control Complex panels b associated delivered hardware No deficiencies discovered that would adversely affect safety of operations MCGAUGHY, J P Mississippi Power & Light Co 80/09/15 2pp
- 8009230627 Final deficiency rept re design nomographs used in sizing & selection of hydramotor electrohydraulic actuators supplied by ITT General Controls Condition determined not reportable under 10CFR30 55(a) MCGAUGHY, J P Mississippi Pawer & Light Co BO/09/15 2pp
- ~-8009230642 Advises no other application determined for NH90 Series Agdramotor actuators No further action planned per IE Bulletin 80-07 DALE/LF Mississippi Power & Light Co 80/07/28 1p
- 8009230595 Interim deficiency rept re unqualified cable insulation repairs in 680-volt cable supplied by Rockbastos in 680-volt cable supplied by Rockbastos in continuing involving safety implications of deficiency final rept by 801216 MCOAU2HY.J P Mississippi Power & Light Co 80/09/16 2pp
- 800924043B Final deficiency rept re failure of handswitch CR2740-US203E in honsafety related area of plant syc water sys investigation indicates that deficiency does not exist in safety related sys 2 is not reportable per 10CFR50 55e MCOAUGHY, J P Hississippi Power & Light Co 80/09/16 2pp
- 8009240480 Final deficiency rept re incorrect translation of weld requirements from design drawings to field sketches Erroneous welding direction corrected Future field sketches will include instruction to refer to design drawing MCGAUGHY.J P Mississippi Power & Light Co 80/09/16 2pp
- DDCKET 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3

 A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NURES-0696, "Functional Criteria for Engrgency Response Facilities " Corments requested within 30 days Proposed implementation schedule for meeting criteria of NUREC-0696 encl M/o NUREC EISENHUT.D G Division of Licensing 80/08/01 119pp
- 8009110523 Discusses interim actions required for plant operation pending final resolution of ATMS in StW PWRs, NURGE-0460 ATMS emergency operating procedures must be submitted by 801130 TEDESCO, R L. Assistant Director for Licensing 80/08/27 3pp
- 8009300403 Responds to Rl. Tedesco 800827 ltr to NO Counsil requesting emergency operating procedure to be used for prompt recagnition of ATMS event & mitigation Procedure is premature to emergency operating procedures developed COUNSIL.N G Northeast Utilities 80/09/18 lp
- @ Inspection reports, IE Bulletins & correspondence
- 8009100113 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312.7yre 304 Stainless Steel Pipe " No SA-312 or A-312 welded pipe used or planned for use at greater than BSX of code allowable stress COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/08/06 ip
- 8007030081 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Fower Plants Designed by C-E " Written response required ORIER, B H. Region 1, Philadelphia, Office of the Director 80/09/15 1p
- 8009180017 Forwards 1E Circular 80-18, "IOCFRSD 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GRIER, B H Region I, Philadelphia, Office of the Director 80/08/22 Ip

- 8009120190 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Dover: 480 Volt Type K-600S & K-DON 600S Circuit Breakers " No written response required GRIER, B H Region I. Philadelphia, Office of the Director 80/08/27 Ip
- B009230791 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required GRIER,B if Region I, Philadelphia, Office of the Director 80/09/10 1p
- 8009240319 Forwards IE Info Notice 80-32. "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/09/12 1p
- S Reportable occurrences, LERs & related correspondence
- 8007220325 Ack receipt of 800730 final deficiency rept re rock anchor design Rept will be reviewed a svaluated Final deficiency rept dt 800730 re structural problems in auxiliary, Eurobine a svc bldgs encl CARLEDIA T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/03 lp
- --8009220330 Final deficiency rept re structural problems in auxiliary, turbine & svc bldgs Auxiliary & svc bldg problems caused by incomplete calculations & models originally used Stone & Webster technical review program modified CQUMBIL.W G Northeast Utilities 80/07/30 3pp
- DOCKET 50-424 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/o NUREO EISENHUT, D O Division of Licensing 80/08/01 119pp
- O Adjudicatory correspondence
- E009300375 Requests that Georgians Against Nuclear Energy petition be reconsidered in light of new data projecting excess capacity of 40-46% after plant completion Requests hearings re need for power & EIS suppl Atlanta Journal 800822 article enci. FLACK.G Mysr. Bowman, Stroup & Flack 80/09/25 3pp
- G Inspection reports, IE Bulletins & correspondence
- 8009040635 Responds to 1E Bulletin 80-05 Vol control,boric acid storage & boron recycle holdup,component cooling water surge,waste evaporator concentrates holdup & auxiliary component surge tanks are acceptable No further action planned DVITON.D Georgia Power Co 80/08/05 2pp
- 8009040637 Responds to IE Bulletin 79-03A No welded SA-312 or A-312 piping identified that exceeds pressure design stresses of BS% max allowable stress at design temp Westinghouse requested extension until 80100% to reply DUITON.D Georgia Power Co 80/08/05 2pp
- 8009030154 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E " Written response required G'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/15
- 8009160147 Forwards IE Circular 80~18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22
- 8009120311 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boyer! 489 Volt Type K-6008 & K-DON 6008 Circuit Breakers."

 No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/27
- 8009220133 Responds to IE Bulletin 80-16 no Rosemount Models 1151 or 1152 pressure transmitters or Rosemount Model 510DU trip units used for any safety-related sys or components DUTTOM:D Georgia Power Co 80/09/02 1p

- 8009240389 Reponds to 1E Bulletin 80-19 re +ailures of mercury-wetted matrix relays in reactor protective sys Relays in question are not used in reactor trip circuits Forty menhours expended for review

 OUTTOKED Georgia Power Co 80/09/02 2pp
- 8009290282 Forwards IE Circular 80-21, "Regulation of Refueling Crows" No written response required D'REILLY, J.P. Region 2. Atlanta, Orfice of the Director 80/09/10
- BOO9300110 Bubmits response to 1E Bulletin 80-20 Westinghouse Type W-2 control switches are not used in safety-related applications BUTCMI. D Georgia Power Co BO/09/16 2pp
- S Reportable occurrences, LERs & related correspondence
- B009100416 Interim deficiency rept re dewatering & erosion of backfill Various actions enabling util submittel of final rept will be completed in 6 to 8 wks
 MILLSIL 14 Georgia Power Co 80/07/23 2pp
- 8009030489 Final deficiency rept re dewatering & erosion of backfill in power block area resulting from heavy rainfalls Repair work campleted Aug 1980 Bechtel consultant rept dtd 800815 & GA Power Co 800815 itr to Southern Co Sics encl DUITON D Georgia Power Co 80/08/29 100pp
- 800904045B Final deficiency rept re dewatering & erosion of backfill All erosion in power block backfill was satisfactorily repaired, w/oxception of minor deviations There is no detrimental effect on oxisting structures

 DUTTON D Georgia Power Co 80/08/29 75pp
- 8009190493 Interim deficiency rept re defective bolting maths from Sauthern Bolt & Fastener Co Util has placed on hold all math received from supplier Final rept will be submitted by BO1115 DUTFON,D Georgia Power Co 80/09/12 2pp
- DOCKET 50-425 ALVIN W VOOTLE HUGLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8007080080 Forwards draft NUREO-0676, "Functional Criteria for Emergency Response Facilities" Corments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0676 encl W/a NUREO EISENNUT, D G Division of Licensing 80/08/01 119pp
- G Adjudicatory correspondence
- 8009300375 Requests that Opergians Against Nuclear Energy petition be reconsidered in light of new data projecting excess capacity of 40-45% after plant completion Requests hearings re need for power & EIS suppl Atlanta Journal 800822 article encl FLACK.O Hyer, Downan, Stroup & Flack 80/09/25 3pp
- Q Inspection reports. IE Bulletins & correspondence
- 8009040535 Responds to 1E Mulletin 80-05 Vol control, boric acid storage & boron recycle holdup, component cooling water surge, waste evaporator concentrates holdup % auxiliary component surge tanks are acceptable. No furthar action planned DUTTON, D Georgia Power Co 80/08/05 2pp
- 8009040637 Responds to IC Bulletin 79-03A No welded GA-312 or A-312 plping identified that exceeds pressure design stresses of 85% max allowable stress at design temp Westinghouse requested extension until 801001 to reply DUTTON.D Georgia Power Co 80/08/05 2pp
- 8009030154 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Marcury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/08/15 to
- 8007160147 Forwards IE Circular 80-18, "10CFR50 57 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22

- B009120311 Forwards IE Info Notice B0-31. "Maloperation of Gould-Brown Bover: 480 Volt Type K-6005 ? K-DDN 6005 Circuit Bleakers " No written response required O'REILLY, J P Region 2 Atlanta, Orfice of the Director B0/08/27
- 8007220133 Responds to 1E Builetin 80-16 no Rosemount Models 1151 or 1152 pressure transmitters or Rosemount Model 510DV trip units used for any safety-related sys or components DUTTON.D Georgia Power Co 80/09/02 ip
- 8009240389 Reponds to 16 Bulletin 80-19 re failures of nercury-wetted matrix relays in reactor protective sys Relays in question are not used in reactor trip circuits Forty manhours expended for review

 DUTTO!/.D Georgia Power Co 80/09/02 2pp
- 8009290282 Forwards IE Circular 80-21. "Regulation of Refueling Crews" No written response lequired O'REILLY.J P Region 2. Atlanta Office of the Director 80/09/10 Sop
- 8009300110 Submits response to 1E Bulletin 80-20 Westinghouse Type W-2 control switches are not used in safety-related applications DUITON.D Georgia Power Co 80/09/16 2pp
- S Reportable occurrences, LERs & related correspondence
- 8009100416 Interim deficiency rept re dewatering & erosion of backfill Various actions enabling ofti submittal of final rept will be completed in 6 to 8 oks
 MILLS, L N Georgia Power Co 80/07/23 2pp
- 8009030489 Final deficiency rept re dewatering & erosion of backfill in power block area resulting from heavy rainfalls Repair work completed Aug 1980 Bechtel consultant rept dtd 800915 & GA Power Co 800815 itr to Southern Co Sycs encl DUTTON, D Georgia Power Co 80/08/29 100pp
- 8009040458 Final deficiency rept re devatering & erosion of backfill All erosion in power block backfill was satisfactorily repaired.w/erception of minor deviations There is no detrimental effect on existing structures
 DUTTON.D Georgia Power Co 80/08/29 75pp
- 8009[90493 Interim deficiency rept re defective bolting matls from Southern Bolt & Fastener Co Util has placed on hold all matl received from supplier Final rept will be submitted by 80115 DUITON.D Georgia Power Co 80/09/12 2po

DOCKET 50-431 GENKAL, UNIT 1

- A Application/construction stage documents & correspondence
- 8009090631 Notification of cancellation of 800827 meeting w/DWR licensing review group to discuss concensus positions on TMI issuen (NUREG-0694) WILSON, J N Assistant Director for Licensing 80/08/04 10pp
- DOCKET 90-433 UC-SANIA BARBARA RESEARCH REACTOR

 F Security, modical, emergency & fire protection plans
- 8009110552 Responds to 800615 % 1102 1trs requesting approval of physical mods & revised security plan, respectively Ltrs were treated as license amend request Forwards Amend 2 to License R-124 identifying security plan MILLER.H J Standardization & Special Projects Branch 80/08/28
- --8009110583 Amend 2 to License R-124 identifying currently approved security plan
 MILLER, J.R. Standardization & Special Projects Branch 80/08/28

DOCKET SIN-50-437 FLOATING NUCLEAR PLANT

- A Application/construction stage documents & correspondence
- 8007080080 Forwards draft NUREO-0676, "Functional Criteria for Emergency Response Facilities " Corments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0676 encl N/O NUREO EISENHUT,D Q Division of Licensing 80/08/01 117pp

- 8009100586 Requests that schedule be established for completing review of application for afg license 5 that NRC resources be committed for that purpose NRC should initiate review of util 800715 responses to NURG-0660 HAGALP 3 Offshore Power Systems (subs of Westinghouse Electric Corp) 80/09/05 3pp
- Q Inspection reports. IE Bulletins & correspondence
- 8007030181 Forwards Revision 1 to 1E Dulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Region 2, Atlanta, Orrice of the Director 80/08/15
- 6009160108 Forwards iE Circular 80-18. "IOCFRSO 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY.J P Region 2 Atlanta. Office of the Director 80/08/22 to
- 8009120248 Forwards IF Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-6005 % K-DUN 6005 Circuit Breakers " No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/08/27
- B009290269 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/09/10 5pp

DUCKET 50-438 BELLEFONTE NUCLEAR PLANT. UNIT &

- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREC-0696. "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREC-0696 encl 8/a NUREG EISENHUT, D G Division of Licensing 80/08/01 119pp
- 9009150016 Forwards minutes of 800806 meeting w/TVA concerning independent code stress analysis in process at ETEC for decay heat removal sys
 BOU9NIA.A Operating Reactors Branch (80/08/25 1p
- ---8009150018 Summary of 800806 meeting w/TVA at site re outstanding items concerning independent code stress analysis in process at ETEC for decay heat removal sys CAPPUCCI.A J Mechanical Engineering Branch 80/08/20 3pp
-)09120619 Forwards request for add1 info in area of reactor physics, for review of CL application TEDESCO.R L Assistant Director for Licensing 80/08/26 4pp
- 109110529 Discusses interim actions required for plant operation pending final resolution of ATWS in BAW PWRs.NUREO-0460 ATWS energency operating procedures must be submitted by B001130 TEDESCO.R L Assistant Director for Licensing 80/08/27 3pp
- 8009090522 Forwards final response to Question F 15 of NRC 800325 ltr Const of all portions of plant justified & CP should not be modified, suspended or revoked CROSS J L Tennessee Valley Authority 80/09/04 9pp
- 8009150460 Forwards add1 info on Topical Rept CEB-76-25, Revision 1. "Pipe Rupture Analysis for Guard Pipe" re util penetration design & CEB-78-14, Revision 1. "Analysis of Bollefonte Main Steam Guard During Postulated Pipa Rupture "
- --8007150468 "Analysis of Bellefonte Main Steam Guard Pipe During Postulated Pipe Rupture " LOEMIS.) D Tennessee Valley Authority CEB-78-14 RI 80/06/16 26ps
- 1009300400 Forwards technical questions re implementation of interim policy on 10CFR50 \$ 51 MILLS.L M Tennessee Valley Authority 80/09/23 3pp

Financial information

1009090543 Forwards Annual Financial Rept 1979 CROSS.J L Tennessee Valley Authority 80/09/04 Lp

- --8009090563 Annual Financial Rept 1979
 * Tennessee Valley Authority 80/09/04 44pp
- Q Inspection reports, 1E Bulletins & correspondence
- 8009100063 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture "No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/07/24
- 8009020214 Forwards response to IE Bulletin 79-03A No SA-312 & A-312, Type 300 series fusion welded pipe used or planned for use in safety-related sys at greater than 85% design stress ercept latts Bar Matl under investigation at Matts Bar Milluff Notestigation at Matts Bar Milluff Notestigation at Matts Bar Milluff Notes Notes
- 8007070802 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASKE SA-312. Type 304 Stainless Stoel Pipe " Use of maths still under investigation for sys supplied by NSS vendor MILLS.L M Tennessee Valloy Authority 80/08/05 2pp
- 8009150300 Forwards IE Investigation Repts 50-438/80-10 & 50-439/80-10 on 800604-05 No noncompliance noted LOKO.F J Region 2. Atlanta. Office of the Director 80/08/05 2pp
- --8007150304 IE Investigation Repts 50-438/80-10 & 50-439/80-10 on 800604-05 No noncompliance noted Major area inspected util handling of "Michelson Rept" re potential defect of B&W NSSS 3 applicable iOCFR21 requirements WILLIAMSON.E L. LONG.F.7 Region 2. Atlanta. Office of the Director BROWNLEE.V L. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/08/09 61pp
- 8007020303 Forwards IE Insp Repts 50-327/80-24, 50-328/80-15, 50-370/80-20, 50-371/80-14, 50-438/80-13, 50-439/80-13, 50-581/80-11, 50-581/80-11, 50-581/80-11, 50-553/80-11, 80-554/80-10, 50-566/80-10 & 50-567/80-10 O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/05 2pp
- --8007020312 Natice of violation from insp on 800707-11
 * Region 2. Atlanta, Office of the Director 80/08/06 4pp
- --8009020337 IE Insp Repts 50-327/80-24,50-328/80-15,50-390/80-20,50-391/80-14,50-438/80-13,50-439/80-13,50-518/80-11,50-519/80-11,50-526/80-11,50-521/80-11,50-539/80-11,50-539/80-11,50-539/80-11,50-539/80-10,50-566/80-10 & 50-567/80-10 on 800707-11 BROWNLEE, V L Region 2, Atlanta, Office of the Director 80/08/06 24pp
- 8009030145 Forwards Revision i to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/08/15
- 8009160193 Forwards iE Circular 80-18, "10CFRSO 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22 to
- B007070524 Responds to tE Insp Repts 50-43B/B0-12 & 50-439/B0-12 Corrective actions siping will be inspected & cleaned in accordance w/MEU-SDP-605 Expeditious capping of stainless steel piping received w/a caps has been emphasized MILLS, J II Tennessee Valley Authority B0/0B/27 Bpp
- 8009120340 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover: 480 Volt Type K-6008 & K-DDN 6006 Circuit Breakers "
 No written response required
 O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/27
- 8009180087 Forwards response to IE Bulletin 80-16 Resembnt Models 1151 & 1152 pressure transmitters are not used or planned for use except at Bellefonte Nuclear Plant where use will be evaluated MILLS,L M Tennessee Valing Authority 80/08/29 2pp
- B007240494 Forwards response to IE Bulletin 80-16 re potential misapplication of Rosemount pressure transmitters No corrective action required due to results of evaluation that indicated impossibility of anomalous output MILLS.L M Tennessee Valley Authority 80/08/27 2pp.

- 8009120679 Responds to IE Sulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Relays identified are not used in facility forty manhours expended for review MYLLS.L M Tennessee Valley Authority 80709704 ip
- 8009260375 Forwards IE Circular 80-21, "Regulation of Refueling Crews"
 No written response required
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/10
 500
- S Reportable occurrences, LERs & related correspondence
- 8009120293 Part 21 final rept re defective NAMCO Type 170-42100 & 170-4100 limit switches Vendor revised all drawings to show proper physical layout Util currently revising cable termination, schematic & condust drawings to reflect changes MILLS.L. M. Tennessee Valley Authority 80/07/10 3pp
- B009100401 First interim deficiency rept re improperly tubed differential pressure indicators on air cleanup units Appropriate tubing reworking method boing investigated Next written rept will be submitted by B01110 MILLS.L # Tennessee Valley Authority B0/08/29 2pp
- 8009160648 Part 21 final rept re improper insertion of buffer cards
 Caused by possible ambiguity in wording of product
 instruction book Maint instructions reworded to require
 buffer module be removed before buffor card insertion
 MILLS, L M Tennessee Valley Authority 80/08/29 3pp
- 8009100494 First interim deficiency rept re RCS pump cases out of level Appropriate info transmitted to B&W for review Next rept will be submitted by 801128 Mill.B.L ff Tennessee Valley Authority 80/09/04 2pp
- 8009160353 Interim deficiency rept re tensile anchor capacitles lower than design allowables Util completed design review of auxiliary 8 control bldgs Next written rept to be submitted by 819401 MILLS.L M Tennessee Valley Authority 80/09/03 ip
- 8009160353 Interim deficiency rept re tensile anchor capacities lower than design allowables Util completed design review of auxiliary 3 control bldgs Next written rept to be submitted by 810401 MILLS-L M Tennessee Valley Authority 80/09/08 Ip
- 8009160377 First interim deficioncy rept re 480-volt motor control ctr control transformer fuses per 10CFR50 55e & 10CFR21 Design of control circuits is being re-evaluated to determine cause of fuse operation & what changes are required MILLS.L M Tennessee Valley Authority 80/09/08 2pp
- 8009160437 Third Interim deficiency rept re nonconformance in const QA audit Plans being finalized to ensure that training & retraining of certified wolders & foremon will be completed Final rept will be submitted 801023
 MILLS,L M Tennessee Valley Authority 80/09/10 ip
- 8009290296 First Interim deficiency rept re excessive vibration in essential raw cooling water pump/motor assembly while running Util contacted vendor & requested assistance correcting problem Next rept to be submitted approx 801202 MILLS, L M Tennessee Valley Authority 80/09/17 2pp
- 8009250240 First interim deficiency rept re 600-volt & 8 & 15 kV power cables, Types CPJ & CPSJ, which do not meet lECE 383-1974 flame tast requirements Cause not stated Alternatives being evaluated Next rept will be submitted by 801210 MILLS, L M Tennessee Valley Authority 80/09/18 2pp
- 8009290346 First interim deficiency re deficient fillet welds Program buing implemented to reinspect & correct all deficient welds Next rept due by 801215 MILLS, L M Tennessee Valley Authority 80/09/19 lp
- B009300411 Third interim deficiency rept re ITT incorrect selection of actuators for dampers Caused by erroneous selection charts misrepresenting thrust delivery to damper assembly MILLS/L II Tennessee Valloy Authority 80/09/23 2pp
- B009300480 Second interim deficiency rept re failure of main steam lines because of main feedwater overfill Util & B&W proceading w/evaluation to incorporate mitigative instrumentation Next rept by 801229 MILLS,L M Tennessee Valley Authority 80/09/23 ip

- BO0930034B Final deficiency rept re intl Telephone & Telegraph actuator for Ruskin dampers Actuators supplied at facility will deliver sufficient torque w/o spring mod & have been accepted for use MILLS.L M Tennessee Valley Authority BO/09/24 2pp
- 8009300427 Fourth interim deficiency mept re water found in rock anchor tendon head protoctive grease cams Ground water pumped from 23 holes in Unit 1 tendon gallery Floor pumps will be installed permanently in Units 1 & 2 galleries
 MILLS.L M Tennessee Valley Authority 80/09/24 3pp
- DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENRUT,D G Division of Licensing 80/08/01 119pp
- 8009190016 Forwards minutes of 800806 meeting w/TVA concerning independent code stress analysis in process at ETEC for decay heat removal sys

 BOURNIA:A Operating Reactors Branch | 80/08/25 | 1p
- --8009150018 Summary of 800806 meeting w/TVA at site re outstanding items concerning independent code stress analysis in process at ETEC for fecay heat removal sys CAPPUCCI.A J Mechanical Engineering Branch 80/08/20 3pp
- 8009120619 Forwards request for addit lines in area of reactor physics, for review of OL application
 TEDESCO,R L. Assistant Director for Licensing 80/08/26 App
- 8009110529 Discusses interim actions required for plant operation pending final resolution of ATMS in B&W PMRs,NUREG-0460 ATMS emergency operating procedures must be submitted by B01130 TEDESCO:R L Assistant Director for Licensing 80/08/27 3pp
- 8007090522 Forwards final response to Question F 15 of NRC 800325 ltr Const of all portions of plant justified & CP should not be modified suspended or revoked CROSS.J L Tennessee Valley Authority 80/09/04 9pp
- 9009190460 Forwards addl info on Topical Rept CEB-76-25, Revision 1, "Pipe Rupture Analysis for Guard Pipe" re util penetration design & CEB-70-14.Revision 1, "Analysis of Bellefonte Main Steam Guard During Postulated Pipe Rupture "
 HILLS.L M Tennessee Valley Authority 80/09/09 3pp
- --8009150468 "Analysis of Selleronte Main Steam Quard Pipe During Postulated Pipe Rupture" LOEWNS, J D Tennessee Valley Authority CEB-78-14 Rt 80/06/16
- 8009300400 Forwards technical questions re implementation of interim policy on IOCFR50 & 51 MILLS.L H Tennessee Valley Authority 80/09/23 3pp
- I Financial information
- 8009090543 Forwards Annual Financial Rept 1979 CROSS,J L Tennessee Valley Authority 80/09/04 ip
- --B007070563 Annual Financial Rept 1979 * Tennessee Valley Authority 80/09/04 44pp
- @ Inspection reports. IE Bulletins & correspondence
- 8009100063 Forwards IE Builetin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Powps Following Secondary Side High Energy Line Rupture " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/07/24
- 8009020214 Forwards response to 1C Bulletin 79-03A No SA-312 & A-312, Type 300 series fusion wolded pipe used or planned for use in safety-related sys at greater than 85% dasign stress accept Natts Bar Matl under investigation at Watts Bar Miller Response Willey Bulley Authority 80/08/05 2pp

- 8009090502 Responds to IF Sulletin 79-02A. "Longitudinal Held Defects in ASFE SA-012. Type 304 Stainless Steel Pipe." Use of natis still under investigation for six supplied by HISSS vendor MILLS.L II. Tennesse Valley Authority. 80/08/05. 28p
- 8009150300 Forwards IE Investigation Repts 50-438/80-10 & 50-439/80-10 on 600604-05 No noncompliance noted LOPS, F.J. Region 2. Atlanta, Office of the Director BO/08/05 2pp
- --8009150304 IE Investigation Repts 50-438/80-10 & 50-439/80-10 on 800604-05 No noncompliance noted Major area inspected util handling of 'Michelson Rept' re-potential defect of B&W NSSS & applicable 10CFR21 requirements WILLIAMSOME L. LONG.F.J. Region 2. Atlanta. Office of the Director 8R&MHLEF.V. Region 2. Atlanta. Resctor Construction & Engineering Support Branch 80/08/05 61pp
- 8009020303 Foruards IE lnsp Repts 50-327/80-24, 50-328/80-15, 50-398/80-20, 50-391/80-14, 50-438/80-13, 50-311/80-11, 50-519/80-11, 50-519/80-11, 50-519/80-11, 50-553/80-11, 50-553/80-11, 60-554/80-10, 50-564/80-10 & 50-567/80-10 O REILLY, J P Region 2, Atlanta, Office of the Director 80/08/06
- --8009020312 Natice of violation from insp on 800707-11 • Region 2. Atlanta. Office of the Director 80/08/06 4pp
- --8007920337 IE Insp Repts 50-327/80-24.50-328/80-15, 50-379/80-20, 50-371/80-14.50-439/80-13.50-439/80-13.50-518/80-11. 50-519/80-11. 50-519/80-11. 50-554/80-10 50-526/80-11. 50-554/80-10 on 800707-11 BROWNLEE, V L Region 2. Atlanta, Office of the Director 80/08/06 24pp
- 8009030146 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Hritten response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/15 to
- 8009160153 Forwards IE Circular 80-18, "10cFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/08/22 to
- 8009090524 Responds to IE Insp Repts 50-438/80-12 & 50-439/80-12 Corrective artions piping will be inspected & cleaned in accordance w/MEU-SCP-405 Erpeditious capping of stainless steel piping Peceived w/o caps has been emphasized MILLS.J M Tennessee Valley Authority 80/08/27 8pp
- 8009120340 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DDN 6008 Circuit Breakers" No written response required O'REILLY, J.P. Ragion 2. Atlanta, Office of the Director 80/08/27 Ip
- 8009183087 Forwards response to 16 Bulletin 80-16 Rosemount Models 1151 & 1152 pressure transmitters are not used or planned for use except at Bellefonte Nuclear Plant where use will be evaluated MILLS.L N Tennessee Valley Authority 80/08/29 2pp
- 8009240454 Forwards response to IE Bulletin 80-16 re potential misapplication of Rosemount pressure transmitters No corrective action required due to results of evaluation that indicated impossibility of anomalous output MILLS, L.M. Tennessee Valley Authority 80/08/29 Zpp
- 8009120679 Responds to 1E Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Relays identified are not used in facility Forty manhours expended for review MILLS.L K Tehnessee Valley Authority 80/09/04 ip
- 8009260375 Forwards IE Circular 80-21, 'Regulation of Refueling Crows "
 No written response required
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/10
 Spp
- S Reportable occurrences. LERs & related correspondence
- 8009120293 Part 21 final rept re defective NAMCO Type 170-42100 & 170-41100 limit switches Vendor revised all drawings to show proper physical layout Util correctly revising cable termination-schematic & conduit drawings to reflect changes MILLS.L H Tennessee Valley Authority 80/07/10 3pp

- 8009100401 First interim deficiency rept re improperly tubed dirferential pressure indicators on air cleanup units Appropriate tubing reworking method being investigated Next unitten lept will be submitted by 801110 MILLS, L M Tennossee Valley Authority 80/08/29 2pp
- B00916064B Part 21 final rept re improper insertion of buffer cards.
 Caused by possible ambiguity in wording of product
 instruction book Maint instructions reworded to require
 buffer module be removed before buffer card insertion
 MILLS.L M Tennessee Valley Authority 80/08/29 3pp
- 8009j60353 Interim deficiency rept re tensile anchor capacities lower than design allowables Util completed design review of auxiliary & control bidgs Next written rept to be submitted by 810401 MILLS, L. M. Tennessee Vailey Authority 80/09/08 1p
- 8009160377 First interim deficiency rept ra 480-volt matar control ct control transformer fuses per 10CFRSO 55e & 10CFR21 Design of control circuits is being re-evaluated to determine Cause of fuse operation & what changes are required MILLS, L M Tennessee Valley Authoriby 80709708 2pp
- 8009160437 Third interim deficiency rept re nonconformance in const d audit Plans being finalized to ensure that training & retraining of certified welders & foremen will be completed Final rept will be submitted 801023 MILLS.L M Tennessee Valley Authority 80/09/10 lp
- 8009250240 First interim deficiency rept re 600-volt & B & 15 kV power cables. Types CPJ & CPSJ, which do not meet IEEE 383-1974 flare test requirements Cause not stated Alternatives being evaluated Next rept will be submitted by 801210 MILLS.L M Tennessee Valley Authority 80/09/18 2pp
- 8009290346 First interim deficiency re deficient fillet welds Program being implemented to reinspect & correct all deficient welds Next rept due by 801215 MILLS,L ii Tennessee Valley Authority 80/09/19 ip
- BO09300411 Third interim deficiency rept re ITY incorrect selection of actuators for dampers Caused by erroneous selection charts misrepresenting thrust delivery to damper assembly MiLLS, L M Tennessee Valley Authority B0709/23 2pp.
- 8009300480 Second Interim deficiency rept re failure of main steam lines because of main feedwater overfiil Util & B&W proceeding w/evaluation to incorporate mitigative instrumentation Next rept by 801229 MILLS.L IF Tennessee Valley Authority 80/09/23. 1p
- 8009300348 final deficiency rept re Intl Telephone & Telegraph actuatos for Ruskin dampers Actuators supplied at facility will deliver sufficient torque w/o spring mod & have been accepted for use MILLS.L M Tennessee Valley Authority 80/09/24 2pp
- 8009300427 Fourth interim deficiency rept re water found in rock anchor tendon head protective grease cans Ground water pumped from 23 holes in Unit I tendon gallery Floor pumps will be installed permanently in Units I & 2 galleries
 MILLS.L M Tennessee Valley Authority 80/09/24 3pp
- DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- 8007080080 Forwards draft NUREG-0676, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl W/o NUREG EISENHUT, D G Division of Licensing 80/08/01 117pp
- 8009190431 Forwards replacement Pages 13 & 15 to 800626 OL application Page 13 is changed to reflect revised ownership shares among Central Area Power Coordination Group members & Page 15 to include notative signature of States of Page 15 to DAVIDSON, D R Cleveland Electric Illuminating Co 80/09/12 2pp
- -8009170435 Replacement Pages 13 to 15 to 800626 OL application, reflecting revised ownership shares among Central Area Power Coordination Group members & providing notarized signature, respectively & Cleveland Electric Illuminating Co. 80/09/12 2pp

- K Utility Final Safety Analysis Report (FSAR) & amends
- 8009190133 Forwards Perry 1 & 2 FSAR includes schedule for further transmittals of addl info DAVIDSON,D R Cleveland Electric Illuminating Co 80/09/12 2pp
- B009190141 Chapter i to Perry 1 & 2 FBAR, "Introduction & General Dascription of Plant" + Cleveland Electric Illuminating Co B0/09/12 400pp
- B009190144 App 1A to Perry 1 9 2 FSAR. "NUREO-0674.TM1-Related Requirements for New OLs "
 + Cleveland Electric illuminating Co B0/09/12 10pp
- E009190149 Chapter 2 to Perry i & 2 FBAR, "Site Characteristics " + Cleveland Electric Illuminating Co 80/09/12 1300pp
- 8009190156 App 2A to Perry 1 & 2 FSAR. "Annual Joint Frequency Distributions for Cleveland & Erie " * Cleveland Electric Illuminating Co 60/09/12 22pp
- 8009190162 App 20 to Perry 1 % 2 FBAR. "Monthly & Annual Frequency Distributions for Perry Nuclear Power Plant.10-Mile Winds " * Cleveland Electric Illuminating Co 60/09/12 82pp
- 8009190165 App 2C to Perry 1 & 2 FSAR, "Monthly & Annual Joint Frequency Distributions for Perry Nuclear Power Plant. Frequency Distributions for Perry Nuclear Power Plant. 40-Hile Winds " * Cleveland Electric Illuminating Co 80/09/12 82pp
- 8009190219 App 2D to Perry 1 ½ 2 FSAR, "Bedrock Deformation in Cooling Water Tunnel"

 * Cleveland Electric illuminating Co 80/09/12 125pp
- 8009190224 App A to Perry 1 & 2 FSAR, "Study of Microcracks Associated W/Faulting at Perry Nuclear Power Plant Site " Prepared Apr 1979 * Cleveland Electric Illuminating Co SIMMONS, O Affiliation Unknown 80/09/12 21pp
- 8007190234 App B to Porry 1 % 2 FSAR, "Study of Isotopic Composition of Hater From Fault in Intake & Discharge Tunnels at Perry Nuclear Power Plant " Prepared Apr 1979

 Cleveland Electric Illuminating Co SIMKONS, 9 Affiliation Valaewa 80/09/12 600
- 8009190240 App C to Porry 1 & 2 FBAR, "Geophysical Methods " Prepared Apr 1979

 # Cleyeland Electric Illuminating Co * Weston Geophysical Corp
- 6009190244 App D to Perry 1 & 2 FBAR, "Evaluation of Local Selemicity Around Perry Nuclear Power Plant Site " Prepared 790921 * Cleveland Electric illuminating Co * Neston Geophysical Corp 122pp
- 8009190248 App E to Perry 1 & 2 FSAR, "Stress Measurements Hydrofracturing Technique, Perry Nociear Power Plant "
 Prepared for LD Schultz of Gilbert Associates, Inc in Sept Cleveland Electric Illuminating Co ROEGIERS, J C , MCLENNAN, J D ronto, Univ af, 80/09/12 12ipp
- 8009190252 App F to Perry 1 % 2 FSAR, "Independent Reviews of Cooling Water Tunnel Faulting " * Cleveland Electric Illuminating Co 80/09/12 1p
- --8007170256 App F to Porry 1 % 2 FSAR. "Bedrock Deformation in Woter Intake Tunnel, Perry Nuclear Power Plant. Lake County, OH "Prepared on 790217 RG LaFleur of Rensselaer Polytechnical Insp 790130 itr to Gilbert Associates, Inc enci & Cleveland Electric Illuminating Co MURPHY, J Ohio Historical Society 80/07/12 10pp
- --E009190263 App F to Perry 1 & 2 FBAR, "Investigation of Cooling Hater Tunnel Faults,Perry Nuclear Power Plant,OH " * Cleveland Electric Illuminating Co. VOIGHT,B Pennsylvania State Univ 80/09/12 78pp

- 8009190272 App H to Perry i / 2 FSAR. "Consulidation Tests on Cooling Water Tunnel Fault Gouge Samples " Tables transmitted on 790705
- 8009190279 App 2E to Perry 1 & 2 FSAR. "Soil & Rock Borings" * Cleveland Electric Illuminating Co 80/09/12 500pp
- 8009190285 Chapter 3 to Perry 1 % 2 FSAR: "Design of Structures; Components, Equipment % Sys "
 Cleveland Electric Illuminating Co 80/09/12 1450pp
- 8009190293 App 3A to Perry 1 & 2 FSAR. "Hydrodynamic Loads for Perry Nuclear Power Plant" * Cleveland Electric illuminating Co 80/09/12 19pp
- 8009190296 App 3D to Perry 1 & 2 FSAR, "Containment Loads" * Cleveland Electric Illuminating Co 80/09/12 500pp
- 8009190303 Chapter 4 to Perry 1 & 2 FBAR. "Reactor"

 * Cloveland Electric illuminating Co 80/09/12 400pp
- 8009190305 App 4A to Perry 1 & 2 FSAR. "Results of Core Simulation Cloveland Electric Illuminating Co 80/09/12 84pp
- 8007170307 Chapter 5 to Perry 1 & 2 FS4R. "RCS & Connected Sys "
 Cleveland Electric Illuminating Co 80/09/12 350pp
- 8009190312 Chapter 4 to Perry 1 & 2 FSAR. "Engineered Safety Features"
 * Cleveland Electric illuminating Co 80/09/12 400pp
- 8009190314 Chapter 7 to Perry 1 & 2 FSAR. "Instrumentation & Controls" * Cleveland Electric Illuminating Co 80/09/12 350pp
- 8009190318 Chapter 8 to Perry 1 & 2 FSAR. "Electric Power" * Cleveland Electric illuminating Co 80/09/12 250pp
- B009190321 Chapter 9 to Perry [& 2 FSAR. "Auxiliary Bys * Cleveland Electric Illuminating Co 80/09/12 900
- 8009190329 Chapter 10 to Perry 1 & 2 FSAR. "Steam & Power Conversion Sys "

 Cleveland Electric Illuminating Co 80/09/12 100pp
- 8009190334 Chapter 11 to Perry 1 & 2 FSAR. "Redwaste Hgt " Cleveland Electric Illuminating Co 80/09/12 390
- 8009190337 Chapter 12 to Perry 1 2 2 FSAR, "Radiation Protection" * Cleveland Electric Illuminating Co 80/09/12 200pp
- 8007190342 App 12A to Perry ! & 2 FSAR, "Dffgas Sys Component inventory Cleveland Electric Illuminating Co 80/07/12 17pp
- 8009190371 Chapter 13 to Porry 1 & 2 FSAR. "Conduct of Operations "
 * Cieveland Electric Illuminating Co 80/09/12 150pp
- 8009190404 App 13A to Perry 1 % 2 FSAR, "Emergency Plan" Cleveland Electric Illuminating Co 80/09/12 250p
- 8009190406 Chapter 14 to Perry 1 & 2 FBAR. "Initial Test Program "
 * Cleveland Electric Illuminating Co 80/09/12 130pp
- 8009190407 Chapter 15 to Perry 1 & 2 FSAR, "Accider * Cleveland Electric Illuminating Co 80/09/12 "Accident Analyses "
- B009190400 App 15A to Perry 1 & 2 FSAR, "Objectives "
 * Cleveland Electric Illuminating Co 80/09/12 200pp
- 8009190410 App 15B to Perry 1 & 2 FSAR. "BWR/6 Generic Rod Withdrawal Error Analysis Claveland Electric Illuminating Co 80/09/12 100pp
- 8007170411 Chapter 16 to Perry 1 % 2 FSAR. "Toch Specs " To be filed at Cleveland Electric Illuminating Co 80/09/12
- B007190413 Chapter 17 to Perry 1 & 2 FBAR. "GA"
 # Cleveland Electric Filuminating Co B0/07 B0/09/12 100pp

- G. Inspection reports. 1E Bulletins & correspondence
- 6009040536 Forwards 1E Bulletin 80-07, Suppl 1, "BUR Jet Pump Assembly G Region 3 Chicago, Orrice of the Director 80/05/14 KEPPLER, J G
- 8009100i18 Forwards 1E losp Rept 50-440/80-10 on 800825-27 & notice of violation FIDRELLI.O Region 3, Chicago, Reactor Construction & Engineering Support Branch 83/07/09 2pp
- --8099100120 Natice of violation from insp on 800525-27 → Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/07/97 2pp
- ~-8039100126 IE Insp Rept 50-440/80-10 on 800625-27 Noncompliance noted Pailure to neet velding procedure requirements & failure to receding procedure requirements & failure to identify nanconforming pipe hanger welds

 DAHLELSON D H Region 3 Chicago, Reactor Construction & Engineering Support Branch LEE E W K Region 3, Chicago, Office of the Director 80/07/07 5pg
- 8009030195 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Ratted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required
 MEPPLER. J G Region 3, Chicago, Office of the Director 80/08/15
- E009100105 Ack receipt of 600730 ltr informing NRC of steps taken to Correct violations noted in 1E Insp Repts 50-440/60-09 & 50-441/80-09 FIC9ECLE.9 Region 3. Chicago, Reactor Construction & Engineering Support Branch 60/08/IS ip
- --8009100112 ForLards response to MRC 800626 ltr re violations noted in IE Insp Repts 50-440/80-09 & 50-441/80-09 Corrective actions ultrasonic thickness measurements obtained on recirculation notices it is builterins & circulars reviewed DAVIDSON DR Cleveland Electric Illuminating Co 80/07/30 3pp
- E009160536 Responds to IE Bulletin 80-19 re failure of C-E mercury-wetted matrix relays in reactor protective sys Identified relays are not used in facility Three manhours expended on DAVIDSON, D R Cleveland Electric Illuminating Co 80/08/18 ip
- 8009290525 Forwards IE Insp Repts 50-440/80-12 & 50-441/80-11 on 800701-31 No noncompliance noted FioReLLi & Rigion 3. Chicago. Reactor Construction & Engineering Support Stanch 80/08/19 2pp
- --8009290526 IE Insp Repts 50-440/80-12 & 50-441/80-11 on 800701-31 No noncompliance noted Major areas inspected licenses action on previous findings.concrete work activities & related quality records & NSSS equipment HUGHES-J. HULLIAMS.C C Region 3. Chicago, Office of the Director 80/68/18 9pp
- specific action or response requested

 KEPPLER.J G Region 3. Chicago. Office of the Director 80/08/20
- 709120041 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Posts to Insert During Scram at BUR" No written response equired EPPLER, J G Region 3, Chicago, Office of the Director EO/OS/22
- 7170412 Forwards IE Circular BO-18, "10CFR50 59 Safety Evaluations or Changes to Radwaste Treatment Sys " No written response KEPPLER, J G Region 3. Chicago, Office of the Director 80/08/22.
- O9230068 Forwards 1E Info Notice 80-31, "Maloperation of Gould-Brown Boyer: 480 Volt Type K-6005 & K-DDN 6008 Circuit Breakers" No written response required KEPPLER, J O Region 3. Chicago, Cifice of the Director 80/08/28
- 8009250230 Act receipt of 800813 itr informing NRC of steps taken to correct violations noted in IE insp Rept 50-440/80-10 FightLLI, G Region 3, Chicago, Reactor Construction & Engineering Support Stanch 80/08/30 ip

- 8009240095 Forwards IE Circular 80-21, "Regulation of Refueling Craws " No written response required
 KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/10
- S Reportable occurrences. LERs 3 related correspondence
- 8009260018 Part 21 rept re nonconforming maths that were sent to util Job site Negotiation is in process for replacement of nonconforming terminal blocks & return of certain units for rewiring u/conforming wires BERGQUIST.R G Eaton Corp Cutler-Hammer Products Div 80/08/20
- B009020067 Final deficiency rept me post-LOCA hydrogen analyzers
 During functional testing, pump failed due to panel autlet
 valves being closed when pump started Relief bypass valve
 installed across pump to stabilize temp Analyzer mods made
 DAVIDSON, D R Cleveland Electric Illuminating Co 80/08/26
- 8009120297 Part 21 rept re drive shaft of Reliance IE motor driving Dia-Vac diaphragm pumps which stopped in two places during in-house functional test of post-LOGA hydrogen analyser. Deficiencies not reportable per 10FFRSO 35(e) or Part 21, DAVIDSON.OR Cleveland Electric Illuminating CO 80/08/29 2p
- 8009240227 Act receipt of 800826 final deficiency rept re post-LOCA hydrogen analyzers FIORELLI,O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/08 lp
- 8009290071 Ack receipt of 800829 Itr re Part 21 rept on post-LOCA deuterium analyzers Matter will be reviewed during insp despite util statement that matter is not reportable per IOCFR50 55(e) FIGRELLIO Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/08 Ip
- DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2 A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NURES-0696, "Functional Criteria for Emergency Response Facilities "Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0476 encl d/b NUREO EISENHUT.D 0 Division of Licensing 80/08/01 119pp
- 800919043I Forwards replacement Pages 13 & 15 to 800626 OL application Page 13 is changed to reflect revised ownership shares among Central Area Power Coordination Group members & Page 15 to include notarized signature DAVIDSON,D R Cleveland Electric Illuminating Co 80/09/12 2pp
- --8009190435 Replacement Pages 13 & 15 to 800626 DL application; reflecting revised ownership shares among Contral Area Power Coordination Group members & providing notarized signature; respectively & Claveland Electric Illuminating Co 80/09/12 2pp
- K Utility Final Bafety Analysis Report (FBAR) & amends
- 8009190133 Forwards Perry I & 2 FSAR Includes achedule for further transmittals of addl info DAVIDSOM,D R Cleveland Electric Illuminating Co 80/09/12 2pp
- --8009190138 Perry 1 & 2 FSAR * Cleveland Electric Illuminating Co. 80/09/12 10000pp
- 8009190141 Chapter i to Perry i & 2 FSAR, "Introduction & General # Cleveland Electric Illuminating Co 80/09/12 400pp
- 8009190144 App 1A to Perry 1 & 2 FSAR, "NUREG-Q694, TMI-Related Requirements for New OLs" * Cleveland Electric Illuminating Co 80/09/12 10pp
- 8009190149 Chapter 2 to Perry 1 & 2 FBAR. "Site Characteristics." + Cleveland Electric Illuminating Co 80/09/12 1300pp.
- 8007190156 App 2A to Perry 1 & 2 FSAR, "Annual Joint Frequency Distributions for Cleveland & Eris "

 * Cleveland Electric Illuminating Co 80/09/12 22pp
- 8009190162 App 28 to Perry 1 & 2 FSAR, "Monthly & Annual Frequency Distributions for Perry Nuclear Power Plant.10-Mile Winds " * Cleveland Electric Illuminating Co 80/09/12 82pp

- 8009190165 App 2C to Perry 1 & 2 FSAR, "Monthly & Annual Joint Frequency Distributions for Perry Nuclear Power Plant, 60-Hile Hinds" * Cleveland Electric Illuminating Co 80/09/12 82pp
- 8009190219 App 2D to Perry 1 & 2 FSAR, "Bedrock Deformation in Cooling Water Tunnel "
 Cleveland Electric filuminating Co 80/09/12 125pp
- 8009190224 App A to Perry 1 & 2 FSAR, "Study of Microcracks Associated W/Faulting at Perry Nuclear Power Plant Site " Prepared
- M/Fautring as Apr 1979 * Cleveland Electric Illuminating Co SIMMONS.O Affiliation Uninoun 80/09/12 21pp
- 8009190234 App B to Perry 1 & 2 FSAR, "Study of Isotopic Composition of Water From Fault in Intake & Discharge Tunnels at Perry Nuclear Power Plant " Prepared Apr 1979
- + Cleveland Ejectric Illuminating Co SIMMONS.G Affiliation
 Uninoum 80/09/12 600
- 8009190240 App C to Porry 1 & 2 FSAR, "Geophysical Methods " Prepared
- Apr 1979

 * Cleveland Electric Illuminating Co * Weston Geophysical Corp
- 8009190244 App D to Perry 1 & 2 FSAR. "Evaluation of Local Seismicity Around Perry Nuclear Power Plant Site " Prepared 77092i * Cieveland Eiectric Illuminating Co * Weston Geophysical Corp 80/09/12 12200
- 6009190248 App E to Perry 1 & 2 FSAR. "Stress Measurements Hydrofracturing Technique, Perry Nuclear Power Plant " Prepared for LD Schuitz of Ollbert Associates, Inc. in Sept
 - Cieveland Eiectrlc liiumlnatlng Co ROEOIERS, J C , MCLENNAN, J D conto, Univ of, 80/09/12 121pp Toronto, Univ of,
- 8009190252 App F to Perry i & 2 FSAR, "Independent Reviews of Cooling Water Tunnel Faulting" Cleveland Electric liluminating Co 80/09/12 ip
- --B009190255 App F to Perry 1 & 2 FBAR. "Bedrock Deformation in Water Intake Twnnei,Perry Nuclear Power Plant,Lake County,OH " Prepared on 790219 RO LaFieur of Rensselaor Polytechnical Insp 790130 itr to 011bert Associates,Inc encl ** Cleveland Electric Tiluminating Co MURPHY. J Ohio Historical Society 80/09/12 10pp
- --8009190263 App F to Perry 1 & 2 FBAR, "Investigation of Cooling Water Tunnel Faults.Perry Nuclear Power Plant, OH " " Cleveland Electric Illuminating Co VOIGHT, B Pennsylvania State Univ B0/09/12 78pp
- 8009190270 App 0 to Perry 1 & 2 FSAR, "TX-Series Boring Logs " Covers pariod 780821-790619 * Claveland Electric Illuminating Co * Gibert/Commonwealth Cos
- 80/09/12 125pp
- 8009190272 App H to Perry i & 2 FBAR. "Consolidation Tests on Cooling Water Tunnel Fault Couge Samples " Tables transmitted on 790705
- Clevetand Electric liluminating Co WALLER, F 8 Woodward-Clydensultants, Inc 80/09/12 lipp Consultants, Inc
- 8009190279 App 2E to Perry 1 & 2 FSAR, "Soil & Rock Borings" * Cheveland Electric Illuminating Co 80/09/12 500pp
- 8009190285 Chapter 3 to Perry 1 & 2 FSAR. "Design of Structures. Components. Equipment & Sys " * Cleveland Electric lliuminating Co 80/09/12 1490pp
- 8009190293 App 3A to Perry 1 & 2 FSAR, "Hydrodynamic Loads for Perry Nuclear Power Plant" * Cleveland Electric Illuminating Co 80/09/12 19pp
- 8009190276 App 38 to Perry (& 2 FSAR, "Containment Loads"

 Cleveland Electric Illuminating Co BO/09/12 500pp
- 6009190303 Chapter 4 to Perry 1 & 2 FBAR, "Reactor "

 * Cheveland Electric Illuminating Co 80/09/12 400pp
- 8009190305 App 4A to Perry 1 & 2 FBAR, "Results of Core Elmulation
- Studies " * Cleveland Clectric Illuminating Co 80/09/12 84pp
- 8009190309 Chapter 5 to Perry 1 & 2 FSAR, "RCS & Connected Sys "
 # Cleveland Electric Illuminating Co 80/09/12 350pp

- 8009190312 Chapter 6 to Perry 1 & 2 FSAR, "Engineered Safety Features" * Cleveland Electric Illuminating Co 80/09/12 600pp
- 8009190314 Chapter 7 to Perry 1 ? 2 FSAR, "Instrumentation & Controls "
 * Cleveland Electric Illuminating Co 80/09/12 350pp
- 800919031B Chapter 8 to Perry 1 8 2 FSAR. "Electric Fower" Gleveland Electric Illuminating Co 80/09/12 250pp
- 8009170321 Chapter 9 to Perry 1 & 2 FSAR. "Auxiliary Sys "
 Cleveland Electric illuminating Co 80/09/12 900pp
- 8009190329 Chapter 10 to Perry 1 & 2 FSAR, "Steam & Power Conversion
 - Sys " # Cleveland Electric Illuminating Co 80/09/12
- 8009190334 Chapter 1: to Perry 1 % 2 FSAR, "Radwaste Mgt"
 * Cleveland Electric Filuminating Co 80/09/12 350pp
- 8009190337 Chapter i2 to Perry 1 & 2 FSAR. "Radiation Protection "
 * Cleveland Electric Ii)uminating Co 80/09/12 200pp
- 8009190342 App 12A to Perry 1 & 2 FSAR, "Offgas Sys Component Inventory Cleveland Electric (Huminating Co 80/09/12 17pp
- 8009190371 Chapter i3 to Perry 1 & 2 FSAR, "Conduct of Operations"
 * Cleveland Electric Itluminating Co 80/09/12 150pp
- 8009190404 App i3A to Perry 1 & 2 FSAR. "Emergency Plan
 * Cleveland Electric illuminating Co 80/09/12 256 250pp
- 8009190406 Chapter i4 to Perry 1 % 2 FSAR. "Initial Test Program" * Gieveiand Electric Illuminating Co 80/09/12 130pp
- 8009190407 Chapter i5 to Perry 1 & 2 FSAR. "Accident Analyses "

 * Cleveland Electric illuminating Co 80/09/12 400pp
- B00919040B App 15A to Perry 1 & 2 FSAR. "Objectives "
 * Cieveland Electric Illuminating Co 80/09/12 20000
- 8009190410 App i50 to Perry 1 & 2 FSAR. "BWR/6 Generic Rod Withdrawai Error Analysis "
 # Cieveland Electric illuminating Co 80/09/12 100pp
- B009190411 Chapter 16 to Perry 1 & 2 FBAR. "Tech Specs " To be filed at Cievoland Electric Miluminating Co BO/09/12 ip
- 8009190413 Chapter 17 to Perry 1 % 2 FSAR, "QA"
 * Cleveland Ejectric Illuminating Co 80/09/12
- Q Inspection reports: 1E Bulietins & correspondence
- 8009040936 Forwards IE Bulletin 80-07. Suppi t. "BWR Jet Pump Assembly Fallure " Response required Response required G Reglan 3, Chicago, Office of the Director 80/05/14 KEPPLER, J G
- 8009030195 Forwards Revision 1 to IE Bulletin 80-i9, "Failures of Mercury-Hetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER, J O Region 3, Chicago, Diffice of the Director 80/08, Region 3, Chicago, Office of the Director 80/08/15
- 8009100105 Ack receipt of 800730 jtr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/80-09 & 50-441/80-09 FIORCLLI, O Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/08/15 ip
- --8009100112 Forwards response to NRC 800626 ltr re violations noted in IE Insp Repts 50-440/80-09 \$ 50-441/80-09 Corrective actions ultrasonic thickness measurements obtained on recirculation notzies & IE bullatins & circulars reviewed DAVIDSON,D R Cleveland Electric Illuminating Co 80/07/30 3pp
- 8007140434 Responds to IE Bulletin 80-17 re fallure of C-E mercurywetted matrix relays in reactor protective sys Identified relays are not used in facility Three manhours expended on DAVIDSON, D.R. Cleveland Electric Hiluminating Co. 80/08/19 1p

- 6009290525 Forwards lE Insp Repts 50-440/80-12 & 59-441/80-11 on 600701-31 No noncompliance nated floreLL.G Region 3. Chicago. Reactor Construction & Engineering Support Branch 60/08/19 2pp
- --8009290526 IE Insp Repts 50-440/80-12 & 50-441/80-11 on 800701-31 No noncompliance noted Major areas inspected licensee action on previous findings, concrete work activities & related quality records & NSSS equipment HUGHES J. WILLIAMS, C.C. Region 3. Chicago, Office of the Director 80/08/18 9pp
- 8009:50469 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Ecram Function & Honessential Centrol Air at Certain GE BHR Facilities " No specific action or response requested
- 8009120041 Forwards Buppl 3 to [E Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR " No written response required KEPPLER.J O Region 3, Chicago, Office of the Director 80/08/22
- 8009170412 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER. J G Region 3. Chicago. Office of the Director 80/08/22
- 80092300AB Forwards IE Info Notice 80-31. "Maluperation of Gould-Brown Bover: 480 Volt Type K-500S & K-DON 500S Circuit Breakers "No written response required KEPPLER.J Q Region J. Chicago. Office of the Director 80/08/28
- 8009240095 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required KEPPLER.J O Region 3. Chicago, Office of the Director 80/09/10 In
- S Reportable occurrences, LERs & related correspondence
- 8009020067 Final deficiency rept re post-LOCA hydrogen analyzers
 During functional testing, pump failed due to panel outlet
 valves being closed when pump started Relief bypass valve
 installed across pump to stabilize temp Analyzer mods made
 DAVIDSON D R Cleveland Electric Illuminating Co 80/08/26 4pp
- 8009120297 Part 21 rept re drive shaft of Reliance IE motor driving Dia-Vac diaphragm pumps which stopped in two places during in-house functional test of post-LOCA hydrogen analyzer Deficiencios not reportable per 100fR50 50(e) or Part 21 DAVIDSON D R Cleveland Electric Illuminating Co RO/08/29. 2pp
- 8009240227 Ack receipt of 800826 final deficiency meet me post-LOCA hydrogen analyters FIGHELI.G Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/07/08 1p
- 8007270071 Ack receipt of 800829 ltr re Part 21 rept on post-LOCA deuterium analyzers Matter will be reviewed during insp despite util statement that matter is not reportable per 10CFR50 55(e) FIORELLI.G Region 3. Chirago, Reactor Construction & Engineering Support Branch 80/09/08 ip
- DOCKET 50-443 SEABROOK NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8007050194 Advises that Class I fee is due for 790516 amend application DIGOS.R M License Fee Management Branch 80/08/13 1p.
- O Adjudicatory correspondence
- 8009020036 Expresses disagreement on behalf of Beacoast Anti-Pollution League, w/J Handrie decision to participate in 2 206 petition Although petition is not same proceeding as CP, from which JM Hendrie was disqualified, case is factually related BACKUB, R A O'Reil, Backus. Spielman 80/08/25 4pp
- 3009100597 Responds to 800825 ltr on behalf of Beaccast Anti-Pollution League apposing Hendris participation in NRC action on 10CFR2. 206 petition Review period expired 800822 "articipation in areas outside CP proceeding will continue ENURIE, 3 M Commission 80/09/08 fp.

- 9009120398 Order granting extension until 800926 for Commission to review ALAB-422 % relevant portions of ALAB-561 CHILK, S. J. Office of the Secretary of the Commission 80/09/10 ip
- 8009300037 Order, CLI-80-33, remanding ALAB-422 to ASLAB for add1 evidence on Chinnery methodology Parties must discuss relation between max ground accelerations & max effective ground acceleration of Ahearne dissenting opinion encl CHILK, S. J. Office of the Secretary of the Commission 80/09/25 600
- H General correspondence
- 8009290220 Responds to 800630 ltr QLs will not be issued until util develops & implements emergency plan for safe evacuation of surrounding area DENION H R Office of Nuclear Reactor Regulation. Director 80/09/05 | 2pp
- Q Inspection reports. IE Bulletins & correspondence
- E0091i0478 Responds to IE Sulletin 79-03A Results of review of SA-312, Type 304 fusion-welded stainless steel pipe indicate sufficient min pipe uall thickness DEVINCENTIS.J Public Service Co of New Hampshire 80/08/04 is
- 8009190089 Ack receipt of 800627 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-443/80-04 & 30-444/80-04 CARLSON,R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/08/14 ip
- --8009190074 Responds to NRC 800523 ltr re violations noted in 1E Insp. Repts 50-443/80-04 & 50-444/80-04 Corrective actions weld repair process sheets revised to include sequences for visual examination. DEVINCENTIS. J. Public Service Co. of New Hampshire 80/06/27 Pag.
- --8009190100 Forwards IE Insp Repts 50-443/80-04 & 50-444/80-04 on 800414-17 & notice of violation CARCSGIN:R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/23 2pp
- --8009190104 Notice of violation from insp on 800414-17 * Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/05/21 ip
- --B009190106 IE Insp Repts 50-443/80-04 & 50-444/80-04 on B00414-17 Noncompliance noted failure to provide sequence of pipe weld repairs to assure code compliance MCGAUOHY, R M Region I, Philadelphia, Reactor Construction & Engineering Support Branch CERNE, A C, VARELA, A A Region I, Philadelphia, Office of the Director B0/03/21 Bpp
- 8009030047 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Mercury-Watted Matrix Relays in Reactor Protective 89s of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER, 9 H Region 1, Philadelphia, Office of the Director 80/08/15 ip
- 8007180048 Forwards IE Circular 80-18. "10CFR50,59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GRIER,B H Region 1, Philadelphia, Office of the Director 80/08/22 lp
- SCO912021: Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6005 & K-DON 6005 Circuit Breakers " No written response required GRIER.B H Region I, Philadelphia, Office of the Director 8000027
- 8009230796 Forwards 1E Circular 80-21, 'Regulation of Refueling Creus' No written response required gales, 8 H Region 1. Philadelphia, Office of the Director. 80/09/10 ip
- 8009240332 Forwards IE Info Notice 80-32, "Clarification of Cartain Requirements for Exclusive-Use Shipments of Radioactive Matls "No written response required ORIER.B H Region 1. Philadeiphia, Office of the Director. 80/09/12 ip

5 Reportable occurrences. LERs & related correspondence

- 8009030553 Interim deficiency rept re rod drop analysis Nestinghouse topical rept unavailable until late Sept 1980 Final rept espected by Dec 1980

 DEVINCENTIS, B Public Service Co of New Hampshire G0/08/21 1p
- 8009090419 Final deficiency rept re use of invalid seismic amplified response spectra Short-term audit of seismic Category 1 sys & components complete Redesign of containment annular steel complete Beismic verification program will be completed DEVINCENTIS.J Public Service Co or New Hampshire 80/08/28 5p
- e009160645 Part 21 final rept re use of invalid seismic amplified response spectra in design of components supported by containment bldg annular stee! framing Annular stee! redesigned to increase rigidity
 SARBTEN. © E United Engineers & Constructors, Inc (subs of Raytheon Co) 80/08/29 8pp

DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8009050194 Advises that Class I fee is due for 790516 amend application DIGOS:RM License Fee Management Branch 80/08/13 ip

G Adjudicatory correspondence

- B009020036 Expresses disagreement on behalf of Seacoast Anti-Pollution League.w/J Hendrie decision to participate in 2 206 patition Although petition is not same proceeding as CP, from which JM Hendrie was disqualified case is factually related BACKUS, R A O'Neil, Dackus, Spielman 80/08/25 4pp
- 8009100597 Responds to 800825 ltr on behalf of Seacoast Anti-Pollution League opposing Hendris participation in NRC action on IOCFR2 206 petition Review period expired 800822 Participation in areas outside CP proceeding will continue HENDRIE, J M Commission 80/09/08 lp
- 8009120398 Order granting extension until 800926 for Commission to review ALAB-422 & relevant portions of ALAB-541 CHILK.S J Office of the Secretary of the Commission 80/09/10
- 8009300037 Order, CLI-80-33, remanding ALAB-422 to ASLAB for additional on Chinnery methodology Parties must discuss relation between max ground accelerations & max effective ground acceleration JF Abearne dissenting opinion encl CHILK-S J Office of the Socretary of the Commission 80/09/25

H General correspondence

- 8009270220 Responds to 800630 ltr OLs will not be issued until util develops & implements emergency plan for safe evacuation of surrounding area DENTON.H R Office of Nuclear Reactor Regulation, Director 80/07/03 2pp
- 4 Inspection reports, 1E Bulletins & correspondence
- 8009110478 Responds to IE Bulletin 79-03A Results of review of 6A-312, Type 304 fusion-welded stathless steel pipe indicate sufficient min pipe wall thickness DEVINCENTIS. J Public Service Co of New Hampshire 80/08/04 ip
- E009190089 Ack receipt of 800627 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-443/80-04 & 50-444/80-04 CARLEON,R T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/14 ip
- --8009190094 Responds to NRC 800523 ltr re violations noted in IE Insp Repts 50-443/80-04 & 30-444/80-04 Corrective actions weld repair process sheets revised to include sequences for visual examination DEVINCENTIS, J Public Service Co of New Hampshire 80/06/27 200
- --8009190100 Forwards IE Insp Repts 50-443/80-04 & 50-444/80-04 on 800414-17 & notice of violation CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/23 2pp

- --8009190104 Notice of violation from insp on 800414-i7

 4 Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/21 ip
- --8009190106 IE Insp Repts 50-443/80-04 & 50-444/80-04 on 800419-17 Noncompliance noted failure to provide sequence of pipe weld repairs to assure code compliance MCGAUGHY.R W Region I, Philadelphia, Reactor Construction & Engineering Support Branch CERNE.A C . VARELA.A A Region 1, Philadelphia, Office of the Director 80/09/21 8pp
- 8009030047 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Notted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER.0 II Region L. Philadelphia. Office of the Director 80/08/15 19
- 8009180048 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwasto Treatment Sys " No written response required GRIER B H Region L. Philadelphia. Office of the Director 80/08/22 1p
- 8009120211 Forwards IE info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-6006 & K-DON 6008 Circuit Breakers " No written response required GRIER.B M Region 1. Philadelphia, Office of the Director 80/08/27 Ip
- 8009230796 Forwards IE Circular 80~21. "Regulation of Refueling Crews " No written response required GRIER B H Region 1. Philadelphia. Office of the Director 80/09/10 1p
- 8007240332 Forwards IE Info Notice 80-32. "Clarification of Certain Requirements for Erclusive-Use Shipments of Radioactive Matis " No written response required GRIER, B H Region i, Philadelphia Office of the Director 80/09/12 IP
- S Reportable occurrences, LERs & related correspondence
- 8009030353 interim deficiency rept re rod drop analysis Westinghouse topical rept unavailable until late Sept 1980 Final rept expected by Dec 1980

 DEVINCENTIS: 8 Public Service Co of New Hampshire 80/08/21 1p
- 8009090419 Final deficiency rept re use of invalid seismic amplified response spectra Short-term audit of seismic Category 1 sys A components complete Redesign of containment annular steel complete Seismic verification program will be completed DEVINCENTIS.J Public Service Co of New Hampshire 80/08/20 5pp
- DOCKET 50-445 COMANCHE PEAK STEAM CLECTRIC STA . UNIT 1
- A Application/construction stage documents & correspondence
- 8009020219 "Initial Draft Safety Evaluation on Metallurgy Review "
 ANDERSON, W E , ATTERIBOE. D G , OLSON, N J Dattelle Memorial
 Institute. Pacific Northwest Laboratory 80/07/31 60pp
- 8009080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/O NUREO EISENHUJ, D G Division of Licensing 80/08/01 119pp
- 8009030460 Forwards requests for add1 info re instrumentation & control sys in order to complete evaluation of OL applications FSAR should be amended to include requested info TEDESCO.R L Assistant Director for Licensing 80/08/14 iOpp
- 8009020491 Forwards request for addl info re confirmatory piping analysis
 TEDESCO.R L. Assistant Director for Licensing 80/08/18 App
- 8009100004' Notification of 800826 meeting w/util in Bethesda,MD to discuss implementation of NUREG-0676 functional criteria BURNELL.8 B Operating Reactors Branch 2 80/08/22 3pp
- 8009170404 Forwards request for add1 info re environ review for facility Environ rept should be amended to include Encl 1 info TEDESCO.R L Assistant Director for Licensing 80/08/27 17pp

- 8009160352 Responds to 800814 request for addl info Answers to questions from Instrumentation & Controls Bys Branch & ANL consultants will be submitted by Amend to FSAR on B01031 GARY, R. J. Texas Utilities Generating Co. 80/09/08 ip
- 8009220334 Forwards add1 electrical instrumentation > control drawings to assist in NRC review OARY,R J Texas Utilities Generating Co 80/09/12 2pp
- --8009220333 "Diesel Generator & Monitor Lights Schematic & Connection Diagram Sheet Issue Record & Index " Sheet O # Gibbs & Hill, Inc. (subs. of Dravo Corp.) 2323 80/09/12 10
- --8009220344 "Diesel Generator 1D01.Start Circuit Channel I.Schematic Diagram " Sheet 4! # Gibbs 7 Hill, Inc (subs of Dravo Corp) 2323 80/08/27
- --8009220348 "Diesel Cenerator 1DC1.Start/Stop Circuit Channel II. Schematic Diagram " Sheet 42 * Gibbs & Hill. Inc. (subs. of Drave Corp.) 2323 80/08/27
- --8009220357 "Diesel Generator 1D02.Start Circust Channel I.Schematic Diagram " Sheet 43 a Gibbs & Hill, Inc (subs of Dravo Corp) 2323 80/08/27 ip
- ~-8009226368 "Diesel Generator 1802.Start/Stop Circuit Channel II. Schematic Diagram " Sheet 44 * Oibbs ' Hill, Inc. (subs. of Dravo Corp.) 2323 80/08/27
- --8009220380 "Diesel Cenerator 1DC1.Miscellaneous Circuits Sheet 1. Schematic Diagram " Sheet 45

 + Gibbs S Hill. Inc (subs of Dravo Corp) 2323 80/08/27
- --8009220383 "Diesel Generator IDG1.M(scellaneous Circults Sheet 2. Schematic Diagram " Sheet 46 * Gibbs & Hill, Inc. (subs. of Dravo Corp.) 2323 80/08/27
- --8009220385 "Diesel Generator 1092-Hiscellaneous Circuits Sheet (, Schematic Diagram " Sheet 47 4 Gibbs & Hill, Inc. (subs. of Dravo Corp.) 2323 60/08/27 1p
- --8009220387 "Diesel Generator 1DG2/Miscellaneous Circuits Sheet 2. Scheratic Diagram " Sheet 48 • Olobs & Hill. Inc. (subs. of Dravo Corp.) 2323 80/08/27 1p
- --8009220392 "Diesel Generator IDGI.Miscellaneous Circuits Sheet 3, Schematic Diagram " Sheet 49 # Gibbs & Hill, Inc (subs of Dravo Corp.) 2323 80/08/27 ip
- --8009220393 "Diesel Opnerator ID92.Miscellaneous Circuits Sheet 3. Schematic D(agram " Sheet 50 # Gibbs & Hill. Inc. (subs. of Dravo Corp.) 2323 80/08/27
- 8009230623 Forwards response to NRC 800827 request for add1 info re environ review & amended environ review pages List of encls only encl Encls sent to J Lehr in separate package WERNER.R Texas Utilities Bervices. Inc 80/09/12 3pg
- C Utility Environmental Report (ER), amends & correspondence
- 8009300442 Confirms 800925 teleon Review team will use unofficial amended environ rept until docteted Amend 1 received HARRIS,V A Argonne National Laboratory 80/09/26 ip
- F Security, medical, emergency & fire protection plans
- 8007020143 Invites participation in 800822 workship in Atlanta, CA to solicit comment re proposed functional critoria for emergency response facilities in NUREC-0576 Discussion to include location, size 2 staffing of emergency ctrs. SEYPRIT, K V. Region 4. Dallas. Office of the Director 80/08/12 to

- G Adjudicatory correspondence
- 8007070239 Response in opposition to applicant Aug 1980 first set of interrogatories Moves for protective order due to harasmant a intimidation Requests unspecified extension of time to answer interrogatories Certificate of Svc encl HAMTHORNE, S. GAY, 9 M. Association of Community Organizations for Reform Now-Texas. HAMTHORNE, S. West Texas Legal Services 60/09/28.
- 8009020432 Forwards 800729 FR notice re procedural assistance change in adjudicatory licensing proceeding effective 800725 Policy does not apply to RL Fouke 800815 request for 790522 transcript which may be paid for & obtained from PDR RDTHSCHILD, M U Hearing Branch 1 80/08/29 Sep
- 8009150045 Offer of proof in support of intervenor 800701 motion for reconsideration of GA/OC contention Urges admission to modify Contention 5 to include issues raised in encl interprets Certificate of Svc enci OAY.O M Association of Community Organizations for Reform Now-Texas CAY.O M West Texas Legal Services 80/08/29 6pp
- --8009190050 Forwards IE Insp Repts 50-445/73-02 & 50-446/73-02 on 731203-06 & notice of violation HQNARD,E M Atomic Energy Commission 74/01/07 2pp
- ---8009150051 Natice of violation from insp on 731203-06
 * Atomic Energy Commission 74/01/07 Spp
- ~~8009150555 IE Insp Repts 50-445/73-02 % 50-446/73-02 on 731203-06 Noncompliance noted GA program did not comply w/App B % not carried out per written policies WARNICK,R F , PERANICH,M W , MADSEN,Q L Atomic Energy Commission 74/01/07, 20pp
- --B009150057 Forwards IE Insp Repts 50-445/74-01 & 50-446/74-01 on 740313-14 No noncompliance noted HOWARD.E M Atomic Energy Commission 74/03/19 3pp
- --8009150060 IE Insp Repts 50-445/74-01 & 50-446/74-01 on 740319-14
 Certain items of previous QA concerns remain open re
 requirement of AMSI distribution of drawings & vendor
 qualification for bidders' list
 WARNICK-R F . MADSEN.G L Atomic Energy Commission 74/03/18
- --8009150063 Forwards IE Insp Repts 50-445/74-02 % 50-446/74-02 on 740627-28 HONARD, E.H. Atomic Energy Commission 74/07/11 3pp
- --8009150066 IE Insp Repts 50-445/74-02 & 50-446/74-02 on 740627-28
 Noncompliance noted GA policy & gracedures do not meet ANSI
 stds
 CROSMAN, W A. STEWART, R C. MADSEN, O L. Atomic Energy Commission
 74/04/11 10pp
- ~-8009150068 Forwards IE Insp Repts 50-445/74-03 & 50-446/74-03 on 740718-19 Nancompliance noted HOMARD, E M Atomic Energy Commission 74/07/30 2pp
- ---BOD9150071 IE Insp Repts 50-445/74-03 % 50-446/74-03 on 740718-19
 Noncompliance noted lack of delineation of QA/GC interface
 activities & failure to detail responsibilites
 STEMART.R G , CROSSMAN.W A , MADSEN.O L Atomic Energy Commission
 74/07/30 789
- ---8009150113 Forwards IE Insp Repts 50-445/74-04 & 50-446/74-04 on 741107-08 Moncompliance noted HOWARD,E M Atomic Energy Commission 74/11/19 3pp
- --8009150075 IE Insp Repts 50-445/74-04 & 50-446/74-04 on 741107-08
 Noncompliance noted OC procedures not adequately controlled
 & QA program manual had no procedural control re changes,
 revision or addition
 STEMART, R C , DICKERSON, M W , MADSEN, O L Atomic Energy
 Commission 74/11/19 11pp
- --8009180114 Forwards IE Insp Repts 50-445/75-12 & 50-446/75-12 on 750911-12 No noncompliance noted MADSEN,O L Region 4, Dallas, Reactor Construction & Engineering Support Branch 75/10/01 2pp
- --8009150077 IE Insp Repts 90-445/75-12 & 50-446/75-12 on 750911-12 No noncompliance noted Areas inspected licenses action on previously identified enforcement matter STEMARTIR C. HUJACEKIN G. CROSSMAN, W.A. Region 4, Dallas, Office of the Director 75/10/01 App

- --8009150120 Forwards IE Insp Repts 50-445/76-01 & 50-446/76-01 on 760107-09 Nancompliance noted MADSEN, 0 L Region 4, Dalias, Reactor Construction & Engineering Support Branch 76/01/29 2pp
- --80091500B0 IE Insp Repts 50-445/76-01 1 50-446/76-01 on 760107-09
 Noncompliance noted OC/GA surveillance conducted w/o
 prescribed procedures
 STEWART,R C , DICKERSON,M H Region 4, Dallas, Office of the
 Director CROSSMAN,W A Region 4, Dallas, Reactor Construction &
 Engineering Support Branch 76/01/27 14pp
- --8009150122 Forwards IE Insp Repts 50-445/76-08 & 50-446/76-08 on 760726-30 Noncompliance noted SEIDLE, W C Region 4. Dallas. Office of the Director 76/08/20 2pp
- --8009190083 IE Insp Repts 50-445/76-08 & 50-446/76-08 on 760724-30 Noncompliance noted OA manager duties & responsibilities encompassed engineering functions beyond GA program manual SIEWART,R C. ROSENBERG.A B. CROSSMAN,W A Region 4. Dallas, Office of the Director 76/08/19 15pp
- --EC09150125 Forwards IE Insp Repts 50-445/77-02 & 50-446/77-02 on 770301-04 Noncompliance noted BEIDLE, W C Region 4, Dallas. Reactor Construction & Engineering Support Branch 77/03/23 2pp
- --80091500B7 IE Insp Repta 50-445/77-02 % 50-446/77-02 on 770301-04 Noncompliance noted failure to meet GA procedure reporting requirement CROSSMAN.W A . STEWART.R C . TAPIA.J I Region 4. Dallas, Office of the Director 77/03/23 iipp
- --8007150127 Forwards IE Insp Repts 50-445/78-05 & 50-446/78-05 on 770321-24 & notice of violation SEIDLE.W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 78/04/06 2pp
- --8007[5007] Notice of violation from insp on 780321-24
 Region 4, Dallas, Office of the Director 78/04/05 ip
- --8009150093 IE Insp Repts 50-445/78-05 & 50-446/78-05 on 780321-24 Noncompliance noted vendor quality documentation unavailable TAYLOR.R O , HALL.R E , CROSSMAN,W A Region 4. Dallas, Office of the Director 78/04/05 5pp
- --8909150133 Forwards IE Insp Repts 50-445/78-07 & 50-445/78-07 on 780416-21 & notice of violation SEIDLE, U.C. Region 4, Dallas, Office of the Director 78/05/10 20p
- --B009150094 Notice of violation from insp on 780411-21 * Region 4, Dallas. Office of the Director 78/05/10 ip
- --B009190100 IE Insp Repts 80-449/78-07 t 50-446/78-07 on 780411-21 Noncompliance noted failure to meet PBAR commitments re concrete testing frequency TAYLOR:R 0 , FOSTER:M C , WARD, J J Region 4, Pallas, Office of the Director 78/05/10 10pp
- --8009150136 Forwards IE Insp Repts 50-445/78-11 & 50-446/78-11 on 780620-23 & notice of violation SEIDLE, H C Region 4, Dallas, Office of the Director 78/06/30
- --8009150102 Notice of violation from insp on 780420-23 * Region 4, Dallas, Office of the Director 78/04/29 ip
- --B009150105 IE Insp Repts 50-445/78-11 & 50-446/78-11 on 780620-23 Noncompliance noted failure to follow piping installation procedures TAYLOR, R 0 , CROSSMAN, W A Region 4, Dallas, Office of the Director 78/06/29 App
- BOC9100435 Motion for extension until 800915 to respond to applicants' first set of interrogatories Certificate of Svc encl MCCOLL.A C , MILLS.T , HART, J L Citizens for Fair Utility Regulation BO(09/02 2pp
- 8009090579 Forwards original of verification encl w/answers to applicant 800903 first set of interrogations & requests to produce Affidavit oncl W/o verification ELLIS, J Citizens Association for Bound Energy 80/09/03, 2pp

- 8009i10034 Response to applicants' first set of interrogatories & requests for production of documents Moves for 60-day extension to respond to Interrogatories 55-65 re cost/benerit baiance Objects to remaining questions ELLIS, J Citizens Association for Sound Energy 80/09/03 42pp
- --8009(100044 Forwards affidavit re intervenor 800903 response to applicants' first set of interrogatories Certificate of Svc encl ELLIS, J Citizens Association for Sound Energy 80/09/03 3pp
- 8009080039 Response stating no objection to Citizens Association for Sound Energy 800820 motion for extension until 800903 to reply to applicants' first set of interrogatories Certificate of Svc encl ROTHSCHILD.M U Hearing Branch 1 80/09/04 3pp
- 8009110048 Response to Citizens Association for Sound Energy request for production of documents contained in 800707 first set of interrogatories Matis will be available for insp & copying upon arrangement w/HG Schmidt Certificate of Svc enc? REYNOLDS,N S . HORIN,W A Texas Utilities Generating Co REYNOLOS,N S Debevoise & Liberman 80/07/08 Spp
- 6009110369 Confirms conversation re objection & intent not to respond to util 600825 interrogatories & document requests Factual discovery closed since 800314 interrogatories are ill-timed as efforts have been made to encourage settlement STAML, D N Isham, Lincoln & Beate 80/09/08 ip
- 8009110781 Response stating no objection to Citizens for Fair Util Regulation 800902 request for extension until 800915 to respond to applicants' 800813 first set of interrogatories & request for production of documents W/Certificate of 8vc REINOLDS,N S . HORIN,W A Texas Utilities Generating Co REYNOLDS,N S Debevoise & Liberman 80/09/09 3pp
- 8009110794 Response stating no objection to Citizens for Fair Util Regulation 800902 motion for extension until 800919 to respond to applicants' first sets of interrogatories & request for production of documents Centificate of Eve encl ROTHSCHILD.M U Hearing Branch 2 80/09/11 3pp
- 8009170361 Submits status of ropt on settlement negotiations on behalf of TX-LA Electric Cooperative of TX Inc No unresolved issues exist at present Certificate of Svc enc1
 BURCHETTERW H Northcutt Ely BO/09/11 3pp
- 8009170141 Motion to compel TX Association of Community Organizations for Reform Now response to applicants interrogatories Opposes intervenor motions for protective order & for addition W/Certificate of Svc Related correspondence REYNOLDS.N S . HORIN.W A Texas Utilities Generating CorrEYNOLDS.N S . Debevoise & Liberman 80/09/12 16pp
- 8009260005 Response to applicants' first set of interrogaturies & request for production of decuments Objects to majority of questions on basis of ambiguity Certificate of Svc encl FOUVE,R L , HART,J L , MCCOLL,A C Citirens for Fair Utility Regulation 80/09/15 17pp
- 8009230005 Motion to compel Citizens Associatin for Sound Energy response to first set of interrogatories Opposes motion for 40-day altension re Interrogatories 55,57,59,61,62 & 64 Responds to request for clarification W/Certificate of Svc REYNOLDS,N S , HARIN. M A Texas Utilities Generating Co REYNOLDS,N S Debevoise & Liberman 60/09/18 22pp
- 8009260008 Motion for protective order due to applicants' 800813 voluminous first set of interrogatories & request for production of documents consisting of 167 basic demands Certificate of Svc enci HART, J. MILLS, T. MCCOLL, A. Citizens for Fair Utility Regulation 80/09/18 7pp

H Quneral correspondence

- 800902010B Responds to 80080B ltr Advises that heat-induced illness being watched closely at plants Const has progressed to point that most work being done indoors Applicants have taken steps to improve working conditions by adding fans DENION. If R Office of Nuclear Reactor Regulation, Director 80/08/12 1g
- ----8009020112 Informs that TX experiencing severe heat wave Requests that const on nuclear reactors be halted until temp at normal level for season Humanly impossible for const workers to do excellent work required LEVINE.H R Affiliation Unknown 80/07/08 1p

M Antitrust currespondence

- 8009040196 Response to applicants.Central & South West Corp & City of Austin T/ objections to TY Border Cooperative petition to intervene Asserts interests under LBP-74-13 Urges full party participation W/Certificate of Svc O'Nell.R A Southwest Tesas Electric Cooperative O'NElL.R A Miller,Balis & O'Nell 80/07/31 16pp
- 8009020282 Requests that info be provided to all parties re wheeling rate development per 800826 discussions Discusses principles to be considered re-smaller util participation in facility ownership SPIEGEL.9 Spiegel & McDiarmid SPIEGEL.0 Brownsville, TX 80/08/28 4pp
- 8009030721 Advises that appropriate steps have been taken to insure svc of status repts 2 pleadings CHANANIA.F D Antitrust Division 80/08/29 [p
- 8007040287 Jpint motion for partial revision of ASLB 800813 order re procedural schedule Suggests 800712 for settlement status repts, 800715 for prehearing conference & 801112 for evidentiary hearing connencement Certificate of Svc encl CHANANIA; D Antitust Division FLYNN, P Q Houston Lighting & Power Co FABRIKANI, R Justice, Dept of 80/08/27 7pp
- 8009100261 Designates WA Russell of WA Russel & Associates as expert engineering witness which DDJ may call at trial of facility licensing proceeding MCHILLENN H Justice Dept of 80/09/03 1p
- 8009110792 Order revising procedural schedule set in ASLB 800813 order Settlement status rept shall be submitted on 800912, prehearing conference shall commence on 800915, trial briefs on 801008 % 22 & evidentiary hearing on 801112 MILLER.M.E. Atomic Safety and Licensing Board Panel 80/09/08 2pp
- 8009150417 Notion to compet Central Power & Light response to 800829 interrogatories Objection erroneous due to necessity to know full scope of take-over plans N/DM Stohl 800908 itr, excerpts of util corrected discovery & Certificate of Svc SPIEGEL, 0, POIRIER M R Brownsville, TX SPIEGEL, 0 Spiegel & McDiarmid 80/09/11 23pp
- 9009160275 Notice of taking MP Sayles & T Russell of CP&L 800923 & 24 depositions Examination will address possible purchase of Brownsyllte electric util tys & related studies & issuance of bonds Certificate of Syc enc!
 PDIRIER: M R Brownsyllie, TX POIRIER: M R Spiegel & McDiarmid 80/09/12 7pp
-)09170188 Settlement status rept Author approval of terms of stipulated licensing conditions not yet given No position on issues & procedures presented Certificate of Svc encl JOHN, D. F. HUNTER, M. South Teass Electric Cooperative JOHN, D. F. Medinaelectric Cooperative, Inc. 80/09/12 Spp
- 8009170359 Settlement status rept per ASLB 800813 order Agreement reached by util.NRC & DOJ which will dispose of all Comanche Peak issues when approved by ASLB Enci stipulation will insure OL would not violate antitrust laws SAMPLES.N D. KNOTTS.J B. Texas Utilities Generating Co SAMPLES.N D. Worsham, Forsythe & Sampels 80/09/12 2pp
- --BOD7170364 Stipulation incorporating encl license conditions Licensed denies past conduct w/o conditions violated antitrust laws Stipulation I conditions so not constitute admissions of violations CHANANIA.F D Antitrust Division * Justice.Dept of SURCHETIE.W H Texas-Louisiana Electric Cooperative.Inc BO/09/12 10pp
- --8007170369 Stipulation incorporating encl license conditions Licensee denies past conduct w/o conditions violated antitrust laws Stipulation & conditions do not constitute admissions of violations tivo conditions Certificate of Syc encl STARL.D Central > South West Corp KNDTTS, J B Texas Utilities Generating Co STARL.D Isham, Lincoln & Seale 80/09/12 App
 - 9170229 Fourth settlement status rept Stipulations w/applicants mbodying two sets of license conditions accomplished Final sation re need for hearing will be submitted after amination of conditions by parties W/Certificate of Syc IANANIA.F D Antitrust Division 80/09/14 7pp
 - 109170232 Stipulation incorporating new license conditions w/o admission of violation to antitrust laws CHANANIA,F D Antitrust Division FABRIKANT, R Justice, Dept of BURCHETTE, W H Texas-Louisiana Electric Cooperative, Inc 90/09/12 3pp

- --B009170235 Stipulation incorporating encl license conditions w/o admission of violation to antitrust laws BTAHL.D M Central & South West Corp BOUKNIOHT.J A Teras Utilities Generating Co B0/09/12 17pp
- ---B009170239 Stipulation incorporating enci license condition w/o admission of violation to antitrust laws FABRIKANT,R Justice. Dept of CHANANIA.F D Antitrust Division STAHL.D N Central & South Nest Corp 80/09/12 20pp
- 6005160157 Settlement status rept per ASLB 800813 order Endorses encl stapulation re license conditions reached by DDJ.NRC.FERG & Houston Lighting & Power Resolves concerns evidencing intent to litigate DDE endorsed settlement entirely in FERC case COPELAND.J 0 Houston Lighting & Power Co COPELAND.J 0 Baker & Botts 80/09/15 2pp
- --8009160160 Stipulation incorporating license conditions Licensee past or planned action w/o conditions not inconsistent w/ antitrust laws Conditions do not consistiute admission or violations Certificate of Svc encl FABRIKANTIR Justice Dept of CHANANIA.F D Antitrust Division 8TAHL.D Houston Lighting & Power Co 80/09/15 17pp
- 8009160102 Settlement status ropt per ASLU 80813 order Requests unspecified extension to receive 5 review new arguments & to determine 8 submit unresolved issues License canditions 5 settlement re FERC not yot received W/Certificate of Svc POIRIER.4 R Brownsville.TX POIRIER.4 R Spiegei & McDiarmid 80/09/15 9pp
- 8009170177 Settlement status rept Suggests approval of stipulated license conditions to maintain situation consistent w/ antitrust laws FERC & SEC approval of dc interconnections necessary for settlement execution Certificate of Svc encl STAHL, D M Central & South Mest Corp STAHL, D M Isham, Lincoln & Beale 80/09/15 12pp
- 8009180460 Suppl status rept per ASLB 800813 order DOJ reached agreement w/parties in Comanche Peak proceedings re proposed set of license conditions Agreement reached w/applicant in Bouth TX proceeding Certificate of Svc enci MCMILLENIN H Justice Dept of 80/09/19 7pp
- 8009250028 Order granting extension until 800929 for Commission to review ALAB-608 CHILK 8 J Office of the Secretary of the Commission 80/09/22 in
- B009260318 Motion for one-day extension to file comments on proposed settlement conditions Last minute consultations & discussions needed Ceptificate of Svc encl POIRIER.M R Drownsville.TX POIRIER.M R Spiegel & McDiarmid B0/09/24 ópp
- B009300035 Comments on proposed settlements per ASLB 800915 directive Proposed license conditions will serve to preclude or limit consideration of competitive implications of dc ties by FERC Certificate of Svc encl 0'NEIL.R A Southwest Texas Electric Cooperative 0'NEIL,R A Miller, Balls & 0'Neil 80/09/24 12pp
- 8009300488 Confirms that JR Choukas-Bradiey was authorized to express position of Miller, Balis & O'Neil, P C on behalf of TX Border Cooperatives at 800915 status hearing re leave to intervene out of time O'NEIL, R A Miller, Balis & O'Neil 80/09/24 2pp
- --8009300474 Comments of TX Border Gopperatives on proposed settlements of NRC & DOJ re licensing proceedings Certificate of Svc anci O'NEIL,R A Miller,Balis & O'Neil O'NEIL,R A Texas Border Cooperatives 80/09/24 10pp
- 8009300013 Motion in apposition to 800912 proposed license conditions due to failure to address crucial issues re effects of ac & dc interconnections Urges further proceedings to cure inconsistency w/antitrust laws Certificate of Svc encl SP1EGEL.0 , JABLON,R A , ROTH.A J Brownsville.TX 80/09/25 32pp
- 8009300326 Order granting extension until 800925 for all parties to comment on 800915 stipulation & licensing conditions WOLFE.S J Atomic Safety and Licensing Board Panel 80/09/25 ip
- N Antitrust hearing transcripts
- 8009190764 Transcript of 800915 prehearing conference in Bethesda, MD Pp 1078-1138 * Atomic Safety and Licensing Board Panel 80/09/15 44pp

- Q Inspection reports. IE Bulletins & correspondence
- 8009180095 Discusses 1E Insp Repts 50-445/80-15 & 50-446/80-15 on 800606 & 09 & forwards notice of violation EEIDLE.W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/06/23 2pp
- --B009180100 Notice of violation from insp on B00606 & 09 Noncompliance noted failure to establish QA program for Class 5 pipe support sys a Region 4. Dallas. Office of the Director 80/06/23 ipp
- 8009170420 Ack receipt of IE Insp Repts 50-445/80-11 & 50-446/80-11 Mo proprietary info CARY, R J Texas Utilities Generating Co 80/07/02 ip
- 8009150012 Responds to 'E Bulletin 80-05 re vacuum condition resulting in damage to holdup or low pressure tanks Tanks have adequate protection against vacuum conditions Design of holdup tanks compatible w/overflow requirements GARY, R J Teras Utilities Generating Co 80/07/il 3pp
- E009150337 Forwards IE Insp Repts 90-445/80-15 & 50-446/80-15 during June 1980 & notice of violation SEIDLE.W C Region 4. Dailas, Reactor Construction & Engineering Support Branch 80/07/23 2pp
- --8009180363 Notice of violation from insp during June 1980 * Region 4, Dalias, Reactor Construction & Engineering Support Branch 80/07/22 ip
- --B007150367 IE Insp Repts 50-445/80-15 ½ 50-446/80-15 during June 1980 Noncompitance noted failure to establish QA program for Class 5 pipe support sys ½ failure to follow const procedures required by drawings TAYLOR.R 0 . CROSGMAN.W A Region 4, Dalias, Office of the Director 80/07/22 App
- 8009180497 Submits response to IE Bulletin 79-03A SA-312 Type 304 & 316 fusion weld pipe has been used in safety-related sys which may be subj to design stresses in excess of 89% of code allowable stresses List of subj pipos enci CARY.R J Teras Utilities Generating Co 80/07/28 App
- B009100269 Forwards IE insp Repts 50-445/80-17 & 50-446/80-17 on B00714-18 & notice of violation SEIDLE,W C Region 4. Dalias, Reactor Construction & Engineering Support Branch B0/07/31 2pp
- --8009100273 Notice of violation from insp on 800714-18 * Region 4, Dalias, Office of the Director 80/07/31 ip
- --80091G0279 iE Insp Repts 50-445/80-i7 & 50-446/80-i7 on 800714-i8
 Noncompliance noted failure to use proper weld preparation
 counterbare transition tapers
 HALL.R E. OILBERT, L. D. Region 4, Dallas, Reactor Construction &
 Engineering Support Branch MARTIN, L. E. Region 4, Dailas, Office
 of the Director 80/07/31 Spp
- 8007290229 Responds to 800717 Itr Extends due date for response to notice of violation identified in IE Insp Repts 50-445/80-15 & 50-446/80-15 to 800820 SEIDLE.W C Region 4. Dallas. Reactor Construction & Engineering Support Branch 80/07/31 ip
- --8009290571 Requests extension until 800820 to determine scope of problem identified in IE Insp Repts 50-445/80-15 & 50-446/80-15 OARY, R J Texas Utilities Generating Co 80/07/17 1p
- 8009300055 Submits response to IF Bulletin 80-16 Rosemount Model 1151 or 1152 gressure transmitters have not been purchased nor are planned for safety-related applications ORRYR J. Texas Utilities Generating Co 80/08/08, ip
- BOO9030265 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required SEYFRIT.X V Region 4, Dallas, Office of the Director BO/OG/15 Ip
- 8009170406 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required SEYFRIT.K V. Region 4, Dallas. Office of the Director 80/08/22 in

- 8009120434 Forwards IE lnfo Notice 80-31, "Maloperation of Gould-Brown Bover1 480 Voit Type K-600S / K-DDN 600S Circuit Breakers " No written response required SEYPRIT,K V Region 4, Dallas, Office or the Director 80/08/27
- 8009300070 Submits response to 1E Sulletin 80-20 re Westinghouse Type W-2 control switches Requests extension to 801201 to complete review & corrective action GARY, R J Texas Utilities Generating Co 80/08/29 $_{\rm 1p}$
- 8009300065 Submits response to IE Bulletin 79-03A Etching ends of sarety-related 6A-312 Type 300 series fusion-welded pipe (s in progress Results of etching will be submitted by 801015 GARY, R. J. Teras Utilities Generating Co. 80/09/08 lp
- 8009300076 Submits response to 1E Bulletin B0-19, Revision 1 No CP Clare Model HG2X-1011 mercury-wetted relays in reactor protection sys GARY, R J Texas Utilities Generating Co 80/09/08 ip
- S Reportable occurrences, LERs & related correspondence
- 8009180045 interim deficiency lept re installation of welded conduit supports Typical engineering drawings for major support have been developed & included in conduft support package Inspiristruction revised GARY, R J Texas Utilities Generating Co 80/07/25 3pp
- B009230301 Deficiency rept re discrepancies in installation & insp requirements for Class V safety-related piping supports Caused by inadequate documentation to ascertain that supports satisfy design & seismic load requirements GARY, R J Texas Utilities Generating Co B0/09/18 2pp
- V Operator Examinations
- 8007070387 Forwards licensed operator training lessons for fluid flow heat transfer & thermodynamics in response to NRC 800328 itr Training re mitigation of severe core damage per inst for Nuclear Power Operations guidelines will be developed GARY,R J Texas Utilities Generating Co 80/08/11 184pp
- DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STA JUNIT 2

 A Application/construction stage documents & correspondence
- BD09020219 "Initial Draft Bafety Evaluation on Metallurgy Review " ANDERSON,W E , ATTERIDGE D Q , OLSON,N J Battelle Memorial Institute, Pacific Northwest Laboratory 80/07/31 60pp
- 8007080080 Forwards draft NUREG-0676. "Functional Criteria for Emergency Response Facilities" "Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 enci W/o NUREG EISENHUT, D Q Division of Licensing 80/08/01 119pp
- 80090300.60 Forwards requests for add1 info re instrumentation & control sys in order to complete evaluation of CL applications FSAR should be amended to include requested into TEDESCO.R L Assistant Director for Licensing 80/08/14 10pp
- 8009020491 Forwards request for addl info re confirmatory piping analysis
 TEDESCO, R L. Assistant Director for Licensing 80/08/18 4pp
- 8009100004 Notification of 800826 meeting w/util in Bethesda.MD to discuss implementation of NUREO-0696 functional criteria BURWELL.8 B Operating Reactors Branch 2 80/08/22 3pp
- 8009170404 Forwards request for addl info re environ review for facility Environ rept should be amended to include Encl I info TEDESCO,R L Assistant Director for Licensing 80/08/27 17pp
- 8009160362 Responds to 800814 request for add1 info Answers to questions from Instrumentation 2 Controls Sys Branch & ANL consuitants will be submitted by amend to FBAR on 801031 GARY, R J Teyas Utilities Generating Co 80/09/08 ip
- 8009220334 Forwards addit electrical instrumentation & control drawings to assist in NRC review GARY.R J Taxas Utilities Generating Co. 80/09/12 2pp.

- --8009220333 "Diesei Generator & Honstor Lights Schenatic & Connection Diagram Sheet Issue Record & Index " Sheet O + Gibbs & Hill: inc (subs of Dravo Corp.) 2323 80/09/12 ip
- --B009220344 "Diesei Generator 1001.Start Circuit Channel I.Schematic Diagram " Sheet 4i * Gibbs & Hill, Inc (subs of Dravo Corp.) 2323 80/08/27 1p
- --BO09220357 "Diesel Generator 1D02-Start Circuit Channel 1, Schematic Diagram " Sheet 43 # Gibbs 2 Hill Inc (subs of Dravo Corp) 2323 B0/08/27 ip
- --8009220369 "Diesel Generator iDC2.Start/Stop C;rcuit Channel II. Schematic Diagram " Sheet 44 # Gibbs 2 Hill, inc (subs of Dravo Corp) 2323 80/08/27 1P
- --8009220380 "Diesel Generator IDG1, Miscellaneous Circuits Sheet 1, Schematic Diagram " Sheet 45 a Gibbs 5 Hill, Inc (subs of Dravo Corp) 2323 BO/08/27
- --8007220393 "Diesel Generator IDG; Miscellaneous Circuits Sheet 2. Schematic Diagram " Sheet 46 * Gibbs & Hill, Inc (subs of Dravo Corp) 2323 60/08/27 Ip
- --8009220335 "Diesel Generator ID02.Miscellaneous Circuits Sheet I. Bohematic Diagram " Sheet 47 • Olbbs % Hill. Inc. (subs of Dravo Corp.) 2323 80/08/27 1p
- --8009220387 "Diesel Generator IDG2.Miscellaneous Circuits Sheet 2. Schemafic Diagram " Sheet 48 > Gibbs & Hill, Inc (subs of Dravo Corp) 2329 60/08/27 ip
- ~-8009220392 "Diesel Generator (DGI, Hiscellaneous Circuits Sheet 3, Schematic Diagram " Sheet 47 * Gibbs & Hill, Inc (subs of Drave Corp) 2323 80/08/27 ip
- --8009220393 "Diesel Generator 1D02.Miscellangous Circuits Sheet 3, Schenatic Diegram " Sheet 50 • Gibbs & Hill. Inc. (subs. of Drayo Corp. 1 2323 80/08/27 1s
- 8007230623 Forwards response to NRC 800927 request for addl info re environ review & amended environ review pages List of encis only enci Encis sent to J Lehr in separate package WERNER,R Texas Utilities Services, Inc. 80/09/12 3pp
- C Utility Environmental Report (ER), amends & correspondence
- 8009300442 Confirms 800925 telcon Review team will use unofficial amended environ rept until docketed Amend 1 received HARRIS.V A Argonne National Laboratory 80/09/26 1p
- F Security, medical, emergency & fire protection plans
- 8009020143 Invites participation in 800822 workshop in Atlanta, GA to solicit comment re proposed functional criteria for amergancy response facilities in NUREO-0696 Discussion to include location. Size & Staffing of emergency ctrs

 EEYFRIT. K V Region 4. Dallas. Office of the Director 80/08/12

G Adjudicatory correspondence

- 8007070238 Response in opposition to applicant Aug 1780 first set of interrogatories Hoves for protective order due to harassment & intimidation Requests unspecified extension of time to answer interrogatories Certificate of Svc encl HAMIHORNE, S. QAY, C.M. Association of Community Organizations for Reform Now-Texas HAWIHORNE, S. West Texas Legal Services 80/08/28 4pp
- 009020432 Forwards 800725 FR notice or procedural assistance change in adjudicatory licensing proceeding, effective 800725 Policy loss not apply to RL Foute 800815 request for 790522 ranscript which may be paid for & obtained from PDR WHSCHILD, KU Hearing Branch i 80/08/29 5pp

- 8009150045 Offer of proof in support of intervenor 800701 motion for reconsideration of GA/QC contention Urges admission to modify Contention 5 to include issues raised in enci insprepts Certificate of Svc enci GAY:0 M Association of Community Organizations for Reform Now-Texas QAY:0 M West Texas Legal Services 80/08/29 dpp
- --8009150050 Forwards IE Insp Repts 50-445/73-02 & 50-446/73-02 on 731203-06 & notice of violation HOMARDLE M Atomic Energy Commission 74/01/07 2pp
- ---8009150051 Netice of violation from insp on 731203-06 + Atomic Energy Commission 74/01/07 Epp
- --B009150055 lE insp Repts 50-445/73-02 & 50-446/73-02 on 731203-06
 Noncompliance noted GA program did not comply w/App B & not
 carried out per written policies
 WARNIGK.R F. PERANICH.M N . MADSEN.G L Atomic Energy Commission
 74/01/07 20pp
- --8009150057 Forwards IE Insp Repts 50-445/74-01 & 50-446/74-01 pri 740313-14 No noncompliance noted HOWARD.E M Atomic Energy Commission 74/03/19 3pp
- --8009150060 IE Insp Repts 50-445/74-01 & 50-446/74-01 on 740313-14
 Certain items of previous GA concerns remain open re
 requirement of ANSI, distribution of drawings & vendor
 qualification for bidders' list
 WARNICK, R F, MADSEN, G L. Atomic Energy Commission 74/09/18.
- --8009150063 Forwards IE Insp Repts 50-445/74-02 & 50-446/74-02 on 740627-28 HOKARD,E M Atomic Energy Commission 74/07/11 3pp
- --BOD9150066 JE Insp Repts 50-445/74-02 & 50-446/74-02 on 740627-26 Noncompliance noted GA policy & procedures do not meet ANSI stds CROSSMAN, W A , STEWART, R C , MADSEN, Q L Atomic Energy Commission 74/04/11 10on
- --8009150068 Forwards IE Insp Repts 50-445/74-03 & 50-446/74-03 on 740718-19 Noncompliance noted HOWARD E M Atomic Energy Commission 74/07/30 2pp,
- --B009180071 IE Insp Repts 80-445/74-03 & 50-446/74-03 on 740718-19
 Noncompliance noted lack of delineation of QA/QC interface
 activities & failure to detail responsibilities
 STEWART.R C , CROSSMAN, W A , MADSEN, O L Atomic Energy Commission
 74/07/30 7pp
- --8009150113 Forwards IE Insp Repts 50-445/74-04 & 50-446/74-04 on 741107-08 Noncompliance noted HOWARD, E M Atomic Energy Commission 74/11/19 3pp
- --8007150075 IE Insp Repts 50-445/74-04 & 80-446/74-04 on 741107-0B Noncompliance noted GC procedures not adequately controlled & GA program manual had no procedural control re changes, revision or addition STEWART.R G , DICKERBON,M W , MADBEN,G L Atomic Energy Commission 74/11/19 ilpp
- --8009150116 Forwards IE Insp Repts 80-445/75-12 & 50-446/75-12 on 750911-12 No noncompliance noted MADSEL OL Region 4, Dalias, Reactor Construction & Engineering Support Branch 75/10/01 2pp
- --8009150077 iE Insp Repts 50-445/75-12 & 50-446/75-12 on 750911-12
 No noncompliance noted Areas inspected licensee action on previously identified enforcement matter.
 STEMARTR C, HUDACEK, W G, CROBSMAN, W A Region 4. Dallas, Giffice of the Director 75/10/01 Spp
- --8009150120 Forwards IE Insp Repts 50-445/76-01 & 50-446/76-01 on 760107-09 Noncompliance noted MADSEN.0 L. Region 4, Dallas, Reactor Construction & Engineering Support Branch 76/01/29 Zpp
- --8009150080 IE Insp Repts 50-445/76-01 & 50-446/76-01 on 760107-09.
 Noncompilance noted QC/GA surveillance conducted w/o
 prescribed procedures
 STEMART,R C., DICKERSON,M N Region 4, Dallas, Office of the
 Director CROSSMAN,W A Region 4, Dallas, Reactor Construction &
 Engineering Support Branch 76/01/29 14pp
- --B007i90122 forwards IE Insp Repts 50-445/76-08 & 50-446/76-08 on 760726-30 Noncompliance noted SEIDLE.U C Region 4, Dailas, Office of the Director 76/08/20 3pp

- --8009150083 IE Insp Repts 50-445/74-08 & 50-446/76-08 on 740726-30 Noncompliance noted OA manager duties & responsibilities encompassed engineering functions beyond GA program manual STEMART,R C. ROSENBERG.A B. CROSSMAN,W A. Region 4, Dallas, Office of the Director 76/08/19 15pp
- --E009150125 Forwards IE Insp Repts 50-445/77-02 & 50-446/77-02 on 770301-04 Noncompliance noted SEIDLE,N C Region 4. Dailas, Reactor Construction & Engineering Support Branch 77/03/23 2pp
- -- ACO9150087 IE lnsp Repts 50-445/77-02 % 50-446/77-02 on 770301-04 Noncompliance noted failure to meet 9A procedure reporting requirement CROSSMAN, W A , STEWART, R C , TAPIA, J I Region 4, Dailas, Office of the Director 77/03/23 11pp
- --8009150129 Forwards IE Insp Repts 50-445/78-05 % 50-446/78-05 on 770321-24 & notice of violation SEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 78/04/06 2pp
- --8009150091 Notice of violation from insp on 780321-24
 * Region 4. Dailas. Office of the Director 78/04/05 lp
- --B009130093 IE Insp Repts 50-445/78-05 & 50-446/78-05 on 7B0321-24 Noncompliance noted vendor quality documentation unavailable TAYLOR, R O , HALL, R E , CROSSMAN, N A Region 4, Dallas, Office of the Director 7B/04/05 5pp
- --8009(50133) Forwards IE Insp Repts 50-445/78-07 & 50-446/78-07 on 780411-21 & notice of violation SEIDLE, H C Region 4, Dallas, Office of the Director 78/05/10 200
- --8009150096 Notice of violation from insp on 780411-21 • Region 4. Dallas. Office of the Director 78/05/IO 1
- --8009150100 IE Insp Repts 30-445/78-07 % 50-446/78-07 on 780411-21 Noncompliance noted failure to moet PSAR commitments re concrete testing frequency TAYLOR,R 0 - FOSTER, W E , WARD, J J Region 4, Dallas, Office of the Director 78/05/10 10pp
- --8009150136 Forwards IE Insp Repts 50-445/78-11 & 50-446/78-11 on 780620-23 & notice of violation SEIDLE, IF C Region 4, Dallas, Office of the Director 78/06/30 2pp
- --8009150102 Notice of violation from insp on 780620-23 • Region 4. Dallas, Office of the Director 78/06/29 lp
- --8009130105 lE Insp Repts 50-445/78-11 & 50-446/78-11 on 780620-23 Nancompliance noted failure to follow piping installation procedures TAYLOR.R 0 , CROSBMAN,W A Region 4, Dallas, Office of the Director 78/06/29 App
- 8007(00433 Motion for extension until 800715 to respond to applicants' first set of interrogatorios Certificate of Byc encl MCCOLL.A C . MILLB.T . HART.J L Citizens for Fair Utility Regulation 80/07/02. 2pp
- 8009090579 Forwards original of verification encl w/answers to applicant 800903 first set of interrogations & requests to produce Affidavit encl M/o verification ELLIS.J Citizens Association for Sound Energy 80/09/03 2pp
- 8009i10034 Response to applicants' first set of interrogatories & requests for production of documents Moves for 60-day extension to respond to Interrogatories 55-65 re cost/banefit balance Objects to remaining questions ELLIS. J Citizens Association for Sound Energy 80/09/03 42pp
- ~-8009110044 Forwards affidavit re intervenor 800903 response to applicants' first set of interrogatories Certificate of 8vc enc1
 ELLIS,J Citizens Association for Sound Energy 80/09/03 3pp
- 8009080039 Response stating no objection to Citizens Association for Sound Energy 800820 motion for extension until 800903 to reply to applicants' first set of interrogatories Certificate of Svc snc! ROTHSCHILD, N U Hearing Branch i 80/09/04 3pp

- 800911004B Response to Citizens Association for Sound Energy request for production of documents contained in 800707 ffrst set of interrogatories Matls will be available for insp. & copying upon arrangement w/MC Schmidt Certificate of Svc encl REYNOLDS N S . HORIM W A Texas Utilities Generating Co REYNOLDS N S Debevoise & Liberman 80/09/08 5pp
- 8009110369 Confirms conversation re objection & intent not to respond to util 800825 interrogatories & document requests Factual discovery closed since 800314 interrogatories are ill-timed as efforts have been made to encourage settlement STAHL, D.M. Isham, Lincoin & Beale 80/09/08 ip
- 8009110781 Response stating no objection to Citizens for Fair Util Regulation 800902 request for extension until 800915 to respond to applicants' 800813 first set of interrogatories & request for production of documents W/Certificate of Svc REYNOLDS.N S . HORIN.W A Teras Utilities Generating Co REYNOLDS.N S Debevoise & Liberman 80/09/09 3pp
- 8009110794 Response stating no objection to Citizens for Fair Util Regulation 800902 motion for extension until 800915 to respond to applicants' first sets of interrogatories & request for production of documents Certificate of Evc enci ROTHSCHILD.M U Hearing Branch 2 80/09/11 3pp
- 8009170361 Submits status of rept on settlement negotiations on behalf of TX-LA Electric Gooperative of TX, Inc No unresolved issues exist at present Certificate of Svc enci BURCHCTYE.W H Northcutt Ely 80/09/11 3pp
- 8009170141 Motion to compel TX Association of Community Organizations for Reform Now response to applicants interrogatories Opposes intervenor motions for protective order 5 for addition W/Certificate of 8vc Related correspondence REYMOLDS.N S . HORIN.N A Texas Utilities Generating CoreyNOLDS.N S Debevoise & Liberman 80/09/12 16pp
- 8009260005 Response to applicants' first set of interrogatories & request for production of documents Objects to majority of questions on basis of ambiguity Certificate of Svc enci FOUXE, R L , HART, J C , MCCOLL, A C Citizens for Fair Utility Regulation 80/09/15 17pp
- 8007230005 Motion to compe) Citizens Associatin for Sound Energy response to first set of interrogatories Opposes motion for 40-day extension re interrogatories 35, 37, 59, 61, 62 & 64 Responds to request for clarification W/Certificate of Svc REYMOLDS.N S , HORIN.W A Texas Utilities Generating Co REYMOLDS.N S Debevoise & Liberman 80/409/18 22pp
- 800926000B Motion for protective order due to applicants' B00813 voluminous first set of interrogatories & request for production of documents consisting of 167 basic demands ' Gertificate of Svc encl HART.J. MILLS.T., MCCOLL.A Citizens for Fair Utility Regulation B0/0971B 7pp

H Osqeral correspondence

- 8009020108 Responds to 800808 ltr Advises that heat-induced illness being watched closely at plants Const has progressed to point that most work being dane indoors Applicants have taken steps to improve working conditions by adding fans DENTON: HR Office of Nuclear Reactor Regulation. Director 80/08/12 ip
- --8009020112 Informs that TX experiencing severe heat wave Requests that const on nuclear reactors be halted until temp at normal level for season Humanly impossible for const workers to do excellent work required LEVINE, H R Affiliation Unknown 80/07/08 1p

M Antitrust correspondence

- 8009010196 Response to applicants.Central & South West Corp & City of Austin.TX objections to TX Border Cooperative potition to intervene Asserts Interests under LBP-74-13 Urges full party participation W/Certificate of Svc O'NEIL,R A Bouthwest Toxas Electric Cooperative O'NEIL,R,A Miller,Balls & O'Neil 80/07/31 16pp
- 8009020282 Requests that info be provided to all parties re wheeling rate development per 600826 discussions Discusses principles to be considered re smaller utal participation in facility education by BPIEGEL, G. Spiegel & McDiarmid SPIEGEL, G. Brownsville, TX 60/08/28 4pp

- 8009030721 Advises that appropriate steps have been taken to insure svc or status repts & pleadings CHANANIA.F D Antitrust Division 80/08/29 ip
- CHANANIA, F D ANTITTUST DIVISION 80/08/27 15
- 8009040289 Joint motion for partial revision of ASLB B00B13 order re procedural schedule Suggests 800912 for settlement status repts 800915 for prehearing conference & B01112 for evidentiary hearing commencement Certificate of Svc encl CHANAMIA.F D Antitust Division FLYNH,P G Houston Lighting & Pajer Co FABRIKANT,R Justice-Dept of 80/08/27 7pp
- B009100261 Designates WA Russell of WA Russel & Associates as expert engineering witness which DOJ may call at trial of facility licensing proceeding MCHILLEMAN W Justice-Dept of B0/09/03 lp
- 8009110792 Order revising procedural schedule set in ASLB 800Bi3 order Sattlement status rept shall be submitted on 800912, prehearing conference shall commence on 800915, trial briefs on 801008 & 22 & evidentiary hearing on 801112 MILLERIN E Atomic Safety and Licensing Board Panel 80/09/08 2pp
- 80091504i7 Motion to compel Central Pauer & Light response to 800825 interrogatories Objection erroneous due to necessity to know full scope of take-over plans W/DM Stohl 800908 ltr, excepts of util corrected discovery & Certificate of Syc SPIEGEL, O, POIRIER, MR Brownsville, TX SPIEGEL, O Spiegel & McDiarmid 80/09/ii 23pp
- 8009160275 Notice of taking WP Sayles & T Russell of CP&L 800923 & 24 depositions Examination will address possible purchase of Brownsville electric util sys & related studies & issuance of bonds Certificate of Svc encl POIRIER.M R Spiegel & McDiarmid 80/09/12 7pp
- 8009170168 Settlement status rept Author approval of terms of stipulated licensing conditions not yet given No position on issues & procedures presented Certificate of Svc encl JDHN, D F, HUNTER, M South Tesas Electric Cooperative, JOHN, D F Medinaslectric Cooperative, Inc. 80/09/12 5pp
- BO09170359 Settlement status rept per ASLB B00813 order Agreement reached by util.NRC & DOJ which will dispose of all Comanche Peak issues when approved by ASLB Encl stipulation will finaure OL would not violate antitrust laws
 SAMPLES.N D . KNOTTS.J B Teras Utilities Generating Co
 SAMPLES.N D Worsham, Forsythe & Sampels B0/09/12 2pp
- --8009170364 Stipulation incorporating encl license conditions Licensee denies past conduct w/o conditions violated antitrust laws Stipulation & conditions do not constitute admissions of violations CHANANIA,F D Antitrust Division & Justice, Dept of BURCHETTE,N H Texas-Louisiana Electric Cooperative, Inc B0/09/12 10pp
- --8009170369 Stipulation incorporating enci license conditions Licensee denies past conduct w/o conditions violated antitrust laws Stipulation & conditions do not constitute admissions of violations W/o conditions Certificate of Svc enci STAHL.D Central & South West Corp KNOTTS.J B Texas Utilities Generating Co STAHL.D Isham. Lincoln & Beale 80/09/12 App
- 8009170229 Fourth settlement status rept Stipulations w/applicants ambodying two sets of license conditions accomplished Final position re need for hearing will be submitted after examination of conditions by parties W/Certificate of Svc CHANANIA,F D Antitrust Division 80/09/14 7sp
- --B009170232 Stipulation incorporating new license conditions w/o admission of violation to antitrust laws CHANANIA.F D Antitrust Division. FABRIKANIA.R Justice.Dept of BURCHETIE.W H Texas-Louisiana Electric Cooperative.lnc B0/09/12 3pp
- -8009170235 Stipulation incorporating encl license conditions w/o admission of violation to antitrust laws STAML,D M Central & South West Corp BOUKNIGHT, J A Texas Utilities Generating Co 80/09/12 17pp
- O9140157 Settlement status rept per ASLB 800813 order Endorses encl stipulation re license conditions reached by DBJ, NRC, FERC & outton Lighting & Power Resolves concerns evidencing intent a litigate DDE endorsed settlement entirely in FERC case CPELAND, J G Houston Lighting & Power Co COPELAND, J G Baker & atts 80/09/15 2pp

- 8009160182 Settlement status rept per ASLB 80813 order Requests unspecified extension to receive & review new arguments & to determine & submit unresolved issues License canditions & settlement re FERC not yet received W/Certrilicate of Bvc PDIRIER,M R Brownsville,TX PDIRIER,M R Spiegel & McDiarmid 80/09/15 900
- 8009170177 Settlement status rept Suggests approval of stipulated license conditions to maintain situation consistent w/ antitrust laws FERC & SEC approval of de interconnections necessary for settlement execution Certificate of Bvc encl 87AHL, D M Central & South Mest Corp STAHL, D M Isham, Lincoln & Beale 80/09/15 12pp
- 8009180460 Suppl status rept per ASLB 800813 order DDJ reached agreement w/parties in Commence Peak proceedings re proposed set of license conditions Agreement reached w/Applicant in South TX proceeding Certificate of Svc encl HCMILLEN,N H Justice,Dept of 80/09/15 7pp
- B009250028 Order granting extension until 800929 for Commission to review ALAB-608 CHILK:S J Office of the Secretary of the Commission 80/09/22 ip
- 8009260318 Motion for one-day extension to file comments on proposed settlement conditions Last minute consultations & discussions needed Certificate of Svc encl POIRIER, M R Brownsville, TX POIRIER, M R Epiegol & McDiarmid 80/09/24 App
- 8009200035 Comments on proposed settlements per ASLB 800915 directive Proposed license conditions will serve to preclude or limit consideration of competitive implications of dc ties by FERC Certificate of Svc encl 0'MEIL.R A Southwest Texas Electric Cooperative 0'MEIL.R A. Miller.Balis & O'Neil 80/09/24 12pp
- 8009300488 Confirms that JR Choukas-Bradley was authorized to express position of Miller,Balis & O'Neil,P C on bohalf of TX Border Cooperatives at 800915 status hearing re leave to intervene out of time O'NEIL,R A Miller,Balis & O'Neil 80/09/24 2pp
- --8009300494 Comments of TX Border Cooperatives on proposed settlements of NRC & DOJ re licensing proceedings Certificate of Svc encl O'MEIL,R A Miller,Balis & D'Neil O'MEIL,R A Texas Border Cooperatives 80/09/24 10pp
- 8007300013 Motion in opposition to 800712 proposed license conditions due to failure to address crucial issues re effects of ac & dc interconnections Urges further proceedings to cure inconsistency w/antitrust laws Certificate of 8vc encl SPIE0EL, 0, JABLON, RA, ROTH, AJ Brownsville, TX 80/09/25 32pp
- 8009300326 Order granting extension until 800925 for all parties to comment on 800915 stipulation & licensing conditions WOLFE,S J Atomic Safoty and Licensing Board Panel 80/09/25, ip
- N Antitrust hearing transcripts
- 8009190764 Transcript of 800915 prehearing conference in Dethesda. MD Pp 1078-1138 * Atomic Safety and Licensing Board Panel 80/09/15 44pp
- G Inspection reports, 1E Bulletins & correspondence
- 8009180095 Discusses IE Insp Repts 50-445/80-15 & 50-446/80-15 on 800806 & 09 & forwards notice of violation SEJDLE-W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/06/23 2pp
- --8009180100 Notice of violation from insp on 800606 & 07 Noncompliance noted failure to establish OA program for Clase 5 pipe support sys * Region 4. Dallas, Office of the Director 80/06/23 ipp
- 8009170420 Ack receipt of IE Insp Repts 50-445/80-11 & 50-446/80-11 No proprietary info OARY, R J Texas Utilities Generating Co 80/07/02 1p.
- B009150012 Responds to IE Bulletin B0-05 re vacuum condition resulting in damage to holdup or low pressure tanks Tanks have adequate protection against vacuum conditions Design of holdup tanks compatible w/averflow requirements GARY,R J Taxas Utilities Generating Co B0/07/II 3pp

- 8009150337 Forwards IE insp Repts 50-445/80-15 \$ 50-446/80-15 during June 1980 & notice of violation EEIDLE, U.C. Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/07/23 2pp
- --8009150363 Notice of violation from insp during June 1980 * Region 4, Dallas, Roactor Construction & Engineering Support Branch 80/07/22 ip
- --GC09150367 IE Insp Repts 50-445/80-15 & 50-446/80-15 during June 1980 Noncompliance noted failure to establish GA program for Class 5 pipe support sys & failure to follow const procedures required by drawings
 TAYLOR, R 0 . CROSSHAN. W A Region 4. Dallas, Office of the Director 80/07/22 & pp
- 8009180457 Submits response to IE Bulletin 79-03A SA-312 Type 304 & 316 fusion weld pipe has been used in safety-related sys which may be subj to design stresses in excess of 857 of code allowable stresses Life of subj pipes encl
 GARY,R J Texas Utilities Generating Co 80/07/28 4pp
- 8007100269 Forwards IE Insp Repts 50-445/80-17 & 99-446/80-i7 on 800714-18 & notice of violation BEIDLE.W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/07/31 2pp
- --8009100273 Notice of violation from insp on 800714-18 * Region 4, Dallas, Office of the Director 80/07/31 i
- --8009100279 IE insp Repts 50-445/80-17 & 50-446/80-17 on 800714-18 Noncompliance noted failure to use proper weld preparation counterbore transition tapers HALL,R E , GILBERT,L D Region 4. Dallas, Reactor Construction & Engineering Support Branch MARTIN,L E Region 4. Dallas, Office of the Director 80/07/31 Spp
- BD09290229 Responds to 800717 ltr Extends due date for response to notice of violation identified in IE Insp Repts 50-445/80-15 & 50-445/80-15 to 800820 SEIDLE.H. C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/07/31 ip
- --800729057; Requests extension until 800820 to determine scope of problem identified in IE Insp Repts 50-445/80-15 & 80-446/80-15 CARY.R J Texas Utilities Cenerating Co 80/07/17 ip
- BOO9300055 Submits response to IE Bulletin BO-16 Rosemount Model 1151 or 1132 pressure transmitters have not been purchased nor are planned for safety-related applications
 OARY,R J Teras Utilities Generating Co BO/OB/OB 1p
- 8009030265 Forwards Revision 1 to IE Bulletin 80-19. "Failures of Mercory-Netted Matrix Relays in Reactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E " Uritten response required BEYFRIT.K V Region 4. Dallas. Office of the Director 80/08/15
- 5009170406 Forwards IE Circular 80-18. "IOCFR50 59 Safety Evaluations for Changes to Radwaste Troatment Sys " No written response required SEYFRIT,K V Region 4, Dallas, Office of the Director 50/08/22
- 8009120434 Forwards IE Info Notice 80-31, "Malaperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/08/27
- 8007300070 Submits response to IE Bultetin 80-20 re Westinghouse Type H-2 control switches Requests extension to 801201 to complete review & corrective action OARY.R J Texas Utilities Generating Co 80/08/27 1p
- 8009300065 Bubmits response to IE Bulletin 79-03A Etching ends of safety-related 8A-312 Type 300 series fusion-welded pipe is in progress Results of etching will be submitted by 801015 QARY,R J Texas Utilities Generating Co 80/09/08 1p
- 8009300076 Submits response to 1E Bulletin 80-19.Revision 1 No CP Clare Model H02X-1011 mercury-wetted relays in reactor prutection sys GARY.R J Texas Utilities Generating Co 80/09/08 ip

- S Reportable occurrences. LERs & related correspondence
- 8009180045 Interim deficiency rept re installation of welded conduit supports Typical engineering drawings for major support have been developed & included in conduit support package Inspiristruction revised GARY, R J Texas Utilities Generating Co 80/07/25 3pp
- 8009230301 Deficiency rept re discrepancies in installation & insp requirements for Class V safety-related piping supports Caused by inadequate documentation to ascertain that supports satisfy design & seismic load requirements GARY,R J Texas Utilities Generating Co 80/09/18 2pp
- U Congressional/Executive Correspondence
- 8007170383 Requests assistance in securing hearing date for CP Util has sought for 3 yrs to secure trial date Further delays impact on util to customers
 WYATT.J House of Rep. 80/07/10 2pp
- V Operator Examinations
- 9007070387 Forwards licensed operator training lessons for fluid flow heat transfer 2 thermodynamics, in response to NRC 800328

 Itr Training re mitigation of severe coro damage por Inst for Nuclear Power Operations guidelines uill be developed OARY.R J Texas Utilities Generating Co 80/08/11 184pp

DOCKET 50-452 GREENWOOD ENERGY CENTER, UNIT 2

- Q Adjudicatory correspondence
- 8009110603 Notifies of ASLB order granting 800709 request for withdrawal & honoring request to withhold documents per 10CFR2 790 CHR16TEKBURY,E | Hoarings Division 80/07/34 lp

DOCKET 50-453 GREENWOOD ENERGY CENTER, UNIT 3

- Q Adjudicatory correspondence
- 8007ii0603 Notifles of ASLB order granting 800709 request for withdrawal & honoring request to withhold documents per iOCFR2 790 CHRISTERMURY,E Hoarings Division 80/07/31 to

DOCKET 50-454 BYRON STATION, UNIT 1

- A Application/construction stage documents & correspondence
- B009050032 Discusses void formation in vessel head during B006() natural circulation cooldown event Requests epinion repotential for voiding phenomenon in Westinghouse designed NSSS CHECK,P & Assistant Director for Plant Systems 80/07/28 2pp
- B0070B00B0 Forwards draft NUREG-0694, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl N/o NUREG EISERNHUT, D @ Division of Licensing 80/08/01 117pp
- B009i10327 Discusses review of pressurtration analyses for pressurtrar subcompartment Review should be focused on assuring that restricted vols do not result in unacceptably high local pressures MOON, C W Licensing Branch 1 80/09/03 ip
- 8009300455 forwards drawing of block diagram on turbine trip protection in response to NRC request for addl FBAR info NAUGHTON W F Commonwealth Edison Co 80/09/24 1p
- .—8009300465 "Block Diagram Turbine Cenerator Emergency Fluid Trip Bys "

 → Sargent & Lundy, Inc 4391 80/07/28 ig
- F Security, medical, emergency & fire protection plans
- 8009120091 Forwards emergency planning info for placement in local PDR W/o encl SOUDER, J L Library Brench 80/08/28 1p

- 8009120094 Forwards emergency planning info for placement in local PDR SOUDER, J L Library Branch 80/08/28 ip
- 8009120446 Forwards preliminary evacuation time studies of 10-mile radius emergency planning rome in response to NRC 800702 ltr Studies have been submitted for review to state & local officials No significant comments resulted
 DELGEORGE.L. O Commonwealth Edison Co 80/08/29 43pp
- B009110187 Advises of acceptance of safeguards contingency plan submitted by 890324 ltr YOUNGSLOOD,B J Licensing Branch 1 80/09/02 2pp
- a Inspection reports, 18 Bulletins & correspondence
- 8009110307 Forwards JE Inso Repts 50-454/80-12 % 50-455/80-11 on 800517-19 & notice of violation
 FIORELLIG Region G. Chicago, Reactor Construction & Engineering
 Support Branch 80/07/10 2pp
- --80091103i3 Notice of violation from insp on 800617-19
 4 Region 3, Chicago, Reactor Construction & Engineering Support
 Branch 80/07/09 2pp
- --8009110324 IE Insp Repts 50-454/80-12 & 50-455/80-11 on 800617-19
 Noncompliance noted improper design of component cooling
 water pipes presents possibility of accident rendering
 emergency diesel generators in & 18 insperable
 HAYES.D W Region 3. Chicago. Reactor Construction & Engineering
 Support Branch NAIDUK R. SCHAPKER.J F Region 3. Chicago.
 Office of the Director 80/07/09 iOpp
- B009020109 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " SA-312 pipe not present in operating plants Final confilmation from suppliers anticipated by 800915 re const plant piping sys NAUOHTON.W F Communwealth Edison Co 80/08/07 2pp
- 8007030231 Forwards Revision I to IE Bulletin 80-17, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E " Unitten response required KEPPLER.J C Region 3. Chicago. Office of the Director 80/08/15
- 8009110545 Responds to IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds," supplementing 800709 response Corrects Zion response re rings used for field circumferential butt weld Reviews accuracy of other Statements ABEL.US Commonwealth Edison Co 80/08/15 4pp
- 8009110665 Forwards IE Insp Repts 50-454/80-13,50-455/80-12, 50-456/80-07 % 50-457/80-07 on 800722 % 24-25 No noncompliance noted
 FIORELLI.O Region 3. Chicago, Reactor Construction & Engineering
 Support Branch 80/08/15 2pp
 - -8007110675 IE Insp Repts 50-454/80-13, 50-455/80-12, 50-456/80-07 & 50-457/80-07 on 800722 & 24-25 No noncompliance noted Major areas inspected licensee actions re control of IE bulletins & circulars & mgt meeting NAIDU.K R Region 2. Atlanta, Office of the Director KONKLIM.J E. JONES.C E Region 3. Chicago, Office of the Director 80/08/14 9pp
- 8009160081 Submits supplementary response to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds." correcting statement made in DL Peoples 800709 ltr Further review not necessary ABEL.J S Commonwealth Edison Co. 80/08/15 App
- 8007290188 Forwards IE Insp Repts 50-454/80-14 & 50-455/80-13 on 800729-27 No noncompliance noted FIGRELLI, Q Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/08/19 Epp
- -8009270193 1E Insp Repts 50-454/80-14 & 50-455/80-13 on 800728-29 No overvirid it insp kepts 30-49740-14 & 30-49576-13 on 900728-29 ke noncompliance noted Major areas inspected setting & alignment of reactor pressure vessel & Unit 1 cavity liner & installation of in-core flux tubes WILLIAKB, C c . JONES, C E . ERB, C M Region 3, Chicago, Office of the Director 80/08/18 App
- 800918055: Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response XEPPLER, J G Region 3, Chicago, Office of the Director 80/08/22

- 8009230094 Forwards IE info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-600S & K-DDN 6008 Circuit Breakers " No written response required Region 3. Chicago, Office of the Director 80/08/28 KEPPLER, J G
- B009180466 Rosponds to IE Bulletin B0-19 re failures of mercury-wetted matrix relays in reactor protective sys Identified relays are not used in facility No action required Twenty-four manhours expended on review RAUSCH, T J Commonwealth Edison Co 80/08/29 1p
- 8009190007 Responds to IE Bulletin 80-16 re potential misapplication of Rosemount pressure transmitters Identified transmitters are not used in Byron & Braidwood safety-related areas LaBaile will comply w/requirements by defining mads by 801001 RAUSCH.T J Commonwealth Edison Co 80/08/29 2pp
- 9009250468 Supplemental response to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies " Deficient springs in actuators w/ Masoneillan valves for safety-related applications will be replaced prior to shipment to site RAUSCH,T J Commonwealth Edison Co 80/08/29 3pp
- 8009240133 Forwards IE Circular 80-21, "Regulation of Refueling Creus" No written response required
 KEPPLER, J G Region 3. Chicago, Office of the Director 80/09/10
- 8009300200 Forwards response to 16 Bulletin 80-20 No Westinghouse Type W-2 control switches are used in safety-related sys at Dresden, Guad Cities & LaSalle County Responses for Zion & Dyron are encl RAUSCH. T J C Commonwealth Edison Co 80/09/15 600
- 8009300215 Responds to 800812 ltr re noncompliance noted in 1E Insp Repts 50-454/80-12 & 50-455/80-11 on 800617-17 NRC position unchanged Response re present & future corrective steps & date of full compliance, must be submitted within 30 days KEPPLER. J G Region 3. Chicago, Office of the Director 80/09/16 80/09/16

V Operator Examinations

8009300287 Forwards preliminary topical outlines of proposed modules on thermal hydraulics & core damage mitigation to be included in revised reactor operator training program per 80032B' request NAUGHTON, W F Commonwealth Edison Co 80/09/15 7pp

DOCKET 50-455 BYRON STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8007050032 Discusses void formation in vessel head during 800611 natural circulation cooldown event Requests opinion reputential for voiding phenomenon in Westinghouse designed CHECK, P 8 Assistant Director for Plant Systems 80/07/28 2pp.
- 8009080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0695 encl W/o NUREG EISENHUT, D C Division of Licensing 80/08/01 119pp
- 8009110327 Discusses review of pressurization analyses for pressurizer subcompariment Review should be focused on assuring that restricted vols do not result in unacceptably high local pressures. MODN,C W Licensing Branch 1 60/09/03 ip
- 8009300455 Forwards drawing of block diagram on turbine trip protection in response to NRC request for addl FSAR Info NAUONTION U F Commonwealth Edison Co 80/09/24 ip
- --8009300465 "Block Diagram Turbing Generator Emergency Fluid Trip Sys "
 Sargent & Lundy, Inc. 4391 80/07/28 1p
- F Security, medical, emergency & fire protection plans
- BOO9120091 Forwards emergency planning info for placement in local PDR SOUDER, J. L. Library Branch 60/08/28 ip
- BOD9120094 Forwards emergency planning info for placement in local PDR W/o encl SOUDER, J L Library Branch 80/08/28 ip

- 8009120446 Forwards preliminary evacuation time studies of 10-mile radius emergency planning jone, in response to NRC 800702 ltr Studies have been submitted for review to state % local officials No significant comments resulted DELOEORGE, LO Commonwealth Edison Co 80/08/29 43pp
- 8009110187 Advises of acceptance of safeguards contingency plan submitted by 800324 ltr YOUW09100D.B J Licensing Branch 1 80/09/02 2pp
- @ Inspection reports: IE Bulletins & correspondence
- 8009110307 Forwards IE lnsp Repts 50-454/80-12 & 50-455/80-11 on 800617-19 & notice of violation FIORELLE, O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/07/10 2pp
- --8009110313 Notice of violation from insp on 600617-19
 * Region 3. Chicago, Reactor Construction & Engineering Support
 Branch 80/07/09 2pp
- --B009110324 IE Insp Repts 50-454/80-12 & 50-455/80-11 on 8006i7-i9
 Noncompliance noted improper design of component cooling
 water pipes presents possibility of accident rendering
 smergency dissel generators 1A & IB inoperable
 HAYES.D W Region 3. Chicago. Reactor Construction & Engineering
 Support Branch NAIDU, K R . SCHAPKER.J F Region 3. Chicago.
 Office of the Director 80/07/09 iOpp
- 8009020109 Responds to 1E Bulletin 79-03A. "Longitudinal Weld Defects In ASME SA-312. Type 304 Stainless Steel Pipe " SA-312 pipe not present in operating plants Final confirmation from suppliers anticipated by 800915 re const plant piping sys NAUOHTON, W F Commonwealth Edison Co 80/08/07 2pp
- 8009030231 Forwards Revision 1 to 1E Bulletin 80-19. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER.J O Region 3. Chicago. Office of the Director 80/08/15
- 8009110545 Responds to IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds," supplementing 800709 response Corrects Zion response re rings used for field circumferential butt weld Reviews Actoracy of other statements ABEL.J S Commonwealth Edison Co 80/08/15 App
- 8009(10665 Forwards IE Insp Repts 50-454/80-43,50-455/80-12, 50-456/80-07 & 50-457/80-07 on 600722 & 24-25 No noncompliance noted FIORELI,O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/15 2pp
- --8009110675 IE Insp Repts 50-454/80-13,50-455/80-12,50-456/80-07 & 50-457/80-07 on 800722 & 24-25 No noncompliance noted Major areas inspected licenses actions re control of IE bulletins & circulars & mpt meeting NAIDU.K R Region 2, Atlanta, Office of the Director KONKLIN.JE, JUNES.C E Region 3, Chicago, Office of the Director 80/08/14 9pp
- ECO9160/81 Submits supplementary response to IE Bulletin 60-08, "Examination of Containment Liner Penetration Welds," correcting statement made in DL Peoples 800709 ltr Further review not necessary ABEL. J S Communuealth Edison Co 80/08/15 4pp
- 800729018B Forwards 1E Insp Repts 50-454/80-14 & 50-455/80-13 on 800728-29 No noncomptiance noted FIGRELLI, O Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/08/19 2pp
- --8009290193 IE Insp Repts 50-454/80-14 & 50-455/80-13 on 800728-29 No noncompliance noted Major areas inspected setting & alignment of reactor pressure vessel & Unit 1 cavity liner & installation of in-core flux tubes WILLIAMS, C C , JUNES, C E , ERB, C, M Region 3, Chicago, Office of the Director 80/08/i8 App
- E0091E0551 Forwards IE Circular 80-18, *10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys * No written response required KEPPLER.J O Region 3, Chicago, Office of the Director 80/08/22
- 8009230094 Forwards 1E Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-400S & K-DDN 400S Circuit Breakers " Na written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/28

- 8009180466 Responds to 1E Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys identified relays are not used in facility No action required Twenty-four manhours expended on review RAUSCH.7 J Commonwealth Edison Co 80/08/29 1p
- 8009196007 Responds to JE Sulletin 80-16 re potential misapplication of Rosemount pressure transmitters Identified transmitters are not used in Syron 8 Braidwood safety-related areas La83ile will comply w/requirements by defining mods by 801001 RAUSCH.T J Commonwealth Edison Co 80/08/29 2pp
- 800929046B Supplemental response to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies" Deficient springs in actuators of Masoneilian valves for safety-related applications will be replaced prior to shipment to site RAUSCH.T J Commonwealth Edison Co 80/08/29 3pp
- 8009240133 Forwards IE Circular 80-2; "Regulation of Refueling Crews" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 60/09/10 to
- 8009300200 Forwards response to 1E Bulletin 80-20 No Westinghouse Type N-2 control switches are used in safety-related sys at Dresden, duad Cities & LaSalle County Responses for Zion & Byron are encl RAUSCH.T J Commonwealth Edison Co 80/09/15 App
- 8009300215 Responds to 800812 itr re noncompliance noted in 1E insp. Repts 50-454/80-12 & 50-455/80-11 on 800617-19 NRC position unchanged Response re present & future corrective steps & date of full compliance.must be submitted within 30 days KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/16
- V Operator Examinations
- B009300287 Forwards preliminary topical outlines of proposed modules on thermal hydraulics & core damage mitigation to be included in revised reactor operator training program per B00328 request NAUGHTON, W F Commonwealth Edison Co 80/09/15 7pp
- DOCKET 90-456 BRAIDWOOD STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8009050032 Discusses void formation in vessel head during 800411 natural circulation cooldown event Requests opinion repatential for voiding phenomenon in Westinghouse designed NSSS CHECK, PS Assistant Director for Plant Systems 80/07/28 2pp
- 8009080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 ent N/o NUREG EISENHUT.D G Division of Licensing 90/08/01 119pp
- BOO9110327 Discusses review of pressurilation analyses for pressurizer subcompartment Review should be focused on assuring that restricted vols do not result in unacceptably high local pressures
 MOGN.C W Licensing Branch (BD/09/03 Sp
- 8009300455 Forwards drawing of block diagram on turbine trip protection in response to NRC request for addl FBAR info NAUOHTON W F Commonwealth Edison Co 80/09/24 1p
- --8009300465 "Block Diagram Turbine Genorator Emergency Fluid Trip Sys "
 # Sargent & Lundy, Inc 4391 80/07/28 ip
- F Security, medical, emergency & fire protection plans
- B009;20446 Forwards preliminary evacuation time studies of 10-mile radius emergency planning tone in response to MRC 800702 itr Studies have been submitted for review to state & local officials No significant comments resulted DELGEORGE, L O Commonwealth Edison Co 80/08/29 43pp
- 8009110397 Advises of acceptance of safeguards contingency plan submitted by 800324 ltr YDNOBLOOD, B J Licensing Branch 1 80/09/02 2pp

G Inspection reports, IE Bulletins & correspondence

- 8009170217 Forwards IE insp Repts 50-456/80-06 & 50-457/80-06 on 800709-10 No noncompliance noted FIGRELLI. Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/07/28 2pp
- --8009170221 IE insp Repts 50-455/80-05 % 50-457/80-06 on 800709-10
 No noncompliance noted Major areas inspected review action
 taken on previous insp findings, electrical contractor
 procedures % storage of electrical equipment
 MAIDULA R. SCHAPAER. J. Region 3. Chicago. Office of the Director
 HAYES, D.W. Region 3. Chicago. Reactor Construction & Engineering
 Support Branch 80/07/24 5pp
- 8007020109 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312 Type 304 Stainless Steel Pipe " SA-312 pipe not present in operating plants Final contribution from suppliers anticipated by 800915 re const plant piping sys NAUGHTQU.N F Commonwealth Edison Co 80/08/07 2pp
- 8009030231 Forwards Revision 1 to IE Bulletin BO-19, "Failures of Mercury-Hetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Hritten response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/15
- 8009110545 Responds to JE Bulletin 80-08, "Exam of Containment Liner Penetration Welds," supplementing 800709 response Corrects Zion response je rings used for field circumferential butt weld Reviews accuracy of other statements ABEL.JS Commonwealth Edison Co 80/08/15 App
- 8009110665 Forwards IE Insp Repts 50-494/80-13.50-455/80-12. 50-456/80-07 & 50-457/80-07 on 600722 & 24-25 No noncompliance noted FIDRELLI-9 Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/06/15 2pp
- --8009110675 IE Insp Repts 50-454/80-13.50-455/80-12.50-456/80-07 & 50-457/80-07 on 800722 & 24-25 No noncompliance noted Major areas inspected licensee actions re control of IE bulletins & circulars & mpt meeting MAIDU, K R. Region 2. Atlanta, Office of the Director KOMALIN. J E. JONES, C E. Region 3. Chicago. Office of the Director 80/08/14 9pp
- 8009160681 Submits supplementary response to IE Bulletin BO-OB, "Examination of Containment Liner Penetration Welds," correcting statement made in DL Peoples 800709 itr Further review not necessary ABEL.J S Commonwealth Edison Co 80/08/15 App
- 1009180551 Forwards IE Carcular 80-18, "100FR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER.J G Region 3, Chicago. Office of the Director 80/08/22
- 009230094 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DDN 6008 Circuit Breakers"

 No written response required

 KEPPLER. J G Region 3, Chicago. Office of the Director 80/08/28
- :009180466 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Identified relays are not used in facility No action required Twenty-four manhours expanded on review RAUSCH.T J Commonwealth Edison Co 80/08/29 tp
- >009190007 Responds to IE Bulletin 80-16 re potential misapplication of Rosemount pressure transmitters Identified transmitters are not used in Byron & Braidwood safety-related areas LaBalle will comply wirequirements by defining mods by 801001 RAUSCH.T J Commonwealth Edison Co 80/08/29 2pp
- 100925046B Supplemental response to IE Dulletin 80-09. "Mydramotor Actuator Deficiencies " Deficient springs in actuators w/ Masoneriien valves for safety-related applications will be replaced prior to shipment to site RAUSCH.T J Commonwealth Edison Co 80/08/29 3pp
- 009240133 Forwards IE Circular 80-21, 'Regulation of Refueling Crows " No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/09/10 in

- 8009300200 Forwards response to 1E Bulletin 60-20 No Westinghouse Type W-2 control switches are used in safety-related sys at Dresden. Guad Cities & LaSalle County Responses for Zion & Byron are enci RAUSCHIT J Commonwealth Edison Co 60/09/15 6pp
- V Operator Examinations
- 8009300287 Forwards preliminary topical outlines of proposed modules on theimal hydraulics >> core damage mitigation to be included in revised reactor operator training program per 800328 request NAVCHTCH.N F Commonwealth Edison Co 80/09/15 7pp
- DOCKET 50-457 DRAIDWOOD STATION: UNIT 2
- A Application/construction stage documents & correspondence
- 8009050032 Discusses void formation in vessel head during 800611 natural circulation cooldown event Requests opinion repotential for voiding phenomenan in Westinghouse designed NSSS CHECK.PS Assistant Director for Plant Systems 80/07/28 2pp.
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT
- 8009110327 Discusses review of pressurization analyses for pressurizar subcompartment Review should be focused on assuring that restricted vols do not result in unacceptably high local pressures MOON, C II Licensing Branch 1 80/09/03 ip
- 8009300455 Forwards drawing of block diagram on turbine trip protection, in response to NRC request for addl FSAR info NAUOHTQN,W F Commonwealth Edison Co 80/09/24 ip
- --8009300465 "Bluck Diagram Turbine Generator Emergancy Fluid Trip Bys" * Sargent & Lundy, inc 4683 80/07/28 ip
- F Security, medical, emergency & fire protection plans
- E009120446 Forwards preliminary evacuation time studies of 10-mile radius emergency planning zone, in response to NRC 800702 Itr Studies have been submitted for review to state & local officials No significant comments resulted DELGEORGE, L.O. Commonwealth Edison Co. 80/08/29 43pp
- B009110397 Advises of acceptance of safeguards contingency plan submitted by 800324 ltr YUUNGBLOOD, B J Licensing Branch 1 80/09/02 2pp
- Q inspection reports, IE Bullatins & correspondence
- 8007170217 Forwards IE insp Repts 50-456/80-06 & 50-457/80-06 on 800709-10 No noncompliance noted fibreLt.1.0 Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/07/28 2pp
- --8007170221 IE Insp Repts 50-456/80-06 & 50-457/80-06 on 800709-10
 No noncompliance noted Major areas inspected review action
 taken on previous Insp findings, electrical contractor
 procedures & storage of electrical equipment
 MAIDU.K R. SCHAPKER.J Region 3. Chicago. Office of the Director
 HAYEB.D W Region 3. Chicago. Reactor Construction & Engineering
 Eupport Branch 80/07/24 Spp
- 8007020109 Responds to IE Builetin 79-03A. "Longitudinal Weld Defects in ASKE SA-312, Type 304 Stainless Steal Pipe " SA-312 pipe not present in operating plants Final confirmation from suppliers anticipated by 800915 re const plant piping sys NAUGHTON, W F Commonweelth Edison Co 80/08/07 2pp
- BO07030231 Forwards Revision 1 to IE Builetin BO-19. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Unitten response required KEPPLER, J 9 Region 3, Chicago, Office of the Director BO/OS/15
- BOO9110545 Responds to 1E Bulletin 80-08. "Exam of Containment Liner Penetration Welds," supplementing 800709 response Corrects Zion response re rings used for field circumferential butt wold Reviews accuracy of other statements ABEL, J S Commonwealth Edison Co 80/08/15 App

- 8009110665 Forwards lE Insp Repts 50-494/80-13,50-455/80-12, 30-456/80-07 & 50-457/80-07 on 800722 & 24-25 No noncompliance noted FIGRELLIG Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/15 Zpp
- 8009160681 Submits supplementary response to IE Bulletin 80-08, "Eramination of Containment Liner Penetration Welds." correcting statement made in DL Peoples 800709 Itr Further review not necessary ABELJ 6 Commonwealth Edison Co 80/08/15 4pp
- BOO9180551 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/08/22
- 8009230094 Forwards IE Info Notice 80~31, "Maloperation of Gould-Drown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/08/28 18
- BO091B0466 Responds to IE Builetin 80-19 re failures of nercury-wetted matrix relays in reactor protective sys Identified relays are not used in facility No action required Twenty-four manhaurs expended on review RAUSCH, T J Commonwealth Edison Co 80/08/29 ip
- BOOP170007 Responds to IE Builetin BO-i6 re potential misapplication of Rosmount pressure transmitters Identified transmitters are not used in Byron & Braidwood safety-related areas LaSalle will comply w/requirements by defining mods by B01001 RAUSCH.T J Commonwealth Edison Co B0/08/29 2pp
- 8009250448 Supplemental response to IE Builetin 80-09. "Hydramotor Actuator Deficiencies " Deficient springs in actuators w/ Mayoneilian vaives for safety-related applications will be replaced prior to shipmont to site RAUSCH.T J Commonwealth Edison Co 80/08/29 3pp
- 8007240133 Forwards IC Circular 80-21, "Regulation of Refueling Crows "
 No written response required
 MEPPLER, J G Region 3, Chicago, Office of the Oirector 80/09/10
 ip
- BOO7300200 Forwards response to IE Builetin 80-20 No Westinghouso Type W-2 control switches are used in safety-related sys at Dresden, Quad Cities & LaSalie County Responses for Zion & Byron are encl RAUSCH, T J Commonwealth Edison Co 80/09/15 App

V Operator Examinations

- BOO9300287 Forwards preiiminary topical outlines of proposed modules on thermal hydraulics & core damage mitigation to be included in revised reactor operator training program per 800328 request NAUCHTON.W F Commonwealth Edison Co 80/09/15 7pp
- DOCKET 50-458 RIVER BEND STATION, UNIT 1
- A Application/construction stage documents & correspondence
- BOOTOBOOBO Forwards draft NUREG-0676, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days. Proposed impirementation schedule for meeting criteria of NUREG-0676 encl W/o NUREQ EISENSUT. D © Division of Licensing 80/08/01 119pp
- 8009120113 Forwards 800811 memorandum of agreement w/Advisory Council on Historic Preservation for proposed transmission line & expanded corridor Acknowledgement of agreement & certification of acceptance encl
 TEDESCORR L Division of Licensing 80/08/21 3pp
- 8009090409 Confirms telcon w/M Karlowicz re 791026 application to amend CPPR-145 Cajun Electric Power Cooperative share of const costs, nuclear fuel b transmission lines will be financed through Rural Electrification Administration DRAPER.E L Oulf States Utilities Co 80/08/28 ip

- 800930020 Advises that issue or continuation of transmission line activities through Port Hudson nat! historic landmark has been concluded to NRC satisfaction Commitments contained in BOOG21 ltr satisfactory MIRAGL!A.F J Licensing Branch 3 80/09/16 2pp
- F Security, medical, emergency & fire protection plans
- 8009020134 Invites participation in 800822 workshop in Atlanta, GA to solicit comment to proposed functional criteria for emergency response facilities in NUREG-0696 Discussion to include location.size 5 staffing or emergency ctrs SEYFRIT.X V Region 4, Ballas, Office of the Director 80/08/12
- 8009090532 Forwards "Evacuation Time Estimates for 10-Mile Emergency Planning Zone," in response to 800702 ltr DRAPER.E L Gulf States Utilities Co 80/09/27 ip
- --8009090537 "Evacuation Time Estimates for 10-Kile Emergency Planning Zone " Approved by State of LA atticials * Commonwealth Edison Co BOBLINGER, L H , BORDAN, A J Louisiana. State of 80/08/29 36pp

G Adjudicatory correspondence

- 8009170410 Ack receipt of 800721 petition under 10CFR2 206 for halt to const of facilities based on allegations of questionable const practices Denies request for immediate action since public health & safety as not affected STELLO.V Office of Inspection & Enforcement, Office of the Director 80/08/18 2pp
- --8097170414 Ack receipt of B00721 petition under 10CFR2 206 for halt to const of facilities based on allegations of questionable const practices Demies request for immediate action since public heaith t safety is not affected Forwards FR notice STELLOV Office of Inspection & Enforcement, Office of the Director 80/08/18 2pp
- ---B009170417 Notice of UCS 800721 request for action under 10CFR2 206 DEYDUNG,R C , STELLO,V Office of Inspection & Enforcement, Office of the Director 80/08/18 1p
- 8009090406 Order granting extension until 800922 for Commission to elect whether to review Director's 800816 decision under IOCFR2 206 not to suspend CP CHILK.8 J Office of the Secretary of the Commission 80/09/05 ip
- 8009290039 Order granting extension until 800929 for Commission to elect whether to review Director's 800818 decision not to suspend const of Facility under 10CFR2 206 CHILK.S J. Office of the Secretary of the Commission
- 9 Inspection reports, IE Buileting & correspondence
- 8009040511 Forwards IE Bulletin 80-07, "BUR Jet Pump Assembly Failure "No response required
 SEYFRIT.K V Region 4, Dallas, Office of the Director 80/04/04
 ia
- 8007090039 Forwards IE Bulletin 80-07, Suppl 1, "BIR Jot Pump Assembly Failure" No response required SEYFRIT, X V Region 4, Dallas, Office of the Director 80/00/13 to
- 9009020934 Forwards Suppl 2 to IE Bulletin 80-17. "Failures Revoaled by Testing Subsequent to Failure of Control Rods to Insert During Scram at BWR "No written response required SCYRIT.X V Region 4. Dailas. Office of the Director 80/07/22
- 8009150340 Forwards IE Insp Rept 50-459/80-06 on 800609-10,24-27 % 30 0703 notice of violation 3 notice of deviation SEIDLE, & C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/07/28 2pp
- ---B009150352 Natice of violation from insp on B00609-10,24-27 & 30 & 0703
 * Region 4, Dallas, Reactor Construction & Engineering Support Branch 60/07/25 2pp
- --8009150353 Notice of deviation from Insp on 800609-10,24-27 & 30 & 0703 4 Region 4. Dailas, Reactor Construction & Engineering Support Branch 80/07/25 (a

- --8009150357 IE Insp Rept 50-458/80-06 on 800607-10,24-27 & 30 & 0703
 Noncompliance noted failure to follow procedures for
 identification of training needs 1 use of air entrainment
 admisture in Category 1 concrete
 BEACH.A B. OllBERT,L D. IDALINSON,D P. Region 4, Dallas, Reactor
 Construction & Engineering Support Branch 80/07/25 lipp
- 8009250390 Forwards IE Jnsp Rept 50~458/80-07 on 800715~18 & notices of violation & deviation SEIDLE.N C Region 4. Dallas. Reactor Construction & Engineering Support Branch 60/08/11 2pp
- ~-8009250393 Notice of violation from insp on 600715~18 → Region 4. Dallas, Office of the Director 80/08/08 2pp
- --8009250375 Notice of deviation from insp on 800715-18 * Region 4. Dailas, Office of the Director 80/08/08 299
- --8007250398 IE Insp Rept 50-458/80-07 on 800715-18 Noncompliance noted railure to follow procedural requirements for good housekeeping & inappropriate accept/reject criteria for total air content in exterior uali placement HALL.R E Region 4. Dallas. Reactor Construction & Engineering Support Branch CROSSMAN, M 4. BEACH.A 3 Region 4. Dallas. Office of the Director 80/08/08 Epp
- 8009030271 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Marcury-Welted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required SEY+RIT,K V Region 4, Dallas, Office of the Director 80/08/15 to
- 8009050517 Ack receipt of 800729 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-458/80-09 Addi info requested &EIOLE.W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/08/85 2pp
- -8009050522 Responds to NRC 800710 itr re viciations noted in IE Insp Rept 50-458/80-05 Corrective actions GC Instruction FRI-D2 5 -010 revised & NPD 9400 superseded by NPD 9701 Air fry unit weight tests to be completed by SNA by 800901 DRAPER.E L Ouif States Utilities Co 60/07/29 lOpp
- 9150338 Forwards IE Insp Rept 50-459/80-08 on 800730-31 No oncompliance noted EIDLE,N C Region 4. Dallas, Reactor Construction & Engineering apport Branch 60/08/19 2pp
- BCO91503±2 IE Insp Rept 50-458/80-OB on BCO730-31 No noncompliance noted Major areas inspected licensee investigation of concerns expressed in UCS BCO721 Itr to NRC BEACH.A D. GBERG.C R. Region 4. Dallas, Defice of the Director HALL.R E. Region 4. Dallas, Reactor Construction & Engineering Support Dranch BC/C8/18 App.
- B009160032 Forwards IE info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Stram Function & Monessential Control Air at Certain OE 3WR Facilities "No specific action or response requested SEYFRIT.X V Region 4, Dallas, Office of the Director 80/08/19 fp
- 3009120025 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BUR' No written response required SEYFRIT.K V Region 4. Daltas. Office of the Director 80/08/22
- 1009170372 Forwards IE Circular 80-18, "IOCFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required SEY-RIT.K V Region 4, Dallas, Office of the Director 80/08/22 IP
- OO9250412 Ack receipt of IE Insp Rept 50-458/80-03 on 800819 No proprietary into DRAPER.E L. Ouif States Utilities Co. 80/08/22 1p
- 1009120422 Forwards IE Into Notice 80-31. "Matoperation of Oould-Brown Boveri 480 Volt Type K-6005 & K-DDN 6005 Circuit Breakers " No written response required SEX-RII.K V Region 4. Dallas. Office of the Director 80/08/27
- 009300084 Submits response to IE Bulletin 80-16 No Rosemount Model 1151 or 1!52 pressure transmitters are to be used in safety-related applications DRAPER.E L Gulf States Utilities Co GO/09/05 2pp

- 8009290325 Ack receipt of 800805 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-458/78-04 & 50-459/78-04 SEIDLE.W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/09/10 ip
- --8009270326 Forwards third annual status rept of progress of environ studies of effect of Aliigator Bay Culver crossing in response to Request 3 of IE Insp Repts 50-458/78-04 & 50-459/78-04
 DRAPER.E L Gulf States Utilities Co 80/08/05 3pp
- DQ.KET 50~459 RIVER BEND STATION, UNIT 2

 A Application/construction stage documents & correspondence
- BOO9080080 Forwards draft NUREO-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 entl W/O NUREG EISENHUT, D @ Division of Licensing 80/08/01 119pp
- 8009120113 Forwards 800811 memorandum of agreement w/Advisory Council on Historic Preservation for proposed transmission line & expanded corridor Acknowledgement of agreement & certification of acceptance and TEDFSCO.R L Division of Licensing 80/08/21 3pp
- 8009300220 Advises that issue of continuation of transmission line activities through Port Hudson natl historic landmark has been concluded to NRC satisfaction Commitments contained in 800821 ltr satisfactory firAdCLIA: J Licensing Branch 3 80/09/16 2pp
- F Security, medical, emergency & fire protection plans
- 8009020134 Invites participation in 800822 workshop in Atlanta, GA to solicit comment re proposed functional criteria for emergency response facilities in NUREG-0.696 Discussion to include location, size to staffing of emergency ctrs SEYFRIT.K V Region 4. Dallas, Office of the Director 80/08/12
- 8009090532 Forwards "Evacuation Time Estimates for 10-Mile Emergency Planning Zone." in response to 800702 ltr DRAPER.E L Gulf States Utilities Co 80/08/27 1p
- --B009090537 "Evacuation Time Estimates for 10-Mile Emergency Planning Zone " Approved by State of LA officials * Componwealth Edison Co BOBLINGER,L H , BORDAN,A J Louisians, State of B0/08/29 36pp
- G Adjudicatory correspondence
- 8009170410 Att receipt of 800721 petition under 10CFR2 206 for halt to const of facilities based on allegations of questionable const practices Denies request for immediate action since public health & safety is not affected STELLO.V Office of Inspection & Enforcement, Office of the Director 80/08/18 2pp
- --8009170414 Act receipt of 800721 petition under 10CFR2 206 for halt to const of facilities based on allegations of questionable const practices Denies request for immediate action since public health & safety is not affected Forwards FR notice STELLO,V Office of Inspection & Enforcement, Office of the Director 80/08/18 2pp
- --8009170417 Notice of UCS 800721 request for action under 10CFR2 204 DEYOUNG:R C . STELLO, V Office of Inspection & Enforcement, Office of the Director 80/08/18 1p
- B009090406 Order granting extension until 800922 for Commission to elect whether to review Director's 800818 decision under 10CFR2 206 not to suspend CP CHILK.S J Office of the Secretary of the Commission 80/09/05
- 8009250039 Order granting extension until 800929 for Commission to elect whether to review Director's 800818 decision not to suspend const of facility under 10CFR2 206 CHILK.S J Office of the Secretary of the Commission 80/09/22

Q Inspection reports, IE Bulletins & correspondence

- 8009040511 Forwards IE Builetin 80-07. "BWR Jet Pump Assembly Failure " No response required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/04/04 10
- 8009090039 Forwards IE Bulletin 80-07. Suppl i, "BWR Jet Pump Assembly Failure " No response required SEYFRIT.K V Region 4. Dallas, Orfice of the Director BO/05/13
- E007070534 Forwards Suppi 2 to IE Duiletin 80-17, "Failures Revealed by Testing Subsequent to Failure of Control Rads to Insert During Scram at BNR " No written response required SEYFRIT,K V Region 4, Dallas, Office of the Director B0/07/22
- BO09030271 Forwards Revision 1 to IE Builetin BO-19, "Failures of Mercury-Hetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required SEY-RIT,K V Region 4. Dalias. Office of the Director BO/08/15
- 6009i40032 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE BWR Facilities " No specific action or response requested SEYFRIT, X V Region 4, Dailas, Office of the Director BO/OB/19 in
- 8009120025 Forwards Suppi 3 to IE Builetin 80-17, "Failure of Control Rods to Insert During Scram at DWR " No written response required SEYFRIT, K V Region 4, Dailas, Office of the Director 80/08/22 fp
- 8009170392 Forwards IE Circuiar 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written responso required SEYFRIT,X V Region 4, Dallas, Office of the Director 80/08/22
- 8009120422 Forwards iE Info Notice 80-31, "Maioperation of Gould-Brown Baveri 480 Volt Type K-600S & K-DON 600S Circuit Breakers " No written response required GEYRNIT,K V Region 4. Dalias. Office of the Director 80/08/27
- 8009300086 Submits response to lE Bulietin 80-16 No Rosemount Model 1151 or 162 pressure transmitters are to be used in safety-related applications DRAPER.E. Culf States Utilities Co 80/09/05 2pp
- 9009290329 Ack receipt of 800805 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-458/78-04 & 50-459/78-04 SEIDLE:N C Region 4, Dailas, Reactor Construction & Engineering Support Branch 80/09/10 ip
- --8009270326 Forwards third annual status rept of progress of environ studies of effect of Alligator Bay Culver crossing in response to Request 3 of IE Insp Repts 50-458/78-04 & 50-459/78-04 DRAPER.E L Gulf States Utilities Co 80/08/05 3pp

DOCKET 50-460 WPPSS NUCLEAR PROJECT, UNIT 1

- A Application/construction stage documents & correspondence
- 8007080080 Forwards draft NUREQ-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREQ-0676 enci W/O NUREQ EISENHUT, D 0 Division of Licensing 80/08/01 117pp
- 8009120099 Recommands listed steps be taken to reduce risk from ATMB events during interim period before required mods Requires submission of ATMB emergency operating procedure, YEDESCO.R L Assistant Director for Licensing 80/08/27 Spp
- 8007070496 Forwards addl geologic info re time of latest movements of earth faults on Gable Mountain near ctr of reservation Mg conclusions re significance have been reached & info is not considered reportable under 10CFR21
 RENBERGER, D. L. Washington Public Power Supply System 80/09/02
 3pp

- F Security, medical, emergency & fire protection plans
- 8009030267 Notifies of 800819.22 \$ 30 regional workshops re development of guidance for acceptable method for coping w/emergencies at racility Requests that representative be sont Subj areas to be discussed include function of facilities & location ENGELKEN,R H Region 5. San Francisco. Orfice of the Director 80/08/12 2pp
- G Inspection reports, IE Bulletins & correspondence
- 8009160622 Responds to iE Bulletin 80-16. "Potential Misapplication of Rosemount, Inc Models 1151 & 1152 Pressure Transmitters w/ Either A or D Output Codes " No subj transmitters installed or planned to be installed in sarety-related sys RENBERGER, D L. Washington Public Power Supply System 80/09/07 ip
- 8009170393 Responds to IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe" No SA-312 or A-312 Type 304 fusion welded pipe in use or planned for use in safety-related sys at facilities
 RENBEROER, D. L. Mashington Public Power Supply System 80/08/07
- 8009260303 Forwards [E info Notice 80-27, "Broken Studs on Terry Turbine Steam Iniet Flange " No written response required "NOELKEN,R N Region 5, San Francisco, Office of the Director 80/09/07 1p
- 8009120304 Forwards IE lnsp Repts 50-460/80-08 & 50-513/80-08 on 800714-18 No noncompliance noted SPENGER.C S Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/08/12 2pp
- --8009120309 IE Insp Repts 50-460/80-08 % 50-513/80-08 on 800714-18 No noncompliance noted Major areas inspected RCPB piping insulation % incensee action on previous insp findings DODDS: R T Region 5, San Francisco, Reactor Construction & Engineering Support Branch HERNANDEZ, G , WAGNER, W J Region 5, San Francisco, Office of the Director 80/09/09 App
- 8009030292 Forwards Revision 1 to 18 Duiletin 80-19. "Failures of Mercury-Metted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Kritten response required ENGELKEN.R H Region 5, San Francisco. Office of the Director 80/08/15 ip
- 8009290302 Forwards IE info Notice 80-27 re degradation of reactor coolant pump studs ENBELKEN R1 Region 5, San Francisco. Office of the Director 80/08/18 4nn
- 8009110415 Ack receipt of 800725 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50~460/80~07 & 90~913/80~07

 SPENCER.0 S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/08/20 1p
- --B009110422 Responds to NRC B00626 ltr re violations noted in IE Insp Repts 50-460/B0-07 & 50-513/80-07 Corrective actions rework of support 174-3413-2910 completed Support 17-4-3404-300A rework not completed RENBERGER.D L. Washington Public Power Supply System B0/07/25 39p
- --8009110424 Forwards IE insp Repts 50-460/80-07 & 50-513/80-07 on 800401-30 & potice of violation SPENCER.O S Region S, Sam Francisco, Reactor Construction & Engineering Bupport Branch 80/06/26 2pp
- --B009110426 Notice of violation from insp on 800401-30 * Region 5, San Francisco, Office of the Director 80/06/25 1
- ---8009110429 IE Insp Repts 50-460/80-07 & 50-513/80-07 on 800401-30 Noncompliance noted deficiency in area of cable tray support wolding TOTH-R D Region 5. San Francisco. Office of the Director DODDS RT Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/05/25 12pp
- 8009160189 Forwards IE Circular 80-18 "10CFR90 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required ENGELMENTRY HE Region 5, San Francisco. Office of the Director 80090129

- 8009120468 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 % K-DON 6008 Carcuit Breakers " No written response required ENSELKBLAR H Region 5, San Francisco, Office of the Director 80/08/27 ip
- 8009120609 Ack receipt of 800819 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-460/80-10 & 50-513/80-10
- ~~8009120616 Forwards lE Insp Repts 50-460/80-10 & 50-513/80-10 on 800602-09 & notice of violation SPENCER, C S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/07/17 2pp
- ---8009120622 Notice of violation from insp on 800602-09
 4 Region 5, San Francisco, Office of the Director 80/07/16 1p
- -8039120631 IE Insp Repts 50-460/80-10 & 50-513/80-10 on 800602-09 Noncomptiance noted fillet welds on columns 22704 & 2283 Undersized contrary to contract specs TOTH.A D., DODS.R T Region 5, San Francisco, Office of the Director 80/07/16 5pp
- 8009300346 Updates 800124 response to IE Bulletin 79-02.Revision 2. "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Anchor bolt loads on existing designs will be recalculated by 810228 Related data enci.

 RENBERGER.D L Washington Public Power Supply System 80/09/25 7 o n
- DOCKET 50-461 CLINTON POWER STATION, UNIT 1
- Application/construction stage documents & correspondence
- 009083080 Forwards draft NUREG-0696, "Functional Criteria for DOPOBUSED Forwards draft NUKES-UAYA, "Functional Criteria ri Emergancy Response Facilities" Communts requested within? days Preposed implementation schedule for meoting criteria of NUREO-0696 encl W/o NUREO EISENHUT, D G Division of Licensing 80/08/01 119pp
- JOO9150494 Approves BOO218 request for exemption of certain containment spray & discharge piping from hydrostatic testing Request re Code Case N-241 must be rewritten to include only submerged portions of referenced sys SCHWENCER. A Licensing Branch 3 80/08/18 3pp
- 8009220130 Advises that recorculation dostharge block valve mods are complete Mod plan, procedures 2 related documents available at site for review Mork, authorized for OE, was subcontracted to Baldon Associates

 KOCH, L. J. Illinois Power Co. 80/08/19 ip
- 09180575 Advises of planned repairs to weld preps of Valve 1E22-F010 L Piping Spool I-HP-1-6 & body of Valve 1E-22-F010 Baldwin Associates authorited to perform work SPERGER. J S IIlinois Power to 60/08/20 Ip
- 1009040491 Forwards design info re Category 1 masonry walls, per NRC B00421 request Oversise drawings available in Central Files WULLER.G E Illinois Power Co 80/09/25 19pp
- 1009020341 Forwards 800807 ltr transmitting petition to amend Rule 203 (1) (10) (aa) of Chapter 3 of fL Pollution Control Board rules 6 regulations & supporting exhibits Ltr petition & exhibits available in Central Files only (WLLER, 0 E lilinois Power Co 80/08/27 ip
- 8007080193 Forwards Amend 3 to OL application, requesting authorization to operate for 40 yrs at power levels up to 2.894 MMt per unit FBAR environ rept, physical security plan & antitrust info encl KOCH,L J Illinois Pawer Co 80/08/29 2pp
- --8009080197 Amend 3 to application for OL Requests authorization to operate for 40 yrs at power levels up to 2,894 MHt per unit # Illinois Power Co 80/08/31 140pp
- 8009190115 Notifies of completed OL application review MRC safety review will be initiated Early response to encl request for additinfore FSAR & environ rept necessary to facilitate detailed technical review M/o encl
 EISENHUT, D G Division of Licensing 80/08/27 3pp

- 8009190754 Forwards request for addl info to complete technical review of 791201 OL application Forwards NUREO-0674, "TM1 Related Requirements for New OLs " W/o encl NUREO EISENHUT,D G Division of Licensing 80/08/29 52pp
- BOO9190513 Certifies that direct distribution has been made of licensing documents re acceptance review of Units 1 & 2 Certificates of Svc encl WULLER. G E Illinois Power Co 80/09/15 App
- C Utility Environmental Report (ER), amends & correspondence
- 8009080202 Forwards environ rept. Vols 1 & 2 Also forwards Amend 3 to OL application requesting authorization to operate for 40 yrs at power levels up to 2.894 NWH per unit.FSAR.physical security plan & antitrust info KOCH.L J Illinois Power Co 80/08/27 2pp
- ---8009080209 Environ rept for facility.Vol 1 * Illinois Power Co 80/08/29 7724pp
- --8007080211 Environ rept for facility, Vol 2 * Illinois Power Co 80/08/29 726pp
- F Security, medical, emorgoncy & fire protection plans
- BO09040445 Issues invitation to sond representatives to participate in regional workshop re emergency response facilities Workshop will facus on presenting & discussing criteria, receiving comments & answering questions KEPPLER.J G Region 3. Chicago, Office of the Director BO/OB/1
- H General correspondence
- 8009080347 Informs of reorganization re three technical depts out under single corporate officer Establishes OA at same reporting level as managers of facility operations & nuclear station engineering
 KOCH.L J Illinois Power Co 80/09/02 ip
- 8007270383 Responds to 1tr to President Carter re White House position on TMI accident Informs of re-examination of design & operation of nuclear power plants including emergency evacuation plans to cope w/potential accidents SCKWENCER.A Licensing Branch 3 80/09/09 ip
- K Utility Final Safety Analysis Report (FBAR) & amends
- 8009090254 Forwards Clinton Units 1 & 2 FSAR Includes Revisions 1-3 KCCH.L J Illinois Power Co 80/08/29 2pp
- ---B009090258 Clinton Units 1 & 2 FSAR Includes Revisions 1-3 # Illinois Power Co 80/08/29 7700pp
- 8009090262 Chapter 1 to Clinton Units 1 & 2 FBAR, "Introduction & General Description of Plant" Includes Revisions 1-3

 * Illinois Power Co 80/08/29 350pp
- 8009090246 Chapter 2 to Clinton Units 1 & 2 FSAR, "Site Characteristics " Includes Revisions 1-3 * Illinois Power Co 80/08/29 1190pp
- 8007090247 Chapter 3 to Clinton Units 1 & 2 FBAR, "Design of Structures.Components.Equipment & Sys " Includes Revisions
 - Illinois Power Co 80/08/29 1100pp
- 8007070272 Chapter 4 to Clinton Units 1 & 2 FSAR, "Reactor " Includes Revisions 1-3 * Illinois Power Co 80/08/29 32000
- 8009090276 Chapter 5 to Clinton Units 1 & 2 FSAR, "RCS & Connected Sys " Includes Revisions 1-3 # Illinois Power Co 80/08/29 250pp
- BO09090279 Chapter 6 to Clinton Units 1 & 2 FSAR, "Engineered Safety Features." Includes Revisions 1~3 # I.linols Power Co 80/08/29 550pp
- 8007070283 Chapter 7 to Clinton Units 1 & 2 FSAR, "Instrumentation & Control Sys" includes Revisions 1-3
 # Illinois Pawer Co 80/08/27 850pp

- 8009090286 Chapter 8 to Clinton Units | & 2 FSAR, "Electric Power" Includes Revisions 1-3 e Illinois Power Co 80/08/29 185pp
- 8009090289 Chapter 9 to Clinton Units 1 % 2 FSAR, "Awxiliary Sys " includes Revisions 1-3
 • Illinois Power Co 80/08/29 625pp
- 8009090293 Chapter 10 to Clinton Units 1 & 2 FSAR. "Steam & Power Conversion Sys " Includes Revisions i-3

 111inois Power Co 80/08/29 100pp
- 8009090296 Chapter ii to Clinton Units | & 2 FSAR. "Radwaste Hgt " Includes Revisions 1-3 Illinois Power Co 80/08/29 200pp
- 8009090299 Chapter 12 to Clinton Units i & 2 FSAR, "Rediation Protection " Includes Revisions 1-3 * Illinois Power Co 80/08/29 200pp
- 8009090301 Chapter 13 to Clinton Units 1 & 2 FSAR, "Conduct of Operations " Includes Revisions 1-3
 Illinois Power Ca 80/08/29 150pp
- 8009090304 Chapter 14 to Clinton Units i & 2 FSAR, "Initial Test Program" Includes Revisions 1-3 Illinois Power Co 80/08/29 150pp
- 8007070307 Chapter i5 to Clinton Units i & 2 FSAR, "Accident Analysis " Includes Revisions 1-3 * Illinois Pouer Ca 80/08/29 400pp
- E009090310 Chapter 16 to Ciinton Units i & 2 FSAR. "Tech Specs " Includes Revisions i-3 + Illinois Power Co 80/08/29 ip
- 8009090313 Chapter i7 to Clinton Units 1 & 2 FSAR, "OA " Includes Revisions i-3 + Illinois Power Co 80/08/29 50pp
- 8009090317 App A to Clinton Units 1 ν 2 FSAR, "Glossary " Includes Revisions 1-3 + 1111nois Power Co 60/08/29 igpp
- 8009090321 App B to Ciinton Units i & 2 FSAR. "Const Mat1 Stds & QC Procedures " Includes Revisions 1-3 s Illinois Power Co 80/08/29 41pp
- 8009090323 App C to Ciinton Units i & 2 FBAR. "Computer Programs " Includes Revisions i-3 Illinois Power Co 80/08/29 200pp
- 8009240457 Forwards proprietary info for FSAR Includes info re initial core fuel design for use of gadoiinia & offgas sys tachnology Affidavit for withholding enci Info available in Central Files only
 HULLER.O E Illinois Power Co 80/09/17 6pp
- @ Inspection reports. IE Bulietins & correspondence
- 8009090043 Forwards IE Bulietin 80-07. Suppl 1. "BUR Jet Pump Assembly Failure " No response required
 KEPPLER, J Q Region 3, Chicago, Office of the Director BO/05/i4
- 8009250346 Forwards IE Insp Rept 50-461/80-11 on 800624-27 & notice of violation
 FIORELLI, Q Region 3, Chicago, Reactor Construction & Engineering
 Support Branch 60/07/18 2pp
- --8009250347 Notice of violation from insp on 800624-27 * Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/07/17 ip
- ~-8009250352 IE Insp Rept 50~461/80-11 on 800624-27 Noncompliance noted failure to follow procedures re storage of metls KNOP.R C , NEISLER, J , WESCOTT. H I Region 3, Chicago, Office of the Director 80/07/17 Spp
- 8007180043 Forwards IE Insp Rept 50-461/80-13 on 800707-10 No NOTHBOURS Formary & They have not construction & Engineering FIGRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/07 2pp

- --8009180061 IE Insp Rept 50-461/80-13 on 800709-10 No noncompliance noted Major areas inspected station roundation subgrade preparation & concerns of certain employees not having access to NRC KNOP,R C . HESCOTT,H M . GALLACHER,E J Region 3, Chicago, Office of the Director 80/08/05
- 8007070808 Responds to IE Bulletin 77-03A, "Longitudinal Held Defects in ASME SA-312, Type 304 Stainless Steel Pipe" No SA-312 or A-312, Type 300 series fusion wolded pipe is planned for use in safety-related sys sub; to stresses greater than 85% MULLER, & E Illinois Power Co 80/08/12 ip
- 8009260249 Forwards IE Insp Rept 50-461/80-15 on 800729-31 No noncompliance noted FiORELLI.G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/08/14 2pp
- --8009260256 IE Insp Rept 50-461/80-15 on 800729-31 No noncompliance
- 8007030204 Forwards Revision i to 1E Bulletin 80-19, "Failures of Mercury-Wetted Katrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required

 KEPPLER, J 0 Region 3. Chicago, Office of the Director 80/08/i5
- 8009150483 Forwards IE info Notice 80-30. "Potential for Unacceptable Interaction Between Control Rod Drive Scram Furction t Nonessential Control Air at Certain GE BWR Facilities " No specific action or response requested KEPPLER, J G Region 3: Chicago, Office of the Director 80/08/20
- 8009120053 Forwards Suppl 3 to IE Bulletin 80-17. "Failure of Control Rods to Insert During Scram at BNR " No written response required KEPPLER, J O Region 3. Chicago, Office of the Director 80/08/22
- 8009170430 Forwards IE Circular 80-18, "10CFR50 59 Safaty Evaluations for Changes to Radwaste Treatment Sys " No written response KEPPLER, J Q Region 3. Chicago, Office of the Director 80/08/22
- 8009ii063i Responds to IE Builetin 80-16. "Potential Misapplication of Resemburt Inc Models ii3i & 1152 Pressure Transmitters of Either A or D Dutput Codes " Pressure transmitters are not currently used on safety-related sys WULLER.O E Illinois Power Co 80/08/23 1p
- 8009250457 Responds to 1E Bulletin 80-i9, "Fatlures of Mercury-Wetted Matrix Relays in Reactor Protective Sys or Operating Nuclear Power Plants Designed by C-E 'No mercury-wetted switches are used in facility safety-related sys WULLER, G E illinois Power Co 80/08/26 ip
- 8009100826 Ack receipt of 800723 t 0813 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-461/80-10 FIGRELLI.G Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/08/28 ip
- --R009i00B30 Responds to RRC 800623 ltr re violations noted in IC Insp Ropt 50-461/80-10 Corrective actions personnel reinstructed on requirements for performing safety-related activities GERSTNER.W C illinois Power Ca 80/07/23 2pp
- --8009100833 Responds to NRC 800623 ifr re violations noted in IE Insp Rept 50-46i/80-iO Clarifies 800723 reply re authorization for drilling operation GERSTNER.W C Illinois Power Co 80/08/13 2pp
- 8009230073 Forwards IE Info Notice 80-31, "Majoperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DDN 6008 Circuit Dreakers" " No written response required KEPPLER, J O Region 3. Chicago, Office of the Director 80/08/28
- 8009280205 Ack receipt of 800818 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-461/80-11 FIORELLI.Q Region 3, Chicago, Reactor Construction & Engineering Support Granch 60/08/30 ip

DOCKETED ITEMS

- --8009250208 Responds to NRC 800718 ltr re violations noted in IE Insp Rept 50-461/80 ll Corrective actions safety-related & nonsarety-related cable reels in electrical cable laydown area were segregated KOCH.4. J llinois Powar Co 80/08/18 2pp
- 8009240104 Forwards 1& Circular 80-21, "Regulation of Refueling Crews" No written response required KEPPLER, J.G. Regson 3, Chicago, Office of the Director 80/09/10 10
- 5 Reportable occurrences. LERs & related correspondence
- 8009020188 Ack receipt of 800715 interim rept re status of investigation or Sargent & Lundy soil characteristics error Final repf will be revioued upon receipt FIGRELLIO Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/08/01 ip
- 8009250474 Ack receipt of 800819 interim deficiency rept re thin-walled elbow in reactor pressure vessel drain line Final rept will be revisued upon receipt FIGRELLIC Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/08/30 ip
- 8009250252 Ack receipt of 800728 & 0815 deficiency repts re RHR heat exchanger lateral support provisions Confirms that addl stiffeners & supports will be installed to meet original design criteria FIGRELLIO Region 3. Chicago. Reactor Construction & Engineering Support Branch 80709705 ip
- 8009296339 Interim deficiency rept re failure of attachment welds swing barriers dividing termination cabinets into bays during shipment Repairs will not be completed until late 1981 No generic corrective action taken to avoid recurrence KOCH, L. J. Illinois Power Co. 80/09/22 Spp.
- DOCKET 50-462 CLINTON POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- BOO9080080 Forwards draft NUREG-DA96. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0694 encl N/o NUREG EISENNUT.D G Division of Licensing 80/08/01 119pp
 - O9150491 Approves BO0218 request for exemption of certain containment spray & discharge piping from hydrostatic testing Request re Code Case N-241 must be rewritten to include only submerged portions of referenced sys SCIMENCER, A Licensing Branch J 80/08/18 3pp
 - 0902034i Forwards 800807 ltr transmitting petition to amend Rule 203 (i) (10) (aa) of Chapter 3 of IL Pollution Control Board rules & regulations & supporting exhibits Ltr petition be exhibits available in Central Files only JULLER, 0 E | Illinois Power Co 80/08/27 1p
- 109080193 Forwards Amend 3 to DL application, requesting authorization to operate for 40 yrs at power levels up to 2,874 MMt per unit FSAR environ rept.physical security plan & antitrust info enci KOCH.L J Illinois Power Co 80/09/29 2pp
- -8009080197 Amend 3 to application for CL Requests authorization to operate for 40 yrs at power lovels up to 2,894 MWt per unit * fillnois Power Co 60/08/31 140pp
- 3009190115 Notifies of completed OL application review NRC safety review will be initiated Early response to encl request for additing refere & environ rept necessary to facilitate detailed technical review N/o encl EISCIMMUT.D © Division of Licensing 80/08/29 3pp
- 1009190754 Forwards request for add1 info to complete technical review of 791201 OL application Forwards NUREC-0694, "TM1 Related Requirements for New Ols "W/o encl NUREC EISENHUT, D G Division of Licensing 80/08/29 52pp
- 1009190513 Certifies that direct distribution has been made of licensing documents re acceptance review of Units i & 2 Certificates of Svc encl HULLER.9 C Illinois Power Co 80/09/15 App

- C Utility Environmental Report (ER), amends & correspondence
- 8009080202 Forwards environ rept.Vols 1 & 2 Also forwards Amend 3 to OL application requesting authorization to operate for 40 yrs at power levels up to 2.894 MUt per unit.F9AR.physical security plan 5 antitrust info KOCH.L J flinois Power Co 80/08/29 2pp
- --8009080209 Environ rept for facility, Vol 1 * fillingis Power Co 80/08/29 7726pp
- F Security, medical, emergency & fire protection plans
- 8009040465 issues invitation to send representatives to participate in regional workshop re emergency response facilities. Workshop will focus on presenting & discussing criteria, receiving comments & answering questions. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/08/it
- H General correspondence
- 8007080347 Informs of reorganization re three technical depts put under single corporate officer Establishes OA at same reporting level as managers of facility operations & nuclear station engineering (NOCH, 1 11) incis Power Co 80/07/02 ip
- 8009290383 Responds to ltr to President Carter re White House position on TMI accident Informs of re-examination of design & operation of nuclear gower plants including emergency evacuation plans to cope w/potential accidents
 SCHNEYCER, A Licensing Branch 3 80/09/09 ip
- K. Utility Final Safety Analysis Report (FSAR) & amends
- B009090254 Forwards Clinton Units 1 & 2 FSAR Includes Revisions 1-3 KDCH.L J 11linois Power Co B0/08/29 2pp
- --8007070258 Clinton Units 1 & 2 FSAR Includes Revisions 1-3 3 Illinois Power Co 80/08/29 7700pp
- B009090262 Chapter i to Clinton Units 1 & 2 FSAR, "Introduction & General Description of Plant" Includes Revisions i-3 * 111inois Power Co 80/08/29 350pp
- 8009090266 Chapter 2 to Clinton Units 1 & 2 FSAR, "Site Characteristics " Includes Revisions 1-3 * Illinois Power Co 80/08/29 1150pp
- 8009090269 Chapter 3 to Clinton Units 1 & 2 FSAR, "Design of Btructures, Components, Equipment & Sys " Includes Revisions 1-3 * 111:npis Power Co 80/08/29 1:00pp
- 8009090272 Chapter 4 to Clinton Units i % 2 FSAR, "Reactor." Includes Revisions i ~3 * illinois Power Co 80/08/29 320pp
- 8009090276 Chapter 5 to Clinton Units i & 2 FSAR, "RCS & Connected Sys " includes Revisions 1-3 * illinois Power Go 80/08/29 250pp
- 8009090279 Chapter 6 to Clinton Units 1 & 2 FSAR. "Engineered Safety Features " includes Revisions 1-3 * Illinois Power Co 80/08/29 550pp
- 8009090283 Chapter 7 to Clinton Units 1 & 2 FBAR, "Instrumentation & Control Bys " Includes Revisions 1-3 * Illinois Power Co 80/08/29 850pp
- 8009090284 Chapter 8 to Clinton Units 1 & 2 FSAR, "Electric Power" Includes Revisions 1-3
 * Illinois Power Co 80/08/29 185pp
- 8009090289 Chapter 7 to Clinton Units I & 2 FSAR. "Auxiliary Sys "
 Includes Revisions 1-3
 * Illinois Power Co 80/08/29 625pp
- 8009090293 Chapter 10 to Clinton Units f & 2 FSAR, "Steam & Power Conversion Sys " Includes Revisions 1-3 * Illinois Power Co 80/08/29 100pp

- 8009090296 Chapter ii to Clinton Units 1 & 2 FSAR, "Radwaste Mgt " Includes Revisions 1-3 Illinois Power Co 80/08/29 200pp
- 8009090299 Chapter 12 to Clinton Units 1 & 2 FSAR. "Radiation Protection " Includes Revisions 1-3 + Illinois Power Co 80/08/29 200pp
- 8009090301 Chapter 13 to Clinton Units 1 & 2 FSAR, "Conduct of Operations" Includes Revisions 1-3
 3 Illinois Power Co 80/08/29 150pp
- B009090304 Chapter 14 to Clinton Units 1 & 2 FSAR, "Initial Test Program" Includes Revisions 1-3 * Illinois Power Co 80/08/29 150pp
- 8009090307 Chapter i5 to Clinton Units 1 & 2 FSAR. "Accident Analysis " Includes Revisions 1-3 4 Illinois Power Co 80/08/29 400pp
- 8009090310 Chapter 16 to Clinton Units 1 & 2 FSAR: "Tech Specs " Includes Revisions i-3 # [llings Power Co 80/08/29 ip
- 8009090313 Chapter 17 to Clinton Units 1 & 2 FSAR, "QA " Includes
 - Illinois Power Co 80/08/29 50pp
- 8009090317 App A to Clinton Units 1 & 2 FEAR, "Glossary " Includes Revisions 1 [11ingis Power Co 80/08/29 i8pp
- 8009090321 App B to Ciinton Units 1 ½ 2 F5AR. "Const Matl Stds & QC Procedures " Includes Revisions 1-3 * Illinois Power Cq 80/08/29 4ipp
- 8009090323 App C to Ciintum Units i & 2 FSAR. "Computer Programs " Includes Revisions i-3 * Illinois Power Co 80/08/29 200pp
- 8009240457 Forwards proprietary info for FSAR Includes info re initial core fuel design for use of gadolinia & offgas systechnology Affidavit for withholding enci Info available in Central Files only WULLER.O E Iilinois Power Co 80/09/17 6pp
- Q Inspection reports. IE Bulletins & correspondence
- 8009090043 Forwards 18 Builetin 80-07. Suppl i. "BWR Jet Pump Assembly Failure." No response required
 KEPPLER, J Q Region 3, Chicago, Office of the Director 80/05/14
- 8007090808 Responds to IC Bulietin 79-03A. "Longitudinal Held Defects in ASME SA-312. Type 304 Stainless Steel Pipe " No SA-312 or A-312. Type 300 series fusion weided pipe is planned for use in safety-related sys subj to stresses greater than 85% HULLER. O E Illinois Power Co 80/08/12 ip
- 8009030204 Forwards Revision 1 to iE Bulletin 80-19. "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER.J O Region 3. Chicago, Office of the Director 80/08/15
- 8009150483 Forwards IE Info Notice 80-30, "Potential for Unacceptable interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE BNR Facilities " No specific action or response requested
 REPPLER, J. G. Region 3. Chicago, Office of the Director 80/08/20
- S009120053 Forwards Suppl 3 to IE Bulletin 80-17. "Failure of Control Rods to Insert During Scram at BWR " No written response required KEPPLER.J Q Region 3. Chicago. Office of the Director 80/08/22
- 8009170430 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response renuired REPPLER. J G Region 3. Chicago, Office of the Director 80/08/22

- 8009110631 Responds to IE Bulletin BO-16. "Potential Misapplication of Rosemount, Inc Models 1151 & 1152 Pressure Transmitters w/ Either A or D Dutput Codes " Pressure transmitters are not currently used on safety-related sys WULLER, O E 11iinois Power Co 80/08/23 1p
- 8009250457 Responds to 1E Bulietin 80-19. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E ' No mercury-wetted switches are used in facility safety-related sys WULLER.O E litinoss Power Co 80/08/26 1p
- 8007230073 Forwards IE Info Natice 80-31, 'Maloperation of Gould-Brown Bover: 480 Voit Type K-6005 & K-DON 6005 Circuit Breakers " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/08/28
- 8009240i04 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/io
- S Reportable occurrences, LERs & related correspondence
- 8009250252 Ack receipt of 800728 & 0815 deficiency repts re RHR heat exchanger lateral support provisions Confirms that addistiffeners & supports will be installed to meet original design criteria FIORELLI.Q Re Region 3. Chicago, Reactor Construction & Engineering ich 80/09/05 (p Support Branch
- DOCKET 50-466 ALLENS CREEK NUCLEAR STATION, UNIT 1 Q Adjudicatory correspondence
- B009050473 Add1 response to F0IA request for 20 documents for use as intervenor in facility proceeding Forwards nonproprietary version of NEOD-24154, Vois 1 to 2, "Ouglification of One-Dimensional Core Transient Model for BHRs " W/o encl FELTON.J M Division of Rules and Records 80/08/12 ip
- 8009080065 Suppis 800801 response to FOIA request for 64 documents for use in facility proceeding Forwards addit documents listed in App A Items 38.61.64 \$ 65 have not been located FELTON, J II Division of Rules and Records 80/08/i8 4pp
- B0090B0447 Supplemental response to FOIA request for 64 documents for use in facsilty proceeding Forwards documents listed in App A H/O encis FELTOH, J M Division of Rules and Records 80/08/22 2pp
- 8009020058 Response to Polithoff first set of interrogatories Restates facts from FES.NUREO-0470.re obstacles to production of methane from organic matl Marine biomass farm environ affects not evaluated W/affidavit & Certificate of Evc MODN.C N Assistant Director for Licensing 80/08/27 App
- 8009020066 Motions to strike second, third & fifth paragraphs of TX PIRG & Dogget 800813 proposed emergency planning contention Proposes form to be admitted in proceeding Certificate of SDMINKLIS M Hearing Branch 3 80/08/27 7pp
- BOO904027i Response in opposition to W Schuessler, S Doggett & TX PIRO 1090002/1 Masponse in opposition to W scruessier;5 Loggett, BOOBIS reworded contention except portion re capability of pian w/iocation Remaining portions do not comply w/ASLB 800724 order Certificate of Svc encl RASKIN, D B, COPELAND, J G Houston Lighting & Power Co Lowerstein, Newman, Reis, Axelrad & Toll 80/08/28 \$2pp RASKIN, D D
- 8009090451 Urges ABLBP not to consider applicant 800B13 appeal for reconsideration of Jan 1981 hearing date Applicant is trying to harass other parties & deny due process in attempt to to daress comments, and the serior of the se MARRACK, D
- 8009040297 Forwards 800819 FR notice re amends to emergency planning regulations SDHINXI.S M Hearing Branch 3 80/09/02 14pp
- 8009110014 Ack receipt of applicant 800822 ltr directed to RM Lazo Concurs w/applicant motion to set schedule for evidentiary hearings Supports any action that may move proceeding expeditiously BLACK.R L. Hearing Branch i 80/09/09 3pg

- 8009170149 Motion for summary disposition of Contention 48 alleging superiority of South TK site to Allens Creek > Texas Public Intelest Research Group 80/09/09 lp
- ---B009170153 Statement of matl racts as to which no genuine issues exist in support of motion for summary disposition of Contention 68 re superiority of South TX site + Texas Public Interest Research Group B0/09/09 2pp
- --8009170154 Affidavit in support of notion of summary disposition of Contention 68 re superiority of South TX site to Allens Creek Discusses environ & economic issues UCHRISCH.C Teras Public Interest Research Group 80/09/09 7pp
- --8009170157 Affidavit in support of summary disposition of Contention 6B re-superiority of South TV site to Allens Creek
 SAX10H.H Texas Public Interest Research Group 80/09/05 4pp
- 8009180475 Further response to TX PIRO 16th interrogatories Discusses future prices of gas, nuclear & coal energy, personnel qualifications, control room design, safety relief valve setpoints & hydrogen explosion Certificate of Svc encl COPELAND, J G , NEUMAN, J R Houston Lighting & Power Co COPELAND, J G Baker & Botts 80/07/09 25pp
- 8009150253 Forwards revised Pages 7-10 % 13 to applicant 800807 response in opposition to TX PIRG Class 9 motion Applicant overlooked provision precluding parties from citing statements at open Commission meetings W/Certificate of Svc NEWHAN, J R Lowenstein, Neuman, Reis, A) elrad % Toll 80/09/10 4pp
- JOO9160527 Response in opposition to NRC & applicant motions to strike portion of emergency planning contention Consolidated language does not incorporate new issues of Terras Public Interest Research Group SCHUESSLER, W J Affiliation Unknown DOGGETT, S A Doggett, B A 80/09/10 2pp
- 9009160201 Motion for extension until 800919 to file affidavits in support of request for protective treatment re GE & Brown & Root documents Appropriate persons unavailable Certificate of Gvc encl
 CULP.R H , COPELAND, J G Houston Lighting & Power Co CULP, R H
 Lowenstein, Newran, Reis, Azelrad & Toll 80/09/11 4pp
- O9180418 Motion for summary disposition of Contention 76 re environ impact of transmission lines DOI 780328 ltr to util, portions of EIG.Royal Soc for Protection of Birds 770822 ltr to TR Scottings & Certificate of Svc encl MARRACK, D Marrack, D 60/09/il 20pp
- 009160520 Order granting extension until 800919 for applicant to file affildavits due to unavailability of appropriate GE & Brown & Root officers
 - WOLFE, S.J. Atomic Safety and Licensing Board Panel 80/09/12 ip
- D09170223 Motion for summary disposition of Contention 43 (AC 8) re natural gas generation & for extension to file motion Alleges availability, sufficiency & superiority of natural gas as alternative to facility M/Certificate of Svc SCOTT.J M Texas Public Interest Research Group 80/09/12 lp
- --8009170225 Affidavit comparing natural gas generation to nuclear flasion generation of electricity as superior alternative to facility JONNISON.C Teias Public Interest Research Group. 80/09/09 12pp
- 8007180542 informs of no need to reconstitute ASLB due to prospect of imminent settlement, in response to 800822 ltr
 LAZO.R M Atomic Safety and Licensing Board Panel 80/09/15 ip
- 8009190229 Memorandum & order denying TX PIRG 800724 motion for preparation of suppl to EIS Te Class 9 accidents NRC alone may bring cases warranting consideration of severe environ impacts to Commission attention
 LINENERGER, 0, WOLFE, 8 J Atomic Safety and Licensing Board Panel 80/09/15 5pp
- 8009220417 Memorandum for PDR summariing 800916 telcon w/J Robbins, legislative assistant to Congressman R Paul re results of 800915 conference Parties will be advised of hearing when decided MOLFE.S J Atomic Safety and Licensing Board Panel 80/09/16 lp

- --8009220420 Forwards envelope addressed to Congressman R Paul for sending copy of ASLD 800916 memorandum FITTI, C Atomic Safety and Licensing Board Panel 80/09/17 2pp
- 8009220415 Order advising of B01201-05,08-12,15-19 & B10105 as convenient dates for hearing on environ matters Whether schedule is desirable & feasible must be decided by parties no later than B00926 WDLFE,S J Atomic Safety and Licensing Board Panel B0/09/17 2pp
- 8009260007 Response in opposition to applicant motion for addl time to file affidavits Good cause required per ASLB 800713 probearing conference directive not established MARRACK, D Affiliation Unknown 80/09/18 2pp
- 8009230691 Forwards affidavits of WC Oang & SH Orate of OE & Brown & Root, respectively, re-claims that certain documents receive protective treatment Affidavits comply w/ASLB 800821 order Related correspondence CULP R H Lowenstein, Newman, Rels. Axelrad & Toll 80/09/19 15pp
- BOO9250058 Urder striking Paragraphs I, II & VI of Schusssler, TX PIRQ & Boggett consolidated contention Accepts Paragraphs III w/o ltem (d), IV & V w/o Braros River contamination Discovery shall cornence immediately & must be completed by BO1020 LINENBERDER, G, WOLFE, S J Atomic Safety and Licensing Board Pane) BO/09/19 Bpg
- 8009240565 Forwards original affidavit by WO Gang re GE document known as Reed Rept W/o encl Related correspondence CULP.R H Lowensteln.Newman.Rels.Axelrad & Toll 80/09/22 2pp
- 8009300027 Response to FH Potthoff third set of interrogatories Objects to all questions due to irrelevancy Affidavits & Certificate of Svc encl Related corrospondence HANCOCK, D. NEWHAN, J.R. Houston Lighting & Power Co
- 8009260674 Memorandum warning intervening parties to read Rules of Practice & amends re svc of documents in adjudicatory proceedings
 MOLFE, S.J. Atomic Safetu and Licensing Board Panel 80/09/23 16
- B009260207 Forwards applicant response to first set of interrogatories Provides status of ASLD actions re final language of emergency planning contention Applicant will file updated response if necessary, following review of ASLD order RASKIN.D B Lowenstein.Nowman.Rels.Axelrad & Toll 80/09/24 1p
- --8007260210 Response to intervenor Schuessier first set of Interrogatories & requests for production of documents Requested documents & Certificato of Byc encl RASKIN,D B Houston Lighting & Power Co RASKIN,D B Lowenstein,Newman,Reis,Axelrad & Toll 80/07/24 75pp
- 8009300012 Response to ASLB 800917 order proposing hearing schedule re environ issues Doherty may respond to applicant & NRC motion for summary disposition by 801023 Opposes TX PIRO motion for add1 time to move for disposition Certificate of 8vc encl BLACK.R L Hearing Branch 1 80/07/25 Spp
- 8009300469 Response in opposition to JF Doherty 800915 motion for additime to reply to NRC & util motion for summary disposition intervenor made no attempt to inspect documents needed for answers until 800911 W/Certificate of Svc & documentation COPELAND, J & NEMMAN, J & Houston Lighting & Power Co COPELAND, J & Baker & Botts 80/09/25 10pp
- 8009300456 Order admitting & consolidating intervenors amended contentions. Comings 9, Griffith 1, Johnson 1 & Lemmer 1 Intervenors shall agree on lead party Discovery shall start immediately & be completed by 801027 LINEMBERGER. O A. WOLFE. S J Atomic Bafety and Licensing Board Panel 80709726 3ps
- H General correspondence
- 8009240540 Provides Subcommittee on Oversight & Investigations w/status of actions re results of hearing on facility CP application, in response to concerns of C Johnson w/intervenor TX PIRO FR excerpt encl PIRCKS:0 J Office of the Executive Director for Operations 80/09/19 days
- U Congressional/Executive Correspondence
- 8009170268 Urges immediate action be taken to institute long overque formal hearings on CP Related correspondence LOEFFLER, T Hause of Rep 80/09/12 1p

- 8009240485 Requests that NRC set date for CP hearing on new nuclear power plant Related correspondence PICKLE-J J House of Rep 80/09/17 ip
- DOCKET 50-467 ALLENS CREEK NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREO-0696, "Functional Criteria for DYNORUBIN Forwards draft NUMEU-0646. "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 enci W/a NUREO ETEENHUT. 9 0 Division of Licensing 80/08/01 119pp
- Q Adjudicatory correspondence
- 8009050473 Add1 response to FOIA request for 20 documents for use as intervenor in facility proceeding Forwards nonproprietary version of NEDO-24154, Vols 1 & 2, "Qualification of One-Disensional Core Transient Model for BMRs "(//o encl FELTON, J M Division of Rules and Records 80/08/12 ip
- 8009050056 Suppls 800801 response to FOIA request for 64 documents for use in facility proceeding Forwards addl documents listed in App A Items 38.61.64 & 65 have not been located W/o encls
 FELTON, J M Division of Rules and Records 80/08/18
- 8009080449 Supplemental response to FOIA request for 64 documents for use in facility proceeding Forwards documents listed in App A W/o encls FELTON J IS Division of Rules and Records 80/08/22 2pp

- BOO9240340 Provides Bubcommittee on Oversight & Investigations w/status of actions re results of hearing on facility CP application in response to concerns of C Johnson w/intervenor Tx PIRO fR excerpt entl DIRCKS.N J Office of the Executive Director for Operations DIRCKS.W J 0:
- SOCKET 50-471 PILORIM NUCLEAR POWER STATION, UNIT 2
- 4 Application/construction stage documents & correspondence.
- 3009080080 Forwards draft NUREQ-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encI W/o NUREO EISEN
- Security, medical, emergency & fire protection plans
- 3009090569 Forwards recommendation for Item 3 1 6/3 2 4 re cable combustibility for fire protection review Recommends that licensee be required to coat okonite & kerite cables HALL.RE Brookhaven National Laboratory 80/07/14 3pp
- Adjudicatory correspondence
- HO09100421 Motion to include latest util 10-yr energy & peak demand forecasts in 790718 hearings re need for power Urges apportunity to suppl findings of fact by all parties re decline in growth rates Certificate of Svc encl WRIGHT.F S Massachusetts, State of 80/09/03 7pp
- OD9190297 Responds to FOIA request for 15 documents listed in bibliography of NURCO-0625. "Rept of Siting Policy Task Force " Documents 6-8 & 13 are available in PDR Forwards remaining documents FELTON, J M Division of Rules and Records 80/09/04
- -8009190587 Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants, for determination of site acceptability & adequacy of engineered safety features MINDOUGAR B Office of Standards Development, Director, SECY-79-362 79/06/04 7pp
- -BDO9190630 Requests that encl, "Differences in Procedures for Estimating Atmospheric Dispersion Conditions at Inland & Coastal Sites," be sent to appropriate Boards SCINTO, J F Hearings Division 79/04/04 16pp

- 8009250049 Response stating no objection w/o concurring in State of MA motion to suppl hearing record on need for power re energy & peak demand forecasts Reserves right to appose future attempts to reopen record Certificate or Svc encl LEWALD, G H, DIGNAN, T C Boston Edison Co LEWALD, G H Ropes & Gray 80/09/18 5pp
- 8009260310 Response stating no objection to State of MA 800903 motion to suppl record on need for power w/applicant & NEPGOL latest 10-yr power demand forecasts Objects to conclusory & argumentative content of motion Certificate of Svc enci CODDARD.R J Hearing Branch 2 80/09/24 5pp
- DOCKET 50-472 PILGRIM NUCLEAR POWER STATION, UNIT 3 F Socurity, medical, emergency & fire protection plans
- 8009090569 Forwards recommendation for Item 3 1 6/3 2 4 re cable combustibility for fire protection review Recommends that licensee be required to cost obouite 1 kerite cables HALL/R E Brockhaven National Laboratory 80/07/14 3pp
- DOCKET STN-50-482 WOLF CREEK GENERATING STATION
- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for DOVIDUOUS FORWARDS STATE NUMBEROUSE. FINEETIDIAL CITEBRIA FOR Emergency Response Facilities "Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0676 enci W/o NUREO EISENHUT.D O Division of Licensing 80/08/01 ii9pp
- 8009030685 Describes interim actions needed prior to issuance of UL to further reduce risk from ATHS before required plant mods, as determined by Commission, are completed ATHS emergency operating procedure should be submitted TEDESCU.R L Division of Licensing 80/08/15 Spp
- 8009030541 Forwards addl info that resulted from preliminary review of FSAR per 800731 request PETRICK.N A Standardized Nuclear Unit Power Plant System 80/08/28 10pp
- 8009190773 Notification of 801607 % 08 meeting w/util in Burlington,KA to discuss NRC case load forecast BTARK,R M Licensing Branch 1 80/08/29 App
- B009300397 Comments on draft NUREG-0696 AIF comments endorsed Deletion recommended for sections prohibiting use of plant process computer to process info for emergency response facilities SCHMDERER, F. Standardized Nuclear Unit Power Plant System 80/09/24 Spp
- F Security, medical, emergency & fire protection plans
- 8009020140 Invites participation in 800822 workshop in Atlanta, QA to splicit comment re proposed functional criteria for emergency response facilities in NUREO-0676 Discussion to include location size & staffing of emergency ctrs
 SEYPRIT, K V Region 4, Dallas, Office of the Director 80/08/12
- K. Utility Final Safety Analysis Report (FSAR) & amends
- BD0919044i Forwards Revision 1 to SNUPPB FSAR, containing responses to NRC acceptance review questions & add1 info generated since initial FSAR submittal in Oct 1979 PETRICK, N A Standardized Nuclear Unit Power Plant System 80/09/17 ip
- ---8009190445 Revision i to SNUPPS FSAR, containing responses to NRC acceptance review questions & add1 info generated since initial FSAR submittal in Oct 1979 includes description of changes made to attain cold shutdoun

 * Standardized Nuclear Unit Power Plant System 80/09/17 160000
- O Inspection reports. IC Bulletins & correspondence
- B009100047 Discusses IE Insp Rept 50-482/80-12 on 800606-10 & forwards notices of violation and deviation SEIDLE-N C Region 4. Dailas. Reactor Construction & Engineering Support Branch 80/06/19 2pg
- --8009100052 Matice of violation from inso on 800406-10 Noncompliance noted failure to establish housekeeping zone designations * Region 4, Dallas, Office of the Director 80/06/19 ip

- --8009100059 Notice of deviation from insp on 800606-10 Noncompliance noted failure to establish fire protection & prevention
 - Region 4, Dallas, Office of the Director 80/06/19 1p
- 8009150014 Responds to IE Bulletin 80-08 re examination of containment itner penetration welds Design uses flued head for penetration connections Field installation just begun & nondestructive examination results not available KDESTER. © L. Kansas Gas & Electric Co. E0/07/01 App
- 8009170324 Forwards IE Insp Rept 50-462/80-16 on 800708-11 No noncompliance moted
 SEIDLE, U C Region 4, Dallas, Reactor Construction & Engineering
 Support Branch 80/07/16 2pp
- --8009170387 IE insp Rept 50-482/80-16 on 800708-11 No noncompliance noted Major areas inspected licensee action on previous insp fundings, site tour & review of procedures & records for uelding
 CROSSMAN.W A Region 4, Dalias, Office of the Director
 HALL,R E., GluseRT,L D. Region 4, Oallas, Reactor Construction &
 Engineering Support Branch 80/07/16 3pp
- 8009090644 Forwards IE Insp Rept 50-482/80-12 in June, 1980 SEIDLE,W C Region 4: Dallas, Reactor Construction & Engineering Support Branch 80/07/21 2pp
- --8009090648 IE insp Rept S0-482/80-12 in June 1980 Noncompliance noted failure to establish housekeeping ione designation & to establish fire protection δ prevention requirements GDERG, C R. HUBACEK, W. G. CROSSMAN, W. A. Region 4, Dallas, Office of the Director 80/07/18 9ρp
- 1009150342 Forwards IE lnsp Rept 50-482/80-15 on 800630-0703 & notice of violation SEIDLE: N C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/07/28 2pp
- --8009150345 Notice of violation from insp on 800630-0703 * Region 4. Dallas. Reactor Construction & Engineering Support Branch 80/07/25 2pp
- --8009150348 IE Insp Rept 50-482/80-15 on 800630-0703 Noncompliance noted failure to provide appropriate procedures for activities affecting quality MARTIN.L. E. OBERO.C R. CROSSMAN.H A. Region 4, Dailas, Office of the Director 80/07/25 Spp
- 1009030263 Forwards Revision 1 to IE Bulletin BO-19. "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Fower Plants Designed by C-E " Written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/08/1 Region 4. Dallas, Office of the Director 80/08/15
- 009150934 Ack receipt of 800624 ltr informing NRC of steps taken to correct deviation noted in IE Insp Rept 50-482/80-08 Add1 info required SEIDLE, U.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/08/20 1p
- --8009150381 Responds to NRC 809523 itr re deviation noted in IE Insp Rept 50-482/80-08 Corrective actions Raceway Seismic Test Program conducted by AE confirmed structural adequacy of commercial grade cable trays KOESTER.O L. Kansas Gas & Electric Co. 80/06/24 2pp
- 8009170396 Forwards 1E Circular 80-16, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response SEYFRIT, K V Region 4. Dallas, Office of the Director 80/08/22
- 8009170416 Responds to IE Bulletin 80-16 re potential misapplication of Rosemburt pressure transmitters identified transmitters are not used in safety-related areas One hundred fifty manhours expended for review PETRICK.N A Standardized Nuclear Unit Power Plant System 80/08/26 1p
- 8007120426 Forwards IE Info Notice 80-31, "Maloperation of Gould-Drown Bover: 480 Voit Type K-6005 & K-DON 6005 Circuit Dreakors " No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/08/27
- 600730060B Ack receipt of 800828 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-462/60-15 SEIDLE-W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/07/15 ip

- --8009300612 Responds to NRC 900728 ltr re violation noted in IE (ns)
 Rept 50-482/80-15 Corrective actions Daniel procedures to be
 revised for controlling insp & installation of supports &
 raceway more effectively
 KOESTER, G L Kansas Gas & Electric Co 80/08/28 3pp
- S Reportable occurrences, LERs & related correspondence
- 8009170442 Deficiency rept re excessive pressures in feedwater lines following postulated high energy line break Pressure can be reduced by relocating feedwater check valves Util no longer considers matter reportable under 10CFR50 59e PETRICK, N.A. Standardized Nuclear Unit Power Plant System 80/06/30 ip
- 8009290218 Discusses investigation of 3.5 inch diameter nuts & bolts used in NSSS lateral supports Bolts & nuts provide adequate safety margins against thread failure at max design load Matter not reportable per 10CFRSO 55e KOESTER.O. L. Mansas Gas & Electric Co. 80/07/28 1p
- 8009150193 Ack receipt of 800724 final deficiency rept re loose bushings in pipe support sway struts CARLSDM.R T Region I. Philadelphia. Reactor Construction & Engineering Support Branch 80/08/06 Ip
- --8009150196 Final deficiency rept re loose bushings in pipe support sway struts Struts found with loose bushings will be replaced Corner & Lada 800724 rept encl PETRICK.N A Standardized Nuclear Unit Power Plant System 80/07/24 10pp

DOCKET STN-50-483 CALLOWAY PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 8007080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0676 encl W/o NUREO EISENHUT.D O Division of Licensing 80/08/01 119pp
- 800909092 Informs that "accepted" version of DL application.consisting of DL application.vol 1.SNUPPS FSAR Vol 1-9 & FBAR Addendum Vol 1-9 will be sent under separate cover 80UDER.J L Division of Rules and Records 80/08/14 ip.
- 8009030672 Describes interim actions needed prior to issuance of OL to further reduce risk from ATMS before required plant mods, as determined by Commission, are completed, ATMS energency operating procedure should be submitted TEDESCOR L. Division of Licensing 80/08/15 2pp
- B009020093 Forwards Dames & Moore 800729 rept, "Results of Detailed Excavation Mapping, Ultimate Heat Sink Area, Essential Svc Water Sys. & Unit 1 Power Block Subgrade, Callaway Plant, Units 1 & 2 "

 5CHNELL, D F Union Electric Co 80/08/25 1p.
- ---8009020099 "Results of Detailed Excavation Mapping, Ultimate Heat Sink Area, Essential Svc Water Sys, & Unit 1 Power Block Subgrade, for Facilities " * Dames & Moore 80/07/29 83pp
- 8009030541 Forwards add1 info that resulted from preliminary review of FBAR per 800731 request PETRICK,N A Standardized Nuclear Unit Power Plant System 80/08/28 10pp
- 8009230770 Notification of 801009 % 10 meetings w/util in Motane & Fulton:KO to discuss NRC case load forecast STARK:R M Licensing Branch 1 80/08/29 App
- G Adjudicatory correspondence
- 8009290034 Response in opposition to JO Reed 800910 petition to intervene Urges denial w/o prejudice to refile petition within 25 days after ruling Concerns of petitioner unclear Wappearance statement & Certificate of Svc
- 8009300870 Response in opposition to JO Reed Sept 1980 petition requesting deferral of OL issuance until local emergency response is adequately operational Intervention defective, but limited appearance feasible Certificate of Byc encl. CHARNOFF, G. HAXTER, T. A. Union Electric Co. CHARNOFF, G. Shi Pittman, Potts & Troubridge 80/09/25 App Shaw.

- 8009020127 Responds to 800625 ltr & L Drey concerns re accountability of in-place embedded anchors Addl testing necessary to develop data to substantiate anchor acceptability NRC evaluation to be conducted following testing completion DIRCKS:W J Office of the Executive Director for Operations 80/08/04 2pp
- 800912026B Submits petitlon to withhold issuance of GL until adequate local emergency response capability has been planned funded Z made operationally effective REED.J O Afflication Unknown 80/09/10 2pp
- M Utility Final Safety Analysis Report (FSAR) & amends
- BOO9i90441 Forwards Revision 1 to SNUPPS FSAR.containing responses to NRC acceptance review questions 5 add1 info generated since initial FSAR submittal in Oct 1979
 PETRICK.N A Standardized Nuclear Unit Power Plant System BD/09/17 ip
- ~~8009190445 Revision 1 to SNUPPS FSAR, containing responses to NRC acceptance review questions & add1 info generated since initial FSAR submittal in Oct 1979 Includes description of changes made to attain cold shutdown

 * Standardized Nuclear Unit Power Plant System 80/09/17 18000
- BOO9230662 Forwards Revision 1 to FSAR site addendum BRYAN, J K Union Electric Co 80/09/18 1p
- --8009230667 Revision 1 to FSAR site addendum
- G Inspection reports, 1E Gulletins & correspondence
- 8009030218 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER.J O Region 3. Chicago. Office of the Director 80/08/15
- B009170440 Forwards IE Circular B0-18, "10CFR50 59 Safety Evaluations for Changos to Radwasto Treatment Sys " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/08/22
- 8009170416 Responds to JE Bullotin 80-16 re potential misapplication of Rosemount pressure transmitters Identified transmitters are not used in safety-related areas One hundred fifty manhours expended for review FETRICK.N A Standardized Nuclear Unit Power Plant System 80/88/26 ip
- 8009230041 Forwards IE 1nfo Notice 80-31. "Maloperation of Could-Brown Boveri 480 Volt Type K-6003 & K-DON 6008 Circuit Breakers " No written response required KEPPLER.J O Region 3. Chicago, Office of the Director 80/08/28
- B009240122 Forwards 1E Circular 80-21, "Regulation of Refueling Craws "
 No written response required
 KEPPLER, J O Region 3, Chicago, Office of the Director B0/09/10
- S Reportable occurrences. LERs & related correspondence
- 8009170442 Deficiency rept re excessive pressures in feedwater lines following postulated high energy line break Pressure can be reduced by relocating feedwater check valves Util no longer considers matter reportable under 10CFR50 55e PETRICK:N A Standardized Nuclear Unit Power Plant System 80/04/30 ip
- 8009150193 Ack receipt of 800724 final deficiency rept re loose bushings in pipe support sway struts CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/05 ip
- --8009150194 Final deficiency rept re loose bushings in pipe support sway struts Struts found with loose bushings will be replaced Corner & Lada 800724 rept encl PETRICK.N A Standardized Nuclear Unit Power Plant System 80/07/24 10pp

- 8009020331 Ack receipt or 800730 interim deficiency rept re Berger-Paterson pape support struct w/mechanical shock arrestor FIORELLI.C Region 3, Chicago. Reactor Construction & Engineering Support Branch 80708/13 ip
- 8009103070 Ack receipt of 800731 final deficiency rept re anchor bolt throad tolerance FIORELLI.0 Region 3 Chicago. Reactor Construction & Engineering Support Branch 80708719 ip
- --8009100080 Final deficiency rept re NSSS lateral support anchor bolt nuts Had noncompormance gone undatected, no significant safety problem would have arisen Item withdrawn as significant deficiency BRYANIJK Union Electric Co 80/07/31 Ip
- 8009090546 Final deficiency rept re adequacy of application & insp of fireproofing matls applied to structural steel, previously reported on 800801 Defective areas noted in reinsp will be reworked to assure application conformance BRYAN, J K Union Electric Co 80/08/29 1p
- 0009230651 Final deflicency rept re-putential bolt head-pipe clamp interferance which could hinder full function of Bergen-Patterson pipe support strut assomblies Bechtel Power Corp advised that all assemblies corrected prior to shipment URYAN.J K Union Electric Co. 80/09/10 2pp
- DOCKET STN-50-485 STERLING POWER PROJECT NUCLEAR, UNIT I
- 8009030059 Forwards Revision 1 to 1E Bulletin 80-19. "Failures of Mercury-Hetted Matrix Relays in Reactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER.B H Region 1. Philadelphia, Office of the Director 80/08/15 1p
- 8009180051 Forwards 1E Circular 80-18, '10CFR30 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director BO/08/22 1p
- 8009120213 Forwards lE info Notice 80-31. "Maloperation of Gould-Brown Bovert 480 Volt Type K-6005 & K-DDN 4008 Circuit Breakers " No written response required GRIER B M Region 1. Philadelphia. Office of the Director 80/88/27 ip
- 8009230798 Forwards 1E Circular 80-21, 'Regulation of Refueling Craws " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/09/10 1p
- B009240335 Forwards IC Info Notice B0-32. "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matis." No written response required GRIER, B H Region 1. Philadelphia. Office of the Director B0/09/12 lp
- 8 Reportable occurrences, LERs & related correspondence
- B00917044R Deficiency rept re oxcessive pressures in feedwater lines following postulated high energy line break Pressure can be reduced by relocating feedwater check valves Util no longer considers matter reportable under 100FR50 95e PETRICK, N A Standardized Nuclear Unit Power Plant System 80/06/30 tp
- DOCKET STN-50-486 CALLOWAY PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8007090080 Forwards draft NUREQ-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREQ-0696 encl M/o NUREQ EISENMUT.D 0 Division of Licensing 80/08/01 119pp
- 8009090092 Informs that "accepted" version of OL application, consisting of OL application. Vol 1:5NUPPS ITSAR Vol 1-9 & FSAR Addendum Vol 1-5 will be sent under separate cover SOUDER, J L Division of Rules and Records 80/08/14 1p

- 8009030672 Describes interim actions needed prior to issuance of GL to rurther reduce risk from ATWS before required plant mods, as determined by Commission, are completed ATWS generously operating procedure should be submitted TEDESCO,R L. Division of Licensing 80/08/15 2pp
- 8007020073 Forwards Dames 5 Moors 800729 rept. "Results of Detailed Ercavation Mapping.Ultimate Heat Sink Area Essential Svc Hater Sys. A Unit 1 Power Block Subgrade, Callaway Plant. Units 1 A 2 " SCHMELL.D F Union Electric Co 80/08/25 1p
- --B007020079 "Results of Detailed Excavation Mapping, Ultimate Heat Bink Area.Essential Svc Hater Sys. & Unit 1 Power Block Subgrade. for Facilities " 4 Dames & Moore 80/07/29 83pp
- 8009030541 Forwards addition that resulted from preliminary review of FSAR per 800731 request PETRICK:N A Standardized Nuclear Unit Power Plant System 80/08/28 1000
- B009230770 Notification of 801009 % 10 meetings w/util in Mokane & Fulton, KO to discuss NRC case load forecast STARK,R K Licensing Branch (80/08/29 6pp

G Adjudicatory correspondence

R009290034 Response in opposition to JC Reed B00910 petition to intervene Urges denial w/o prejudice to refile petition within 25 days after ruling Concerns of petitioner unclear W/appearance statement 5 Certificate of Svc

)09300570 Response in opposition to JO Reed Sept 1780 petition requesting deferral of UL issuance until local emergency response is adequately operational intervention defective, but limited appearance feasible Certificate of Svc encl CHARNUFF.Q BAXTER.T A Union Electric CO CHARNUFF.Q Shaw, Pittman, Potts & Troubridge 80/09/25 4pp

H General correspondence

8009020127 Responds to 800629 itr 3. L. Drey concerns to accountability of in-place embedded anchors Addi testing nacessary to develop data to substantiate anchor acceptability NRC evaluation to be conducted following testing completion DIRCKS.II J. Diffice of the Executive Director for Operations 80/08/04 2pp

O9120268 Submits petition to withhold issuance of OL until adequate local emergency response capabelisty has been planned funded & made operationally effective REED. J O Affiliation Unknown 80/09/10 2pp

Utility Final Safety Analysis Report (FSAR) & amends

- 3009190441 Forwards Revision i to SNUPPS FSAR, containing responses to NRC acceptance review questions & addl info generated since initial FSAR submittal in Oct 1979 PETRICK. N A Standardized Nuclear Unit Power Plant System 80/09/17 ip
- --8009190445 Revision 1 to SNUPPS FSAR, containing responses to NRC acceptance review questions & addi info generated since initial FSAR submittal in Oct 1979 Includes description of changes made to attain cold shutdown

 # Standardized Nuclear Unit Power Plant System 80/09/17 1600pp
- B009230662 Forwards Revision 1 to FSAR site addendum ERYAN.J K Union Electric Co 80/09/18 ip
- --8009230867 Revision 1 to FSAR site addendum * Union Electric Co 80/09/18 200pp
- Q Inspection reports, IE Bulletins & correspondence
- 8009030218 Forwards Revision 1 to IE Bulletin 80-19. "Failures of Kercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/15

- 8009170440 Forwards 1E Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/08/22
- 8009170416 Responds to IE Bullotin 80-16 re potential misapplication of Rosembunt pressure transmitters Identified transmitters are not used in safety-related areas One hundred fifty manhours expended for review PETRICK.N A Standardized Nuclear Unit Power Plant System 80/08/25 ip
- 8009230061 Forwards IE Info Notice 80-31, "Maloperation of Could-Brown Bover(480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required KEPPLER, J G Region 3, Chicago, Office of the Directur 80/08/28
- B009240i22 Forwards IE Circular 80-21, "Regulation of Refueling Creus" No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/09/10 ip
- 8 Reportable occurronces. LERs & related correspondence
- BO09170442 Deficiency rept re excessive pressures in feedwater lines following postulated high energy line break Pressure can be reduced by relocating feedwater check valves Util no longer considers matter reportable under 10CFR50 55e PETRICK.N A Standardized Nuclear Unit Power Plant System 80/06/30 1p
- 8009150193 Ack receipt of 800724 final deficiency rept re loose bushings in pipe support sway struts CARLSONR T Region i. Philadelphia. Reactor Construction & Engineering Support Branch 80/08/06 ip
- --8009150196 Final deficiency rept re loose bushings in pipe support way struts Struts found with loose bushings will be replaced Corner & Lada 800724 rept enci
 PETRICK,N A Standardized Nuclear Unit Power Plant System 80/07/24 10pp
- 8007020331 Ack receipt of 800730 Interim deficiency rept re Berger-Paterson sipe support strut w/mechanical shock arrestor FIDRELLI,O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/13 ip
- 8009100070 Ack receipt of 800731 final deficiency rept re anchor boit thread tolerance FIDRELI,O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/08/19 lp
- --8009100080 Final deficiency rept re NSSS lateral support anchor bolt nuts Had nonconformance gone undetected no significant safety problem would have arisen Item withdrawn as significant deficiency BRYAN, J K Union Electric Co 80/07/31 ip

DUCKET 8TN-50-488 PERKINS NUCLEAR STATION, UNIT 1

- A Application/construction stage documents & correspondence
- BOD90BOOBO Forwards draft NUREC-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREC-0696 encl M/o NUREO EISENHUT, D O Division of Licensing BO/08/01 119pp
- O Adjudicatory correspondence
- 8007030696 Notice of appeal from ASLB 800222 partial initial decision re-alternative sites Seeks exceptions re-ASLB 780717 order which limited reopening of record to evidence re-staff analysis of site alternative Certificate of Svc encl PFEFFERKORN, W Pfefferkorn & Cooley, P A 80/08/29 48pp
- 8009050297 Forwards notice of appeal & brisf Requests oral argument on issues
 SPRINGER, D Affiliation Unknown 80/09/02 1p
- -8007050300 Notice of appeal from ASLB order denying appellant 800413 motion NRC misrepresented to ASLB state position re availability of once-through-cooling No consideration given to alternative sites SPRINDER, D Affiliation Unknown 80/09/02 Zpp

- --B039050303 Brief of D Springer in support of 800415 petition to hear oral argument re opposition to location of facilities No consideration given to how energy, water & financial resources can be conserved Certificate of Svc encl SPRINGER,D Affiliation Unknown 80/09/02 7pp
- 8009050437 Notice of reconstitution of ASLAB in proceeding AS Rosenthal assigned chalman, JR Buck & TS Moore members
 BISHOP, C J Atomic Safety and Licensing Appeal Panel 60/09/02
- 8009160176 Motion for extension until 800930 to respond to A Springer appeal from ASLB 800814 denial of 800419 petition to intervene Parties including A Springer have no objection to such extension Certificate of Svc encl BARTH, C A Hearing Branch 3 80/09/12 3pp
- 8009170116 Order granting extension until 800924 for NRC to file brief re D Springer 800902 appeal from ASL9 800814 order denying Intervention BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/09/15
- 8009180537 Order granting extension until 800924 for all parties to file responsive briefs on D Springer appeal BISHOP, C J Atomic Safety and Licensing Appeal Panei 80/09/15
- B009250015 Motion for 30-day extension to file brief re intervenors' H00827 exceptions to ASLB 800222 partial initial decision Counsel invoived in serious family matter Certificate of Svc enci Oranted on 800922 PFEFFERKORN,W Pfefferkorn 3 Cooley, P A 80/09/18 2pp
- BOO9260251 Responsive brief in opposition to D Springer 800902 notice of appeal & brief from ASLB BOO814 order denying petition to intervene Urges affirmation of order due to unjustified late intervention Certificato of Svc enc1
 BARTH.C A Hearing Branch 3 80/09/24 27pp
- BCO9290028 Responsive brief in opposition to D Springer B00902 notice of appeal from ASLB B00B14 order denying petition to intervene Urges affirmation of order due to unjustifiable late intervention Certificate of Bvc enci
- Q Inspection reports, iE Builetins & correspondence
- 8009020211 Submits response to IE Bulietin 79-03A No BA-312 or A-312, Type 300 series fusion welded pipe in use or planned for use is subj to design stressos greater than 85% of ASME code allowable stresses
 DAIL.L C Dute Power Co 80/08/04 lp
- 8009020139 Responds to iE Bulietin 80-20, Failure of Westinghouse Type W-2 Spring Return to Neutral Control Switches "Review showed no Wostinghouse Type W-2 switchos used in safety-related applications
 DAIL.L C Duke Power Co 80/08/14 ip
- 8009030137 Forwards Revision i to IE Bulletin 80-19, "Failures of Harcury-Wetted Matrix Relags in Reactor Piotective Sys of Operating Nuclear Powor Piants Designed by C-E " Written response required O'REILLY, J P Region 2, Atianta, Office of the Director 80/08/15 to
- B007160133 Forwards IE Circular 80-18, "10CFR50 57 Safety Evaluations for Changes to Radwaste Treatment Bys " No written response required O'REILLY, J P Region, 2, Atlanta, Office of the Director 80/08/22
- 8009120576 Responds to IE Builetin 80~16 No Rosemount Models 1151 & 1152 pressure transmitters are used in safety-related applications
 DAILL C Duke Power Co 80/08/26 Ip
- 8009:20300 Forwards IE Info Notice 80-3:, "Maloperation of Gould-Brown Bover! 480 Volt Tupe K-6008 & K-DDN 6008 Circuit Breakers " No written response required G'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/08/27
- 8009120212 Responds to IE Bulletin 80-19. Revision 1 No mercury-wetted matrix relays are used or planned for use in reactor protection sys
 DAILL C Dute Power Co 80/08/29 ip

- 8009290293 Forwards IE Circular 80-21," Regulation of Refueling Crews "
 No written response required
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/10
 550
- DOCKET STN-50-489 PERKING NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Cornents requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 enti M/o NUREG EISENHUT, D G Division of Licensing 80/08/01 | 119pp
- O Adjudicatory correspondence
- 8009030696 Notice of appeal from ASLB 800222 partial initial decision re-alternative sites Seeks exceptions re-ASLB 780717 order which iimited reopening of record to evidence re-staff analysis of site alternative Certificate of Svc encl PFEFFERKORN.W Pfefferkorn & Cooley, P A 80/08/29 48pp
- 8009050297 Forwards notice of appeal & brief Requests oral argument on issues SPRINGER, D. Affiliation Unknown 80/09/02 ip
- --8009050300 Notice of appeal from ASLB order denying appaliant 800415 motion NRC misrepresented to ASLB state position re availability of once-through-cooling No consideration given to alternative sites
 SPRINGER.D Affiliation Unknown 80/09/02 2pp
- --8009050303 Brief of D Springer in support of 800415 petition to hear oral argument re opposition to location of facilities No consideration given to how energy, water & financial resources can be conserved Certificate of Svc encl SPRINGER.D Affiliation Unknown 80/09/02 7pp
- 8009050437 Notice of reconstitution or ASLAB in proceeding AS Rosenthai assigned chairman, Jil Buck & 18 Moore members
 BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/09/02
 In
- B009160176 Motion for extension until B00930 to respond to A Springer appeal from ASLB B00814 denial of B00415 petition to intervene Parties including A Springer have no objection to such extension Certificate of Bvc encl
 BARTH.C A Hearing Branch 3 80/09/12 3pp
- 8009170ii6 Order granting extension until 800924 for NRC to file brief re D Springer 800902 appeal from ASLB 800814 order denying intervention BISHDP.C J Atomic Safety and Licensing Appeal Panel 80/09/15
- 8009180537 Order granting extension until 800924 for all parties to file responsive briefs on D Springer appeal BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/09/15 ip
- 80092500i5 Motion for 30-day extension to file brief re Intervenors' 800929 exceptions to ASLB 800222 partial initial decision Counsel involved in serious family matter Certificate of 8vc encl Granted on 800922 PFEFFERKORN, W Pfefferkorn & Cooley, P A 80/09/19 2pp
- 800926025i Responsive brief in apposition to D Springer 800902 notice of appeal & brief from ASLB 800814 order denying petition to interveno Urges affirmation of order due to unjustified late intervention Certificate of Svc encl
 BARTH.C A Hearing Branch 3 80/09/24 27pp
- 8009293028 Responsive brief in opposition to D Springer 800902 notice of appeal from ASLB 800814 order denying petition to intervene Urges affirmation of order due to unjustifiable iate intervention Certificate of Svc enci MCGARRY, J M. PERTER, M. L. Dute Power Co MCGARRY, J M. Debavoise & Liberman 80/09/24 18pp
- Q inspection reports, IE Bulletins & carrespondence
- 8009020211 Submits response to 1E Bulletin 79-03A No 8A-312 or A-312, Type 300 series fusion welded pipe in use or planned for use is subj to design stresses greater than 85% of ASME code allowable stresses BAILL C. Dute Power Co 80/08/06 ip

- E009020139 Responds to IE Bullatin 80-20. Failure of Westinghouse Type M-2 Spring Return to Neutral Control Switches " Review showed no Mestinghouse Type W-2 switches used in safety-related applications
 DAILL C Duke Power Co 80/08/14 1p
- 8009030137 Forwards Revision I to IE Bulletin 80-19, "Fallures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/15
- 8009160133 Forwards IE Circular 80-18. "10CFRSO 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/22
- 8009120576 Responds to IE Bulletin 80-16 No Rosemount Hodels 1151 & 1152 pressure transmitters are used in safety-related applications
 DAILL C Duke Power Co 80/08/26 ip
- 8009120300 Forwards IE Info Notice 80-3i, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DDN 6008 Circuit Breakers "
 No written response raquired O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/27
- 8009120212 Responds to 1E Bulletin 80-17.Revision 1 No mercury-wetted matrix ralays are used or planned for use in reactor protection sys
 DAIL.L. C. Dute Power Co. 80/08/29 ip
- 009290293 Forwards IE Circular 80-21, "Regulation of Refueling Crows "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/10
- DCCKET STM-50-490 PERKINS NUCLEAR STATION. UNIT 3

 G Adjudicatory correspondence
- 8007030596 Notice of appeal from ASLB 800222 partial initial decision re-alternative sites Seeks exceptions re-ASLB 780717 order which limited reopening of record to evidence re-staff analysis of site alternative Certificate of Svc encl PFEFFERKORN, W. Pfefferkorn & Cooley, P.A. 80/08/29 48pp
 - NO9050297 Forwards notice of appeal & brief Requests oral argument on issues

 SPRINGER, D Affiliation Unknown 80/09/02 1p
 - 8009050300 Notice of appeal from ASLB order denying appellant 800415 motion NRC misrepresented to ASLB state position re availability of once-through-cooling No consideration given to alternative sites SPRINGER.D Affiliation Unknown 80/09/02 2pp
- -6009050003 Brief of D Springer in support of 800415 potition to hear dral argument re opposition to location of facilities No consideration given to how emergy, water & financial resources can be conserved Certificate of Svc encl SPRINGER, D Affiliation Unknown 80/09/02 7pp
- CO905D437 Notice of reconstitution of ASLAB in proceeding AB Rosenthal assigned chairman, JH Buck & TS Moore members
 BISHOP, C J Atomic Safety and Licensing Appeal Panel. 80/09/02
- B009160176 Motion for extension until B00930 to respond to A Springer appeal from ASLS 800814 denial of 800415 petition to intervene Parties including A Springer have no objection to such extension Certificate of Svc encl
- 8009170116 Order granting extension until 800924 for NRC to file brief re D Springer 800902 appeal from ASLB 800814 order denying intervention BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/09/15 2pp
- 6009190537 Order granting extension until 800924 for all parties to file responsive briefs on D Springer appeal BISHDP.6 J Atomic Safety and Licensing Appeal Panel 80/09/15

- 80092900i5 Motion for 30-day extension to file brief re intervenors' 800929 exceptions to ASLB 800222 partial initial decision Counsel involved in serious family matter Certificate of Svc encl Granted on 800922 PFEFFERKORN, W Pfefferkorn & Cooley, P A 80/09/18 2pp
- 8009260251 Responsive brief in opposition to D Springer 800902 notice or appeal & brief from ASLB 800814 order denying petition to intervene Urges affirmation of order due to unjustified late intervention Certificate of Svc encl BARTH.C A Hearing Branch 3 80/09/24 27pp
- 8007293028 Responsive brief in opposition to D Springer 800902 notice of agreal from ASLB 800814 order denying petition to intervene Urges affirmation of order duo to unjustifiable late intervention Certificate of Svc uncl MCGARRY. J M , PORTER M L Duke Power Co MCGARRY. J M Debevoise & Libermen 80/09/24 18pp
- Q Inspection reports, IE Bulletins & correspondence
- 8007020211 Submits response to IE Bulletin 77-03A No SA-312 or A-312. Type 300 serios fusion welded pipe in use or planned for use is subj to design stresses greater than 85% of ASME code allowable stresses

 DAIL.L C Duke Power Co 80/08/06 ip
- 8009020139 Responds to IE Bulletin 80-20, Failure of Westinghouse Type W-2 Spring Return to Neutral Control Switches, "Review showed no Nestinghouse Type W-2 switches used in safety-related applications
 DAIL, L C Duke Power Co 80/08/14 1p
- 8009030137 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY. J P Region 2, Atlanta, Office of the Director 80/08/15
- G009160133 Forwards IE Circular 80-18, "IOCFR50 59 Bafety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22
- 8009120574 Responds to IE Bulletin 80~16 No Rosemount Models 1151 & 1152 pressure transmitters are used in safety-related applications DAILL C Duke Power Co 80/08/26 lp
- 8009120300 Forwards IE Info Notice 80-31; "Maloperation of Gould-Brown Boveri 480 Volt Type K-6003 & K-DDN 6008 Circuit Breakers" No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/27
- 8009120212 Responds to IE Bulletin 80-19. Revision 1 No mercury-wetted matrix relays are used or planned for use in reactor protection sys. DAIL.L C Dute Power Co 80/08/29 1p
- 8009290293 Forwards IE Circular 80-21," Regulation of Refueling Crews Town written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/07/10
- DDCKET STN-50-491 CHEROKEE NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREO-0696, "Functional Critaria for Energancy Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0596 encl W/o NUREO EISENMUT, D 0 Division of Licensing 80/08/01 119pp
- 8009090037 Submits interim actions for plant operation, pending final resolution of ATMS Emergency operation procedural review may include NRC site visit prior to issuance of GL TEDESCO.R L Assistant Director for Licensing 80/08/27 3pp
- G Inspection reports, IE Bulletins & correspondence
- 8007020211 Submits response to IE Bulletin 79-03A No SA-312 or A-312.
 Type 300 series fusion welded pipe in use or planned for use is subj to design stresses greater than 85% of ASME code allowable stresses
 DAIL.L C Duke Power Co 80/08/06 ip

- 8009020139 Responds to IE Bulletin 80-20. Failure of Westinghouse Type W-2 Spring Return to Neutral Control Switches " Review showed no Westinghouse Type W-2 switches used in safety-related applications Duke Power Co 80/08/14 to DAN . I C
- 8009030137 Forwards Revision 1 to 1E Sulletin 80-19. "Failures of Marcury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written Region 2, Atlanta, Office of the Director 80/08/15
- 8609160133 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/22
- 8009120576 Responds to IE Bulletin 80-16 No Rosemount Models 1151 & 1152 pressure transmitters are used in safety-related applications Duke Power Co B0/08/26 ip
- 8009120300 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Bovers 480 Voit Type K-6005 & K-DON 6008 Circuit Breakers " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/27
- 8009120212 Responds to IE Bulletin 80-19 Revision 1 No mercury-wetted matrix relays are used or planned for use in reactor protection sys DALL_L C Duke Power Co 80/08/27 1p
- 8009290293 Forwards IE Circular 80-21." Regulation of Refueling Crews " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/10 Spp

DOCKET STN-50-492 CHEROKEE NUCLEAR STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8009080080 Farwards draft NURFO-0696, "Functional Criteria for JOYUGUGU FORWARDS OF TERMINED-10076. "FUNCTIONAL CRITERIA FOR EMERGENCY Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/o NUREO EISENHUT.D O Division of Licensing 80/08/01 119pp
- 8009090037 Bubmits interim actions for plant operation, pending final resolution of ATMB Emergency operation procedural review may include NRC site visit prior to issuance of OL TEDESCO, R L Assistant Director for Licensing 80/08/29 Jpp
- Q Inspection reports, IE Builetins & correspondence
- 8007020211 Submits response to IE Builetin 79-03A No 8A-312 or A-312. Type 300 series feeponse to le bulletin /7-03x to BA-32 or Type 300 series feusion welded pipe in use or pianned for use is subj to design stresses greater than 85% of ASME code allowable stresses DAIL/L C Dukw Power Co 80/08/06 ip
- 8007020139 Responds to IE Bulletin 80-20, Failure of Westinghouse Type W-2 Spring Return to Neutral Control Switches " Review showed no Westinghouse Type W-2 switches used in safety-related applications

 DAIL, L C Duke Power Co 89/08/14 lp
- 9009030137 Forwards Revision 1 to IE Bulletin 80-19. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required.

 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08 80/08/15
- 8009160133 Forwards 1E Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwasto Treatment Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22
- 8009120576 Responds to IE Bulletin 80-16 No Rosemount Models 1151 & 1152 pressure transmitters are used in safety-related applications Duke Power Co 80/08/26 ip DAIL L C

- 8009120390 Forwards IE Info Notice 80-31. 'Maloperation of Guuld-Brown Bover: 480 Volt Type K-6005 & K-DON 6008 Circuit Breakers " No written response required G'REILLY.J P Region 2. Atlanta, Office of the Director 80/08/27 10
- 8009120212 Responds to 1E Bulletin 80-19, Revision 1 No mercury-wetted matrix relays are used or planned for use in reactor protection sys
 DAIL-L C Duke Power Co 80/08/29 1p
- 8009290293 Forwards IF Circular 80-21, ' Regulation of Refueling Crews " No written response required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/09/i0
- DOCKET STN-50-493 CHEROKEE NUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREO-0496, "Functional Criteria for Connents requested within 30 Emergency Response Facilities days Proposed Implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT, D G Division of Licensing BO/OB/OI 119pp
- 8009090037 Submits interim actions for plant operation, pending final resolution of ATMS Emergency operation procedural review may include NRC site visit prior to issuance of GL TEDESCO.R L Assistant Director for Licensing 80/08/29 3pp
- G inspection reports, 1E Bulletins & correspondence
- 8009020211 Submits response to 18 Bulletin 77-03A No 5A-312 or A-312. Type 300 series fusion weided pipe in use or planned for use is subj to design stresses greater than 85% of ASME code allowable stresses DAIL.L C Dute Power Co 80/08/06
- 8009020139 Responds to IE Duiletin 80-20. Failure of Westinghouse Type W-2 Spring Return to Neutral Control Switches " Review showed no Westinghouse Type W-2 switches used in safety-related applications
 DAIL.L C Duke Power Co 80/08/14 ip
- 8009030137 Forwards Revision 1 to 1E Bulletin 80-19. "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Re Region 2. Atlanta, Office of the Director 80/08/15
- 8009160133 Forwards IE Circular 80-18, "IOCFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/22
- 8009120576 Responds to 1E Bulletin 80-16 No Rosemount Models 1151 & 1152 pressure transmitters are used in safety-related applications Duke Power Co 80/08/26 DAIL L C
- 8009120300 Forwards 1E Info Notice 80-31, "Maluperation of Could-Brown Bover1 480 Volt Type K-6005 & K-DON 6008 Circuit Breakers " No written response required O'REILLV, J P Region 2, Atlanta, Office of the Director 80/08/27
- 8009120212 Responds to IE Builetin 80-19,Revision 1 No mercury-wetted matrix relays are used or planned for use in reactor protection sys
 DAIL.L.C Duke Power Co 80/08/29
- 8009290293 Forwards IE Circular 80-21, " Regulation of Refueling Crews " No written response required
 D'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/09/10 500
- DOCKET STN-50-498 SOUTH TEXAS PROJECT, UNIT 1
- A Application/construction stage documents & correspondence
- 8007090080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 entl W/o NUREG EISENHUT, D @ Division of Lacensing 80/08/01 119pp Comments requested within 30

- 8009030272 Forwards request for additinfoire instrumentation & control sys in order to complete evaluation of facility FSAR TEDESCO.R L. Assistant Director for Licensing 80/08/15 9pp
- 8007080201 Forwards info & response to NRC questions re Category I masonry calls Fifty-four eversize drawings available in Central Files only OPREA.0 U Houston Lighting 3 Power Co 80/09/04 8pp
- f Security, medical, emergency & fire protection plans
- 8007020147 Invites participation in 800822 workshop in Atlanta, 6A to solicit comment is proposed functional criteria for emergency response facilities in NUREO-0696 Discussion to include location.size 6 staffing of emergency thrs SEYFRIT.K V Region 4. Dallas, Office of the Director 80/08/12 to
- G Adjudicatory correspondence
- 8009050361 Requests extension until 801001 to respond to order to show cause. Item 7 re design change control program

 OPREA.G W Houston Lighting & Power Co 80/08/28 3pp
- 8009040241 Forwards recently promulgated amends to emergency planning regulations DN Boudenick is lead counsel per encl notice of appearance RL Black backup counsel MAC encls
 BORDERICK, BM Hearing Branch 4 80/09/02 2pp
- 8009110359 Confirms conversation re objection & intent not to respond to util 800825 interrogatories & document requests Factual discovery closed sinte 800314 Interrogatories are ill-timed as efforts have been made to encourage settlement STAHL. D M. Isham, Lincoln & Beale 80/09/08 1p
- 100917036f Submits status of rept on settlement negotiations on behalf of TX-LA Electric Cooperative of TX. Inc No unresolved issues exist at present Certificate of Svc encl BUNCHETTE, W.H. Northoutt Ely 80/09/11 3pp
- 8007250042 Memorandum & order, CLI-80-32, denying Citizens Concerned About Nuclear Power & Citizens for Equitable Utils request for hearing on IC 800430 order to show cause re deferral of safety-related const until completion of mods Waddi views CHILK, S. J. Office of the Secretary of the Commission 80/09/22 2pp
- 8005250045 Addendum to Commission 800522 memorandum & order.CLI-80-32 Footnate re ALAB-594 was omitted from JF Ahearne separate views CHILK.S J Office of the Secretary of the Commission 80/09/22 in
- 09250020 Advises that parties may contact BM Bordenick if desiring to borrow 800817 public meeting transcript for review purposes JORDENICK, B II Hearing Branch 4 80/09/23 lp
- 1009300030 Memorandum & order advising parties to agree on contentions reflecting NRC 800430 show cause order.CL1-80-32, but not within 0A/OC Contentions 1 & 2 Rept on issues must be filed by 801015 & Identification of add! discovery by 801201 DECHROEFER.C Atomic Safety and Licensing Board Panel 80/09/24
- (General correspondence
- 8009020108 Responds to 800808 ltr Advises that heat-induced illness being watched closely at plants Const has progressed to point that most work being done indoors Applicants have taken steps to improve working conditions by adding fans DENTON. HR Office of Nuclear Reacto: Regulation, Director 80/08/12 1p
- --8007020112 Informs that TX experiencing severe heat wave Requests that const on nuclear reactors be halted until temp at normal level for season Numaily impossible for const workers to do excellent work required LEVINE, If B Affiliation Unknown 80/07/08 ip
- K Utility Final Safety Analysis Report (FSAR) & amends
- GOC9150559 Forwards Amend 12 to FSAR
 OPREA, 0 N Houston Lighting 8 Power Co 80/09/15 5pp
- --8009150561 Amend 12 to FSAR * Houston Lighting & Power Co 80/09/15 140pp

- 8007250051 Centifies svc of Amend 12 to FSAR, an 800915 * Hauston Lighting & Power Co 80/09/15 2pp
- M Antitrust correspondence
- 8009040196 Response to applicants.Central & South West Corp & City of Austin.TC objections to TX Border Cooperative petition to intervene Asserts interests under LBP-74-13 Urges full party participation W/Certificate of Sur
- 8009020282 Requests that info be provided to all parties re wheeling rate development per 800826 discussions Discusses principles to be considered re smaller util participation in facility ownership SPIEGEL. O Spiegel & McDiarmid SPIEGEL. O Brownsville. TX 80/08/28 4pp
- 8009030721 Advises that appropriate steps have been taken to insure svc of status repts & pleadings CHANAMIA, F.D. Antitrust Division 80/08/29 ip
- 8009040289 Joint motion for partial revision of ASLB 800813 order re procedural schedule Suggests 800912 for settlement status repts.800915 for prehearing conference y 801112 for evidentiary hearing commencement Certificate of Svc encl CHANANIA, F.D. Antitrust Division FLYNN, P.G. Houston Lighting & Power Co. FABRIKANT, R. Justice, Dept of 80/08/29 7pp
- 8009090483 Forwards typescript version of intervenor Utils Board of City of Brownsville.TX 800829 proposed modified license conditions POIRIER.K R Spiegel & McDiarmid 80/09/03 10pp
- 8007100261 Designates WA Russell of WA Russel & Associates as expert engineering witness which DOJ may call at trial of facility licensing proceeding MCMILLEN,N H Justice.Dept of 8D/09/03 1p
- 8009110792 Order revising procedural schedule set in ASLB 800813 order Settlement status rept shall be submitted on 800912, prehearing conference shall commence on 800913, trial briefs on 801008 & 22 & evidentiary hearing on 801112 MILLER, N & Atomic Safety and Licensing Board Panel 80/09/08
- 8009150417 Motion to compel Central Power & Light response to 800829 interrogatories Objection erroneous due to necessity to know full scope of take-over plans W/DM Stohl 800908 ltr. excerpts of util corrected discovery & Certificate of 8vc SPIEGEL, G , POIRIER, M R Brownsville, TX SPIEGEL, G Spiegel & McDiarmid 60/09/ii 23pp
- 8009160332 Notifies that City of Austin has reached tentative agreement to settle w/NRC & DOJ re proposed license conditions Settlement contingent on final wording of draft document. Final version projected for 800915 BALDUGH, R C Texas, State of 80/09/11 2pp
- 8009160275 Notice of taking WP Sayles & T Russell of CP&L 800923 & 24 depositions Examination will address possible purchase of Brownsville electric util sys & related studies & issuance of bonds Certificate of Svc encl POIRIER, M R Spiegel & McDiarmid 80/09/12 7pp
- B009170188 Settlement status rept Author approval of terms of stipulated licensing conditions not yet given No position on issues & procedures presented Certificate of Svc encl JOHN D F , HUMTER/M South Texas Electric Cooperative JOHN D F Medinaelectric Cooperative, Inc. 80/09/12, 5pp
- 8009170359 Settlement status rept per ASLB 800813 order Agreement reached by util NRC & DOJ which will dispose of all Comanche Peak Issues when approved by ASLB Enci stspulation wiil insure DL would not violate antitrust laws SAMPLES, M D , KNDYTS, J B Texas Utilities Generating Co SAMPLES, M D Worsham, Forsythe & Sampels, 80/09/12 2pp
- 8009170229 Fourth settlement status rept Stipulations w/applicants embodying two sets of license conditions accomplished Final position re need for hearing will be submitted after examination of conditions by parties W/Certificate of Svc. CHANANIA, F.D. Antitrust Division 80/09/14 7pp
- --B009170239 Btipulation incorporating encl license condition w/o admission of violation to Antitrust laws FABRIKANT,R Justice,Dept of CHAMANIA,F D Antitrust Division STAHL,D M Central & South West Corp B0/09/12 20pp

- E009160157 Settlement status rept per ASLB 800813 order Endorses and stipulation re license conditions reached by DOJ.NRC.FERC & Houston Lighting & Power Resolves concerns evidencing intent to litigate DOE endorsed settlement entirely in FERC case COPELAND, J G Houston Lighting & Power Co COPELAND, J G Baker & Botts 80/09/15 2pp
- --B009160160 Stipulation incorporating license conditions Licensee past or planned action w/o conditions not inconsistent w/ antitrust laws Conditions do not constitute admission or violations Certificate of Svc encl FARRIKANT, R Justice Dept of CHANANIA, F D Antitrust Division STAHL. D Houston Lighting & Power Co 80/09/15 17pp
- 8009160182 Settlement status rept per ASLB 80813 order Requests unspecified extension to receive 5 review new arguments 5 to determine 5 submit unresolved issues License conditions 6 settlement re FERC not yet received W/Certificate of Svr POIRIER.H R Brownsville.TX POIRIER.H R Spiegel & McDiarmid 900
- 8009170177 Settlement status rept Suggests approval of stipulated license conditions to maintain situation consistent w/ antitrust laws FERC & SEC approval of dc interconnections necessary for settlement execution Certificate of Svc encl STAHL.D M Central & South West Corp STAHL.D M Isham, Lincoln & Beale 80/09/15 12pp
- BOO91BO460 Buppl status rept per ASLB BOO813 order DOJ reached Agreement u/partles in Comanche Peak proceedings re proposed set of license conditions Agreement reached u/applicant in South TX proceeding Certificate of Svc
- 8009250028 Order granting extension until 800929 for Commission to review ALAB-608 CHILK, S J Office of the Secretary of the Commission 80/09/22
- 8009260318 Hotion for one-day extension to file comments on proposed settlement conditions Last minuto consultations & discussions needed Certificate of Svc encl PDIRIER.H R Brownsville.TX PDIRIER.H R Spiegel & McDiermid 6pp
- 8009300035 Comments on proposed settlements per ASLB 800915 directive Proposed license conditions will serve to preclude or limit consideration of competitive implications of do ties by FERC Certificate of Svc encl 0'NEIL.R A Southwest Texas Electric Cooperative 0'NEIL.R A Miller.Balis & 0'Neil 80/09/24 12pp
- B007300488 Confirms that JR Choukes-Bradley was authorized to express position of Miller.Balis & O'Neil.P C on behalf of TX Border Cooperatives at 800715 status hearing re leave to intervene out of time O'NEIL.R A Miller.Balis & O'Neil 80/09/24 2pp
- --8007300476 Comments of TX Border Cooperatives on proposed settlements of NRC & DOJ re licensing proceedings Certificate of Svc enct O'MEIL,R A Miller,Balis & O'Neil O'NEIL,R A Texas Border Cooperatives BO/09/24 10pp
- 8009300013 Notion in opposition to 800912 proposed license conditions due to failure to address crucial issues re effects of ac & dc interconnoctions Urges further proceedings to cure inconsistency w/antitrust laws Certificate of Svc encl SPIEGEL.G , JABLON,R A , ROTH,A J Brownsville,TX: 80/09/25 32p; 80/09/25 32pp
- 8009300326 Order granting extension until 800925 for all parties to comment on 800918 stipulation & licensing conditions WOLFE,B J Atomic Safety and Licensing Board Panel 80/09/25 lp
- 8009300833 Comments on stipulation & proposed license conditions
 Recommends approval although solution to all antitrust
 problems is not guaranteed through incorporation of
 conditions Reserves right to be full party if hearing held
 UNIN.D F South lexas Electric Cooperative JOHN.D F
 Hedinaelectric Cooperative, inc JOHN.D F McDermott, Will & Emery
 80/09/25 2pp
- --B009300542 Motion for one-day extension to comment on stipulation & proposed license conditions Ratification at Board of Directors 800935 meeting needed Certificate of Svc encl JOHN, D F. South Texas Electric Cooperative JOHN, D F Medinaelectric Cooperative, Inc. JOHN, D F McDermott, Will & Emery Medinaelectric Cooperative.Inc 80/09/24 App

N Antitrust hearing transcripts

- 8009190764 Transcript of 800915 prehearing conference in Bethesda, MD Pp 1078-1138

 * Atomic Safety and Licensing Board Panel 80/09/15 64pp
- 9 Inspection reports, 1E Bulletins & correspondence
- 8009050525 Forwards IE losp Repts 50-498/80-17 & 50-499/80-17 on 800623-26 No noncompliance noted SEIDLE:N C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/07/16 2pp
- --8007050533 IE Insp Repts 50-498/80-17 & 50-499/80-17 on 800623-26
 No noncompliance noted Major areas inspected const
 activities including observation of work & review of records
 pertaining to IE insp Repts 50-498/79-19 & 50-499/79-19
 HALL.R E Region 3. Chicago, Reactor Construction & Engineering
 Support Branch TAPIA, J I. CHAUDHARY, S K. Region 3. Chicago,
 Office of the Director 80/07/16 7pp
- 8009170380 Forwards IE Insp Repts 50-499/80-16 & 50-499/80-16 during June 1980 No noncompliance noted SEIDLE,N C Region 4, Dallas, Reactor Construction & Engineering Support Branch B0/07/16 2pp
- --8009170385 IE Insp Repts 50-498/80-16 & 50-499/80-16 during June 1980 No noncompliance noted Major areas inspected insp of safety-related components.containment structural steel welding.OA records sys & mgt meetings CROSSMAN.W A , PHILLIPS.H S Region 4. Dallas, Office of the Director 80/07/16 5pp
- 8009180467 Submits response to 1E Bulletin 80-08 Plant contains flued head penetration design w/containment boundary butt welds between penetration sleeve & process piping Penetration welds radiagraphically examined GPREA.G W Houston Lighting & Power Co 90/08/04 7pp
- 8009180473 Confirms understanding to IE Bulletin 79-03A Pipe stress evaluation will be limited to calculations concerned w/pressure BARKER,D G Houston Lighting & Power Co 80/08/05 1p
- G009180461 Submits response to LE Bulletin 79-03A Desired info should be available for submittal by B01030 OPREA.0 W Houston Lighting & Power Co 80/08/06 2pp
- 8009250402 Forwards IE Insp Repts 50-498/80-19 & 90-499/80-19 on BOO722-24 No noncompliance noted SEIDLE N C Region 4. Dallas, Reactor Construction & Engineering Support Branch BO/08/08 2pp
- --8009250405 IE Insp Repts 50-498/80-19 & 50-499/80-19 on 800722-24 No noncompliance noted Major areas inspected records re IE lnsp Repts 50-498/79-19 & 50-499/79-19 findings on earthwork & concrete HALLER E. TAPIA.J 1 Region 4, Dallas, Reactor Construction & Engineering Support Branch CROSSMAN, W.A. Region 4, Dallas, Office of the Director 80/08/08 Spp
- 8007030159 Ack receipt of 800722 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-498/77-03 & 50-499/77-03 SEIDLE:N C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/08/14 ip
- --B009030170 Responds to NRC ltr re violations noted in IE Insp Repts 50-498/77-03 & 50-499/77-03 Corrective actions sys of reviews & multitlered supervision implemented OPREA G W Haustan Lighting & Power Go 80/07/22 2pp
- 800903024B Forwards Revision 5 to IE Bulletin BD-19, "Failures of Mercury-Wetted Matrix Relays' in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Uritten response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/08/15
- 8007300098 Forwards IE Insp Repts 50-478/80-20 & 50-479/80-20 on 800728-29 No noncompliance noted SEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/08/18 2pp
- --8009300102 IE Insp Repts 50-498/80-20 & 50-499/80-20 on 800728-29
 No noncompliance noted Hajor areas inspected issuance & disposition of nonconformance repts
 YOMLINSON,D P , HALL,R E Region 4, Dallas, Reactor Construction & Engineering Support Dranch CROSSMAN,W A Region 4, Dallas, Office of the Director 80/08/12 3pp

- 8009170394 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required SEYFRIT,K V Region 4, Dallas, Office or the Director 80/08/22
- 8009300545 Submits response to IE Bulletin 80-16 Rosemount Model 1151 or 1152 pressure transmitters will not be used in any safety-related applications OPREA.6 N Houston Lighting 2 Power Co 80/08/22 2pp
- 8009300555 Submits response to IE Bulletin 80-19 Mercury-wetted relays are not used in reactor protection sys OPREA.G W Houston Lighting & Power Co 80/08/26 2pp
- 8009[20423 Forwards If Info Notice 80-31, "Maloperation of Gould-Brown Bover1 480 Volt Type K-6005 & K-DON 6005 Circuit Breakers"

 No written response required SEYFRIF,K V Region 4, Dallas, Office of the Director 80/08/27
- 8009300536 Submits response to 1E Bulletin 80-20 Westinghouse Type W-2 control switches are not used in safety-related applications OPREA,0 & Houston Lighting & Power Co 80/09/09 2pp
- S Reportable occurrences. LERs & related correspondence
- 8009180479 Interim deficiency rept re breakdown im quality program for concrete placement, Evaluation will be conducted in conjunction w/response to show cause order Item 3(b) Next rept will be submitted 800905

 OPREA, G W Hauston Lighting & Power Co 80/08/01 4pp
- 8009190147 Interim deficiency rept re broten tie-down studs for reactur bidg polar crane rail sys Brown & Root continuing to evaluate as-built conditions Stud failure not caused by inadequate design Next rept due by 800917 OPREA,G W Houston Lighting & Power Co 80/08/01 4pp
- 8009020288 Final deficiency rept re 800717 safety injection sys piping Submits addl info re disposition of seal weld between process pipe & emergency sump lines por 800717 request Recirculation valve end loads within stress limit OPREA.G W. Houston Lighting & Power Co. 80/08/22 7pp
- BOO9020290 Second interim deficiency rept re matl control of ASTM A-325 structural steel bolts Documentation for installed bolts in Category 1 applications being identified & located & partial release in Stop Mork S-22 issued OPREA.0 N Houston Lighting & Power Co 80/08/22 4pp
- 009040377 Interim deficiency rept re stud welding on concrete embedments Preliminary evaluation showed that 0 02% of welds were rejectable Status rept will be submitted by 801007 OPREAG N Houston Lighting & Power Co 80/08/28 Jpp
- 3009110384 Final deficiency rept re diesel generator fuel oi, tank room exhaust fans Hold on engineering drawings will be lifted upon procurement of qualified IE motors

 UPREA.G W Houston Lighting & Power Co 80/09/03 5pp
- 3009110367 Final deficiency rept re breakdown in quality program for concrete placement CII-W90 Addl QC inspectors have been added to assure that preplacement insps are conducted thoroughly Placement lighting has been added to checklist QPREA-Q W Houston Lighting 3 Power Co 80/09/04 12pp
- 1009230603 Third interim deficiency rept re rejectable indications for welds which had been previously accepted Cause not stated Re-examination & repair program for essential cooling water sys will be performed Progress rept by 801215

 OPREA,O W Houston Lighting & Power Co 80/09/12 4pp
- 009230&17 Second interim deficiency re breakdown in quality program for procurement cycle of purchased matls & equipment Cause not stated Brown & Root developing procedures & implementation schedule for performing verification program OPREA, Q W Houston Lighting & Power Co 80/09/12 3pp
- 1009230658 Fourth interim deficiency rept re polar crane rail tie-down stud failure Caused by porosity & lack of complete fusion of stud wolds beviations from design did not significantly contribute to failures Existing studs will be renoved OPREA.0 W Houston Lighting 3 Power Co 80/09/15 App
- 8009240439 Final deficiency rept re spent fuel storage racks Evaluation of condition indicates safety of operations not affected & is not reportable under 10CFR50 55e GPREA, G W Houston Lighting & Power Co 80/09/17 3pg

- 8009230402 Final deficiency rept on motor pump shaft failure in Comsip containment hydrogen monitoring sys Nonconformance rapt has been prepared & hold tags issued against equipment until pump is shipped back to manufacturer Pump will be replaced OPREA.O W Houston Lighting & Power Co 80/09/18 3pp
- 8009300161 Second interim deficiency rept re radiographs w/rejectable indications in previously accepted welds Caused by weld spatter & sharp corners All indications to be repaired & reinspected for final acceptance unless concrete embedded OPREA.G W Houston Lighting & Power Co 60/09/23 App
- 8009300453 Fourth interim deficiency rept re damaged steal liner plate in Unit 2 reactor containment bldg Submits updated repair logic Subcontract change order for repair work negotiated & erecuted Deformed section of plate removed UPREA.G H Houston Lighting & Power Co 80/09/25 5pp
- T Hearing transcripts on non-antitrust matters
- 800926028B Forwards transcript & record of 800819 public meeting refacilities w/util & NRC errata & related documentation STELLO.V Office of Inspection & Enforcement, Office of the Director 80/09/19 4pp
- --8009260290 Transcript of 800819 public meeting re facilities in Bay City.7% Pp 1-379 Util & NRC errata & related documentation & correspondence encl + Office of Inspection & Enforcement. Office of the Director 80/09/19 450pp
- DOCKEY STN-50-499 SOUTH TEXAS PROJECT, UNIT 2

 A Application/construction stage documents & correspondence
- B0070B0080 Forwards draft NUREG-0676, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 enci W/o NUREO EISENHUT, D O Division of Licensing 80/08/01 119pp
- 8009030272 Forwards request for add1 info re instrumentation & control sys in order to complete evaluation of facility FSAR TEDESCO.R L. Assistant Director for Licensing 80/08/15 9pp
- 8007080201 Forwards info & response to NRC questions re Category I masonry unlls fifty-four oversize drawings available in Central Files only OPREA/Q W Houston Lighting & Power Co 80/09/04 Spp
- F Security, medical, emergency & fire protection plans
- 8009020147 Invites participation in 800822 workshop in Atlanta, QA to solicit comment re proposed functional criteria for emergency response Pacilities in NUREQ-0696 Discussion to include location.size & staffing of emergency ctrs SEYFRIT, K V Region 4. Dallas. Office of the Director 80/08/12
- Q Adjudicatory correspondence
- 8009050364 Requests extension until 801001 to respond to order to show cause, Item 7 re design change control program

 OPREA-O W Houston Lighting & Power Co 80/08/28 3pp
- 8007040261 Forwards recently promolgated amends to emergancy planning regulations EM Nordenick is lead counsel per encl notice of appearance Rt. Black backup counsel W/o encls BURDENICK, B M Hearing Branch 4 80/07/02 2pp
- BO09110369 Confirms conversation re objection & Intent not to respond to util B00825 interrogatories & document roquests Factual discovery closed since 800314 Interrogatories are 111-timed as efforts have been made to encourage settlement STAHL,D M Isham, Lincoln & Beale 80/09/08 ip
- 8009170361 Submits status of rept on settlement negotiations, on behalf of TK-LA Electric Cooperative of TX.Inc No unresolved issues exist at present Centificate of Svc encl BURCHETTE, N H Northcutt Ely 80/09/11, 3pp
- BO09230042 Memorandum & order.CLI-80-32, denying Citizens Concerned About Nuclear Power & Citizens for Equitable Utils request for hearting on IE 800430 order to show cause re deferral of safety-related const until completion of mods W/addl views CHILK, S J Office of the Secretary of the Commission 80/09/22 200

- BOO9230045 Addendum to Commission BO0922 memorandum & order, CLI-80-32 Footnote to ALAB-594 was omitted from JF Absarne separate views CHILK, B. J. Office of the Secretary of the Commission B0/09/22
 - CHILK, B, J. Office of the Becretary of the Commission 80/09/22
- 8009250020 Assisss that parties may contact BM Bordenick if desiring to borred 800819 public meeting transcript for review purposes BORDENICKUB M Hearing Branch 4 80/09/23 lp
- 8009300030 Hamorandum & order advising parties to agree on contentions reflecting NRC 800430 show cause order/CLI-80-32, but not within QA/QC Contentions 1 & 2 Rept on issues must be filed by 801015 & identification of addi discovery by 801201 BECHNORPER.C Atomic Safety and Licensing Board Panel 80/09/24 3ps.

- BOOPO20108 Responds to BOOBOB itr Advises that heat-induced illness being watched closely at plants Const has progressed to point that most work being done indoors Applicants have taken steps to improve working conditions by adding fans DENTON-H R Dffice of Nuclear Reactor Regulation, Director BO/OB/12. 19
- K Utility Final Safety Analysis Report (FBAR) & amends
- BCC9150559 Forwards Amend 12 to FSAR

 OPREA, O W Houston Lighting & Power Co 80/09/15 5pp
- --HOO9150561 Amend 12 to FSAR
 * Hauston Lighting & Power Co. 80/09/15 140pp
- 8009250054 Certifies svc of Amend 12 to FSAR. on 800915.

 * Houston Lighting & Power Co 80/09/15 2pp

M. Antitrust correspondence

- BOO9040196 Response to applicants. Central & Booth Hest Corp & City of Austin, TX objections to TX Border Cooperative petition to intervene Asserts interests under LBP-74-13 Urges full party participation MyCertificate of Byc CO'NEIL.R. A Boothwest Texas Electric Cooperative. 80/07/31 16pp.
- 8007020282 Requests that info be provided to all parties re wheeling rate development per 800826 discussions Discusses principles to be considered re smaller util participation in facility ownership SPIEOEL-O. Spiecel & McDiarmid 80/08/28 4pp
- BOO9030721 Advises that appropriate steps have been taken to insure even of status repts & pleadings.

 CHANANIA:F D Antitrust Division 80/08/29, 1p.
- BO09040289 Joint motion for partial revision of ASLB 800813 order re procedural schedule Bugpests 800912 for settlement status repts, 800915 for prehearing conference & 801112 for evidentiary hearing commencement Certificate of Svc encl. CHANANIA, F D Antitrust Division DALOUOH, R C Austin, TX HOOD, J C, San Antonio, TX, 80/08/29 7pp
- 8009090453 Forwards typescript version of intervenor Utils Board of City of Brownsville, TX 800829 proposed modified license conditions.
 POIRIER, H R Spiegel & McDiarmid 80/09/03, 10pp
- BOO9100261 Designates WA Russell of WA Russell & Associates as expert engineering witness which DOJ may call at trial of facility licensing proceeding MCHILLEN.N.H Justice, Dept of 80/09/03 ip
- 8007110772 Order revising procedural schedule set in ABLB 800813 order Bettlement status rept shall be submitted on 800912; prehearing conference shall commence on 800715; trial briefs on 801008 % 22 & evidentiary hearing on 801112; MILLER, K E. Atomic Safety and Licensing Board Panel. 80/07/08 2pp.

- 8007150417 Motion to compel Central Power & Light response to 800825 interrogatories Objection erroneous due to necessity to know full scope of take-over plans W/DM Stoni 800708 itr, stcerpts of util corrected discavery & Certificate of Suc 8PIECEL. G Brownsviiis. TX POIRIER, M R Spiegel & McDiarmid 80/09/11 23ns
- 8009160332 Notifies that City of Austin has reached tentative agreement to settle w/NRC & DOJ re proposed license conditions.

 Settlement contingent on final wording of draft document Final version projected for 800915

 BALOUGH,R C Telas, State of 80/09/11 2pp
- 8009140275 Notice of taking WP Sayles & T Russell of CP&L 800923 & 24 depositions Examination will address possible purchase of Brownsville electric util sys & related studies & issuance of bonds Certificate of Svc enci
- BOD71701BB Settlement status rept Author approval of terms of stipulated licensing conditions not yet given No position on issues & procedures presented Gentificate of Svc encl JOHN.D F Bouth Terms Electric Cooperative JOHN.D F KcDermott, Will & Emery HUNTER, M McGinnis, Lochridge & Kilgore 80/09/12 Spp
- 8009170359 Settlement status rept per ASLB 800813 order Agreement reached by util, NRC & DDJ which will dispose of all Comanche Peak issues when approved by ASLB Encl stipulation will insure DL would not violate antitrust laws SAMPLES,M D. Texas Utilities Denerating Co 80/09/12 2pp
- 8007170227 Fourth settlement status rept Stigulations u/applicants embodying two sets of license conditions accomplished Final position re need for hearing will be submitted after examination of conditions by parties W/Certificate of Svc CHANANIA,F D Antitrust Division 80/09/14 7pp
- --8009170239 Stipulation incorporating encl license condition w/o admission of violation to antitrust laws FABRIKANT.R Justice, Dept of CHANANIA, F. D. Antitrust Division STAHL.D M. Central & Bouth West Corp. 80/09/12 20pp
- 8009140157 Sattlement status rept per ASLB 800813 order Enforses encl stipulation re license conditions reached by DQJ,NRC,FERC & Houston Lighting & Power Resolves concerns evidencing intent to litigate DDE endorsed settlement entirely in FERC case COPELAND, J O Houston Lighting & Power Co 80/09/15 2pp
- 8007i60192 Settlement status rept per ABLB 80Bi3 order Requests unspecified extension to receive & review new arguments & to determine & submit unresolved issues License conditions & settlement re FERC not yet received. W.Gertificate of Svc. POIRIER.M.R. Brownsvilje.TX 80/09/15 7gp,
- B009170177 Bettlement status rept Suggests approval of stipulated license conditions to maintain situation consistent w/ antitrust laws FERC & SEC approval of dc interconnections necessary for settlement execution Certificate of Svc and STAHL, D M Gentral & South West Corp B0/09/15 12pp
- 8009180460 Suppl status rept per ASLB 800813 order.DGJ reached agreement w/parties in Comanche Peak proceedings re proposed set of license conditions.Agreement reached w/applicant in South TX proceeding Certificate of Svc ench MCMILLEN.N H Justice,Dept of S0/09/15 7pp
- 8009250028 Order granting extension until 800929 for Commission to review ALAB-608.
 CHILK, B. J. Office of the Becretary of the Commission. 80/09/22 is
- 8009260318 Motion for one-day extension to file comments on proposed settlement conditions Last minute consultations & discussions needed Certificate of Svc encl POIRIER.H R Brownsville.TX 80/09/24 6pp.
- BO09300035 Comments on proposed settlements per ASLB 800915 directive Proposed license conditions will serve to preciude or limit consideration of competitive implications of ac ties by FERG Cortificate of Box ancl 0'NEIL, R A Southwest Texas Electric Cooperative B0/09/24 12pp

- 8009300488 Confirms that JR Choukas-Bradley was authorized to express position of Miller, Balis & O'Neil, P C on behalf of TX Border Cooperatives at 800915 status hearing re leave to intervene out of time O'NEIL, R A Miller, Balis & O'Neil 80/09/24 2pp
- --B009300496 Comments of TX Border Cooperatives on proposed settlements of NRC & DOJ re licensing proceedings Cartificate of Svc encl
 O'NEIL:R A Miller.Balis & O'Neil B0/09/24 10pp
- 8009300013 Motion in apposition to 800912 proposed license conditions due to failure to address crucial issues re effects of ac & dc interconnections Urges further proceedings to cure inconsistencies w/antitrust laws Certificate of Bvc encl SPIEOEL, O Brownsville, TX 80/09/25 32pp
- 8007300326 Order granting estansion until 800729 for all parties to comment on 800715 stipulation & licenting conditions WOLFE.S J. Atomic Safety and Licenting Board Panel. 80/09/25 1p
- 8009300533 Comments on stipulation & proposed license conditions
 Recommends approval although solution to all antitrust
 problems is not guaranteed through incorporation of
 conditions Reserves right to be full party if hearing held
 JOHN.D F South Texas Electric Cooperative JOHN.D F
 Hedinaelectric Cooperative. Inc JOHN.D F McDermott, Will & Emery
 80/09/25 2pp
- -8009300542 Motion for one-day extension to comment on stipulation & proposed license conditions Ratification at Board of Directors 800925 meeting needed Certificate of Syc encl JOHN, D F South Texas Electric Cooperative JOHN, D F. McDermott, Will & Emery R0/09/24 600
- 1 Antitrust hearing transcripts
- 8009190764 Transcript of 800915 prehearing conference in Bathesda, MD Pp 1078-1138
 - * Atomic Safety and Licensing Board Panel 80/07/15 64pp
- @ Inspection reports, IE Bulletins & correspondence
- 8009090525 Forwards IE Insp Repts 50-498/80-17 & 50-499/80-17 on 800623-26 No noncompliance noted SEIDLE.W C Region A. Dallas: Reactor Construction & Engineering Support Branch 80/07/16 2pp.
 - O09050333 IE Insp Repts 30-498/80-17 & 50-499/80-17 on 800623-26. No noncompliance noted Hajor areas inspected constactivities including observation of work & review of records pertaining to IE Insp Repts 50-498/79-19 & 50-499/79-19 HALL, R & Region 3, Chicago, Reactor Construction & Engineering Gupport Branch TAPIA, J I, CHAUDHARY, 8 K Region 3, Chicago, Office of the Director. 80/07/16 7pp
 - 7170380 Forwards IE lnsp Repts 50-498/80-16 & 50-499/80-16 during the 1980 No noncompliance noted IDLE-M.C. Region 4, Dallas, Reactor Construction & Engineering apport Branch 80/07/16 2pp
 - 009170385 IE Insp Repts 50-498/80-16 & 50-499/80-16 during June 1980 No noncompliance noted Major areas inspected insp of safety-related components, containment structural steel welding, GA records sys & mgt meetings CROSSMAN, W A . PHILLIPS.H B. Region 4, Dallas, Office of the Director 80/07/16 5pp
- 009180467 Submits response to IE Bulletin 80-08 Plant contains flued head penetration design w/containment boundary butt welds between penetration sleeve & process piping Penetration welds radiographically examined OPREA, O W Houston Lighting & Power Co 80/08/04 7pp
- 8009180473 Confirms understanding re IE Bulletin 79-03A Pips stress exploation will be limited to calculations concerned w/pressure BARKER, D Q Houston Lighting & Power Co 80/08/05 ip.
- 3009180461 Bubmits response to IE Bulletin 79-03A Desired info should be available for submittal by 801030 OPSEA.O.W Houston Lighting & Power Co 80/09/06 2pp.
- 1009250402 Forwards IE Insp Repts 50-498/80-19 & 50-499/80-19 on 800722-24 No noncompliance noted BEIDLE,N G Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/08/08. 2pp

- --8009250405 IE Insp Repts 50-498/80-19 & 50-499/80-19 on 800722-24
 No noncompliance noted Major areas inspected records re IE
 Insp Repts 50-498/79-19 & 50-499/79-19 findings on earthwork
 & concrete
 HALL,R E. TAPIA, J I Region 4, Dallas, Reactor Construction &
 Engineering Support Branch CROBEMAN,W A Region 4, Dallas,
 Office of the Director 80/08/08 Spp
- 8007030159 Ack receipt of 800722 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498/77-03 & 90-499/77-03 EEIDLE:N C Region 4, Dallas, Reactor Construction & Engineering Eupport Branch 80/08/14 ip
- --8009030170 Responds to NRC ltr re violations noted in IE Inep Repts 50-498/77-03 & 50-499/77-03 Corrective actions sys of reviews & multitiered supervision implemented OPREA, 0 W Houston Lighting & Power Co 80/07/22 2pp.
- 8007030268 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Welted Matrix Relays in Reactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E " Written response required 6EYFRIT.K V Region 4, Dallas: Office of the Director 80/08/15, ip
- 8009300098 Forwards IE Insp Repts 50-498/80-20 & 50-499/80-20 on 800728-27 No noncompilance noted BEIDLE-W C Region 4, Dellas, Reactor Construction & Engineering Support Branch 80/08/18 2pp
- --8009300102 IE Insp Repts 50-498/80-20 & 50-499/80-20 on 800728-29
 No noncompliance noted Major areas inspected issuance & disposition of nonconformance repts
 TOMLINSON.D.P. HALL,R E Region 4. Dallas, Reactor Construction | Engineering Support Branch CROSSMAN.W. A Region 4. Dallas, Office of the Director 80/08/12 3pp
- 8009170394 Forwards IE Circular 80-18. "10CFR50.59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required SEYFRIT, X. V Region 4. Dalles, Office of the Director 80/08/22 ip
- 8007300545 Submits response to IE Sulletin 80-16 Rosemount Model 1151 or 1152 pressure transmitters will not be used in any safety-related applications
 OPREA,O.W Houston Lighting & Power Co 80/08/22. 2pp.
- 8007300555 Submits response to IE Bulletin 80-19 Mercury-wetted relays are not used in reactor protection sys. OPREA,0, W. Houston Lighting & Power Co. 80/08/26 2pp.
- 8009120423 Forwards IE Info Notice 80-31, "Meloperation of Gould-Brown Bover: 480 Volt Type K-6008 & K-DDN 6008 Circuit Breakers," No written response required.

 SEYFRIT, K V Region 4, Dallas, Office of the Director, 80/08/27.
- BO09300536 Submits response to IE Bulletin 80-20 Westinghouse Type W-2 control switches are not used in safety-related applications

 OPREA: O W Houston Lighting & Power Co 80/09/09, 2pp
- S. Reportable occurrences. LERs & related correspondence
- 8009180479 Interim deficiency rept ra breakdown in quality program for concrete placement Evaluation will be conducted in conjunction w/response to show cause order Item 3(b) Next rept will be submitted 800905.

 DPREA.O W Houston Lighting & Power Co 80/08/01. 4pp.
- BOO9190147 Interim deficiency rept re broken tie-down studs for reactor bldg polar crane rail sys, Brown & Root continuing to evaluate as-built conditions Btud failure not caused by inadequate design Next rept due by BOO917. OPREA.O W Houston Lighting & Power Co 80/08/01 App
- 8007020288 Final deficiency rept re 800717 safety injection sys piping Submits addl info re disposition of seal weld between process pipe & emergency sump lines per 800717 request. Recirculation valve end loads within stress limit OPREA: 0.W Houston Lighting & Power Co 80/08/22 7pp.
- 8009020290 Second interim deficiency rept re meth control of ABTM A-G2: structural steel bolts Documentation for installed bolts in Category 1 applications being identified & located & partial release on Stop Work B-22 issued CPREA.0 W. Houston Lighting & Power Co. 80/08/22. 4pp

- BOO9040377 Interim deficiency rept re stud welding on concrete embedments Preliminary evaluation showed that 0 02% of welds were respectable Btatus rept will be submitted by 801007 DRREAG W Houston Lighting & Power Co 80/08/29 3pp
- 9007110384 Final deficiency rept re diesel generator fuel oil tank room ashaust fams Hold on engineering drewings will be lifted upon procurement of qualified IE motors
 OFREA, OW Houston Lighting & Power Co 80/09/03 5pp
- 9009110367 Finel deficiency rept re breakdown in quelity program for concrete placement CII-M90 Addi QC inspectors have been added to assure that preplacement inspectors conducted theroughly Placement lighting has been edded to checklist OFREA.Q W Houston Lighting & Power Co E0/09/04 12pp
- 8009230603 Third interim deficiency rept re rejectable indications for welds which had been previously accepted Cause not stated Re-examination & repair program for assential cooling water says will be performed Progress rept by 801215
 OPREA.O W. Houston Lighting & Power Co 80/09/12 4pp
- 8009230617 Second interim deficiency re breakdown in quality program for procurement cycle of purchased metle & equipment.Cause not stated.Brown & Root developing procedures & implementation schedule for performing verification program DPREA.Q W Houston Lighting & Powe, Co 80/09/12 3pp
- 8009230659 Fourth interim deficiency rept re poler crane rail tie-down stud failure Ceused by porosity & lack of complete fusion of stud welds.Devietione from design did not significantly contribute to failures Existing studs will be removed OPREA.0 W. Houeton Lighting & Power Co 80/09/15 6pp
- 8007240439 Final deficiency rept re spent fuel storags recks Evaluation of condition indicates sefety of operations not effected & is not reportable under IGCFR50 55e OPREA.Q. W Houston Lighting & Power Co 80/09/17 3pp
- 3009230402 Final deficiency rept on motor pump sheft failure in Comeip containment hydrogen monitoring sye Nonconformence rept has been prepared & hold tags issued against equipment until pump is shipped beck to menufacturer Pump will be replaced OPRFA.0 H Houston Lighting & Power Co 80/09/18 3pp
- 8007300161 Becond interim deficiency rept re rediographs w/rejectable indications in previously accepted welds Ceused by weld epatter & sherp corners Ali indications to be repeired & reinspaceted for finel acceptence unless concrete embedded DPRFA:0.W. Houston Lighting & Power Co 80/09/23, 4pp
- 8009300453 Fourth interim deficiency rapt re damaged steel liner plate in Unit 2 reactor containment bidg Submits updeted repair logic Subcontract change order for repair work negotiated & szecuted, Deformed section of plate removed OPREA:0 W Houston Lighting & Power Co 80/09/25 3pp
- T Hearing transcripts on non-entitrust matters
- BOO9260288 Forwards transcript & record of BOO819 public meeting re facilities w/util & NRC errate & related documentation STELLO.V Office of Inspection & Enforcement, Office of the Director SO/09/19 4pp
- --8009260290 Transcript of 800819 public masting re facilities in Bay City,TX.Pp 1-379 Util & NRC errate & related documentation & correspondence encl # Office of Inspection & Enforcement, Office of the Director 80/09/19.
- DOCKET 50-500 DAVIS-SESSE NUCLEAR POWER STATION, UNIT 2

 G Adjustatory correspondence
- BOOG190279 Responds to FOIA request for 15 documents listed in bibliography of NUREO-0625. "Rept of Siting Policy Tack Force." Documents 6-8 & 13 ere available in PDR. Forwards remaining documents FELTON, J. M. Division of Rules and Records BO/09/04 1p
- ---BO091905B7 Informs Commission of proposed changes to meteorological model used in essessing potential accident consequences for nuclear plents for determination of site acceptability & adequacy of engineered safety features.

 MINDOVER B Office of Standards Development, Director BECY-79-362, 79/06/04 7pp.

- --8009190630 Requests that encl. "Differences in Procedures for Estimating Atmospheric Dispersion Conditions at Inland & Coastal Sites." be sent to appropriate Boards ECINTD, J F Hearings Division 79/04/04 16pp
- DOCKET 80-501 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 3
- 8009190299 Responds to FOIA request for 15 documents listed in bibliography of NUREO-0625, "Rept of Siting Poitcy Tesk Force" Documents 6-8 % 13 are available in PDR Forwards remaining documents FELTON-J M Division of Rules and Records 80/09/04 ip
- ~-8009190587 Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants for determination of site acceptability & adequacy of engineered safety features MINOCUE.R B Office of Standards Development. Director SECY-79-362 79/06/04 7pp
- --8009190630 Requests that enci. "Differences in Procedures for Estimeting Atmospheric Dispersion Conditions at Inland & Goastal Bitee." be sent to appropriate Boards ECINTO.JF Hearings Division 79/04/04 idep
- DOCKET STN-30-502 HAVEN NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- B009110856 Forwards FR notice of withdrawal of application for CP YOUNGBLOOD, B J Licensing Branch 1 80/09/04 2pp
- --B009110899 Notice of withdrawel of application for CP YOUNGBLOOD, B J Licensing Branch 1 B0/09/03 ip
- DOCKET STN-90-508 KPPSS NUCLEAR PROJECT. UNIT 3
- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criterie of NUREO-0696 enci M/o NUREO EISENHUT, D O Division of Licensing 80/08/01 119pp
- 8007120102 Recommende listed steps be taken to reduce risk from ATHS events during interim period before required mode Requires submission of ATHS emergency operating procedure TEDESCO.R L Assistant Director for Licensing 80/08/27 3pp.
- 8009120173 Informs of NRC position re welding procedure specs for use in applications requiring impact testing for notch toughness Space should be qualified using max anticipated amperage & voltage setting to be used in production welding. SPENCER.O 8 Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/09/04 2pp
- F. Security, medical, smergency & fire protection plene
- 8007030267 Notifies of 800817,22 & 30 regional workshops re development of guidance for acceptable method for coping w/emergencies et facility Requeste that representative be east. Subj ares to be discussed include function of facilities & location ENGELKEN.R.H. Region 5, San Francisco, Office of the Director 80/08/42. 2pp
- O Inspection reports. IE Bulletins & correspondence
- 8009100179 Responds to IE Bulletin 80-08, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanke "Containment penetration connections are of flued head design w/containment boundary butt welds RENBERGER, D. L. Washington Public Power Supply System 80/07/15.
- 8009240303 Forwards IE Info Notice 80-29, "Broken Bluds on Terry Turbine Steam Inlet Flange " No written response required ENGELKEN.R H Region 5, San Francisco. Office of the Director 80/88/07, ip.

- 8007030272 Forwards Revision 1 to 1E Bulletin 80-19. "Failures of Mercury-Hetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Pawer Plants Designed by C-E " Hritten response required EMOELKEN,R H Region 5, San Francisco, Office of the Director 80/08/15 1p
- 8009290302 Forwards IE Info Notice 80-27 to degradation of reactor coolant pump studs
 ENGELKEN.R M Region 5, San Francisco, Office of the Director.
 80708/IB 4pp
- 8009160189 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required ENGELKEIDR H Region 5, San Francisco, Office of the Director 80/08/22 1b
- 8009120448 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6005 & K-DON 6008 Circuit Breakers" No written response required EMSELKELLR H Region 5, San Francisco, Office of the Director 80/08/27 1p
- B Reportable occurrences, LERs & related correspondence
- 8009030338 Ack receipt of 800625 interim deficiency mept re shutdown cooling heat exchangers
 ENGELKEN.R H Region 5. San Francisco. Office of the Director
 80/07/09 ip
- --8009030342 Interim deficiency rept re shutdown cooling heat exchangers
 Breakdown of mati selection & mfg processes resulted in
 chloride contamination in tubes, below with design weld
 overlay thickness & cracking of weld overlays C-E rept encl
 REMBERGER, D L Hashington Public Power Supply System 80/06/23
 7pp
- DOCKET STN-50-509 WPPSS NUCLEAR PROJECT, UNIT 5
- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft MUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl M/A NUREO EISENHUT, D 0 Division of Licensing 80/08/01 119pp
- 9009120102 Recommands listed steps be taken to reduce risk from ATHS events during interim period before required mode Requires submission of ATHS emergency operating procedure TEDESCO, R. ... Assistant Director for Licensing 80/08/27 3pp
- 8009120173 Informs of NRC position re welding procedure specs for use in applications requiring impact testing for notch toughness Specs should be qualified using max anticipated amperage & voltage setting to be used in production welding SPENCER, 0 S Region 5, Ban Francisco, Reactor Construction & Engineering Support Branch 80/09/04 2pp
- F Security, medical, emergency & fire protection plans
- 8009030267 Notifies of 800819,22 & 30 regional workshops re development of guidance for acceptable method for coping w/emergencies at facility Requests that representative be sent Subj areas to be discussed include function of facilities & location ENGELKEN, R H. Region S. San Francisco. Office of the Director 80/08/12 2pp
- G Inspection reports. IE Bulletins & correspondence
- 8009100179 Responds to 18 Bulletin 80-00. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Containment penetration connections are of flued head design w/containment boundary butt welds RENBERGER. D. L. Washington Public Power Supply System 80/07/15 2pp
- BO09260303 Forwards IE Info Notice 80-29. "Broken Stude on Terry Torbine Steam Inles Flange" No written response required. BNOELEN.R H Region 5. San Francisco. Office of the Director B0/08/07 1p
- 8007030272 Forwards Revision 1 to 1E Bulletin B0-19, "Failures of Marcury-Metted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required ENGELKEN.R H Region 5, San Francisco: Office of the Director 80/03/15 ip

- 8009270302 Forwards 1E Info Notice 80-27 re degradation of reactor toolant pump stude EMGELKEN.R H Region 5, Ban Francisco. Office of the Director. 80/08/18 4pp
- 8009160189 Forwards IE Circular 80-18, "iOCFR50, 59 Safety Evaluation; for Changes to Radwaste Treatment Sys " No written response required ENGELKEN, R H Region 5, San Francisco, Office of the Director.
- 8009120468 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers" No written response required ENGELKEN, R H Region 3, San Francisco, Office of the Director 80/08/27 ip
- S Reportable occurrences, LERs & related correspondence
- 8007030338 Ack receipt of 800625 interim deficiency rept re shutdown cooling heat exchangers ENGELKEN,R H Region 5, Sen Francisco, Office of the Director, 80707709. Ip
- --B009030342 Interim deficiency rept re shutdown cooling heat exchangers
 Breakdown of math selection & mfg processes resulted in
 chloride contamination in tubes; below min design wald
 overlay thickness & cracking of weld overlays C-E rept encl
 RENBERGER, D. L. Washington Public Power Supply System, B0/06/25,
 700
- BOCKET 50-510 BLUE HILLE STATION, UNIT 1
- O Adjudicatory correspondence
- B009090245 Motion for issuance of partial initial decision re with suitability Case uncontested & pending for 13 months Notice of appearance & Certificate of Byc encl.
 TREBY, S.A. Hearing Branch 1, 80/09/05 4pp
- 8009110803 Order directing applicant & NRC to submit briefs reflecting position on applicability of NRC siting-related pronouncements to present early tite review. Orders NRC to respond to applicant reply to NRC proposed findings of fact.

 LITTLE, L W., MILLER, M.E. Atomic Safety and Licensing Board Panel.

 80/09/09 6pp
- DOCKET 50-511 BLUE HILLS STATION, UNIT 2

 9 Adjudicatory correspondence
- 8009090245 Motion for issuence of pan (el initial decision re site suitability Case uncontested & pending for 13 months Notice of appearance & Certificate of Syc encl TRESY, B A Hearing Branch 1 80/09/05 4pp.
- 8009110803 Order directing applicant & NRC to submit briefs reflecting position on applicability of NRC siting-related pronouncements to present early site review. Orders NRC to respond to applicant reply to NRC proposed findings of fact LITILE.LW , MILLER:ME Atomic Safety and Licensing Board Panel 80/09/09
- DOCKET 50-513 WPP8S NUCLEAR PROJECT, UNIT 4
- A Application/construction stage documents & correspondence
- B0090B0080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/o NUREO, EISENHUT, D O. Division of Licensing, 80/08/01 119pp.
- 8009120099 Recommends listed steps be taken to reduce risk from ATMS events during interim period before required mods. Requires submission of ATMS emergency operating procedure.

 TEDESCU, R L Assistant Director for Licensing. 80/08/27 3pp
- 8D09090496 Forwards addl geologic info re time of latest movements of earth faults on Qable Mountain near ctr of reservation No conclusions re significance have been reached & info is not considered reportable under 100FRZI RENBERGER.D L Washington Public Power Supply System 80/09/02.

F Security, medical, emergency & fire protection plans

- 9009030267 Notifies of 800819.22 & 30 regional workshops re development of guidance for acceptable method for coping w/emergencies at facility Requests that representative be sent Subj areas to be discussed include function of facilities & location EXMELENIR H. Region 5. Sen Francisco, Office of the Director BO/08/12. 2pp
- @ Inspection reports, IE Bulletins & correspondence
- BOOY160622 Responds to IE Bullevan 80-16, "Potential Misapplication of Rosenount Inc Models 1151 & 1152 Pressure Transmitters of Either A or D Dutput Codes "No subj transmitters installed or planned to be installed in safety-related sys RENBERGER, D L Washington Public Power Supply System 80/08/07 to
- BOO9170393 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASKE BA-312 Type 304 Stainless Steel Pipe " No 8A-312 or A-312. Type 304 fusion welded pipe in use or planned for use in 44fety-related sys at facilities RENBERGER.D L. Washington Public Power Supply System 80/08/07 to.
- 8009260303 Forwards 1E Info Notice 80-29, "Broken Stude on Terry Turbine Steam Inlet Flange " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director, 80/08/07 1p.
- BO09120304 Forwards IE Insp Repts 50-460/B0-08 & 50-513/B0-08 on BO0714-1B No noncompliance noted BPENCER, Q.S. Ragion 5. San Francisco, Reactor Construction & Engineering Support Branch 80/08/12 2pp
- --8009120309 IE Insp Repts 30-460/80-08 & 50-513/80-08 on 800714-18 No noncompliance noted Major areas inspected RCPB piping insulation & licensee action on previous insp findings DODDB.R T Region 5, Ban Francisco, Reactor Construction & Engineering Support Branch HERNANDEZ.G., WAONER.W J Region 5, Ban Francisco, Office of the Director 80/08/08 App
- 8009030292 Forwards Revision i to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E." Written response required RKQELMEN.R H Region 5, San Francisco, Office of the Director 80/08/15. ip
- BC09290302 Forwards IE Info Notice 80-27 re degradation of reactor captant pump studs. ENGELKEN,R.H Region 5, Ban Francisco, Office of the Director 80/08/18 4pp.
- BOO9110415 Ack receipt of 800725 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-460/80-07 & 50-513/80-07 BrencER, 0.8 Region 5, Ban Francisco, Reactor Construction & Engineering Support Branch, 80/08/20 Ip
- --8009110422 Responds to NRC 800426 ltr re violations noted in IE Insp Repts 50-460/80-07 & 50-513/80-07 Corrective actions, rework of support 1T-43413-2910 completed Support 1T-4-3404-300A rework not completed RENBERGER.D.L. Washington Public Power Supply System 80/07/25 3pp
- --B009110424 Forwards IE Insp Repts 50-460/80-07 & 50-513/80-07 on B00401-30 & notice of violation.

 SPENCER.0 S. Region 5, San Francisco. Reactor Construction & Engineering Support Branch 80/06/26 2pp
- --B009110426 Notice of violation from insp on 800401-30. * Region 5. San Francisco. Office of the Director 80/06/25 ip.
- ---B009110429 IE Insp Repts 30-460/80-07 & 50-513/80-07 on 800401-30 Noncompliance noted deficiency in area of cable tray support welding TOTHER D. Region 5, Ban Francisco, Office of the Director DODBS, R. T. Region 5, Ban Francisco, Reactor Construction & Engineering Support Branch, 80/06/25 12pp.
- GOO9160189 Forwards IE Circular 80-18, "10CFRSO 59 Bafety Evaluations for Changes to Radwaste Treatment Bys." No written response required. ENGELKEN, R. H. Region 5, Ban Francisco. Office of the Director BO/08/22 10

- 8009120468 Forwards IE info Notice 80-31, "Malogeration of Gauld-Brown Boveri 480 Valt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/08/27 lp
- 8009120609 Ack receipt of 800819 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 30-460/80-10 & 50-513/80-10

 SPENCER: 0 B Region 3, San Francisco, Reactor Construction & Engineering Support Branch 80/09/02 ip
- --8009120616 Forwards IE lnsp Repts 50-460/80-10 & 50-513/80-10 on 800602-09 & notice of violation SPENGER.Q S Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/07/17 2pp
- ~~8009120622 Notice of violation from insp on 800602-09
 * Region 5. San Francisco. Office of the Director 80/07/16 [p
- ---B009120631 IE Insp Repts 50-460/80-10 & 50-513/80-10 on 800602-09 Noncompliance noted fillet welds on columns 22704 & 2283 undersited contrary to contract specs TOTH, A D , DDDDS, R T Region 5, San Francisco, Office of the Director 80/07/16 Spp.
- 8009300345 Updates 800124 response to IE Bulletin 77-02, Revision 2, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Boits." Anchor boit loads on existing designs will be recalculated by 810228 Related data encl RENBERGER, D. L. Washington Public Power Supply System, 80/09/25 700
- DOCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- 8007080080 Forwards draft NUREG-0496. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days, Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHVT.D Q Division of Licensing 80/08/01 117pp
- DOCKET 50-515 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8007080080 Forwards draft NUREQ-0576. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Pronosed implementation schedule for meeting criteria of NUREQ-0676 encl M/a NUREQ EISENHUT.D 9 Division of Licensing 80/08/01 119pp
- DOCKET STN-50-516 JAMESPORT NUCLEAR STATION, UNIT 1

 O Adjudicatory correspondence
- 8009190299 Responds to FOIA request for 15 documents listed in bibliography of NUREG-0623, "Rept of Siting Policy Task Force" Documents 4-8 & 13 are available in FDR Forwards remaining documents FELTON, J M Division of Ruies and Records 80/09/04 ip
- --80091905B/ Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants, for determination of site acceptability & adequacy of engineered safety features
 MINGOUE, R B Office of Standards Development, Director BECY-79-082 79/06/04 7pp
- --8009190630 Requests that encl. "Differences in Procedures for Estimating Atmospheric Dispersion Conditions at Inland & Coastal Sites," be sent to appropriate Boards BCINTO, J F. Hearings Division. 79/04/04 16pp
- 8009170194 Status Rept 4 re NY State Siting Board 800908 opinion & order in Case 80003, recommending const of facility Decision re request for judicial review not yet decided Certificate of Svc encl REVELEY, W T Long Island Lighting Co. REVELEY, W T Hunton & Williams 80/09/10 3pp

Q Inspection reports. IE Bulletins & correspondence

- 8009030089 Forwards Revision 1 to IE Bulletin 80-19. "Failures of Hercury-Wetted Matris Relays in Reactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E " Written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/09/15 1p
- 8009180009 Forwards IE Circular 80-18, "10CFR50.59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/08/22 Ip
- 8009120180 Forwards IE Info Notice 80-31. "Maloperation of Quuld-Brown Boveri 480 Volt Type K-400S & K-DON 400S Circuit Breakers " No written response required ORIER, B H Region i, Philadelphia. Diffice of the Director 80/08/27 ip
- 8009230786 Forwards IE Circuler 80-21, "Regulation of Refueling Crews " No written response required ORIER BH Region 1, Philadelphia, Office of the Director 80/07/10 1p
- 8009240315 Forwards IE Info Notice 80-32. "Clarification of Certain Requirements for Esclusive-Use Shipments of Radioactive Matis " No written response required ORIER B H Region 1. Philadelphia. Office of the Director BO/09/12 ip
- DOCKET STN-50-517 JAMESPORT NUCLEAR STATION, UNIT 2

 O Adjudicatory correspondence
- BOO9190299 Responds to FOIA request for 15 documents listed in bibliography of NUREO-0625, "Rept of Biting Policy Task Force " Documents 6-8 & 13 are available in PDR. Forwards remeining documents FELTON.J M Division of Rules and Records. BO/09/04. Ip
- --B0091905B7 Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plents, for determination of site acceptability & adequacy of engineered safety features.
 HINDOUE, R B. Office of Standards Development, Director SECY-79-362 79706/04 7pp
- --8007190630 Requests that enci, "Differences in Procedures for Estimating Atmospheric Dispersion Conditions at Inland & Coastal Sites," be sent to appropriate Board. BCINTO.J F Hearings Division 79/04/04 topp.
- B009170194 Status Rept 4 re NY State Siting Board 800908 opinion & order in Case 80003, recommending const of facility.

 Decision re request for judicial review not yet decided

 Certificate of Syc enci

 REVELEY, W T Long Island Lighting Co REVELEY, W T Hunton & Williams 80/09/10. 3pp
- G Inspection reports, IE Bulletins & correspondence
- 8007030087 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Metrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/08/15 ip
- 9009180009 Forwards IE Circular 80-18, "100FR50.59 Bafety Evaluations for Changes to Radwaste Treatment Sys " No written response required ORIER, B. H. Region 1, Philadelphia, Office of the Director 80/08/22, ip
- Be09120180 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DDN 6008 Circuit Breakers." No written response required ORIER.8 H Region 1. Philadelphia, Office of the Director B0/08/27 1p.
- BO09230786 Forwards IE Circular 80-21. "Regulation of Refueling Crews." No written response required CRIER, B.H. Region 1. Philadelphia. Office of the Director 80/09/10. 1p

- B009240315 Forwards IE Info Notice B0-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Hatls "No written response required ORIER, B H Region 1, Philadelphia, Office of the Director. 80/09/12. 1p
- DUCKET STN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 6007080080 Forwarde draft NUREG-0676, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl M/o NUREO EISEMBUT, D O Division of Licensing 80/08/01 119pp
- 8009300400 Forwards tschnical questions re implementation of interia policy on 100FR50 & 51 KILLB.L H Tennessee Valley Authority 80/09/23. 3pp.
- I Financial information
- 8009090543 Forwards Annual Financial Rept 1979
 CROSS, J.L. Tennesses Valley Authority 80/09/04. ip
- --8009090563 Annual Financial Rept 1979
 * Tennessee Valley Authority 80/09/04 44pp
- u Inspection reports, IE Bullatine & correspondence
- 8009090075 Forwards IE Bulletin 80-07. Suppl 1, "SWR Jet Pump Assembly Failure " No response required O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/05/13 ip.
- 8007110111 Forwards IE Insp Repts 50-518/80-13, 50-519/80-13, 50-520/80-13 & 50-521/80-13 on 800601-28 No noncompliance nated.

 MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/07/28 2pp
- ---8007110177 IE Insp Repts 50-518/80-13,50-519/80-13,50-520/80-13 & 30-521/80-13 on 800A01-28 No noncompliance noted Mejor areas inspected earth compaction & structural concrets for spray & conteinment activities SWAN.R W Region 2. Atlanta, Office of the Director CANTRELL,F 8 Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/28 App
- 8007020184 Submits response to IE Bulletin 79-03A No EA-312 or A-312. Type 300 series fusion welded pipe ie in use or planned for use in safety-related sye MILLS.L M Tenmessee Velley Authority, 80/08/06, 1p.
- 8009020303 Forwards IE Insp Repts 50-327/80-24.50-328/80-15, 50-390/80-20, 50-391/80-14.50-438/80-13, 50-439/80-11.50-518/80-11.50-519/80-11.50-519/80-11.50-519/80-11.50-519/80-10, 50-520/80-11.50-521/80-11, 50-53/80-11, 80-53/80-11, 80-53/80-11, 80-53/80-11, 80-53/80-10, \$0.08/08.280
- --8007020312 Notice of violation from insp on 800707-11.
 ** Region 2, Atlanta: Office of the Director. 80/08/06 4pp
- --8007020337 IE Insp Repts 50-327/80-24,50-328/80-15,50-390/80-20,50-391/80-14,50-438/80-13,50-439/80-13,50-518/80-11,50-519/80-11,50-519/80-11,50-519/80-11,50-519/80-11,50-519/80-11,50-519/80-11,50-519/80-11,50-519/80-11,50-519/80-10,50-5
- B009030146 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Bys of Opsrating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director, B0/08/15, ip
- 8009140043 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Stram Function & Nonessential Control Air at Certain OE BWR Facilities," No specific action or response requested D'REILLY, U. P Region 2, Atlanta, Office of the Director, 80/08/15 ip

- BOO9120046 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BMR " No written response required. O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22
- 8009160153 Forwards IE Circular 80-18, "10CFR50 59 Bafety Evaluations for Changes to Radwaste Treatment Sys " No written response required 0'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22
- BO09240357 Responds to NRC 800617 1tr 80P-30 will be revised & implemented by 800829 resulting in full compliance Ref IE Insp Repts 50-518/80-09, 50-519/80-09, 50-521/80-09 & 50-521/80-09 Tennessee Valley Authority 80/08/22 ip MILLS, L M
- BO09120340 Forwards IE Info Notice 80-31. "Maloperation of Opuld-Brown Bowers 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers "No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director B0/08/27
- BOOMIROOAS Forwards response to IE Bulletin 80-16 Resemble Models 1151 & 1152 pressure transmitters were planned for installation.

 OE will analyze applications of transmitters to determine out-of-range conditions OL Will emaly- ____ out-of-range conditions MILLS.L.H. Tennessee Valley Authority 80/08/29 2pp
- BOO9240427 Forwards response to IE Bulletin BO-16 re patential misapplication of Rosemount pressure transmitters List of identified transmitters used in safety-related areas being complied. Rept will be filled after resolution of deficiency MiLLB.L M. Tennessee Valley Authority 80/08/29 2pp
- BOOP240380 Ack receipt of B00821 ltr informing NRC of steps taken to correct violation noted in IE lnsp Repts 30-318/80-12, 50-319/80-12, 50-320/80-12 & 50-321/80-12 KMRPKY, C Region 2, Atlanta, Reactor Construction & Engineering Support Branch B0/09/02 ip
- --8007240387 Responds to NRC 800728 ltr re violations noted in 1E Insp Repts 50-518/80-12, 50-519/80-12, 50-520/80-12 & 50-521/80-12 Corrective actions reinforcing steel bars cited in rept are being placed on cribbing KILLS:L M. Tennessee Valley Authority 80/08/21 2pp.
- --8009240398 Forwards IE Insp Repts 50-518/80-12,50-519/80-12, 50-520/80-12 & 50-521/80-12 on 800430-0703 & notice of Violation
 HURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering
 Support Branch 80/07/28 2pp.
- ---BO07240406 Notice of violation from insp on 800630-0703 * Region 2, Atlanta, Office of the Director 80/07/ 80/07/25 10
- --B009240421 IE Insp Repts 50-518/80-12.50-519/80-12,50-520/80-12 & 50-521/80-12 on B00630-0703 Noncompliance noted failurs to follow resinforcing steel storage procedure HERDY, A Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch. KLEINBORGE, W P Region 2, Atlanta, Office of the Director. 80/07/25. Bpp
- 6009260375 Forwards IE Circular 80-21, "Regulation of Refueling Crews." No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/09/10.
- 8. Resortable occurrences, LERs & related correspondence
- 8007040449 Final deficiency rept re containment anchor boit chair welds All identified deficient walds will be repaired to original space & repaired areas tested Investigation conducted on previously accepted welds
 MILLB
- BO09100526 Final deficiency rept re improper anchor spacing on surface—mounted plates All improperly installed surface—mounted plates have been identified & will be remounted by 801114 MILLE, L.M. Tennessee Valley Authority 80/08/11 2pp.
- BOO9090427 Final deficiency rept re wiring discrepancies in high pressure core spray metal-clad switchgear Defective 88-12 switches replaced. Hardware corrections will be completed by 8101300 & software corrections by 810630 MILLS, L. M Tennessee Valley Authority, 80/08/28, 3pp.

- 8009090530 First interim deficiency rept re inadequate drawing control Caused by breakdown of GA program re drawing control Drawings will be updated on daily basis by using TVA receipt forms Final rept to be transmitted on or before 801119 MILLS,L M Tennessee Valley Authority 80/08/28 2pp
- B009090434 Final interim deficiency rept re 4-inch Borg-Harner gate valves Valves may fail due to error in design Gate could disengage from guide. when valve in backseat position Valve failure may lead to RHR sys degradation
 MILLS.L M Tennessee Valley Authority 80/08/29 2pp
- 8007070440 Final interim deficiency rept re wiring discrepancies on MPCB components Discrepancies involve wiring terminations not matching wiring diagrams.missing wires & nonlabeling of parts Components will be reworked MILLS.L M Tennessee Valley Authority 80/08/27 3pp
- 8007160643 Part 2: rept re design deficiencies in nuclear sys protection sys power distribution panels Panels returned to GE for redesign & rework to corrected design MILLS,L M Tennessee Valley Authority 80/07/03 3pp
- 8009240423 Final deficiency rept re inadequate document control Caused by failure of manual holders to follow procedures in filing or removing matl Guarterly Internal survey will be conducted MILLS.L M Tennessee Valley Authority 80/09/15 Spp
- 8009240092 Second interim deficiency rept re Rosemount Model 1152 pressure transmitter defects Util is preparing lists of Rosemount 1151 & 1852 transmitters for GE to analyze & replace if necessary final rept will be provided by 810403 MILLS.L M Tennessee Valley Authority 80/09/17 3pp
- 8007270375 Second interim deficiency rept re steam tunnel embedment stiffner plate weld. Cause not stated Util continuing to monitor Atlas GA program to help correct deficiencies MiLLS.L M Tennesses Valley Authority 80/09/19 ip.
- 8009300445 Third interim deficiency rept re reactor pressure vessel shield wall weld. Investigation is continuing & repairs will be made as required. Final rept should be submitted by 801224. MILLS, L. H Tennessee Valley Authority 80/09/24. 1p
- DOCKET STN-50-519 HARTSVILLE NUCLEAR PLANT, UNIT 2 A Application/construction stage documents & correspondence
- 8009080080 Forwards dreft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days. Proposed implementation schedule for meeting criteria of NUREO-0696 encl Wo NUREO EISENHUT, D @ Division of Licensing 80/08/01 119pp
- 8009300400 Forwards technical questions re implementation of interim policy on 10CR950 & 51
 MILLB.L M. Tennessee Valley Authority 80/09/23 3pp.
- I Financial information
- 8009090543 Forwards Annual Financial Rept 1979. CROSS.J L Tennessee Valley Authority 80/09/04 1p
- --8007070563 Annual Financial Rept 1979
 * Tennessee Valley Authority 80/09/04 44pp.
- @ Inspection reports: IE Bulletins & correspondence
- 8009090075 Forwards IE Bulletin 80-07, Suppl in "BWR Jet Pump Assembly Failure " No response required
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director, 80/05/13
- 8009110111 Forwards IE Insp Repts 50-518/80-13,50-519/80-13, 50-520/80-13 & 50-521/80-13 on 800401-28 No noncompliance noted. HURPHY, C.E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/28. 2pp
- --8009110177 IE Jnsp Repts 50-518/80-13,50-519/80-13,50-520/80-13 & 50-521/80-13 on 800601-28 No noncompliance noted Major areas inspected earth compaction & structural concrete for spray & containment activities SMAN, R H Region 2, Aklanta, Office of the Director CANTRELL,F 8 Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/28. opp

- 8009020184 Submits response to IE Bulletin 79-03A No SA-312 or A-312. Type 300 series fusion welded pipe is in use or planned for use in safety-related sys MILLS:L M Tennessee Valley Authority 80/08/04 ip
- 8009020303 Forwards IE Insp Repts 50-327/80-24.50-328/80-15. 50-390/80-20.50-391/80-14.50-438/80-13.50-439/80-13. 50-518/80-11.50-519/80-11.50-520/80-11.50-521/80-11. 50-533/80-11.80-559/80-10.50-566/80-10 & 50-567/80-10 0'REILLY.J P Region 2. Atlanta. Office of the Director 80/08/04 208
- --8009020312 Notice of violation from insp on 800707-11 * Region 2. Atlanta. Office of the Director 80/08/06 4pp
- --8009020337 IE Insp Repts 50-327/80-24.50-328/80-15.50-390/80-20, 50-391/80-14.50-438/80-13.50-439/80-13.50-518/80-11. 50-519/80-11.50-520/80-11.50-521/80-11.50-553/80-11. 50-554/80-10.50-556/80-10 & 50-567/80-10 an B00707-11 BROWNLEE.V L Region 2. Atlanta. Office of the Director 90/08/06 24pp
- 8009030146 Forwards Revision 1 to IE Bulletin 80-19. "Failures of Marcury-Netted Matrix Relays in Reactor Protective 8gs of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/15.
- 8009160045 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain OE BWR Facilities," No specific action or response requested O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/19
- 8007120066 Forwards Suppl 3 to IE Bulletin 80-17, "Feilure of Control Rods to Insert During Scram at BWR " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22
- 8009i60153 Forwards IE Circular 80-i8, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/08/22.
- 8009240957 Responds to NRC 800617 ltr 80P-30 will be revised & implemented by 800829 resulting in full compliance Ref IE Insp Repts 50-518/80-09, 50-519/80-09, 50-520/80-09 & 50-520/80-09 MILLS, L. M. Tennessee Valley Authority 80/08/22 in
- HO09120340 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DDN 6009 Circuit Breakers" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/27 lb
- 800918006B Forwards response to IE Bulletin 80-16 Rosemount Models 1131 & 1132 pressure transmitters were planned for installation GE will analyze applications of transmitters to determine out-of-range conditions MILLS.L M Tennessee Vailey Authority 80/08/29 2pp.
- 8009240427 Forwards response to IE Bulletin 80-16 re potential misapplication of Rosemount pressure transmitters. List of identified transmitters used in safety-related areas being complied Rept will be filed after resolution of deficiency MILLS, L M Tennessee Valley Authority. 80/08/29 2pp.
- 8009240380 Ack receipt of 800821 ltr informing NRC of steps taken to correct violation noted in 1E Insp Repts 50-518/80-12, 50-520/80-12 & 50-521/80-12. MURPHY-C E Region 2, Atlanta. Reactor Construction & Engineering Support Branch 80/09/02 ip
- --8009240387 Responds to NRC 000728 ltr re violations noted in 1E Insp Repts 50-518/60-12.50-519/80-12.50-520/80-12 & 50-521/80-12. Corrective actions reinforcing steel bars cited in rept are being placed on cribbing MILLS,L M Tannessee Valley Authority 80/08/21. 2pp
- --8009240398 Forwards IE Insp Repts 50-518/80-12, 30-519/80-12, 50-520/80-12 & 50-521/80-12 on 800630-0703 & notice of violation, MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/28 2pp

- --8009240406 Notice of violation from insp on 800630-0703 * Region 2. Atlanta, Office of the Director 80/07/25 ip
- --8009240421 IE Insp Repts 50-518/80-12.50-519/80-12.50-520/80-12 & 50-521/80-12 on 800430-0703 Noncompliance noted failure to follow reinforcing steel storage procedure HERDT.A R Region 2. Atlanta. Reactor Construction & Engineering Support Branch KLEINSOR9E.W P Region 2. Atlanta. Office of the Director 80/07/25 Bpp
- 3009260375 Forwards IE Circular 80-21, "Regulation of Refueling Craws," No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/09/10, 500
- 8 Reportable occurrences, LERs & related correspondence
- BO07040449 Final deficiency rapt re containment anchor bolt chair welds All identified deficient welds will be repaired to original specs & repaired areas tested Investigation conducted on previously accepted welds
 MILLS,L M Tennessee Vailey Authority 80/07/24 App
- 9007090427 Final deficiency rept re wiring discrepancies in high pressure core spray metal-clad switchgear Defective BB-12 switches replaced Hardware corrections will be completed by 810130 & software corrections by 810630.

 MILLS.L M Tennesses Valley Authority 80/08/28 3pp.
- 8007070330 First interim deficiency rept re inadequate drawing control.
 Caused by breakdown of GA program re drawing control.
 Drawings will be updated on daily basis by using TVA receipt forms. Final rept to be transmitted on or before 801119.
 MILLB.L M Tennessee Valley Authority 80/08/28. 2pp
- 8007070434 Final interim deficiency rept re 6-inch Borg-Harner 4sts valves Valves may fail due to error in design. Qate could disengage from guida: when valve in backseat position, Valve failure may lead to RHR sys degradation MILLS. L M Tennessee Valley Authority. 80/08/29 2pp
- 8009090440 Final interim deficiency rept re wiring discrepancies on HPCB components. Discrepancies involve wiring terminations not matching wiring diagrams: missing wires & nonlabeling of parts Components will be reworked.

 MILLS.L M Tennessee Vailey Authority. 80/08/29. 3pp
- 8007240425 Final deficiency rept re inadequate document control. Gaused by failure of menual holders to follow procedures in filing or removing mat Guarterly internal survey will be conducted.

 MILLS, L. M. Tennessee Valley Authority. 80/07/15 3pp
- 8009240092 Secand interim deficiency rept re Rosemount Model 1152 pressure transmitter defects Util is preparing lists of Rosemount 1151 & 1152 transmitters for GE to analyze & replace if necessary Final rept will be provided by 810403 MILLS.L M Tennessee Valley Authoritu 80/09/17. 3pp.
- 8007270375 Second interim deficiency rept re steam tunnel embedment stiffner plate weld Ceusa not stated. Util continuing to monitor Atlas GA program to help correct deficiencies. MILLS, L.M. Tennessee Valley Authority 80/09/19 ip.
- B007300445 Third interim deficiency rept re reactor pressure vassel shield wall weld. Investigation is continuing & repairs will be made as required. Final rept should be submitted by 801224.

 MILLS:L M Tennessee Valley Authority. 80/09/24. ip.
- DOCKET BIN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3

 A Application/construction stage documents & correspondence
- BOOTOBOOBO Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl. W/o NUREG EISENHUT, D. O Division of Licensing 80/08/01. 119pp
- 8009300400 Forwards technical questions re implementation of interimpalicy on 100FR50 & 51.
 MILLE: L M Tennessee Valley Authority. 80/09/23. Spp.
- I Financial information .
- 8009090549 Forwards Annual Financial Rept 1979 CROBS, J. L. Tannessee Valley Authority 80/09/04 ip

- --8009090563 Annual Financial Rept 1979
 ** Tennesses Valley Authority 80/09/04 44pp
- @ Inspection reports: IE Bulletins & correspondence
- 8009090075 Forwards IE Bulletin 80-07. Suppl 1. "EWR Jet Pump Assembly Failure" No response required O'REILLY, J P Region 2, Atlanta, Office of the Director, 80/05/13 is.
- 8009110111 Forwards 1E Insp Repts 50-518/80-13,50-519/80-13, 50-520/80-13 & 50-521/80-13 on 800601-28 No noncompliance noted, MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/28 2pp
- BOG9020184 Submits response to IE Sulletin 79-03A No GA-312 or A-312. Type 300 series fusion welded pipe is in use or planned for use in safety-related sys.

 HILLS,L M Tennessee Valley Authority 80/08/06 ip.
- 8009020303 Forwards IE Insp Repts 50-327/80-24,50-328/80-15, 30-390/80-20,50-391/80-14,50-438/80-13,50-439/80-13, 50-518/80-11,50-519/80-11,50-520/80-11,50-521/80-11, 50-553/80-11,60-554/80-10,50-566/80-10 t 50-567/80-10 Q'REILLY, J P. Region 2, Atlanta, Office of the Director 80/08/06
- --B009D203i2 Notice of violation from insp on B00707-ii + Region 2. Atlanta, Office of the Director. 80/08/06 App
- --8009020337 IE Insp Repts 50-327/80-24,50-328/80-15,50-390/80-20,50-391/80-14,50-438/80-13,50-409/80-13,50-518/80-11,50-519/80-11,50-521/80-15,50-553/80-11,50-553/80-10,50-566/80-10 & 50-567/80-10 on 800707-11 SRONNLEE,V L Region 2, Atlanta, Office of the Director BO/08/06. 24pp
- 8007030146 Forwards Revision 1 to IE Bulletin 80-17, "Failures of Marcurg-Watted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J. P Region 2, Atlanta, Office of the Director 80/08/15, ip
- 8009(60045 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Batween Control Rod Drive Scram Function & Nanessential Control Air at Certain GE BMR Facilities." No specific action or response requested D'AEILLY, J P Region 2, Atlanta, Office of the Director 80/08/19,
- 9009120066 Forwards Buppl 3 to IE Bulletin 80-i7. "Failure of Control Rads to Insert During Scram at BMR " No written response required.
 O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/08/22 in
- 8007160153 Forwards IE Circular 80-18, "100FR50 59 Safety Evaluations for Changes to Radwaste Treatment Bys " No written, response
- required.
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/08/22
- 8009240357 Responds to NRC 800617 1tr 80P-30 will be revised & implemented by 800829 resulting in full compliance Ref IE lasp Repts 50-518/80-09, 50-519/80-09, 50-520/80-09 & 50-521/80-09.

 Hitls, L. H. Tennessee Valley Authority 80/08/22 ip.
- B009120340 Forwards IE Info Notice B0-31, "Maloperation of Qould-Brown Bover(480 Volt Type K-6008 & K-DON 6008 Circuit Breakers," No wristen response required O'REILLY, J P Region 2. Atlanta, Office of the Director, 80/08/27.
- 8009180068 Forwards response to IE Bulletin 80-16 Resembnt Models 1151 & 1152 pressure transmitters were planned for installation. CE will analyze applications of transmitters to determine out-of-range conditions KILLS.L.M. Tannessee Valley Authority 80/08/29 2pp.

- 8007180087 Submits response to IE Bulletin 80-17 No mercury-wetted matrix relays are in use in reactor protection sys MILLS,L M Tennessee Valley Authority 80/08/27 ip
- 8009240427 rorwards response to IE Bulletin 80-16 re potential misapplication of Rosemount pressure transmitters List of identified transmitters used in safety-related areas being tompiled Rept will be filed after resolution of deficiency MILLS,L M Tennessee Valley Authority 80/08/29 2pp
- B0092403B0 Ack receipt of B00821 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-518/80-12, 50-519/80-12, 50-520/80-12 & 50-521/80-12 MURPHY. C E Region 2. Atlanta. Reactor Construction & Engineering Bupport Branch 80/09/02 1p
- --8009240397 Responds to NRC 800728 ltr re violations noted in IE Insp Repts 50-518/80-12, 50-519/80-12, 50-520/80-12 & 50-521/80-12 Corrective actions reinforcing steel bars cited in rept are being placed on cribbing HILLS.L M Tennessee Vailey Authority 80/08/21 2pp
- --8009240398 Forwards 1E Insp Repts 50-518/80-12, 50-519/80-12, 50-520/80-12 & 50-521/80-12 on 800430-0703 & notice of violation HURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/28 2pp
- --8009240406 Notice of violation from insp on 800630-0703.

 * Region 2, Atlanta, Office of the Director 80/07/25 ip
- --8009240421 IE Insp Repts 50-518/80-12,50-519/80-12,50-520/80-12 & 50-521/80-12 on 800630-0703 Noncompliance noted failure to follow reinforcing steel storage procedure HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch KLEINSCROE, W P Region 2, Atlanta, Office of the Director 80/07/29 Bpp.
- 8009260375 Forwards IE Circular 80-21, "Regulation of Refueling Grews "
 No written response required
 D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/10
 Spp.
- 8. Reportable occurrences, LERs & related correspondence
- 8009090427 Final deficiency rept re wiring discrepancies in high pressure core spray metal-clad switchgear Defective 89-12 switches replaced. Hardware corrections will be completed by 810430 & software corrections by 810430 MILLS,L M. Tennessee Valley Authority 80/08/28 Opp
- 8009090434 Final interim deficiency rept re 6-inch Borg-Harner gate valves Valves may fail due to error in design Cate could disengage from guide: when valve in backseat position Valve failure may lead to RHR sys degradation MILLS.L.M Tennessee Valley Authority 80/08/29 2pp.
- BO09090440 Final Interim deficiency rept we wiring discrepancies on MPCB components Discrepancies involve wiring terminations not matching wiring diagrams, missing wires & nonlabeling of parts Components will be reworked.

 MILLS.L.M Tennesses Valley Authority 80/08/29 3pp
- 8009240425 Final deficiency rept re inadequate document control Gaused by fallure of manual holders to follow procedures in filing or removing mat! Quarterly internal survey will be conducted.

 MILLS, L. M. Tennessee Valley Authority 80/09/15 3pp
- 8007240372 Second interim deficiency rept re Rosemount Model 1152 pressure transmitter defects Util is preparing lists of Rosemount 1151 & 1152 transmitters for OE to analyze & replace if necessary. Final rept will be provided by 810403 HILLS, L M Tennessee Valley Authority 80/07/17. 3pp
- 8009290375 Second interim deficiency rept re steam tunnel embedment stiffner plate weld. Cause not stated Util continuing to monitor Atlas 0A program to help correct deficiencies MILLS,L M Tennessee Valley Authority 80/09/19 ip.

- DOCKET BIN-90-521 HARTSVILLE NUCLEAR PLANT, UNIT 4
- A Application/construction stage documents & correspondence
- GOO7080080 Forwards draft NUREO-0.976. "Functional Criteria for Emergency Response Facilities " Commente requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0.676 encl W/o NUREO EISENHUT, D O Division of Licensing. 80/08/01. 117pp
- 8009300400 Forwards technical questions re implementation of interim policy on 10CFR90 & 51 KILLS.L M Tennessee Valley Authority 80/09/23 3pp
- I Financial information
- GOO9090543 Forwards Annual Financial Rept 1979 CRUSS, J L. Tennasses Valley Authority 80/ 80/09/04
- --8007070963 Annual Financial Rept 1979

 ** Tennessee Valley Authority 80/07/04 44pp
- @ Inspection reports, IE Bulletins & correspondence
- 8009090075 Forwards IE Bulletin 80-07. Suppl 1, "BHR Jet Pump Assembly Failure" No response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/13.
- 8009110111 Forwards IE Insp Repte 50-518/80-13,50-519/80-13, 50-520/80-13 & 50-521/80-13 on 800601-28 No noncompliance noted KURPIN',C E Region 2, Atlanta. Reactor Construction & Engineering Gupport Branch 80/07/28 2pp
- --8007110177 IE Insp Repts 50-518/80-13, S0-519/80-13, S0-520/80-13 & S0-521/80-13 on 800601-28 No noncompliance noted Major areas inspected earth compaction & structural concrete for spray & containment activities Rigion 2, Atlanta, Office of the Director. 80/07/28 BUAN, R W
- 8009020184 Submits response to IE Sylletin 79-03A No 8A-312 or A-312. Type 300 series fusion welded pipe is in use or planned for use in sefety-related sys. MILLS:L M Tennesses Valley Authority. 80/08/06. ip
- 8009020303 Forwards IE Insp Repts 50-327/80-24,50-328/80-15, 50-390/80-20,50-391/80-14,50-438/80-13,50-439/60-13, 50-518/80-11,50-519/80-11,50-520/80-11,50-521/80-11,50-553/80-11,60-554/80-10,80-564/80-10 D'REILLY, J P Region 2. Atlanta. Offica of the Director. 80/08/06
- --8007020312 Notice of violation from insp on 800707-11 * Region 2, Atlanta, Office of the Director 80/0 80/0B/0A
- --8007020337 IE Insp Repts 30-327/80-24.50-328/80-15.50-370/80-20.50-391/80-14.50-438/80-13.50-439/80-13.50-518/80-11.50-519/80-11.50-521/80-11.50-523/80-11.50-523/80-11.50-539/80-10.50-54/80-10.50-566/80-10.50-567/80-10 on 800707-11 BROWNLEE,V L Region 2, Atlanta, Office of the Director 80/08/05 24pp
- 8009030146 Forwards Revision 1 to IE Bulletin 80-19, "Failuras of Marcury-Wested Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required.

 O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/01 Region 2, Atlanta, Office of the Director, 80/08/15
- G009160045 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Monessuntial Control Air at Certain GE BNR Facilities " No specific action or response requested O'REILLY, J P Region 2. Atlanta, Office of the Director. 80/08/19
- 8007120066 Forwards Suppl 3 to IE Bulletin 60-17, "Failure of Control Rods to Insert During Scram at BHR." No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22.

- 8009160153 Forwards IE Circular 80-19, "10CFR30 59 Bafaty Evaluations for Changes to Radwaste Treatment Sys " No written response O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/08/22.
- B009240357 Responds to NRC 800617 ltr 8DP-30 will be revised & implemented by B00529 resulting in #uil compliance Ref IE Insp Repts 30-518/80-09, 50-519/80-09, 50-520/80-09 & 50-527/80-09 Tennessee Valley Authority 80/08/22 16 MILES, I M
- 8009120340 Forwards IE Info Notice 80-31. "Maloperation of Gould-Erem. Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakere." No written response required O'REILLY.J P Region 2. Atlanta, Office of the Director. 80/08/27 Region 2. Atlanta, Office of the Director. 80/08/27
- 8009180068 Forwards response to IE Bullstin 80-16. Rosemount Models 1151 & 1152 pressure transmitters were planned for installation OE will analyze applications of transmitters to determine out-of-range conditions MILLS, L M Tennessee Valley Authority 80/08/29, 2pp.
- 8009180087 Bubmits response to IE Bulletin 80-19 No mercury-wested matrix relays are in use in reactor protection sys HILLS.L H Tennessee Valley Authority 80/08/29 ip
- 8009240427 Forwards response to IE Bulletin 80-i6 re potential misapplication of Rosemount pressure transmitters. List of identified transmitters used in safety-related areas being compiled Rept will be filed after resolution of deficiency MILLS,L M. Tennessee Valley Authority 60/08/29, 2pp.
- 8009240390 Ack receipt of 800821 ltr informing NRC of steps taken to correct violation noted in 1E Insp Repts 50-516/80-12, 50-517/80-12, 50-520/80-12 & 50-521/80-12 MRPHY.C E Regiom 2. Atlanta, Reactor Construction & Engineering Support Branch 80/09/02 ip
- -8009240387 Responds to NRC 800728 itr re violations noted in IE Insp.
 Repts 50-518/80-12,50-519/80-12,50-520/80-12 & 50-521/80-12.
 Corrective actions reinforcing eteel bars cited in rept are
 being placed on cribbing
 MILLS.L M Tennessee Valley Authority 80/08/21, 2pp
- --8009240398 Forwards IE Insp Repts 50-519/80-12,50-519/80-12, 50-520/80-12 & 50-521/80-12 on 800430-0703 & notice of violation MURPHY,C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/28, 2pp.
- --8007240406 Notice of violation from insp on 800630-0703.
 * Region 2. Atlanta, Office of the Director. 80/07/3 80/07/25 10.
- --8009240421 IE Insp Repts 50-518/80-12,50-519/80-12,50-520/80-12 k 50-521/80-12 on 800630-0703 Noncompliance noted failure to follow reinforcing steel storage procedure HEROT.A R. Region 2, Atlanta Reactor Construction & Engineering Support Branch 80/07/25 Sp
- 8009260375 Forwards IE Circular 80-21, "Regulation of Refueling Craws." No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/09/10
- 8. Reportable occurrences, LERs & related correspondence
- 8007070427 Final deficiency rept re wiring discrepancies in high pressure core spray metal-clad switchgear Dafective 88-12 switches replaced Hardware corrections will be completed by 810130 % eoftware corrections by 810630 % eoftware corrections by 810630 MILLS,L M Tenneesee Valley Authority 80/08/28 3pp
- 8007070434 Final interim deficiency rept re 6-inch Borg-Warner gate valves Velves may fail due to error in design. Cate could disengage from guide, when valve in backseat position Valve failure may lead to RHR sys degradation MILLS.L M Tannasese Vailey Authority. 80/08/27. 2pp
- 8007070440 Final interim deficiency rept rs wiring discrepancies on HPCB components Discrepancies involve wiring terminetions not matching wiring diagrams: missing wires & nonlabeling of parts Components wiil be reworked MILLS.L M Tennesses Valley Authority 80/08/29 3pp.

- 8009240425 Final deficiency rept re inadequate document control Caused by failure of manual holders to follow procedures in filing or removing mail Quarterly internal survey will be conducted HILLS.L. H. Tennessee Valley Authority 80/09/15 3pp
- 8009240392 Becond interim deficiency rept re Rosemount Model 1152 pressure transmitter defecte Util is preparing lists of Rosemount 1151 & 1152 transmitters for QE to analyze & replace if necessary Final rept will be provided by 810403 HILL&.L.M Tennesse Valley Authority 80/09/17 3pp
- BO09290375 Second interim deficiency rept re steam tunnel embedment stiffner plate weld Cause not eteced Util continuing to monitor Atles GA program to help correct deficiencies MILLS, L. M. Tennessee Valley Authority 80/09/19. 1p
- DOCKET BIN-50-522 SKADIT NUCLEAR POWER PROJECT, UNIT 1
- A. Application/construction etage documente & correspondence
- BOO9080080 Forwards draft NUREO-0696. "Functional Criteria for Emergency Response Facilities " Commente requested within 30 days, Proposed implementation schedule for meeting criteria of NUREO-0696 enci M/o NUREO, E18ENHUT.D.O Division of Liceneing 80/08/01 119pp.
- Q. Adjudicatory correspondence
- 8009180528 Statement suggesting that full Commission review of orders k opinions below not necessary due to mootness ASLB 800827 order indicates proceeding has terminated BUBCH, R. W., MEANS, D.B. Affiliation Unknown, 80/09/11 2pp
- DOCKET BIN-50-523 BKAQIT NUCLEAR POWER PROJECT, UNIT 2
- A Application/conetruction stage documents & correspondence
- 8009080080 Forwards draft NUREO-0596, "Functional Criteria for Emergency Response Facilities " Commente requested within 30 days. Proposed implementation echedule for meeting criteria of NUREO-0596 enci. N/o NUREO EISENRUT, D. Q. Division of Liceneing 80/08/01. 119pp
- Q. Adjudicatory correspondence
- 8009180528 Statement suggesting that full Commission review of orders a spinions below not necessary due to mootness. ASLB 800827 order indicates proceeding has terminated.
 BUSCH, R. H., MEANS, D. B. "Affiliation Unknown 80/09/11 2pp
- DOCKET BTN-50-520 PALO VERDE NUCLEAR STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- 8007030285 Responde to 800417 request for info re NRC involvement in archeological data recovery activities for FY77 Completed questionnairs enci DENTON, R. Office of Nuclear Reactor Regulation, Director. 80/06/11. 7pp
- 9009090000 Forwards draft NUREO-0696, "Functional Criteria for Emergancy Response Facilities." Comments requested within 90 days. Proposed implementation schedule for meeting criteria of NUREO-0696 encl. W/o NUREO. EISENFUT.D.O Division of Licensing. 80/08/01. 119pp
- 9009020335 Notification of 800815 meeting w/util in Bethesda.MD to discuss whether auxiliary feedwater sye meets design criteria. KERRIGAN.J Licersing Branch 3. 80/08/14. 2pp.
- BOO9120551 Notification of 800821 & 22 meeting w/util in Phoenix.AZ to discuss auxiliary feedwater sys review. KERRIGAN.J. Lite feedwater Fanch 3. 80/08/18, 3pp
- 8007030511 Submits response to NRC 800421 info request on Category 1 mesonry walls employed by plants under CP & DL review.

 Brawings 19-A-ZJD-507 through 511, 13-A-ZAD-203 & 13-A-ZAD-207 available in Central Files.

 VAN BRUNT, E. E. African Public Service Co 80/08/25. 3pp
- 9009120508 Forwards updated distribution list for suppl & emend to FBAR & snviron rept Supersedes 800618 list EERROAM.U. Licensing Brench 3 80/08/25 5pp.

- 8007070523 Forwards comments of util review board re open items from Class IE do power sye review Six items identified which require addi clerification

 VAN BRUNT.E E Arizona Public Service Go 80/07/04 4pp
- 8009150538 Advises that ASNE Code Casee N-274 & N-275 may be used in piping Spec 13-DM-204 subj to conditions re ferritic matle for N-274 & full weld thickness removal for N-275 Code cases should be documented in FSAR TEDESCOR L Assistant Director for Licensing B0/09/04 3pp.
- 8009180534 Notification of 800925 sys review meeting w/util & Bechtel in Phoeniz.AZ re equipment quelification Agenda encl KERRICAN, J D Licensing Branth 3 80/09/05 3pp
- 8009160595 Natification of 800925 meeting w/util & Bechtel in Phoenix. AZ to conduct sys review meeting re equipment qualification KERRIGAN.J D Licensing Branch 3 80/09/12 3pp
- 8009240422 Forwarde Bechtel Power Corp responses to outstanding open items of Class IE do power sys review Responses are intended to resolve outstanding concerns of BC Power Sys Review Boerd Final resolution of open items will be provided VAN BRUNT, E. E. Arizona Public Service Co. 80/09/18 i2pp
- C Utility Environmental Report (ER), amends & correspondence
- 8009120508 Forwards updated distribution liet for suppl & amend to FSAR & environ rept Supersades 800618 list KERRIGAN, J Licensing Branch 3 80/08/25 5pp
- 8009090392 Forwards Suppl 1 to environ rept for fecility.
 VAN BRUNT, E. E. Arizona Public Service Co. 80/09/08 1p
- --8007070398 Suppl 1 to facility environ rept * Arizona Public Service Co. 80/09/30 53pp
- 8009230701 Forwards proof of evc for Buppl 1 to environ rept.GL etage required by 10CFR2.101 & D Eleenhut 800608 ltr VAN BRUNT, E E Arizona Public Service Co. 80/09/15 Spp
- F Security, medical, emergency & fire protection plans
- 80070302&2 Notifies of B00819,22 & 30 regional workshops re development of guidence for acceptable method for coping w/emergencies at facility Requeste that representative be sent Sub; areas to be discussed include function of facilities & location ENGELKEN,R H. Region 5. San Francisco. Office of the Director. B0/08/12 2pp
- Q. Adjudicatory correspondence
- 8007030714 Response in apposition to PL Haurihen.K Dahl & C Shuey 800811 patition to intervene Petitioners failed to establish etanding or specify interest Aspects affecting patitioners not identified W/Certificate of Svc QEHR.A C , BISCOFF.C.A Arizona Public Service Co QEHR.A C Snell & Wilmer 80/08/26 Opp.
- 8009040276 Response in support of P Hourihan 800811 patition to intervene & request for hearing conditioned on particularization of aspects of concern Supports holding hearings in Phoenix area W/appearance & Certificate of Svc MCGURREN, H J Hearing Branch 1 80/09/02 11pp
- 8009080314 Notice of establishment of ASLB to preside in OL applications, environ rept & opportunity for hearing proceedings, RM Lazo appointed chairman, RF Cole & B Callahan members, LAZO, R M Atomic Bafaty and Licensing Board Panel 80/09/09 2pp
- H General correspondence
- 8009100457 Ack recaipt of 800705 ltr & forwards Friends of the Earth Class 9 petition & Director's decision on patition M/o encl 8CHMENGER, A Licensing Branch 2 80/08/27, 2pp
- --8009100463 Requests Director's decision on Friends of the Earth petition to consider Class 9 accidents in supplemental EIB FRIESEMA, H P Northwestern Univ. 90/07/05 ip
- 80090500B3 Forwards 800725 FR notice re procedurel assistance change in adjudicatory licensing proceedings, per 800902 telcon W/o encl MCCURREN H J Hearing Branch 1 80/09/03 ip

- 8009250466 Responds to 800620 ltr rd NRC licensing procedures rules of practice docketing procedures & milestones for facilities 8CHWENGER.A Licensing Branch 3 80/09/12 20p
- K Utility Final Safety Analysis Report (FBAR) & amends
- 8009120508 Forwards updated distribution list for suppl & amend to FSAR & environ rept Supersedes 800618 list KERRIGAN: J. Licensing Branch 3 80/08/25 5pp
- 8009300402 Forwards Amend 2 to FSAR
 VAN BRUNTLE E Arizona Public Service Co 80/09/29 1p.
- --B009300405 Amend 2 to FGAR responding to NRC 800618 questions & correcting text App 148 & aversize drawings entl # Arizona Public Service Co 80/09/29 300p
- d Inspection reports. IE Bulletins & correspondence
- 8009030674 Responds to IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Facility design incorporates butt wilded sizeve connections for continuity of containment boundary Sixty-three joints have been welded VAN BRUNT, E. Arizona Public Service Co. 80/07/08. 2pp
- 8007050479 Requests 60-day extension to respond to IE Bulletin 79-03A-"Longitudinal Heid Defects in ASME 8A-312, Type 304 Etelnless Steel Pipe " VAN BRUNT, E E Arizona Public Service Co 80/07/16 ip
- 209120272 Forward: 1E Insp Repts 50-528/80-10.50-529/80-10 & 50-530/80-10 on 800602-27 No nencompliance noted SPENCER.O S. Region 5. San Frencisco, Reactor Construction & Engineering Support Branch 80/08/05 2pp
- -8009120296 1E Insp Repte 50-528/80-10,50-529/80-10 & 50-530/80-10 on BOD602-27 No noncompliance noted Major areas inspected. installation of Unit 1 spray pond piping & Unit 2 dome spray headere DODDS, R T Region 5. San Francisco. Reactor Construction & Engineering Support Branch VORDERBRUEGGEN Region 5. San Francisco. Office of the Director 80/08/05 6jp.
- E009:20234 Responds to IE Sulletin 80-16 No Rosemsunt Model 115: & 1152 pressure transmitters are used in any safety-related applications VAN SRUNT, E E Arizona Public Service Co 80/08/11 fp.
 - 9120496 Forwards IE Insp Repts 30-528/80-08,50-529/80-08 & 0-530/80-08 on 800520-23 No noncompliance noted PENCER,0 8 Region 5. San Francisco. Reactor Construction & agineering Support Branch. 80/08/12 2pg
 - pu09120500 IE Insp Repts 50-528/60-08,50-529/60-08 & 50-530/60-08 on 800520-23 No noncompliance noted Major areas inspected const ectivities, preheat & post-weld treatment & containment liner welding containment liner welding DODDS: R T Region 5, San Francisco, Reactor Construction & Engineering Support Branch ECKHARDT. J H, NARBUT, P. P. Region 5, San Francisco, Office of the Director 80/08/11 7pp
 - 9030276 Forwards Revision I to IE Bulletin 80-19. "Failures of ercury-Metted Matrix Relays in Reactor Protective Sys of perating Nuclear Power Plants Designed by C-E " Written esponse required. "VCELKEN.R.H Region 5, San Francisco, Office of the Director #0/08/15 1p
 -)9290307 Forwards IE Info Notice 80-27, "Degradation of Reactor solant Pump Studs." No written response required NOELKEN, R H Region 9, San Francisco, Office of the Director 10/08/18 4pg
 - 9140178 Forwards IE Circular 80-18, "IOCFR50 59 Safety Evaluations or Changes to Radwaste Treatment Sys " No written response equipad NOELKEN.R H Ragion 5, San Francisco, Office of the Director O/08/22 ip
 -)9190159 Forwards IE Inep Repts 50-528/80-11, 50-529/80-11 & 10-530/80-11 on 600610, No noncompliance noted MOELKEN, R H Region 5, San Francisco, Office of the Director 10/09/22 Ip

- --8009190169 IE Insp Repts 50-528/80-11.50-529/80-11 & 50-530/80-11 on 800610. No noncompliance noted Major areas inspected meeting to discuss results of Region 5 licenses performance evaluation for May 1979 through May 1980 ENDELKEN, R H. VURDERERUEGGEN Region 5, can Francisco. Office of the Director SpENCER, O S. Region 5, Sen Francisco. Reactor Construction & Engineering Support Branch 60/08/20 4pp.
- --B009190178 Discusses semiannual regional evaluation of facilities for May 1979 through May 1980 Licenses performance is generally satisfactory & strong licenses effort should be made to ensure current & future work is adequately controlled DIDDG: R Y Region 5. Sen Francisco, Reactor Construction & Engineering Support Branch ECKHARDT.J H., VORDERRRUEGOEN Region 5. Sen Francisco, Diffice of the Director B0/08/20 Epp
- 8009:20456 Forwards IE Info Notice 80-3; "Maloperation of Gould-Brewn Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breekers " No written response required ENGELKEN,R H Region 5, Sen Francisco, Office of the Director, 80/08/27 1p
- S Reportable occurrences, LERs & related correspondence
- 8009020528 Ack receipt of final deficiency rept re Borg-Werner valve stem extension loosening problem ENGELKEN.R H Region 5, San Francisco, Office of the Director. 80/08/15 ip
- --8007020332 Final deficiency rept ra Borg-Werner valve stem extension lossening problem Mod to correct deficiency will be completed prior to startup.

 VAN BRUNTLE E Arizona Public Bervice Co 80/07/29. 3pp.
- 8007030556 Final deficiency rept re undersized structural steel fillet welds Welds are sufficient to hendle design loading while providing adequate sefety margin for crack prevention Dispositioned as not reportable VAN BRUNT, E.E. Arizona Public Service Co. 80/08/25. app.
- --8007030563 "Evaluation of Structural Fillet Weld Samples for Underbead Cracking." FULLING.C., SCHMIDT, G.R., HACKNEY, B.D. Bachtel National, Inc 80702706. 30pp
- 8009230653 final deficiency rept re failure of vertical fire despers to close Investigation of closure problem determined that dasign tolerances not meintained between frame & damper slide Deficient frame & damper blade will be replaced.

 VAN BRUNT, E. E. Arizone Public Service Co 80/09/15 7pp.
- T. Hearing transcripts on non-antitrust matters
- BOOTi60373 Forwards transcript of 800709 review re Class IE at power sys Includes discussion of open items re review board & NRC unenswered questions & requests for info.

 VAN SRUNTLE, E. Arizone Public Service Co 80/07/ii ip.
- ---B009160379 Transcript of B00709 review re Class IE ac power sys in Bethesda.MD.Pp 1-195,W/supporting documentation + Arizona Public Service Co. 80/09/11. 275pp.
- DOCKET STN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8009030285 Responds to 800417 request for info re NRC involvement in archeological data recovery activities for FY79. Completed questionnairs encl.
 DENTON H R. Office of Nuclear Reactor Regulation, Director.
 80/06/11. 7pp
- BOO9080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days, Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/a NUREO EISENHUT, D O Division of Licensing, 80/08/01, 119pp.
- BOO7020335 Notification of BOOB15 meeting w/util in Bathesda:MD to discuss whether auxiliary feedwater sys meets design criteria KERRIGAN, J. Licensing Branch 3 80/08/14 2pp.

- BOO9120551 Notification of B00821 & 22 meeting w/util in Phoenix AZ to discuss auxiliary feedbater sys review KERRIOAN, J. Licensing Branch 3 80/08/15 3pp
- 3009030511 Bubmits response to NRC 800421 info request on Category 1 masonry walls employed by plants under CP & OL review Drawings 13-A-ZJD-509 through 511.13-A-ZAD-203 & 13-A-ZAD-207 available in Central Files
 VAN ERUNT,E E Arixona Public Service Co 80/08/25 3pp
- BOO9120508 Forwards updated distribution list for suppl & emend to FBAR & environ rapt Supersedes 800618 list XERRIGAN, J Licensing Branch 3 80/08/25, 5pp
- 9009070523 Forwards comments of util review board re open items from Gless IE dc power sys review Bix items identified which require addicterification VAN BRINKTIE E Arizone Public Service Co 80/09/04 App.
- 9009150338 Advises that ABME Code Ceses N-274 & N-275 mey be used in ploing Spec 13-DM-204 subj to conditions re ferritic matls for N-274 & full weld thickness removal for N-275 Code cases should be documented in FBAR TEDESCORR L Assistant Director for Licensing 80/09/04 3pp
- BOO9180534 Notification of 800925 sys review meeting w/util & Bechtel in Phoenix: AZ re equipment qualification Agenda ancl KERRIGAN, J D Licensing Branch 3 80/09/05 3pp
- 9009160595 Notification of 800925 meeting w/util & Bechtel in Phoenix.
 AZ to conduct sys review maeting re equipment qualification
 KERRIOAN, J. D Licensing Brench 3 80/09/12 3pp
- BOC9240422 Forwards Bechtel Power Corp responses to outstanding open items of Class IE do power sys review Responses are intended to resolve outstanding concerns of DC Power Sys Raview Board, Final resolution of open items will be provided VAN BRUNT, E. E. Arizona Public Service Co. 80/09/18 12pp
- C Utility Environmental Report (ER), amends & correspondence
- BOO912050B Forwards updated distribution list for suppl & amend to FBAR & environ rept Supersedes BOO618 list KERNIGAN, J. Licensing Branch 3 80/08/25 5pp
- SOOPO90392 Forwards Suppl 1 to environ rept for fecility
 VAN BRUNT, E E Arlzona Public Service Co 80/09/08 1p
- --8009070378 Suppl i to facility environ rept.
- DO09230701 Forwards proof of svc for Suppl 1 to environ rept.OL stage required by 10CFR2.101 & D Eisenhut 800608 1tr UAN BRUNT, E.E. Arizona Public Service Co 80/09/15 5pp
- P. Security, medical, emergency & fire protection plans
- BOO9D30262 Notifies of 800819.22 & 30 regional workshops re development of guidance for acceptable method for coping w/emergencies at facility. Requests that representative be sent Subj arees to be discussed include function of facilities & location. EXOELKEN.R.H Region 5, San Francisco, Office of the Director 80/09/12, 2pp.
- >. Adjudicatory correspondence
- POOPO30714 Response in opposition to PL Hourihan K Dahl & C Shuey BOOS11 petition to intervene Petitioners failed to establish standing or specify interest Aspects affecting petitioners not identified H/Certificete of Svc.

 OCHM: A C., BISCOFF.C. A Arizone Public Service Co GEHR: A C. Shell & Nilmer 30/08/26 Opp
- MOG9040276 Response in support of P Hourihan 800811 petition to Intervene & request for hearing conditioned on particularization of aspects of concern Supports holding heerings in Phoenix area. W/appearance & Certificate of Svc #SCOURREN, H. J Hearing Branch & 80/09/02 11pp.
- PODPOB0514 Notice of establishment of ASLB to preside in OL applications, environ rept & opportunity for hearing proceedings, RM Lezo appointed chairman, RF Cole & B Gallahan members

 LAZO, R & Atomic Safety and Licensing Board Panel 80/09/03 2pp.

- 8009100457 Ack receipt of 800705 ltr & forwards criends of the Earth Class 9 petition & Director's decision on petition W/o encl SCHWENCER: A Licensing Branch 2 80/08/27 2pp
- --8009100463 Requests Director's decision on Friends of the Earth patition to consider Class 9 accidents in supplemental EIS FRIEBEKA, H P Northwestern Univ 80/07/05 ip
- 30090500B3 Forwards B00725 FR notice re procedurel assistance change in adjudicatory licensing proceedings.per 800902 telcon. W/o encl MCGURREN, H J Hearing Branch 1 80/09/03. 1p
- 8009250466 Responds to 800620 ltr re NRC licensing procedures.rules of practice, docketing procedures 8 milestones for fecilities 8CKMENCER.A Licensing Branch 3 80/09/12 Zpp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8009120508 Forwards updated distribution list for suppl & emend to FBAR & environ rept Supersedes 800618 list KERRIGAN, J Licensing Branch 3 80/08/25. 5pp
- 8009300402 Forwards Amend 2 to FSAR
 VAN BRUNT, E E Arizona Public Service Co 80/09/29 ip
- ---B007300405 Amend 2 to FSAR, responding to NRC B00618 questions & correcting text App 148 & oversize drawings enc! * Arizona Public Service Go B0/09/29 300pp
- G Inspection reports, 1E Bulletins & correspondence
- 8009030674 Responds to 1E Bulletin BO-08, "Exem of Conteinment Liner Penstration Wolds " Facility design incorporates butt welded sleeve connections for continuity of containment boundary Bixty-three joints have been welded VAN BRUNT, E.E. Arizona Public Service Co. 80/07/08 2pp
- 8007050497 Requests 40-day extension to respond to IE Bulletin 79-03A. "Longitudine! Weld Defects in ASME SA-312. Type 304 Btainless Steel Pipe"

 VAN BRUNT, E. E Arizona Public Service Co 80/07/10. 1p
- 8007120272 Forwards 1E Insp Repts 50-528/80-10,90-927/80-10 & 50-530/80-10 on 800602-27 No moncompliance noted BPENCER. G 8 Region 5, 8an Frencisco, Reactor Construction & Engineering Support Branch 80/08/05 2pp
- --E009120276 1E Insp Repts 50-528/60-10,50-529/60-10 & 50-530/60-10 on B00602-27 No noncompliance noted Major areas inspected: installetion of Unit i spray pond piping & Unit 2 dome spray headers DODBS, R T Region 5, San Francisco, Reector Construction & Engineering Support Branch VORDERBRUEGOEN Region 5, San Francisco. Office of the Director 80/08/05 App
- 8009120234 Responds to IE Bulletin 80-16 No Rosemount Model 1151 & 1152 pressure transmitters are used in any sefety-related epplications VAN BRUNT,E E Arizona Public Service Co 80/08/11 lp.
- 8007120474 Forwards IE Insp Repts 50-528/80-08.50-529/80-08 & 50-530/80-08 on 800520-23 No noncompliance noted SPENCER. @ 8 Region 5, Sen Francisco, Reactor Construction & Engineering Support Branch 80/08/12 2pp
- 1009120500 IE Insp Repts 50-528/80-03.50-529/80-08 & 50-530/80-08 on 800520-23 No noncompliance noted Major areas inspected const activities, preheat & post-weld treatment & containment liner welding DODDS, R T. Region 5, 8an Francisco, Reactor Construction & Engineering Support Branch, ECKHARDT, J H , NARBUT, P. P. Region 5, 8an Francisco, Office of the Director 80/08/11 7pp.
- B007030276 Forwerds Revision 1 to 1E Bulletin 80-19. "Failures of Marcury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Writtan response required EXOELKEN,R H Region 5, San Francisco, Office of the Director 80/08/15 ip
- 8007290307 Forwards 1E Info Notice 80-27, "Degradation of Reacter Coolant Pump Stude " No written response required ENGELKEN, R H Region 5, San Francisco. Office of the Director 80/08/18 4pp

- 8009160178 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/08/22 10
- E009170159 Forwards IE Insp Repts 50-528/80-11, 50-529/80-11 & 50-539/80-11 on 800410 No noncompliance noted ENSELMEINR H Region 5. San Francisco. Office of the Director. 80/08/22 1p
- --8009190169 IE Insp Repts 50-528/BO-11.50-529/BO-11 & 50-530/BO-11 on BO0610 No noncompliance noted Major areas inspected meeting to discuss results of Region 5 licensee performance evaluation for May 1977 through May 1980 ENGELHEN, R H, VURDERERUEDGEN Region 5. San Francisco, Office of the Director SPENGER, G S Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/08/20 App
- --BC09190178 Discusses semiannual regional evaluation of facilities for May 1979 through May 1980 Licensee performance is generally satisfactory & strong licensee effort should be made to snaure current & future work is adequately controlled DDDDS.R T Region 5, San Francisco, Reactor Construction & Engineering Support Branch ECKHARDT.J H, VORDERBRUEOGEN Region 5, San Francisco, Office of the Director BO/08/20 Spp
- 8009120456 Forwards IE lnfo Notice 80-31. "Meloperation of Gould-Brown Bovari 480 Volt Type K-6005 & K-DON 6005 Circuit Breakers " No written response required ENGELKEN.R H Region 5. San Francisco. Office of the Director 80/09/27 Ip
- } Reportable occurrences, LERs & related correspondence
- 3009020528 Act receipt of final deficiency rept re Borg-Warner valve stem extension loosening problem ENGELKEN.R.H Region S, San Francisco, Office of the Director 80/08/15 ip
- --E009020532 Final deficiency rept re Borg-Warner valve stem extension loosening problem Mod to correct deficiency will be completed prior to startup VAN BRUNT, E E Arizona Public Service Co 80/07/29 3pp
- BOOPO30556 Final deficiency rept re undersized structurel steel fillet welds Helds are sufficient to handle design loading while providing adequate safety margin for crack prevention Dispositioned as not reportable VAM BRUNT, E E Arizona Public Service Co 80/08/25 6pp
- --8009030563 "Evaluation of Structural Fillet Held Samples for Underbead Cracking " FULLINS: C. SCHMIDT: O.R. HACKNEY, B.D. Bechtel National, Inc. B0/02/04 30pp
- 3007230553 Final deficiency rept re failura of vertical fire dampers to close investigation of closure problem determined that design tolerances not maintained between frame & damper slide Deficient frame & damper lade of
- 800930035 Final deficiency rept re dowel ommission from concrete wall pours of control bldg Condition is being corrected following approved deposition to drill & grout required dowels into wall following design drawing requirement VAN ERUNT, E E Arizona Public Service Co 80/09/24, 3pp.
- T Hearing transcripts on non-antitrust matters
- 8009160373 Forwards transcript of 800709 review re Class IE ac power sys Includes discussion of open items re review board & NRC unanswered questions & requests for info VAN BRUNT, E. Arizona Public Service Co. 80/09/ii, 1p
- --B009160379 Transcript of B00709 review re Class IE ac power sys in Bethesda, MD Pp 1-195 W/supporting documentation. * Arizona Public Service Co B0/09/ii 275pp.
- DOCKET STN-50-530 PALO VERDE NUCLEAR STATION, UNIT 3

 A Application/construction stage documents & correspondence
- 8009030285 Responds to 800417 request for info re NRC involvement in archeological data recovery activities for FY79, Completed questionnaire encl DENTON-HR Office of Nuclear Reactor Regulation: Director 80/06/11 7pp

- 8009080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl M/o NUREG EISENMUT, D O Division of Licensing 80/08/01 119pp
- 8009020335 Notification of 800815 mesting w/util in Bethesda. MD to discuss whother auxiliary feedwater sys meets design criteria KERRIGAN. J. Licensing Branch 3 80/08/14 2pp
- 8009120551 Notification of 800821 & 22 meeting w/util in Phoenix, AZ to discuss auxiliary feedwater sys review KERRIOAN, J Licensing Branch 3, 80/08/15 3pp
- B009030511 Submits response to NRC B00421 info request on Category 1 masonry walls employed by plants under CP & OL review Drawings 13-A-ZJD-509 through 511:13-A-ZAD-203 & 13-A-ZAD-207 available in Central Files VAN BRUNT.E E Arizona Public Sarvice Co 80/08/25 3pp.
- 8009120508 Forwards updated distribution list for suppl & amend to FBAR & environ rept Supersedes 800618 list KERRIGAN.J Licensing Branch 3 80/08/25 5pp
- 8009090523 Forwards comments of util review board re open items from Class IE &c power sys review Bix items identified which require addl clarification
 VAN BRUNT, E E Arizona Public Service Co 80/09/04 4pp
- 8009180538 Advises that AGME Code Cases N-274 & N-275 may be used in piping Spec i3-DM-204 subj to conditions re ferritic matls for N-274 & full weld thickness removal for N-275. Code cases should be documented in FSAE TEDESCO.R L Assistant Director for Licensing. 80/09/04 Spp.
- 8009180534 Notification of 800925 sys review meeting w/util & Bechtel in Phoenix,AZ re equipment qualification Agenda ancl KERRIGAN.J D Licensing Branch 3 80/09/05, 3pp
- B009160595 Notification of B00925 meeting w/util & Sechtel in Phpenix, AZ to conduct sys review meeting re equipment qualification. KERRIGAN, J D Licensing Branch 3, 80/09/12, 3pp
- 8009240422 Forwards Bechtel Power Corp responses to outstanding open items of Class IE dc power sys review Responses are intended to resolve outstanding concerne of BC Power Sys Review Board. Final resolution of open items will be provided. VAN DRUNTLE E. Arizona Public Service Co 80/09/18 12pp
- C Utility Environmental Report (ER), amends & correspondence
- 8009090392 Forwards Suppl 1 to environ rept for facility. VAN BRUNT, E E Arizone Public Service Co 80/09/08 1
- --8009090398 Suppl 1 to facility environ rept.
 # Arizona Public Service Co. 80/09/30. 53pp
- 8009230701 Forwards proof of svc for Suppl 1 to environ rept.OL stage required by 10CFR2 101 t D Elsenhut 800608 ltr VAN SRUNT, E E Arizona Public Service Co 80/09/15 Spp.
- F Security, medical, emergency & fire protection plans
- 8009030262 Notifies of 800819.22 & 30 regional workshops re development of guidance for acceptable method for coping w/emergencies at facility Requests that representative be sent 80b; areas to be discussed include function of facilities & location. ENGELKEN,R H Region 5, San Francisco, Office of the Director. 80/08/12 2pp
- 9 Adjudicatory correspondence
- 8009030714 Response in opposition to PL Hourihan,K Dahl & C Shuey 800811 petition to intervene Petitioners failed to establish standing or specify interest Aspects affecting petitioners not identified. W/Certificate of Svc OEHR, A. C. BISCOFF, C. A. Arizona Public Service Co OEHR, A. C. Biscoff, C. Opp.
- 8007040274 Response in support of P Hourihan 800811 petition to intervene & request for hearing, conditioned on particularization of aspects of concern Supports holding hearings in Phoenix area Myappearance & Certificate of Svc. NCGURREN, H J Hearing Branch 1 80/09/02 11pp

- BOOTOBOSIA Notice of establishment of ASLB to preside in OL applications environ rept & opportunity for hearing proceedings RM Leso appointed chairmen.RF Cola & B Callahan mambers LAZO.R M Atomic Bafaty and Licensing Board Panel 80/09/03

- BOG9100457 Ack receipt of 800705 ltr & forwards Friends of the Earth Class 9 patition & Director's decision on patition W/o ancl, BCHMENCER.A Licansing Branch 2 80/08/27 2pp
- ---BOO9100463 Requests Director's decision on Friends of the Earth getition to consider Class 9 accidents in supplemental EIB FRIESMA, H P Northwastern Univ BO/07/05 ip
- 8009050083 Forwards 800725 FR notice re procedural assistance change in adjudicatory licensing proceedings.psr 800902 telcon W/g encl MCGURREN.H J Hearing Branch 1 80/09/03 1p
- 8009250466 Responds to 800620 ltr re NRC licensing procedures, rules of practice, docksting procedures & milestones for facilities 80HWENCER, A Licensing Branch 3 80/09/12 2pp
- K. Utility Final Safaty Analysis Report (FSAR) & amands
- GOO712050B Forwards updated distribution list for suppl & amend to FSAR & environ rept Supersedus SOO60E list KERRICARY J. Licensing Branch 3 80/08/25 5pp
- 8009300402 Forwards Amand 2 to FBAR.
 VAN ERUNT, E E Arizona Public Servica Co 80/09/29 1p.
- -8009300405 Amand 2 to FBAR, responding to NRC 800618 questions & correcting text App 148 & oversize drawings and # Arizona Public Service Co 80/09/29 300pp
- Q Inspection reports, IE Bullatins & correspondence
- 8009030674 Responds to IE Bullatin 80-08, "Exam of Containment Liner Penetration Welds." Facility design incorporates butt welded sleeve connections for continuity of containment boundary Sixty-three joints have been welded VAN ERUNT.E E Arizona Public Bervice Co. 80/07/08 2pp
- BOO9050A99 Requests AO-day extension to respond to IE Bullstin 79-03A. "Longitudinal Weld Defects in ABME 8A-312, Type 304 Stainlass Steel Pips."
 VAN BRUNT, E E Arizona Public Service Co 80/07710 ip
- BOO9120292 Forwards IE Insp Rapts 50-528/80-10,50-529/80-10 & 50-530/80-10 on 800&602-27. No noncompliance noted. BPENCER, O S. Ragion J. Ban Francisco, Reactor Construction & Engineering Support Branch 80/08/05 2pp.
- --BOO9120296 IE Insp Rapts 50-528/80-10.50-529/80-10 & 50-530/80-10 on 800602-27.No noncompliance noted Major areas inspected installation of Unit 1 spray pond piping & Unit 2 dome spray DODDS,R.T. Region 5, Ban Francisco, Reactor Construction & Engineering Support Branch, VORDERBRUEGGEN Region 5, San Francisco, Office of the Director 80/08/05. App.
- 8007120234 Responds to IE Bulletin 80-16 No Rosamount Model 1151 & 1152 pressure transmitters are used in any safety-related applications. VAN BRUNTLE E Arizona Public Service Co 80/08/11 ip.
- 9007120494 Forwards IE Insp Rapts 50-528/80-08,50-529/80-08 & 50-530/80-08 on 800320-23 No noncompliance noted SPENCER.9 B Region 5, Ban Francisco, Reactor Construction & Enginearing Support Branch. 80/08/12 2pp
- --8009120500 IE Insp Repts 50-528/80-08,50-529/80-08 & 50-530/80-08 on 800520-23 No noncompliance noted Major areas inspected const activities, preheat & post-weld treatment & containment liner welding
 DODDE,R T. Region 5, Ban Francisco, Reactor Construction &
 Engineering Support Branch. ECKHARDT,J H, NARBUT,P P. Region 5,
 Ban Francisco, Office of the Director BO/08/11. 7pp
- B009030276 Forwards Revision 1 to IE Bulletin S0-19, "Failures of Marcury-Hetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E." Written response required.
 ENOELKEN.R. # Region 5. San Francisco. Office of the Director. ENCELMENTR, H Region 5. San Francisco, Office of the Director. 80/08/15. 1p.

- 8009290307 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Fump Bluds " No written response required ENGELKEN.R H Ragion 5. San Francisco, Office of the Director 80/08/18. 4pp
- 8009160178 Forwards IE Circular 80-18, "10CFR50 59 Safaty Evaluations for Changes to Radwaste Treatment Sus " No written response raquired ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/08/22
- 8009190159 Forwards IE insp Repts 50-528/80-11, 50-529/80-11 & 50-530/80-11 on 800610 No noncompliance noted ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/08/22 10
- --8009190169 IE lnsp Repts 50-528/80-11.50-529/80-11 & 50-530/80-11 on B00610 No noncompliance noted Major areas inspected meeting to diacuss results of Region 5 licensee performance evaluation for May 1979 through May 1990 ENGELKENR H , VORDERBRUEGEN Region 5, San Francisco. Office of the Director SPERCERIO S Region 5, San Francisco. Reactor Construction & Engineering Support Branch 80/08/20 4pp
- --800919017B Discusses semiannual regional avaluation of facilities for May 1979 through May 1980 Licenses performance is generally astisfactory & strong licenses effort should be made to answer current & future work is adequately controlled DODDB.R T Region 5. San Francisco. Reactor Construction & Engineering Support Branch ECKHARDT.J H , VORDERBRUEGGEN Region 5. San Francisco. Office of the Director 80/08/20 8pp
- 8009120456 Forwards IE Info Notice 80-31, "Maloparation of Gould-Brown Bovari 480 Voit Tupa K-6008 & K-DON 6008 Circuit Breakers" No writtan response required ENGELKEN:R H Region 5, San Francisco, Office of the Director 80/08/27 1p
- S. Reportable occurrences, LERs & related correspondence
- 8007020528 Ack receipt of final deficiency rapt ra Borg-Warner valve stem extension loosening problam ENGELKEN, R H Region 5, San Francisco, Offica of the Diractor 80/08/15 ip
- --B009020532 Final deficiency rapt ra Borg-Warner valve stam extansion loosening problem Mod to correct deficiency will be completed prior to startup VAN BRUNTLE E Arizona Public Service Co. 80/07/29 3pp
- 8009030556 Final deficiancy rapt ra undersized structural steel fillet walds Helds are sufficient to handle design loading while providing adequate selety margin for crack prevention. Dispositioned as not reportable VAN BRUNT, E.E. Arizone Fublic Service Co. 80/08/25 6pp
- --B009030563 "Evaluation of Structural Fillet Weld Samples for Underbeat Cracting " PULLING.C , SCHMIDT, Q R , HACKNEY, B, D Bechtel National, Inc. B0/02/05 30pp
- 8007230653 Final deficiency rapt we failure of vertical fire dempers to closs Investigation of closure problem determined that dasign tolerances not maintained between frame & dampar slide. Deficient frame & damper blade will be replaced.

 VAN BRUNT.E.E. Arizona Public Service Co. 80/09/15 7pp
- T Haaring transcripts on non-antitrust matters
- 8009160373 Forwards transcript of 800709 review re Class IE ac power sys. Includes discussion of open items re review board & NRC unanswered questions & requests for info.

 VAN BRUNT, E. Arizona Public Bervice Go 80/09/11 ip.
- --8009160379 Transcript of 800709 raview re Class IE ac power sys in Bethesda: MD Pp 1-195. W/supporting documentation # Arizona Public Servica Co. 80/09/11 275pp

DOCKET 50-534 0080EN

- P. Operating license stage documents & correspondence
- 8009260466 Application by OE to amand license to export U to Buitterland by adding Fabricationi Nucleari as intermediata consignes, WOLFE B. General Elactric Co. 60/09/16 2pp

DOCKET 50-537 CLINCH RIVER BREEDER REACTOR

- A Application/construction stage documents & correspondence
- 8007020014 Forwards "Clinch River Breeder Reactor Plant Fuel Assembly Structural Analysis in Support of Final Design Review," as partial response to Question 7 of IP Spens 751006 ltr Add1 rept will be submitted COPELAND.R L Energy, Dept of, Clinch River Breeder Reactor Plant 80/08/22 ip
- --B009020017 "Clinch River Breeder Reactor Plant Fuzi Assembly Structural Analysis in Support of Finel Design Revieu " PREVENSLIK.T.V. SAKE, A D., BITNER.J L Westinghouse Electric Corp GRURP-ARD-0204 78/01/31 387pp
- B Utility Preliminary Safety Analysis Report, emends
- 8009020002 Amend to application for OL Forwards Amend 56 to PSAR COPELAND.R L Energy.Dept of Clinch River Breeder Reactor Plant 80/08/29 4pp
- --B009020003 Amend 56 to PSAR

 * Energy, Dspt of, Clinch River Breeder Reactor Plant 80/08/29
 125pp.
- 8009090549 Forwards affidavit confirming distribution of Amend 56 to PSAR to designated local public officials & representatives of EPA COPELAND, R L Energy, Dept of 80/09/05 2pp
- BOG9090575 Forwards affidavit confirming distribution of Amend 36 to facility PSAR to EPA & local officials Related correspondence COPELAKO, R L Energy, Dept of, Clinch River Breeder Reactor Plant BO/09/05 2gp

DOCKET STN-50-546 MARBLE HILL NUCLEAR STATION, UNIT I

- A Application/construction stage documents & correspondence
- BOOODBODED Forwards draft NUREC-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREC-0696 encl M/O NUREQ EISENHUT, D O Division of Licensing 80/08/01 119pp
- 8009180533 Submits add1 cheracterizations of two cetegories of surface irregularities identified & mapped in accordance w/const verification program
 SHIELDS.S W Public Service Co of Indiena. Inc 80/08/13 3pp
- 3009180521 Submits clarification & commitments on repairs & evaluations for concrete patches & repair aress identified to date & which asy be identified in future SHIELDS.S H Public Service Co of Indiana, Inc. 80/08/25 2pp.
- 3009030500 Requests that NRC forward nomination form to Keeper of Netl Register for final determination re digibility of McKiell Stone Fort (Site 12 JE 4) located at planned power location along Marble Hill-Columbus transmission line SHIELDS.S W Public Service Co of Indiana. Inc 80/08/27 2pp
- 9009260071 Submits interim actions for pient operation pending final resolution of ATMS Emergency operation procedural review may include NRC site visit prior to issuance of OL TEDESCO.R.L. Assistant Director for Licensing 80/09/12. Spp
- BOO929D31: Forwards "Const & Metl Varification Program." final rept, Presents results & conclusions of QA program per App Item C.1 & 2 & Item D.1 & 2 of V Stello BOO515 graduated recission order SHIELDS.B W Public Service Co of Indians. Inc BO/09/12 2pp.
- --8009290513 "Const & Hatl Verification Program," final rapt * Public Service Co of Indiana, Inc 80/09/30 725pp
- F Security, medical, emergency & fire protection plans
- B009090702 Confirms util interpretation of Evaluation Criteria J 6 of NUREO-0654/FEMA-REP-1: in response to 800718 request Criteria apply to staff remaining onsite during radiological emergency Language will be clarified GRIMES, B K Emergency Preparedness Program Office 80/08/28 1p.

- G Adjudicatory correspondence
- 8009300094 Responds to NRC 800515 graduated recission of 790815 order & requests partial lifting of order confirming suspension of const Util has completed activities prerequisite for receipt insp SHIELDS.8 W Public Service Co of Indiana, Inc 80/08/26 2##
- 8009180226 Forwards Director's decision under 10CFR2 206 denying Save the Valley request for action re resumption of work at facility DENTON: H R Office of Nuclear Reactor Regulation. Director 80/09/02 4pp
- --8009180232 Director's decision under 10CFR2 206 denuing Bave the Vallsg request for action re resumption of work at facility Evidence of extension of fault zone towards plant site is inconclusive DENTON.H R Office of Nuclear Reactor Regulation, Director. 80/09/02 6pp.
- --8009180237 Notifies of 771129 site visit to examine foundation master in response to NRC request, Mamorandum rept on visit and BROWN, F.R. Army, Dept of, Corps of Engineers, 77/12/12 3pp
- --8009180242 Notice of issuance of Director's decision under 10CFR2 204 DENTON:H R Office of Nuclear Reactor Regulation, Director 80/09/02 2pp
- S009260467 Order granting extension until S01006 for Commission to elect whether to review Director's decision under 10CFR2 206 CHILK:S J Office of the Secretary of the Commission 80/09/23
- H Owneral correspondence
- 8007070574 Forwards organizational changes revising organization description in QA program
 SHIELDS, S. W. Public Service Co. of Indiana, Inc. 80/09/02 1
- --8007070580 Organizationel changes revising QA program.New organization charts re project, project engineering, project conet.project control.project administration, QA & project testing enci.

 * Public Service Co. of Indiana. Inc. 80/09/02 7pp
- 6009300452 Advises that WM Petro assumed full responsibilities as project director affective 600919 SHIELDS,5 H Public Service Co of Indiana, Inc 60/09/23, 1p
- @ Inspection reports. IE Bullevane & correspondence
- 8009150172 Forwards IE Insp Repts 50-846/80-25 & 50-547/80-25 on 800&01-30 No noncompliance noted FIGRELI, G Region G. Chicago, Reactor Construction & Engineering Support Branch 80/07/28 2pp.
- --8009150177 IE Insp Repts 50-546/80-25 & 50-547/80-25 on 800601-30. No noncompliance noted Major areas inspected auxiliary bldg, fuel handling bldg.Upits 1 & 2 containments & storage & maint facilities for safety-related items WILLIAMS.C C . HARRISON.J J Region 3. Chicago, Office of the Director 80/07/25 App
- 8009110764 Forwards IE Insp Repts 50-546/80-21 & 50-547/80-21 on 800603-06 & 0707-11 No noncompliance noted FIORELLI.® Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/07/31, 2pp
- --B009110769 IE Insp Repts 50-546/80-21 & 50-547/80-21 on 800603-06 & 0707-11 No noncompliance noted Major areas inspected blasting work completed ESP line backfill work & comet verification procedures HAYES.D W Region 3. Chicago. Reactor Construction & Engineering Support Branch HAWINS.F C., HARRIS.J R. Region 3. Chicago. Office of the Director 60/07/29. App
- 8007180211 Forwards IE Insp Repts 50-546/80-24 & 50-547/80-24 un 800524-27 No noncompliance noted, KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/05 2pp
- --800718022: IE Insp Repts S0-546/80-24 & 50-547/80-24 on 800624-27, No noncompliance noted Major areas inspected GA/GC insp personnel qualifications > relationship between project GA manual & ASME GA manual FIORELLI, 0 Region 3, Chicago, Rector Construction & Engineering Support Branch SCHMERIBINZ, E R. HARRIGON, J. J. Region 3, Chicago, Office of the Director 80/08/04 11pp.

.

- 8009150894 Forwards IE Insp Repts 50-546/80-23 & 50-547/80-23 on 800610-12, 16-20 & 26-27 & notice of violation FIGRELLI, © Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/07 2pp
- --8009180600 Notice of violation from insp on 800610-12, 16-20 & 26-27 * Region 3, Chicago, Office of the Director 80/08/05 ip
- --8009150602 IE Insp Repts 50-546/80-23 & 50-547/80-23 on 800610-12.
 16-20 & 26-27 Noncompilance noted failure to follow procedures in implementation of Special Process Procedure 7 SCHMETBINZ. E. ERB. CM. CORDERO, Z C. Region 3. Chicago, Office of the Director 80/08/05 11pp
- 8009030213 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Hercury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nucleer Power Plants Designed by C-E " Written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/08/15 is
- 8007270104 Forwards IE Insp Repts 50-546/80-27 & 50-547/80-27 on 800717-18 No noncompliance noted FIORELLI, G. Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/08/19 2pp
- --8009290107 IE Insp Repts 50-546/80-27 & 50-547/80-27 on 800717-18 No noncompliance noted Major areas inspected technical adequacy of util action re Marble Hill concrete issue MAMKINS.F. C , HAVES.D W Region 3, Chicago, Office of the Director 80/08/18 3pp
- 6009290110 Forwards IE Insp Repts 50-546/60-29 & 50-547/60-29 on 800729-0801 No noncompliance noted FIORELLI.0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/08/19 2pp
- --B009290114 IE Insp Repts 50-546/80-29 & 50-547/80-29 on 800729-0801.No noncompliance noted, Major ereas inspected nondestructive examination. Lab equipment & procedures, personnel certifications & radiographs of field welds SCHAPKER.JF Region 3, Chicago, Office of the Director DANIELEON, D. H. Region 3, Chicago, Resctor Construction & Engineering Support Brench 80/08/18 App.
- 8009170436 Forwards IE Circular 80-18, "10CFR50 59 Bafety Evaluations for Changes to Radwaste Treatment Bye " No written response required.

 KEPPLER, J. W. Region 3, Chicago, Office of the Director 80/08/22 is
- BO09230079 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover: 48D Volt Type K-6008 & K-DON 6008 Circuic Breakers" No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/08/28
- 8009280447 Responds to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " No mercury-wetted relays are being used in reactor protection sys SHIELDB,8 W Public Service Co of Indiane, Inc 80/08/28 ip
- 9007180346 Responds to IE Bulletin 80-16 re potential misapplication of Rosemount pressure transmitters Identified transmitters will be installed but will not be subj to input pressures Bignal of differential pressure to be provided across tube BHIELDS, B. H. Public Service Co of Indiana, Inc 80/08/27 ip.
- BO09240116 Forwards IE Circular BO-21, "Regulation of Refueling Crews." No written response required KEPPLER.J. G. Region 3, Chicago, Office of the Director 80/09/10
- 8009270202 Ack receipt of 800820 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/80-23 & 50-547/80-23. FIDRELLIO Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/09/15 ip
- --B00929020B Reeponds to NRC 800807 ltr re violations noted in IE Insp Repts 50-546/80-23 & 50-547/80-23, Corrective actions.util util perform sudits of special process procedure program to ansure that required data are included in checklists. BHIELDS.S W. Public Service Co of Indiana, Inc. 80/08/20 3pp

- 5 Reportable occurrences, LERs & related correspondence
- 8009020249 Ack receipt of 800728 final rept re repair welds which were not reradiographed after repair welding was completed FIORELLIO Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/08/07 ip
- --8007020253 Final deficiency rept re regair sleave welds not reradiographed after repair welding was completed Ultrasonic testing of sleave welds performed indicating that welds were not defective but acceptable as is SHIELDS, BW Public Service Co of Indiana, Inc B0/07/28 ip Available at NRC nrc
- 8009150491 Ack receipt of 800730 interim deficiency rept re 46 of 49 documentation packages for Westinghouse supplied matta missing quality records Final rept will be reviewed upon receipt FIORELLI.O Region 3. Chicago, Reactor Construction & Engineering Support Branch 60/09/18 1p
- 8009030480 Interim deficiency rept re operation of centrifugal charging gumps during high energy line rupture Alternative mods being evaluated by Westinghouse Final rept will be submitted 80114
 SHIELD8.8 W Public Service Co of Indiana, inc 80/08/20 ip
- 8009040427 Interim deficiency rept re inadequate documentation of cadweld splice sampling & testing Reinsp & evaluation of cadweld splices is being parformed as part of const verification program Final rept will be submitted by 801001 SHIELDS,8 W Public Service Co of indiana, Inc 80/08/28 2p
- 8007100469 Interim deficiency rept re inability of contractor GA program to assure that AE design changes were incorporated into plant const activities Visual insp delayed Final rept will be submitted by 801601 GHIELDS,8 W. Public Service Co of Indiana, Inc 80/09/02 1p
- 8007250483 Ack receipt of 8008i3 interim deficiency rept re certain radiographs of steam generator upper lateral support ambedments not meeting density requirements of Section V of ABME BP&V code meeting density Reactor Construction & Engineering Support Branch 80/07/03 ip
- 8009250479 Ack receipt of 800820 interim rept re operation of centrifugal charging pumps during high energy line rupture FIORELLI, Q Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/09/08 ip
- --8009250482 Interim deficiency rept re centrifugal charging pumps during high energy line rupsure Westinghouse analyzed problem & recommended plant mode Final rept will be sent by 80iii4 SHIELD8.8 W Public Bervice Co of Indiana. Inc. 80/08/20. 1p
- 8009160400 Final deficiency rapt re possible nonconformances in reinforcing steel in areas of clear cover.member thickness & size of reinforcing bar Corrective actions described in Section 2 of "Const Verification Program"

 SHIELDS, S. W. Public Service Co. of Indiana, Inc. 80/09/11 2pp.
- 8009160419 interim deficiency rept re undercut welds, undersize fillet welds & incorrect weld contour on steel used to support pipe hangers Deficiencies being investigated Final rept will be submitted by 801215
 SHIELDS, B W Public Service Co of Indiana, Inc 80/09/11 ip
- 8009290197 Ack receipt of 800828 deficiency rept re Cadweid splice sampling & testing FIORELLIO Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/15, ip
- 8007240561 Potentially reportable deficiency rept re failure of previously inspected cadwelds to meet visual inspections. Noncomformance thoroughly evaluated including radiography Machanical splices will meet design strength requirements SHIELDS,8 W Public Service Co of Indiana, Inc 80/07/18 ip
- DOCKET 81N-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NURE9-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NURE9-0696 encl H/O NURE9 EISENHUT, D O Division of Licensing 80/08/01 117pp

- 8009180533 Submits addl characterizations of two categories of surface irregularities identified & mapped in accordance w/const verification program
 SHIELDS.S W Public Service Co of Indiana, inc 80/08/13 3pp
- 8007180521 Submits clarification & commitments on repairs & evaluations for concrete patches & repair areas identified to date & which may be identified in future SHIELDS-S W Public Service Co of Indiana, Inc. 80/08/25 2pp
- 8009030500 Requests that NRC forward nomination form to Keeper of Nati Register for final determination re eligibility of McNiell Stone Fort (Site 12 JE 4) located at planned power location along Marble Hill-Columbus transmission line SHIELDS.S N Public Service Co of Indiana. Inc 80/08/27 2;
- B009260071 Submits interim actions for plant operation, pending final resolution of ATMS Emergency operation procedural review may include NRC site visit prior to issuance of OL TEDESCO,R L Assistant Director for Licensing 80/09/12 5pp
- 8009290511 Forwards "Const & Matl Verification Program," final rept Presents results & conclusions of GA program per App Item C.1 & 2 & Item D.1 & 2 of V Stello 800515 graduated recisation order SHIELDS.8 W Public Service Co of Indiana, Inc. 80/09/12 2pg.
 - 8009290513 "Const & Hatl Verification Program," final rept 4 Public Service Co of Indiana, Inc. 80/09/30 725pp

Adjudicatory correspondence

- 09300094 Responds to NRC 600515 graduated racission of 790815 order & requests partial lifting of order confirming suspension of const Util has completed activities prerequisite for receipt SHIELDS, S H. Public Service Co of Indiana, Inc. 80/08/24 2pp.
- 8007180226 Forwards Director's decision under 10CFR2 206 denying Bave the Valley request for action re resumption of work at facility DENION, HR Office of Nuclear Reactor Regulation, Director, 80/09/02
 - 9009180232 Director's decision under 100FR2 206 denying Bave the Valley request for action re resumption of work at facility Evidence of extension of fault zone towards plant site is DENTUM H R Office of Nuclear Reactor Regulation, Director
 -)9180237 Notifies of 771129 sits visit to examine foundation matts in response to NRC request Hemorandum rept on Visit encl BRDHN.F R Army, Dept of, Corps of Engineers 77/12/12 3pp
 - O9180242 Notice of issuance of Director's decision under 10CFR2.206. DENTUN-H R. Office of Nuclear Reactor Regulation. Director 80/09/02. 2pg
 - 260467 Order granting extension until 801006 for Commission to ect whether to review Director's decision under CFR2 206 ILK.S J Office of the Secretary of the Commission 80/09/23

uneral correspondence

- 070574 Forwards organizational changes revising organization scription in GA program
 IELDS, S.W. Fublic Service Co. of Indiana, Inc. 80/09/02 ip
- .07070580 Organizational changes revising GA program. New organization charts re-project project engineering, project const.project control. project administration. GA & project testing enci # Public Service Co of Indiana. Inc 80/09/02 9pp
- 9300452 Advises that WM Petro assumed full responsibilities as roject director effective 800919
 HIELDS.6 W Public Service Co. of Indiana, Inc. 80/09/23 ip
- Inspection reports: IE Bulletins & correspondence
- 09150172 Forwards IE Insp Repts 50-546/80-25 & 50-547/80-25 on 800001-30 No noncompliance noted. FIDRELLI,O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/20 2pp

- --8009150177 IE Insp Repts 30-546/80-25 & 50-547/80-25 on 800601-30 No noncompliance noted Hajor areas inspected auxiliary bldg, fuel handling bldg, Units 1 & 2 containments & storage & maint facilities for safety-related items HILLIAMS.C C. HARRISON.J J Region 3, Chicago, Office of the Director 80/07/23 App
- 8009110764 Forwards IE insp Repts 50-546/80-21 & 50-547/80-21 on 800603-06 & 0707-11 No noncompliance hoted FIDRELLI, O Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/07/31 2pp
- --8009110769 IE Insp Repts 80-546/80-21 & 50-547/80-21 on 800603-06 & 0707-11 No noncompliance noted Major areas inspected. blasting work.completed ESP line backfill work & const verification procedures

 MAYES.D W Region 3. Chicago. Reactor Construction & Engineering Support Branch HAHKINS.F C. HARRIS.J R Region 3. Chicago. Office of the Director 80/07/29. App
- 8009180211 Forwards IE Insp Repts 30-346/80-24 & 50-547/80-24 on 800624-27 No noncompliance noted KEPPLER.J O. Region 3. Chicago. Office of the Director 80/08/03
- --8009180221 IE Insp Repts 50-546/80-24 & 50-547/80-24 on 800624-27 No DOYBOOZI IE INSP REPER DU-DROFOUNCE A DOVUMENT ON BOODERT OF THE NORTH PROPERTY OF THE PROPERT Region 3, Chicago,
- 8009190594 Forwards 1E Insp Repts 50-546/80-23 & 50-547/80-29 on 800610-12,16-20 & 26-27 & notice of violation FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/07 2pp
- --8009150500 Notice of violation from insp on 800510-12,14-20 & 26-27.
 * Region 3. Chicago, Office of the Director, 80/08/05 ip
- -8009150602 IE Insp Repts 50-346/80-23 & 50-547/80-23 on 800610-12, 16-20 & 26-27 Noncompliance noted failure to follow procedures in implementation of Special Process Procedure 7 SCHMEIBINZ,E , ERB.C M., CORDERO,Z C, Region 3, Chicago, Office of the Director 80/08/05 lipp
- 8009030213 Forwards Revision 1 to IE Bulietin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective 8gs of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/06. Region 3, Chicago: Office of the Director 80/08/15
- 8009290104 Forwards IE Insp Repts 50-546/80-27 & 50-547/80-27 on 800717-18. No noncompliance noted FIGRELL, O Region G. Chicago, Reactor Construction & Engineering Support Branch 80/08/19 2ps.
- --B009290107 IE Insp Repts 50-546/B0-27 & 80-547/B0-27 on 800717-18.Ha nancompliance noted Major areas inspected technical adequacy of util action re Marble Hill concrete issue. HAKKIRS-F. C. HAYES.D W Region 3, Chicago. Office of the Director. 80/08/18 3pp
- 8009290110 Forwards IE Insp Repts 50-546/80-29 & 50-547/80-29 on 800729-0801 No noncompliance noted FIDRELLI, C Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/08/19 2pp
- --8009290114 IE Insp Repts 50-546/80-29 & 50-547/80-29 on 800729-0801.No noncompliance noted. Major areas inspected nondestructive examination: lab equipment & procedures personnel certifications & rediographs of field welds SCHAPKER: JF. Region 3: Chicago. Office of the Director. DANJELSON. DH. Region 3: Chicago. Reactor Construction & Engineering Support Branch 80/08/18 App
- 8009170436 Forwards IE Circular 80~18, "10CFR50 59 Bafety Evaluations for Changes to Radwasta Treatment Sys " No written response KEPPLER, J Q. Region 3, Chicago, Office of the Director 80/08/22
- 8007230077 Forwards IE Info Notice 80-31, "Meloperation of Qould-Brown Bover! ABO Volt Type K-6008 & K-DON 6008 Circuit Breakers." No written response required. KEPPLER.J O Region 3, Chicago, Office of the Director. 80/08/28

- 8009250447 Responds to IE Bullstin 80-19. "Failures of Mercury-Wetted Hatrix Relays in Reactor Protective Sus of Operating Nuclear Power Plants Designed by C-E " No mercury-wetted relays are being used in reactor protection sys

 BHIELDS.8 N Public Service Co of Indiana. Inc. 80/08/28 ip
- 8009180346 Responds to IE Bulletin 80-16 re potential misapplication of Resembnt pressure transmitters Identified transmitters will be installed but will not be sub; to input pressures Bignel of differential pressure to be provided across tube ENIELDS-8 W Public Service Co of Indiana. Inc 80/08/29 ip
- B009240116 Forwards IE Circular 80-21. "Regulation of Refugling Crews"
 No written response required
 KEPPLER, J O Region 3, Chicago, Office of the Director B0/09/10
- 8009290202 Ack receipt of 800820 ltr informing NRC of steps taken to correct violations noted in IE Inso Repts 50-546/80-23 & 50-546/80-23 & 50-546/80-23 & FIORELLI, O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/09/15 ip
- --8009290208 Responds to NRC 800807 ltr re violations noted in IE Insp Repts 50-546/80-23 & 50-547/80-23 Corrective actions util will perform audits of special process procedure program to ensure that required data are included in checklists SHIELDS.8 W Public Service Co of Indiana. Inc 80/08/20 3pp
- B Reportable occurrences, LERs & related correspondence
- BO09020249 Ack receipt of 800728 final rept re repair welds which were not reradiographed after repair welding was completed FIDRELLI.O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/07, ip.
- --8009020253 Final deficiency rept re repair sleeve welds not reradiographsd after repair wilding was completed Ultrasonic testing of sleeve welds performed indicating that welds were not defective but acceptable as is SHIELDS, 8 W Public Service Co of Indiane, Inc 80/07/28. 1p. Available at NRC mrc
- 8009150491 Ack receipt of 800730 interim deficiency rapt re 45 of 49 documentation packages for Wastinghouse supplied matia massing quality records Final rapt will be reviewed upon raceipt.
 FIORELLI, U region 3. Chicago, Reactor Construction & Engineering Support Branch. 30/08/15 ip
- 8009030480 Interim deficiency rept re operation of centrifugal charging pumps during high energy line rupture Alternative mods being evaluated by Wessinghouse Final rept will be submitted 801114.

 8HIELDS B. W Public Service Co of Indiana. Inc. 80/08/20 ip
- BO09040427 Interim deficiency rept re inadequate documentation of cadwald splice sampling & testing Reinsp & evaluation of cadwald splices is being performed as part of const varification program Final rept will be submitted by B01001 SHIELDS.B W Public Service Co of Indiana. Inc 80/08/28 2pp
- BXXXIIOVANY Interim deficiency rept re inability of contractor QA program to assure that AE design changes were incorporated into plant const activities. Visual insp delayed Final rept will be submitted by 80:101
 SMIELDS, 8. W Public Service Co. of Indiana. Inc 80/09/02, 1p
- BO072504B3 Ack "sceipt of BO0813 interim deficiency rept re certain radiographs of steam generator upper lateral support embedments not mesting density requirements of Bection V of ABME BPAV ode FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Tranch 80/07/03 ip
- 8009250479 Ack receipt of 800820 interim rept re operation of centrifugal charging pumps during high energy line rupture. FIORELLI.O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/08 ip
- --8009250482 Interim deficiency rept re centrifugal charging pumps during high energy line rupture Westinghouse analyzed problem & recommended plant mode Final rept will be sent by 801114.
 SHIELDS.8 M. Public Service Co of Indiana, Inc. 80/08/20 ip
- BOO9150400 Final deficiency rept to possible nonconformances in reinforcing steel in areas of clear cover, member thickness & size of reinforcing bar Corrective actions described in Baction 2 of "Gonst Verification Program,"

 BHIELDS, B, W. Public Service Co of Indiana, Inc. 80/09/11. 2pp.

- 8009160419 Interim deficiency rept re undercut welds undersize fillet uelds & incorrect weld contour on steel used to support pipe hangers Deficiencies being investigated Final rept will be submitted by 801219 SHELDS, B W Public Service Co of Indiana. Inc 80/09/11 1p
- 8009290197 Ack receipt of 800828 deficiency rept re Cadueld splits sampling & testing FIGRELLI,G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/15 ip
- 8009240861 Potentially reportable deficiency rept re failure of previously inspected cadwolds to meet visual inspections of Nancomformance thoroughly evaluated including radiography Mechanical splices will meet design strength requiraments SHIELDS:8 W Public Service Co of Indiana, Inc. 60/09/18 ip.
- DOCKET STN-50-559 PRIPPS SEND NUCLEAR PLANT, UNIT :

 A Application/construction stage documents & correspondence
- 80090B0080 Forwards draft NUREC-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation achedule for meeting criteria of NUREC-0696 and N/O NUREC EISENHUT
- 8009040484 Forwards description of fault zone in rock foundation for Unit 1 control & diesel generator bldgs Drawing encl MILLS.L M Tennesses Valley Authority 80/08/22 4pp
- ---8009040487 "Pian View Geologic Map.Unit 1 " * Tennessee Valley Authority 80/07/21 ip
- 8007100472 Forwards info re add1 faults discovered at facility in area of essential svc water spray pond Photographs & drawings available in Central Files
 MILLS L M Tennosses Valley Authority 80/08/22 3pp
- I Financial information
- 8009090543 Forwards Annual Financial Rept 1979
 CRD88.J L Tennessae Valley Authority 80/09/04 lp
- --8009090563 Annual Financial Rept 1979 * Yennessse Valley Authority 80/09/04 44pp
- G Inspection reports, 1E Bulletins & correspondence
- 8009090075 Forwards IE Builetin 80-07. Suppl i. "BWR Jet Pump Assembly Failure" No response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/13 tp
- 8009090253 Forwards iE Insp Repts 50-559/80-10 & 50-554/80-09 on 800623-27 No noncompliance noted MCRPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/07/21 2pp
- --8007090289 IE insp Repts 50-593/80-10 & 50-994/80-09 on 800623-27 No noncompliance noted Major areas inspected licenses action on previous insp findings. VEL heavy lifting & transporting activities, const & IE bulletin status CANTRELL.F 8 Region 2, Atlanta, Reactor Construction & Engineering Support Branch WRIGHT, R W Region 2, Atlanta, Office of the Director 80/07/21 iOpp
- 8009020184 Submits response to IE Bulletin 79-03A No EA-312 or A-312, Typs 300 series fusion welded pipe is in use or planned for use in safety-related sys MILLS.L.M Tennesses Valley Authority 80/08/04 ip
- 8007020303 Forwards IE Insp Repts 80-327/80-24,50-329/80-15, 50-390/80-20,50-391/80-14,50-438/80-13,50-439/80-13, 50-518/80-11,50-518/80-11,50-518/80-11,50-521/80-11,50-521/80-11, 50-553/80-11,50-554/80-10,50-566/80-10,50-567/80-10, 50-567/
- --B009020312 Notice of violation from insp on 800707-11
 ** Region 2, Atlanta, Office of the Director. B0/08/06 4pp

- --8009020337 IE Insp Repts 50-327/80-24,50-328/80-15,50-390/80-20,50-391/80-14,50-438/80-13,50-439/80-13,50-518/80-11,50-519/80-11,50-521/80-11,50-521/80-11,50-553/80-11,50-554/80-10,50-566/80-10 & 50-567/80-10 on 800707-11,8880NNLEE,V L Region 2, Atlanta, Office of the Director 80/88/06 24pp
- 8009030146 Forwards Revision 1 to IE Builetin 80-19. "Feilures of Mercury-Wetted Matrix Relays in Reactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY.J P. Region 2. Atlanta. Office of the Director 80/08/15
- B009160045 Forwards IE Info Notice 80-30. "Potential for Unacceptable Interaction Between Control Red Drive Scram Function & Nonessential Control Air at Certain OE BHR Facilities "No specific action or response requested O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/19 to
- 8007120066 Forwards Suppl 3 to 16 Bulletin 80-17. "Failure of Control Rods to Insert During Scram at BUR" No written response regulated D'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/08/22
- B009160153 Forwards IE Circular 80-18, "IOCFR90 59 Bafety Evaluations for Changes to Radwaste Treatment Sys "No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director. B0/09/22 to.
- 3009120340 Forwards iE info Notice 80-31, "Meloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers "No written response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/08/27 fp.
- 3009180068 Forwards response to IE Builetin 80-16 Rosemount Models 1151 & 1152 pressure transmitters were planned for installation.

 OE will analyze applications of transmitters to determine out-of-range conditions

 MILLS,L M Tannessee Valley Authority 80/08/29 2pp
- 1009180068 Submits response to 1E Bulletin Bo-19 No marcupy-wetted metrix relays are in use in reactor protection sys siLLS.L M Tannessee Valley Authority 80/08/29 ip-
-)9240427 Forwards response to IE Bulletin 80-16 re patential disemplication of Rosemount pressure transmitters List of dentified transmitters used in safety-related areas being compiled Rept will be filed after resolution of deficiency miLLS, L.ff Tennessee Valley AuthorSty. 80/08/27 2pp
- 09260375 Forwards IE Circular 80-21, "Regulation of Refueling Craws." No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/10.
- Reportable occurrences. LERs & related correspondence
-)09160649 Part 21 rept re design deficiencies in nuclear sys protection sys power distribution panels Panels returned to QE for redesign & rework to corrected design MILLS.L M Tennessee Vailey Authority B0/09/03 Opp
- 109240392 Second interim deficiency rept re Rosemount Model 1152 pressure transmitter defects Util is preparing lists of Rosemount 1151 & 1152 transmitters for OE to analyze & replace of necessary Final rept will be provided by 810403 MILLS, L. M Tennessee Valley Authority 80/09/17. 3pp
- 009290355 Interim deficiency rept re deficient welds on weir well liner piates Ail welds made w/incorrect electrodes will be removed & replaced by welds w/proper stainless steel alectrode Addl corrective action may be warranted MILLB.L M Tennessee Vallay Authority. 80/09/19 2pp
- 2009270375 Becond interim deficiency rept re steam tunnel embedment stiffner plete weld Cause not stated, Util continuing to monitor Atlas OA program to help correct deficiencies HILLB.L M. Tennessee Valley Authority 80/09/19 19

- DOCKET STN-50-554 PHIPPS BEND NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl. W/o NUREG EIGENRUT.D O Division of Licensing 80/08/01 '119pp
- 8007100472 Forwards info re addl feults discovered at facility in area of essential svc water proep pond Photographs & drawings available in Central Files
 MillS L M Tennessae Valley Authority 80/08/22 3pp
- I Financial information
- 8009090543 Forwards Annuel Finencial Rept 1979 CROSS.J L Tennessee Vallay Authority 80/09/04 ip
- --B009070563 Annual Finencial Rept 1979
 * Tennessee Valley Authority 80/09/04 44pp.
- @ Inspection reports. IE Bulletins & correspondence
- 8009090075 Forwards IE Bullatin 80-07, Suppl 1, "BWR Jet Pump Assembly Failure" No response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/05/13
- 8007070233 Farwards IE insp Repts 50-553/80-10 & 50-554/80-09 an 800623-27 No noncompliance noted MURPHY.C.E Region 2, Atlente, Reactor Construction & Engineering Support Branch 80/07/21 2pp
- --8009090259 IE Insp Repts 50-553/80-10 & 50-554/80-09 on BO0623-27.Ne noncompliance noted. Major areas inspected licensee action on previous insp findings. VEL heavy lifting & transporting activities. const & IE bulletin status CANTRELL.F. 8 Region 2. Atlanta. Reactor Construction & Engineering Support Branch MRIGHT.R.W Region 2. Atlanta, Office of the Director 80/07/21 10pp
- 8007020184 Bubmits response to IE Bulletin 79-03A No 8A-312 or A-312 Type 300 series fusion welded pipe is in use or planned for use in safety-related sys MILLS,L H Tennessee Vallay Authority 80/08/06 ip
- 8007020303 Forwards IE Insp Repts 50-327/80-24,50-328/80-15, 50-370/80-20,50-391/80-14,50-438/80-13,50-439/80-13 50-518/80-11,50-519/80-11,50-520/80-11,50-521/80-11, 50-553/80-11,80-554/80-10,50-566/80-10 & 50-567/80-10 0'REILLY,J P. Region 2, Atlanta, Office of the Director 60/08/06.
- --8009020312 Notice of violation from insp on 800707-11.

 * Region 2: Atlanta: Office of the Director 80/08/06 4pp
- --8009020337 IE Insp Repts 50-327/80-24:50-328/80-15:50-390/80-20:50-391/80-14:50-438/80-13:50-439/80-13:50-518/80-11:50-518/80-11:50-518/80-11:50-518/80-11:50-518/80-11:50-554/80-10:50-5
- 8007030144 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Marcury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nucleer Power Plants Designed by C-E " Written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director, 80/08/15.
- 8009160045 Forwards IE Info Notice 80-30. "Potential for Unacceptable Interaction Between Control Rod Drive Screm Function & Nonessential Control Air at Certain GE BMR Facilities." No specific action or response requested D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/08/19 In.
- 8009120066 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to insert During Scram at BWR " No written response required G'REILLY, J.P. Region 2, Atlante, Office of the Director. 80/08/22 to

- BOO9160153 Forwards IE Circular 80-19, "10CFR50 59 Safety Evaluations for Changes to Radwasta Treatment Bys " No written response tequired CREILLY, J.P. Region 2, Atlanta, Office of the Director BO/08/22
- 8009120340 Forwards IE Info Notice 80-31. "Haloperation of Gould-Brown Boyer1 480 Volt Type K-6005 & K-DON 6008 Circuit Breakers" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/27
- 8009:800&B Ferwards response to IE Bulletin 80-i6 Rosemount Models 1:51 & 1:52 pressure transmitters were planned for installation OE will analyze applications of transmitters to determine out-of-range conditions
 MILLS.L M Tennessee Valley Authority 80/08/27 2pp
- BOO91800AB Submits response to IE Bulletin 80-19 No mercury-wested matrix relays are in use in reactor protection sys MILLS.L M. Tennessee Valley Authority 80/08/29 1p.
- 8009240427 Forwards response to IE Bulletin 80-16 re potential misapplication of Rosemount pressure transmitters List of identified transmitters used in safety-related areas being complied Rept will be filed after resolution of deficiency MILLS.L.M Tennessee Valley Authority 80/08/29 2pp.
- 8009260375 Forwards IE Circuler 80-21, "Regulation of Refueling Grews "
 No written response required
 O"REILLY, J P Region 2, Atlanta, Office of the Director 80/09/10.
 Sep
- 8 Reportable occurrences, LERs & related correspondence
- 8009240392 Second interim deficiency rept re Rosemount Hodel ii52 pressure transmitter defects Util is preparing lists of Rosemount Ii51 & ii52 transmitters for GE to analyze & repiace if necessary Final rept will be provided by 8i0403 MiLLS,L.H Tennessee Velley Authority 80/09/17. 3pp.
- 8009290355 Interim deficiency rept re deficient walds on wair wall liner plates. All weids made w/incorrect electrodes will be removed & replaced by welds w/proper stainless steel electrode Addi corrective action may be warranted.

 HILLS, L. H. Tennessee Valley Authority 80/09/19 2pp
- 8009290375 Second interim deficiency rept re steam tunnel embedment stiffner plate weld.Cause not stated Util continuing to monitor Atlas GA program to help correct deficiencies MILLS,L M Tennessee Vailey Authority 80/09/19. ip
- DOCKET STN-50-556 BLACK FOX STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days. Proposed implementation schedule for meeting criteria of NUREO-0696 encl. N/a NUREO EISENHUT. D. O Division of Licensing. 80/08/01 119pp
- F Becurity, medical, emergency & fire protection plans
- 8009020197 Invites participation in 800822 workshop in Atlanta, QA to solicit comment re proposed functional criteria for amergency response facilities in NUREO-0696 Discussion to include location size & staffing of emergency ctrs.

 8EYFRIY, K V Region 4, Dallas, Office of the Director 80/08/12 in
- O Adjudicatory correspondence
- BO09250010 Memorandum & order to ALAB-573 certified question. Holds that environ health effects associated w/App I design objectives for effluent releases may be litigated in licensing proceedings of Ahearne dissenting opinion enci CHILK.8 J Office of the Secretary of the Commission 80/09/22, 23ap
- 8009260637 Hod of Commission 800922 memorandum & order to ALAB-573 cartified question Corrected version of JF Ahearne dissenting views encl
 CHILLS J Office of the Secretary of the Commission 80/09/23.

- 8009260639 Mod of Commission 800922 memorandum & order re ALAB-573 certified question Corrected version of JF Ahearne dissenting views encl CHILK-8 J Office of the Secretary of the Commission 80/09/23 Jpp
- DOCKET STN-50-557 BLACK FOX STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT,D 0 Division of Licensing 80/08/01. 119pp
- F Security, medical, emergency & fire protection plans
- 8007020137 Invites participation in 800822 workshop in Atlanta,6A to solicit comment re proposed functional criteria for emergency response facilities in NUREO-0676 Discussion to include location, size & staffing of emergency ctrs SEYFRIT.K V Region 4. Dallas, Office of the Director 80/08/12 in
- O Adjudicatory correspondence
- 8009250010 Memorandum & order re ALAB-573 certified question Holds that environ health effects associated w/App I design objectives for effluent releases may be [fit]ated in licensing proceedings JF Ahearne dissenting opinion encl CHILK.8 J Office of the Secretary of the Commission 80/09/22.
- 6009260639 Mod of Commission 800922 memorandum & order re ALAB-573 certified question Corrected version of JF Ahearns dissenting views encl CHILK, 8 J Office of the Secretary of the Commission 80/09/23.
- DOCKET 50-559 MAANBHAN NUCLEAR STATION, UNIT 2
- O Adjudicatory correspondence
- 8007070233 Response in opposition to Citizens Against Nuclear Power, J J Runyon & E Oogol petition for review of ASLAB 800729 order affirming ASLB 800530 dismissai of contentions Const will not be allowed prior to environ review W/Certificate of Svc MILLER, H I Commonwealth Edison Co. BIELAWSKI, A P Isham, Lincoln & Beale 80/08/29 12pp
- DOCKET 50-564 NUCLEAR FUELS RECOVERY & RECYCLE CENTER
- O Adjudicatory correspondence
- 8009170366 Comments on rulemaking 50-5 re mixed oxide fuel GESMO & other recycle-related licensing proceedings should continue Postfive effirmative action to approve licenses recommended KIRK, W F William F Kirk 80/08/28
- 8009160224 Requests GEBMO re fueld be completed Info is needed for future decisions re reprocessing of spent nuclear fuel VILLEMY, G R Affiliation Unknown 80/09/08 1p
- B007160420 Comments on rulemaking 50-5 OEBMO proceedings should be respensed to provide sarly procedural framework for subsequent licensing.
 RICHARDS,R B Oeneral Electric Co 50/09/08. 2pp
- B009300514 Expresses concern re reopening of GESMD & other related licensing proceedings for reprocessing sites FEIG.P Affiliation Unknown 80/09/13 ip
- 8009260641 Urges resumption of GESHD bearings 80LON, A. E. Affiliation Unknown, 80/09/16 ip
- --8007260646 Opposes reopening of OESMO hearings BURRELL:A Affiliation Unknown 80/09/13 ip
- --8009260652 Urges reopening GESMO & recycle-related proceedings & consideration of expanding scope to include recycle of LMR fuel in breeder reactors MCCORNACK.M House of Rep. 80/09/22 2pp

- 8009300325 Forward's comments in response to Commission 800807 order retarminated GESMO proceedings Reopening would be inimical to mati security & defense & at odds u/nonproliferation objectives

 BIALIK, E 1 New York, State of 80/09/23 7pp
- BOOP300540 Comments on reopening of GESMO proceedings Addi use of nuclear generated electricity should be paced to preserve significant quantities of hydrocarbon reserves for use as raw matis in future chemical mfg BURRIS.L American Institute of Chemical Engineers BO/09/23 2pp
- 8007300561 Supports reopening of GESMO & other recycling license proceedings
 PRICE.J E Affiliation Unknown 80/07/23 ip
- H General correspondence
- BOO9100490 Comments on RM 50-5 public should be advised of advantages & disadvantages of implementing Pu recycle NRC should not have terminated efforts on OESMO fuels
 DECHER.U Affiliation Unknown BO/09/03 Ip
- DOCKET STN-50-566 YELLOW CREEK NUCLEAR PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- BOO7080080 Forwards draft NUREO-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/o NUREO EIGENHUT. D O Division of Licensing 80/08/01 119pp
- I Financial information
- 8009090543 Forwards Annual Financial Rept 1979 CROSS, J. L. Tennessee Valley Authority 80/09/04 ip
- O Inspection reports. IE Builetins & correspondence
- O09100063 Forwards IE Builetin 80-18, "Meint of Adequete Min Fiow Through Centrifugal Charging Rumps Following Secondary Bide High Energy Line Rupture " No written response required O'REILLY, J.P. Region 2, Atlenta, Office of the Director 80/07/24 fp
- 009250109 Forwards IE Insp Repts 50-566/80-11 & 50-567/80-11 on 800715-17 & notice of violation MURPHY,C E Region 2. Atianta, Reactor Construction & Engineering Support Branch 80/08/04 2pp
- 3009250i12 Notice of violation from insp an 8007i5-17
 * Region 2, Atjenta, Office of the Director 80/08/04, ip
- D09250114 IE Insp Repts 50-566/80-11 & 50-567/80-11 on 800713-17 Noncomplience noted failure to follow procedure for curing concrete test cylinders ANTRELLES Region 2. Atlanta, Reactor Construction & Engineering Support Branch, THOMAS, M. Region 2. Atlanta, Office of the Director 80/08/04, 4pp
 - 20214 Forwards response to IE Builetin 79-03A No BA-312 & A-312.

 300 series fusion weided pipe used or plenned for use
 rafetu-releted sys at greater then 85% design stress
 1pt Matta Ber Hati under investigation at Watta Bar
 S.L.M. Tennessee Valley Authority 90/08/05 2pp
 - 3802 Responds to IE Bulletin 79-03A. "Langitudinel Weld Defects IME SA-312. Type 304 Stainless Steel Pipe " Use of matls under investigation for sys supplied by NBSB vendor p.L.M. Tennessee Valley Authority 80/08/05 2pp
 - 0303 Farwards IE Insp Repts 50-327/80-24, 50-328/80-15, 90/80-20, 50-391/80-14, 50-439/80-13, 50-439/80-13, 18/80-11, 50-519/80-11, 50-520/80-11, 50-521/80-11, 50-521/80-10, 50-366/80-10 & 50-367/80-10 ILLY, J P Region 2, Atlanta, Office of the Director 80/08/06

- --8009020337 IE Insp Repts 50-327/80-24,50-328/80-15,50-496/80-20,50-391/80-14,50-438/80-13,50-439/80-13,50-518/80-11,50-518/80-11,50-518/80-11,50-518/80-10,50-586/80-10,50-586/80-10 on 800707-11 BROWNLEE.V L Region 2, Atlanta, Office of the Director 80/08/06 2890
- 8007030146 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Hercury-Wethed Matrix Relays in Resector Protective 8ys of Operating Nuclear Power Plants Designed by C-E," Written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/08/15 ip
- 8009160183 Forwards IE Circular 80-18, "10CFR30 59 Safety Evaluations for Changes to Redwaste Treatment Sys " No written response required O'REILLY, J P Region 2, Atlante, Office of the Director 80/08/22 ip
- 8009120340 Forwards IE Info Notice 80-31, "Meloperation of Gould-Brown Bover1 480 Voit Type K-6008 & K-DON 6005 Circuit Breakers," No written response required O'REILLY, J.P. Region 2. Atlante, Office of the Director, 80/08/27 ip
- 8009180087 Forwards response to IE Bulletin 80-16 Rosemount Hodels 1151 % 1152 pressure trensmitters are not used or planned for use except at Beliefonte Nucleer Plent where use will be eveluated MILLS, L.H. Tunnessee Veliey Authority 80/08/29. 2pp.
- 8007240454 Forwards response to IE Bulletin 80-16 re potential misepplication of Rossmount pressure transmitters. No corrective action required due to results of evaluation that indicated impossibility of enomalous output, MILLS, L.K. Tennessee Valley Authority, 60/08/27 2pp.
- 8007240583 Ack receipt of 800818 ltr informing NRC of eteps taken to correct violation noted in IE Insp Repts 50-566/80-03 & 50-567/80-03 MURRHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/09/02 ip.
- --8009240600 Responds to NRC 800228 itr re violations noted in EE Inep Repts 50-566/80-03 & 50-567/80-03 Corrective ections: radiographs before 800207 re-examined & radiographers instructed in requirements of shim placement MILLE, L M Tannessee Valley Authority 80/08/18. 3pp
- 8009120679 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrix releys in resector protective sys. Relays identified are not used in fecility Forty memburs expended for review MILLB, L N Tennessed Valley Authority 80709704 fp.
- 8009260375 Forwards IE Circular 80-21, "Regulation of Refueling Craws No written response required, O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/10-5pp
- 8 Reportable occurrences, LERs & related correspondence
- 800716036B Final deficiency rapt re 84 reinforcing bars left out of well pour CI-Fi located in control bidg Caused by inspector arrow k/or rebar removed for other installations Missing reber replaced. Deteil checkoff list initiated to aid insp. MILLS, L. M. Tennessee Valley Authority. 80/09/11. 3pp
- DOCKET STN-50-567 YELLOH CREEK NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- BOOTOBOODO Forwards draft NUREO-0676, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0676 encl W/o NUREO EISENHUT, D 9 Division of Licensing, 80/08/01 i19pp.
- G Adjudicatory correspondence
- 8009300549 Request extension of time for comment on Commission 800007 order re reopening QESMO proceeding HOLDEN,R B Ailied General Nucleer Bervices 80/09/23 1p
- I Financial information
- 8009090543 Forwards Annual Financial Rept 1979 CRDS8,J L Tennessee Valley Authority 80/09/04 ip

- à Inspection reports: IE Bulletins & correspondence
- 8009100063 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " No written response required, O'REILLY, J. P Region 2, Atlanta, Office of the Director 80/07/24
- 9009250109 Forwards IE Insp Repts 50-566/80-11 & 50-567/80-11 on 800715-17 & notice of violation MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/08/04 2pp
- --8097250112 Notice of violation from insp on 800715-17 • Region 2: Atlanta: Office of the Director 80/08/04 ip
- ~-8009250114 IE Insp Repts 50-566/80-11 & 50-567/80-11 on 800719-17
 Noncompliance noted failure to follow procedure for curing
 concrete test cylinders
 CANTRELL.F S. Region 2, Atlanta: Reactor Construction &
 Engineering Support Branch THOMAS,M Region 2, Atlanta, Office
 of the Director. 80/08/04, 4pp
- 8009020214 Forwards response to IE Bulletin 79-03A. No 8A-312 & A-312, Type 300 series fusion welded pipe used or planned for use in safety-related sys at greater than 85% design stress except Hatts Bar, Matl under investigation at Hatte Bar. MILLS, L.M. Tennesses Valley Authority 80/08/05. 2pp
- 8009090802 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASRE 8A-312, Type 304 Stainless Steel Pipe." Use of matts still under investigation for sys supplied by NSSS vendor HILLELL M Tennessee Valley Authority 80/08/05 2pp.
- 8007020303 Forwards IE Insp Repts 50-327/80-24,50-328/80-15, 30-390/80-20,50-391/80-14,50-438/80-13,50-439/80-13, 50-518/80-11,50-520/80-11,50-520/80-11,50-520/80-11,50-520/80-11,50-520/80-11,50-520/80-10,50-520/8
- --9009020312 Notice of violation from insp on 800707-11.
 Region 2, Atlanta, Office of the Director 90/08/06. App
- --8009020337 IE Insp Repts 50-327/80-24.50-328/80-15, 50-390/80-20, 50-391/80-14.50-438/80-13, 50-439/80-13, 50-518/80-11, 50-519/80-11, 50-519/80-11, 50-519/80-11, 50-55/80-11, 50-55/80-10, 50-55/80-
- 8009030146 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercory-Wetted Matrix Releys in Reactor Protective Sus of Decrating Nuclear Power Plants Designed by C-E " Written response yequired O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/08/15, 1p.
- 9009160153 Forwards IE Circular 80-18, "iOCFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys." No written response required G'REILLY, J. P. Region 2. Atlanta. Office of the Director 80/08/22 is
- 8009120340 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Rover: 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers."
 No written response required,
 D'REILLY, J. P. Region 2/ Atlanta, Office of the Director 80/08/27.
 ip.
- 8009180087 Forwards response to IE Bulletin 80-16 Rosemount Models 1151 & 1152 pressure transmitters are not used or planned for use except at Bellafonte Nuclear Plant where use will be evaluated. MILLS.L M Tennessee Vallay Authority 80/08/29. 2pp
- BO09240454 Forwards response to IE Builetin 80-16 re potential misapplication of Rosemount pressure transmitters No corrective action required due to results of evaluation that indicated impossibility of anomalous output.

 MILLE/L M Tennessee Vallay Authority 80/08/29. 2pp
- 8009240583 Ack receipt of 800818 ltr informing NRC of steps taken to correct violation noted in 1E Insp Repts 50-566/80-03 & 50-567/80-03 MURPHY.C. E. Region 2: Atlanta: Reactor Construction & Engineering Support Branch. 80/09/02 ip.

- --8009240600 Responds to NRC 800228 ltr re violetions noted in IE Insp Repts 30-866/80-03 & 30-367/80-03 Corrective actions radiographs before 800207 re-examined & radiographers instructed in requirements of shim placement MILLS: I Tennessee Valley Authority 80/08/18 3pp
- 8009120679 Responds to IE Bulletin 80-19 re failures of marcury-wetted metrix relays in reactor protective sys Relays identified are not used in facility Forty manhours expanded for review MILLS,L M. Tennessee Valley Authority 80/09/04 tp
- B009260375 Forwards IE Circular 80-21, "Regulation of Refueling Crews "
 No written response required
 O'REILLY, J P Region 2, Atlanta, Office of the Director, B0/09/10

DOCKET STN-50-574 BAGNAC NUCLEAR POWER PROJECT

- O. Adjudicatory correspondence
- 8008250025 Bupports Movement of Concerned Citizens of Philippines petition to intervene Justification of NRC actions re dropping safety.health & environ review requested MATSON.M Australia. BO/08/05 Ip
- DOCKET 50-582 BUNDEBERT, UNIT 1 O. Adjudicatory correspondence
- 8009170169 Motion for withdrawal of application for CP NEWHAN.J R. Ban Dlego Gas & Electric Co NEWHAN.J R Lowenstein: Newman, Reis: Axelrad & Toll 80/09/11. ig

DOCKET 50-583 SUNDESERT, UNIT 2 Q Adjudicatory correspondence

- BOO9170169 Motion for withdrawal of application for CP NEWMAN, J R Sam Diego Gas & Elactric Go NEWMAN, J, R Lowenstein, Newman, Reis, Azelrad & Toll BO/09/11. lp
- --8009170171 Motion for termination of proceeding due to withdrawal of application for CP Certificate of Bvc ancl NEMMANJ R. Ban Diego Gas & Electric Go 80/09/11 3pp

DOCKET BTM-50-592 PALG VERDE NUCLEAR STATION, UNIT 4

- A Application/construction stage documents & correspondence
- 800903051 Submits response to NRC 800421 info request on Category 1 majorry walls employed by plants under CP & OL review. Drawings 13-A-ZJD-509 through 511.13-A-ZAD-203 & 13-A-ZAD-207 re concrete & auxiliary bidgs encl VAN SRUNT, E E Arizona Public Servica Co 90/08/25 3pp

DOCKET STN-50-593 PALG VERDE NUCLEAR STATION, UNIT 5

- A Application/construction stage documents & correspondence
- 8009030511 Bubmits response to NRC 800421 info request on Category 1 masonry walls employed by plants under CP & OL review. Onewings 13-A-ZJD-309 through 511:13-A-ZAD-203 & 13-A-ZAD-207 re concrete & auxiliary blogs encl
 VAN BRUNT.E E Arizona Public Service Co 80/08/25 3pp

DOCKET 50-579 CARROLL FACILITY I

O. Adjudicatory correspondence

B009090233 Response in opposition to Citizens Against Nuclear Power. J J Rungon & E Cogol petition for review of ASLAB 800729 order affirming ASLB 800530 dismissel of contentions Const will not be allowed prior to environ review M/Certificate of Svc MILLER. M I., BIELANSKI. A P Commonwealth Edison Co MILLER. M I. Isham, Lincoln & Beale 80/08/29. 12pp. 8009160142 Order granting extension until 801006 for Commission to review ALAB-601 CHILK: 8 J Office of the Becretary of the Commission 80/09/11

DDCKET 50-600 CARROLL FACILITY 11 O Adjudicatory correspondence

BOO9090233 Response in opposition to Citizens Against Nuclear Power, J Runyon & E Dogol petition for review of ASLAB 800729 order affirming ASLB 800530 dismissal of contentions Const will not be allowed prior to environ review W/Certificate of Svc. HILLER: M I . BIELAMSKI.A P Commonwealth Edison Co MILLER: M I Isbam, Lincoln & Beale 80/08/29 12pp

8009160142 Order granting extension until 801006 for Commission to review ALAB-601 CHILK: S. J. Office of the Secretary of the Commission 80/09/11 is

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DOCKET 70-0008 BATTELLE COLUMBUS LABORATORIES

8009090886 Forwards physical security plan for protection of SNM of moderate or low strategic significance Plan withheld (ref 10CFR2 790). TOY, H L Battelle Memorial Institute, Columbus Laboratories 80/05/22 lp

8009120691 Forwards NUREC-0561 & info on transportation routes through populated areas W/o encl MCCORKLE, G W Physical Security Licensing Branch 80/07/08 ip

8009230376 Forwards IE Circular 80-20, "Changes in Safe-Blab Tank Dimensions" No written response required. KEPPLER.J G Region 3, Chicago, Office of the Director 80/08/21,

DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP

8007120620 Requests rascission of approved security plan.Al-74-86.for protection of greater than threshold quantities of 8NM at 8anta Susana plant Forseable plans do not involve passession & handling of greater than threshold quantities REMLEY.M E Rockwell international Corp., Energy Systems Div 80/07/67 2pp.

8007120161 Notifies that Section 9.0 of Amend MPP-1 to License SNN-21 is amended deleting Section 9 B re physical protection plan, affective immediately MCCORKLE.O W Physical Security Development Branch 80/07/24. 1p.

8007070835 Advices of refund re fee submitted w/800626 application to amend License SNM-21
MILLER, W.O. License Fee Management Branch 80/08/06 ip.

800905018B Forwards 1E Insp Rept 70-0025/80-05 on 800515-20 No noncompliance noted Entl withheld (ref 10CFR2 790) NGRDERHAUO, L R Region 5, San Francisco, Safeguards Branch 80/08/12 2pg

9009230371 Forwards IE Circular 80-20, "Changes in Safe-Slab Tank Dimensions " No written response required ENGELHEN,R H Region 5, San Francisco, Office of the Director 80/08/21. 4pp

8009240589 Requests that all personnel be reminded of surpose of emergency notification sys & health physics network. Bys installed for govt use during emergency ENGELERN.R H. Region 5, San Francisco, Office of the Director 80/08/22 Sap

DOCKET 70-0027 BABCOCK & WILCOX CO

8009030001 Application for amend to License BNM-0042, Amend provides for quarterly sampling of airborne radioactive affluent released from laundry operations GORDANI.R A Babcock & Wilcox Co 80/06/05 5pp

NOOF120157 Forwards response to site-specific questions re SNM search requirement to security lighting HCCORKLE.O W Physical Security Licensing Branch. 80/07/10 2pp.

8009110767 Requests exemption from 10CFR70 51(a)(3)(i) to delaw commencing Jul/Aug 1980 9NM inventory until 800905 CORDANI.R A Babcock & Wilcox Co , Naval Nuclear Fuel Div. 80/07/25 ip.

8007070885 Informs of tentative meeting w/United Nuclear Corp rerecovery contract for beginning of Aug Requests joint meeting w/NRC in late Aug pending resolution of contractural/safeguards problems ECKERT, J.P. Babcock & Wilcox Co., Naval Nuclear Fuel Div B0/07/29, 1p

8009090836 Advises that no add1 fae required for review & approval of Amend 11 to License SNM-42 MILLERN 0 License Fee Management Branch 80/08/06 ip

8009090124 Requests analysis & evaluation of airborna sampling data for two previous yrs to provide justification for change from continuous to quarterly sampling requested on 800005 Data should include sampling methods & counting technique KETZLACH.N Uranium Recovery Licensing Branch 80/08/11 1p

8009230391 Forwards 1E Circular 80-20, "Changes in Bafe-Slab Yank Dimensions " No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/08/21 4pp

8009230323 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency O'REILLY, J.P. Region 3, Chicago, Office of the Director 80/08/22.

8009100790 Forwards IE Insp Rept 70-0027/80-11 on 800701-03 & 07-11 No noncompliance noted KENNA, N. B. Region 2, Atlanta, Bafeguards Branch, 80/08/26 ip.

--B009100795 IE Insp Rept 70-0027/80-11 on 800701-03 & 07-11 No noncompliance noted Major areas inspected physical inventory verification Details withheld (ref 100FRZ 790) CLAY, E.L., TODD, O.A. Region 2, Atlanta, Offica of the Director, QILLESPIE, F. P. Region 2, Atlanta, Sefeguards Branch 80/08/23, ip.

DOCKET 70-0033 TEXAS INSTRUMENTS, INC

8009150078 Requests consideration of extension of submission date for plan required by safeguards upgrade rule implementation. Delay due to need to reflect substantive change in status Bubmittal data would be extended from 800822 to 0930, CHURCHILL, R. L. Texas Instruments, inc. 80/06/18, 2pp.

8009110702 Requests extension from 800822 to 801231 for submittal of add1 info required by NRC re application to renew License BNM-23 Portions of NRC request require svcs of outside consultants CHURCHILL, R L Texas Instruments, Inc 80/06/19 2pp

8009120170 Responds to 800618 ltm. Grants extension until 800930 for submittal of ravised fixed site safeguards physical protection plan Implementation date remains 810320 or 90 days after approval whichever is later BURNETTAR F Division of Safeguards 80/07/07. ip

8009170084 Confirms 800701 telcon re 800619 ltr requesting relief from request for addl info to suppl license renewal application. Info needed to provide sufficient justification for addl flexibility requested in application. CROW. W.T. Uranium Fuel Licensing Branch. 80/07/07 1p.

B009120668 Advises of withdrawal of license renewal application submitted 790829 Requests extension of existing license until termination of HFIR operation SHERMAN.F.L. Texas Instruments, Inc. 80/07/16, 1p.

8009180487 Ack receipt of 800721 ltr informing NRC of steps taken to correct violations noted in IE Insp Rapt 70-0033/80-07 Util ltr to be withheld (ref 100FR2 790) MARTIN.W Q. Region i. Philadelphia, Safeguards Branch, 80/08/05 to

--8009180491 Forwards IE Insp Rept 70-0033/80-07 on 800609-13.

MARTIN.W. G Region 1, Philadelphia, Safeguards Branch 80/07/01

- BO09240334 Amends License BNM-23 extending expiration data until B20630 & adding Conditions 26-30 re personnel qualifications & sampling of redicactivity in fuel mfg area PAOE.R O Uranium Fuel Licensing Branch BO/08/15 2pp
- --B009240339 Bafety evaluation of B00716 application to amend License BNM-23, euthorizing extension of license Recommends issuence of license amend subj to addi Conditions 26-30 XETZLACH.N. CRDW, W T Uranium Fuel Licensing Branch B0/0B/15 dep.
- 2009230415 Forwards IE Circular 80-20. "Changes in Hafa-Slab Tank Dimensions" No written response required SRIER.B.H Region i. Philadelphia, Office of the Director 80/08/21, 4pp
- 8009230220 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency GRIER.B.H. Region 1. Philadelphia, Office of the Director 80/08/22 3ao
- 8009020255 Forwards "Effluent & Waste Disposal Semiannual Rept for Jan-June 1980." supplemental info MCDAVITY.D F. Texas Instruments, Inc. 80/08/25 ip
- --8009020259 "Effluent & Waste Disposal Semiannual Rept for Jen-Jun. 1980." supplemental info a Texas Instruments. Inc 80/08/25 3pp
- DOCKET 70-0036 COMBUBTION ENGINEERING, INC
- 8009150166 Forwards IE Insp Rept 70-0036/80-02 on 800709-11 No noncompliance noted. DAVIS.A B Region 3. Chicago, Fuel Facility & Meterials Bafety Brench 80/07/30 2pp
- 8009230377 Forwards IE Circular 80-20. "Changes in Safe-Slab Tenk Dimensions " No written response required. AEPPLER, J. C. Region 3. Chicago, Office of the Director. 80/08/21.
- BOO9250419 Ack receipt of BDOB27 1fr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0035/80-03.
 HIND, J. A. Region 3, Chicago, Safeguards Branch, BO/09/09 ip
- --8007250422 Responds to NRC 800808 ltr re violations noted in IE lnsp Rept 70-0036/80-03, Corrective actions individuals authorized to sign internal transfer forms have been instructed on proper procedures ESKRIDDE, H. E. C-E Power Systems 80/08/29 2pp
- DOCKET 70-0135 BABCOCK & WILCOX CO
- BOOT110244 Requests 2-wk extension for reconciling plant ledgers & filing low enriched U plant SNM inventory rept Reconciliation of available physical inventory data shows inventory difference meeting 1/2% spec.
 AUBTIN.M.A Babcock & Wilcox Co , Nuclear Material Div 80/06/25 ip.
- 3009160179 Forwards IE Insp Repts 70-0135/80-16 & 30-0364/80-14 on 800609-13.No noncompliance noted.
 MARTIN,M. Q. Region 1, Philadelphia, Safeguards Branch. 80/07/08.
 288
- -8009160186 IE Insp Repts 70-0135/80-16 & 30-0364/80-14 on 800609-13 No nancompliance noted Major areas inspected physical inventory & assessment & observation of nondestructive assey work perfermed by licensee Details withheld (ref 100FRZ 770). BIBBETT, P.H., SUMMERS, R.J. Region 1, Philadelphia, Office of the Director, JOYNER, U.H. Region 1, Philadelphia, Safeguards Branch, 80/07/01, 19
- M09090874 Forwards application to amend License BNM-145, requesting revision to approved Apollo plant high enriched U plan covered by License Condition 2.1 in MPP-1 Encl & attachments withheld (ref 10CFR2 790).
 AUSTIN: A Babcock & Wilcox Co., Nuclear Material Div. B0/07/18

- 8009150403 Responds to 800718 request for limited exemption to permit highly enriched U leaching operation Forwards Amend MPP-1 to License SNM-145 Request will not endanger public health & safety or common defense & security
 MCCORKLE,O W Physical Security Licensing Branch 80/07/24 ip
- --8009150406 Adds condition to Amend MPP-1 to License SNH-145 granting limited exemption to permit high enriched U leaching operation within incinerator area • Physical Security Licensing Branch 80/07/24 1p
- 8009150347 Forwards IE Insp Rept 70-0135/80-19 t on 800707-10 No noncomplience noted MARTIN.W O Region 1. Philadelphia, Safeguards Branch 80/07/25
- --8009150358 IE insp Rept 70-0135/80-19 on 800707-10 No honcompliance noted. Major areas inspected independent measurements by MRC inspectors of residual U-235 holdup in high enriched U fecility Details withheld (ref 10CFR2 790) BISSETT-P H, COMEN.I, JUYNER.J H Region i, Philadelphia, Bafeguerds Branch 80/07/22 is
- 8009110262 Ack receipt of 800710 ltr informing NRC of steps taken to correct violations noted in iE lasp Repts 70-0135/80-15 & 70-036/80-13, MARTIN, M.Q. Region 1, Philadelphia, Safeguards Branch 80/08/05
- --8009110274 Forwards IF Insa Reats 70-0135/80-15 & 70-0344/80-13 on
- --8009110274 Forwards IE Insp Repts 70-0135/80-15 & 70-0364/80-13 on 800505-30 & notice of violation MARTIN.W O Region i, Philadelphia, Safeguards Branch 80/06/24 2pg
- --8009ii0276 Notice of violation from insp on 800505-30
 * Region 1, Philadelphia, Office of the Director 80/06/23 ip.
- --B009i102Bi IE Insp Repts 70-0135/80-13 & 70-0364/80-13 on 800505-30 Noncompliance noted feilurs to perform nuclear criticality evaluation JOYNER, J H Region 1. Philadelphia, Bafaguards Branch KUSHNER, H L Region 1. Philadelphia, Diffice of the Director 80/06/23 9pp
- 800718018:3 Informs of out-of-spets condition of five cylinders of low enriched U hezeflouride received BOD731 Cylinders will not be introduced to production sys Requests one-time exemption to return meth to govt at shipper values Fee forthcoming AUSTIN, M A Babcock & Wilcox Co , Nuclear Material Div 80/08/05 ip.
- ---R009180196 Forwards check for edministrative amend fee re one-time exemption relative to mat: returns at shipper values

 AUSTIN:M A Babcock & Wilcox Co , Nucleer Material Div 80/08/05
- 8009150480 Forwards rept on radioactive affluents discharged to unrestricted areas as result of work performed under Licanses SNM-145 & SNM-414 Rept covers Jan-June 1980 AUSTIN, M.A. Babcock & Hilcox Co., Nuclear Meterial Div 80/08/13. 3pp
- 8009110263 Ack receipt of 800715 ltr informing NRC of steps taken to correct violations noted in iE Insp Rept 70-0135/80-14 MARTIN.W G Region I, Philadelphia, Bafeguards Branch. 80/08/19
- ---8009i10272 IE Insp Rept 70-0i35/80-14 on 800527-30 No noncompliance noted Mejor arees inspected, effluent waste treatment sys in low enriched U plant Datalls withheld (ref 10CFR2 790) JOYNER, J. ZIBULEKY, H. Region 1, Philadelphia, Safeguards Branch 80/06/24, ip
- 8009230409 Forwards IE Circular 80-20, "Changes in Bafe-8leb Tank Dimensions" No written response required ORIER,B H. Region 1, Philedelphia, Office of the Director 80/08/21 4pp
- 8009230211 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network flys installed for govt use during emergency GRIER, B H Region 1, Philadelphia, Office of the Director, 60/08/22 3pp.

- DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC.
- 8009050179 FDIA request for documents re inventory difference at facility
 CDCHRAN, T B Natural Resources Defense Council 79/12/10 2pp
- B009050480 FOIA request for list of facilities for which comprehensive avaluation repts have been prepared. NUREG repts to MUF, list of documents re facility MUF & NRC decision to reopen plant DAVIS.P S Affiliation Unknown 80/06/25 ip
- 8009050180 Forwards IE Insp Rept 70-0143/80-23 on 800714-18 No noncompliance noted KENNA-W B Region 2. Atlanta. Safaguards Branch 80/08/07 1;
- --B0090501B4 IE Insp Rept 70-0143/80-23 on 800714-18 No noncompliance noted Major areas inspected training, maint, nuclear criticality safety, followup on IE info notices & independent areas KAHLELJ 8 Region 2, Atlanta, Office of the Director KENNA, W B Region 2, Atlanta, Safeguards Branch 80/08/07 5pp
- 8009150027 Forwards Revision iB to fundemental nuclear meterial control plan Encl withheld (ref 100FR2 790)
 HENSLEY.K D Nuclear Fuel Services. Inc (subs of Gatty Oil Co)
 80708/07 2pp
- 8009050408 Responds to FOIA request for list of facilities for which comprehensive evaluation repts have been prepared.NUREOs re MUF, list of documents re facility MUF & NRC decision to reopen plant Forwards NUREO-0350 & 0430 M/o encis FELTON, J M Division of Rules and Records 80/08/08 2pp
- 8009120096 Advises that security plan for low enriched matl of low strategic significance meets requirements Matls & plant protection Amend HPP-1 to License SHM-124 is amended by adding Saction 12 re physical protection requirements MCCORKLE.0 W Physical Becurity Development Branch. 80/08/11 ip
- 8009050168 Responds to FOIA request for mati received considered or approved by Commission during consideration of inventory at facility Forwards App A documents App B documents withheld restricted data (ref FOIA Exemption 3) FELTON.J N Division of Rules and Records 80/08/14 3pp
- BO09050177 Responds to FOIA request for documents re inventory difference at facility reported on 790917 List of documents listed in App A & App B App B documents withheld restricted data (ref FOIA Exemption 3) FELTON. J N Division of Rules and Records 80/08/14 Spp.
- 8009100902 Ack receipt of 800718 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0143/79-44 & 70-0143/80-20
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/14, in
- --8009100910 Forwards IE Insp Rept 70-0143/80-20 on 800517-19 Roncompliance noted O'REILLY.J P Region 2. Atlanta, Office of the Director. 80/06/24 2pp
- --8007100714 IE Insp Rept 70-0143/80-20 on 800617-19 Noncompliance noted corrective action on previous item of noncompliance dealing w/item control Details withheld (ref 10CFR2 790).
 TODD-9 A Region 2, Atlanta, Office of the Director.
 GILLESPIE,F,P Region 2, Atlanta, Bafeguards Branch. 80/06/24, ip
- BOO9120147 Ack receipt of IE Insp Rept 70-0143/80-23 on BO0714-18 No proprietary info HANSER, M C Nuclear Fuel Services, Inc. (subs of Getty Oil Co). 80/08/18 ip

- --8009120224 Forwards IE Insp Rept 70-0143/60-23 on 800714-18. No noncompliance noted KENNA, W B Region 2, Atlanta, Bafeguards Branch 80/08/07 ip
- --8009120227 IE lnsp Rept 70-0143/80-23 on 800714-18 No noncompliance noted Major areas inspected training, maint, nuclear criticality safety & follows on IC info notices KAHLE, J.B. Region 2. Atlanta, Office of the Director KENNA, U. B. Region 2. Atlanta, Safeguards Branch 80/08/07 5pp.
- 8009120124 Ack receipt of 800801 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0143/80-21 KENNA,W B Region 2, Atlanta, Bafeguards Branch 80/08/20, Ip
- --8009120126 Responds to NRC 800717 ltr re violations noted in IE Insp Rept 70-0143/88-21 Corrective actions taken & results withheld (ref 10CFR2 790) MANSER W C Nuclear Fuel Services. Inc (subs of Oatty Dil Co.). 80/08/01 ip
- --8009120130 Forwards IE Insp Rept 70-0143/80-21 on 800616-20 & notice of violation Notice of violation withheld (ref 100FR2 790).

 KENNA, W B Region 2. Atlanta, Bafeguards Branch. 80/07/17. 2pp.
- --8009120133 IE Insp Rept 70-0143/80-21 on 800616-20. Noncompliance noted failure to determine systematic weighing errors & failure to evaluate measurement control data Details withheld (ref 106FR2 790).

 JONES.D W. Region 2. Atlanta. Office of the Director.
 OILLESPIE.F.P. Region 2. Atlanta. Safeguards Branch. 80/07/17.
- 8009230404 Forwards IE Circular 80-20, "Changes in Bafe-Blab Tank Disensions," No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/21.
- 8009150395 Responds to 800B18-21 site visit re safeguarde sys for highly enriched U Forwards new conditions for Amend MPP-1 to License SNM-124 clarifying intent of tamper-safing program. PARTLOW, J G Material Control Licensing Branch 80/08/22 Ip.
- --8007180378 Revises Amend MPF-1 of License 8NM-124, incorporating Conditions 2.30 & 2.31 re personnel performance of item control audits & changing Condition 7.3 re tamper-safing surveillance # Material Control Licensing Branch 80/08/22 ip.
- 8009230325 Requests that all personnel ba reminded of purpose of emergency notification sys & health physics natural Bys installed for got use during emergency of RELLLY.J P Region 3. Chicago. Office of the Director. 80/08/22
- 8009090465 RO on 800728, fire occurred in Bldg 302 tube cleaning room Fire involved ductwork. HEPA filter media, plexigles & other matls, releasing caphonaceous sook. Room void of All radioactive matls except low level surface contamination. MANEER, H. C. Nuclear Fuei Services, Inc. (subs. of gatty Gil Go.) 80/08/27 Bpg.
- 8009040258 Motion for extension until 801015 to file direct submissions Awaiting confirmation of new NRC chairman prior to decision. Certificate of Syc enci. WEISBLE R Natural Resources Defense Council HEISBLE R Shaldon, Harmon & Weiss 80/08/29 3pp.
- 8007070504 Forwards "Rept of Effluent Monitoring & Release to Unrestricted Areas, Jan-June 1980 " MICHEL, C J Nuclear Fuel Bervices, Inc. (subs. of Qetty Oil Co.) 80/08/27 1p
- --8009090507 "Rept of Effluent Monitoring & Release to Unrestricted Areas, Jan-June 1980." * Nuclear Fuel Bervices, Inc. (subs. of Getty Gil Co). 80/08/29.
- B009240742 Advises that B00819 request for amend to mafaguards plan requires major amend to License BNM-124. Payment of Category iA fee should be made to NRC. WEISS,D License Fee Management Branch, B0/09/04 1p
- 8009110391 Forwards "Proposed Program for Determination & Demonstration of Whatman-41 Filter Media Efficiency for Collection & Retention of Soluble U Particles at NFS Perimeter Air Sampling Stations "
 HIGHEL C J Nuclear Fuel Services, Inc. (subs. of Oatty Oil Co.).
 80/09/05 1p

- --3009110393 "Proposed Program for Determination & Demonstration of Whatmen-41 Filter Hedia Efficiency for Collection & Retention of Soluble U Particles at NFS Perioater Air Sampling Stations "

 + Huclear Fuel Bervices, Inc. (subs. of Getty Oil Co.) 80/09/05
- 8007110372 Forwards response to NRC 800813 ltr ra violations noted in IE Insp Rept 70-0143/80-22 Response withheld tref 10CFR2 770) MANSER,H C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 80/09/05. 1p
- BOO9230435 Forwards IE Insp Rept 70-0143/80-22 on 800714-16 No nancompliance noted insp summary only encl (ref 100FR2 790) KENNA, W B Region 2, Atlanta, Bafeguards Branch 80/08/13 2pp.
- --9009250437 IE Insp Rept 70-0143/80-22 on 800714-16 No noncompliance noted Major ereas inspected corrective actions to items 60-08-1.80-08-02 % 79-46-01.security organization & barriers Details withheld (ref 10CFR2 790)
 TOBIN.H.J. PERNY.C D Region 2, Atlanta, Office of the Director GillESPIE.F P Region 2, Atlanta, Safaguards Branch 80/08/05 ip
- BO09120421 Forwards Chapter 19 of physical safeguards plan M/o encl MICHEL,C.J. Nuclear Fuel Services, Inc (subs of Getty Dil Co) BO/09/08 ip
- BOO9240624 Ack receipt of BOO721 Itr,informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0143/BO-13
 BTGHR,J.P. Region 2. Atlenta. Fuel Facility & Materials Bafety Branch. BO/09/08 1p
- --B009240631 Responds to NRC 800626 ltr re violations noted in IE Insp Rept 70-0143/80-13 Corrective actions employee exposure repts & affluent release data updated MANSER, N C Nuclear Fuel Services. Inc (subs of Getty Oil Co.), 80/07/21 4pp
- --B009240637 Forwards IE Insp Rept 70-0143/80-13 on 800321,0421-25 & notice of violation STDHR,J.P. Region 2, Atlanta, Fusi Facility & Matarials Safety Branch 80706/26 2pp
- --8009240640 Notice of violation from insp on 800321,0421-25.

 ** Region 2. Atlanta, Office of the Director 80/06/23. is
- 8009270374 Revises License Condition 2 1 of Amend MPP-1 to incorporate revised Section 6.0 & App C Revised Sections 1 0 & 8 O require addl clarification PARTLON.J O Physical Security Licensing Branch. 80/09/10 2pp.
- 8009250435 Notifies of intention to be rapresented by NRDC for written testimony before 801001

 SHERBONDY, S. N. Affiliation Unknown 80/09/16 1p
- 8009240559 Advises that Plant 1 inventory difference for Jul 1980 high enriched U physical inventory exceeded limit of error Encl withheld (raf locraz, 790). HENSLEY,K D. Nuclear Fuel Services, Inc. (subs of Oetty Qil Co.), 80/09/19 1p
- S009250053 Order effectively denying NRDC 800714 petition to stay effectiveness of decision that granted lagislative hearing w/o discovery privileges. Sets schedule for hearing. Grants additiated participations JF Aharma separate views encl CHILK.S J Office of the Secretary of the Commission. 80/09/22 App.
- BOO9300475 Forwards mat) balances covering inventory period May-Aug 1980. Encl withheld (ref 100FR2 790) HENSLEY,K.D. Nuclear Fuel Services, Inc. (subs of Oatty Oil Co). BO/09/24 1p

DOCKET 70-0258 ILLINDIS, UNIV OF, URBANA-CHAMPAIGN

BOO9120Ail Application to amend License SNM-23A, increasing max amount of U-235 to 300 g. Description of use & analysis of hazards encl.

MANDEL.H. Illinois, Univ. of, Urbena-Champaign BO/04/03 Bpp

- --8007120614 "UF6 Handling Sys for Nuclear-Pumped Laser Experiments "
 BOODY.F P Illinois, Univ of, Urbana-Champaign 78/12/31 27pp
- 8007150181 Amend 1 to License SNM-236, authorizing posession of up to 300 g U-235 to be used in experiments
 PAGE.R O Uranium Fuel Licensing Branch 80/09/29 ip
- --8009150183 Bafety evaluation supporting Amend 1 to License SNM-236 SOBNO.A L , CROW.W T Uranium Fuel Licensing Branch 60/08/29 Spp

DOCKET 70-0312 MASSACHUSETTS, UNIV OF

- 8009100634 Ack receipt of 800806 ltr informing NRC of steps taken to correct sipiration of license noted in TE Insp Rept 70-0312/E0-02 KINNERAN, J D Region 1, Philadelphia, Office of the Director 80/08/14 lp
- --H009100447 IE Insp Rept 70-0312/GO-02 on 800707 No noncompliance noted Major areas inspected expiration of license & application for new license Kinneman. J. Region 1. Philadelphia, Fuel Factifity & Materiale Befety Branch ROWE.CA Region 1. Philadelphia, Office of the Director BO/08/13 2pp
- --B009100651 Application for renewal of License SNM-292 KOFFLER, H Massachusetts, Univ of 80/09/06 lp.
- DOCKET 70-0343 RUTGERS, NEW JERSEY, THE STATE UNIV OF
- 8009120529 Ack receipt of 800710 ltr informing NRC of steps taken to correct violation noted in IE Inap Repts 70-0343/80-01. 30-06983/80-01.30-06991/80-01 & 30-00356/80-01 EMITH, O H. Region 1. Philadelphia, Fuel Facility & Materials Bafety Branch 80/08/14 1p
- --8009120936 Responds to NRC 800624 itr re violation noted in IE Insp Repts 70-0343/80-01.30-00883/80-01.30-06991/80-01 & 30-00356/80-01 Corrective actions research procedures will be reviewed & bulletin issued NOMELL.D.B Rutgers.New Jersey. State Univ of Busch Campus 80/07/10 2pp
- --809120942 Forwards IE Insp Repts 70-0343/40-01,30-00803/40-01, 30-06971/40-01 & 30-00356/80-01 on 800501-02 % notice of violation KINNEMANJ D Region 1. Philadelphia, Fuel Facility & Materials 9afety Branch 80/06/24 2pp
- --B00912054B Notice of violation from insp on B00501-02 Noncompliance noted individual in biochemistry dept worked w/mCi quantities of tritium w/o registering or w/o authorization from radiation safety ofc

 * Region i, Philadelphia, Office of the Director E0/06/24 Ip

DOCKET 70-0349 NORTHWESTERN UNIV . EVANSTON - CHICAGO

- B009110827 Requests amend to Liconses 12-00382-03,12-00382-05, 12-00074-06,8UD-556 & BNN-330 to reflect encl membership of radiation safety committee
 MILLER, D.R. Northwestern Univ 80/06/25, 2pp
- --B009110B31 Notifies that amend to Licenses 12-003B2-03, 12-003B2-05, 12-00094-05, BUD-556 t. BNN-330 is fee exempt COUPER, J. Region 3. Chicago, Office of the Director 80/06/30
- --8009110835 Notifies that amend to Licenses 12-00382-03.12-00382-05. 12-00094-06.SUD-556 & ENM-330 is fee exempt HILLER.H.D License Fee Management Branch 80/07/18 ip.
- DOCKET 70-0364 PARKS TOWNSHIP SITE, BARCOCK & WILCOX CO
- 8009230138 Requests amend to Tech Spec 1 B 5 revising Pages 1.B.5 14 & I B 5 14(a), providing criteria for use of continuous monitors & clarifying use of general air samplers at Pufacility
 AUSTIN. H A Babcock & Hilcox Co , Nuclear Material Div. 80/07/02, 1p.

- --8009230137 Revised Tech Spec Pages I B 5 14 & I B 5 14(a), providing criteria for use of continuous monitors & clarifying use of gameral air samplers at Pu facility
 + Babrock & Wilcox Co , Nuclear Material Div 80/07/02 2pp
- BOO9160179 Forwards IE Insp Repts 70-0195/80-16 & 30-0364/80-14 on 800609-13 No noncompliance noted MARTIN.W G Region 1, Philadelphia, Safeguards Branch 80/07/08.
- --8009160186 IE Insp Repts 70-0135/80-16 & 30-0364/80-14 on 800609-13 No noncompliance noted Major areas inspected physical inventory & assessment & observation of nondestructive assay work performed by licenses Details withheld (ref 10CFR2 770) BISSETT, P H, SUMMERS,R J Region 1, Philadelphia. Office of the Director JOYNER, J H Region 1, Philadelphia. Safeguards Branch 80/07/01 ip
- 8009110262 Ack receipt of 800718 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0135/80-15 & 70-0354/80-13 MARTIN-W O Region 1, Philadelphia, Safeguards Branch 80/08/05
- --8009110274 Forwards IE Insp Repts 70-0135/80-15 & 70-0364/80-13 on 800505-30 & notice of violation MARTIN.W © Region i, Philadelphia, Safeguards Branch 80/06/24 20p
- ~~8009110276 Notice of violation from insp on 800505-30 # Region i, Philadelphia: Office of the Director 80/06/23 i;
- --8009110281 IE Insp Repts 70-0135/80-15 & 70-0364/80-13 on 800505-30. Noncompliance noted failure to perform nuclear criticality systemation JOYNER. J H. Region 1. Philadelphia. Safeguards Branch KUSHNER. W L. Region 1. Philadelphia, Office of the Director 80/06/23. 90p
- 800911044B Forwards amend to Section 9 O of Amend MPP-1 to License SNM-414, approving interim physical security plan by withdrawing License Conditions 9 1.9 1A/9.18 & 9 iC & reissuing License Condition 9 1 MCCORKLE.O W Physical Security Licensing Branch 80/08/11 2pp
- 8009150524 Orants 800326 & 0623 requests for exemption from certain code requirements for packaged SNM in form of waste Waste must be limited to solid matls & afforded physical protection per code BURNETION F Division of Safeguards 80/08/11 2pp
- 8009150480 Forwards rept on radioactive effluents discharged to unrestricted areas as result of work performed under Licenses SNM-145 & SNM-414 Rept covers Jan-June 1980 AUSTIN, M A Babcock & Wilcox Co , Nuclear Material Div 80/08/13 3pp
- 8009230409 Forwards IE Circular 80-20, "Changes in Safe-Biab Tank Dimensions" No written response required ORIER.B H Region 1. Philadelphia. Office of the Director 80/08/21 4pp
- 8009230211 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency ORIER, 8 H. Region 1. Philadelphia, Office of the Director 80/08/22 Spp

OCKET 70-0371 UNITED NUCLEAR CORP

- 09120150 Forwards IE Insp Rept 70-0371/80-10 on 800616-20 No noncompliance noted MARTIN, W G Region 1, Philadelphia, Safeguards Branch 80/07/11 to
- 8009120235 IE Insp Rept 70-0371/80-10 on 800516-20 No noncompliance noted Major areas inspected: facility organization & measurement control program Details withheld (ref 100FR2 790)
 ZIBULBYV.H , MOLTNER.E Region 1, Philadelphia, Office of the Director JOYNER.J H Region 1, Philadelphia, Safeguards Branch 80/07/08 1P
- 8009240660 Discusses requirement that central & secondary alarm stations must have ability to take control of all electronic security sys in event of collusion by guards or takeover by intruders

 MIRK.W F. United Nuclear Corp. Naval Products Div 80/07/15 Gpp

- 8009100642 Responds to 800530 ltr in response to IE Insp Rapt 70-0371/80-05 & notice of violation flem of noncompliance regalins MARTININ Q Region i, Philadelphia, Safeguards Branch. 80/08/13. 300
- --8009100646 Forwards IE Insp Rept 70-0971/80-05 on 800401-03 & notice of violation Notice of violation withheld (ref 10CFR2 790).
 MARTIN, H. G. Region 1, Philadelphia, Safeguards Branch. 80/05/09
- --8009100652 IE Insp Rept 70-0371/80-02 on 800401-03 Noncompliance nets/failure to properly store & tamper-wafe seal unattended SNM container & to maintain exit portal SNM detector in operable condition Details withheld (ref 100FR2 790) MADDEN:W Region i. Philadelphia, Office of the Director DEVLIN.J Region i. Philadelphia, Safeguards Branch. 80/05/07.
- 8009230416 Forwards IE Circular 80-20, "Changes in Bafe-Slab Tenk Dimensions" No written response required ORIER.B H Region 1, Philadelphia, Office of the Director, 80/08/21 4pp
- 8009230223 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Bys installed for govt use during emergency ORIER'S H Region 1. Philadelphia. Office of the Director 80/08/22 Spp

DOCKET 70-0398 COMMERCE, DEPT OF

8007230421 Forwards IE Gircular 80-20, "Changes in Bafe-Slat Tank Dimensions" No written response required GRIER H Region 1, Philadelphia, Office of the Director 80/08/21 4pp

DOCKET 70-0575 LEBANON VALLEY COLLEGE

8009160217 Discusses IE Insp Repts 70-0575/80-01 & 30-00895/80-01 on 800220 No noncompliance noted Major areas inspected actions taken to correct 750911 noncompliance HCCLINTOCKNR O. Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/02/27 ip

DOCKET 70-0600 SEATTLE UNIV

8009120043 Forwards Reg Quide 5 59 to develop physical security plan, in response to 800717 conversation Plan must be submitted by 800831. W/o encl Physical Security Development Branch 80/07/25 ip

DOCKET 70-0687 UNION CARBIDE CORP

- 8009120139 Forwards Union Carbide route w/revised guidance NUREQ-0561.
 reflecting latest amend to interim rule for physical
 protection of irradiated reactor fuel in transit
 Regulirements must be implemented by 800703 W/o encls,
 MCCORKLE.G M Physical Security Development Branch 80/07/07 1p
- 8009080489 Revises Amend MPP-3 to License SNM-639, Condition 2 : & adds Condition 2.6 to require rept of first yr recovery date from U-waste form process operation PARTLOW, J G Material Control Licensing Branch 80/08/06.
- 8009100066 Ack receipt of 800729 ltr informing NRC of add1 steps taken to correct violations noted in IE insp rept, & payment of civ11 penalty STELLO. V Office of Inspection & Enforcement, Office of the Director 80/08/21, 1p
- 8007230417 Forwards IE Circular 80-20, "Changes in Safe-Slab Tank Dimensions " No written response required. GRIERS H Region 1, Philadelphia. Office of the Director 80/98/21 App

DOCKET 70-0710 MERRIMACK COLLEGE

B009240044 Ack receipt of B00125 & 0724 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0710/79-01, 30-08305/79-01 KINNEMAN.J.D. Region I, Philadelphia, Fuel Facility & Materials Safety Branch B0/08/11 1p

- --8009240051 Responds to NRC 791204 ltr re violations noted in IE Insp Repts 70-0710/79-01 & 30-08305/79-01 Corrective action removal of sealed Pu-Be source Required surveys & tests conducted & records maintained re NRC regulations HCLAUGHLIN.J P Merrimack College 80/07/24 ip
- --B009240060 Notice of violation from insp on 791103-06 Noncompliance noted: failure to test Pu-Be source for contamination, to conduct & record required surveys w/ON survey meter & to maintain records of disposals of licensed matter as Region 1, Philadelphia, Office of the Director 79/12/04. 2pp

DOCKET 70-0734 GENERAL ATOMIC CO

- 8009120646 Advises that 800506 request for approval to ship HTQR fuel is approved Forwards approved route & data re initial arrangements w/law enforcement agencies along route Encls withheld (ref 100FR2 790) MCCORKLE.Q.W Physical Security Licensing Branch 80/06/06 ip.
- 8009020254 Forwards IE Insp Rept 70-0734/80-05 on 800603-06 No noncompliance noted BDOK:HE Region 5. San Francisco, Fuel Facility & Materials Safety Branch 80/07/11 2pp
- --BO09020261 IE Insp Rept 70-0734/80-05 on 800603-06 No noncompliance noted Major areas inspected organization, facility changes & mods, employes training, maint operations review & criticality safety CDDLEY. H. J. Region 5. San Francisco, Office of the Director. THOMAB, R. D. Region 4. Dallas, Office of the Director BOOK, H. E. Region 5. San Francisco, Fuel Facility & Materials Safety Branch. 890/07/11 Spp
- BOOGS70212 Discusses IC Insp Rept 70-0734/80-07 conducted on 600714-18 No noncompliance noted Major areas inspected program for controlling & accounting for SNM per license requirements Rept withheld (ref 100FR2 790) NORDERHAUD.L. R Region 5. San Francisco, Bafeguards Branch 80/08/10 10
- 8009040896 PNO-V-80-064 on 800811, explosion of aluminum container of UC-ThC contaminated five smployees Explosion was caused by leakage of inerting gas or by reaction w/impurities Licensee has initiated investigation THOMAS, R. D. COOLEY, H. J. Region 5, Ban Francisco, Office of the Director, 80/08/11. 2pp
- 8009170209 Discusses IE Insp Rept 70-0734/80-08 conducted on 800728-0801. No noncompliance noted, Major areas impacted activities re physical protection against industrial sabotage & against thaft of SMM Rept withheld (ref 10CFR2 790) NONDERHAUG, L.R. Region 5. San Francisco, Bafeguards Branch 80/08/20 2pp
- 8007230363 Forwards IE Circular 80-20, "Changes in Bafe-Blab Tank Binensions " No written response required EMQELKEN, R H Region 5, San Francisco, Office of the Director 80/08/21. 4pp.
- 8009160561 PNO-V-BO-064A updating rept of 800811 explosion of container of UC-ThC. Nasal wipes indicate some internal deposition may have occurred Region 5 evaluation indicates no exposures in excess of 10CFR20 limits.

 THONAB.R D . CODLEY, H. J. Region 5, San Francisco, Office of the Director 80/08/22 2pp
- 8009230334 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Bys Installed for govt use during emergency EMPELKEN.R.H. Region 5, San Francisco, Office of the Director Bn/08/22 Spp
- DOCKET 70-0754 VALLECITOS NUCLEAR CENTER, GENERAL ELECTRIC CO
- 9009190751 Forwards proposed security plan. Plan withheld (ref 10GFR2 790).
 MBSGRER, R.A., CUNNINGHAM, O.E. General Electric Co. BO/05/09. 1p.
- 8009110225 Forwards confirmation of understanding re NRC interpretation of 10CFR73 discussed in 800617 telcon. Site licensed to possess BNM requiring physical security may possess & use lass than low strategic significance amount w/o security CUMNINOHAM, G E General Electric Co 80/06/20. 1p

- 8009120149 Forwards GE route w/revised guidance NUREO-0561 reflecting latest amend to interim rule for physical protection of irradiated reactor fuel in transit Requirements shall be implemented by 800703 W/o encis MCCORKLE.G W Physical Security Development Branch 80/07/07 ip
- 8007110227 Forwards administrative amend fee as requested in NRC 800708 1tr CUNNINGHAM.0 E General Electric Co 80/07/15 ip
- --B009i10246 Responds to B0062D ltr re use of BNM outside secured areas License amend & administrative amené fee required Requests payment WEISS,D License Fee Management Branch B0/07/08 ip
- 8009120089 Forwards info requesting route approval of irradiated fuel samples shipment Immediate attention requested 4/o enc1 KIRKLAND, M W General Electric Co 80/07/28 1p
- 8009110279 Forwards info requesting route approval of irradiated reactor fuel samples W/o encl KIRKLAND, M W Deneral Electric Co 80/08/05 ip
- BOO7160235 Approves of 800330 request to amend License SNM-760, adding License Condition i & modifying License Condition 2.1 re fundamental nuclear mati control & accounting plan PARTLOW, J O Material Control Licensing Branch. 80/08/i3 ip
- --B009i60241 Amend MPP-2 to SNM-960, superseding all previous safegaurds amends. Adds License Condition 1.1 & modifies License Condition 2 1 re fundamental nuclear mat1 control & accounting program * Material Control Licensing Branch B0/08/13 5pp.
- BO09100741 Forwards TERA Corp repts. "Beismic Risk Analysis for GE Pu Facility, Pleasanton. CA: "Parts I & II. NRC bas endorsed repts for application in succeeding analyses. Byc list encl ROUSE. L. C Advanced Fuel & Spent Fuel Licensing Branch BO/08/1B
- ---B009100745 "Beismic Rist Analysis for GE Pu Facility Pleasanton, CA, " Part I * TERA Corp. 78/07/31 57pp
- --800910074B "Selamic Risk Analysis for GE Pu Facility, Pleasanton, CA " Part II * TERA Corp 80/06/27 100pp
- B009230370 Forwards IE Gircular B0-20. "Changes in Bafe-Blab Tank Dimensions " No written response required ENGELKEN.R H Region 5. San Francisco. Office of the Director B0/08/21 4pg
- 8009180289 Forwards IE Insp Rept 70-0754/80-05 on 800218-19 No noncompliance noted Encl withheld (ref 10GFR2 790) NORDERHAUO, L.R. Region S. San Francisco. Safeguards Branch

DOCKET 70-0820 UNITED NUCLEAR CORP

- 8007180927 Advises that present decommissioning plans include roundthe-clock operation, w/possibility of six to seven days/wk. Guardforce levels to be implemented on 800707 BOMERS, C E United Nuclear Corp., UNC Recovery Systems Div 80/06/24 1p
- 8009110221 Informs of decision to terminate recovery of highly enriched U at facility Requests exemption from requirements contained in 100F873, 20,73 45 & 73 46 BDHERS, C United Nuclear Corp., UNC Recovery Systems Div. 80/06/26 2pp
- ---B009110249 Ack receipt of 800626 ltr re exemption from requirements of 100FR73 20,73 45 & 73 46 Request requires minor amend to license Minor safeguards amend fee required WEIBS, D License Fee Management Branch 80/07/08 19
- --H009110252 Forwards minor safeguards amend fee requested in NRC 800708 Itr Payment made under protest HOMERS, C E United Nuclear Corp , UNC Recovery Systems Div 80/07/18 2pp.
- 8009110235 Requests waste shipments to burial be exempted from 10CFR73 67(e) & (g) requirements Potential theft of U-235 minimal Fas payment made under protest BOWERS, C. E. United Nuclear Corp., UNC Recovery Systems Div 80/06/26 239

- 009250334 Forwards IE Insp Rept 70-0820/80-08 on 800602-05 & notice of
- .. H. Region 1. Philadelphia. Fuel Facility & Matsrials Safety 80/07/01 2pp
- 8009250335 Notics of violation from insp on 800602-05 * Rigion 1. Philadelphia. Fuel Pacility & Materials Sefsty Branch 80/06/30 1p
- 8009250326 IE insp Rapt 70-0820/80-08 on 800602-05 Noncompliancs noted failure to post nuclear criticality safety limit in carshouss for storage of fissils math in innsr containsrs from URC-2600 shipping containsrs CROCKER.H W Region 1, Philadelphia, Fuel Fecility & Materials Safety Branch Kinney.W W Region 1, Philadelphia, Office of the Director 80/06/30 lipp
- 09i10267 Requests response to concerns raised by town of Charlestown, R1 re contamination of groundwetsr by radwastss EEARDLE P House of Rep 80/07/02 2pp
- 99080444 FOIA requestion behelf of Concerned Citizens of RI, for four catagories of Info re facility
 JORDAN.W 8 8hsldon, Harmon & Weiss 80/07/23 3pp.
- J9220064 Submits questions on bshalf of Concerned Citizens of RI resurial of radwasts at plent site & presence of Sr-90 in soil c/or in storage or elsewhere JORDAN, H S Encidon, Harmon & Helss 80/07/23 4pp.
- 09120155 Responds to 800826 ltr Grants specific excaption from GNM ransport requirements re scrap for burial described in ltr ICCORKLE.O W Physical Security Development Branch 80/07/31 1p
- PRIORSO Informs of engaging svcs of consultants Goldberg-Zoino & ssociatss Inc Consultants will svaluate info at facility & vill identify optimum placement & depth of test well to best ategorize containation profile
 OMERS.C E United Nuclear Corp , UNC Recovery Systems Div
- 9170001 Forwards correspondence received or generated by Governor olicy Ofc re facility Viewgraphs from 800708 meeting encl ROW, H T Uranium Fuel Licensing Branch 80/08/14 bpp
- OO9170002 Lists concerns of clisht, Concerns Citizens of RI re burial of radwasts & presence of Br-90 at sits
 JORDAN, W S Schiff, Hardin & Waits 80/07/23 4pp.
-)OP170005 Requests consideration in establishing realistic bactground radiation basis Except from data taken in Apr 1963 and BOMERS.C E United Nuclear Corp UNC Recovery Systems Div. 60/07/09 2pp 20 p
- '230413 Forwards IE Circular BO-20, "Changes in Safs-Slab Tank mensions " No writtsn response required IER.B H Region 1. Philadelphia, Office of the Director /08/21 4pp
- OBO439 Responds to FOIA request on bshalf of Concernsd Citizens of for four categoriss of info re facility Documents are allable in PDR to Ofc of NMSS LTON.J H Division of Rules and Records 80/08/22. 2pp
- 230225 Requests that all personnel be reminded of purpose of argency notification sys & health physics network Sys stalled for got use during emergency IER.8 H. Region i. Philadelphia. Office of the Director '08/22 Spp
- 110294 PNO-I-80-124: water samples taken from test wells close to fluent wasts lagoons have shown presence of redionuctides withly semples from test wells indicate byproduct matl lionuctides (NEY,W H . CROCKER,H W . SMITH,O H Region 1, Philadelphia, Office the Director 80/08/28 2pp
- T 70-0824 BABCOCK & WILCOX CD
- 30388 Forwards IE Circular 80-20, "Changes in Safe-Slab Tank Siniana " No writts n response required
 EILLY, J P Region 2, Atlanta, Office of the Director. 80/08/21.

- 8009230277 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Bys installed for govt use during emergency O'REILLY, J.P. Region 2, Atlanta, Offics of the Director BO/08/22 O'RETLLY, J P
- 8009110667 Responds to IE Bulletin 80-19. Emergency notification systems tasted during site power trip on 800705 Each unit tested a no difficulties were noted OLSEN, A.F. Babcock & Wilcox Co. 80/08/27 2pp
- DUCKET 70-0925 CIMMARON FACILITY, KERR-MCGEE CORP
- 8009180233 Submits info in response to IE Bulletin 80-15. Emergency notification sys determined to be powered by onsite power instead of by local telephone company Equipment will be relocated for power backup to safeguard instrumentation bus. SHELLEY, W J Kerr-McGee Nuclear Corp 80/08/20 2pp.
- 8009230380 Forwards IE Circular 80-20, "Changes in Safe-Slab Tank Dimsnsions " No writtsn response required.
 KEPPLER, J O Region 3, Chicago, Office of the Director 80/08/21
- 8009230280 Requests that all personnel be reminded of purpose of emergency notification sys & health physics natuork Sys installed for govt use during emergency.

 KEPPLER, J O Region 3. Chicago, Office of the Director 80/08/22.
- DOCKET 70-0959 NUCLEAR FUEL SERVICES, INC . (SUBS OF CETTY OIL CO)
- 8009230215 Requests that all personnel be reminded of purpose of smargancy notification sys & health physics network Bys installs for govt use during emergency GRIER B H. Region i. Philadelphia. Office of the Director. 80/08/22 3pp
- DUCKET 70-0984 PACIFIC NORTHWEST LAS
- 8009020235 Forwards IE Inap Rept 70-0984/80-01 on 800424-25 No noncompliance noted 800K.H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 80/07/16 2pp
- --8009020237 IE Inep Rept 70-0984/80-01 on 800424-25, No noncompliance noted Major arses inspected internal review & audit, employee training, criticality safety & radioactive waste mgt. COOLEY, W.J. TROMAS, R.D. Region 5, San Francisco, Office of the Director BOOK, H.E. Region 5, Gan Francisco, Fuel Facility & Metsrials Safety Branch. BO/07/14 4pp.
- 8007230375 Forwards IE Circular 80-20. "Changes in Bafe-Slab Tank Dimensions" No written response required ENGELKEN, R H Region 5, Ban Francisco. Office of the Director. 80/08/21 4pp
- 8009230329 Asquests that all personnel be reminded of purpose of emergency notification sys & health physics network. Bys installed for govt use during emergency ENGELKEN A H. Region 5. San Francisco, Office of the Director. 80/08/22 Spp
- DUCKET 70-1007 GENERAL ELECTRIC CO
- 8009180509 Requests emend to Conditions 34 & 35 of License BNM-54 CUNNINGHAM.9 E. General Electric Co 80/06/27 2pp.
- 8009230370 Forwards IE Circular 80-20, "Changes in Bafe-Blab Tank Officerions "No written response required English Tan English Tan ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/08/21 4pp
- DOCKET 70-1097 GENERAL ELECTRIC CO.
- 8009230396 Forwards IE Circular 80-20, "Changes in Safe-Slab Tank Dimensions " No written response required.
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/21.

DOCKET 70-1100 COMBUSTION ENGINEERING. INC.

- BOOP15002B Application for review of ravised Section 5 1, inventory requirements, of fundamental nuclear math control plan for License SNM-1067 Plan is being forwarded under separate cover.
 LICHTENBERGER C-E Power Systems 80/06/17 ip
- GCO9110706 Informs NRC that quarterly reporting requirement for 1980 second quarter was axcasded as result of absolute filter change in FA-4 vantilation sys Caused by failure to replace filters in tight-sealing configuration

 LICHTENBERGER Combustion Engineering, Inc. 80/07/10 2pp
- 8009160136 Ack receipt of 800710 itr reporting incident durany e00624 HEPA filter installation resulting in minor release of radioactivity into environ Corrective actions will be reviewed CURNINGHAM, R.E. Division of Fusi Cycle & Material Bafety E0/08/04.
- BOO9230405 Forwards IE Circular 80-20, "Changes in Safe-Slab Tank Bimanaions." No writtan rasponae requirad, CRIER, B.H. Region 1, Philadaiphia, Office of the Director 80/08/21 4pp

DOCKET 70-1113 GENERAL ELECTRIC CO

- 8007090866 Application for Amend b-19 to Licensa SNM-1097, authorizing acclusion of raviaw & audit required by iOCFR70 57(b)(3) for DDE or Natl Labs Details withhald (ref 10CFR2 790) KAPLANA.L. General Electric Co , Nuclear Energy Producta DIV 80/06/ii. ip
- 8009:1901il Raquasts amend to Licensa ENM-1097 to construct warshouse bidg on plant site Datalla andi KAPLAN.A.L. Ganarai Electric Co.. Nuclear Energy Products Div BO/06/11 4pp
- 8009240312 Discusses environ assessment for facility mode Forwards quartions re conversion plant expansion, incinerator replacement & environ rept SPAETM M.E. Science Applications, inc. GO/07/21 12pp.
- 8007170242 Responds to 800611 ltr ra application for Amend N-B, praposing warshouse bldg const Prior to bldg use, fundamental nuclear mat1 control plan must be modified.
 PARTLOM J C. Material Control Licansing Branch. 60/08/12 ip.
- B009100290 Forwards IE Insp Rept 70-1113/80-13 on B00B11-13. No noncoepitance noted. KENRA/M B Region 2. Atlanta, Safsguards Branch B0/08/20. 2pp
- --BUUY100297 IE Insp Rept 70-1113/80-13 on 80081i-13. No noncompliance moted. Hajor areas inspected wasta treatment plant & chemical lagoon, Liquid effluent pathway toured for preparation of EIA pertaining to new incinerator.

 AENNAL B Region 2, Atlanta, Bafaguards Branch KAHLE, J B. Region 2, Atlanta, Office of the Director. 80/08/19. 3pp.
- BOOM110126 Ack recaipt of 800B15 ltr informing NRC of atape taken to correct violations noted in IE Inap Rapt 70-1113/80-10 KENNA, W B. Region 2, Atlanta, Safeguarda Branch. 80/08/27 ip.
- --8009110161 Responds to NRC 800717 ltr re violations noted in IE Inep Rept 70-1113/80-10 Corrective actions, survey conducted to determine solutions naceasary to provide positive assurance that referenced problems would not occur. KAPLAN.A.L. General Electric Co 80/08/15 2pp
- --BO09110153 Notice of violation from insp on 800623-27
 a Region 2. Atlanta, Office of the Director. 80/07/16 ip.
- --B009110150 IE Insp Rapt 70-1113/80-10 on B00623-27. Noncompliance noted: failure to keep fuel rod cabinet doors closed when unattended. KAHE.J.B., KENNA, W. B., Ragion 2, Atlanta, Safeguards Branch. B0/07/16 6pp
- BOOTISO601 Ack receipt of 800821 ltr forwarding IE Insp Rept 70-1113/80-12 KAPLAN,A.L. General Electric Go , Nuclear Energy Products Div BO/09/28. Ip.

- --8009150604 Forwards 1E insp Rapt 70-1113/80-12 on 800811 No noncompliance noted KENNA W B Region 2, Atlanta, Bafeguarda Branch. 80/08/21 2pp
- --8009130605 IE Insp Rept 70-1113/80-12 on 800811 No noncompliance noted Major areas inspacted license conditions & storage procedures KARLE, J. B. Region 2, Atlanta, Bafeguards Branch CORYELL, O P. Region 2, Atlanta, Office of the Director 80/08/21 3pp
- 8009260525 Forwards request for addi environ info re license amend application on installation & use of incinerator & major plant expansion Response should be submitted by 800922 SHUMLE Y Uranium Fuel Licensing Branch 80/09/15 7pg

DOCKET 70-1120 WESTINGHOUSE ELECTRIC CO

- B009030046 Advises that procedures for decommissioning activities must be submitted & approved by NRC before any shipments can be made PARTLOW, J. O Material Control Licensing Branch B0/08/06 ip
- DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP
- S009100187 Forwards application for amend to Licensa BNM-1120, adding ancl description for decontaminating & decommissioning glove boxes
 DIPIAZA, R P Westinghouse Electric Corp. 80/06/12 Spp
- ---8009100193 Application for amend to Ličense SNM-1120, describing ataps for decontaminating & decommissioning glove boxes. # Westinghouse Electric Corp. 80/06/12 21pp
- 8009230i69 Forwards marked-up fraft fundamental nuclear meti control plan for decommissioning activities & fraft proposed license conditions re measurament control Lists suggested revisions for control plan W/o and suggested revisions PARTLON, J.O. Material Control Licensing Branch. 80/07/23 ip
- 8009180360 Amends License BNN-1120, adding License Condition 5.3 retemporary storage of contaminated equipment in temper-safe containers at assimated BNN values, in response to 800709 request.
 PARTLONIJ 9 Material Control Licensing Branch. 80/08/06 ip
- 8007230405 Forwards IE Circular 80-20, "Changes in Bafs-Slab Tank Dimensions " No written response required ORIER, B H Ragion 1. Philadeiphia, Offica of the Director. 80/08/21 App
- 800923022B Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during amergency ORIER, BH Ragion 1, Philadelphia, Office of the Director 80/08/22. Spp

DOCKET 70-1191 WESTINGHOUSE ELECTRIC CORP

- 8009190108 Forwards into ra const & usa of new facility for U hexafivoride cylinders New facility will be extension of existing waste storaga bldg. Const to begin mid-Aug No licensa amend necessary REITLER.E K. Westinghouse Electric Corg , PWR Systams Div 80/06/30 3pp
- 8007100681 Approvas 800624 request for withholding propriatory pages of application for amend Pages contain trade secrets, confidential or commercial info CUNNINGKAM.R.E Division of Fuel Cycle & Material Befety 80/08/11.
- 8009170079 Advises that 1:200 lb of molybdenum acrep described in 800529 ltr may be released for unrestricted use. PAGE:R O Urenium Fuel Licensing Branch. 80/08/11 ip.
- 8007050173 Forwards IE Insp Rept 70-:151/80-19 on 800721-22 No noncompliance noted MURPHY.C E Region 2: Atlanta: Reactor Construction & Engineering Support Branch 80/08/12 2pp
- --B009050176 IE Insp Rept 70-1151/80-19 on 800721-22.No noncomplianta noted Major areas inspected fire protection/prevantion. MILLER.W.H. Region 2. Atlanta, Office of the Director. CONLONITE Region 2. Atlanta, Reactor Construction & Engineering Support Branch, 80/08/12 Spp

- 8009230397 Porwards IE Circular 80-20, "Changes in Safa-Slab Tank Dimensions" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/21 480
- 8009110122 Ack receipt of 800811 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1151/80-18
 KENNA-W B Region 2, Atlanta Safeguards Branch 80/08/27 lp
- --B009110135 Responds to NRC B00728 ltr re violations noted in IE Insp Rept 70-1151/80-18 Corrective actions withheld (ref 10CFR2.790) G00DHIN.W L , D'AMORE.M Westinghouse Electric Corp 80/08/11
- --8009ii0139 Forwards IE Insp Rept 70-1151/80-18 on 800624-26 & notice of violation Notice of violation withheld (ref 10CFR2 790)
 KENNA.W B Region 2. Atlanta, Safeguards Branch 80/07/28 2pp
- --8009110142 IE Insp Rept 70-1151/80-18 on 800624-24 Noncompliance noted failure to establish adequate inventory procedures Details withheld (ref 10CFR2 790)
 TODD.0 A Region 2, Atlanta, Diffice of the Director.
 OILLESPIE,
- 8009250062 Forwards IE Insp Rept 70-1131/80-24 on 800812-14 No noncompliance noted KENNA-W B., Region 2. Atlanta, Safeguards Branch 80/08/29, 2pp
- --8009250066 IE Insp Rept 70-1151/80-24 on 800812-14 No noncompliance noted Major areas inspected facility organization math control measurements, physical inventory & math control Details withheld (ref 100FR2 790)
 GILLESPIE.FP Region 2. Atlanta. Safeguards Branch. JUNES, D. W. Region 2. Atlanta, Office of the Director 80/08/29 ip.
- 8009230464 Amend 6 to License SNM-1107, authorizing use of SNM in advanced waste treatment process
 PAGE.R O Uranium Fuel Licensing Branch 80/09/11 4pp.
- --8009250470 Rafety evaluation re 800407 & 0624 applications to authorize operation of advanced waste treatment process Concludes that U recovery operations can be conducted w/o undue risks to public & personnel health & safety Recommends approval SIEVENSON.R L . CROW.R T Uranium Fuel Licenting Branch 80/09/11 3pp
- DOCKET 70-1167 NORTHWESTERN OKLAHOMA STATE UNIV
- 9009260389 Forwards IE Bulletin 79-19, "Packaging of Low Level Radwaste for Transport & Burial " Response required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/08/10, ip
- --8009260416 Responds to IE Bulletin. "Packaging of Low Level Radwaste for Transport & Buriai " Licensee reminded of writtan response requirement. • Northwestern Oklahoma State Univ. 79/11/01 1p
- --8009260419 Responds to IE Bulletin 79-19, "Packaging of Low Level Radwaste for Transport & Burial " No radwaste generated BROWLK H Northwestern Oklahoma State Univ. 79/11/07 ip
- DOCKET 70-1193 CIMARRON FACILITY, KERR-MCGEE CORP
- 8009150239 Submits info in response to IE Bulletin 80-15 Emergency natification sys determined to be powered by onsite power instead of by local telephone company. Equipment will be relocated for power backup to safeguard instrumentation bus SMELLEY, N. J. Kerr-McGee Nuclear Corp. 80/08/20. 2pp
- 8007230380 Forwards IE Circular 80-20, "Changes in Safe-Slab Tank Dimensions " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director, 80/08/21.
- 8007230280 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network. Sye inetailed for govt use during emergency KEPPLER, J.O. Region 3. Chicago, Office of the Director. 80/08/22 3pp
- E009190760 Requests amend fee re B00B21 NRC granting of specific exemption from requirements of upgrade rule for Category I SMI WEISS.D License Fee Hanagement Branch 80/09/03. 1p

- DOCKET 70-1201 UF & CONVERSION FACILITY, BABCOCK & HILCOX CO
- 8009030004 Application for amend to License SNM-1168 revising action levels for air effluent releases to unrestricted areas & isolation criteria between fuel assembly storage array & shipping container loading area # Babcock & Hilcox Co. 80/06/12, 10pp
- 8009090874 Application to amend SNM-1168, authorizing storage of SNM over 12 months w/measurement uncertainties greater than 10% & limited use of nonrepresentative stds Attachments withheld (ref 10CFR2 790)

 ZEFF, D W General Electric Co 80/06/26 ip.
- B009180517 Forwards fundamental nuclear mati control plan for MRC approval Plan submitted as Revision O.including revised table of contents & page—date index Plan withheld (ref 10CFR2 790)
 ZEFF,D H Babcock & Hilcox Co. B0/07/15, 1p
- 8009230457 Forwards gaseous effluent monitoring results for Jan-June 1980 ZEFF,D.W. Babcock & Wilcox Co. 80/08/20 2pp.
- 8009230398 Forwards 1E Circular 80-20, "Changes in Safe-Slab Tank Dimensions," No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/08/21
- 8009290266 Informs that review of fundamental nuclear mati control plants complete Recommends deleting License Conditions 1,1,2 4, 2,5,9 1,4,4,5 to 2,5,3 4, 1,6 2,7 to 8 to 8 adding License Condition 7 S re tamper-safing.

 PARTLOW, J O Physical Security Licensing Branch 80/09/09, 1p.
- DOCKET 70-1220 GENERAL ELECTRIC CD
- 8009230383 Forwards 1E Circular 80-20, "Changes in Gafe-Slab Tank Dimensions" No written response required KEPPLER.J O. Region 3, Chicago, Office of the Director. 80/08/21
- DOCKET 70-1257 MIXED OXIDE FABRICATION PLANT, EXXON NUCLEAR CO., INC.
- 8009040473 Forwards upgraded & clarified revisions to SNH-1227 license renewal application. ESTEV.H P. Exxon Nuclear Co., Inc. (subs. of Exxon Corp J. 80/06/05 2pp
- --8009040475 Application for amend to 8NM-1227, authorizing activity of mechanical operations involving recovery of U from solid wastes

 * Exxon Nuclear Co., Inc. (subs. of Exxon Corp.), 80/08/05
 1000
- 8009110278 Application to amend license to require only single storage stage HEPA filtration of exhaust air from U processing facilities Amended Table 3 3-1 k Figure 2.3-2 encl
 EBTEY,H.P. Exxon Nuclear Co , Inc (subs of Exxon Corp.).
 80/06/19 3pp.
- 8009110718 Application to amend License SNM-1227, authorizing increase in possession limit of SNM in form of enriched U from 10 to 35 g ETSEY, H P Exxon Nuclear Co , Inc (subs. of Exxon Corp.), 80/06/27.
- 8009160523 Responds to IE Bulletin 80-15, "Possible Loss of Emergency Notification 84s (ENS) w/Loss of Offsite Power." ENS equipment located at Qaneral Telephone Co North Richland Central Ofc physically inspected on 800624 ESTEV. H P Exxon Nuclear Co , Inc (subs. of Exxon Corp.) 80/07/07 Spp
- 8009100232 Forwards "Risk Analysis for Postulated Pu Releases From Erron Nuclear Mixed Oxide Fuel Plant as Result of High Winds & Earthquakes." Recommends review & conclusions be adopted as staff position subj to approval.

 AVER, J E . BURKHARDT, H. Advanced Fuel & Spent Fuel Licensing Brench.
 80/08/14 1p.

- ---BOOT10023B "Risk Analysis of Postulates Pu Releases From Exxon Nuclear Hized Oxide Fuel Plant As Result of High Winds & Earthquakes "
 - renquexes Probabilistic Analysis Otaff 80/08/14 29oo
- 8009150389 Requeste review of procedures for SNM accounting determination re changes required to solve problems listed a revision of fundamental nuclear math control plan to facilitate incorporation of addl procedures PARTLOWJ Q Material Control Licensing Branch 80/08/14 2pp
- 8009230367 Forwards IE Girculer 80-20. "Changes in Safe-Slab Tank Dimensions." No written response required ENGELKEN.R H Region 5. San Francisco, Office of the Director BO/08/21 4pp
- GOO9230332 Requests that all personnel by reminded of purpose of amergency notification sys & health physics network Sys installed for port use during emergency ENGELKEN,R H. Region 5, San Francisco, Office of the Director, BO/08/22 Spp
- 8009250472 Forwards revised License SNM-1227 & eafsty evaluation rept PAGE.R 0 Uranium Fuel Licensing Branch 80/09/10 ip

- DOCKET 70-1308 HORRIS OPERATIONS, GENERAL ELECTRIC CO.
- 8007110488 Forwards info re ages & everage burnup of fuel presently in storage in response to 800630 telcon & request by T Glark. DAMSON, D M General Electric Co E0/07/01 3on
- 8007120543 Summary of 800610 meeting w/OE re 800123 request for amend to License SMM-1265 CLARK, A T Advanced fuel & Spent Fuel Licensing Branch 80/07/07
- B009050431 FOIA request for documents re possible purchase, lease or condemnation of facility by federal govt
 MILLERIM E Mudge, Rose, Outhrie & Alexander 80/07/18. 2pp.
- BOOT050439 Requests that date referenced in revised amend request be changed to BOO123 From BOO118 DAMBON.D M. General Electric Co BO/07/18 2pp
- 8009150409 Forwards 780010 memo re meeting between Southwest Muclear Co & MRC.as follows to 800804 telcon
 EMPBON.F M. Advanced Fuel & Spent Fuel Licensing Branch 80/08/06
- --80091804;2 Busmary of meeting w/Bouthwest Nuclear Co re use of Carey Salt Mine in Lyons, KB for low level waste disposal, Lyons Chamber of Commerce 780327 1tr & sketch of receiving area OCHNOON, T. C. High Level Waste Technical Development Branch. 78/08/10, Spp
- ROOF030445 Add1 response to FOIA request for documents re possible purchase, lease or confermation of facility by federal govt Forwards documents listed in App A, FELTOM, J. H Division of Rules and Records 80/08/11 2pp.
- 8009270070 Formards IE Insp Rept 70-1308/80-04 on 800729-0801. No nonrempliance noted
 DAVIS, A B. Region S. Chicago, Fuel Facility & Materials Safety 80/08/18. 200
- -800#270074 IE Inep Rept 70-1308/80-04 on 900727-0801. No noncompliance noted. Major areas inepected, fuel receipt & storage, external exposure control, respiratory protection & bioassay program PECK, C. C. Region 3, Chicago, Office of the Director FISHER, W. L. Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/08/15, App.
- 8009230383 Fu, sarés IE Circular 80-20, "Changes in Bafe-Slab Tank Dimensions " Ne written response required KEPFLER J. O. Region 3: Chicago, Office of the Director. 80/08/21.

- 800903037B Forwards revised description of compressed air sys Only few changes necessary to adapt description to current configuration of sys.per 800716 telcon DAMSON.D M General Electric Co 80/08/25 4pp
- 8009170078 Requests assistance in evaluation of contentions admitted by ASLB re renewal of GE License SNM-1265 for storage of irradiated LWR fuel & in preparation of testimony for ASLB ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch 60/08/27
- 8009170083 Requeste assistance in evaluation of contentions admitted by ASLB re renewal of GE License SNM-1265 for storage of irradiated LWR fuel & in preparation of testimony for ASLB hearing
 ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch 80/08/27
- 8009170086 Requests assistance in evaluation of contantions admitted by ASLB rs renewal of CE License SRM-1265 for storage of irradiated LWR fuel & in preparation of testimony for ASLB ROUSE, L C Advanced Fuel & Spent Fuel Licensing Brench 80/08/27
- 8007080033 Advises that NRC does not intend to respond to applicant 800819 motion to compel State of IL answers to 800804 discovery requests ROTHSCHILD: M U. Hearing Branch 1 80/09/04
- 8009100325 Informs that deposition of DM Dawson re licenes renewal will begin in Chicago on 800912 Related correspondence.
 RODNEY, M A Mayer, Brown & Platt 80/09/04 1p
- 8009090461 Advises that responses to GE 800814 motion to compel discovery against Rorem dus 800829 GE believes motion to be complete: since no response has been received Also believes that ASLB is ready to rute Related correspondence ROONEY. If A Mayer, Brown & Platt 80/09/05 2pp
- 8007i10015 Advises that NRC will attend & examine at DM Deuson 8007i2 deposition in Chicago. IL per 800704 telcon during which no objection was stated DACHMANN.R O Rulemaking & Enforcement Division 80/09/07. ip
- 8009120022 Order advicing BL Rorem, et al to respond to applicant & NRC interrogatories by 800930 Motions for summary disposition shall be filed by parties by 801020 & subsequent responses by 801110 Q00DHDF.A.C Atomic Safety and Licensing Board Panel 80/09/09
- 0009140403 Requests AT Clark & FD Fisher for depositions in Chicago, IL on 801001 AT Clark deposition will concern present facility operation, licensing application & planned operation, Fisher will be deposed re Contentions 4-6 SEKULER, & N 1111nois. State of 80/09/10 ip
- 8007160374 Discusses OE 800817 motion to compal discovery against State of IL No response was received from State of IL by 800703 Record re motion is complete & ready for ruling by Spard ROCKEY. H A Mayer, Brown & Platt, 80/07/11, 1p.
- B009230044 Advises that AT Clark & FD Fisher will be available for ROTHECHILD, N U Hearing Branch 1 80/09/19 ip.
- 8009300580 Forwards GE 800917 ltr & Revision 5 to NEBO-20776, "Spent Fuel Sycs Operation GA Plan " Related correspondence RDONEY, M A Meyer, Brown & Platt, 80/09/24 2pp.
- --8009300585 Forwards Revision 5 to REDD-20776, "Spent Fuel Sycs Operation GA Plan," Syc list encl. DAWSON.D M Operal Electric Co. 80/09/17. 2pp.
- --8009300586 Revision 5, "Spent Fuel Bucs Operation GA Plan" * Ceneral Electric Co NEOD-20776 R5, 80/07/15 10pp
- 8009300018 Advises of 800919 approval of new iOCFR72, "Licensing Requirements for Storage of Spent Fuel in Independent Spent Fuel Storage Installations "Regulation will be provided upon issuance & publication of final form

- 8009300049 Anticipates delay in issuance of NRC safety evaluation due to Commission approval of 10CFR/2 for which add1 info & review are required firm issuance date will be provided when established

 80CHMANN, R Q Rulemaking & Enforcement Division 80/09/26 1p.
- DOCKET 70-1309 MORRIS OPERATIONS, SOURCES & STANDARDS, GENERAL
- 8009230383 Forwards IE Circular 80-20, "Changes in Safe-Sleb Tenk Dimensions" No written response required. KEPPLER, J. C. Ragion 3, Chicego, Offics of the Director 80/08/21
- DOCKET 70-1927 UF & CONVERSION FACILITY. ALLIED GENERAL NUCLEAR
- 8009170346 Comments on relemating 50-5 re mixed oxide fuel GESMO & other resustance discensing proceedings should continue Positive affirmative action to approve licenses recommended KIRK-W F William F Kirk BO/OS/28 4pp
- 8009:00490 Comments on RM 50-5 public should be advised of advantages & dieadvantages of implementing Pu recycle NRC should not have terminated efforts on GESMO fuels DECMER.U Affiliation Unknown 80/09/03 ip
- 8009160224 Requests GESMO re fueld be completed Info is needed for future decisioners reprocessing of spent nuclear fuel VILLEMY.O R Affiliation Unknown 80/09/08 1p
- 8009160420 Comments on rulemaking 50-5-DESMO proceedings should be reopened to provide early procedural framework for subsequent licensing RICKARDS/R B General Electric Co 80/09/08 2pp
- 8009300514 Expresses concern re respening of OEBMO & other related licensing proceedings for reprocessing sites. FEIO.0 Aff511ation Unknown 80/09/13 lp
- 8009220226 Comments on rulsmaking 50-5 CESMO proceedings should be rappened Technical economic & safety issues must be addressed in order for decisions to be made re use of mixed-oxide fuels
 WEITZBERG, A. Affiliation Uninown 80/09/15 is.
- 8009260641 Urgss resumption of GESHO hearings BOLON, A. E. Affiliation Unknown 80/09/16 1
- --8007260646 Opposes reopening of GESMO hearings BURRELL.A Affiliation Unknown 80/09/13 I
- --8009260652 Urges reagening GESMO & recycle-related proceedings & consideration of expanding scape to include recycle of LMR fuel in breeder reactors

 MCCORMACK: M House of Rep 80/09/22 2pp
- 8009300525 Forwards comments in response to Commission 800807 order reterminated OESMO proceedings Reopening would be inimical to nati security & defense & at odds w/nongroliferation objectives
 BIACIKE. I New York, State of 80/09/23 7pp
- 8009300540 Comments on reopening of QESMO proceedings Add1 use of nuclear generated elsctricity should be paced to preserve significant quantities of hydrocerbon reserves for use as raw matts in future chemical mfg BURRISL American Institute of Chemical Engineers, 80/09/23 2pp.
- 8009300549 Request extension of time for comment on Commission 800807 order re reopaning GESMO proceeding HOLDEN-R, B Ailied Osneral Nuclear Services 80/09/23 ip
- 8009300361 Supports respening of SESHO & other recycling license proceedings
 PRICE-J E Affiliation Unknown 80/09/23 is

DOCKET 70-1349 HOSPITAL PAVIA

8009260274 Forwards IE Circular 80-19, "Noncompliance W/License Requirements for Medical Licensees" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/08/26

- DOCKET 70-1377 HANNA MINING CO
- 8009300606 Discusses IE insp of Licensee 22-05587-01, 22-015785-01, SNM-1333, SNM-1841, SNM-1864 on 800814-15 & forwards notice of violation DAVIB, A B Region 3, Chicago, Fuel Fecility & Materials Safety Brench. 80/09/02 2pp
- --8009300611 Notice of violation from insp on 800814-15 Noncompliance noted physical inventories not being performed as required.

 * Region 3, Chicego, Office of the Director 80/09/02, 1p

DOCKET 70-1397 ST MARY'S HOSP RICHHOND, VA

8009260317 Forwards IE Circular 80-19, "Noncompliance W/License Requirements for Medical Licensees" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/26 is.

DOCKET 70-1401 VET ADMIN, HOSP DALLAB, TX

- 8009100362 Forwards IE Circular 80-19, "Noncomplience W/License Requirements for Medical Licensees" No written response required SEYFRIT-K V Region 4, Dellas, Office of the Director 80/08/26.
- DOCKET 70-1417 GREATER SOUTHEAST COMMUNITY HOSP WASHINGTON, D. C.
- 8009230142 Ack receipt of 800710 ltr informing NRC of steps taken to correct violations noted in IE Inep Repts 30-01334/80-01 & 70-1417/80-01 KINNEMAN.J D Region 1, Philadelphia, Fuel Fecility & Materials Safety Branch 80/07/30 ip
- ---B009230147 Responds to NRC 800708 telcon re violations noted in IE Ini Repts 30-01334/80-01 & 70-1417/80-01. Corrective actions: personnel will use syrings shields RBBINBON, CR Orester Southeest Community Hosp Weshington; D. C. 80/07/10 ip
- ---8009230150 Discusses IE Insp Repts 30-01334/80-01 & 70-1417/80-01 an BO0312 & forwards notice of violetion GROCKER.H W Region 1. Philadelphie, Fuel Fecility & Materials Bafety Branch. 80/03/31 2pp
- --8009230152 Notice of violation from insp on BOO312 Noncompliance nets: individuels prepared patient doses in mCi quantities w/o using syringe shielde * Region I. Philadelphia. Office of the Director. 80/03/3i Ip
- DOCKET 70-1492 RECYCLE FUELB PLANT, WEBTINGHOUSE ELECTRIC CORP.
- 8007170366 Comments on rulemeking 50-5 re mixed oxide fuel, OESMO & other recycle-related liceneing proceedings should continue. Positive affirmative action to approve licenses recommended KIRK, W F William F Kirk 80/08/28 4pp
- BO09100490 Comments on RM 50-3 public should be edvised of advantages & disadventages of implementing Pu recycle NRC should not have terminated efforts on GEBMO fuels
 BECHER.U. Affiliation Unknown. 80/09/03. ip
- B009160224 Requests GESMO refuel be completed. Info is needed for future decisione rereprocessing of spent nuclear fuel VILLEMY, G.R. Affiliation Unknown. B0/09/08 ip
- 8009i60420 Commente on rulemaking 50-5-GEBMO proceedings should be reopened to provide early procedural framework for eubsequent licensing.
 RICHARDS,R.B. General Electric Co. 80/09/08 2pp.
- 8009300514 Expresses concern re reopening of QESMO & other related licensing proceedings for reprocessing eites FEIQ.D Affiliation Unknown 80/09/13. 1p.
- BO07220226 Comments on rulemaking 50-5 GEBMO proceedings should be reopened Technical, economic & safety issues must be addressed in order for decisions to be made re use of mixed-oxide fuels
 WEITZDERG, A Affiliation Unknown 80/07/15. ip

- BOO9260641 Urges resumption of GESMO hearings
 BDLON, A E Affiliation Unknown 80/09/16 ip
- --9009260646 Opposes reopening of GESMO hearings SURRELL, A Affiliation Unknown 80/09/13 ip
- --8009280652 Urges reopening GEBMO & recycle-related proceedings & consideration of expanding scope to include recycle of LHR fuel in breeder reactors MCCORMACK.M House of Rep. 80/09/22 2pp
- 9009300525 Forwards comments in response to Commission 800807 order re terminated GESMO proceedings Reopening would be inimical to natl security & defense & at odds w/nonproliferation objectives. BIALIK,E. I New York, State of 80/09/23 7pp
- 8007300540 Comments on reopening of CESMO proceedings Addl use of nuclear generated electricity should be paced to praserve significant quantities of hydrocarbon reserves for use as raw matts in future chemical mfg BURRIS, L. American Institute of Chemical Engineers 80/09/23. 2pp
- B009300549 Request extension of time for comment on Commission 800807 order re reopening GEGMO proceeding MOLDEN.R B Allied General Nuclear Services 80/09/23 ip
- 800920054: Supports reopening of OESMO & other recycling license proceedings.
 RRICE, J. E. Affiliation Unknown 80/09/23 ip
- DOCKET 70-1470 VET ADMIN, HOSP LOS ANGELES, CA
- 6009260311 Forwards IE Circular 80-19, "Noncompliance W/License Requirements for Ksdical Licensees " No writtsn response required ENOELKEN,R H Region 5. San Francisco, Office of the Director 80/08/24 in
- COCKET 70-1729 FUEL REC & STOR STA , ALLIED GENERAL NUCLEAR BERVICES
- 8009230038 Responds to 800915 ltr directed to T Engelhardt. Every effort will be made to advise of development of facility use as away-from-reactor storage unit.

 MCQURREN.H. J Heering Branch i 80/09/19 2pp
- DOCKET 70-1738 PACIFIC GAR & ELECTRIC CO
- 8009020107 Requests renewal of Licenses SNM-1503 & SNM-1667, extending expiration date to 801231 Addl time necessary to complete facility licensing process SNACHELFORD.B. Pacific Oas & Electric Co 80/06/25 ip
- DOCKET 70-1739 TRI-STATE MOTOR TRANSIT CO
- 8009150545 Discusses IE Insp Rept 70-1739/80-02 conducted on 800616-18 & 20-25. No noncompliance noted Major areas inspected activities re physical protection against industrial sabotage & theft of SNM Rept withheld (ref 10CFR2, 790) NORDERHAUG, L. Region 5, Ban Francisco, Safaguards Branch, 80/08/20 2pp.
- DOCKET 70-1821 PLUT PROD FACIL. . ALLIED GENERAL NUCLEAR BERVICES CORP.
- BO09170366 Comments on rulemeking 50-5 rs mixed oxide fuel. GEBMD & other recycle-related licensing proceedings should continus Positive affirmative action to approve licenses recommended KIRK.M.F. William F. Kirk B0/08/28. App
- 8009100490 Comments on RM 50-5.public should be edvised of advantages & disadvantages of implementing Pu recycle NRC should not have terminated efforts on GESMO fuels
 BECHER, U. Affiliation Unknown. 80/09/03, ip.
- 8009160224 Requests GESMO re fuel be completed Info is needed for future decisions re reprocessing of agent nuclear fuel VILLEMY, G.R. Affiliation Unknown. 80/09/08, 1p.

- 8009300514 Expresses concerning reopening of GESMO & other related licensing proceedings for reprocessing sites FEIO.D Affiliation Unknown 80/09/13 ip
- 8009220296 Comments on rulemaking 50-5 GEEMO proceedings should be reopened Technical aconomic & safety issues must be addressed in order for decisions to be made re use of mixed-oxide fuels
 WEITZBERO, A Affiliation Unknown BO/09/15 1p
- 8009260641 Urges resumption of GESMO hearings BGLON, A E Affiliation Unknown 80/09/16 1p
- --8009260646 Opposes respening of GESMO hearings BURRELL.A Affiliation Unknown 80/09/13 1p
- --8009260652 Urges reapening OESMO & recycle-related proceedings & consideration of expanding scope to include recycle of LWR fuel in breeder reactors
 MCCORMACK.M House of Rep 80/09/22 2pp
- 8009300525 Forwards comments in response to Commission 800807 order rs terminated GESMO proceedings Reopening would be inimical to math security & defense & at odds w/nonproliferation objectives

 8IALIK,E I New York, State of 80/09/23 7pp
- 8009300540 Comments on reopening of OESMO proceedings Addl use of nuclear generated electricity should be paced to preserve significant quantities of hydrocarbon reserves for use as raw matts in future chemical mfg
 BURRIS.L American Institute of Chemical Engineers. 80/09/23 2pp.
- 8009300549 Request satension of time for comment on Commission 800807 order re-reopening GESMO proceeding HOLDEN,R.B Allied Operal Nuclear Services 80/09/23 ip
- B007300561 Supports reopening of OESMO & other recycling license proceedings
 PRICE, J E Affiliation Unknown 80/07/23 is
- DOCKET 70-2172 PITTSTON CO COAL GROUP
- BOO70B0450 IE losp Findings & Licensee Ack dtd BOO722 of License BMM-1617. Insp findings no noncompliance noted # Region 2, Atlanta, Office of the Director BO/07/22 ip
- DOCKET 70-2010 NUCLEAR FUEL SERVICES
- 8009020475 Notification of contract execution, Mod 1 to "West Valley Maste Burial & Storage Facilities" Contractor Univ of State of NY HAGEY, H. Research Contracts Branch. FIR B-6380 80/08/18 ip
- --8009020481 Mod 1.granting no cost extension for 1 yr.to "West Valley Haste Burial & Beorage Facilities" • New York Stats Univ of: (Albany). MORTON,K V Research Contracts Branch FIN B-6350 80/08/18 2pp
- DOCKET 70-2322 EDLOW INTERNATIONAL CO
- 8009120129 Forwards Ediow Intl routs w/revissd guidance NUREG-0361, reflecting letest amend to Interim rule for physical protection of irradiated reactor fuel in transit Requirements must be implemented by 800703 W/o encis MCCORKLE, O W Physical Security Development Branch 60/07/07 ip
- DOCKET 70-2375 PACIFIC GAS & ELECTRIC CO
- 8007020107 Requests renewal of Licenses 8NM-1503 & 8NM-1667, extending expiration date to 801231 Addl time necessary to complete facility licensing process SHAGKELFORD. B Pacifit Oas & Electric Co 80/06/25 ip
- DOCKET 70-2478 TRANSNUCLEAR, INC.
- 8009120136 Forwards Transnuclear route w/revised guidancs NUREO-0361, reflecting latest amend to interim rule for physical protection of irradiated reactor fuel in transit. Requirements must be implemented by 800703 W/o encis. MCCORKLE.O.W. Physical Security Dsvelopment Branch 80/07/07 ip

- 8009180512 Forwards safeguard plan for shipments of irradiated test reactor fuel Plan withheid (ref 10CFR2 790) MANOUSI, J. Transnuclear, Inc. 80/07/10 ip
- BOO9110240 Forwards Revision 1 of safeguard plan for shipments of irradiated test reactor fuel Hevision withheld (ref 100FR2,790)
 MANOUSI, J Transnuclear, Inc 8D/O8/01 ip

DOCKET 70-2479 TRANSMUCLEAR, INC

- 8009120136 Forwards Transnuclear route w/revised guidance NUREO-0561, reflecting latest amend to interim rule for physical protection of irradiated reactor fuel in transit Requirements must be implemented by 800703 W/o encls NCCORKLE,0 W Physical Security Development Branch 80/07/07 lp
- 8009110240 Forwards Revision I of safeguard plan for shipments of lreadiated test reactor fuel Revision withheld (ref 10CFR2 790) MANGUELJ Transpuciear, inc 80/08/01 19

DOCKET 70-2520 WEST VIRGINIA UNIV MEDICAL CENTER HORGANTOWN, WV

8009260316 Forwards IE Circular 80-19, "Nancompliance W/License Requirements for Medical Licenses" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/26 is

DOCKET 70-2554 VALLEY HOSP RIDGEHOOD

8009240712 Discusses IE Insp Rept 70-2554/80-01 conducted on 800620 No noncompliance noted License inactive KINNEMAN.J D Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/07/30 to

DOCKET 70-2560 OXLAHOMA OSTEOPATHIC HOSP TULGALOK

- 8009260392 Forwards IE Bulletin 79-19. "Packaging of Low Level Radwaste for Transport & Burial " Response required SEYRIT, K V Region 4, Dallas, Office of the Director. 79/08/10
- --8007260405 Responds to IE Bulletin, "Packaging of Low Level Radwaste for Transport & Burial " Waste allowed to decay to background levels & then disposed of in normal trash MORRIS.H D Oklahoma Osteopathic Hosp Tulsa.Ok 80/09/22 ip

DOCKET 70-2399 BERRIEN GENERAL HOSP BERRIEN CENTER/MI

8009160023 IE Insp Findings & Licenses Ack dtd 800808 of License SNM-1736 Insp findings no items of noncompliance or unsafe conditions noted REICHMOLD, W.P. Region 3. Chicago, Office of the Director. 80/08/08

DOCKET 70-2609 COMMONWEALTH EDISON CO

- 8009180261 Forwards request for amond to Licenses 8NM-1802 & SNM-1803 Mod to fuel assemblies to address potential fratting concern on water-rook in assemblies has resulted in numerous transfers of fuel between spent fuel storage pools PEOFLES.D L Commonwealth Edison Co. 80/07/11 2pp
- 3009110217 Forwards Revision (to security plan in response to NRC 800A07 ltr Revision withheld (ref 10CFR2 770) PEOFLES, D L Commonwealth Edison Co 80/07/28 ip

ICKET 70-2621 RIVERSIDE HOSP NEWPORT NEWS, VA

109260314 Forwards IE Circular 80-19, "Noncompliance H/License Requirements for Medical Licensees " No written response required (REILLY. J.P. Region 2, Atlanta, Office of the Director. 80/08/26.

- DOCKET 70-2623 MCGUIRE SPENT FUEL POOL, DUKE POWER CO
- 8009110275 Forwards Revision 3 to spant flux transportation security plan, which meets requirements of iOCFR73 37, as amended 800603 Requests approval of primary route for shipment of Oconee spent flust Revision withheld (ref 10CFR2 770) PARKER.W U Duke Power Co 80/07/02 ip
- BOO9150049 Advises that list of 60 addl heavily populated areas has been included in encl revised guidance document, NUREO-0561, per NRC amend rule for physical protection of irradiated reactor fuel in transit.effective 800703 H/o encl MCCORKLE.OW Physical Security Licensing Branch 80/07/07 is
- 8009150392 Responds to util 800417.28 & 0702 ltrs re physical protection of irradiated reactor fuel in transit Approvas Rayision 3 to spent fuel transportation plan MCCORKLE:0 W Physical Security Licensing Branch 80/07/11 lp
- 8009260527 Forwards comments re storage & in-transit security plan for ENM of low strategic significance Response requested within 30 days Comments withheld (ref 10CFR2 790) MCCCRKLE,0 W Physical Security Licensing Branch
- 8009190236 Forwards FR notice re rejocation of local PDR to Atkins Library. Univ of NC. Charlotte. NC FELTON, J H Division of Rules and Records 80/09/02. 2pp
- ---8009190242 Notice of rejocation of local FDR to Atkins Library, Univ of NG, Charlotte, NG FELIDN.J M Division of Rules and Records 80/09/02 200
- 8009160349 Forwards FR notice of relocation of LPDR KETCHEN, E O Hearing Branch 4 80/09/12, ip
- --8009160347 Forwards notice of relocation of LPDR.
 CHILK: S J Office of the Secretary of the Commission 80/09/05
- ---8009160352 Notice of relocation of LPDR to Atkins Library, Univ of NC. Charlotte: UNICC Station. NC FELTON, J M Division of Rules and Records 80/09/02 ip

DOCKET 70-2705 ST FRANCIS MEDICAL CENTER HOSP LYNWOOD, CA

8009300188 Responds to 1E Bulistin 80-22, "Autometion Industries Mofel 200-520-008 Bealed Source Connectors " Hosp does not utilize subjectionent MCORATH-E T 85 Francis Peorie, IL 80/09/15 ip.

DOCKET 70-2786 GENERAL ELECTRIC CO

- 8009:10763 Forwards Info requesting route approval for shipment of irradiated reactor fuel W/o encl ELDER,K General Electric Go 80/07/01 lp
- SOO9030454 Requests escort svc for irradiated fuel shipment expected to arrive in Los Angeles.CA on 800825 New requirements in 10CFR73 require surveillance of shipment vessel while docked in populated area
 KIRKLAND.H W. General Electric Co 80/07/17. 2pp
- 8009120152 Forwards approved spant fuel route & law enforcement contect info in response to 800701 ltr Approval not intended to provide relief from licensee assurance of highway safety Encl withheld (ref 105782,790)

 MCCORKLE, G W Physical Security Development Branch. 80/07/21 ip.
- 8009240680 Forwards comments, lesson plans & list of individuals who have completed escort training requirements per iOCFR73.37. MORTENSEN, W General Electric Co 80/07/21 19pp

DOCKET 70-2883 HANNA MINING GO

- BO09300606 Discusses IE insp of Licenses 22-05587-01, 22-015785-01, SNN-1383, BNN-1841, GNN-1864 on 800B14-15 & forwards notice of violation DAVIS, A B. Region 3, Chicago, Fuel Facility & Naterials Safety Branch, 80/09702. 2pp
- --8009300611 Notice of violation from insp on 800814-15 Noncompliance noted physical inventories not being performed as required * Region 3, Chicago, Office of the Director 80/09/02. 1p.

DOCKET 70-2885 COMMONNEALTH EDISON

8009180261 Forwards request for eacend to Licenses SNM-1802 & SNM-1833 Mod to fuel assemblies to address potential fratting concern on water-rods in assemblies has resulted in numerous transfers of fuel between spent fuel atorage pools PEOPLES, D. L. Commonwealth Edison Co. 80/07/11 2pp

GOO9110217 Forwards Revision 1 to security plan in response to NRC BCO609 ltr Revision withheld (ref 10CFR2 770).
PEOPLES D L Commonwealth Edison Co 80/07/28 1p

DOCKET 70-2892 AUXILIO MUTUO HOSP

BO09260277 Forwards IE Circular 80-19, "Noncompliance W/License Requirements for Medical Licenses" No written response required, O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/26

DOCKET 70-2909 VET ADMIN HOBP BAN DIEGO, CA

BOO9260309 Forwards IE Circular 80-19, "Noncompliance H/License Requirements for Medical Licensees "No written response required EMBELERY R. H. Region 5, San Francisco, Office of the Director, BOOMS 18.

DOCKET 70-2909 WEBTINGHOUSE ELECTRIC CORP POWER SYSTEMS

BOOT020453 Transcript of BOOB21 hearing in Montgomery, AL ra Wastinghouse application for SNM license Pp 1-190 Morning session. • Atomic Bafety and Licensing Board Panel BO/08/21 190pp

8009150411 Forwards comments from appropriate state agencies to DES for Westinghouse fuel fabrication plant in Frattville, AL. AMOS, M.R. Alabama, State of 80/07/01 10pp

8007040242 Motion for 20-day extension to file add1 valid contentions per ASLB 800821 special prehearing conference order, Certificate of 8vc encl. MLRED.D.L Affiliation Unknown 80/08/29 2pp

3009160330 Hemorandum & order granting withdrawal of R Aronov, CO Butler, MF Butler, RH Campball, S Draut, RE Ely, JA Johnson, LO Hoore, A Tolado & W Carroll BU0407 petitions Affirms denial of DL Allred petition for continuance FOREMAN, H. STEINDLER, M J. WOLF, J F Atomic Bafety and Licensing Board Panel 80/09/11 6pp

BOOT170126 Response stating no objection to DL Alired & Safe Energy Alliance of Central AL 800821 motions for extension until 800920 to file contentions
TURK.6 E Hearing Branch 1 BACHMANN.R.Q Rulsmeking & Enforcement Division, 80/09/15 2pp

--B009170129 Response in support of R Archov.CO Butler, MF Butler, RM Campbell, S Braut, RE Ely. JA Johnson, LO Moore, A Toledo & W Carroll B00925 withdrawal of original patitions Interests Tapresented by Safe Energy Alliance of Central AL TURK, S.E. Hearing Branch i. 80/09/15. 4pp

--8009170133 Suggested corrections to 800821 special prehearing conference transcript. Notice of appearance & Certificate of Byc encl.

a Hearing Branch 1 80/08/21 5pp.

DOCKET 70-2910 TENNESSEE VALLEY AUTHORITY

8009190759 Application for amend to Licenses SNM-1863 & ENM-1861, extending expiration dates to 810331 & 1231, respectively MICLS, L.M Tennessee Valley Authority. 80/07/23 ip.

8009150206 Forwards add1 comments re transportation portion of fuel storage shysical security plan dtd 800516 Requests that response be consolidated w/responses to NRC 800716 ltr & be submitted within 30 days of receipt of ltr.

MCCORKLE, O W Physical Security Licensing Branch 80/08/11 1p.

DOCKET 70-2913 TENNESSEE VALLEY AUTHORITY

8009190759 Application for amend to Licenses BNM-1863 & BNM-1861, extending expiration dates to 810331 & 1231, respectively MILLS,L M Tennessee Valley Authority 80/07/23 1p

DOCKET 70-2914 HANNA MINING CO

BO09300606 Discusses IE insp of Licenses 22-05587-01, 22-015755-01, BNM-1353, BNM-1841, SNM-1864 on BO0814-15 & forwards notice of violation DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Sefety Branch B0/09/02 2pp

---B009300611 Notice of violation from insp on B00814-15 Noncompliance noted physical inventorize not being performed as required * Region 3. Chicago, Office of the Director B0/09/02 ip.

DUCKET 70-2932 TEXAS UTILITIES CENERATING CO

BO09150213 Forwards application for ENN License to permit receipt, possession storage, insp & package for transport of universitated nuclear fuel assemblies, for psrind beginning BIO101 OARY, R J Texas Utilities Generating Co BO/07/10 ip

--8009150215 Application for 8NH license to permit, recsipt, possession, storage, insp & package for transport of unirradiated nuclear fuel assemblies, for period beginning 810101 GARY, R J Texas Utilities Generating Co 80/07/10. Bpp.

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0002 CHEM-NUCLEAR SYSTEMS. INC.

8009260074 Notifies of intent to change vendor name to ATCOR Engineerad Bys.Inc Official mod will appear in revised GA program projected for Oct 1980 HDLF.C.R. ATCOR 80/08/27 1p

DOCKET 71-0017 RHODE IBLAND ATOMIC ENERGY COMMISSION

8009230785 Forwards QA program approval for radinactive met1 peckage MACDONALD, C E Transportation Branch 80/08/29 1p

--8009230787 GA program approval for radioactive math package 0017.
Revision 0
MACDONALD.C E Transportation Branch 80/08/29 ip

DOCKET 71-0018 NUCLEAR ASSURANCE CORP

8009150542 Forwards requests for add1 info re GA manual MACDORALD, C.E. Transportation Branch. 80/09/04 2pp

DOCKET 71-0035 ROCKHELL INTERNATIONAL

GOO9230753 Forwards request for add1 info to complete review of GA program
MACDONALD, C E Transportation Branch. BO/08/29. 2pp

DOCKET 71-0082 KERR-MODEE NUCLEAR CORP

8009180334 Responds to 800703 ltr requesting add1 info re QA program Revisions to QA program will be submitted by 810131 SHELLEY, W. J. Kerr-McGee Nuclear Corp. 80/08/04, 1p

DOCKET 71-0108 MISSOURI, UNIV OF

8009250494 Forwards OA program approval for radioactive mati package MACDONALD,C E Transportstion Branch 80/09/10 ip

--8007250498 GA program approval for radioactive matt package.0108, Revision 0 MACDONALD.C E Transportation Branch 80/09/10 ip

DOCKET 71-0109 UNION CARBIDE CORP

- 8009110595 Forwards GA progrem approval for radioactive matl package MACDONALD.C E Transportation Branch 80/08/26 1p
- --8009110597 QA program epprovel for radioactive meti peckage 0109. Revision O MACDONALD.C E Transportation Branch 80/08/26 1p/

DOCKET 71-0112 NAVY, DEPT OF

- 8009150188 Notifies of transfer of Certificates of Compliance 4888 & 5862 to Naval Engineering & Environ Support Activity. Forwards GA program for approval HENDRIX.0 B) Navy.Dept of. Naval Facilities Engineering Commend 80/08/15 200
- --8009150189 QA program for radioisotops thermolectric generators * Navy.Dept of, Naval Facilities Engineering Command 80/07/31 7pp

DOCKET 71-0138 BATTELLE COLUMBUS LABORATORIES

8009230752 Forwards request for edd1 info to complete review of GA program
MACDONALD,C E Trensportation Branch 80/09/02 2pp.

DOCKET 71-0192 NUCLEAR PACKAGING, INC

- BO09250500 Forwards GA program approval for redicactive matl peckage MACDONALD, C. E. Transportetion Brench 80/09/10 ip
- --8009250502 GA progrem approval for radioactive metl package 0192. Revision O MACDOMALD.C E Transportation Branch 80/09/10 1p

DOCKET 71-0198 NUCLEAR FUEL SERVICES, INC

8007270237 Advises that modified QA progrem does not meet applicable criteria of App 8 to 10CFR50 Requests submittal within 60 days of revised application addressing 790605 request for edd info MACDONALD.C.E Trensportation Branch 80/09/f1, 1p

DOCKET 71-0244 NL INDUSTRIES, INC.

8009190692 Forwards request for add1 info to complete raview of GA program

MACDDNALD, C E Transportation Branch 80/09/02 App.

DOCKET 71-0370 AMEREHAM CORP.

8009150407 Forwards request for additinfo to complete review of GA program
MAGDUNALD.C E Transportation Branch 80/08/25 4pp

DOCKET 71-0382 INTERIOR, DEPT OF, GEOLOGICAL SURVEY

8009230758 Forwards request for addl info to complete review of QA program
MACDQNALD:C E Transportation Brench 80/08/29 3pp.

DOCKET 71-0385 HAVY, DEPT OF, NAVAL NUCLEAR POWER UNIT PORT HUENEME, CA

- BO07020522 Forwards Change 1 to GA progrem for packaging of radioactive matl for transport & transportation of radioactive matl under centain conditions

 JARDINE, E.F. Navy, Dept of, Forces Afloat, B0/08/12 2pp.
 - -8007020525 Change 1 to GA program for packeging of radioactive metl for transport & transportation of redioactive matl under certest conditions JARDINE, E. F. Navy, Dept of, Forces Afloat 80/06/30. 2pp.

DOCKET 71-0394 NUCLEAR SOURCES & SERVICES, INC

- 8007150405 Forwards request for add1 info to complete review of QA program MACDONALD, C. E. Transportagion Branch 80/09/26 11pp.
- DOCKET 71-0395 NAVY, DEPT. OF, NAVAL FACILITIES ENG COMMAND
- 9009150188 Natifies of trensfer of Certificates of Compliance 4888 to 5862 to Navel Engineering & Environ Support Activity Forwards (A program for approve) HENDRIX, O W Navy, Dept of, Navel Facilities Engineering Command 80/08/15, 2pp
- --8009150189 GA progrem for radioisotope thermolectric generators, # Navg, Dept of, Naval Fecilities Engineering Command. 80/07/3: 7pp

DOCKET 71-0396 ATCOR WASHINGTON, INC

- 8009290024 Informs of upcoming name change to ATCOR Engineered Bys.Inc. Revised GA program will be submitted by mid-Oct. WOLF.C R. ATCOR. 80/08/27, 1p
- 8007300207 Forwards OA progrem for epprovel to finelize plans for shipping excess fuel to Dek Ridge, TM. GA progrem was written using radiography guide for GA plans NELBON, P. R. HARRIB, D. R. Rensseleer Polytechnic Inst
- --8009300210 GA progrem for shipping peckages * Rensselaer Polytechnic Inst 80/09/04 2pp
- DOCKET 71-4888 MODEL SENTINEL-25A, B, C, C3, D, E, F, TELEDYNE ENGERY
- BO07080442 Advises that Command has no further need for Certificates of Complience 4888 & 5862 which should be registered under present user. Navel Energy & Environ Support Activity Approval of encl GA program requested HENDRIX.O.W Nevy, Dept of, Navel Facilities Engineering Command. 80/08/15 2pp
- --8007080445 GA program for radioisotope thermoelectric generators. * Nevy, Dept of 80/07/31. 7pp

DOCKET 71-4986 MODEL RA-2, EXXON NUCLEAR CO , INC

- 8009240127 Forwards Revision B to Certificate of Compliance 4986 for Model: RA-1,RA-2,RA-3 & RA-J. MACDONALD,C E. Transportation Brench 80/09/02. 2pp
- --8009240132 Certificate of Compliance 4986, Revision 8, for Models RA-1, RA-2, RA-3 & RA-J.
 MACDONALD.C E. Transportation Branch 80/09/02 App
- 8009240739 Advises of partial refund of amend fee for review of epplication for revision to Certificate of Compliance 4984. Expenditures were calculated for NRC review effort from 800402 submittel dete until 800722 withdrawal. HILLER: W O License Fee Manegament Brench. 80/09/08 1g.

DOCKET 71-5088 MODEL. D34710-1, U 8 NUCLEAR, INC

- 8009150396 Requests remember of registration as user of Model D34710-10 REMLEY, M E Rockwell International Corp., Energy Systems Div 80/08/11 ip
- 8009190594 Application for renewal of Certificate of Compliance 5089 for Model D24710-1 shipping conteiner. Atomics Intl is primary user Univ should be listed as secondery user BRUGGER.R M. Missouri Univ. of, Columbia, 80/08/29. 2pp.
- DOCKET 71-5442 MODEL LA-36, BABCOCK & WILCOX CO.
- 8009i30ob3 Informs renewal of Certificate of Compliance 5442 for Model LA-36 shipping conteiner not desired.
 AUSTIN, M. A. Babcock & Wilcox Co., Nuclear Material Div. 90/08/26 ip.

- DOCKET 71-5450 MODEL RCC-1.-2.-3. WESTINGHOUSE ELECTRIC CORP
- BOOTO20114 Notification of registration as user of Model RCC in response to util request MACDCNALD,C E Transportation Branch 80/07/24 is
- DOCKET 71-5740 MODEL ORNE TRU OF SHIPPING CONTAINER, ENERGY, DEPT OF
- 8009270263 Request registration es user of ORNL TRU Cf shipping container BPIECEL. Commerce, Dept of, National Bureau of Standards 80/08/18 ip
- BO09250321 Denies request for registration es user of Model ORNL TRU Cf (DDE-DR), Rev 2 packaging Pactage not approved by NRC, but currently under review RAGDONALD, C E Transportation Branch 80/09/11 ip
- DOCKET 71-5862 MODEL, BENTINEL-100F, TELEDYNE ENERGY BYSTEMS
- 9009080442 Advises that Commend has no further need for Certificates of Compliance 4889 & 5862 which should be registered under present user. Neval Energy & Environ Support Activity, Approval of ancl GA program requested HENDRIX,O W Nevy, Dept of, Nevel Facilities Engineering Command 80/08/15 2ap
- --8007080445 QA program for radioisotope thermoelectric generators.

 Navy,Dept of 80/07/31. 7pp
- DOCKET 71-5926 MODEL 100. GENERAL ELECTRIC CD
- BO09240703 Application for amend to Certificate of Complience 5926 re GE Model 100 permitting shipment of byproduct & SNM in solid nonfissile irradiated metal hardware Fee encl GUNNINGHAM.O.E General Electric Co 80/08/26 ip
- 8009260100 Advises of forthcoming amend fee refund re Revision 5 to Certificate of Compliance 5926 MILLER, W. O License Fee Management Branch 80/09/11 1p
- DOCKET 71-5942 MODEL GE-700, GENERAL ELECTRIC CO.
- 8009050379 Advises that personnel-hour expenditures required for review of 800318 application for amend to Certificate of Compliance 3942 have been reviewed Actual fee is less than fee paid for request review & approval.
- DOCKET 71-5957 MODEL, BMI-1, ENERGY, DEPT OF
- BO09110570 Notification of registration as user of Model BHI-1 in reaponse to util request. MACDONALD,C E Trensportation Branch 80/07/28 ip.
- DOCKET 71-5971 MODEL, GE-200, GENERAL ELECTRIC CO
- 8009260104 Application for amend to Certificate of Compliance 5971 for QE Model 200, permitting shipment of byproduct & SNM in fuel rof.piate & fuel assembly form & solid nonfissile matl contained in metal cladding. Fee encl CUNNINGHAM. Q. E. General Electric Co. 80/08/26. 1p
- DOCKET 71-3980 MODEL: QE-600, GENERAL ELECTRIC CO.
- 8009150001 Application for revision of Certificate of Compliance 5980 to permit shipment of 500/300/300 g fissile loading as Fissile Class 2 CUNINGHAN, G. E. General Electric Co., Nuclear Energy Products Div 80/03/21 200.
- B007030454 Requests escort syc for irradiated fuel shipment expected to arrive in Los Angeles, CA on 800825. New requirements in 10CFR73 require surveillance of shipment vessel while docked in populated erea KIRKLAND. H W General Electric Co. 80/07/17 2pp

- 8009300122 Forwards Revision 5 to Certificate of Compliance 5980 for Model GE-600 MACDENALD, C.E. Transportation Branch 80/09/17 2pp
- --8009300125 Certificate of Compliance 5980 Revision 5 for Model 0E-600 MACDONALD C E Transportation Branch 80/09/17 3pp
- DOCKET 71-5998 MODEL 09-400, QENERAL ELECTRIC CO
- B009260051 Application for among to Certificate of Compliance 5998 for OE Model 400, permitting shipment of byproduct math masting special form requirements or solid monfissile math in metal ciadding Fee ancl CUNNIGNHAM.O E General Electric Co B0/08/26 1p
- DOCKET 71-4058 MODEL 89-1, NUCLEAR ENGINEERING CO
- B00926016B Application for amend to Certificate of Compliance 605B for Model B-3, deleting ennual O ring replacement requirement Fee encl
 BAER, T S Nuclear Engineering Co , Inc , (tubs of Teledyne, Inc.)
 80/05/30 ip
- --8007260173 Forwards NRC 800627 ltr requesting fee for 800530 request for emend to Cartificate of Compliance 6058 Fee remains outstanding WEISS,D License Fee Management Branch 80/08/05 ip
- --8009260176 Notifies that 800530 request for emend to Certificate of Compliance 6058 has been classified as minor & requires addifee MEISS, J. D. License Fee Management Brench 80/06/27 ip
- DOCKET 71-6144 HODEL 6144. NUCLEAR ENGINEERING CO
- 8007300602 Requests registration as user of Model CNSI-6144 JONES.R A R J Reynolds Tobacco Co 80/08/18 ip
- DOCKET 71-6357 MODEL NNFD-10. BABCOCK & WILCOX
- 8009190544 Notification of registration as user of Model NNFD-10 MACDONALD, C E Transportation Branch 80/09/10. ip
- DOCKET 71-4400 MODEL SUPER TIGER, PERTINGHOUSE ELECTRIC CORP
- 8009190019 Forwards info requested re 800710 eppiication to emend Certificate of Compliance 6400 Info provides discussion of safety significance of deviations from Protective Pactaging. Inc. Drawing No. 32106-1 AUSTIN.M A Sebcock & Wilcox Co., Nuclear Naterial Div. 80/08/15
- 8009300227 Requests remaining as registered user of Model Super Tiger, Certificate of Compliance 6400 Valiectics Nuclear Gtr does not own any containers, but rents from Nuclear Engineering Co.

 CUNNINGHAM.O. E. General Electric Co. 80/08/18 1p.
- B009180153 Requests add1 documentation re 800815 application for amend to Model Super Tiger MACDGNALD, C E Transportation Branch. 80/08/29 1g
- DOCKET 71-6458 MODEL: BU-5, GENERAL ELECTRIC CO
- 8009190552 Notification of registration as user of Model 8U-5 MACDONALD, E.C. Transportation Branch. 80/09/10. ip
- DOCKET 71-4581 MODEL \$1032-1 & 1A, EXXON NUCLEAR CO , INC.
- 8009260105 Forwards Page 2-14 to 800806 amended consolidated license renewal application for Models 5:032-1 & la Page inadvertently unitted from original. HANBEN.L. E Exxon Nuclear Co . Inc. (subs of Exxon Corp) 80/08/15 ip
- --8009260117 Page 2-14 to 800806 consolidated license renewal application for Models 51032-1 & ia.

 * Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) XN-52-02 R1 80/08/15 ip

DOCKETED ITEMS

DOCKET 71-6717 MODEL 6717 8

- 8009170136 Requests continuation of registration as user of Certificate of Compliance 6717
 DALLINGER, J. F. Oemoral Dynamics Corp., Electric Boat Div. 80/08/12
 Ip
- 8009180529 Application by NC Dept of Transportation, Div of Highways, Matls & Tests Unit for use of transportation packages identified as Certificates of Compliance 6717 & 9036 WAGNER:FT North Carolina, State of 80/08/12 ip
- DOCKET 71-9001 MODEL IF-300, GENERAL ELECTRIC CO
- B009230756 Forwards Revision 10 to Certificate of Compliance 9001 for Model IF-300
 MACDDMALD, C.E. Transportation Stanch 80/08/27 2pp
- --8009230761 Certificate of Compliance 9001, Revision 10, for Model IF-300 NACDUNALD, C E Transportation Branch 80/08/27 App
- DOCKET 71-9009 MODEL FL 10-1, GENERAL ELECTRIC CD
- 8009110730 Forwards Ravision 9 to Certificate of Compliance 9009 for Model FL 10-1 MACDONALD.C E Transportation Branch 80/09/03, 2pp
- --8009110759 Certificate of Compliance 9009, Revision 9, for Model FL 10-1 MACDONALD.C E Transportation Branch 80/09/03 8pp
- DOCKET 71-9018 MODEL BU-6, GENERAL ELECTRIC CO
- 8009250463 Raquests changes of user registration for Models CNSI-14-195-H.CNSI-AL-33-90 & CNSI-6-80-2 New contact individual is CP Yundt YUNDI.C.P Partland General Electric Co 80/08/07 Ip
- DOCKET 71-9019 MODEL BU-7, GENERAL ELECTRIC CO
- 8009050414 Forwards Application Amend T-16 for revision of Certificate of Compliance 9019 W/o encl KAPLANA AL General Electric Co , Nuclear Energy Products Div 80/08/21 ip
- --8009050417 Forwards Application Amend T-16 for revision of Cartificate of Compliance 9019 for GE Bu-7 transport package, changing allowed H/U ratio in package contants from 0 45 to 1.577 KAPLAN, A L. General Electric Co., Nuclear Energy Products Div 80/07/25 19
- --8009030419 Application for amend of Certificate of Compliance 9019, consolidating prior applications for revision & test results & changing H/U ratio in package contents from 0 45 to 1 577 + General Electric Co , Nuclear Energy Products Div 80/07/25, 152po
- DOCKET 71-9022 HODEL. CE-250-2, COMBUSTION ENDINEERING CO , INC
- 3009260184 Application for amend to Certificate of Compliance 9022, to permit closure of Model CE-250-2 by either licensed or proposed alternate closure was Fee encil HANSEN.LE Exxon Corp 80/08/14 3pp
- DOCKET 71-9027 MODEL 741, TECHNICAL OPERATIONS, INC
- 8009020125 Notification of registration as user of Models 650,680 & 741 in response to US Navy request MACDONALD, C E. Transportation Stanch. 80/07/24 ip.
- DOCKET 71-9032 MODEL 650, TECHNICAL OPERATIONS, INC.
- 6009020125 Notification of registration as user of Models 650.680 & 741 in response to UB Navy request MACDONALD, C E Transportation Branch 80/07/24 ip

- DOCKET 71-9033 MODEL 660 & 660E, TECHNICAL OPERATIONS, INC
- BO09090093 Requests registration as user of Tech/Ops Model &&O BANSON R Contra Costa Industrial X-Ray Co 80/07/23 ip.
- BOCKET 71-9034 MODEL TRIGA-1, GENERAL ATOMIC CO ,
- B009300135 Forwards Revision 3 to Certificate of Compliance 9034 for Model TRIOA-1 MACDONALD, C E Transportation Branch 80/09/17 1p
- --8009300137 Certificate of Compliance 9034 Revision 03 for Model TRIOA-1.

 MACDONALD C E Transportation Branch 80/09/17 2pp.
- DOCKET 71-9035 MODEL: 680, TECHNICAL OPERATIONS, INC
- 8009020125 Notification of registration at user of Modals 450,480 & 741 in response to US Navy request MACDONALD, C.E. Transportation Branch 80/07/24 lp.
- DOCKET 71-9036 MODEL. C-1. BOURCE PRODUCTION EQUIPMENT CO.
- 8007180523 Application by NC Dapt of Transportation. Div of Highways, Matls & Tests Unit for use of transportation packages identified as Cartificates of Compliance 6717 & 9036 HAGNER, T. North Carolina, State of 80/08/12
- DOCKET 71-9037 MODEL TRIGA-2, GENERAL ATOMIC CO.
- B009300127 Forwards Revision 3 to Certificate of Compliance 9037 for Model TRIOA-2, MACDONALD, C E Transportation Branch B0/07/17 ip
- --B009GD01GO Certificate of Compliance 9037, Revision 3.for Model TRIGA-2 HACDDNALD, C E Transportation Branch 80/09/17 2pp
- DOCKET 71-9039 MODEL 715, TECHNICAL OPERATIONS, INC.
- 8009020313 Forwards info to support renewel of Cartificate of Compliance 9039, per 800811 teleon MUNRO, J Tach/Ops (Tachnical Operations, Inc.). 80/08/12, 4pp
- 8009080454 Forwards Revision 5 to Certificate of Compliance 9039 for Model 713. MACBONALD, C E Transportation Branch 80/08/19 4pp.
- --8007080457 Certificate of Compliance 9039, Revision 5, for Model 715. MACDONALD.C E Transportation Branch 80/08/19 2pp.
- 8009190548 Notification of registration as usar of Model 715, MACDONALD.C.E Transportation Branch 80/09/10. ip
- DOCKET 71-9044 MODEL, DE-1600, GENERAL ELECTRIC CO
- B009150390 Requests registration as user of Model OE 1600 shielded container HARVEY,J L. Bouth West Nuclear Co. 80/08/13 ip.
- B009260391 Application for amend to Certificate of Compliance 9044 for OE Model 1600, permitting shipment of Pu in excess of 20 Ci in metal alloy or reactor byproduct & BNM as solid metal or oxide fee encl.

 CUNNINGHAM.O E General Electric Co 80/08/26 1p.
- DOCKET 71-9049 MODEL GE-500. GENERAL ELECTRIC CO
- BOO9260581 Application for amend to Certificate of Compliance 9049 for GE Model 500, permitting shipment of byproduct meth meeting special form requirements & solid nonfissile irradiated metal hardware contained in metal cladding. Fee encl CUNNINGHAM, O. E General Electric Co 80/08/26 ip

8009290144 Advises of partial refund of amend fee for NRC review of 800208 & 21 applications for Revision 2 to Certificate of Cospliance 9049
**ILLER.W O License Fee Management Branch 80/09/08 1p

DOCKET 71-9074 MODEL AP-100, ANEFCO, INC.

9009150591 Requests registration as user of Model AP-100 to ship radioactive matls HILLS, L.M Tennessee Valley Authority 80/08/11 tp

DOCKET 71-9080 MODEL HN-600, HITTMAN NUCLEAR & DEVELOPMENT CORP

8009220172 Opposes Revision 4 incorporating Certificates of Compliance 9113 & 9080 into single package Differences between Model HM-600 & CNB 7-100 are sufficient to warrant issuance of apparate certificates CORBETT. J B. Chem-Nuclear Systems. Inc. 80/08/14 1p

DOCKET 71-9081 MODEL: CN81-1600, CHEM-NUCLEAR SYSTEMS, INC

90091905&1 Notification of registration as User of Model CNS-1600 MACDONALD-C, E. Transportation Branch 80/09/10 1p.

DOCKET 71-9094 MODEL: CHBI-14-195-H, CHEM-NUCLEAR BYSTEMB, INC.

8009020121 Notification of registration as user of Model CNBI-14-195-H in response to util request MACDONALD, C.E. Transportation Branch. 80/07/24 1p

BOO9250463 Requests changes of user registration for Models CNBI-14-195-H.CNBI-AL-33-90 & CNBI-6-80-2 New contact individual is CP Yundt YUNDI.C.F Portland General Electric Co. 80/08/07, ip

DOCKET 71-909A MODEL: CN81-21-300, CHEM-NUCLEAR BYSTEMS, INC.

9009110756 Requests registration as user of Model CNSI 21-300 CRANE,P.A Pacific Ges & Electric Co 80/08/12 ip

8009090624 Forwards Revision 4 to Certificate of Compliance 9096 for Model CNS 21-300 MACDONALDIC E. Transportation Branch 80/08/28 3pp

--BOGF090526 Revision 4 to Certificate of Compliance 9096.for Model CNB 21-300 MACDONALD.G.E Transportation Branch 80/08/28 2pp

DOCKET 71-9097 MODEL: CNSI-14-195L, CHEM-NUCLEAR SYSTEMS, INC.

8009260039 Requests hearing re NRC 800807 denial of application for design approval for Model CNBI 14-195L REYNOTOLE Chem-Nuclear Systems, Inc. 80/08/26 1p.

JOCKET 71-9108 HODEL AL-33-90, ATCOR, INC

B009020116 Notification of registration as user of Model Al-33-90 in response to util request
MACDONALD, C E Transportation Branch, 80/07/24, ip.

8009020119 Notification of registration as user of Model Al-33-90 in response to util request MACDONALD,C E Transportation Branch 80/07/24 1s

8009170555 Notification of registration as user of Model AL-33-90 MACDONALD, C E Transportation Branch 80/07/10 1p

DOCKET 71-9111 MODEL CN6-80A, CHEM-NUCLEAR, INC

8007230463 Requests changes of user registration for Models CNSI-14-173-H. CNSI-AL-33-90 & CNSI-6-80-2 New contact individual is CP Yundt YUNDT.C P Portland General Electric Co 80/08/07 1p

DOCKET 71-9113 HODEL 7-100, CHEM-NUCLEAR SYSTEMS, INC

8009150399 Requests registration as user of Model 7-100 ABEL, J S Commonwealth Edison Co 80/08/11 1p

8009220172 Opposes Revision 4 incorporating Certificates of Compliance 9113 & 7080 into single package Differences between Model NN-600 & CNB 7-100 are sufficient to warrant issuance of separate certificates

CORBETT, J S Chem-Nuclear Systems, Inc. 80/08/14 1p

DOCKET 71-9114 HODEL CN4-808, NUCLEAR PACKAGING, INC

8009050458 Requests hearing re denial of application for approval of Model CN6-BOB shipping package BIMCHUK, J D Nuclear Packaging. Inc 80/08/20 1p

8009240211 Confirms telcon re NRC 800731 denial of application re design approval for Model CN6-808 & vendor 800820 request for formal adjudicatory hearing informel discussion w/NRC required prior to initiation of formal hearing JAMEL. E Regulations Division 80/09/09. 1p

DOCKET 71-9136 HODEL OF 9136, OEMERAL ELECTRIC CO

8007230766 Notification of registration as user of Models QE-9136-01, QE-9136-02 & QE-9136-03 in response to 800331 request MACDONALD, C E Transportation Branch 80/08/27 2pp

DOCKET 71-9508 MODEL: DOT SPEC &M. ENERGY, DEPT. OF

8009050205 Forwards Certificate of Compliance 9508, engineering evaluation & safety analysis for mod to allowed contents of 6M spec packaging. ROSE,D M Energy, Dept of, 80/08/05 2pp

--8009030207 Certificate of Compliance 7508 for Package 6M ROEDER, J R Energy, Dapt. of 79/06/01 2pp

---8007030214 "Uss of DOT Spec &M Container for Shipping Polystyrene-Pu Compacts " SHITH.D R . DROWN, W K Los Alamos Scientific Laboratory 80/08/05 Spp

DOCKET 71-9853 MODEL DRNL - BNL - NBS UN FUEL CONTAINER, ENERGY,

8007050453 Requests registration as user of Model ORNL-BNL-NBS O'ROURMERS A Los Alamos Scientific Laboratory. 80/08/13, 1p

· ·			

NONDOCKETED ITEMS

8007030074 Forwards further Commission guidance for power reactor CLs for FR publication on 800620
CHILK, 8 J Office of the Secretary of the Commission 80/06/17 --8009030079 "Further Commission Guidance for Power Reactor DLs. Statement of Policy " CHilk.8 J Office of the Secretary of the Commission 80/06/16

COMMISSION MEETING RECORDS

8009030093 Forwards notice of Commission meetings during wk of 800623 CHILK,B J Office of the Secretary of the Commission 80/06/18

--8009030098 Notice of Commission meetings during wk of 800023 to discuss proposed interim hydrogen requirements for small containments & financial statue of utils HAGEE.W Office of the Secretary of the Commission 80/06/17

8007030102 Forwards notice of Screening Committee for Lawyer Vacancies on Licensing Board Panel 800618 meeting in Washington,DC for FR publication on 800618 HDYLE,J C Office of the Becretary of the Commission 80/06/17

-8009030105 Notice of Boreening Committee for Lawyer Vacancies on Liceneing Board Panel 800618 meeting in Washington.DC HOYLE.J C Office of the Becretary of the Commission 80/05/17

8009050481 Transcript of 770608 discussion of NRC safety reviews of foreign facilities in Washington, DC Pp 1-25

• Commission 77/06/08 27pp

B009090641 Transcript of 770603 discussion of proposed Commission lagislative program in Washington, DC Pp 1-51 = Commission 77/06/03 53pp

8009090649 Transcript of 770322 discussion on research budget in Hashington, DC Pp 1-50 • Commission 77/03/22 52pp

8007100001 Transcript of 770503 briefing on Commission testimony on Benate Biil 877 in Washington, DC Pp i-13 # Commission 77/05/03 14pp

B009100020 Transcript of 771229 discussion of hearing board for clearance rule proceeding in Washington, DC Pp 1-24 Portions withheld as noted in encl Commission 77/12/29 29pp

8009100089 Commission determination releasing encl transcript of 770303 briefing on possible classified & litigative aspects of GERMD in Hashington.DC Pp 1-23 Page 23 Lines 7-9 remain Commission 77/05/03 24pp

8009100115 Commission determination releasing encl transcript of 770428 discussion of policy decisions/NRC Authorization Bill in Hashington DC Pp 1-72 Page 3 Line 11 through Page 4 Line 17 remain withheld.

Commission 77/04/25 73pp

8009160443 Transcript of 800904 discussion of SECY-80-399 re proposed interim amends to 100FR50 rm hydrogen control & certain degraded core considerations in Washington, DC Pp 1-86 Yiewgraphs encl # Commission 80/09/04. 95pp

BOO9160489 Transcript of B00908 discussion of Commission program to review DL applications in Washington.DC Pp 1-63 Related documentation & correspondence enci * Commission B0/09/09 154pp

8009180133 Transcript of 800903 Affirmation Session 80-38 in Washington.DC Pp 1-3 * Commission 80/09/03 6pp

8009180269 Transcript of 800904 public meeting in Washington, DC re discussion & vote on enforcement policy Pp 1-91 * Commission 80/09/04 93pp

--8009180277 SECY-80-139A Recommends adoption of proposed policy of enforcement action as interim guidance Draft FR notice and STELLD, V Office of Inspection & Enforcement, Office of the Director 80/08/27 Sopp

--B009180284 Bummary of Commission B00319 meeting in Washington.DC re BECY-B0-139 dealing w/MRC enforcement program Revised policy discussed but no final conclusione reached CHILK.B J Office of the Secretary of the Commission 80/03/28

---B009180291 Commente on SECY-80-139 re enforcement policy NRC divs must submit alternatives to Executive Director of Operations AKEARNE, J F Commission 80/03/24 App

--8009180298 Commente on proposed enforcement policy Policy paper is good first step but of little use if licensee commitments & NAC state are not in enforceable form BRADFORD.P A Commission 80/04/09 18pp

8009190771 Transcript of 800903 public briefing by EPA on draft general stde (occupational exposures.mill tailings) in Washington, DC Pp i-101 Commission 80/09/03, 10ipp

--8009190775 Requests comments on draft disposal stde for U mill tailings remedial action program.Draft FR notice & EIS enci ROSENDAUM,D M Environmental Protection Agency 80/08/11 90pp

GOO9230276 Transcript of 800704 Affirmation Session 80-39 to discuss fass for withdrawl of applications for CPe & CLs in Washington, BC Pp 1-2 Draft proposed rules and Commission 80/09/04, 20pp

--80072502B0 EECY-80-364 DOVACOUSED DECT-80-364
Recommends recovery of liceneing review fees for applicatione denied, withdrawn, suspended or poetponed Draft FR notice enci
BONDOHUE, D.J. Office of Administration 80/08/04 lipp

BO0927002: Transcript of B00916 public meeting in Washington,DC re discussion & vote on Commission program to review DL applications,AM session Pp 1-62 AHEARNE,J A Commission B0/09/16 65pp

--8009290032 SECY-80-414 unvariouse BECY-BU-414
Requests approval of conceptual draft plan re systematic safety evaluation of all currently operating nuclear power reactors H/draft 90-day status rept.considerations re identification of regulations & draft public announcement DENTGN.H R Office of Nuclear Reactor Regulation. Director, 80/09/09 Sipp

ACRE ADVISORY COMMITTEE ON REACTOR BAFEQUARDS

- B00903064B Forwards notice of ACRB B00904-06 meetings in Machington, DC for publication in FR CHILK-S J Diffice of the Secretary of the Commission. 80/08/19
- --8009030550 Notice of ACRS 800904-06 meetings in Washington, DC. HOYLE, J C Office of the Becretary of the Commission. 80/08/19.
- 8009050388 Transcript of ACRS Subcommittee on Class 9 Accidente 800828 hearing in Washington DC Pp 1-251 # ACRS Advisory Committee on Reactor Bafeguards 80/08/28
- 8007080250 Transcript of ACRS Reactor Fuel Subcommittee 800703 meeting in Hashington DC Pp 1-213
 ACRS Advisory Committee on Reactor Bafeguards 80/09/03 214pp
- 8009080255 Transcript of AGRS Subcommittee on Safety Philosophy. Technology & Criteria 800903 meeting in Hashington BC Pp. 1-275.

 #_AGRS Advisory Committee on Reactor Safeguards 80/09/03 276pp.
- 8009080385 Transcript of 245th ACRS meeting on 800904 in Washington.DC, Pp 1-308, Supporting documentation encl. # ACRS Advisory Committee on Reactor Safeguards. 90/09/04.
- 8009090620 Transcript of ACRS Bubcommittee on Fuel 800821 meeting in ID Falls, ID. Pp. 1-220, W/supporting documentation # ACRS Advisory Committee on Reactor Safeguards, 80/08/21
- 8009100157 Bunmary of ACRB LER Subcommittee 800422 meeting in Nashington DC re-status of new NRC Ofc for Analysis & Evaluation of Operational Data. ACRB - Advisory Committee on Reactor Safeguards, 80/07/11, 11pp
- 8009100160 Summary of ACRS Subcommittee on Natural Heat Removal 800926 meeting in Mathington.DC re various modes of natural circulation heat removal in PMRs.

 ACRS Advisory Committee on Reactor Safeguards. 80/05/30 9pp
- BOOPIODIBO Summary of ACRS Subcommittee SO0424 meeting re natural circulation decay heat removal in reactor sys under various conditione.

 * ACRS Advisory Committee on Reactor Bafeguards. 80/06/25. 10pp.
- 8009100163 Summary of ACRS Subcommittee on Reliability & Probabilistic Assessment 800430 meeting in Washington DC re budget, research on flood program & development of quantitative safety criteria.

 ACRS Advisory Committee on Reactor Safeguards. 80/07/09. 7pp.
- 8009100195 Summary of ACRS Subcommittee on Regulatory Activities 800504 meeting in Machington DC re proposed revisions to 10CFR55, 10CFR50 & proposed Reg Quide 1. 23.Revision 1. # ACRS Advisory Committee on Resctor Safeguards. 80/05/27. 7pp.
- 8009100572 Forwards corrected pages & supplemental info submitted as entl to 800410 ltr re proposed reg guide. "Lightning Protection for Nuclear Power Plants."
 JCHNESNAI.8 Affiliation Unknown. 80/04/18 16pp.
- B009100917 Forwards 800807 FR notice of ACRS Subcommittee on Consideration of Class 9 Accidents 800828 meeting CHILK, 8, J. Office of the Secretary of the Commission, 80/08/07.
- ---B009100920 Notice of ACRS Subcommittee on Consideration of Class 9
 Accidents 800828 meeting re hydrogen generation & control
 methods widegraded core confitions
 HOYLE, J. C. Diffice of the Secretary of the Commission, 80/08/07.
- 8009110293 Transcript of 800906 ACRS Thedani presentation in re ATMS Washington: DC. Pp 1-29.

 **ACRS Advisory Committee on Reactor Safeguarde. 80/09/06. 3ipp
- B009110597 Summary of ACRS Subcommittee on Safeguards & Security 800526 meeting in Washington DC re review of FYB2 budget.

 * ACRS Advisory Committee on Reactor Safeguards. 80/07/23, 8pp.

- 8009110864 Transcript of 245th meeting of ACRS on 800905 in Washington, DC Pp 1-109. # Commission 80/09/05. 120pp
- 8009150245 Provides addl comments on hydrogen control & improvement of containment capability. Recommendations in ACRB 791213 ltr re-reliability assessments & design features for core damage & core selt accidents should be adopted & given priority. PLESSET,M 8, ACRS Advisory Committee on Reactor Bafeguards. 80/09/08, 2pp
- BO09150249 Discussee 245th ACRB meeting re final version of NUREO-0430, "Cladding Swelling & Rupture for LOCA Analysic " laplementation should be held in abeyance until NRC revises code requirements PLESSET, H 8 ACRB Advisory Committee on Reactor Bafeguards. 80/09/09. 2pp.
- 8009150A40 Notice of ACRB Bubcommittee on Safety Philosophy & Criteria 800903 meeting in Mashington.DC HOYLErJ, C. Office of the Secretary of the Commission, 90/08/13.
- 8009150443 Notice of ACRS Subcommittee on Reactor Fuel 800821 meeting in Idaho Falle.ID. CHILK, S. J. Office of the Secretary of the Commission. 80/07/31.
- BOO9160074 Notice of various ACRB subcommittee Aug-Nov 1980 meetings in Mashington.DC & Idaho Falle.ID & ACRS full committee BOO904-06:1009-11 & 1106-08 meetings.
 HOYLE.J C Office of the Secretary of the Commission. BO/08/19.
- B007160077 Notice of ACRS Subcommittee on Reactor Fuel 800703 meeting in Heetington DC to review NUMEG-0630, "Cladding Swelling & Rupture Models for LOCA Analysis."
 HOYLE, J. C. Office of the Secretary of the Commission, 80/08/13
- 8009160503 Notice of room change for ACRS Subcommittee on Befety Philosophy & Criteria 800806 meeting. Discussion of proposed echecules for developing quantitative safety goale added to aganda. CHILK, S. J. Office of the Secretary of the Commission, 80/07/31.
- 8009190261 Forwards FR notice of change in status of ACRS meetings. Requeste publication on 800626 CHILK.S.J Office of the Secretary of the Commission. 80/06/23.
- --8009190266 Notice of change in statue of ACRS meetings Determined that closed seesings will not be necessary
 HOYLE.J C. Office of the Secretary of the Commission 80/06/23
- 8009190416 Discusses response to ACRB 800716 ltr re reactor coolent pump trip & HPI termination criteria Agrees w/comments by ACCRB w/exception of two items ZECH-0.0 Technical Support Branch. 80/09/03. 2pp.
- BOO919077B App. summary & table of contents to minutes of 238th ACRS meeting on BOO207-09. * ACRS Advisory Committee on Reactor Safeguards. BO/02/09 1600pp.
- 8009230111 Comments on 800604 presentation re evaluation of seismic riek in states lying east of Rocky Mountains due to rarity of earthquakee in majority of area, Calculation of max expectable seismic acceleration would not be satisfactory. MAXWELL, J. C. Affiliation Unknown, 80/06/14 4pp.
- BO09230113 Discusses SIMMER code for advances reactor eafety research. Limitations result from assuming droplet field & associated assumptions re drop eits & heat transfer. Focus should be on physical process being modeled. CATTON, I. ACRS Advisory Committee on Reactor Bafeguards, 80/07/09. 1p.
- 8009240690 Comments on ACRS 800722 meeting re Class 9 accident safety analyses. Mental stress resulting from continued presence of substantially degraded core should be considered. Emphasis should be placed on prevention.

 SIEDEL. 8. Advanced Energy Systems. 80/07/22 3pp
- 8009260219 Comments on matters discussed at ACRS 800630 meeting re SIMMER effort to describe core disruptive accident in complex sus Principal priority & emphasis should be placed on prevention as compared Wimitigation. SIEOEL'S Advanced Energy Systems. 80/07/08. 3pp.

CONSCION NEC CONTISSIONERS

- SOCHOZOCO Provides status of OERHO proceedings in response to SOCIOO litr requesting that Commission re-examine 1977 decision to terminate proceedings w/completion of Intl Nuclear Fuel Cycle Evaluation (INFCE) W/o encl.
 HENORIE-J, H. Commission 80/08/08, 2pp
- --BOOFC2C204 Provides status of GERMO proceedings in response to BOO5C2 litr requesting that Commission re-examine 1977 decision to terminate processings w/completion of Intl Nuclear Fuel Cycle Evaluation (INFCE) W/o encl.
 HENDRIE, J.M. Commission. BO/08/08 2pp.
- --BOOTO20204 Provides status of GESHO proceedings in response to 800602 1tr requesting that Commission re-examine 1977 decision to terminate proceedings w/completion of Intl Nuclear Fuel Cycle Evaluation (INFCE) W/o sncl. HEMORIE, J. M. Commission. 80/08/08 2pp.
- --- B009020207 Provides status of QESMO proceedings in response to B00402 lit requesting that Commission re-examine 1977 decision to turminate proceedings w/completion of Intl Nuclear Fusi Cycle Evaluation (INFCE) H/o encl. HENDRIEJ M Commission. 80/09/08 2pp.
- --BOOFCROZIO Provides status of GEBMO proceedings in response-to 800602 lir requesting that Commission re-examins 1977 decision to terminate proceedings w/completion of Intl Nuclear Fuel Cycle Evaluation (INFCE). M/o sncl. HENORIE, J. M. Commission. 80/08/08 2pp.
- -- 9009020217 Requests status of GEBMO proceedings due to concern that NRC FYR: budget did not reflect masd to resume hearings.
 BANTINI, J., MCCORMACK, H., MYDLER, J. M., House of Rep. 80/06/02
- 9009020348 Provides Bubcommittss on Federal Spanding Practices w/ request for assistance in implementing Sunshins Act. Supports cencept of openess in conduct of Commission business. AMEZAME, J.F. Commission. 80/08/13. 2pp.
- BOCTOBOST3 Responds to BOO605 request for Commission to begin rulemaking to establish safety goal for licensing & regulating nuclear plants, Dec of Nuclear Regulatory Research expanding research on safety decisionmaking. AMEARNE, J. F. Commission 80/07/31. 3pp
- 8009090083 BECY-80-293
 Weekly info rept for wk ending 800413
 REM,T.A. Offics of the Executive Director for Operations.
 80/04/18 40pp.
- 3009070579 Forwards plan for investigation of interaction between stectromagnetic pulses & commercial nuclear plant sys. DENTON.M R. Office of Nuclear Reactor Regulation, Director 60/08/05, 10pp.
- 8007070601 Accepts 800723 lecture invitation for 801119 HEMORIE, J. M. Commission 80/07/30, ip.
- --BOOTOTOGOT Requests presence of Commissions: for Iscture on BO1117, KANTER, M. A. Argonns National Laboratory, BO/07/22, ip.
- 8009090632 Heskly info rept for wk ending B00815. REMLT.A. Office of the Executive Director for Operations. 80/08/21. 28pp.

- 8009090639 Ack receipt of 800328 ltr re NRC rulemaking on exergency planning for nuclear facilities & forwards final rules on exergency planning AHEARNELUF Commission 80/08/14 ip.
- --B009090451 Comments on proposed rules 10CFR50 & 70 rs emergency planning:detailed evaluation planning unnacessary Fiftsen-minute warning requirement should be rejected in favor of PBAR criteria COX,F.T Texas, State of 80/05/28 7pp
- --8009090655 Comments on draft guidelines published as NUREQ-0610, "Draft Emergency Action isvel Guidelines for Nuclear Power Plants."

 NRC should give more cognitence to programs & responsibilities of federal state & local govt agencies, COX.F.T Texas, State of 79/11/29. Spp
- --B009090462 Comments on NUREO-0654 re emergency response plans Objects to provisions asseingly included for benefit of federal personnel reviewing state & local plans COX.F T Taxes. Beate of B0/05/13 7pp
- 8009100086 Comments on 8. 2880.Consultant Reform Act of 1980.Supports basic thrust of legislation re-maximizing competition. considering organizational conflicts of interest & providing documented record of got contracts.

 AHEARNE, J. F. Commission 80/08/20, 2pp
- --8009100093 Requests comments on encl S. 2980, Consultant Reform Act of 1980.
 RIBICOFF. A. Benats, Povernmental Affairs. 80/07/02, 27pp
- 8009100098 Comments on 8, 2443 re authorizing DOE to carry out high level liquid nuclear waste mgt demonstration project at Hestern NY Svc Ctr. Supports project initiation to DOE involvament. Recent among raises some problems.

 AHEARNE, J F. Commission. 80/08/20, 2pp
- --8009100102 Comments on 8 2449 rs authorizing DDE to carry out high level liquid nuclear waste mgt dismonstration project at Western NY Byc Ctr. Supports project initiation & DDE involvement Recent amend raises some problems AHEARNE, J F Commission. 80/08/20 2pp.
- --8009:00:107 Requests comments on encl 8, 2443 re authorizing DDE to carry out high level liquid nuclear waste mpt demonstration project at Western NY Bvc Ctr in West Villey.

 JACKSON: H M Senate: Energy & Natural Resources. 80/04/04 7pp.
- ---8009100109 Requests comments on encl 8. 2443 re authorizing DOE to carry out high level liquid nuclear waste mgt demonstration project at Mastern NY Svc Ctr in Mast Vallay M/o encl. BTACCERS.H.O., House of Rep., Interstate & Forsign Commerce. 80/03/24 7pp.
- 8009100111 Forwards repts to Congress on number of full-time permanent smplayees hired & promoted during second & third quarters of FYBO.NRC procedures unchanged from previous repts. H/o encl AMEARNE.J.F. Commission 80/08/22, ip.
- --8009100114 Forwards repts to Congress on number of full-time permanent smployees hired & promoted during second & third quarters of FYBO, NRC procedures unchanged from previous repts. W/o encl AMEARNE, J F Commission. 80/08/22 ip.
- ~~8009100116 Provides Subcommittee on Energy & Power w/repts to Congress on number of full-time permanent employees hired & promoted during second & third quarters of FYBO NRC procedures unchanged from previous repts. W/o sncl.

 AHEARNE, J F. Commission 80/08/22 19.
- ---B009100122 Provides Subcommittee on Environ, Energy & Natural Resources w/repts to Congress on number of full-time permanent smployees hired & promoted during second & third quarters of FY60, NRC procedures unchanged from previous repts 4/o encl AHEARNE, J. F. Commission, 80/08/22 1p.
- --8009100124 Provides Subcommittee on Nuclear Regulation w/repts to Congress on number of full-time permanent employees hired & promoted during second & third quarters of FYSO MRC procedures unchanged from previous repts. W/o encl. AHEARNE, J. F. Commission. 80/09/22. 1p.
- ---B009100128 Provides Bubcommittee on Energy & Environ w/repte to Congress on number of full-time permanent smployees hired & promoted during second & third quarters of FYBO, NRC procedures unchanged from previous repts.

 AHEARNE, J F. Commission 80/08/22, 5pp.

- 8009110408 Forwards response to 800512 inquiry re Commission implementation of export authority under Nuclear Nonproliferation Act, particulary concerning supply reliability includes supporting documents AHEARNELJF Commission 80/08/15. 280pp
- ---B009110413 Forwards questions re Commission implementation of Nuclear Nonproliferation Act
 CHURCH:F Senste: Foreign Relations Committee 80/05/12 3pp.
- 8009i104i7 Responds to 8005i7 ltr enclosing naws article re risk assessment techniques Commission uses risk assessment tschniques:particularly where comparison of alternative courses of action can be made HENDRIE, J H Commission 80/07/29 ip.
- --800911041B Forwards articles re 800514 & 15 hearings on H R 4939 rs comparative rists. RITTER,D House of Rep. 80/06/17, 4pp
- BOOP110325 Forwards MRC ltr to Senator Hart addressing matters re NRC BOO404 response to Subcommittee on Nuclear Regulation questions about pressure suppression containments. W/o snc1 HENDRIE. J M Commission. BO/08/19. ip
- 8009110753 Weekly info rept for wk ending 800822 REHM.T A. Office of the Executive Director for Operations 80/08/27. 28pp.
- 8009120477 Provides Bubcommittee on Energy Research & Production w/ position on Commission pilot program for procedural assistence.in response to 800731 request. Program should not be considered as "funds for intervenors."

 AHEARNE, J. F. Commission. 80/08/22. 1p.
- --8009120480 Discusses position on Commission pilot program for procedural assistance, in response to 80073; request Program should not be considered as "funds for intervenors " AMEARNE, J. F Commission 80/08/22, ip.
- ---8009120483 Discusses position on Commission pilot program for procedural assistance, in response to 800731 request Program should not be considered as "funds for intervenors." AMEARNE, J.F. Commission. 80/08/22 ip.
- --8009120484 Discusses position on Commission pilot program for procedural assistance, in response to 800731 request, Program should not be considered as "funds for intervenore." AMEARNE, J. F. Commission 80/08/22 ip.
- --8009120485 Discusses position on Commission pilot program for procedural assistance, in response to 800731 request Program should not be considered as "funds for intervenors" AHEARNE, J. F. Commission 80/08/22. Ip
- --80091204B9 Discusses position on Commission pilot program for procedural assistance, in response to 800731 request Program should not be considered as "funds for intervenors" AHEARNE, J. F. Commission. 80/08/22 1p.
- ---8009120494 Requests response to suggestion that NRC plane to implement pilot program for procedural assistance should be suspended due to inconsistency w/legizlative history on intervenor funding.

 HCCDRRACK, M , BEVILL, T. , SATTERFIELD, D. House of Rep , Science & Technology. 80/07/31. 2pp.
- 8009150026 Forwards response to questions raised during Committee on Environ & Public Works 800228 hearing & UCB criticisms re ATMS safesty MENDRIE, J M Commission 80/04/04 32pp
- --BOO9150030 Responds to questions re ATWS position Itr ACRS should reply to ltr at Apr meeting AEC/ACRS ltr exchanges & info paper on ATWS should be placed in PDR.
 HENDRIEJ H. Atomic Energy Commission. Deputy Director for Technical Review (Pre-1975). 73/03/20 2pp.
- ---B009150035 Responds to request for comments on methods for evaluating effectiveness of complete SARs. One round of questions is necessary to clarify dateils, Reduction of preparation & review time is prime concern of applicant in CP review HENDRIE, J M. Atomic Energy Commission, Deputy Director for Technical Review (Pra-1975), 72/06/14, 2pp.

- ---BD09150047 Comments on encl proposed rule re separate hearing on single issues Intolerable burdens will be imposed on AEC. w/delays in overall revise of cases HEXDRIG.J M. Atomic Energy Commission, Deputy Director for Technical Raview (Pre-1978). 72/11/15 ip
- ---BO09150052 Comments on and proposed rule change providing for separate hearing on selected issue or issues. Change would affect licensing. Requests views from Director of Licensing. Forwarding its end HMNTZING, L. M. Atomic Energy Commission 72/10/30. 5pp.
- --BOD9150054 Discusses implementation of position on BUR MSIV sealing sys. Bealing sys will be required to suppl MSIV for BUR plants from Duane Arnold. Bhoreham & Fitspatrick onward HENDRIE. J. M. Atomic Energy Commission. Deputy Director for Technical Review (Pre-1975). 73/02/27. 3pp.
- --B009180086 Discusses Calvert Cliffs' fuel desification analysis difficulties. Matter should be addressed in suppl for ACRB June meeting indicating that further info is forthcoming & will be evaluated.
 HENDRIE: J. M. Atomic Energy Commission, Deputy Director for Tschnical Review (Pre-1975). 73/04/19. 1p
- --800915006: Recommends encl proposition as test case for early const start on new plant HENDRIES,J.M. Atomic Energy Commission, Deputy Director for Technical Review (Pre-1975) 74/01/09. 1p
- ---B009130064 Describes proposed procedure for expedited licensing of facility mear Charleston.RI Early site acceptability review provides mechanism to expedite licensing process. Agreements W-state & utils on procedures are required to proceed, BALLARD.R L. Atomic Energy Commission, Directorate of Licensing, 74/01/07 App.
- --- B009150069 Summary of 731219 site visit m/Naraganestt Electric Cs, New England Electric Bys, Vankee Atomic Electric Co & etate & local officials at Naval Air Facility near Charleston, RI. Agande & list of attendess sncl BELLS, D. E. Atomic Energy Commission, Directorate of Licensing. 74/01/03, 4ps.
- ~~BOO9150090 Comments on working paper rs BMR main steam line sealing sys. Urges deletion of phrass indicating that turbins stop vaives should maintain integrity during SBE HENDRIEJ. M. Atomic Energy Commission, Deputy Director for Technical Rsview (Pre-1975). 74/07/23 4pp.
- 8009180410 Forwards responses to 900527 questions as into provided by NRC on 800501 concerning differences in role of NRC & Executive Brench in processing export requests. Supporting documentation ench. AFEARNE.JF Commission. 80/08/22. 13pp.
- --8009150418 SECY-78-216A
 Forwards documents re proposed license for Transnuclear, Inc
 to amount high-enriched U to Sweden.
 SHEAJJR Office of International Programs, Director. 78/05/11.
 3pp.
- --9009130422 Bubmits conclusions as proposed licenss for Transnuclear. Int to export high-enriched U to Sweden. License issuance would be consistent w/Nuclear Nonproliferation Act. HORRER, N. Office of International Programs. Director 78/05/10. Spp.
- --BO09150423 Provides comments on proposed license for Transnuclear, inc to export high-mariched U to Sweden, Supporting documentation encl. TARNOFF, P State, Dept. of. 78/03/03. Spp.
- ---8007150428 Forwards revised analysis of Transnuclear, Inc application to export high-enriched U to Sweden, NOSENZO, L. V. Btate, Dept. of, Bursau of Oceans & Internati Environ. & Scientific Affairs 78/05/08, 17pp.
- --B009180433 Application by Transnuclear, Inc to export 21 053 kg U hazafluoride, antiched to max 93 90X U-235, to Bwadan. End usa statement encl MATSON.V. Transnuclear, Inc. 77/01/25 2pp.
- --8007150438 Forwards application for license to export 19.642 kg U-235, contained in 21 053 kg U as U hexafluoride enriched to 93 3%, to Sweden. H/o encl. Proposed license encl. HATSON, V Transnuclear, Inc 77/01/25, 4pp

- 8009150521 Weekly info rept for wk ending 800829. RDM:T.A. Office of the Executive Director for Operations 80/09/04. 26pp.
- BOOTIA0644 Responds to 800619 ltr re impact of resident inspector program on resident inspector family unit. Every reasonable etep will be taken to reduce personal hardehips associated w/program.

 AHEARMS.J.F. Commission. 80/08/18, 5pp
- -- 8009160647 Expresses concerns re impact of resident inspector program en resident inspector family unit. Focuses on hidden costs of relocation.

 COOK. L. Affiliation Unknown. 80/06/19 5pp.
- 8009190569 Forwards estimate of recources required by NRC & Defence Nuclear Agency for investigation of interaction between electromagnetic pulse & commercial nuclear plant eye DENTON, H.R. Diffice of Nuclear Reactor Regulation, Director, 80/09/10. 2pp.
- SOCYTOORI Comments & recommende actions in response to 800819 memo re new unresolved safety lesues, SECY-80-325. Issues of concern must be added to liet of items requiring further study. Draft special rept to Congress incorporating concerns underway. DENTON, H.R. Office of Nuclear Reactor Regulation, Director 80/09/10. Spp.
- 8009300188 Neekly info rept for wk ending 800712. REHM,T.A. Office of the Executive Director for Operations 80/09/19. 25pp.
- BOOT300250 Discusses draft GAD rept, "Proposed Interim Consolidation of NCC," Agrees that scattered physical locations seriously affect NRC operations, DMS suggestion preferable to GAO plan. AMEANNE, J. F. Commission. BO

CONTRACT NRC CONTRACTS AND MODIFICATIONS

- BOOPCOODE Notification of contract execution, Mod 2 to "Shuttle Bus Byc. " Contractor: Beltway Limoueine Byc. Inc. FLYNY, M. J. Administrative Contracte Branch. NRC-10-80-372. 80/08/19. 1p.
- --8001030085 Med 2, changing daily echedule to "Shuttle Eus Svc."
 ROBERTSON, J. D. Beltway Limousine Service, Inc. MATTIA, M
 Administrative Contracts Branch. NRC-10-80-372 80/08/19. 3pp
- 8009000208 Notification of contract execution. Mod 4 to "Kinewatice of Teanelating Tornado Mindfields." Contractor. TX Tech Univ. HAMEY.H. Research Contracts Branch. FIN B-6177. NRC-04-77-016. 80/08/13. ip.
- --BO09030216 Hod 4, granting no cost extension, to "Kinswatics of Translating Tornado Minifielde " JONES, J.K. Texas Technologial College, HORTON, K.V. Research Contracts Branch, FIN B-6177, NRG-04-77-016, 80/08/13, 2pp.
- 8009040468 Notification of contract execution: "Technical Assistance to Support NRC IE Personnel in Investigations of Incidents." awarded to Parameter. Inc. BAISDENL. Research Contracts Branch. FIN 8-1270, NRC-05-80-251. 80/07/02, ip.
- --B007040470 Contract: "Technical Assistancs to Support NRC IE Personnel In Investigations of Incidents," awarded to Paramster, Inc. LOPY, R. A. Parameter, Inc. MORTON, K. V. Research Contracts Branch FIN 3-1270, NRC-05-80-251, S0/07/02, Spp

- 8009100002 Notification of contract execution "Environ Honitoring Frogram H/State of HS." awarded to State of HS. BAISDEN,L Research Contracte Branch FIN 8-1257 NRC-05-80-289 80/08/22 19
- --8009100003 Contract: "Environ Monitoring Program H/Btats of MS."
 awardsd to Stats of MS
 COBP.A B Mississippi, State of MORTON, K V
 Branch FIN B-1257 NRC-05-80-289 80/08/22 9pp
- 8009100010 Notification of contract execution. Mod 3 to "Study of Gruen Loads in Transportation Accidents " Contractor SRI Intl. HAIRBTON.C A Technical Assistance Contracts Branch FIN 8-6124 NRC-03-78-084. 80/08/08
- ---9007100012 Mod 3, modifying final rspt requirements to "Study of Crush Loade in Transportation Accidents." # BRI International QLAODLA.A.F Technical Assistance Contracte Branch FIN B-6124 NRC-03-78-084 80/08/08 1p
- BOO9100035 Notification of contract exscution, Mod 10 to "Analysis of Hypothetical Accidents Resulting from Core Neltdown." Contractor:Battelle Columbus Labe MORTON, K.V., Reesarch Contracts Branch FIN A-40&7. NRC-04-7&-293 80/08/11. 1p.
- --B009100041 Hod 10. adding funding & changing scope of work to "Analysis of Hypothetical Accidents Resulting from Cors Meltdown."

 LUKE, F. J. Battells Hamorial Instituts, Columbus Laboratorise HORTON: K V. Research Contracts Branch FIN A-4067.

 NRC-04-76-293 80/08/11, 1p.
- 8009100054 Notification of contract execution "Presentation of GE RHR/6 Design & Operation Courses," awarded to GE EAIBDEN, L. Research Contracte Branch FIN 8-1224, NRC-05-80-282 80/08/18, 1p.
- --8009100061 Contract: "Presentation of GE SWR/& Design & Operation Courses: " awarded to GE.
 PIERCE.R.L General Electric Co. MORTON, K V. Research Contracte Branch. FIN B-1224 NRC-05-80-282. 80/08/18. 4pp.
- 8009100071 Notification of contract execution. Mod 9 to "Investigatione in States of Stress in Crusts Under Northsastern US."
 Contractor. NY State Energy Research & Development Authority.
 NORTON, K V Research Contracts Branch FIN 8-3615. NRC-04-75-145-80/05/01. 1p.
- ---B009100077 Hod 9.extending period of performance, to "Investigations in Btates of Stress in Grusts Under Northeastern US,"
 PRIME, H J. New York, Btate of, MORTON, K.V. Ressarch Contracts
 Branch, FIN B-3615 NRC-US-75-145. B0/05/01. ip.
- BO09100405 Notification of contract sxecution. "Bubscription to 1980 Edition of ABME Boiler & Pressure Vessel Code, Including Automatic Addenda Byc." awarded to ABME, COLEMAN.R. Administrative Contracts Branch. NRC-10-80-696. 80/08/22. 1p.
- --8009100409 Contract: "Bubecription to 1980 Edition of ARME Boiler & Preseure Veecel Code. Including Automatic Addenda Svc." awarded to ARME.
 AQUILERA, H. F. American Society of Mechanical Engineers.
 MATTIA: H. J. Administrative Contracts Branch NRC-10-80-496 80/08/22 58pp.
- BO09110001 Notification of contract sxecution. Task Orders 1,2,3 & 4 to, "Technical Assistance to Support NRC IE Technical Personnel in Investigations of Incidents " Contractor: Parameter, Inc.
 BAIEDEN.L. Research Contracte Branch. FIN B-1270 NRC-05-80-251, 80/08/08. ip.
- --8007i10002 Forwards Task Order 1.authorizing expenditure of funds currently obligated for expenses & in-house fees, to "Technical Aceietance to Support NRG IE Technical Personnel in Investigations of Incidents."

 MCRTON.K.V. Research Contracts Branch FIN B-1270.

 NRC-05-80-251 80/07/24. Spp.
- ---8009110003 Forwards Task Order 2. authorizing expenditure of funds currently obligated to provide assistance as technical consultant, to "Technical Assistance to Support NRC IE Technical Personnel in Investigations of Incidents." HORTON.M. V Research Contracts Branch FIN B-1270 NRC-05-80-251. 80/07/24. 5pp

- --8009110004 Forwards Task Order 3, authorizing expenditure of currently obligated funds to provide technical exaistence 4 svcs. to "Technical Assistance to Support NRC IE Technical Personnel in Investigations of Incidents"
 HORTON.K V Research Contracts Brench FIN B-1270
 NRC-05-80-251 80/07/24 5pp
- --8009110005 Forwards Tast Order 4, suthorizing argenditure of currently obligated funds to provide technical staistance & svcs, to "Tachnical Assistance to Bupport NRC IE Technical Personnel in Investigations of Incidents"
 HORTON, K. V. Research Contracts Branch FIN 8-1270
 NRC-05-80-251. 80/08/07. 4pp
- 8009110022 Notification of contract execution "Conduct courses entitles" "Medical Uses of Redionuclides for State Regulatory Personnel," ewarded to Memorial Sloan-Kettering Cancer Ctr FLYNN, M J Administrative Contracts Branch NRC-06-80-302 80/07/28. lp.
- --B009110025 Contract. "Conduct courses entitled "Medical Use of Radionuclides For State Regulatory Personnel" ewarded to Remorial Bloan-Kettering Cancer Ctr # Memorial Bloan-Kettering Cancer Center New York, NY MATTIA, M J Administrative Contracts Branch FIN B-5090 NRC-06-80-302 80/07/28 67pp.
- 8009110215 Notification of contract execution, Hod 1 to "Development of Automated Vandor Balection Sya " Contractor: Gassar Associates HAGAN.T.F. Administrative Contracts Branch FIN 8-1214. NRC-05-80-253 80/07/29. App
- --8009110222 Mod 1.correcting dollar amount on cover sheet & clarifying delivery schedule, to "Davalopment of Automated Vandor Salaction Bys "
 QABSER,E.R Qassar Associates, MATTIA,M J Administrative Contracts Branch FIN 8-1214 NRC-05-80-253 80/07/28 3pp.
- BO09110293 Notification of contract stacution. Hod 5 to "FLECHT-SEABET." Contractors: Westinghousa & EPRI HORTON.K.V Research Contracts Branch. FIN 8-6204. NRC-04-77-127 80/08/19 1p
- --8009110255 Mod 5, providing addi funds. to "FLECHT-BEASET" FARRAR.A C Electric Power Research Institute. MORTON, K V. Research Contracts Branch # Westinghouss Electric Corp FIN B-6204 NRC-04-77-127 B0/08/19. 2pp
- BOO9110331 Notification of contract exacution, Mod 3 to "TMI Spacial Inquiry Team " Contractor: BC Boyle, MORTON: K V Research Contracts Brench, NRC-17-79-453 80/08/25 10.
- --8009110338 Mod 3.deobligating funds.to "TMI Special Inquiry Team "
 DDYLE, B. C. Bernard C. Doyle MORTON.K V. Research Contracts
 Branch NRC-17-79-453 80/08/23. 1p
- 8009110346 Notification of contract execution "Environ Homitoring Program H/State of MI," ewarded to State of MI BAIBDEN.L. Research Contracts Branch, FIN 8-1244, NRC-05-08-284, 80/08/22 1p
- ---8009110350 Contract. "Environ Monitoring Program W/Stata of MI."
 awarded to State of MI.
 REIZEN,M S Michigan, State of MORTON.K V Research Contracts
 Branch FIN 8-1244 MRC-05-80-284. 80/08/22 9pp
- 8009110375 Notification of contract execution. Hod & to "Bafaguards for High Lavel Wasts Repositories" Contractors Science Applications Inc. FOSTER. J. M. Technical Assistance Contracts Branch. FIN 8-6376-9. NRC-02-79-035 80/07/31. 19
- --B009110379 Mod 6, artanding period of performance k revising Article I. to "Bafesyards for High Leval Haste Repositories"
 TREVINO, T. Bejence Applications, Inc. OLAGOLA, F. Tachnical
 Assistance Contracts Branch. FIN 8-6376-9 NRC-02-79-035
 80/07/31 200
- 8009110409 Notification of contract execution, Hod 3 to "Btudy of IN Fault Locations .. New Madrid, MO Region " Contractor IN Univ HADEY, H Research Contracts Branch FIN B-6262 NRC-04-77-164 80/08/25, 2pp
- --8009110410 Mpd 3.extending period of performance w/add1 funds.to "Btudy of IN Fault Locations . . New Madrid.HD Region " HULHOLLAND.J Indiana Univ MORTON.K, V. Research Contracts Branch FIN B-6262, NRC-04-77-164 80/08/25. 3pp

- B009110412 Notification of contract closeout for "Madular Appreach to Fault Trae & Reliability Analysia " Contractor MIT.

 HAGEY:H Research Contracts Branch FIN 8-6236 80/08/04. 2pp.
- 8007120004 Notification of contract execution. Mod 3 to "Georgination of Cooperative Beismotectonic Study in New Madrid Area."

 Contractor St Louis Univ.

 HADEY.H. Rasearch Contracts Branch. FIN 8-6335. NRC-04-78-251 80/09/03 1p
- 8009120010 Notification of contract execution, Hod 3 to "Evaluation of Cross Operator Error Retes Based on Past Experience in Commercial Nuclear Power Plants." Contractor IA State Univ. BROMBERO, B Research Contracts Branch FIN B-6305 NRC-04-78-221 80/08/27 ip
- --8009120012 Hod 3, extending period of performance to "Evaluation of Orose Operator Error Rates Based on Past Experience in Commercial Nuclear Power Plants "
 HABBROOK, R. E. Iowa State Univ HORTON, K. V. Rasearch Contracts
 Branch. FIN B-6305. NRC-04-78-221. 80/08/27 2pp.
- 8009120013 Notification of contract execution, Mod 1 to "Furnish Sanf & Dust Data Basa Occurrences for US," Contractor. NOAA.

 OUSTAVE, R P. Research Contracts Branch FIN 8-10748.

 NRC-01-78-015 80/08/15 1p
- ---8007120014 Mod 1, extending pariod of performance, to "Furnish Band & Dust Data Base Occurrences for US"
 HITCHELL, D. B. Commerce, Dapt, of: National Oceanographic & Akmosphanic Administration. HORTON, K.V. Research Contracts Branch FIN B-10748 NRC-01-78-015 90/08/15. 1p.
- 8009120017 Notification of contract exacution, Mod 6 to "Study of Earthquake Hexards in NY State 4 Adjacent Areas" Contractor: NY State Energy R&D Authority MORTON, K. V Research Contracts Branch. FIN 8-6046 NRC-04-76-369.
- ---B009120019 Mod 6, extanding pariod of performance & increasing funds, is "Btudy of Earthquake Hazards in NY State & Adjacent Aress." PRIME, H. J. New York, State of. MORTON, K. V. Research Contracts Branch FIN B-6046 NRC-04-76-369 B0/08/01 ip
- 8009120023 Notification of contract exacution Mod 3 to "Seismicity & Tectonic Relationship for Upper Great Lakes Precambrian Shield Province." Contractor MI Technological Univ BROMBERO, B Research Contracts Branch, FIN 8-6174, NRC-04-77-112 80/06/28 ip.
- --8009120033 Mod 3, extanding pariod of performance, to "Seismicity & Tectonic Relationship for Upper Great Lakes Precambrian Shield Province"

 EVANB.T.P. Hichiyan Technological Univ. MORTON, K. V. Research Contracts Branch FIN 8-6174, NRC-04-77-112 80/08/28 2pp
- 8009120028 Notification of contract execution: "Review of Staffing Requirements for Neer-Tarm OL Facilities," awarded to BioTachnology, Inc.
 MILES, E. Purchasing Section FIN N-75-2, NRC-03-80-147, 80/06/18.
- --8009120037 Contract "Review of Staffing Requirements for Near-Ters CL Facilities," awarded to BioTechnology.Inc BHANAHAN,W P Biotachnology.Inc PERLMAN,J. Administrative Contracts Branch. FIN B-75-2. NRC-03-08-147. 80/08/18. Spp
- 8009120068 Notification of contract execution: "Environ Monitoring Program W/State of 9A." Contractor State of 9A BAIBBENL. Research Contracts Branch FIN 8-5203, NRC-05-90-279. 80/09/03, ip.
- --8009120075 Contract. "Environ Monitoring Program W/Stats of QA."
 awarded to State of QA
 LEDSETTER.L. Georgia, State of, MORTON.K.V Research Gontracts
 Branch FIN 8-5203. NRC-05-80-279 80/09/03 14pp
- 8009120070 Notification of contract execution, Mod 2 to "Technical Editing Sycs for DESMO Fuel," Contractor JF Holman & Co. MARTIN, L. C. Tachnical Assistance Contracts Branch. FIN 8-1492 NRC-02-76-290 80/07/21, ip

- --B009120083 Mod 2.deobligating funds to "Technical Editing Svcs for OCENC Fuel"
 HOLMAN, J.F. John F. Holman & Co.: Inc. DOUGHERTY, D. J. Technical Assistence Contracts Branch FIN 8-1492 NRC-02-76-290 B0/07/21. 1p
- 8009120104 Notification of contract execution "Comparative Review of Risk Assessments Bafety Coals & Related Concapts For Commercial Nuclear Power & Alternative Sources of Energy, " awarded to Intl Planning Mgt HYYLEA. Administrative Contracts Branch FIN 8-7501 MCC-03-80-146 80/08/18 ip
- --BOO9120115 Contract. "Comparative Review of Risk Assessments, Bafety Goals & Related Concepts For Commercial Nuclear Power & Aiternative Edurces of Energy," awarded to Intl Planning Hgt.

 a International Planning Management, PERLMAN, J Administrative Contracts Branch, FIN 8-7501, NRC-03-80-146 BD/08/18 App.
- GOOP120559 Notification of contract execution "Electrostatic Copying Sycs." awarded to Literature Research Co.
 FLYNNH.J. Administrative Contracts Branch NRC-17-80-450 80/08/27 1g
- BOO9120665 Notification of contract execution Mod 11 to "Document Control Bys" " Contractor: TERA Advances Bycs Corp.
 LEEG.C.D. Administrative Contracts Branch NRC-10-78-580.
 BO/09/04. 1p.
- BOOTIS014D Notification of contract execution. Mod 5 to "Economic Consulting Byes in Connection W/Btanislaus Nuclear Unit "Contractor P Quemann. OCACOLA: A. Technical Assistance Contracts Branch. FIN 8-6521. NRC-03-77-113. B0/06/30. 2pp.
- --B009150143 Hod 5.extending period of performance & increasing ceiling amount, to "Economic Consulting Byes in Connection W/ Stantslaus Nuclear Unit."
 SUTMANN, P. Outman, Peter. OLAODLA, A.F. Technical Assistance Contracts Brench. FIN 8-4521. NRC-03-79-119. 80/04/30 ip.
- 9009180146 Notification of contract execution, Hod 10 to "Review of Environ Impacts of High Level Radwaste Hot " Contractor. Tehnskron. BRITHOP.A. Technical Assistance Contracts Branch. NRC-02-77-165. 80/07/21. ip.
- --8009150147 Mod 10, modifying delivery dats of Bubtask 2 rept & to key personnel clause; to "Review of Environ Impacts of High Level Radwaste Mgt."

 COHEN.B. Teknekron, Inc. DOUOHERTY, D. J. Technical Assistance Contracts Branch, NRC-02-77-165, BO/07/21 ip.
- BOOTESOITA Notification of contract execution "Development of Nuclear Reactor Plant Date Bank," awarded to Small Business Afainistration, Subcontractor: Technology Development of CA, Inc. JACOBB.A. Research Contracts Branch. FIN 8-7077. NRC-04-80-215. BO/08/22. 19
- --BOOTISOITH Contract: "Development of Nuclear Power Plant Data Bank" awarded to Small Business Administration. Subcontractor Tecnology Development of CA: Inc HOPHERBONH, Basil Business Administration. CRACRAFT, T. M Technology Development of California, Inc. HORTON, K V. Research Contracts Branch. FIN 9-7077. NRG-04-80-215 80/08/22 64pp
- 8009150409 Notification of contract execution. Mod 1 to "Assessment of Strength of Ice Condenser Containment."
 Contractor: RkD Associates.
 FLEENOR. C. H. Afainistrative Contracts Branch FIN 8-1314.
 NRC-17-80-451. B0/08/25 1p.
- BC09160485 Notification of contract execution Rod 4 to "Wind Tunnel Heasurements of Dispersion & Turbulence in Wakes of Ruciest Reactor Plants." Contractor: CO State Univ 14465; 41. Research Contracts Brench. FIN 8-3829. NRC-04-75-235-B0/08/22. ip

- --BO09160488 Mod 4.providing add1 funds & extending period of performance to "Hind Tunnel Heasurements of Dispersion & Turbulence in Hates of Nuclear Reactor Plants "BROWN.J F Colorado Blats Univ HORTON,K V Research Contracts Branch. FIN B-5829 NRC-04-76-236 80/08/22 5pp
- 8009160491 Notification of contract execution.Mod 4 to "Assessing Capability of Existing Pu Facilities to Hithstand Natural Phenomena." Contractor NN Newmark OLAOU.A.A.F. Technical Assistance Contracts Branch FIN B-6150-9
- --B009i60475 Had 4.extending period of performance to "Assessing Capability of Exitting Pu Facilities to Withstand Natural Phenomena"

 **N K Newmark Consulting Engineering Bervices GLACOLA.A F Technical Assistance Contracts Branch FIN B-6150-9 NRC-03-70-150. B0/07/29 ip
- 8009i605ii Notification of contract execution, Mod 4 to "Advanced Process Control " Contractor. Science Applications, Inc FOSTER, J M Technical Assistance Contracts Branch FIN E-6930-0 NRC-02-79-043-1. 80/07/21 ip
- --B009160315 Mod 4.adding accounting & appropriations data contained in Item 10 to "Advanced Process Control." # Eciance Applications, Inc. DOUGHERTY, D J Technical Assistance Contracts Branch FIN 8-6930-0 NRC-02-79-043-1 B0/07/21 ip
- 8009180143 Notification of contract execution Mos 8 to "Maint of Data General Corp C-330 Computers & Associated Parigherals " Contractor Data Consultants Inc HERRIN L. A K Administrative Contracts Branch NRC-10-77-195 80/08/28 1p
- --8009180150 Mod B.correcting affective date of Mod 7 to "Maint of Data Qeneral Corp C-330 Computers & Associated Paripherals " * Data Consultants Inc HATTIA.H J Administrative Contracts Branch NRC-10-77-196. 80/08/28 ip
- 8009180159 Notification of contract execution Mod 11 to "Document Control Sys," Contractor TERA Advanced Sycs Corp LEBD.C D Tachnical Assistance Contracts Branch NRC-10-78-580 80/09/04 1p.
- --8009180165 Mod 11. increasing funds, to "Document Control Sys "
 * TERA Corp. HATTIA.H.J. Administrative Contracts Branch
 NRC-10-78-580. 80/09/04. 2pp
- 8009180167 Notification of contract execution Mod 1 to "Publication Distribution Sycs " Contractor Computer Data 8gs Inc HAGAN, T F Administrative Contracts Branch NRC-10-80-362 80/09/08 ip
- ---8009180191 Hod 1.adding requirement for add1 storage capacity & increasing funds, to "Publication Distribution Svcs "
 COMBB,C. Computer Data Systems, Inc. MATTIA, M. J Administrative Contracts Dranch. NRC-10-80-362 80/09/08 1p
- 8009180207 Notification of contract execution. "Bource Term Characterization Resulting from Explosively-Caused Becondary Violations of Spant Fuel Chipping Caeks." awarded to DMI. HOLLETT, S. Research Contracts Branch. FIN 8-6710 NRC-04-80-180 80/09/03 1p.
- --8009180217 Contract. "Source Term Characterization Resulting from Explosively-Caused Secondary Violations of Spent Fuel Shipping Casks: " awarded to BMI EUKZ, F. J. Battells Hembrial Institute. Columbus Laboratories MORTON, K. V. Research Contracts Branch FIN B-6710. NRC-04-80-180, 80/09/03 18pp.
- 8009180320 Notification of contract execution, Mod 3 to "KY-70 Secure Voice Terminals." Contractor Netl Security Agency MEDROW.L.A.K. Administrative Contracts Branch. NRC-10-77-170. 80/09/04 [p
- --B009180027 Mod 3; decreasing total amount of agreement & complating closeout action to "KY-70 Secure Voice Terminals " DAVIEB,D.L. National Becurity Agency MATTIA.M.J Administrative Contracts Branch NRC-10-77-170 80/07/04, ip.
- BOO9190051 Notification of contract execution. Hod 3 to "Union Carbide Urayan Mill Tailings Evaluation " Contractor Geotechnical Engineers: Inc HARREION. C. A. Technical Assistance Contracts Dranch FIN B-6926 NRC-02-79-035 80/08/21 Ip

- ---8009190057 Hod 3.extending period of performance.to "Union Carbide Urayan Hill Tailings Evaluation."

 LACATTA.D P. Geotechnical Engineers.Inc HAIRSTON.C.A Technical Assistance Contracts Branch FIN B-6926, NRC-02-79-055 80/09/21 1s
- 8009190188 Notification of contract execution Mod 6 to "Oncall Heint for NRC Computer Peripheral Equipment " Contractor: Computer Bys Support Corp MEDROW, L.A. K. Administrative Contracts Branch NRC-10-79-395 80/08/28, 1p
- --8009190190 Mod 6.correcting effective date of Mod 5.to "Oncall Maint for NRC Computer Peripheral Equipment" * Computer Systems Support Corp HATTIA.H J. Administrative Contracts Branch. NRC-10-79-375. 80/08/28 p
- 8009190702 Notification of contract execution. Mod 4 to "Development & Implementation of Flaw Analysis Sys Based on Synthetic Aperture Ultrasonic Imaging Technique " Contractor: Southwest Research Inst HOLLETY.S Research Contracts Branch FIN 8-5605 NRC-04-77-145, 80/08/29. ip
- --8009190713 Mod 4.extending period of performence from 800131-81073), to "Development % Implementation of Flaw Analysis Sys Based on Synthetic Aparture Ultrasonic Imaging Technique" SPRENCEL.JF. 8outhwest Research Institute. MORTON.K V Research Contracts Branch FIN 9-5605. NRC-04-77-145 80/08/29 4pp.
- BO09190727 Notification of contract execution, Mod 9 to "Critical Experiments, Measurements & Analysis to Establish Crack Arrest Methodology for Nuclear Pressure Vessel Steels," Contractor Battelle Calumbus Labs MCRTON, K. V Research Contracts Branch. FIN A-4046 NRC-04-76-293. BO/08/29 ip
- --BO09190738 Mod 9, increasing workscope & providing add1 funding to, "Critical Experiments Measurements & Analysis to Establish Crack Arrest Methodology for Nuclear Pressure Vessel Bteels."

 LUKZ.F.J. Battelle Memoriel Institute: Columbus Laboratories HORTON-K.V Research Contracts Branch. FIN A-4046, NRC-04-76-293. B0/08/29. ip.
- 8009230137 Notification of contract execution. Hod 1 to "Licensing Assistance/Tailinge Hgt Program Technical Evaluation." Contractor.J.H Klainfalder & Associates HAIRSTON.C A. Technical Assistance Contracts Branch. NRG-02-79-031. 80/08/20 1p
- --BOOT230161 Mod 1.extending period of parformance to B10707 to,
 "Licensing Assistence/Tailings Mgt Program Technical
 Evaluation"
 KLEINFELDER, J. J H Kleinfelder & Associates. GLACOLA, A.F
 Technical Assistance Contracts Branch, NRC-02-77-031 80/08/20
- 8009230354 Notification of contract execution, Hod 2 to "Bafety Assessment of Concrete Nuclear Structures " Contractor: HIT BRUMBERO, B Research Contracts Branch. FIN 8-6618 NRC-04-79-181 80/04/01 ip.
- --B009230359 Mod 2. extending period of performance, to "Bafety Assessment of Concrete Nuclear Structures,"

 DUMMER. 9 M. Hassachusetts Institute of Technology MORTON, K. V. Resserch Contracts Branch. FIN B-6618 NRC-04-79-181 80/04/01 2pp
- 8009230364 Notification of contract execution. Mod 4 to "Beismological Study of Northern Extent of New Madrid Beismic Zone."
 Contractor: Baint Louis Univ.
 RROMERGUS. Research Contracts Branch. FIN 8-5964 NRC-04-76-282 80/08/26. 1p.
- ---BO07230372 Mod 4, increasing funds & sitending period of performance, to "Selemblogical Study of Northern Extent of New Madrid Seismic Zone"
 STAUDER: B J. St. Louis Univ HORYON, K, V Research Contracts
 Branch FIN B-5964, NRC-04-76-282, 80/08/26 49p
- 8009230751 Notification of contract execution, Mod 5 to "Seismotectonic Study of New England & Adjacent Areas," Contractor, Boston College,

 JACOBBIA. Research Contracts Branch. FIN 8-5961 NRC-04-76-291,
 80/08/27. ip
- ---8009230755 Mod 5, extending period of performance & increasing funds & workscope to "Setsmotectonic Study of New England & Adjacent Areas."

 SMITH, J. R. Boston College, MORTON, K. V. Research Contracts
 Branch FIN 8-5961, NRC-04-76-291 80/08/27 7pp

- B009230768 Notification of contract execution Mod 1 to "Eastern TN/ Hestern NC Regional Beismic Natwork," Contractor Hemphia Btate Univ HA0EY, H Research Contracts Branch, FIN 8-6675 NRC-04-79-214 B0/08/27 1p
- --8009230771 Mod 1.extending period of performance until 801130.to
 "Eastern Th/Mastern NC Regional Seismic Network."
 CARPENTER.T 0 Memphis State Univ MORTON.K.V Research
 Contracts Branch FIN 8-6675 NRC-04-79-214 80/08/27. 2pp.
- 8009230774 Notification of contract execution. Mod 3 to "Biructural Framework of MS Embayment of Southern IL." Contractor Univ of IL at Urbana HAGEY, H Research Contracts Branch FIN 8-6251 NRC-04-77-159, 80/08/29, 1p.
- --8009230777 Mod 3.estending period of performance & increasing funds.ts "Btructural Framework of MS Embayment of Southern IL."

 BRADY.R.W Illinois Univ. of Urbana-Champaign MORTON, K. V. Research Contracts Branch FIN 8-6251 NRC-04-77-139, 80/08/29 40s.
- 8009240023 Notification of contract execution: "Coordination of Cooperative Organizations Participating in Geological, Ocophysical & Beismological Studies," awarded to 8t Louis Univ WOLLETT,8, Research Contracts Branch FIN 8-7242 NRC-04-80-229, 80/09/03, 1p
- ~-8009240028 Contract "Coordination of Gooperative Organizations Participating in Geological, Geophysical & Beiemological Bitudies:" awarded to Bt Louis Univ STAUDER: W. Bt. Louis Univ. MORTON, K V. Research Contracts Branch FIN 8-7242. NRC-04-80-229. B0/09/03. Spp.
- BO09240034 Notification of contract execution: "Fission Product Transport Analysis:" awarded to Battelle Columbie Labe. HADEY, H. Research Contracts Branch. FIN 8-6747 NRC-04-80-177. 80/09/09. 1p.
- --800924003B Contract. "Fission Product Transport Analysis," awarded to Battelle Columbus Labs RICHARDBON, T. F. Battelle Memorial Institute, Columbus Laboratories, MORTON, K. V. Research Contracts Branch. FIN 8-6747. NRC-04-80-177. 80/09/09. Opp
- 9009240065 Notification of contract execution, Mod & to "Std Containere for SNM Storage, Transfer & Measurement," Contractor: IRT Corp., OUSTAVE, R.P., Research Contracts Branch. FIN 8-1051. NRC~01-78-001. B0/08/12 1p.
- ---8009240049 Mod & providing no cost extension to "Std Containers for BM Storage. Trensfer & Messurement."

 MCVEIN.J. IRT Corp MORTON, K. V. Research Contracts Branch. FIN B-1051 NRC-01-78-001 80/08/12 ip.
- BOO9240073 Notification of contract execution. "Independent Assessment: Destructive Testing & Analysis." Contractor: Franklin Inst. BAISDEN, L. Research Contracte Branch. FIN:B-1212 NRC-05-79-253 BO/06/21. 1p.
- ---8009240079 Forwards Contract NRC-05-79-253, Task Order A, authorizing #25,000.00 to provide essistance in systematic review of responses to IE Bulletin 79-01B.
 HORTON K.V Research Contracts Branch, FIN 8-1212.
 NRC-05-79-253. 80/07/22 4pp.
- 9009240123 Notification of contract execution. "Wabash Valley Seismic Profile," awarded to Purdup Research Foundation. WOLLETT, B Research Contracts Branch. FIN B-7223. NRC-04-80-224 80/09/08. ip
- --8009240130 Contract: "Mabash Vailey Beismic Profile," awarded to Purdua Research Foundation. GREENKORN,R A. Purdua Research Foundation. MORTON,K V. Research Contracts Branch. FIN 8-7223. MRC-04-80-224. 80/09/08. 17ps.
- 8009250258 Notification of contract execution, Mod 7 to "Svcs of WR Johnson on ABLAP," Contractor: Univ of VA COLEMAN, R. Administrative Contracts Branch NRC-10-75-140 80/09701. 1p
- --8009250263 Mod 7, extending period of performance & providing complete funding adjustment to "Sycs of HR Johnson on ASLAP"

 " Virginia: Univ. of. MATTIA, N J Administrative Contracts Branch. NRC-10-75-140, 80/09/01. 1p.

- 8009250493 Notification of contract execution. Mod 5 to "Study of Consumer Products Containing Radioactive Hatl " Contractor Science Applications Inc HAIRSTON. G Tschnical Assistance Contracts Branch FIN 8-0280-NRC-02-78-045. 80/08/15 1p
- --8009230497 Mod 5, providing dus dates for Task 2 repts, to "Study of Consumer Products Containing Radioactive Matl " MCDONALD, R J. Science Applications, Inc OLAODLA, A F Technical Assistance Contracts Branch FIN B-0280 NRC-02-78-045 80/08/15, ip.
- 8009260229 Notification of contract execution: Mod i to "Davelopment of Automated Vandor Salaction Bys." Contractor Gassar Associates.

 HAGAN, T.F. Administrative Contracts Branch FIN B-1214

 MRC-05-80-253 80/07/28 ip
- 9009280232 Notification of contract execution, Mod 2 to "Osmaral Osalogy, Daughtysics & Beismicity of Northwest AL", Cantractor: Osological Survey of AL, Univ of AL. BROWSERG. B. Research Contracts Branch. FIN B-6617 80/09/04. 1p.
- --8009260238 Mod O2.extanding pariod of performence & adding addl funds, to "General Geology, Geophysics & Beismicity of Northwest AL "
 - AL *
 JUINER, T. J. Alebene, State of MORTON, K. V. Research Contracts
 Brach FIN B-6617 NRC-04-78-262 B0/09/04 2pp.
- BOOT250243 Notification of contract execution Mod 1 to "Wabash Valley Seissic Profile", Contractor Purdue Research Foundation WOLLEYT'S, Research Contracts Branch, FIN 8-7223 80/09/10 ip.
- --8009260247 Mod 1.increasing FY80 funding to "Wabash Valley Seismic Profils". a Pundus Research Foundation MORTON.K V Research Contracts Branch. FIN 8-7223 NRC-04-80-224 80/09/10, 1p.
- BOO9260676 Notification of contract stacution, Mod 2 to "Two Phase Flow Aspacts of Reactor Bafety " Contractor: Dartmouth College HAIRBTON C. Technical Assistance Contracts Branch FIN 8-6525, MRC-03-79-102 80/08/29. ip.
- -8009250480 Mod 2, changing Article VI re authorized representative, to "Two Phasa Flow Aspacts of Reactor Bafety," # Dertmouth College DOWGHERTY, D J Technical Assistancs Contracts Branch, FIN B-6525, NRC-03-79-102, 80/06729, 2pp.
- 8009290139 Notification of contract execution: "Environ Monitoring Fragram w/Stata of 8C," awarded to Stata of 8C. BAIBDENLL Research Contracts Branch. FIN 8-5112 NRC-05-80-273 80/09/09. ip.
- ---B009290142 Contract: "Environ Monitoring Program w/Btate of SC." awardsd to State of SC. DANTZLER.M.U. South Carolina: State of. MORTON,K.V. Ressarch Contracts Sranch. FIN 8-5112. NRC-05-80-273 60/09/09. 16pp.
- 9007D00093 Notification of contract execution, Mod 1 to "Keypunch & Verification Svcs." Contractor: Small Susiness Administration, Subcontractor: Intl Susiness Svc. Inc. WIGGIBS. E. Administrative Contracts Branch. NRC-10-80-695 B0/09/03. 19
- BOOT300118 Notification of contract execution. Med 1 to "Nondestructive Exemination Mobile Van.Region 1." Contractor Mobile Bys. MIGOINS.E. Administrative Contracts Branch. NRC-05-80-259 BO/09/02 is.
- --B009300121 Med 1, adding door to vahicle, to "Nondestructive Examination Mesile Van Region 1,"
 KIMELL J. J. Mobils Systems. MATTIA: H J. Administrative Contracts
 Brench. NRC-05-80-239, 60/09/02, 1s.
- BO09300193 Notification of contract execution, Mod 8 to "Design of IFMIS," Contractor Small Business Administration, Bukcontractor: Technessociates, Inc. HAONALTF. Administrative Contracts Branch, NRC-10-80-395, 90/09/09 1p.

- ---B00730019B Hod B, increasing funds, to "Design of IFHIS "
 TUNBTALL, J E Beall Business Administration MATTIA, M J
 Administrative Contracts Branch YYHIER, P Technosocciatss, Inc
 NRC-10-EB-395 B0/09/05 3pp
- GOO9300206 Notification of contract execution. Mod 1 to "ADP Bys Support " Contractor Basil Business Administration, Subcontractor Technassociates Inc. FLYNN.M J Administrative Contracts Branch NRC-10-80-673 BO/09/09 1p
- --8009300209 Mod 1, changing dates for project status repts & adding consultant category, to "ADP 8ys Support"
 TUNSTALL.J E Gmail Business Administration YTHIER.P
 Technassociates, Inc. MATILAM J Administrative Contracts
 Branch NRC-10-80-673 80/09/09 3pp
- BOO9300257 Notification of contract execution "Containment Safety Under Internal Explosions," awarded to MIT JACOBS.A. Research Contracts Branch FIN 8-7085 NRC-04-80-194 BO/09/12 19
- --8009300264 Contract: "Containment Safaty Under Internal Explosions" awarded to MIT. DUMTER: O.H. Hessachusatts Institute of Technology MDRTON, K. V Research Contracts Branch FIN E-7085 NRC-04-80-194 80/09/12 600.
- BOO9300271 Notification of contract execution "Prepara Summary of NUREG-0578, Absorption of Krypton & Xanon on Activated Carbon," awarded to Univ of Pittsburgh. FLEENOR, C. M. Administrative Contracts Branch FIN 8-1557 NRC-11-80-403. 80/09/11 1p
- 8009300592 Natification to contract execution. Had it a "Coordination of Cooperative Organizations Participating in Geological, Geophysical & Beismological Studies, " Contractor Bt Louis Univ.
 WOLLETT, B. Research Contracts Branch FIN B-7242 NRC-04-80-229 80/09/09 1p
- ---8009300597 Mod 1, increasing funds & sztending period of performance to "Coordination of Gooperative Organizations Participating in Geological, Geophysical & Seismological Studies" * 8t. Louis Unly. MCRYON, V Research Contracts Branch FIN B-7242 NRC-04-80-229 80/09/09. ip
- 8007900593 Notification of contract asscution: "Environ Assessments of Burface & Groundwater Impacts From U Racovery Operations: " awarded to Ott Hater Engineers, Inc. HAIRETON, G Technical Assistance Contracts Branch NRC-02-80-028-01, 80/09/04, ip.
- ---B007300575 Contract "Environ Assassments of Surface & Groundweter Impacts from U Recovery Operations," awarded to Ott Hater Engineers, Inc.
 OTT, R.F. Ott Water Engineers, Inc. DOUOHERTY, D. J. Technical Assistance Contracts Branch. NRC-02-80-028-01. 80/07/04 1889
- DISCLOSURE FINANCIAL DISCLOSURE INFORMATION
- BOO9180101 Advises that review of Confidential Statement of Employment & Financial Interests revealed vested interest in Union Cambide Co. Exemption granted from requirements of 10CFRO 733-21 DIRCKS.W.J. Office of Nuclear Material Safety & Safeguards BO/06/19 10
- 8009250065 Grants exemption from provisions of 100FRO 795-21 allowing for participation in matters affecting Bechtni Power Corp. while having vested interest in company employes trust fund RDSB.D Division of Systems Integration. 8D/09/03 ip.
- FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES
- 7703230216 Confirms actions undertaken on 770131 re use of licensed byproduct meth by individuals not authorized as users. Corrective actions will halb use of math secure licensed meth on hand & resume use only by approval KEPPLER, J. C. Region 3. Chicago. Office of the Director. 79/02/01 lp.

- 7904120080 Discusses 1E insp of License 12-18044-01 on 790131-0202 & forwards notice of violation KEPPLER.U G Region 3. Chicago. Office of the Director 79/04/05
- --7904120082 Notice of violation from insp on 790131-0202 Noncompliance noted procured seven bulk shipments of Xe-133 merked "Not for Human Use." no licensed supervision of licensed matl & no program to measure radioactive matl in air * NRC Regional Offices 79/04/05 Spp
- 7904170409 Schedules 790323 meeting to discuss noncompliance items noted in insp of Licenses 48-17466-0MD & 12-18044-0MD KEPPLER, J C. Region 3. Chicago, Office of the Director 79/03/19 in
- 7904170412 Schedules 790323 meeting to discuss noncompliance items noted in kinsp of License 48-17466-01MD KEPPLER,J O Region 3, Chicago, Défice of the Director 79/03/19
- 790A010084 Act receipt of 790305 itr informing NRC of staps taken to correct violations noted in IE insp of License 08-18308-01MD on 790208
 MCCLINTOCK,R O Region 1, Philadeiphia, Office of the Director 79/03/23 1p
- ---7906010086 Responds to NRC 790223 ltr re violation noted in IE inep of License 08-18308-01HD on 780208 Corrective actions no further transfers of Xe-133 to individuals lacking necessary license info & chart w/licensing info posted IRWIN.R F Pharmetopes, Inc. 79/03/06 2pp.
- ---7905010088 Discusses IE inep 30-14826-01 of Licence 08-18308-01 on 790208 & forwards notice of violation MCCLINTOCK.R.O Region 1, Philadelphia, Office of the Director, 79/02/23 2pp
- --7906010091 Notice of violation from insp on 790208 Noncompliance noted shipped Xe-133 to hosp w/o verifying that hosp licenee authorized Xe-133.

 * Region i, Philadelphia, Office of the Director 79/02/23 ip
- 7905290524 Ack receipt of 790425 ltm informing NRC of steps taken to correct violations noted in IE insp of License 12-18044-01 on 790405
 KEPPLER, J. O Region 3, Chicago, Office of the Director 79/05/18 to
- --7906290556 Responds to NRC 790405 itr re violations noted in IE insp of License 12-18044-01 on 790405 Corrective actions will not buy Xo-123 w/a label "for human user" bicassay procedure changed & bired addi personnel ZIMMER.A.M Nuclear Pharmacy, inc 79/04/25 7pp
- 7910020407 Orants extension to 791022 for submission of response to 790817 notice of violation served on Nuclear Pharmacy Inc STELLO.V Office of Inspection & Enforcement, Office of the Director 79/09/07 2pp
- 79:1090069 Discusses IE insp of License 12-179:0-01MD on 790926 & i010 & forwards notice of violation DAVIB.A B Region 3. Chicago. Fuel Fecility & Materiale Safety Branch 12-179:0-01MD 79/10/25 ip
- ---7911090077 Notice of violation from insp on 790926 & 1010 Noncompliance noted failure to make surveys he redistion exposure to personnel extrantities, failure to made monthly thyroid readings of person using I-131 & failure to make lab survey * Region J. Chirago. Office of the Director 12-17910-01MB 79/10/25 1p
- 7712040149 Ack receipt of 771105 itr informing NRC of steps taken to correct violation noted in IE insp of License 12-17190-01MD on 791025

 DAVIG.A B Region 3. Chicago, Fuel Facility & Meterials Safety Branch. 79/11/21 ip
- --7912040156 Responds to NRC 791025 ltr re violations noted in IE insp of License 12-17190-01MD on 791025 Corrective actions evaluations on personnel ring badge readings for 781225-791024 & 0625-0725 sent to R S.Landauer, JR & Co for records COMER.F M Pharmaco Nuclear, Inc. 79/11/05 4pp
- 7712180310 Discusses IE (nep of License 37-18461-01 MD on 770828-29 No noncompliance noted Major areas inspected review of circumstances surrounging receipt of peckage containing Ke-133 MCCLINTOCK, R O Region 1, Philadelphia, Office of the Director 79/10/03. 1p

- 7912190014 Ack receipt of 790917 ltr informing NRC of steps taken to correct violation noted of License 37-18461-01MD on 790618 GRIER, B H Region i, Philadelphia, Office of the Director 79/10/03 ip
- --7912190023 Responds to NRC 790910 ltr re viciation noted in IE inspectives 37-18461-0iMD on 790618 Corrective actions restricted area workers will be instructed auditor will survey radiation hazards & syrings shields will be used. DESSEL.8 Nuclear Pharmacy, Inc 79/09/17 4pp
- --7912190047 Responds to NRC 790821 ltr re violetion noted in IE lnsp of License 37-18461-01MD on 790618 Corrective actions: sent copy of guidelines for radwaste packaging & pick up to customers & Institued training program for transporters DESSEL.8 Nuclear Pharmacy, Inc 00618 79/09/10 34pp
- ~-7912190054 Ack receipt of 790807 ltr informing NRC of steps taken to correct violation noted in IE insp of License 37-18461-01MD on 790618 Requests addl info re mgt control sys. to be received within 7 days of itr BMITH.0 H Region 4, Dalles, Office of the Director 79/09/10 is.
- --7912190067 Responds to NRC 790723 ltr re violations noted in IE inspet License 37-18461-01MD on 790618. Corrective actions: surveys of radioactive matte discharged in effluent air from fume bood will be done routinely DESSEL.8. Nuclear Phermacy, Inc. 79/08/07 3pp
- --7912190073 Forwards notice of violation from IE insp of License 37-1846i-OIMD on 790618. QRIER B H. Region i, Philadelphia. Office of the Director. 79/07/23 2pp
- --7912190080 Notice of violation from insp on 790618, * Region 1, Philadelphia, Office of the Director 79/06/23 3pp
- 8001020069 Ack receipt of 791120 itr informing NRC of steps teten to correct violations noted in IE insp of License 08-18308-01MD on 790913
 MCCLINTOCK,R O Region i, Philadelphia, Office of the Director, 79/12/10 is
- ---B001020073 Responds to NRC 791114 1tr re violations noted in IE inspet License OB--1B308--01KD on 790913 Corrective actions, dose calibrator will be adjusted or repaired when activity measurements during linearity tests differ by more than 5%. IRHIN,R F Phermatopes, Inc 79/11/20 ip.
- --8001020078 Ack receipt of 791017 ltr informing NRC of steps taken to correct violations noted in IE insp of License 08-18308-01MD on 790913. Requests addl info re dose calibrator adjustment & uipe tests

 MCCLINTOCK, R. C. Region i, Philadelphia, Office of the Director,
- ---B001020083 Responds to NRC 790922 ltr re violations noted in IE inspectives actions oB-18308-01MD on 790913 Corrective actions syrings shields will be used at all times & linearity tests will be repeated upon indication of more than 10% iRHIN.R F Pharmatopes, Inc. 79/10/17 3pp
- --8001020105 Discusses IE insp of License 08-18308-01HD on 790913 & forwards notice of violation.

 HCCLINTDCK.R D Region 1, Philadelphia, Office of the Director 79/09/27. 2pp
- --800102010B Notice of violation from insp on 790913 Noncompliance noted failure to use lead syrings shields, failure to record constancy checks on 790820-21 & failure to perform wipe test on incoming packages.

 * Region 1, Philadelphia, Office of the Director 79/09/27, 2pp
- 8001290275 Ack receipt of 800107 ltr informing NRC of steps taken to correct violations noted in IE insp of License 24-14617-01MD.

 DAVIS, A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/01/18. 1p.
- --8001270281 Responds to NRC 800102 itr re violatione noted in IE insp of License 24-16617-01MD. Corrective actions have requested NRC to amend to license from three months to yearly calibr for redistation monitors

 KEESEE, R. Pharmaco Nucleer, Inc 80/01/07. 1p.
- 8002130273 Confirms meeting to be held between NRC & Nuclear Pharmacy.
 Inc on 800122 in King of Prueeie,PA to discuss results of
 NRC 770802-03 insp & noted noncompliance.
 GRIER,B H Region i, Philadelphia, Office of the Director.
 80/01/09 ip

- 8002150283 Discusses error in 800109 ltr Purpose of meeting is to discuss results of 800103 insp Heeting date is 800122 at Region 1 ofc BMITH.0 H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/01/15 ip
- BOO2190229 Ciarifias Nuclear Pharmacy, Inc comments made during 800121 mesting or NRC notice of vicietion Forwards summary of facts available to NRC prior to issuance of notice Urges dismissal or remission of civil pensities
 VAKERICE.T V D'Connor & Hennan 80/02/05 7pp
- 8003050215 Ack receipt of 791221 ltr informing NRC of steps taken to correct violations noted in IE insp of License 37-18461-01MD on 791109 ltem A corrective & preventive actions will be discussed at 800122 NRC meeting GRIER, B # Region 1, Philadelphia, Office of the Director 80/01/21.
- --S009050219 Responds to NRC 791211 ltr re violations noted in 1E insp of License 37-18461-01MD on 791109. Corrective actions steps have been taken to lower employee radiation exposure Syrings shield will be used whenever possible.

 DESSEL. 6 Nuclear Pharmscy, inc 79/12/21 4pp
- --8003050224 Forwards notice of violation from IE insp on 791109 One item of noncompliancs noted in NRC 790723 ltr has not been totally corrected NRC has no further questions re Item B corrective actions.

 ORIER.B.H Region i, Philadelphia, Office of the Director. 7971211 2pp
- --B003030226 Notice of violation from insp on 791109 Noncompliance noted: saployee overexposure.feilure to report overexposures, failure to conduct required surveys
 4 Region 1. Philadaiphie, Office of the Diractor 79/12/11 Opp.
- --B003050232 Bubmits revised quarterly figures to extramity exposures Gompany has instituted adequate measures to ansure significantly lower exposure levels.

 DESSEL, B Nuclear Pharmacy, Inc. 79/11/12 2pp.
- GOOX190517 Ack receipt of 800128 itr informing NRC of steps taken to correct violations noted in IE insp of License 45-18378-01 MD on 791205.

 BTORR.J.P Region 2. Atlanta. Fuel Facility & Meteriais Safety Branch. 80/02/06
- --8003190529 Discusses IE insp of License 45-18378-01MD on 791206 & forwards notice of violation.
 BTOHR, J P Region 2, Atiants, Fuel Facility & Materials Safaty Branch. 80/01/18 2pp.
- --B003190537 Notice of violation from insp on 791216.Noncompliance noted: linearity tests not conducted on dose calibrators between Apr & Nov 1979 Records of rediation surveys performed on begs of syringes at disposal not recorded # Region 2. Atlanta. Office of the Director B0/01/18, ip.
- BOO324003B Forwards on behalf of Nuclear Pharmacy. Inc. cashiar chack recivil penalty imposed par 800219 notice of violation to Eifreth Alley Apothecary in Philadeiphia. PA Will not challenge penalty. Situation will be corrected per anci.
 MCDONALD. M E Butin, Thayar & Browns. 80/03/10 5pp
- B003250232 Forwards reconstructed 1978 film badge summary rept Results of summary repts from RS Landauer Co & Sasris Diagnostic will be forwarded within next month Advises of move to new licensed facility.

 HUBER, S. A. Nucleer Pharmacy, Inc. 80/02/19, 3pp.
- BOO32800B7 Submits closeout radiation survey of facility under License 12-18044-DIND HUBER, B. A., DEBANTIS, N. Nuclear Pharmacy, Inc. 02B36 B0/02/14 & &ab.
- BOO4110323 Forwards results of closeout radiation survey for facility located at 770 Church Road, Suite F. Elmhuet, IL, under License 12-18044-01MD. DE SANTIS, Nuclear Pharmacy, Inc. 03125 80/03/07 Spp

- 8005090553 Informs of change in 790807 proposed corrective actions re IE losp Rept 30-15125/79-01. Instead of installing portal monitor in threshold area between ofcs & lab.plans to install permanent contamination survey station STEPHENS.C W Nuclear Pharmacy. Inc CMS-280-8 60/02/20 2pp
- 8003140027 Submits classout survey for facility authorized under License 12-17710-01 MD COMER.F M Pharmaco Nuclear, Enc 03545 80/04/18 5pp
- 8005230654 Ack receipt of full civil penalty payment imposed in NRC 800219 ltr & receipt of licenses 800310 ltr re corrective setions info on mgt controls & audit program expected by 800512 STELLO,V Office of Inspection & Enforcement, Office of the Director 80/04/07 ip
- 8005300691 Forwards IE Insp Rept 30-14386/80-02 on 800403 of activities under License 12-18044-01 No noncompliance noted DAVIB, A B Region 3. Chicago, Fuel Fecility & Materials Befety Branch 80/04/21 Zpp
- --8005300695 iE Insp Rapt 30-14386/80-02 on 800403 No noncompliance noted Major wreas inspected deconteminated radiopharmaceutical facility ADAM,U J. PAPERIELLO,G J. Region 3, Chicago, Office of the Director 80/04/15. 3pp.
- 8006120881 Forwards IE Insp Rept 30-1362280-01 on 800416 of ectivities under License 12-17910-01 MD No noncompliance noted DAVIS.A B. Region 3. Chicago, Fuel Facility & Heterials Sefety Branch. 80/05/07 2pp
- --8006120884 IE Insp Rept 30-13622/80-01 on 800416 No noncompliance noted Major areas inspected matis, facilities & equipment, receipt & transfer of matl/surveys & radioactive effluents & waste disposal.

 OBERG-C Y Region 3, Chicago, Office of the Director PAPERIELLO.C J. Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/05/06 12pp
- 8006240527 Submits info re reorganization of radiation safety program for Matl/Syproduct License 37-18461-01MD, in response to NRC 800219 & 0407 ltrs. Corrective actions to reduce radiation exposure listed. RCCLINTOCK, R O Eifreth Alley Apothecary 1037 80/05/05 3pp
- 8009020175 Responds to FDIA request for NRC Annual Rept on FDIA for 1977, 1978 & 1979 Forwards repts W/o encis FELTON, J M Division of Rules and Records 80/08/12 1p
- 8009020176 FGIA request for NRC Annual Rept on FGIA for 1977, 1978 k 1979. MGBB:L 8 Babson College 60/08/06 1p
- 8009020182 Responds to FDIA request for winning technical proposal & contract NRC-05-80-253 ewarded to Gassor Associates Forwards basic contract & nonproprietary version of technical proposal, summary of qualifications & experience H/o encis FELTON, J. M. Division of Rules and Records 80/08/12 ip
- 8007020185 F01A request for contract NRC-05-80-253 & Gasser Associates winning proposal submitted in response to RFP-RS-01E-80-253.
 "Automated Vandor Selaction Sys"

 EBERLEINF Control Data Corp 80/07/31 1p
- 800902049B Responds to FOIA request for paper entitled, "Intensified Nuclear Safaguards & Civil Libartiss." prepared under Contract AT(49-24)-0190 Document is available in PDR FELTON, J. M. Division of Rules and Records 80/08/19 ip
- 8007020505 FOIA request for paper antitled, "Intensified Nucleer Bafeguerds & Clvil Liberties," prepared under Contract AT(47-24)-0190 ORDSSMAN.K island Closeup News Servics 80/08/11, 1p.
- 8007080123 Add1 response to FBIA request for records partaining to proposed fire protection rule FELTON, J M Division of Rules and Records, 80/08/05 ip
- --B009050124 Forwards Sandia Labs 790919 & 0904 memos re fire protection in nuclear plants & BECY-79-478 updating status of NRC actions in response to UCB patitions.

 HANAUER. B. H. | TKI-2 Unresolved Safety Issues 79/11/08 5pp

- --8009050131 BECY-79-478
 Informs Commission of present status of NRG actions in response to USB getition for emergency & remedial action & petition for reconsideration Seven items have been completed DENTON.H R Office of Nuclear Reactor Regulation, Director 79/08/08 4pp
- 8009050402 Forwards atd order for DDE work, "Geoscience Cass Reviews 11." ECHROEDER, F Division of Systems Safety FIN A-7118-9 79/09/18
- --8009050412 Std order for DOE work. "Geoscience Case Reviews II." issued to LABL Beatsment of work encl.
 TRIPLETT.M P Division of Systems Safety FIN A-7118-9
 20-79-192 79/09/17 Bpp
- 8009050455 Submits list of RMSS away-from-reactor spent fuel cases Included in budget. Budgeted resources are adequate to satisfy DGE requirements SARRY,L H Office of the Controller 78/08/10. 1p
- ---8009050452 Discusses BDE 771018 press conference on new spent fuel policy Includes briefing highlights Final text of DDE public announcement sucl FOUCHARD, J Office of Public Affairs 77/10/18 5pp
- B009030491 Responds to FOIA request for 47 documents concerning QEBMO. Forwards 28 documents listed in App A.Remaining 19 documents cannot be located M/c encis FELTON.J M Division of Rules and Records. B0/08/18 4pp
- --8009230141 BECY-75-338

 Recommends that Commission approve correspondence w/
 concerned parties to obtain clarification of comments on
 750508 FR notice re provisional view on Pu recycls
 CHAPMAN.K R Office of Nuclear Material Sefety & Befeguards
 75/07/03 5pp
- ---S009230145 Responds to SECY-75-338 re comments received during Purecycle proceedings. Recommendation should be accepted w/caution Request for clarification will delay comment procedures
 STRAUSB.P L. Office of the Osneral Counsel. 75/07/09. 2pp
- --8009230156 Informs that QESHO comment logs were delivered to Commission as requested by MA Rouden at 750811 Folicy Session 75-42 CHILK, B. J. Office of the Secretary of the Commission. 75/08/11
- --8009230159 Notifies of 750902 meeting w/ERDA to Pu recycle as requested at 750814 Policy Session 75-45
 CHILK: 8 J Office of the Secretary of the Commission. 75/08/20.
- --8009230164 Forwards compromise schedule for comment review on Purecycle provisional views
 CHILK-B J. Office of the Secretary of the Commission, 78/08/20
 400
- --8009230176 Discusses issue of providing guidence to NRC staff concerning specific alternatives for further enalysis of Purecycling, Recommends that final guidence be transmitted in written form to minimize possibility of misinterpretations. HUBERMAN, B. Commission 75/09/12. 3pp
- --8009230183 Fowerds corrected pages revising staff paper re issues & alternatives concerning Pu recycle provisional views.

 LCHENBERG.H Assistant Director for Operations & Technology. 75/09/12. 28m.
- ---8009230187 Discusses B Huberman 780912 memo re providing guidance re Pu recycle. Lists four assumptions implicit in analysis Advises that discussion be held MASON. E. A. Commission. 75/09/17, 1p.
- --8009230190 Discusses staff paper on Pu recycle -- final decision procedures & interta licensing Requests decision re whether range of reasonable alternatives is unduly restrictive, HUBERMAN.B. Commission. 75/10/07. 2pp.
- --8009230195 Draft Commission paper providing Commission w/elternatives to facilitate formulation of views on procedures for reaching decision on widescale use of Pu recycle in LWRs & on interio actions.

 CHAPMAN, K. R. Office of Nucleer Material Safety & Bafeguards 735/10/07. 141pp

- --8009230201 Discusses Commission agenda re procedures for reaching final decision governing widescale Fu recycle in LMRs & interim licensing of Pu facilities Discussion topics encl. MAGON-E A. Commission 70/10/08 9pp
- --8009230170 Forwards draft staff paper presenting issues & alternatives re provisional views concerning upcoming Pu recycle decision.

 CHAPMAN, K.R. Office of Nuclear Material Bafety & Bafaguards
- --8009230206 Discusses need for hearing in QESMO & procedures to expedite hearing. Binca QESMO is policy decision, legislative proceeding is more appropriate REISS.L A Commission 75/09/05. Spp.
- --8007230207 Discusses treatment of licensing.pending final Pu racycle decision. Continuing licensing actions is consistent w/past judicial interpretations & AEC/NRC practice WEIBB.L A Commission 75/09/05. 4pp.
- --8009230213 Discusses scope of licensing activity, panding outcome of QESKO proceedings Individual licensing applications & reviews should be allowed through final decision, subj to reasonable policy of restraint WEISS.L.A. Commission 75/09/05. 2pp.
- ---BOO9230218 Discusses procedures NRC may employ to expedite GESMO hearings Hearings will be very complex Commission should adopt comprehensive scheme to deal w/all foreseable occurrences
 WEISPS.L. A. Commission 75/10/06. Sinc.
- --8009230224 Documents statements made at meeting re decision concerning procedures for reaching final decision on DEBMO. Authorizing widescale use of Pu will involve litigative risks STRAUSS.P.L. Office of the Oeneral Course. 75/10/14 Bpp.
- --8009230229 Draft Commission paper providing Commission w/addl alternatives for interim licensing of Pu rocycle plants.Addl info re interim licensing of reactors using Pu recycle fuel & environ inpact will be forwarded. BMAPAR.H K Office of the Executive Legal Director. 75/10/15. 1300.
- ---8009230232 Forwards draft instructions covering content of FR notice & add1 back-up mat1 re Pu recycle in response to Commission request Also forwards tentative achesule of activities leading to 751030 date for publicizing FR notice, HALLER'N Commission. 75/10/15. 4pp
- --8009230234 Draft Commission paper forwarding draft FR notics to scope & procedures for generic Pu recycle environ statement & interim licensing actions

 SHAPAR,H. K. Office of the Executive Legal Director. 75/10/20, 42pp
- ---8009230238 Summarizes V Gilinsky views on draft GESMO FR notice, Term "person" to refer to those commenting is inaccurate, "Retrospective implementation" or similar phrase might be substituted for "backfitting"

 BPECTOR. L S Office of the Executive Legal Director, 75/10/22, 5pp
- --8009230251 Comments on encl draft FR notice of Pu recycle decision.
 Notice should be prefaced by summary which sets out purpose,
 states objectives of decision & describes what is being
 decided, N/A encl draft FR notice
 KENNEDY, R T Commission 75/10/22, 2pp,
- ---BOO9R30254 Expresses appractation for collating Commission comments on draft FR notice. Requests preparation of document to support schadule mentioned in FR notice.

 MABON, E. A. Commission. 75/10/24, lp.
- ---8009230260 Comments on interim licensing of Pu recycle facilities. Supports Commission position re licensing other Pu fuel cycle facilities on interim basic per eafequards rules to be proposed following publication of DES 01LINSKY.V. Commission. 75/10/24. Spp.
- ---B009230266 Forwards revised draft FR notice re scope & procedures for generic Pu recycle environ statement & interim licensing actions Draft FR notice reflects input of Ofce of General Counsel.Policy Evaluation & Executive Legal Director, BMAPAR:H, M. Office of the Executive Legal Director 75/10/29. 42pp

- --B009230268 Forwards revised draft FR notics re scope & procedures for generic Pu recycle environ statement & interim licensing actions. Revised FR notice reflects input of Ofice of General Counsel, Policy Evaluation & Erecutive Legal Director BMAPAR.H K Office of the Executive Legal Director 75/11/03.

- ---B0092302B3 Responds to 75110B request for supplemental info re draft FR natice. Forwards planning schedules impact value considerations & comparison of impact from NRC & AEC procedure schedules for decision re use of mixed oxide fuel. CHAPMAN, K.R. Office of Nuclear Naterial Bafety & Safeguards 75/11/10. 10pp.
- ---B009230289 Discusses use of words "criteria", "enfequards regulations" & "setsguards requirements" in draft FR notice Te Fu recycle.Lists ways in which terms should be defined in FR notics to sliminate possible confusion glLNSXY,V. Commission 75/11/07, 2pp.
- --B009230291 Forwards discussion paper rs Pu recycle provisional views.
 Paper shows revisione suggested by Ofc of Executive Legal
 Director M/o encl.
 106MENGERO, M. Assistant Director for Operations & Technology
 75/09/11. 1p.
- 8009050492 FOIA request for 47 documents concerning OESMO Descriptive list enti. METLAY.D. Indiana Univ 80/04/16 App
- BOOTOBO25: Responds to FOIA request for L Bickwit 7910iB memo, adequate protection of health & safety of public Forwards msmo, FELTON-J. H. Division of Rules and Records 80/08/05, ip.
- BOO9080236 FOIA request for L Bickwit 791018 memo re adequate protection of health & safsty of public BIELAMEKI, A Isham, Lincoln & Bsais, 80/07/16, 2pp.
- 8000080238 Addl response to FOIA request for existing regulations radisposal of high & low isvsi wasts. Forwards SECY-79-580 discussing procedural aspects of disposal of high level radwaste in geologic repositories M/o snci FELTON.J. M Division of Rulss and Records. 80/08/05 ip
- 8007070348 Responds to 710722 itr transmitting calculation of thyroid dose for LOCA, Lists two assumptions in calculational model accounting for computed thyroid doses above guidelines. "Methyl lodide Fraction in Containment Atmosphere" encl. PORRIB. P. A. Atomic Energy Commission, Directorate of Licensing. 71/10/04, 8pp.
- BOOTHIO286 Responds to FOIA request for winning proposal, "Effects of Bhift Menning Strategies on Nucisar Operator Performance," awarded to Biotechnology, Inc under NRC-03-80-147. Forwards nonpropristary version of proposal. FELTON-J.M. Division of Rules and Records. BO/07/04. ip.
- --B009110296 Forwards proposal in response to RFP to "Review & Interpret RBD Literature Relevant to Staffing Requirements for Control Room Operations." Includes technical & cost proposals & fully executed Btd Form 18
 BHANAHAN.W.P. Bio-Tec. Inc. B0/08/18, ip.

- --8009110302 Response to "Effects of Shift Manning Strategies on Nuclear Operator Performance" under NRC-03-80-147 Includes introduction: unique qualifications of company, technical approach & staffing # Bio-Tec. Inc. NRC-03-80-147. 80/09/18 17pp
- BO09110291 FOIA request for winning technical proposal. "Effects of Bhift Hanning Btrategiss on Nuclear Operator Performance." awarded to Biotechnology Inc under NRC-03-B0-147. RUTHERFORD, J F BDM Gorp BDH/H-JFR-6315. B0/08/22 ip
- 8009110335 Responds to FDIA request that specific listed documents be placed in PDR D9 Eisenhut 760302 memo to K Goller will be placed in PDR FELTON.J M Division of Rules and Records 80/09/04 ip
- --8009110347 Forwards topical rept evaluation of NEDE-21156, "Suppl Info for Plant Mod to Eliminats Bignificant In-Core Vibration " EISENHUT.D Q. Division of Operating Reactors 76/03/02 2pp
- --8009110351 Topical rept svaluation of NEDE-21154, "Suppl Info for Plant Mud to Eliminate Significant In-Core Vibration " Mods are acceptable * Office of Nuclear Reactor Regulation, Director. 76/02/28.
- 8009110339 FOIA request that encl listed documents be placed in PDR CONNOR.L Doc Swarch Associates 80/08/13. 2pp
- 8009110354 Responds to FOIA request for released portions of IE manual change notices, beginning w/Change Notice 80-03 Forwards documents. W/o entis FELTON, J H Division of Rules and Records 80/09/05. In
- 8007110336 FDIA request for released portions of IE manual change notices; beginning w/Change Notice 80-03 JOHNBON; J H Carolina Power & Light Co GGA-80-227 80/08/27 1p
- BO09:10359 Responds to FOIA request for documents re-granting of License 45-00034-26 to Univ of VA. Forwards documents listed in App A W/o encls. FELTON:J M. Division of Rules and Records. BO/09/05. 2pp
- 8009110361 FOIA request for documents is granting of License 42-00034-26 to Univ of VA BEEGLE.C.W Affiliation Unknown, 80/08/19. 2pp,
- 8009110527 Responds to FDIA request for details of spent fuel rod transportation from San Unofre, CA to Morris, IL, including emergency & evacuation plans Forwards one page tabulation of spent fuel shipments & RUREG-0535, M/o ench NUREO.

 FELTON, J. H. Division of Rulee and Records 80/09/08, ip
- --8009110533 "Bhipments of Spent Fuel from Sen Onofre,CA to Morris, IL. 790101-800825" " Commission 80/08/25 ip.
- 8009110531 FOIA request for details of spant fuel rod transportation from San Onofre.CA to Morris.IL.including emergency & svacuation plans.

 SHERIDON'S F. Affiliation Unknown. 80/08/13. ip
- B00911053B Responds to FOIA request for text, "Loe Alamos Primer," part of Los Alamos Project Document is under DDE jurisdiction Request has been forwarded to DDE for direct response, FELTON, J M. Division of Rules and Records. 80/09/09 ip.
- BO09110542 FOIA request for text. "Los Alamos Primsr." part of Los Alamos Project Document was declassified detween 1954-1964 MARKER,J L Affiliation Unknown. BO/09/04 19
- BO09110546 Responds to FOIA request for new control & accounting stds proposed by MRC for strategic BNM Proposed rule is being developed. Briefing charts re stds are available in PDR. FELTON.J.M Bivision of Rules and Recorde B0/09/08. ip
- 8009110849 FOIA request, submitted on behalf of NRDC, for new control & accounting stds proposed by NRC for strategic BNM Nucleonics Hk 800821 erticis citing proposed stds encl.
 HE188, E. R Sheldon Harmon & Weiss. 80/09/21. Spp.
- BO09110867 Add1 response to FOIA request for NRC file on WB Kessler Hemorial Hosp in Hammonton,NJ Forwards documents listed in App A. H/o encis. FELTON,J.H. Division of Rulss and Records. B0/09/08. 2pp.

- 8009:20586 "Analysis Summary in Support of Early Reactor Coolant Pump Trip " * Babcock & Wilcox Co 80/09/28 51pp.
- 8009120583 FOIA request for two documents concerning ECCS in B&W WEISS, E. R. Sheldon, Harmon & Weiss 80/08/21 ip
- 8009120591 Responde to FOIA request for Science Applications, Inc winning proposal under RFF RS-RES-79-200 Forwards nonproprietary version of proposal FELTON, J H Division of Rules and Records 80/09/02 ip
- --8009120597 Nonproprietary response to RFP RS-RES-79-200, "Riek Assessment Methodology Development for Waste Isolation in Deologic Hedia "Includes technical approach, statement of work, related experience & available resources & facilities B Science Applications, Inc. RG-RES-79-200 79/08/31
- 9009120594 FOIA request for Science Applications, Inc winning proposal under RFP RS-REB-79-200 ORHONDE:S Affiliation Unitnown 80/08/08, ip
- 8009150002 Responds to FDIA request for NRC records re organization, Mobilization for Survival Forwards documents listed in App A FELTON, J N Division of Rules and Records 80/08/26 2pp.
- --8009150004 "Btop Nuclear Exports to Philippines." Statement to NRC Commissioners & 790305 flyer re March on Washington and # Affiliation Unknown 80/02/15 4pp.
- --9009150005 NRC Announcement 48 re 790506 march from Ellipse to US Capitol & 790507 mass lobby day at Congress, DOE & NRC Demonstrators should be treated in courteous manner. QUSEICK, L. V. Office of the Executive Director for Operations, 79/05/03. 1p
- 8009150003 FOIA request for NRC records re organization, Mobilization Village Voice BO/07/28 fp.
- 8009130302 Responds to FOIA request for info re release of U herafluoride from Piketon, OH Oaseous Diffusion Plant & procedures & stds.concerning waste disposal, Request is under DDE jurisdiction & has been referred for direct response FELTON, J H Division of Rules and Records. 80/09/10. ip
- 9009150305 FOIA request for info re release of U hexafivoride from Piketon.OH gaseous diffusion plant & procedures & stde concerning waste disposal ZITO.N Affiliation Unknown 80/09/02 ip
- 800915036B Responds to FOIA request for rept, "Review of Delegations of Authority Bithin NRC " Document is available in PDR, FELTON J M Division of Rules and Recorde, 80/08/28 is.
- 8009150371 FOIA request for rept, "Review of Delegations of Authority Within NRC."
 FIDELL, E.R. LeBosuf, Lamb, Leiby & MecRae 80/08/12. 1p.
- 009170049 Responds to FOIA request for statistical summaries of personnel monitoring for radiation exposure at nuclear plants in BC.Forwards NUREO-0463, "Occupational Radiation Exposure" & five pages of 1978 summary repts. N/o NUREO FELTON: J. M. Division of Rules and Records 80/09/02. 80/09/02. 1p.
- SOO9170054 Excerpt from "Annual Summary Repts for 1976," Rept consists of personnel monitoring for radiation exposure at facilities in SC.

 # Affiliation Unknown RIS6276 79/12/07 3pp.
- 09170052 FOIA request for statistical summarise of personnel nonitoring for radiation exposure at nuclear plants in BC KITTRELL, J. O Affiliation Unknown 80/08/18 1p
- 109170057 Responds to FOIA request for documents provided on request of J McKeever re svaluations of cracks & reactor containment of J McKeever re symbolions of cracks & reactor containment problems for various sites. Forwards listing of requested documents per 800828 telcon, FELTON-J M Division of Rules and Records, 80/09/02, 300. Division of Rules and Records, 80/09/02, 3pp.
- BO09170059 FOIA request for documents provided on request of J McKeevsr re evaluations of cracks & reactor containment problems for various eites.

 CHONG, L. K. Affiliation Unknown 80/08/13 ip

- 8009170063 Responds to FOIA request for bidder invitation list for RFF R8-NRR-80-111 Forwards document FELTON, J M Division of Rules and Records. 80/09/02 is
- --- 8009170070 Provides list of applicante submitting proposals in response to RFP RB-NRR-80-111 DOUGHERTY.D. J. MENCZER,W B Technical Assistance Contracts Branch. BO/01/18 3pp
- 8009170065 FOIA request for bidder invitation list for RFP RS-NRR-80-PUSCHEL, H. A Consumers Power Co PUSC 33-80 80/08/14 is
- BOO9190299 Responds to FOIA request for 15 documents listed in bibliography of NUREQ-0625, "Rept of Siting Policy Task Force." Documents 6-B & 13 are available in PDR Forwards remaining documents. FELTON, J H Division of Rules and Records 80/09/04 1p.
- --8009190320 BECY-75-518 DO9190320 BECV-73-518
 Responds to Commission direction to develop alternative plans for revieion of code re power feactor siting regulations. Forwards diagram of scheduling network, makeup of study panel & study that ecope of work.
 MINDOUE, R B. Office of Standarde Development, Director. 75/09/12.
- --8009170326 Bummarizes 750611 briefing re adequacy of 10CFR100, Commission requested that staff devise more specific plan of action for proposed revision of code.Plan will return as golicy eession item CHILK: 8 J Office of the Secretary of the Commission, 75/06/12,
- --8009190358 Forwards SECY-75-286.concerning reactor siting policy. Issue is large & complicated NRC will prepare oral briefing to outline principal areas of concern & potential solutions.

 90881CK, U Office of the Executive Director for Operations 76/05/25 1p.
- --8009190366 BECY-76-286
 Forwards "Staff Review of Site Evaluation Policy & Practics." Recommends that Commission hold further discussione w/Directore of NRC ofcs to develop basis for decisions concerning future site evaluation policy.
 HIMDOUR, R. B. Office of Standards Development, Director. 76/05/23-4-1
- ---B009190370 "Steff Review of Bite Evaluation Policy & Practice "
 Commission 76/05/25. 55pp.
- --8009190377 Provides recommendations from review of siting policies for licensing nuclear facilities Recommends that criteria be developed for other portions of fuel cycle. Related documentation encl. KERR.W. ACRE Advisory Committee on Reactor Sufeguards 75/12/10. 35pp
- --8009190383 Informs that Commission has reviewed BECY-75-518 rs reactor siting. Program described re development of policy paper is not fully consistent w/intent of Commission directive Lists Commission requests re program ANDERS, M. A. Office of the Executive Director for Operations. 75/10/30 3pp
- --8009190386 Discusses review of 760301 memo re reactor site evaluation to practice. Paper needs significant improvement in defining further actions & providing basis for Commission decision on those actions
 HUBERMAN. B. Office of Policy Evaluations. 76/03/19. 1p
- ---8009190390 Discusses review of reactor site evaluation policy & practice. Review is well written & makes persuasive statement for thorough revision of existing site evaluation policy. Proposed actions re existing policy issues encl.

 BTRAUSS, P. L. Office of the General Counsel. 76/04/01, 13pp
- --B009190394 SECY-76-286A NOTIFUGIPA SECY-76-286A
 Requests Commission approval of development plan for nuclear facility siting policy & practice revision. Recommends that Commission approve proposed plan & direct staff to proceed w/programs Related documentation encl.
 MINDOUE.R. B Diffice of Standards Development, Director, 76/12/14
- -9009190397 Forwards commente on development plan for nuclear facility siting policy & practice, Requests that comments be reviewed, modified commented on & summarized. REPRITA Office of the Executive Director for Operations. 76/11/23. 1p

- --B009190400 Discusses development plan for nuclear facility siting pelicy & practice revision Principal concern is whether NEPA considerations will receive adequate attention BTRAUSS, P.L. Office of the General Counsel 76/11/23 2pp
- --BO09190464 Comments on 761103 draft of "Development Plan for Nuclear Facility Siting Policy & Prectice Revision " Draft is not adequate response to Commission 760830 guidance Ofc of Stds Development response encl. HUBERMAN, B Office of Policy Evaluations 76/11/11 13pp
- --BOOT190470 Provides Commission comments on SECY-76-286 re reactor sits avaluation policy study Rept provides valuable partial background for sits evaluation policy formulation Lists benefits of cohesive explicit siting policy CHILK, B.J. Office of the Becretary of the Commission 76/08/31
- --B009190480 Responds to 760831 request for comments on Commission review of BECY-76-286, "Staff Review of Reactor Sits Evaluation Policy & Practice "Ofc of Stds Development will produce program plan re reformulation of siting policy.

 HINDOUS.R.B. Office of Standards Development. Director 76/09/24
- ---BO09190484 Recommends public release of SECY-76-286 & BECY-76-286A on siting policy & practice Requests review & concurrence in placement of documents in PDR. MINOOME, R B. Office of Standards Development, Director 77/03/02. Zpp.
- of Ceneral Counsel

 SHAPAR, H. K. Office of the Executive Legal Director 77/03/18.
- --8009190307 Forwards updated program outline & echedule of development plan for nuclsar facility siting policy & practice Status rept on extending scope to include fuel cycle facilities encl MINDQUE, R.B. Office of Standards Development, Director 77/04/15
- -- #009190514 SECY-77-288 009190514 SECY-77-203 Forwards proposed general policy statement on nuclear reactor site evaluations. Recommends that Commission provide guidance on proposed policy statement & directive re development of replacement regulation. HINDOUE, R. B. Office of Standards Development, Director. 77/06/07
- -- 8009190520 SECY-77-298 NO9190520 SECY-77-208
 Comments on general policy statement re nuclear reactor site evaluations. Paper is inadequate & does not set forth range of options open to Commission Possible legal problems exist w/general policy Statement approach as proposed KELLY, J. L. Diffice of the General Counsel, 77/06/02, 3pp.
- --- 8009190526 Forwards comments on 770527 draft of "General Policy CONTITUONS FORWARDS COMMENTS ON //UDX/ GRAFT OF "GENERAL POIL STATEMENT ON NUCLEAR REACTOR BITE EVALUATION POIL(y." General approach is inadequate for Commission decision regeneral reactor site evaluation policy TERRELLIN. Office of Policy Evaluations. 77/06/02 lipp.
- -8009190532 BECY-77-433 DO9190532 BECY-77-433
 Businits policy statement on alternative eits evaluations under NEPA for nuclear generating stations, Recommends that Commission require review & approval of applicant site selection process prior to acceptance of CP application MINDOUE, R. B. Office of Standards Development, Director 77/08/16.
- --B009190539 Comments on draft of "Policy Statement on Alternative Site Evaluation Under NEPA for Nuclear Stations," Paper is suitable for Commission review, Value of paper could be enhanced by enci comments.

 PEDERSEN.K. Office of Policy Evaluations 77/07/18. App.
- --B009190546 Comments on proposed policy statement on evaluation of alternate sites. Policy statement does not clearly identify how Commission will act to enforce stde. Related documentation encl. KELLEY, J. L. Office of the General Counsel, 77/07/25. Spp.
- --8009190550 BECY-78-371
 Reviews BECY-77-288, "Oeneral Policy Statement on Nuclear Fower Reactor Site Evaluations," Recommends approval of general statement of current policy on nuclear power site evaluations for publication in FR & draft ltr.
 MINDOUG, R. B. Office of Standards Development, Director, 78/07/03.

- --8009190597 Lists Commission requests for further action to be taken on SECY-77-288 concerning siting policy & practice Four siting policy issue papers should be forwarded to Commission as proposed in schedule CHILK.8 J Office of the Secretary of the Commission 77/06/30
- -8009190368 Comments on general policy statement on current nuclear reactor site evaluation Liste items which should be considered before statement is adopted a published Ofc of Btds Development responses encl BHAPAR.H K Office of the Executive Lsgal Director 78/05/08
- --8009190387 BECY-79-362
 Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants, for determination of site acceptability & adequacy of engineered safety features
 MINCOUE, R B Office of Standards Development, Director. 79/06/04
- --8009190612 Draft Reg Quide 88 724-4, "Atmospheric Dispersion Models for Potential Accident Consequency Assessments at Nuclear Power Plants."
 - Office of Standards Development, Director, 79/06/04 29pp
- ---8009190424 Draft value/impact assessment of proposed Reg Guide 88 724-4, "Atmospheric Dispersion Hodsls for Potsntial Accident Consequence Assessments at Nuclear Power Plants " Reg guide should be developed. Documentation encl * Office of Standards Development, Director, 79/06/04. 34pp
- 8009190313 FOIA request for 15 documents listed in bibliography of NUREQ-0625. "Rept of Biting Policy Task Force " DAVIS.R J NUS Corp E80-80-170(EC). 80/09/15. 2pp.
- 8009190614 Add1 response to FOIA request for nine categories o documents re ACC amend to 10CFR50 57(c) proposed on 701028 & adopted on 710514, Forwards documents lieted in app FELTON, J. M. Division of Rules and Records.
- --8009190634 Forwards 10CFR50, "Authorization of Low Power Operation." Requests publication, MCCOOL,W.B Atomic Energy Commission 71/05/10 1p
- --8007190638 "Authorization of Low Power Operation," 10CFR50 effective rule Proposed amends define extent of preoperational activities which could be conducted prior to issuance of OL & provide for authorization of low power testing, HOBBS,F.T Atomic Energy Commission 71/05/03. Spp
- --B009190642 Discusses proposed rule 100FR80 re authorization of low power operation Commission should adopt rule in affective form. Adoption of proposed amend re flust loading under CP is not recommended Draft FR notice encl.

 PRICE, H. L. Atomic Energy Commission 71/04/21 itop
- --- 9009190647 Forwards draft FR notice re proposed rule 10CFR50, "Licensing of Production & Utilization Facilities" & public announcement, Proposed rule provides for operation during pending OC proceedings, FR notice only enci.
 PRICE, A. L. Atomic Energy Commission 71/04/13 4pp.
- --8009190633 Bummary of 710115 Regulatory Info Meeting 445 List of attendace included Proposed amends to 10CFR50 & 2 reeffective date of initial decision authorizing issuance of OL approved, MCCOOL, W B. Atomic Energy Commission. 71/01/15. 2pp.
- --8009190668 Forwards comments on proposed rules 10CFR2 & 50 reeffective date of initial decision authorizing lesuance of
 GL Bone features of groposed rules, unless clarifies, could
 introduce further uncertainty into licensing processe
 GLEASON, O. L. Atomic Industrial Forum. 10CFR2. 70/12/31 23pp
- -8009190676 Comments on proposed rules 10CFR2 & 50 re effective date of initial decision authorizing issuance of OL Preoperational radiological monitoring programs should be completed prior to core loading & low power testing.

 # Interior.Dept of Fish & Hildlife Service. 10CFR2 70/12/18

- --B0091906B2 Responds to request for info re proposed changes in AEC regulations concerning definition of CPs & low power testing of nuclear facilities Provides details of proposed changes. Changes will aminaize licensing delays
 WWR.M M Atomic Energy Commission 70/12/03 3pp
- --BO091906BB Speech entitled "Reactor Licensing Delays in Perspective Froblems, Progress, New Directions" presented at AIF 1970 Annual Conference in Hashington.DC RAMEY.J T Atomic Energy Commission B-41-70 70/11/17 36pp.
- --B009170695 Forwards 700716 asso which supersedes 700707 memo re possible rule & legislativa changes concerning authorization of low power reactor operation Memo should be used as basis for Commission discussion M/O enci memo PRICE.H L Atopic Energy Commission 70/08/11 ip
- --B009190701 Bummary of 700717 Regulatory Info Mesting 414 List of meeting attendees included MCCOOL.W B Atomic Energy Commission 70/07/17 2pp
- 8009190629 FDIA request for nine categories of documents re AEC amend to 10CFR50 57(c) proposed on 701028 & adopted on 710314 BROMM H Hill Christopher & Phillips 80/08/07 2pp
- BOO9240012 Responds to FOIA request for nine categories of documents re AEC amend to iOCFR50 57(c) proposed on 701028 & adopted on 710514 Forwards documents listed in App A responding to Items 1-5 Bearch is continuing for addi records FELTON, J. M. Division of Rules and Records 80/08/21 2pp.
- ---B009240014 Bubmite questions for response re undue delaye in licensing procese Delays will disrupt efforts concerning development of peaceful uses of nuclear energy.Licensing delays are attributed to administrative obstacles PASTORE, J D Senate 71/03/09, 2pp
- -8009240016 Forwards responses to specific questions in 710308 ltr concerning delays in licensing process Expanding technological demands.strikes during constriats delivery of congenent parts & const problems cause licensing delays SEABORO.0 T Atomic Ensrgy Commission 71/04/27 15pp.
- ---BO09240018 Forwards draft notice of proposed rules 10CFR2 & 10CFR50. Proposed amends authorize nuclear fuel loading in reactor core w/o attainment of critical reaction & authorize Director of Regulation to issue license PRICE, H L Atomic Energy Commission 70/10/22 12pp
- --8009240021 Forwards FR notice re AEC proposed rules 10CFR2 & 10CFR50, "Rules of Practice" & "Licensing of Production & Utilization Facilities DLs " Requests publication.
 HCCOOL, H B Atomic Energy Commission 70/10/22 ip
- BO09240024 Notice of AEC proposed rules lOCFR2 & lOCFR50, "Rules of Practice" & "Licensing of Production & Utilization Facilities OLF," respectively MCCOOL, W B Atomic Energy Commission 70/10/20 Bpp.
- BO09240026 Approves proposed rules 10CFR2 & 50 discussed at Regulatory Info Meeting 421 re authorization of low power reactor operation regulations Proposed rules & legislative amend enci PRICE-H L Atomic Energy Commission 70/09/14 12pp
- -BCOP240041 Submits possible rule & legislative changes re authorization of lew power reactor operation regulations No showing of good cause would be required for authorizing low power operation W/proposed rules 10CFR2 & 50 & legislative amend PRICE.H L Atomic Energy Commission, 70/08/26 12pp
- ---BO09240047 Discusses possible rule & legislative changes re authorizetion of low power reactor operation Commission approved changes subj to comments by Commissioners Ramey & Thompson & deferred action for statutory change MCCOOL.W. B Atomic Energy Commission 70/09/22 ip.
- -- 6009240034 Recommends listed changes in AEC regulations re authorization of low power reactor operation CPs would authorize fuel loading short of criticality Proposed rules 10CFR2 & 50 & legislative amond enci. PRICE.H L. Atomic Energy Commission 70/07/16 11pp
- ---BOO9240039 Discusses proposed rules iOCFR2 & iOCFR50 re effective date of initial decisions authorizing issuance of ULs. Recommends that Commission adopt amends Comments on notice of proposed rulemaking encl.

 PRICE, H L Atomic Energy Commission iOCFR2 7i/O1/14 5pp.

- --8007240063 Comments on proposed rules 10CFR2 & 50.on hehalf of Bave New England. Commission should undertake thorough & comprehensive review of entire licensing scheme contained in proposed rule. w/full public hearing KESSLER. 0 Affiliation Unknown 10CFR2 70/12/20 11pp.
- ---8009240070 Comments on proposed rules 10CFR2 & 50 re effective date of initial decisions authorizing issuance of OLs. Change in procedures undercute congressional review procedures for objections to issuance of OL Draft FR notice encl.

 BUTLER: M A Environmental Defense Fund 10CFR2, 70/12/28. 7pp.
- ---B009240075 Forwards FR notice re rules 10CFR2 & 50 *Effective Data of Initial Decisions Authorizing Issuance of OLs * Requests publication MCCOOL, M, B Atomic Energy Commission 71/01/18 ip.
- --9009240086 "Effective Date of Initial Decisions Authorizing Issuance of OLs," 10CFR2 & 50 effective rule. Amend provides for immediate effectiveness of initial decisions authorizing issuance of OLs.

 HOBBS,F.T. Atomic Energy Commission. 71/01/15 4pp
- --8009240092 Forwards HL Price 710421 memo & info for Commission consideration at info meeting Includee draft notice of rulewaking draft ltr to EJ Bauser & draft public announcement.

 HCCOOL.M.B. Atomic Energy Commission.
- --8007240i08 Discusses progused rule 10CFR50 re authorization of lew power operation. Recommends that Commission adopt rule in effective form Draft notice of rulemaking. It to EJ Bauser & draft public announcement encl. PRICE, H L. Atomic Energy Commission. 71/04/21, 15pp.
- ---8009240ii3 Informs that Commission approved SECY-R 22i re preposed rule 10CFR50 concerning authorization of low power operation, MCCOOL, M.B. Atomic Energy Commission. 71/04/29 ig.
- --- 8009240117 Discusses indications of serious deficiencies in AEC procedural & administrative mechanism for licensing of nuclear plants. Requests that NRC investigate factors attributing to licensing delays.
 HOLIFIELD.C., HOSMER.C. Congress (Joint & Rotating Committees, etc.), 70/09/24 2pp.
- --8009240082 Responds to 700924 ltr sepressing concern about AEC procedural & administrative mechanisms for licensing nuclear plants. Forwards statement reviewing licensing record from 1957 to present & discusses efforts to improve process. SEABORG. O. T. Atomic Energy Commission. 70/11/27. Epp
- 8009240141 Responds to FDIA request for list of firms responding to announcement in Commerce Business Daily re NRC RFP-RB-NRR-80-138 Forwards document, "Bolicitation Document Distribution," containing firm names & addresses. FELTON, J. M. Division of Rules and Records. 80/09/10. ip.
- --8009240151 "Salicitation Document Distribution," Commission. 80/09/10. 10pp.
- BOO9240147 FOIA request for list of firms responding to announcement in Commerce Business Daily re NRC RFF-RB-NRR-BD-13B, "Technical Assistance in Support of NRC Reactor DL Action Program " STERN, A Al Stern Associates. BO/08/22. 1p.
- 8009230448 Responde to FOIA request for MRC responses to BH Hanauer 790406 memo, Forwards CF Hiller 790423 memo, FELTON, J. H. Division of Rules and Records, 80/09/16, 1p.
- ---8009250453 Discusses environ qualification & instrumentation to follow course of accident as result of TMI accident. Lists items which should be reconsidered HANAUER, S. H. Assistant Director for Plant Systems. 79/04/06 ip
- 8009250452 FOIA request for NRC responses to 8H Hanauer 790406 memo MEISB, E.R. Sheldon, Harmon & Weiss. 80/08/25, ip.
- B009250484 Responds to FOIA request for info re U mining & effects upon environ & people, repts on Natl U Resource Evaluation Program & Council of Energy Resource Tribes activities & repts of safety violations by TVA Forwards documents in app.

 FELTON, J. M. Division of Rules and Records. | 80709/15. 2pp.
- B009250486 FOIA request for info re U mining & effects upon environ & people, repts on Natl U Resource Evaluation Program & Council of Energy Resource Tribes activities & repts of safety violations by Union Carbide & TVA.

 FREEMAN, J Affiliation Unknown. B0/08/17. 1p.

- 9009270025 Responds to FOIA request for documents rs NRC Jan 1979-June 1980 into of facilities owned & operated by Pharmatopse. Inc Pharmaco Nuclear, Inc & Nuclear Pharmacy. Inc Documents 4-6 partially withheld individual names (ref FOIA Exemption 6) FELTON, J M. Division of Rules and Records 80/09/08 5pp.
- --8004290037 IE Insp Rspt 30-i3622/79-01 on 790926 & 1010 Noncompliance nutse.failure to svaluate extremity exposure for two questions, to perform monthly thyroid readings for ons person on several occasions & to perform weekly lab surveys PAUL.P.A., PAPERIELLO,C.J. Region 3, Chicago, Office of the Director. 79/10/24. 19pp
- --8009290041 IE Insp Rspt 30-15134/79-01 on 791128 Noncompliance noted failure to use gloves during generator elution.
 COSTELLO,F. M. Region 3, Chicago, Office of the Director MCCLINTOCK,R O. Region i, Philadelphia, Fuel Facility & Materials Bafety Branch. 79/12/04 iipp.
- --8009290046 Forwards IE Insp Rept 30-i339/79-01 on 791212 & notice of viciation.
 DAVID: A.B. Region 3, Chicago, Fuel Facility & Materiais Safety Branch. 80/01/02 ip.
- -- 8009290052 Notice of violation from insp on 791212 e Region S. Chicago, Fuel Facility & Materials Safety Branch. 79/12/27, 1p.
- --B009290064 IE Insp Rept 30-14826/79-02 on 790913. Noncompliance noted, failure to use springs shields to survey incoming packages & used lead containers. Dose calibrator checks unrecorded Info gartially withheld: individuals names (ref FOIA Examption 6). CAMPBELL.M , MCCLINTOCK.R.O. Region i, Philadslphia: Office of the Director. 79/09/10 22pp
- ---BO0927006B IE Insp Rspt 30-i4826/79-0i on 75020B Noncompliance noted: failure to verify license authorization for shipment of xs-153 to Oscar Hunter Memoriai Hosp & shipment to organization w/o license, D'NEILLEB, CLEMONS, P. Rspion 1, Philadelphia, Offics of the Director, McCLINTOCK, R.O. Region 1, Philadelphia, Fuel Facility & Materials Safety Franch 77/02/13, Ypp
- --- 8007270073 IE Inep Rept 30-14764/79-01 on 791206. Noncompliance noted: 3-yr linearity tests were not performed on calibrators. Byrings box surveys were not recorded, although syringss were stored for decay for min of 90 days before transferring MOODROFF, R. L. Region 2, Atlanta, Defice of the Director 80/01/02. 18ap.
- --B009290085 Mati/Suproduct License 12-01721-01 for Univ of Chicago is asseded in its entirsty per 730821 application. Amend 15 authorizes possession k use of 500 mGi of sach byproduct mati between Atomic Numbers 3-83 in any form.
 BOMYER. J. E. Atomic Energy Commission, Directorate of Licensing, 74/01/15. 3pp.
- --BOCG229087 IE Insp Rept GO-15125/79-03 on 791109. Noncompliance noted; failure to perform swipes of external container of incoming packages & to monitor boxes prior to delivering. Info partially withheid: individuals names (ref FOIA Examption 6). DAVIS, J., MCOINNIG, J.A., OLENN, J.E. Region 1, Philadelphia, Office of the Director. 79/11/21. 11pp.
- -BOOP270072 Draft IE Insp Rspt 30-15125/77-02 on 790828-31. No nencempliance noted Major areas inspected notification of incident; package history, visits to licenses, visit to Esderal Express Philadalphia station & Mamphis Station. BAVIS, J. S., JERMAN, P.C. Region 1, Philadelphia, Office of the Director, MCCLINTOCK, R. D. Region 1, Philadelphia, Fusi Facility & Materials Safety Branch, 79/10/05. App.

- --8009290006 Responds to 790829 notification that package of Xa-133 shipped by Federal Express had excessive radiation levels Forwards insp of Federal Express facility in Memphis.TN Dosage to any individual was minimal BUTHERLAND, J T Region 2. Atlanta, Fusi Facility & Haterials Bafety Branch. 79/09/07. 3pp.
- --8009270099 IE Insp Rept 30-15125/79-01 on 790618 Noncompliance noted failure to survey for radiation levals in unrestricted areas & to evaluate radiation overexposure to individual preparing doss w/o using suringe shield O'NEILL.8.. MCOINNIE! Region 1. Philadelphia, Office of the Director MCCLINTOCK.R.O. Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 79/06/28 lipp
- ---8009290102 Ack receipt of 800307 ltr re results of closeout eurvey of Elahurst. It. facility.
 DAVIS: A B Region 3. Chicago, Fuel Facility & Materials Bafety Branch 80/03/24. is.
- --8009270105 Ack receipt of 800219 ltr w/1978 film badge summary rept Clossout survey will be conduted in vacating of Elmhurst facilities, after receipt of consultant clossout survey. KEPPLER.J.O. Region 3. Chicago, Fuel Facility & Materials Bafety Branch. 80/03/17 ip
- --8009290111 Discusses 800214 closeout survey & NRC 800228 confirmatory survey. NRC survey results are consistent w/vendor results. Facility meste NRC discontamination guidelines. Approves facility release for unrestricted use

 KEPPLER. J G. Region 3. Chicago, Office of the Director 80/03/13
 ip
- --8009290113 Responds to 800125 notification of intended move NRC has no objections to proposed decontamination & decomplisationing procedures, NRC clossout survey will be conducted upon receipt of final survey & wipe test results.

 KEPPLER, J. Q Region 3, Chicago, Offics of the Director ip
- ~-B009290116 Ack receipt of B00123 ltr informing NRC of steps taten to correct violations noted in IE inep of License 12-18044-01MD on B00122 DAVIG-A B. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 80/01/31, ip
- --8009290122 Discusses consolidation of operations at one location Radioactive matls will be moved to second facility until Chicago facility is ready. No problems anticipated w/residual activity
 DESANTIB,N Nuclear Pharmacy, Inc. 80/01/25 2pp
- --8009290127 Responds to violations noted in IE insp of License 12-18044-01MD on 800122 Corrective actions:within 45-day extension will do everything possible to bring facility into compliance rs recordisaping & safety DESANTIS.N Nuclear Pharmacy, Inc. 80/01/23, 1p.
- --B009270140 Forwards IE Insp Rspt 30-15125/80-01 on 800103. GRIER.B.H Region 1, Philadelphia, Office of the Director B0/02/20. 2ps.
- ---8009290182 IE Insp Rept 30-18128/80-01 on 800103. Noncompliance noted, overexposure to extramitize of one individual & failure to use syrings shields during dispensing operations. HCCLINTOCK, R. O. HCCHNES, J., OLENN, J.E. Region i, Philadelphia, Office of the Director, 80/01/23 Spp.
- ---8007290156 Submite rept re overexposure of employee Inadvertent placement of ring badge in vicinity of glove disposal box is apparent cause of high exposure readings. Added precaution shall be taken to insure proper response to actual exposure. 'BROWNING.M. Nuclear Pharmacy, Inc. 100FR 020.405 79/12/28. ip.
- --8009290188 Forwards draft insp rept of 790131 & 0202 insp of License 12-18044-01MD. W/o encl. KEPPLER, J. O. Region 9, Chicago, Office of the Director, 79/08/21.
- --8009290163 Discusses IE insp of License 37-18461-01MD on 800122 & forwards notice of violation & notice of proposed imposition of civil penalties.

 STELLOV. Diffice of Inspection & Enforcement, Office of the Director.
- --8009270164 Notice of violation from inep on 800122.
 ** Office of Inspection & Enforcement, Office of the Director. 80/02/19. 1p.

- --9009290170 Notice of proposed imposition of civil penalties * Office of Inspection & Enforcement, Office of the Director 80/02/19 ip.
- --800929017A Requests 60-day extension on behalf of Nuclear Phermacy, Inc for responding to 790817 notice of violation Vandor would like to prepare effective, thorough written reply Excerpts from IE insp manual sncl. VAKERICS.T V O'Connor & Hannen. 79/08/29 Sipp
- 6009290027 FDIA request for documents re NRC Jan 1979-June 1980 insp of facilities owned or operated by Pharmatopss, Inc.Pharmaco Nuclear, Inc & Nuclear Pharmaco, Inc VEVE, M.E. D'Connor & Hannsn 80/06/30 2pp.
- 8009270414 Responds to FOIA request for listing of specific info re current contracts. Forwards list sntitled, "Contracts Executed in FYBO" FELTON, J M Division of Rulss and Records 80/09/10 is
- 8009290423 FDIA request for listing of specific info re current contracts.
 01LL0014.j J PRC Information Services Corp. 80/09/04 is
- 8009290443 Responde to FOIA request for NUREO-0654/FEMA-REP-1, 1964-65 revision of MASH-740, "Theoretical Possibilities & Consequences of Major Accidents in Large Nuclear Power Plants" & NUREO-0610, Forwards documents in app. W/o encis. FELTON, J M Division of Rules and Records. 80/09/22 2sp.
- 8009290449 FDIA request for NUREC-0654/FEMA-REP-1,1944-65 revision of HABH-740, "Thioretical Possibilities & Consequences of Major Accidente in Largs Nuclear Power Plants" & NUREC-0610 CAPANANA, 8 Affiliation Unknown. 80/09/07, 1p.
-)09300109 Responde to appeal rs denial of J Holiver FOIA request for rept. "Economic Evaluation of Alternatives." associated ltr & summary rspt Document is etill being withheld Forwards correspondence between NRC & Cincinnati Cas & Elsctric Co. FELTON.J M Division of Rules and Records. 80/09/11 1p.
- --8009300119 Responds to NRC request for addl info ra FDIA request for rept, "Economic Evaluation of Alternetives " Release of document could cause substantial harm to involved pertiss, NRC should deny appeal & continue to withhold rept. WETTERHAHN, M J. Conner, Moore & Corber, 80/02/15 2pp.
- --8009300126 Responds to NRC 791221 request for add1 info re FOIA request for rept. "Economic Evaluation of Alternatives " NRC should continue to withhold document info is significant to competitive poetitions Supporting documentation sncl. BORGHANN-E.A Cincinnatí Gas & Electric Co 80/01/11 7pp
- --8007300136 Requests response to questions to sid in NRC determination of whether Sargent & Lundy Engineers Rept 8L-2361, "Economic Evaluation of Alternatives." associated ltr & summary rept is exempt from public release under FOIA Exemption 4. CARR. J. C. Division of Rulse and Records 79/12/21 2pp.
- 8009300113 Requeste, on behalf of J Woliver, that NRC reconsider denial of FOIA request for Bargent & Lundy Engineers rapt. "Economic Evaluation of Alternatives." associated itr & summary rept. HEYER-K.A. Public Citizen Litigation Group. 80/06/27. 2pp
- 8009300284 Responds to FOIA request for listing of locations where nuclear matie are stored user or dumped in US. Forwards documents listed in App A & discusses four categories of nuclear wasts. Listing of agreement states only sncl. FELTON, J H Division of Rules and Records. 80/09/23 4pp.
- 8009300289 FDIA request for listing of locations where nuclear matter are stored used or dumped in UB BOSHORTH.Q.R Affiliation Unknown. 80/08/20 ip
- 8009300330 Responds to FOIA request for written rept & itr involving 800619 insp of Diagnostic Isotopss. Inc Forwards documents. Info partially withheld name oirthdate & social security number (ref FOIA Exemption 6) Wo encle.

 FELTON, J. K Division of Rules and Records 80/09/23, 1p
- 8009300333 FDIA request for written rept & 1tr involving 800619 insp of Diagnostic isotopes, Inc. INICK, E.J. Affiliation Unknown, 80/09/03 ip.

- GOO9300620 Responds to FOIA request for all notifications received by NRC re ehipment of radioactive matis through FL from Jan 1979 to present No documents have been located subj to request FELTON.J M. Division of Rules and Records. 80/09/16. 1p.
- 8009300624 FOIA request for all notifications received by NRC reshipment of radioactive matle through FL from Jan 1979 to present.
 WILLIB,R J. Florida Rural Legal Services, Inc. 80/08/01 2pp.

OEN TEC IS GENERIC TECHNICAL ISBUES

- 8009020519 "Evolution of Wake in Unstrady Flow & Transverse Forces," Unpublished memo. BARPKAPA.T A ## 1141111 Unknown 80/08/25 18pp.
- 8009030667 Forwards FR notice of issuance & availability of NUREO-O612, "Control of Heavy Loads at Nuclear Power Plants Resolution of Task A-36."

 CHILK: S. J. Office of the Secretary of the Commission 80/08/15, in
- --8009030669 Notice of issuance & availability of NOREO-0612. "Control of Heavy Loads at Nuclear Power Plants Resolution of Task A-36."
 EISENHUT, D. O. Division of Licensing. 80/08/12 4pp.
- 8009230430 Forwards nonproprietary version of NEDO-24798. "Mark II Containment Program.Caoreo Extended Discharge Test Rept." on behalf of Hart II owners group as part of Taek 8-5. BUCHMOLZ.R.H. General Electric Operating Plant Cuners Group. MFN-158-80 80/09/12. 1p.
- ---8009230431 NEDO-24798
 Nonpropristary version of "Mark II Containment Program, Caorso Discharge Test Rept"
 HDLAN.J., MINTZ.B., MUZZY.R J. Gensral Electric Co BONED282
 80/08/31 35pp
- 8009230472 Forwards nonpropristary version of NEDD-24811, "4T Condensation Decillation (4TCD) Test Program Final Isst Rept:" on behalf of Mark II owners group as part of Task A-17. BUCHHOLZ, R.H. General Electric Operating Plant Dwners Group. NEN 153-80 80/09/03. ip
- --8009230475 NEDO-24811 Numpropriatary version of "AT Condensation Oscillation (ATCO) Tsst Program Final Test Rept." BYAD.P.K., FITZBIHMONS,O., ROGERS,A E General Electric Co. BONED057, 80/07/31, 100pp.
- 8009300214 Summary of 800827 meeting w/nuclear industry representatives in BethesdasHD re resolution of differences that exist between NRC & industry approaches to component support fracture toughness problem.

 ENAIDER:R P. Systematic Evaluation Program Branch (Pre 791030), 80/09/10 Zipp

INSPECTION AND ENFORCEMENT

- 8005050055 1E Bulletin 80-07. Suppl 1, "BHR Jst Pump Assembly Failure," # Office of Inspection & Enforcement: Office of the Director. 80/05/03 1p.
- 8005050070 IE Circular 80-19, "Noncompliance W/License Requirements for Medical Licensees,"

 # Office of Inspection & Enforcement, Office of the Director 80/08/26. 3pp.
- 800619002B IE Info Notice 80-27, "Broken Stude on Tarry Turbine Steem Inlet Flange." # Office of Inspection & Enforcement, Office of the Director. 80/08/07, 2pp.
- 8006190036 IE Circular 80-20, "Changes in Safe-Slab Tank Dimensions."

 * Office of Inspection & Enforcement, Office of the Director.
 80/08/21 3pp.
- 8006190038 IE Circular 80-18, "10CFR50, 59 Safety Evaluations for Changes to Radwaste Trestment Sys."

 * Office of Inspection & Enforcement, Office of the Director 80/08/22 4pp

- 8006190040 IE Info Notice 80-31, "Maloperation of Gould-Brown Bovers 480 Volt Type K-6008 & K-DCN 6008 Circuit Breakers " # Office of Inspection & Enforcement, Office of the Director BO/68/27, 7pp.
- 8006190042 IE Bulletin 79-26, Revision 1, "Boron Loss from BWR Control Blades."

 * Office of Inspection & Enforcement, Office of the Director, 80/08/29 400
- 8006190044 IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipment of Redicactive Mat1 "
 @ Office of Inspection & Enforcement, Office of the Director (1997)
- 80C6190052 IE Bulletin 80-19. Revision i. "Failures of Marcury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " • Office of Inspection & Enforcement, Office of the Director. 80/08/15 3pp
- 9004190081 IE Circular 80-21, "Regulation of Refueling Crews" * Diffice of Inspection & Enforcement, Office of the Director, 80/09/10, 4pp
- 8008210419 EN-80-036.on 900811.order to show cause why license should not be revoked & order suspending license (effective immediately) are being issued. Action based on alleged items of noncompliance re double dosage for certain scans.

 BROCKETT.T.M., THOMPSON.D. Office of Inspection & Enforcement, Office of the Director 90/08/11. is
- 8009020501 PNO-I-80-122:on 800815.unplanned release of gaseous radioactivity from Unit 3 reactor bldg vent occurred. Release rate was 33% of Tech Spec limit. Caused by malfunction of Unit 2 offges sys during mods.

 OREENMAN.E. Region 1. Philadelphia. Office of the Director 80/08/15. 2pp.
- 9009100372 PNO-I-80-125:on 800829. Region i received inquiries about fire in commercial garbage truck which contained radioactive math. State of PA has dispatched radiological inspector No significant radiological hazard is expected.

 COSTELLO, F., BHITH, O.H. Region 1, Philadelphia, Office of the Director. 80/08/29 ip
- 90091R0214 PNO-V-80-066, media increase on rise Board of Bupervisors of City & County of Ban Francisco & other groups have been critical of EPA for delays in release of info on surveys of eas disposal sites off coast of CA. BOOM-M.E. Region 5. Ban Francisco, Office of the Director. BO/08/20. Zpp.
- 8009:80149 PNO-IV-80-028: on 800903, svc water flow to containment cooling coils failed to meet min flow rate required by Tech Specs. When compliance w/Tech Specs could not be demonstrated unit was shut down. Licensee is investigating.

 JOHNSON, M. D. Region 4, Dallas, Office of the Director. 80/09/04, 288.
- 8009190418 EN-80-039.on 800910.notice of violation & notice of proposed imposition of civil penalty will be issued, based upon alleged item of noncompliance re loss of radiographic exposure device.

 BROCKETY.T.W., THOMPBON.D. Office of Inspection & Enforcement, Office of the Director. 80/09/08, ip.
- 8009190600 FNO-IV-80-030 on 800905, during full power operation steem generator tube leak occurred, Leak was indicated by N-ib detector, offgas monitor & main stack monitor. Unit will be shut down approx two wks.

 JOHNSON, W. D. Region 4, Dallas, Office of the Director, 80/09/05, 1s.
- BO09190765 PNO-78-147; on 780818, one of six air compressors experienced massive failure resulting in rapid loss of control air pressure to all units. Caused by large hole in cylinder head. State of AL notified. Media attention enticipated. KLINGER, O., NOLAN, F., SNIEZEK, J. Office of Inspection & Enforcement, Office of the Director. 78/08/18, jp.
- 8009230655 PNA-BO-S3:on 800903.Medical Research Foundation.Inc.shipped 4 yiels of microspheres tagged w/Yb-90.Customer notified company of apparent tagging problem. Eight patients treated. OA will not reauthorize shipments w/o FDA verification. KERR.O.M.. MCORATH, J. R. Office of State Programs, Director. BO/09/1B. ip.

- 8009300048 EN-80-041 on 800918 notice of violation & proposed imposition of civil penalties will be issued Action based upon items of noncompliance re shipment of low specific activity radioactive mati RROKKETT.T.W. THOMPSON.D. Office of Inspection & Enforcement, Office of the Director 80/09/16 ip
- 8009300162 PNO-V-80-066 state & local govts in CA have been critical of EPA for delays in release of info re surveys of sea disposal sites on CA coast Inquiries received from media BDOK-H E Region 5. Ben Francisco, Fuel Facility & Materials Sefety Branch 80/08/20 2pp
- 8009300166 EN-80-042 on 800919 notice of violation & notice of proposed imposition of civil penalties to be issued to C Zimmerman MD Action based on two allsped items of moncompliance re loss of I-i31 capsule BROCKETT. T., THOMPSON D. Office of Inspection & Enforcement, Diffice of the Director. 80/09/17 ip
- 8009300190 PNS-80-003-on 800910, near Roanoke, VA truck carrying shipment of low enriched U was abandoned by driver because of two flat tires. Another driver & mechanic were dispatched to truck.

 JAMES, J W . BUSH, L. L . HONARD, E. M. Office of Inspection & Enforcement, Office of the Director 80/09/15 ip.
- 8009300600 PNO-I-80-127: on 800914, plant was shutdown when one of three seals failed on three reactor coolant gump Bhutdown expected to last until 800918. LAZARUS.W.J. Region 1, Philadelphia, Office of the Director. 80/09/15 ip

MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

- 8009080485 Ack receipt of ltr re GA of training programs. Study of operator training programs & methods for accrediting training institutions underwey RFP will be forwarded if need for GA program is established.

 COLLINS, P. F. Operator Licensing Branch. 80/08/14. 1p.
- 8009:00632 Forwards FR notice of Advisiony Committee on Medical Uses Isotopes 8008:19 public meeting CHILK-8. J. Office of the Secretary of the Commission 80/06/20 in
- --8009100635 Notice of Advisory Committee on Medical Uses of Isotopes 800818 public meeting re experience criteria for physician users & other related Issues HOYLE, J. C. Office of the Secretary of the Commission. 80/06/20.
- 8009110599 Discusses draft IE Builetin 80-21 re integrity of polymer coating for surfaces inside containment All plant sys which take suction from containment sump during accident matigation should be included in projected evaluation MICHELSON.C. Director's Office. IEB-80-21. 80/08/29. 2pp.
- 8009150447 Responds to request re funding for development of training programs for nuclear gower plant personnel. At present, training is responsibility of industry Study is underwey to determine if NRC should become involved.

 COLLING.P F. Operator Licensing Branch 80/08/26 if
- 8009170178 Responds to 800730 ltr requesting published repts on U mining & milling including repts on exploration & hazards involved Forwards draft GEI8 on U milling & NUREO/CR-0573 H/o encl.
 FISHER, B P Uranium Recovery Licensing Branch 80/08/24 1p.
- ---BO09170181 Requests repts on U mining & milling, including repts on axploration & hazards & NUREO-0511, PASSAKANI.B Affiliation Unknown BO/07/30 ip
- 8007190197 Recommends endorsement of research program, antitled "Bur Mave & Meteorological Measurements Along Coast of FL." BCHROEDER.F. Assistant Director for Generic Projects, REB-80-3 80/88/29 1p
- --8009170205 Forwards research proposal entitled "Burge, Have & Meteorological Heasurements Along Coast of FL." Requests return of signed memo if proposal is responsive to Ofc of Nuclear Reactor Regulation."

 BUDNITZ, R. J. Office of Nuclear Regulatory Research, Director RES-80-3 80/06/27. App.
- ---B007170211 Harked-up research proposal entitled "Hydrodynamic & Meteorological Measurements of High Wind Over Shallow Water Along Coast of FL " * Florida. Univ of. Oainssville. 80/03/31 16pp.

BO09220125 Responds to 800715 ltr requesting info re licensing delays of new nuclear plants TMI accident has delayed licensing activities NRC currently considering licensing three plants Forwards NUREO-0694 H/o enci DENTON.H R Office of Nuclear Reactor Regulation, Director 80/08/15 4pp

--8009220128 Requests info re nuclear plant licensing delays Nuclear power viewed as great benefit to country.

EEATTY, D Affiliation Unknown 80/07/15 1p.

8009290379 Forwards recommendations re OC of sieves used to test concrete & soil const metls Verification sieve conforms to requirements when received. Frequent visual checks by user & annual period checking recommended HAASS, W.P. Quality Assurance Branch. 80/09/03 2pp

8009270498 Submits check list for issuance of facility licenses Includes required findings, license conditions & requirements preraquisite to licensing REIS, E. J. Hearings Division 80/09/19 9pp

NUREO REPORTS AND RELATED CORRESPONDENCE

8008280370 Forwards comments on proposed Revision 2 to BRP 3.7 6. value/impact statement & NUREG-0677. UTLEY.E. E. Carolina Power & Light Co. NO-80-1123. 80/07/30. 12pp.

8009020023 Discusses schedule for Alternate 2A ATMB plant mode proposed in Draft Vol 4 of NUREQ-0460, Proposed schedule unrealistic due to non-ATMB mode Preliminary schedule of 3 5 yrs reached w/Middle South Bycs is more realistic.

SHERWOOD, 0.0 Qeneral Electric Co MFN 146-80. 80/08/22 2pp.

800902016: NUREO/CR-1607
"Prop-Size Estimates for LOCA."
"ESTEL,A , OIDO,R.O , LAPKIN,D.E Los Alamos Beisntific Laboratory.
"N A-7105 LA-8447-MS. 80/08/31, 31pp. Available at GPD.
"N. 100 CARROLL ST. 100 CA

0294 Comments on proposed revision to SRP Section 3.9 6, ervice Testing of Pumps & Valves. Document does not titute viable testing program, in present for LEGUD.L. Commonwealth Edison Co. 80/07/31. 4pp

O316 Submits review of draft NUREQ-0676 re proposed nuclear data .Recommends that specific provisions re determining ential for breaching barriers to radioactivity release & litoring site meteorological data be added EALY, H O South Carolina, State of 80/08/27, 2pp

J9020349 NUREO/CR-1377

"Risk Methodology for Gaologic Disposal of Radwaste:
Transport Model Sensitivity Analysis."

CAPPBELL, J E., IMAN.R.L. Bandia Laboratories REEVES, M INTERA
Environmental Consultants, Inc. FIN A-1292, SANDBO-0644, B0/06/90
83pp Available at NTIS.

120355 NUMED/CR-1602
rength & Stiffness of Tensioned Reinforced Concrete
le Subjected to Hembrane Shear, Two-Way Reinforcing."
IKARIS.P.C. MITE.R.N. GERGELY, P. Cornell Univ FIN B-5698.
7/31 350pp. Available at NTIG.

0358 NUREO/CR-1482
lear Power Plant Simulators. Use in Operator Training & alification."
8.D N. BEER.D.K., FRANCIS, C.C. Dak Ridge National Laboratory.
8-0421-8, ORM./NUREO/TM-3 80/07/31 144pp. Available at

"361 NUREO/CR-1448
icai Protection of Nuclear Facilities, Guarterly
ese Rept Jan-Mar 1980, "
MANL D. Bandia Laboratories, FIN A-1060, BANDBO-1006
/31, 19pp, Available at NTIS,

373 NUREO-0540 V2 NO5 » List of Documents Hade Publicly Available, " 780, Vol 2, Number 5, fice of Afministration 80/05/31, 552pp. Available at NTIS

179 NUREO/CR-1392 satible Analysis of Inlet Plenum Pressure Rise Due to ofling in Fuel Subassemlies During Pump Coastdown

AH, HUMMEL,H. M. Argonne National Laboratory FIN A-2015, B. 80/05/31 21pp. Available at NTIS.

BOO9020483 NUREO/CR-1340

"State-of-the-Art Study Concerning Near-Field Earthquake
Oround Mction." annual rept.Sept 1978-Sept 1979
BHANGER.H. J. MURPHY.J R. SENMETT.T J. Systems. Sciences &
Boftware FIN 8-6491 868-R-80-4217. 80/08/31 148pp. Available

BOO9020519 "Evolution of Wate in Unsteady Flow & Transverse Forces," Unpublished memo.

BAPPAYA.T. Affiliation Unknown 80/08/25 18ss

8007030006 Comments on proposed Revision 2 to SRP 3.96. CURTIB.N.N. Pennsylvania Power & Light Co ASFR36236 011. ED/07/30 2pp

BOO7030012 Comments on proposed Revision 2 to SRP 3.9.A re inservice testing of pumps & valves:revision required due to inconsistency w/requirements of ABME code CROUSE:R P Totedo Edison Co. 45FR36236 00B, B0/07/25. 3pp

BOO9030014 Comments on proposed Revision 2 to SRP 3 9.6:improper forum for enumerating new requirements to be backfitted onto licensed facilities, Mandating generic change to specific facility before risk assessment is performed imappropriate OLBON-R C. Baitimore Oas & Electric Co 45FR36236 013 80/07/28.6pp.

8009030032 Forwards notice of availability of NUREO/CR-1580, "Draft Human Engineering Quide to Control Room Evaluation," for publication in FR CHILK, B J Diffice of the Secretary of the Commission. 80/09/15. 1e.

--BO09030055 Notice of availability of NUREO/CR-1580, "Draft Human Engineering Quide to Control Room Evaluation." TONDI,D Human Factors Engineering Branch. 80/08/12. 3pp.

8009030663 86-1120838-00 "Evaluation of Instrumentation to Detect Inadequete Core Cooling," prepared for 177 owners group FRDTH D Baccock & Wilcox Co. 80/08/15. 18pp

8009030667 Forwards FR notice of issuance & availability of NUREO-0612, "Control of Heavy Loads at Nuclear Power Plants - Recolution of Task A-36,"

CHILK, B J Office of the Secretary of the Commission, 80/08/15.

--8009030669 Notice of issuance & availability of NUREO-0412, "Control of Heavy Loads at Nuclear Power Plants - Resolution of Task A-36" EISENMUT.D Q. Division of Licensing. 80/08/12 App.

BOO9030671 NUREO/CR-1563

"Eddy-Current Insp for Steam Generator Tubing Program,"
annual progress rept for puriod ending 79:231.
DODD,C V. DEEDS.M., MCCLLWO,R W. Oak Ridge National Laboratory.
FIN B-04:7 DRNL/MREO/THI-. 80/07/31. 27pp. Available at NTIS

8009040437 NUREO/CR-1487
"Vital Area Analysis Using Set Equation Transformation Sys."
8TACK, D. N. FRANCIS, K. A. Sandia Laboratories, FIN A-1040.
80/05/31. 25pp. Available at NT18.

8009040487 Notice of aveilability of draft NUREO/CR-1580, "Human Engineering Quide to Control Room Evaluation." TONDI,D Division of Human Factors Bafety. 80/08/12. 3pp.

8009040461 BECY-80-253
Informs of Ofc of Nuclear Regulatory Research comments on ACRB rapt to Congress - NUREO-0557, "Review & Evaluation of NRC Safety Research Program for FYS1," Annual ACRS review is extremely valueble Specific comments encl.
BUDNITZR. J. Office of Nuclear Regulatory Research, Director. 80/05/19 50.

BOO9040485 Bubmits comments re draft NUREC-0578, "Clarification," per BOO815 meeting request. Discusses shift personnel education & training.
THOMAS,E L. Institute of Nuclear Power Operations. BO/08/27, 2pg.

8009050361 Forwards draft radiological emergency preparedness plan, addressing criteria in NUMES-0638, M/o enci.
DAVIDDFFD 8. New York, State of. 80/09/02 2pp.

8009050397 Transcript of 800820 workshop re emergency response facility hosted by Region 3 in Chicago, IL, Pp 1-238.

* Commission 80/08/20, 238pp.

8009050403 Transcript of 800819 workshop re emergency response facility hasted by Region 1 in Valley Forge, PA Pp 1-291 a Commission. 80/08/19. 291pp.

S009060092 NUREO/CR-1592
"Compressible Analysis of Inlet Plenum Pressure Rise Dum to Sadium Epiling in Fuel Subassemblies During Pump Coastdown of LHFER RALIMULAH, HUMMEL, H. H. Argonne National Laboratory. FIN A-2015. ANL-80-48 80/05/31, 22pp Available at NTIS

8004080402 NUREO/CR-1583
"Radon Release & Dispersion from Open Pit U Mine "
KJBIELEGKI, H.E. Argonne National Laboratory FIN A-2209.
ANL/EB-97 80/06/30. 74pp Available at NTIS

8007090020 NURE9/CR-1484
"Dynamic Analysis to Establish Normal Bhock & Vibration of Radioactive Hatl Shipping Packages," quarterly progress rapt Oct-Dec 1979.
[ELDB, R. R., MECH. S. J. Hanford Engineering Development Laboratory FIN 2-2263, HEDL-TME 80-24. 80/08/31. 33pp

BOOTO90639 Ack receipt of BOOS28 itr re NRC rulemaking on emergency planning for nuclear facilities & forwards final rules on energency planning.
AMEARMESULE Commission. 80/08/14 1p.

--8009090453 Comments on draft guidelines published as NUREQ--0610, "Draft Emergency Action Level Quidelines for Nuclear Power Plants." NRC should give more cognizance to programe & responsibilities of federal-state & local govt agencies. COX:F.T. Texae: State of 79/11/29 Spp.

--- 8009090662 Comments on NUREO--0654 re emergency response plans, Objects to provisions exemingly included for benefit of federal personnel reviewing state & local plane. COX.F.T. Texas: State of 80/05/13 7pp

9009090799 SECY-79-430

DOPOVOYY DELT-/Y-Sur Informs of Ofc of Nuclear Regulatory Research comments on ACRS rest to Congress — NUREO-0496, "1978 Review & Evaluation of NRC Safety Research Program " ACRS comments & recommendations useful Specific comments enci LEVING. B. Office of Nuclear Regulatory Research. Director 3370. 79/07/06. 26pp.

BOOGIOOGIA MUREO/CR-1185

*COMPARE-Mod I Code Addendum *
GIDO,R.O., MILLCUTT,O J.E., LUNSFORD, J.L. Los Alamos Scientific
Laboratory, FIN A-7109, LA-7199-MS ADDI. 80/08/31, 54pp
Available at NTIS. #3 25.

8009100043 NREO/CR-1625

*Steam-Nater Mixing % Sye Hydrodynamics Program - Task 4, *
quarteriy progress rept Jul-Sept 1979.
COLLIER'S P., DHORAK', A. FLANIOAN, L. J. Battelle Memorial
Institute, Columbus Laboratories. FIN A-4049 BMI-2038 B0/08/31.
125pp. Available at NTIB. \$4.75.

8009100033 NUREO/CR-1458 "Radiation Dose Estimates & Hazard Evaluations for Inhaled Airborne Radionuclidee," annual pregress rept Jul 1978-June 1979, MEMHINNEY, J.A. Lovelace Biomed & Environmental Research Institute. FIN A-1031. LF-71. 80/04/30, 96pp. Available at NTIS. \$5.25.

#2007100158 NUREO-0478
**Effects of Temp. Moleture, Concentration, Pressure & Hass
Transfer on Adsorption of Krypton & Xenon on Activated Carbon. "

CARDERHILL, D. W., MOELLER, D. W. ACRB - Advisory Committee on Reactor Safeguards. BO/08/31, 200pp.

B00+100403 NUREO/CR-1349

"Risctor Bafety Research Programs: " quarterly rept/Dct-Dec 1979. IYTY,
DOTBON,G.W. Battelle Memorial Institute, Pacific Northwest
Laboratory, FIN B-2041, PNL-3040-4, B0/08/31, 175pp, Available
at NTIE, X5.50.

BO06100407 NUREO-0453
"Rept on Nuclear Industry GA Procedures for Safety Analysis Computer Code Davelopment & Use,"
SHERON, I.W. Reactor Systems Branch, ROGITOCZY, Z. P. Equipment Qyslification Branch, 80/08/31, 163pp, Available at NTIS

B009100413 NUREQ/CR-1847

"Criticality Experients H/Bubaritical Clusters of 2.35 Ht% & 4.31 Ht% U-235 Enriched U Dioxide Rode in Mater at Hater to Fuel Vol Ratio of 1 6."
BIERHAN, S R . CLAYTON, E D Battelle Memorial Institute, Pacific Northweet Laboratory. FIN 8-2094 PNL-3314 80/07/31 38pp Available at NTI8

8009100944 NUREQ/CR-1347

NOPIOOP44 NUREO/CR-1347
"Thermacouple Signal Sensitivity to Sheath Thickness of
Thermal-Hydraulic Test Facility Indirectly Heated Electric
Fuel Pin Simulators"
DABBS: D., DTT.L. J. Gak Ridge National Laboratory FIN 8-0125
ORNL/NUREO-62 80/08/31 64pp Available at NTIS.

B009100947 NUREO/CR-1404

AVIOUSE MAKEVUK-1944
"Transient Analysis of Goolent Flow & Heat Transfer in
LHFBR Piping Eys "
MADNI, I.K Broothaven National Laboratory. FIN A-3015
BNL-MUREG-51179. 80/04/30 49pp Available at NTIS

8009100950 NUREO/CR-0803

"Risk Assessment of PHR for Clase 3-8 Accidente "
HALL, R.E. Brookheven National Laboratory, FIN A-3057
BML-NUREG-50950 79/10/31 494pp Available at NTIS.

8009100933 NUREO/CR-1521
"HYOR Bafety Studies for Div of Reactor Safety Research."
quarkerly progress rept. Jan-Mar 1980
BALL 8 J., CLEVELAND. J. C., CONKLIN. J. C. Dat Ridge National
Laborator, FIN B-0122 GRNL/MUREO/TM-3

8009100954 NUREO/CR-1450
"Multirad Burst Test Program," progress rept for Jul-Dec 1979. CHAPHAN, R. H. 1979. CHAPMAN,R.H Dak Ridge National Laboratory FIN 8-01: DRNL/NUREG/TM-3 80/08/31, 138pp Available et NTIS. FIN 8-0120

BOO9110321 NUREO/CR-1402
"Advanced Reactor Bafety Research Div," quarterly progress
rept,Oct-Dac 1977.
KOUTG-H.J.C., KATO.H Y., ROMANO,A.J. Brochaven National Laboratory.
FIN A-3015. BML-NUREQ-51177. B0/04/30 95pp Available at QPO

B009110372 NURE9/CR-0200 VI

NOVILOSIZE NOMEO/CN-0200 VI **Bleate, Modular Code Bye for Performing Standardized Computer Analyses for Licensing Evaluation: Scale Sys Criticality Safety Analyses Modulee CBASI & CRASE ** BUCHOLI, J. A., WESTFALL, R. H. HERMANN, O. H. Dak Ridge National Laboratory, FIN 8-0172, ORNL/NUREO/CSD-. 80/08/31. 305pp.

B009110500 NUREO/CR-0761

NOVILODOU NUREO/GR-0/01
"Extended Analysis of Data from 1/5-Bcale Mark I BWR
Pressure Suppression Experiment "
MCCAULEY,E W : HOLMAN,O.B., CARR,E.W. Laurence Livermore Laboratory
FIN A-0188-9 UCRL-52707 S0/07/d1. 293pp.

BOD9110303 NUMEO/CR-1516

"Nuclear Reactor Safety," quarterly progress rept
Oct - Dec 1977.

JACKBON J. F. BTEVENSON, M. Q. Los Alamos Scientific Laboratory
LA-8299-FR. 80/05/31. 154pp Available at NTIS

8009110639 NUREO-0436 NO1 Bi "Plan for Re-avaluation of NRC Policy on Decommissioning of Nuclear Facilities," CALKING. O. D. Office of Standards Development, Director. 80/08/31

9009120333 NUREO--0540 VZ NO6

Title List of Documents Made Publicly Available, " June 1990, Vol 2: Number 6. 1700/01 x.number o. **

Bivieion of Technical Information & Document Control. 80/08/31. 455pp. Available at NRC 48.50.

8009120336 NUREO/CR-1609
"Beterministic-Probabilistic Model for Containment
Transport." user manual
80HMMTZ:F W. CROME.A. COS, Inc. FIN 8-6693 COS/NR85U060
80/08/31. 166pp Available at NRC #5 50.

8009120337 NUREG-0479

MYTINGS / MARKEG-0679
"Pipe Gracking Experience in LWRs."
"Pipe Gracking Experience in LWRs."
"FRANK.L. Structures & Components Standards Branch HAZELTON W S.
Materiale Engineering Branch. HERMANN.R.A. Office of Inspection &
Enforcement, Office of the Director 80/08/31 Sipp. Available at
NRG. #2 25.

8009120338 NUREG/CR-1038
"Dynamic:Inelestic Buckling Analysis of Mark I Torus Support
Columns"
BENDA, B. J. Laurence Livermore Laboratory FJN A-0213 UCRL-52723.
80/08/31 65pp Available at NRC 63 50

8009120339 NUREO/CR-1120 V3
"Seismic Safety Hargins Research Program (Phase 1),"
Programs Rept 7, through June 1980, Vol 3
BAILEYJR D . BHITH, P. D . DONO, R. Q Laurence Livermore Laboratory
FIN A-0126 80/06/30 95pp. Available at NRC. 84 00

8009120628 NUREG-0718 DRFT
"Proposed Licensing Requirements for Pending Applications for CPs & Hfg Licenses," dreft rept for comment * Office of Nuclear Reactor Regulation, Director 80/08/31 86pp

8009120664 Reaffirms NRC position on incorporating Lessons Learned Short-Term Requirement 2 i 3 b in TMI action plan.
Instrumentation to guidelines for indication of inadequate reactor core cooling do not satisfy long-term requirement.
RDSS.D F Division of Systems Integration 80/09/09 2pp

8009150245 Provides addi comments on hydrogen control & improvement of containment capability Recommendations in ACRS 791213 ltr re reitability assessments & design features for core damage & core melt accidents should be adopted & given priority. PLESSET, M S ACRS - Advisory Committee on Reactor Befeguarde, 80/09/08 2pp.

8009150249 Discusses 245th ACRS meeting re final version of NUREO-0630, "Cladding Swelling & Rupture for LDCA Analysis." Implementation should be held in absyance until NRC revises code requirements
PLESETI.N. ACRB - Advisory Committee on Reactor Sefeguards.
80/09/09 2pp

8009150585 NUREO/CR-1608
"Scenario Development & Evaluation Re Rick Assessment of High Level Radwaste Repositories," final rapt, June 1979-June 1980 BCHMARTY, F W , DONATH, F A COS, Inc. FIN B-6693. CGB/NR85F060 80/08/31 98pp Available at NRC 44 00

009150595 NUREO/CR-1471
"Assessment of LHR Fusi-Failure Propagation Potential:
Literature Burvay "
CRONENBERO, A. SCOTT, J H Los Alamos Scientific Laboratory
LA-URBO-45-15, 80/08/31, 150pp, Available at NRC \$4.75

8009150397 NUREO/CR-1302
"Study of Pu Oxide Powder Emissions from Simulated Shipping
Container Leate"
"YESSO, J D. NADIA, H. J Battelie Hamorial Institute, Columbus
Laboratories SCHMENDIMAN.L. Battelle Memorial Institute, Pacific
Northwest Laboratory Fin 8-2093 PML-9278 80/08/31, 109pp
Available at NRC 94, 23

BOD9150599 NUREO/CR-1634
"Film Entrainment & Drop Deposition for Two-Phase Flow,"
informal rept.
KOESTEL, A., OiDO, R. O., QILBERTS, J. B. Los Aismos Scientific
Laboratory FIN A-7112 LA-8475-MS, 80/08/31. 26pp. Available at
NRC 41.75

8009160198 NUREO/CR-1933
"Fiow Topography Instrumentation & Analysis Sys "
CARY.C.N Crears, Inc FIN A-4070, TN-314, 80/08/31 45pp.
Available at NTIS. #3 30.

BOO9140202 NUREO/CR-0200 VI
"SCALE Modular Gode Sys for Performing Standardized Computer
Analyses for Licensing Evaluation, SCALE Sys Criticality
Safety Analysis Modules CSASI & CSAS2."
BUCHGLZ, J. A. Oak Ridge National Laboratory, FIN 8-0172,
ORNL/NUREO/CSD-. 80/09/31 450pp, Available at NTIS \$7.00

3009160446 NUREO/CR-1593
"Performance Testing of Personnel Dosimetry Svcs'
Alternatives & Recommendations for Personnel Dosimetry
Testing Program "
PLATO, P. HUDSON.O. Michigan, Univ. of FIN B-1049, 80/08/31.
55pp Available at NTIS \$3.50.

8009150450 NUREO/CR-1045
"Acute Effects of Inhalation Exposure to U Hexafluoride & Patterns of Deposition U Hexafluoride/U02F2 Studies in Experimental Animals.Rep Period/June 1978-Jul 1979."
HORROW.P.E., LEACH.L. J., SHITH,F A Rochester Univ. of FIN A-4083, 80/08/31, 114pp. Available at NIIB #4 25,

8009160456 NUREO/CR-1298
"Orouth & Histological Effects to Protothaca Staminea
(Littleneck Clam) of Long-Term Exposure to Chlorinated Salt
Water."
GIBSCN.C I , HILLMAN.R.E , HILKINSON.P. Bettelia Memorial Instituta,
Pacific Northweet Laboratory FIN 8-2098 PNL-3158, 80/08/31
84pp Available at NTIS \$3.75

8009160481 NUREO/CR-0893
"Acute Toxicity & Diosccumulation of Chloroform to Four Species of Freshwater Fish."
ANDERSON, D.R.: LUSTY, E.B.: Batteile Hemorial Institute, Pacific Northwest Leboratory. FIN 8-2098 PNL-3046 80/08/31. 54pp. Available at NTIS 83.50

8009160493 NUREO/CR-1539
"Methodology & Preliminary Data Base for Examining Health
Rieks of Electricity Generation from U & Coal Fuele."

* Dak Ridge National Laboratory EL-BASSIONI.A Science
Applications, Inc FIN B-0424-8 ORNL/8UB-7615/1. 80/08/31
592pp. Available at NTIS

8009180434 NUREQ/CR-1582 V3
"Seismic Harard Analysis, Solicitation of Expert Opinion,"
Vol 3.
BERNREUTER, D. L. Laurence Livermore Laboratory * TERA Corp. FIN
A-0233 80/09/31 16/7p Available at NTIS. 45.50

8009:80443 Forwards comments on proposed Revision 2 to SRP 3.9.6 Draft i, "Inservice Testing of Pumps & Vaives," App A to SRP 3.9.6 "Leak Testing of Pressure Isolation Vaives," Revision 0. Draft i & valve/impact statement for proposed App A LOOMIS,J.8 Bargent & Lundy, Inc. 45FR36236 016, 80/08/14, 2pp.

8009180446 NUREO/CR-1582 V2
"Beismic Haierd Analysis, Methodology for Eastern U8," Vol 2.
BERNREUTER, D.L. Lawrence Livermore Laboratory # TERA Corp FIN
A-0233. 80/08/31. 138pp. Available at NTB. \$4.75.

8009190398 NUREO/CR-1492
"Gualification Testing Evaluation Program LWR Bafety
Research," quarterly rept.Jul-Sept 1979.
BONZON,L L., OILLEN,K T. Sandia Laboratories. FIN A-1051-0
SANDB0-1117 80/07/31. 62pp. Available at NTIS

BO09190405 NUREO/CR-1358

"Vagetetional Cover in Monitoring & Stabilization of Shallow
Land Burial Sites," annual rept for Oct 1978-Sept 1979.

HALLACE,A., ROMNEY,E.M. N. NISHITAH California, Univ. of, Los
Angeles FIN B-3027-9, UCLA 12-1235 79/09/30. 132pp.

8009190672 Comments on proposed Revision 2.Draft i,to SRF 3 9 6. "Inservice Testing of Pumpe & Valves" CAMN.A.L. Bechts1 Corp. 45FR36236 004 80/07/24 2pp.

8009190677 Comments on proposed Revision 2 to SRP 3 9.6. "Inservice Pump & Valve Testing " Rephracing & clarification, as indicated, will be useful in development of pump & valve test programs. App A & value/impact statement should be withdrawn RENBERGER, D. L. Hashing ton Public Power Supply System 45FR36236 005. 80/07/23. 10pp.

8009190684 Comments on proposed Revision 2, Draft 1 of BRP 3.9.6, "Inservice Testing of Pumpe & Valves " Frequency of leak teeting should ref ABME requirements rather than having basis on percentage of design pressure, PATTI.F.J. Burns & Roe Co 45FR36236 014, 80/08/08 2pp.

BOOP190691 Comments on proposed Revieion 2 to BRP 3 9.6 re inservice testing of pumps & valves. AddI guidance should be provided to reviewer specifying pumps & valves to be included in inservice testing program.

ODODWIN, C. Portland General Electric Co 45FR36236 015 80/08/14.

9009190743 NUREO/CR-1509
"LUR Safety Research Program," quarterly rept Jan-Mar 1980.
BERMAN, Bandia Laboratories, FIN A-1019, BANDS0-1304/10F,
BO/07/31, 148pp. Available at NTIS,

8009190782 NUREC/CR-1527
"Enhancement of Nuclear Matl Mgt & Sefeguarde Sys," final rapt,
* Beeing Computer Services, Inc. (subs. of Boeing Co.), FIN B-6902-9, 80/08/31, 200pp. Available at OPD

BD09220219 Forwards comments on NRC draft criteria for util mgt & technical competence. Title should be changed to recognize distinction of document as being guidelines rather than criteria KEARNEY, J. J. Edison Electric Institute. B0/09/17. Opp

8009220275 Documents comments made at NRC 800827 meeting w/industry representatives or NVRE0-0577 NUREQ-0577 does not distinguish between integral & nonintegral supports Integral supports have had more restrictive requirements ANDERBON, T. M. Hestinghouse Electric Corp. NB-TMA-2304 80/09/09. Te.

9009220277 Comments on NRC Biting Policy Task Force rept.Retionale for selecting ain exclusion distance of 12.5 miles for all capable faults not clear Small faults which may be capable according to existing criteria may not be hazerdous VEATCH.M.D. Shannon & Wilson, Inc. 80/09/12 ip

B009240A05 NUREG/CR-1113
"Licensebility of CANDU-Type Reactors in UB," preliminary essessment of R&D requiremente CAVE.L. California, Univ of, Los Angeles FIN B-3004-9 UCLA-EN0-7953 B0/08/31, 110pp Available at CPD

BO09240886 NUREO/CR-1677 V1
"Piging Benchmark Problems: Dynamic Analysis Uniform Support Hotion Response Spectrum Method." Vol 1.
BEZLER.P. HARTIMAN.M., REICH.M. Brookhaven National Laboratory FIN A-3223. ENL-NUREO-51267 BO/OB/31 412pp Available at NTIS 49.00.

8009260028 NUREO/GR-1631
"Lateral Loads on Vent Pips in Steam Chugging"
CATTON.1., CHAN.C.K., DHIR.V K California, Univ of, Los Angeles
FIN 8-5875 60/08/31. 158pp.

BOC4240092 NUREC/CR-1579
"Considerations on Nuclear Deta Link Implementation in Relation to Technical Support CtriEmergency Operations Facility & Safety Parameter Display Sys."
STIFFELD, B. CEPPESEN, D. Sandia Laboratories FIN A-1239 SAND BO-1618. BO/07/31 29pp.

9009240191 Notice of extension of period for comment on draft NUREQ/ CR-1380, "Human Engineering Guide to Control Room Evaluation." TONDI, D Human Factore Engineering Branch 80/08/25. 1p

8009260936 NUREO/CR-1529

"Ywo-Phese Flow Measurements w/Advanced Instrumented Spool Fisces:"
TURNAGE.K C. Oak Ridge National Leboratory FIN 8-0401. CRN_FUREO-72 80/09/30. 36pp Available at NTIS.

8009240669 NUREO/CR-1561
"Behavior of Hydrogen During Accidents in LHRe"
GHERMAN,M.P. BERMAN,M Sandia Laboratories. BIENIARZ,P.P Energy
Incorporated. FIN A-1051. SANDBO-1495 80/08/31. 310pp
Available at OPD.

BOO7250488 NUREO/CR-1428
"Bolubility Classification of Airborne U Products from LNR-Fuel Plants."
KALKHARF,D R Battells Memoriel Institute, Pecific Northwest
Laboratory. FIN B-21239, PNL-3411, 80/08/31, 68pp. Available at
QPD, 43,75.

8007270038 NUREO 0020 V4 NOB
"Operating Unite Status Rept," data as of 800731
s Office of Management and Program Analysis, 80/08/31 200pp.
Available at NTB. \$12,50.

8009290062 NUREO/CR-1485 VI NO1
"Bafaguarda Matl Control & Accounting Program," quarterly rept Oct-Dac 1979: Vol 1:NO1.
DURN.D. Lawrence Liveraors Laboratory FIN A-0115-0.
UCRL-52715-80-1. 80/09/30. 24pp. Available at NRC \$1.75.

BO07270276 Comments on draft NUREO-0876, "Functional Criteria for Eastgency Associate Facilities." Document would be improved if repetition of same requirements were minimized & expended to provide guidance to multiple unit sites.

COX:E L. Black & Vestch. 80/09/19, 2pp.

8009300160 NUREO/CR-1282
"Statistical Analysis of Steam Cenerator Insp Plans & Eddy Current Teeting " EASTERLING, R. G. Sandia Laboratories, FIN A-1109, SAND79-2300, BO/08/31, 101pp, Available at OPD, 44,25

8009300164 NUMEO/CR-1657
"Bteam-Nater Mixing & Sys Hydrodynamics Program-Task 4,"
quarterly progress mapt for Oct-Dec 1979.
SEQEV.A. FLANIGAN.L. J., COLLIER.R.P. Battells Memorial Institute.
Columbus Laboratories FIN A-4048 SMI-2062. 80/08/31, 118pp.
Available at OFD. \$4,25

8009300303 NUREG-0483
"Environ Assessment for Effective Changes to 10CFR30 & App E to 10CFR30 Energy Planning Requirements for Nuclear Power Plants."
OTT, M. R. 81t & Environ. Stds Br (formerly Environ Prot 8tds Br.) 20/08/31 58pp

8009300300 NURE0-0404 V2 NO3
"Ofc of Nuclear Reactor Regulation Unreactived Safety Issues Bummary Aque Book," Vol 2 N 3
" Office of Managament and Program Analysis 80/08/15 44pp

8009300337 Forwards comments on MUREO-0496, "Functional Criteria for Emergency Response Facilities " Quidelines should be developed from evaluation of what is atteinable & actually nacessary UTLEY, E. E. Carolina Power & Light Co. 80/09/26 Bpp

8009300390 Comments on draft NUREO-0696 rs functional criteria for amergency response facilities Independent varification requirements introduce unnecessary delays Aveilebility goal about 6 be adjusted DUMN, C. N Duquesne Light Co 80/09/26 4pp

8009300398 Comments on draft NUREO/CR-1580 re human angineering guida to control room evaluation Representetive date emples must be included in development of human engineering stde SEELEY, O. T., LEFPKE, D. M. Fluor Fower Service, Inc. 80/09/26 App.

8009300436 Comments on draft NUREO/CR-1580, "Human Engineering Guide to Control Room Evaluation," Color conventions re red & green for abnormal & normal/respectively, may be dangerous Alternets method suggested, SHERIDAN, T.B. Massachusetts Institute of Yechnology 80/09/23

8009300443 Commente on NUREO/CR-1280, "Power Plant Staffing." Caution unged before acceptance of info dus to superficial nature of review & unsubstantiated statements. Neval nuclear propulsion program has shortcomings TMI requirements not in rept. COUNSIL.N.O. Northeast Utilities HOC-80-0-623 80/09/25, 9pp

8009300447 Comments on NUREO-0696, "Functional Criteria for Emergency Response Facilities "Impossible for util to direct work & plan for new requirements w/o explicit direction Plant should be exampl from such requirements if derivad by NRC BRYAN, J. K. Union Electric Co. ULNRC-391. 80/09/23. 1p.

8009300466 Forwards comments on draft NUREO/CR-1580, "Human Engineering Guide to Control Room Evaluation," Guide not directed at obvious problem, Recommendations include endorsement of ATOO approach & use of B&W ATOO training procedures

ENRIVER, E. L. Affiliation Unknown 80/09/26 Spp

8009300646 Forwards comments on NUREO/CR-0570 re technology, sefety & costs of decommissioning ref low level wasts burial ground.
Rept is thorough & analysis has been carefully considered
MENARD, H. M. Interior, Dept of, Ocological Burvey. EGB-ER-60/841
80/09/11. 5pp.

DRO CORRESPONDENCE WITH OTHER DROANIZATIONS

8009030082 Forwards notice of aveilability of IAEA draft safety guides re preparedness for emergencies at nuclear gover plants. CHILK, B. J. Diffice of the Secretary of the Commission. 60/06/18 is.

BOO9030305 Advises that Revision i to IE Bulletin BO-19, "Failures of Mercury-Wetted Harrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E," was sent to 11sted licensess on BOO815.

PAPPAG.H Region 3, Chicago, Office of the Director. 80/08/18.
200

8009050402 Forwards std order for DDE work, "Oposcience Case Reviews II * BCHROEDER,F. Division of Systems Safety. FIN A-7118-9. 79/09/18 28p.

--B009050412 Std order for DDE work, "Geoscience Case Reviewe II," issued to LASL Statement of work encl.
TRIPLETT, B P. Division of Systems Safety, FIN A-7118-9.
20-79-192, 79/09/17, Spp

8009090117 Advises that IE Bulletin 80-07. Suppl 1, "BWR Jet Pump Assembly Failure," was sint to listed licensess on 800513, PAPPAS,H Region 3, Chicago, Office of the Director. 80/05/15.

NONDOCKETED ITEMS

- BO09140092 Advises that IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Ceptain GE BHR Facilities:" was sent to listed licensees on 800819 PAPPAB.H Region 3, Chicago, Office of the Director 80/08/22
- 8009180042 Advises that IE Circular 80-18, "10CFR50 59 Bafety Evaluations for Changes to Raduasta Treatment Sys," was sent to listed licensess on 800822 PAPPAS:H Region 3, Chicago, Office of the Diractor 80/08/26 Rpp.
- 8009180123 Advises that Suppl 3 to IE Bulletin 80-17. "Failure of Control Rods to Insert During Boram at SHR," was sent to listed utils on 800822 PAPFAB.H Region 3. Chicago. Office of the Director 80/08/29 200
- 8007180353 Recommends approval of fraft ANBI/ANS 8td 3.3(NIS 17), "Security for Nuclear Power Plants" Submits comment on grandfather clause is criminal records check in personnel screening.

 8CHROEDER: F. Division of Safety Technology 80/09/10 lp
- 8009230106 Advises that IE Info Notice 80-31, "Malogeration of Quuid-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers," was sent to listed licensees on 800827 PAPPAB, II Ragion 3, Chicago, Office of the Director 80/08/30 200
- 8007230423 Advises that IE Circular 80-20, "Changes in Safe-Blab Tank Dimensions," was sent to listed licensees on 800821 PAPPAS,H Region 3, Chicago, Office of the Director, 80/08/23 4pg
- 8009230537 Advises that Revision 1 to IE Bullstin 79-25, "Boron Loss from BHR Control Blades," was sent to listed licensees on 800829, PAPPAGEH Region 3, Chicago, Office of the Director. 80/09/02 19
- 8009240386 Advises that IE Circular 80-19, "Noncompliance W/License Requirements for Medical Licensees," was sent to medical literasees on attached list on 800826, PAPPAB, H Region 3, Chicago, Offica of the Director 80/08/30

R PROPOSED SULE

- 6005210647 Comments on proposed rule 100FR50:primary emphasis on plant safety should be maintained & present scope should not be expanded to safety-related sys & components PRATT.C. M Power Authority of the State of New York. 80/03/27. App.
- 8009020544 Forwards notice of final rule 100FR40 re deletion of source mat1 medicinals from general license for small quantities of source mat1 for publication in FR on 800B20 CHILK.S. J Office of the Secretary of the Commission 80/08/15, ip
- ~-8009020546 Notice of final rule 100FR40 re deletion of source mati medicinals from general license for small quantities of source stati. DIRCKG-M.J. Office of the Executive Director for Operations 80/08/07. 4pp.
 - 9030006 Comments on proposed Revision 2 to SRP 3.96
 URTIGN W Pennsylvania Power & Light Co FLE 214. 80/07/30.
 Pp.
 - 9030A39 Forwards request to restore CA Energy Commission & CA Dept & Conservation to syc list for NRC waste confidence ulsmaking.
 "RANIMITE E California, State of 80/08/12 1p.
 - OPOSO649 Motion to request 30-day extension of time for filing cross-statements of position due to NRC failure to serve position statements upon CA Energy Commission & CA Dept of Conservation Certificate of Svc encl. VARANINI, E.E., CREW.P. California. State of 80/09/12 Bpp
 - 109030647 Provides substitution for LC Lampher for receiving metls on behalf of CA Energy Commission & CA Dept of Conservation. VARANINI, E E California, State of. 60/08/27. 1p

- 8007030576 Comments on proposed rule 10CFR34 re permanent records of radiation exposure to radiagraphers Supports proposed amend. BROHN, W F Reliance Testing Laboratories, Inc. 43FR39856 006 80707/25 ip
- BOO904011B Comments on proposed rule 10CFR34 re packet desinster readings & amending regulation to provide that records used be retained for only 2 yrs Bupports amend. HOY.C E Intermountain Testing Co. BO/07/28 1p.
- 8007050123 Addl response to FOIA request for records pertaining to proposed fire protection rule. FELTON, JK Division of Rules and Records 80/08/05. is
- --8009050126 Forwards Sandia Labs 790919 & 0904 memos re fira protection in nuclear plants & SECY-79-478 updating status of NRC actions in response to UCB patitions, HANADER:8. H THI-2 Unresolved Safety lasuss 79/11/08. Sap.
- BO07050427 Cross-statement specifying that industry failed to establish factual basis for confidence that nuclear wasts will be safely disposed of by any given date. Technical gaps, deficiencies & uncertainties have prevented resolution. ABRAMS, R., CORMIN, J. M., SIALIK, E. I. New York, State of B0/09/02 70op
- 8009050494 Response in opposition to CA Energy Commission & CA Dept of Conservation request for extension to file cross-statements of position & suggestions re new areas. Urges application of extension to all parties, if granted H/Gertificats of Evc AXELRAD. H Edison Electric Institute. AXELRAD.H Lowenstein, Newman, Reis, Axelrad & Toll. 80/09/03 7ap.
- BOO9080034 Forwards notice of "Emergency Planning," 10CFR50 % 10CFR70, final rule & "Emergency Planning, Negative Dsclaration; Finding of no Bignificant Impact for Effective Rule Changes." 10CFR50 final negative declaration CHILK, B J Office of the Becretary of the Commission. BO/08/12 is.
- --B00908003 "Emergency Planning: Negative Declaration: Finding of No Bignificant Impact for Effective Rule Changes: "IOCFR50 final negative declaration: finding no need to prepare EIS. Rule would not significantly impact human environ. MINOSUE: R.B. Diffice of Standards Development, Director, 80/08/04 14pp.
- 8009090317 Comments on proposed rules 10CFR 50 & 51 re storage & disposel of nuclear waste. Arguments by participants in proceeding for litensing moratorium are misplaced.

 # Atomic Industrial Forum, 80/09/05. 12pp.
- 8009090639 Ack receipt of 800528 ltr re NRC rulemaking on emergency planning for nuclear facilities & forwards final rules on emergency planning AMEARNE. J. F. Commission. 80/08/14 ip.
- --8007070651 Comments on proposed rules (OCFR50 & 70 re emergency planning detailed evaluation planning unnecessary. Fiftsen-minute warning requirement should be rejected in favor of PSAR criteria.

 COX.F T. Texas, State of. 80/05/28 7pp.
- 8007070826 Comments on proposed rule iOCFR60 re technical criteria for regulating geologic disposal of high level radwastes. Fails to recognize distinction between important siting requirements & conditions.

 AKELRAD M Lowenstein, Newman, Reis, Axelrad & Toll. 45FR31393 028.
 80/07/31. 3ipp.
- 8009100444 Cross-statement re proposed rulemaking on radwaste storage & disposal Urgas treatment of sits of each new nuclear maste generating unit as sits for indefinite storage of maste. MUCHNICKI,E D., BROWN,M.J. Ohio, State of. 80/09/08. Zpp.
- SOO9100446 Cross-statement re proposed rulemaking on redweste storge & disposal Urges conservative decision w/option of permanent disposal site prior to generation. Away from reactor storage should be avaided.

 MACARTOR, J D Delaware, State of. 80/09/05. 5pp

- 8009100390 Gross-statement of DDE re proposed rulemaking on storage & disposal of nuclear weste Disposal site decision should be made on hasis of economice & logistics of operation within framawork of applicable regulations. H/Certificate of Svc. COLEMAN.L. R., DISTEFANG.J., BROWN.G.F. Energy Dept of, DDE/NE-007 Si. 80/09/03. 250pp Available at NTIS \$17.00
- 8009110012 Grose-statement re proposed rulemaking on radwaste storage & disposel. Onvt plan for centablishing gaologic rapositorias is effective for devaloping safe disposel sys MCMEDIESE, R. M. ZUMBRUN, R. A. HHITE, E. B. American Nuclear Bociaty, 80/07/05. 23pp
- 8009110026 Cross-statement of position by CA Dapt of Conservation Affirms 800707 position Concurs w/ssveral participant positions that comprehensive sita studies must be conducted prior to locating geologic rappelitory OREW.F.C. California, Stata of 80/09/05 44pp
- BOO9110796 Order dismissing as most CA Energy Commission & CA Dept of Conservation 800828 motion for 30-day extension to file tross-statements Hovents filed timely position on dua date.

 NILLER.M.E. Atomic Safety and Licensing Board Panel. 80/09/09 ip.
- 8009120368 Gross-statement of Environ Coalition on Nuclear Power representings on proposed rulemaking on radwasts disposal to spent fuel storage Radwasta is production problem Production should cease due to lack of space disposal JOHERRUDLY H Environmental Coalition on Nuclear Power, 44PR61372 017. 80/09/10 8pp.
- --B009120374 Request for unserved documents listed in Environ Goalition on Nuclear Power cross-statement ra proposed rulemaking on radwasta disposal & spent fuel storaga.

 JOHNBRUD, J. H. Environmental Coalition on Nuclear Power 80/09/10.
- --BOOT120377 Motion to suspand proposed rulemaking on radwasts disposal & spant fual storage Statements raise areas of deficiancy & grocadural voida. Cartificata of Svc ancl.

 UNRSRUD, J H Environmental Coalition on Nuclear Power 80/09/10.
- 8009180182 Forwards Newport News Shipbuilding & Dry Dock Co comments on proposed rula 10CFR19 re paratiting NRC & licenses to invite third earty to participate in NRC insps Proposed rules are vague & responsibility for amployae participation unclear TRIBLE.P. House of Rep., Merchant Marine & Fisheries 45FR19564 057. 80/07/22, 1p.
- 8009180185 Commants on proposed rule iOCFR60 by including so much detail, NRC is inviting endlase lawsuits by organizations that will stop at nothing to delay waste isolation as long as gassible.

 RRAJBKOPF, K. B. Btanford Univ 45FR31393 101, 60/06/30 1p.
- BOO9160046 Joint cross-statement re proposed rulemaking on radwasta storage & disposal industry approach ra performance critaria of quologic waste depositoriaa is unworkabla & violates defense-in-dapth concept. Lagal stda misstated. WEISS.E.R. Natural Resourcas Defense Council. WEISS.E.R., COCHMANT. Naw England Coalition on Nuclear Pollution. 80/09/10. 9049.
- 8009160161 Cross-statement ra proposed rulemaking on radwaste storage & disposel, Buitable sites are unrenamable natural resources. Total number of geological rapositories w/expanses & availability must be datermined through investigation. LEMIS,M.I. Affiliation Unknown, 80/09/11. Spp.
- BOOP160281 Cross-statement re proposed rulemaking on radwaste storage & fisposel, Supports & adopts encl comments of DO Bridenbaugh of 開始 Technical Associates. Radwasta cannot be safely storad onsite after expiration of licenses MURRAY, M. J. FAPNER, T. C., VAN VRANKEN, J. Illinois, State of, 90/09/03 16pp.
- --8009160284 Review & comments on 800707 statement prepared for Util Nuclear Maste Mgt Group & EEI re "Gapability for Bafa Interim Storaga of Spent Fuel." BRIDENBAUCH, D. 1488 Technical Associates. 80/08/28 20pp.
- 9009150443 Transcript of 800904 discussion of SECY-80-399 rs proposed interim amends to 10CFR80 re hydrogen control & certain degraded cora considerations in Washington DC Pp 1-86. Viewgraphs encl. s Commission. 80/09/04. 95pp.
- 8009180522 Cross-statement re rulemaking proceeding on radwaste storaga b dispesal Discusses cost of maintaining monitoring station. Certificate of Byc encl. COCHEJET, N. A. Affiliation Unknown. 80/09/05 Spp.

- 8009190103 Comments on proposed rule 10CFR60 re regulating geologic disposal of high level radwastes Considerations adequately identify relevent issues involved in disposal of high level waste. Esposure limits are inappropriate HEUBNER. A T Connecticut. State of. 45FR31393 027 E0/07/14 ip
- 8009190529 Response in opposition to Environ Coalition on Nuclear Power 800910 motion to suspend further proceedings Certificate of Bvc encl COLEMAN, L R , DISYEFAND, J , BROWN, O F Energy, Dept of 80/09/15
- BOOP190614 Add1 response to FOIA request for nine categories of documents re AEC emend to 100FRBO 57(c) proposed on 701028 & adopted on 710514. Forwards documents listed in app FELTON, J H Division of Rules and Records 80/09/02 2pp
- --BO09190634 Forwards 10CFR30, "Authorization of Low Power Operation "
 Requests publication.
 MCCOOL.H B. Atomic Energy Commission 71/03/10. 1p.
- --8007170638 "Authorization of Low Power Operation," 100FR50 effective rule Proposed amends define extent of preoperational activities which could be conducted grior to issuence of CL & provide for authorization of low power testing.
 HOBSS,F.T. Atomic Energy Commission 71/05/03 Spp.
- --8009190642 Discusses proposed rule 10CFR50 re authorization of low power operation Commission should adopt rule in affective form Adoption of proposed amend re fuel loading under CP is not recommended. Dreft FR notice ancl PRICE, H. L. Atomic Energy Commission 71/04/21 iipp
- ~8009190647 Forwards draft FR notice re proposed rule iOCFR50, "Licansing of Production & Utilization Facilities" & public announcement. Proposed rule provides for operation during panding OL proceedings. FR notice only snc1 PRICE, A L. Atomic Energy Commission. 71/04/13 4pp
- ---B009190653 Bunmary of 710it5 Regulatory Info Meeting 445 Liet of attandees included, Proposed amende to 10CFR50 & 2 ra effective date of initial decision authorizing issuance of DL approved MCCOOL, N B. Atomic Energy Commission, 71/01/15 2pp
- --8009170687 Informs that Commission approved amends to 10GFR50 & 2 re effective date of initial decision authorizing issuance of M. at 710115 Info Meeting 445, M/o attached FR notice. PRICE/H L Atomic Energy Commission 71/01/15 ip.
- ---8009190668 Forwards comments on proposed rules iOCFR2 & 80 reeffective date of initial decision authorizing issuance of
 DL Bone features of proposed rules unless clarified could
 introduce further uncertainty into licensing process.
 GLEASON.O.L Atomic Industrial Forum. iOCFR2. 70/12/31 23pp
- ---8009190676 Comments on proposed rules 10CFR2 & 50 ra effactiva date of initial decision authorizing issuance of OL. Praeperational radiological monitoring programs should be completed prior to core loading & low power testing.

 W Interior, Dept. of, Fieh & Hildlifa Bervice. 10CFR2, 70/12/18 2pp
- 8009190629 FOIA request for nine categorias of documents ra AEC amand to 100FR30 37(c) proposed on 701028 % adopted on 710514 BROWN,H,H Hill Christopher & Phillips 80/08/07 2pp.
- 8009190567 Comments on proposed rule 10CFR30 re anviron qualification fire protection: "DOR Ouiselines" should be viewed as preliminary & used by NRC as guidaline not as rule, in evaluating equipment qualification
 MHITE, L. D. Rochester Gas & Electric Corp 45FR36082 053 80/08/05
 2pp.
- 8009190707 Comments on proposed rule 100FR34 re retaining pockat dosinatar racords. Concurs w/proposal. Retention period should be reduced to i yr instaad of 2 yrs HENDRIX.O.M. Nevy.Dapt. of. Naval Facilities Engineering Command 45FR39856 005 80/07/28 ip
- 8009240012 Responds to FQIA request for nine categories of documents re AEC amend to 100FR50 57(c) proposed on 701028 % adopted on 710514 Forwards documents listed in App A responding to Items 1-5. Rearch is continuing for add records FELTON. J. H. Division of Rules and Records 80/08/21 2pp

- --8009240018 Forwards draft notice of proposed rules 10CFR2 & 10CFR50 Proposed amends authorize nuclear fuel loading in reactor core w/o stasinment of critical reaction & authorize Director of Regulation to issue license PRICE,H L Atomic Energy Commission 70/10/22 12pp.
- --8009240021 Forwards FR notice to AEC proposed rules 10CFR2 & 10CFR50, "Rules of Practice" & "Licensing of Production & Utilization Facilities OLs " Requests publication., HCCGOL, N B Atomic Energy Commission 70/10/22 ip

- --B009240024 Notice of AEC proposed rules iOCFR2 & iOCFR50, "Rules of Practice" & "Licensing of Production & Utilization Fecilities OLe." respectively HCCOOL, B Atomic Energy Commission 70/10/20 Bpp
- --8009240069 Comments on proposed rules locFR2 & 30.on behalf of Bave New England Commission should undertake thorough & comprehensive review of entire licensing echams contained in proposed rule.w/full public hearing MESSLER. # 4ffiliation Unknown. 100FR2. 70/12/28 1ipp
- --B009240070 Comments on proposed rules 10CFR2 & 50 re effective date of initial decisions authorizing issuance of DLs Change in procedures undercuts congressional review procedures for objections to issuance of GL Draft FR notice encl.

 BUTLER, W A Environmental Defense Fund. 10CFR2. 70/12/28 7pp
- --BQ09240086 "Effective Date of Initial Decisions Authorizing Issuance of OLe," 10CFR2 & 50 effective rule. Amend provides for immediate effectiveness of initial decisions authorizing leguance of OLe HOBBS,F T Atomic Energy Commission. 71/01/15 App. Atomic Energy Commission. 71/01/15 App.
- --8009240092 Forwards HL Price 71042; memo & info for Commission consideration at info meeting. Includes draft notice of rulemaking, draft ltr to EJ Beuser & draft public announcement Atomic Energy Commission SECY-R 221 71/04/21 1p
- --BO09240108 Discusses proposed rule 10CFR50 re authorization of low power operation Recommends that Commission adopt rule in effective form Draft notice of ruleweking. It to EJ Bauser & draft public announcement encl
 FR1CE, H L Atomic Energy Commission. 71/04/21. 15pp.
- --8009240113 Informs that Commission approved SECY-R 221 re proposed rule 100FR50 concerning authorization of low power operation MCCDDL, W B Asomic Energy Commission 71/04/29
- 8009240562 Comments on proposed rulemaking, "Qualifications of Reactor Operators" Provisions should be made for phasing in administration of NRC simulator exams in same manner as requellification exems

 DENTON.H R Office of Nuclear Reactor Regulation, Director, B0/QB/23
- B009240563 Forwards corrected erratum sheet to be incorporated in position statement. Correction provides further degree of conservation in supporting containment & isolation objectives proposed by DEE BROWN, O.F. Energy, Dept. of B0/09/19. 2pp.
- 8009300303 NUREO-0685 NYMODOUGH NUMBERVOOR REPORT OF THE CONTROL OF THE C Plants " OTT, M R Sit & Environ Stds. Br (formerly Environ. Prot Stds. Br }, 80/08/31 58pp. Sepp.

PRM PETITION FOR RULEHAKING

- 8009050337 Advises that 800603 request for exemption of industrial radiographers from certain code requirements is under consideration as patition for rulemaking 71-8 No 1trs of comment have been received in response to encl FR notice.
 HENRY-J Transportation & Product Standards Branch. 80/08/13
- 8009120492 Forwards quarterly rept on petitions for rulemaking as of 800630 for transmittal to PDR FELTON-J M Division of Rules and Records, 80/08/18 24pp

- 8009160204 Comments on petition for rulemaking 71-8 re requirement that user have all documents referred to in certificate.
 Acceptance would relieve industry from chore which has no benefit toward improved safety. Technical Operatume. Inc 45FR39519 002. 80/08/11 2
- 8009160206 Comments on petition for rulemaking 71-8 from Foster Whisler Energy Corp Supports proposed exemption of persons under 100FR34 from provisions of 100FR71 12(b), (i) & (j).

 THOMAS,E L Air Transport Association 45FR99519 00\$ 80/00/(1.
- BOO9140209 Comments on petition for rulemaking 71-8 re requiring focumentation referred to in license certificate or other approvel in order to deliver licensed math Certificate of complience is adequate documentation to have on file. BROWN, W.F. Reliance Teeting Laboratories, Inc. 45FR37519 001 B0/07/30
- 8009190661 Comments on petition for rulemaking 2-10 re increased publi involvement in licensing process. request should be denied HAFFMAN, D.P. Consumers Power Co. 45FR26071 013 80/08/05 2pp

PROJECTS - PREDOCKET LICENSING PROJ

- 8009150140 Notification of contract execution, Mod 5 to "Economic Consulting Byce in Connection H/Stanislaus Nuclear Unit " Contractor P Outmann GLACOLA, A F Technical Assistance Contracts Branch NRC-03-79-113. 80/06/30 2pp
- ~-B009180143 Mod 5.extending period of performance & increasing ceiling amount, to "Economic Consulting Sycs in Connection M/ Btantslaue Nuclear Unit." GUTMANN.P. Outman, Peter OLAOGLA, A.F. Technical Assistence Contracts Branch FIN B-6521. NRC-03-79-113 80/06/30 1p.

PT9 100FR, PART 9 -

- 7903230216 Confirms actions undertaken on 790131 re use of licensed byproduct mat1 by individuals not authorized as users.

 Corrective actions will halt use of mat1, secure licensed mati on hand & resume use only by approval
 KEPPLER, J. O Region 3, Chicago, Office of the Director, 79/02/01
- 7904120080 Discusees IE insp of License 12-18044-01 on 790131-0202 4 forwards notice of violation.

 KEPPLER, J G Region 3, Chicago, Office of the Director, 79/04/05.
- --7904120082 Notice of violation from insp on 790131-0202 Noncompliant noted procured seven bulk shipments of Xe-133 marked "Not for Humen Use:" no licensed supervision of licensed matl & no program to measure radioactive matl in air * NRC Regional Offices. 79/04/05 3pp
- 7904170409 Schedules 790323 meeting to discuss noncompliance items noted in inep of Licenses 48-17464-01MD & 12-18044-01MD. KEPPLER, J G Region 3. Chicago. Office of the Director 79/03/
- 7904170412 Schedules 790323 meeting to discuss noncompliance items noted in inep of License 48-17464-01MD.
 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/03/19.
- 7906010084 Ack receipt of 790304 ltr informing NRC of steps taken to correct violations noted in IE inep of License 08-18308-01MD on 790208 MCCLINTOCK, R O. Region 1, Philadelphia, Office of the Director.
- ---7906010086 Responds to NRC 790223 Itr re violation notef in IE insp License 08-18308-01HD on 780208 Corrective actions:no further transfers of Xe-133 to individuals lacking necessary license info & chart w/licensing info posted, IRWIN.R F. Pharmatopes, Inc 79/03/06 2pp
- --7904010088 Discusses IE insp 30-14826-01 of License 08-18308-01 en 790208 & forwards notice of violation
 MCCLINTOCK.R O. Region i, Philadelphia, Office of the Director.
 79/02/23 2pp

- --7905010091 Notice of violation from inep on 790208 Noncompliance noted shipped X=-133 to hosp w/o verifying that hosp license authorized X=-133.

 * Region i. Philadelphia. Office of the Director. 70403/00. Region i, Philadelphia, Office of the Director 79/02/23. 1p
- 7906290324 Ack receipt of 790425 ltr informing NRC of steps taken to correct violations noted in IE insp of License 12-18044-01 en 790405
- en ,70900 KEPPLER, J Q Region 3. Chicago, Office of the Director 79/05/18
- ---7906290556 Rasponds to NRC 790405 ltr re violations noted in IE insp of Licanse 12-18044-01 on 790405, Corrective actions will not buy Xe-183 w/o label "for human user" bicassay procedure changed & hired addl personnel ZIMMER, A M Nuclear Pharmacy, Inc. 79/04/25 7pp
- 7410020407 Grants extension to 791022 for submission of response to 790817 notice of violation served on Nuclear Pharmacy Inc. STELLO,V Office of Inspaction & Enforcement, Office of the Director 79/09/07 2pp.
- 7711070067 Discusses IE insp of License 12-17910-01MD on 790926 & 1010 & farwards notice of violation.
 DAVIE.A B. Region 3, Chicago, Fuel Facility & Meterials Bafety Franch. 12-17910-01MD 79/10/25 ip.
- --7911070077 Notice of violation from insp on 790926 & 1010 Noncompliance noted: failure to make surveys re radiation exposure to personnel extremities, failure to made monthly thyroid readings of person using 1-131 & failure to make lab survey a Region 3, Chicago: Office of the Director 12-17910-01MB. 79/10/23 1p
- 7912040149 Act receipt of 791105 itr informing NRG of steps taken to correct violation noted in IE insp of License 12-17190-01MD en 791025.

 DAVIG.A. B. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/11/21
- --7912040136 Responds to NRC 791025 itr re violations noted in IE inep of License 12-17190-01MD on 791025 Corrective actions.

 evaluations on personnel ring badge readings for 781225791024 & 0625-0725 sent to R. B Landauer. JR & Co for records
 GOMER.F. M Pharmaco Nuclear, Inc. 79/11/05 4pp
- 7412180310 Discusses IE insp of License 37-18461-01 MD on 790828-29. No noncompliance noted Major areas inspected review of circumstances surrounding receipt of package containing -133 MCCLINTOCK, R O. Region 1. Philadelphia. Office of the Director 79710/05 ip
- 7912190014 Ack receipt of 790917 ltr informing NRC of steps taken to correct violation noted of License 37-18461-01MD on 790618 GREER, B. H. Region i, Philadelphia, Offica of the Director 79/10/03.
- --7912190023 Responde to NRC 790910 itr re violation noted in IE insp of License 37-18461-01MD on 790618. Corrective actions' restricted area workers will be instructed auditor will survey radiation hazards & springe shielde will be used. DESSEL 8 Nuclear Pharmacy, Inc 79/09/17. App.
- --7912190047 Responds to NRC 790B21 ltr re violation noted in IE insp of License 37-18461-01MD on 790618. Corrective actions, sent copy of guidelines for radwaste packaging & pick up to customers & Institued training program for transporters.

 DESBEL. 8 Nuclear Pharmacy, Inc. 00618 79/07/10. 34pp
- --7912190054 Act receipt of 790807 ltr informing NRC of steps taken correct violation noted in 1E insp of License 37-18461-01MD on 790618 Requests addl info re mpt control sys. to be received within 7 days of ltr.
 BMITH.O H Region 4. Dallas. Office of the Director. 79/09/10 taken to
- --7912190067 Responds to NRC 790723 itr re violations noted in IE insp of License 37-18461-01MD on 790618, Corrective actions; surveys of radioactive matis discharged in effluent air from fume hood will be done routinely DESBELIB, Nuclear Pharmacy, Inc. 79/08/07 3pp
- --79[2190073 Forwards notice of violation from IE insp of License 37-18461-01MD on 790618, ORIER.B.H. Region i. Philadelphia, Office of the Director. 79/07/23 2pp

- --7912190080 Notice of violation from insp on 790618
 * Region 1, Philadelphia, Office of the Director 79/06/23 3pp
- 8001020069 Ack receipt of 791120 ltr informing NRC of steps taken to correct violations noted in IE imap of License 08-18308-01MD on 790913 MCCLINTOCK, R O Region 1, Philadelphia, Office of the Director 79/12/10
- --8001020073 Responds to NRC 791114 1tr re violations noted in IE 10sp of Licanse 08-18308-01MD on 790913 Corrective actions dose calibrator will be adjusted or repaired when activity measurements during linearity tests differ by more than 5X IRWIN.R F Pharmatopes. Inc 79/11/20 ip
- --8001020078 Ack receipt of 791017 ltr informing NRC of steps taken to correct violations noted in IE insp of License 08-18308-0IMD on 790913 Requests edd1 info re dose calibrator adjustment & wips tests HCCLINICCK,R C Region 1, Philadelphia, Office of the Director 79/11/14
- --8001020083 Responds to NRC 790922 itr re violations noted in IE insp of License 08-18308-014D on 790913 Corrective actions surings shields will be used at all times & linearity tests will be repeated upon indication of more than 10%. Pharmatopes, Inc 79/10/17 TRUIN R F
- --8001020105 Discusses IE insp of License 08-18308-01MD on 790713 & forwards notice of violation
 MCCLINTOCK,R C. Region 1, Philadelphis, Office of the Director 79/09/27. 2pp
- ---800102010B Notice of violation from insp on 770713, Noncompliance noted, failure to use 1sed syrings shields, failure to record constancy checks on 770820-21 & failure to perform wipe test on incoming packages a Region i. Philadelphie. Office of the Director 79/09/27 2pp
- 8001290275 Act receipt of 800107 ltr informing NRC of eteps taken to correct violations noted in IE insp of License 24-15617-01MD. DAVIB.A B. Region 3. Chicago, Fuel Facility & Materials Safaty Branch. 80/01/18 1p
- --8001290281 Responds to NRC 800102 ltr re violations noted in IE insp of License 24-16617-0140 Corrective actions, have requested NRC to amend to license from three months to yearly calibr for radiation monitors. Pharmare Nuclear, Inc. 80/01/07
- BOO2150275 Confirms meeting to be held between NRC & Nuclear Pharmacy.
 Inc on BOO122 in King of Prussia.PA to discuss results of
 NRC 790802-03 insp & noted noncompliance.
 GRIER.B.H. Region i, Philadelphia, Office of the Director NRC 79000. ORIER, B. H Re
- 8002150283 Discusses error in 800109 itr Purpose of meeting is to discuss results of 800103 insp Meeting date is 800122 at Region 1 ofc SMITH OH Region 1, Philadelphia. Fuel Facility & Materials Safety Branch. 80/01/15 ip
- 8002190229 Clarifies Muclear Pharmacy. Inc comments made during 600121 meeting re NRC notice of violation forwards summary of facts available to NRC prior to issuance of notice Urges dismissal or remission of civil penalties.

 VAKERIGS, T V D'Connor & Hannan 80/02/03 7pp
- 8003050215 Ack receipt of 791221 itr informing NRC of steps taken to correct violations noted in IE insp of License 37-18461-01MD on 791109 itsm A corrective & preventive actions will be discussed at 300122 NRC masting.

 ORIER.3 H Region i, Philadelphia, Office of the Director 80/01/21 ip.
- -8003050219 Responds to NRC 791211 itr re violations noted in 1E insp of License 37-18461-014D on 791109 Corrective actions steps have been taken to lower employee radiation exposure Syringe shield will be used whenever possible.

 DEBBEL-8 Nuclear Pharmacy, Inc. 79/12/21. 4pp
- --- 8003080224 Forwards notice of violation from IE insp on 791109. One item of noncompliance noted in NRC 790723 ltr has not been totally corrected NRC has no further questions re Item 8 corrective actions. ORIER, D.H Region i, Philadelphia, Office of the Director 79/12/11. 2pp.

- --8003050226 Notice of violation from insp on 791109 Noncompliance noted emplayes eversiposure: failure to report overeiposures: failure to conduct required surveys expion i. Philadelphia, Office of the Director 79/12/11 3pp
- --8003050232 Submits revised quarterly figures re extremity exposures Company has instituted adequate measures to ensure significantly lower exposure levels DESSELS Nuclear Pharmacy, Inc. 79/11/12 2pp
- 8003190517 Ack recaipt of 800128 itr informing NRC of staps taken to correct violations noted in IE insp of License 45-18378-01 MD on 791206 P. Region 2: Atlanta: Fuel Facility & Materials Safety 80/02/06 | 1p Branch
- --8003190525 Responds to NRC 800118 ltr re violations noted in IE insp of License 45-18378-01MD on 791206. Corrective actions linearity test of both dose calibrators will be performed first Monday of calendar quarter POTTER-M F Pharmatopes. Inc 80/01/28 1p
- --8003190529 Discusses IE insp of Licanse 45-18378-01MD on 791206 & forwards notice of violation STOHR.J.P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/01/18 2pp.
- ---8003190537 Notice of violation from insp on 791216 Noncompliance notad. linearity tests not conducted on fose calibrators between Apr & Nov 1979.Records of radiation surveys performed on bags of syringes at disposel not recorded * Region 2. Atlanta. Office of the Director 80/01/18 lp
- 8003240038 Forwards on behalf of Nuclear Pharmacy, Inc. cashier check recivil panelty imposed par 800219 notice of violation to Elfreth Alley Apothecary in Philadalphia. Ph Hill not challenge penelty Situation will be corrected per encl HCDONALD. H E. Butin, Thayer & Browne 80/03/10 5pp
- 9003250232 Forwards reconstructed 1978 film badga summary rapt Results of summary rapts from AB Landauer Co & Bearle Diagnostic will be forwarded within next month Advises of move to new licensed facility

 #UBER.8 A Nuclear Phermacy, Inc. 80/02/19 3pg
- JSDF0552 Atk receipt of 800220 ltr ra plans & progress in upgrading radiation protaction program per IE Insp Rept 30-15125/79-01. SMITH.0 H Region 1. Philadalphia, Fual Facility & Materials Safety Branch. 80/02/28 ip
- --8005090553 Informs of change in 790807 proposed corrective actions re [E Insp Rept 30-15125/79-01. Instead of installing portal monitor in threshold area between ofcs & lab.plans to install permanent contemination survey station BTEPHENB.C W. Nuclear Pharmacy. Inc. CMB-280-8 80/02/20 2pp.
- 8005230654 Ack receipt of full civil penalty payment imposed in NRC 800219 ltr & receipt of licenses 800310 ltr re corrective actions Info on agt controls & audit program expected by actions into on age controls & audit program expected by 800512
 STELLO.V. Office of Inspection & Enforcement, Office of the Director. 80/04/07 ip
 -)3300691 Forwards IE Insp Rept 30-14386/80-02 on 800403 of activities under License 12-18044-01 No noncompliance noted NAVIS.A B Region 9, Chicago, Fuel Facility & Haterials Safety branch 80/04/21. 2pp
 - 1005300695 IE Insp Rept 30-14396/80-02 on 800403 No noncompliance noted Major areas inspected Secontaminated radiopharmac sutical facility.

 ADAN.M. J. PAPERIELLO, C. J. Region 3. Chicago, Office of the Director. 80/04/15, 3pp
 - 005300697 Submits rept ra results of closeout radiation survey. RUBER, S. A. Nuclear Phermacy, Inc., 80/03/07. 7pp.
 - 4120881 Forwards IE Insp Rept 30-1362280-01 on 800416 of activities inder License 12-17910-01 MD No noncompliance noted NAVIS.A B. Region G. Chicago, Fusi Facility & Materials Safety Franck 80/03/07, 2pg
 - -8005120884 IE Insp Rept 30-13522/80-01 on B00415. No noncompliance noted Hajor areas inspected, matts, facilities & equipment, recalpt & transfer of matt, surveys & radioactive effluents & waste disposal. receipt α vransfer of Massisurveys & recipectave errivents & waste disposal. G. Chicago, Office of the Director PAPERIELLO, C.J. Region G. Chicago, Fuel Facility & Materials Safety Brench 80/05/06. 12pp.

- PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE
- 8009120699 Revised Part 21 rept ra dafactiva pipe hangers. Revised list of hangers shipped to Job site encl BECKBYED. W F Bargen-Pattarson Pipe Support Corp 75000-32-0669 80/08/14. 3pp
- BO09180255 Part 21 rapt re pump failure in containment gas monitoring sys. Causad by deadheading pump w/inclusion of check valva & bypass line for prassura Rept should be considered part of original BO0402 rept MERCER. W Comsip. Inc. / Delphi Systems Div 80/08/22 1p.

QUALITY ASSURANCE INSPECTIONS **GA999**

- 8009050280 Informs NRC that deficiency re walding of attachments to sefaty-related piping occurred in North Anna Units 1 & 2 only Corrective action has been completed. No sefety hazard exists Further raylew of item is not warranted.

 JACOSS.8 B Stone & Wabster, Inc. 100FR 050 55E 80/08/27 2pp
- 8009080465 Forwards QA Program Insp Rept 99900061/80-01 an 800605-06. No noncompliance noted
 PDTAPOVS,U Region 4. Dallas, Vandor Inspection Branch 80/07/09.
- --8009080467 GA Program Insp Rept 99900061/80-01 on 800603-06. No DYOROUSE OF TENERS HAS REPT 97900061/80-01 on BOO603-06. No noncompliance noted Major areas inspected implementation of 100FR50. App B & applicable codes & stds & followup on reported deficiancy of sheared pin on valve disc HMITGEGELL, D E. KELLEY, N D Region 4, Dallas, Vandor Inspection Branch 80/07/07. 7pp.
- B009100208 Ack receipt of 800723 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99700247/80-01 PDTAPOVS, U Region 4, Dallas, Vendor Inspection Branch. 80/08/22.
- --8009100219 Responds to NRC 800626 ltr re daviation noted in GA Program Insp Rept 99900347/80-01 Corrective actions GA manual revised & will be released approx 800815 ROMHOL, M B. Gulf & Heatern Industries, Inc. 80/07/23. 2pp.
- --8009100223 Forwards GA Program Insp Rept 99900347/80-01 on 800602-04 k notice of deviation POTAFOVS, U Region 4, Dallas, Vendor Inspection Branch. 80/06/26.
- --8009100227 Notice of deviation from insp on 800602-04 * Region 4, Dellas: Office of the Diractor. 80/06 80/06/20 2pp.
- --B009100231 GA Program Insp Rept 99900347/B0-01 on B00602-04,
 Noncompliance noted calibr activities not performed in
 accordance W/procedures required by GA manual.
 HHITESELL, DE ..., BUTTGN.D.E. Ragion 4, Dallas, Vendor Inspection
 Branch. B0/06/20. App
- 8009110613 Forwards GA Program Insp Rept 99900357/80-01 on 800602. No noncompliance noted. POTAPOVS.U Region 4. Dalles, Vendor Inspection Branch. 80/06/ Region 4. Dallas, Vendor Inspection Branch. 80/06/30
- -8009110618 GA Program Insp Rept 99900357/80-01 on 800602.No moncompliance noted Hajor areas inspected implementation of code requirements including applicable codes & stds & raviaw of vandor activities HHITESELL, D. E., KELLEY, H. D. Region 4, Dallas, Vendor Inspection Branck 80/06/27 8pp
- 8009120334 Forwards GA Program Insp Rept 99900522/80-02 pm 800616-20. No noncompliance noted POTAPOVE, U. Ragion 4. Dallas. Vandor Inspection Branch 80/07/09.
- --8009120335 GA Program Insp Rept 99900522/80-02 on 800616-20 No noncompliance noted Major areas inspected: seismic analysis of as-built safety-related piping sys implementation of 10CFR50 in areas of design change document control. BRICKLEY/R.H. AGEE, J.R., HALE, C.J. Region 4, Dellas, Office of the Director 80/07/02, 10pp.
- 8007120654 Ferwards QA Program Insp Rept 99900328/80-01 on 800419-19 No noncompliance noted FOTAPOVB, U. Region 4: Dallas, Vendor Inspection Branch. 80/07/10

- --9009120657 QA Program Insp Rept 99900528/80--01 on 800618--19 No noncompliance noted Major areas inspected activities re IE Bulletin 79-14. HALE.C.J. BRICKLEY:R H. VIN.I T Region 4. Dallas, Vendor Inspection Branch IE8-79-14 80/07/02 8pp
- 8009150017 Farwarde GA Program Insp Rept 99900064/80-01 on 800624-27. No nancompliance noted
 PDTAPOVS, U Region 4. Dallas, Vendor Inspection Branch 80/07/11
- --B009130021 GA Program Insp Rept 99900064/B0-01 on 800624-27 No noncompliance noted. Major areas inspected, implementation of 100FR80. App B. Including control of nonconformances, actions & audits
 HHITESELL.D E. BROWN.R L. Region 4. Dallae, Vendor Inspect WHITEBELL, D E , BROWN, R L Region 4, Dalias, Vendor Inspection Branch. 80/07/09 6pp
- 8009150171 Forwards QA Program Insp Rept 99900726/80-01 on 800624-27. No noncompliance noted
 FOTAPOVB.U Region 4. Delles, Vendor Inspection Branch 60/07/15.
- --B009150173 GA Program Insp Rept 99900726/80-01 on 800624-27 No noncompliance noted Major areas inspected GA program vendor activities, welding control re purchase, lesuance & storage & possible welder certification deficiency OLLER.R.E., POTAPOVB.U Region 4, Dallas, Vendor Inspection Branch, 80/07/10, 12pp.
- 8009150195 Ack receipt of 800808 & 0520 ltrs informing NRC of eteps taken to correct deviation noted in QA Program Insp Rept 99900109/80-01. POTAPOVS.U. Region 4: Dallas, Vendor Inspection Branch BO/OB/22.
- --B009150199 Responds to NRC 800602 ltr re deviation nated in GA Progrem Insp Rept 99700109/80-01. Corrective action: current temporary attachments procedures revised to include all aspects of utilization & emphasize met
- --BOO9150200 Ack receipt of BO0520 ltr informing NRC of staps taken to correct deviation noted in GA Program Insp Rept 99900109/BO-01 Requests addl info.
 POTAPOVB.U Region 4. Dallas. Vender Inspection Branch 80/06/02.
- -8009180204 Responds to NRC 800417 ltr re deviation noted in GA Program Insp Rept 99900109/80-01 Corrective actions welder surveillance repts reviewed & equipment corrected to produce electrical requirements esteblished in welding procedures, MUELLER, A J Pittsburgh-Des Moines Steel Co 80/05/20 7pp
- --8009150207 Forwards QA Program Insp Rept 99900109/80-01 on 800324-28 & notice of deviation.

 POTAPOVB.U. Region 4, Dallas, Vendor Inspection Branch 80/04/17.
- --B009150210 Notice of deviation from insp on 800324-28.
 * Region 4. Dallas, Vendor Inspection Branch. 80/04/16 ip.
- --8009150217 GA Program Insp Rept 99900109/80-01 on 800324-28
 Noncompliance noted; installation & removal of temporary
 attachments not documented on fabrication check hist. Helding
 procedure electrical cheracteristics not maintained
 HHTEGELL, D. E. , BUTTON-J W Region 4, Dellas, Vandor Inspection
 Branch, 80/04/16, 14pp.
- 8009180221 Ack receipt of 800520,0804 & 0626 ltrs informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 97900525/60-01, PGTAPOVS.U. Region 4, Dallas, Vendor Inspection Branch. 80/08/18,
- --- 8009150224 Ack receipt of 800520 & 0626 ltrs informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900525/80-01. Requests addl info re deviation I tems B. 2 & POTAPOVS.U. Region 4. Dalles, Vendor Inspection Branch. ED/07/16. ip.

- -8009130224 Responds to NRC 800603 ltr re deviations noted in GA Progra Into Rept 99900525/80-01 Corrective actions all but seven Items identified in Internal Audit IA-80-1 resolved. Requests extension re Deviation Items 8 2 & 8.3 HARKER.N R 011bsrt/Commonwealth Cos 80/06/26 2pp
- ---B009150227 Ack receipt of 800520 ltr informing NRC of steps teken to correct deviations noted in QA Program Insp Rept 99900525/80-01.Requests addl info re Deviations B 2.8.3.C 1 POTAPOVS.U Region 4. Dallas, Vendor Inspection Branch 80/06/03 2 s s
- --800918022B Responds to NRC 800421 ltr re deviations noted in QA Program Insp Rept 99900525/80-01. Coreective actions procedures to be prapared to record annual mpt review & changes made in design control program

 DARKER
- --8009150229 Forwards OA Program Insp Rept 99900525/80-01 on 800324-28 & notice of deviation, POTAPOVE.U Region 4. Dellas, Vendor Inspection Branch 80/04/21
- ---8009150231 Notice of deviation from insp on 800324-28 * Region 4. Dallas, Office of the Director 80/04.
- --8009150234 OA Program Insp Rept 99900525/80-01 on 800324-28
 Noncompliance noted no procedures for conducting annual mgt
 reviews of GA programs Certain design ectivities & eudits
 not performed in accordance w/epproved procedures.
 HALE.G J., JOHNBON.J H., FOX.D.F. Region 4, Dallas, Vendor
 Inepection Branch 80/04/18. 30pp
- 8009170155 Forwarde QA Program Insp Rept 99900389/80-01 on 800708-09 No noncompliance noted. POTAPDVB.U Region 4, Dellas, Vendor Inspection Brench 80/07/21.
- --8009170159 GA Program Insp Rept 99900389/80-01 on 800708-09, No noncompliance noted Major areas inspected evaluation of supplier performance & followup of corrective action taken re GA Program Insp Rept 99900389/79-01.
 WHITEGELL, D. E. , DRONN, R. L. Region 4, Dellas, Vendor Inspection Branch. 80/07/17 App
- 8009170156 Forwards QA Program Insp Rept 99900014/80-01 en 800630-0703 No nencompliance notes. POTAFGVS, U Region 4: Dallas, Vendor Inspection Brench 800/07/21.
- --8009170158 GA Program Inep Rept 99700014/80-01 on 800630-0703 No noncompliance noted Mejor areas inspected equipment calibr. mondestructive examination & audits. BARKEB. I. ROBERDS. M. M. Region 4. Dallas. Vendor Inspection Branch. 80/07/18. Sep.
- 8009180036 Ack receipt of 800821 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 79790321/80-01 POTAPOVS. U Region 4. Dallas, Vendor Inspection Brench. 80/08/28.
- --8009180064 Responds to NRC 800729 ltr rs deviation noted in OA Progra Inst Rept 99900321/80-01 Corrective actions: serial number log to be used to control (erial number identification on all tools. BROWN, M E. , PEET, W. J. Ametek, Inc. 80/08/21. 3pg.
- --8009180070 Forwards GA Program Insp Rept 99900321/80-01 on 800707-10 & notice of deviation, PDTAPOVS,U Region 4. Dallas, Vandor Inspection Branch 80/07/29
- --8009180077 Notice of deviation from insp on 800707-10. * Region 4. Dallas. Office of the Director 80/07.
- --8009180085 GA Program Insp Rept 99900321/80-01 on 800707-10
 Noncompliance noted insp tool one month overdue for
 calibr & earlel number log not maintained
 HUNTERLY H., HHITEBELL, D.E. Repion 4, Dallas, Vendor Inspection
 Branch. 60/07/25 Spp.
- 8007180072 Ack receipt of 800805 ltr informing NRC of steps taken to correct deviation noted in GA Progrem Insp Rept 97900081/80-01. POTAPOVS.U Region 4. Dallas, Vendor Inspection Branch

- --BOO9180099 Responds to NRC 800625 ltr re deviation noted in QA Program Insp Rept 99900081/80-01 Corrective actions fuel assembly follower card form reissued w/space to record weld wire release number VOLMER, C J Exxon Nuclear Co , Inc (subs of Exxon Corp) 80/08/05 3pp
- --BD09180104 Forwards GA Program Insp Rept 979000B1/80-01 on 800610-12 & notice of deviation.
 PDTAPDUS U Region 4. Delles, Vendor Inspection Branch 80/04/25 & App.
- -8009180107 Notice of deviation from insp on 800610-12 e Region 4. Dellas, Vendor Inspection Branch. 80/06/23 ip.
- -8009180119 GA Program Insp Rept 99900081/80-01 on 800610-12.

 Noncompliance noted, mati not traceable to starting mati per Guality Procedure 8 Mati not labeled w/cleaning date re GC 8td XN-368146

 MCNEILL, W M , WHITESELL, D.E. Region 4, Dallas, Vendor Inspection Branch 80/06/23, App.
- 009180169 Ack receipt of 800806 itr informing NRC of steps taken to correct deviation noted in GA Program Insp Repts 9990400/79-04 & 99900400/80-01 POTAPOVB. U Region 4, Dallas, Vendor Inspection Branch. 80/09/02 in
- -8009180177 Responds to NRC ltr re deviations noted in QA Insp Repts 99900400/79-04 & 99900400/80-01 Corrective actions.NPQD calculation procedure revised to define common knowledge design inputs QUILBERT, D. E. Bebcock & Hilcox Co. 80/08/06. 2pp
- -BOOY:BOIGS Responds to NRC ltr re deviations noted in QA Insp Repts 79700400/79-04 & 79900400/80-01 Corrective actions.

 evaluation of calculation pactages shows common knowledge theory to be technically sound OUILBERT, D. E. Babcock & Wilcox Co. 80/06/24. 10pp.
- 009180484 Ack receipt of 800613 & 0813 ltrs informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99700245/80-Q1. POTAPDVB.U Region 4, Dallas, Vendor Inspection Branch. 80/08/26
- -8009180490 Responds to NRC 800509 itr re deviation noted in GA Program Insp Rept 99900245/80-01 Corrective actions revised Section 3 Class I valve drawings to have flange backfacing machined using 3/16-inch radius tool bits.

 LITTLEFIELD, J. J. E. Lonergen Co. 80/08/13. 1p
- 8009180495 Responds to NRC 800509 ltr re deviation noted in GA Program Into Rept 97900245/80-01 Disputes NRC findings of deviation re backfacing machining details Drawings under review.

 General note requirements to be incorporated.

 LITTLEFIELD, J J E Lonergan Co 80/06/13 2pp.
- BD09180500 Forwards GA Program Insp Rept 99700245/80-01 on 800421-22 & notice of deviation PDTAPDVB. U. Region 4. Dallas. Vendor Inspection Branch 80/05/09.
- 0009180502 Notice of deviation from insp on 800421-22 # Region 4. Dallas. Office of the Director 80/05/08 ip
- 800918050B GA Program Insp Rept 99900245/80-01 on 800421-22
 Noncompliance noted:removal of radius of Bonnet 0022010172
 by backfacing operation contrary to code requirements &
 drawing dimensions.
 KELLY-W D , WHITESELL-D.E Region 4. Dallas, Vendor Inspection
 Branch. 80/05/08. 9pp.
- 09180027 Forwards GA Program Insp Rept 99900039/80-01 on 800604-05 No noncompliance noted "OTAPOVS.U Region 4. Dalles. Vendor Inspection Branch. 80/07/07 2pp
- 1009180536 GA Program Insp Rept 9990059/80-01 on 800604-05 No noncompliance noted Major areas inspected corrective action to sandric considerations repotential const deficiency involving Turkay Point Unit 4 including assessment of cause BUTTON. J W. WHITEBELL.D E Region 4, Dallas, Vendor Inspection Branch 80/07/01 App.
- 9180562 Forwards GA Program Insp Rept 99900344/80-01 on 800609-12 to moncompliance noted OTAPDVB.U Region 4. palles, Vendor Inspection Branch 80/07/03 as

- --8007180366 QA Program Insp Rept 99900344/80-01 on 800609-12.No noncompliance noted, Major areas inspected audit control, records, welding, nondestructive testing & design document control HUNTER.V H , WHITEBELL.D E. Region 4, Dailas, Vendor Inspection Branch 80/07/01 3pp.
- BO09190014 Ack receipt of 800703 & 0804 ltre informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900297980-01. PDTAPOVB, U Region 4, Dallas, Vendor Inspection Branch 80/08/28 in
- --8009190017 Responds to NRC 800716 ltr re deviation noted in QA Program
 Insp Rept 99700259/80-01 Corrective actions base metal
 repair & Incomel cladding completed by temper bead welding
 technique
 HHITE.C.E., ALMEDA.D.C. C-E Power Systems 80/08/04 2pp
- ~-B009190020 Ack receipt of 800703 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 9990259/80-01 Add1 info requested POTAPOVS.U Region 4: Dellas, Vendor Inspection Branch, 80/07/16 1b.
- ---B009190024 Responde to NRC B00606 ltr re deviation noted in QA Program
 Insp Rept 99900259/80-01. Corrective actions documentation
 for production welding etressed in training program &
 voltage meter on power source replaced.
 WHITE: C E , ALMEDA, D. C C-E Power Systems, 80/07/03. 3pp.
- --B009170027 Forwards QA Program Inep Rept 99900259/80-01 on 800519-23 & notice of deviation POTAPOVS:U. Region 4, Dallae, Vendor Inspection Branch. 80/04/08. 28p.
- --8009190027 Notice of deviation from inep on 800519-23.
 * Region 4. Dallae. Office of the Director 80/06/05. Spp.
- --8009190031 QA Program Inep Rept 99900259/80-01 on 800519-23.

 Noncompliance noted; use of nonspecified detail welding procedurs & performance of production welding using amperage & voltage values above allowed ranges.

 POTAPOVS.U., ELLERSHAN, L. E., BARNEGI Region 4, Dallas, Vendor Inspection Branch 60/06/05, 10pp.
- 8009250307 Ack receipt of 800730 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 97900346/80-01 POTAPOVS.U Region 4, Dallas, Vendor Inspection Branch 80/08/21.
- --8009250313 Responds to NRC 600830 Itr re deviation noted in GA Prograd Insp. Rept 99900346/80-01. Corrective actions: PGRe changed to reflect correct F number applicable at time of qualification.
 FRANCOIS.E. I., HUCK, H. J. Veian Valve Co. 80/07/30. 3pp.
- --8009250325 Forwarde GA Program Inep Rept 99700346/80-01 on 800603-05 to notice of deviation PDTAPGVS.U. Region 4. Dallas, Vendor Inspection Branch. 80/06/30.
- --8009250326 Notice of deviation from insp on 800603-05.

 * Region 4, Dallee, Vendor Inspection Branch. 80/06/27. 1p.
- ---B009250327 GA Program Insp Rept 99900346/80-01 on B00603-05 Noncompliance noted test coupen not welded within MPB specified amperage range. HHITEELLID E r KELLEY-M. D. Region 4. Dallas, Vendor Inspection Branch, 80/06/27 13pp
- 8009290310 Ack receipt of 800724 & 0821 ltrs informing NRC of steps taken to correct deviations noted in GA Program Insp Rept 99700049/80-01 PGTAPOVS,U. Region 4, Dallas, Vendor Inspection Branch. 80/09/03. 1p
- --8009270312 Responds to NRC 800623 ltr re deviations noted in GA Program Insp Rept 99700049/80-01. Corrective actions; corrected procedures for visual insps & calculations include backseat loading on cover TOMEATTI.V.W. Atwood & Morrill Co., Inc. (subs. of Foster Wheeler Corp.). 80/08/21 8pp
- --8009270314 "Performing Visual Insp of Matls & Items " LYONS.H D Atwood & Morrill Co., Inc. (subs. of Foster Wheeler Corp.), GC-210-4. 80/05/12. 2pp.

- --B009290315 Forwards JM Cowley ltr inadvertently emitted from response to GA Program Insp Rept 99900049/80-11 re Class 2 Mys Stop Chect Valve w/hydraulic operator TONEATTI, V.M. Atwood & Morrill Co , Inc (subs of Foster Wheeler Core) 80/07/31 2pp
- ---B009290316 "Design Stress Rept for 16-inch -- 1500# Class 2 Mye Stop Check Valve M/Hydraulic Operator " a Atwood & Morrill Co , Inc (subs of Foster Wheeler Corp). 79/01/09. 3pp
- ---8009290318 Responds to NRC 800625 ltr re deviation noted in GA Program Intel Rept 99900049/80-01 Corrective actions surface defects caused by arc strikes ere being eliminated & area around temporary attechments marked so that area cen be identified TONEATTI, V.W. Atwood & Morrill Co., Inc. (subs. of Foster Wheeler Corp.) 80/07/24 2pp.
- --B009270320 Forwards GA Program Insp Rept 97700049/80-01 on 800508-06 & notice of deviation.
 POTAPDVB.U. Region 4, Dailes, Vendor Inspection Branch 80/06/25
- --B009290322 Notice of deviation from insp on 800305-06.
 * Region 4. Dailas, Office of the Director 80/06/19. 2pp
- --B009270323 GA Program Insp Rept 99700049/80-01 on 500505-06.

 Nancompliance noted:design & stress rept did not include calculations force imposed by operator in closed position & procedures did not provide for removal of surface defects.

 WHITESELL, D.E., KELLEY, M.D. Region 4, Dalles, Office of the Director 80/06/19. 14pp

REQULATORY QUIDES

- 7909040729 Comments on proposed Reg Guide 1 XXX:considers static calibration for manual scenning is more repeateble, scanning at increased (2X or 6dB) sensitivity level enhances resolution Guestions determinetion of near/far degradation. MOORE:R.L. Affiliation Unknown. 79/07/19 2pp.
- 8009020529 Forwards notice of issuance & availability of draft Reg Quide B. (OH 710-4): "Health Physics Burvey in U Mills," for gublication in FR. CHLLK, B. J. Office of the Becretary of the Commission, 80/08/15, 1s.
- --B009020331 Notice of issuance & availability of draft Reg Guide E (QH 710-4). "Mealth Physics Survey in U Mills "
 OOLLER, K R. Division of Siting, Health & Bafeguards Standards B0/08/11 2pp
- 8009030061 Forwards notice of issuance & availability of Reg Ouide 8.25. "Calibr & Error Limits of Air Sempling Instrumente for Total Vol of Air Sempled." for publication in FR GHILK.8 J Office of the Becretary of the Commission 80/08/15.
- --8009030067 Notice of issuance & availability of Reg Guide 8 25, "Calibr & Error Limits of Air Sampling Instruments for Total Vol of Air Bampled "
 HINCOUE, R. B. Office of Standards Development, Director. 80/08/12
- BOOG9090147 Comments by Instituto de Investigaciones Electricas on Reg Quide 1,57. "Design Limits & Loading Combinations for Metal Primary Reactor Containments Bye Components." Regulatory position portion seems incomplete LINARES,F. Affiliation Unknown FCL/01/80 80/07/03 1p.
- BOO91006R8 Advises of inebility to endorse Reg Quide 1.97.Revision 2 in present form Suggests that scope of guide be reduced or contents clarified. PLESET, MS AGRS Advisory Committee on Reactor Bafeguards BO/08/13, 3pp.
- 8009100672 Forwards corrected pages & supplemental info submitted as enc! to 800410 ltr re proposed reg guide, "Lightning Protection for Nuclear Power Plents."

 JOHNSON, I. 8 Affiliation Unknown. 80/04/18 16pp
- 8009120539 Comments on proposed Revision 1 to Reg Guide 8 12, "Criticality Accident Alarm Bys " Exampting new fuel storage areas from criticality monitoring will improve revision since these areas fit into size constraints, BULLIVAN.T. J Gensumers Power Co. 9552, 80/07/25 ip,

- 8009120540 Comments on proposed Revision 1 to Reg Ouide 8 12, "Criticality Accident Alarm Sys." Page 2, second line "handled, used or stored" does not explicitly include transports even though transportation is addressed BDSWELL, J & C I du Pant de Nemours & Co , Inc 80/07/23 ip
- 8009150167 Comments on proposed Revision 4 to Reg Quide 8 8 "Info Relevant to Ensuring That Occupational Radiation Exposures WIII be ALARA " Rule ludicrous as NRC is requesting more stringent requirements for industry then for NRC steff. CHASE. Q Affiliation Unknown 80/08/15 2pp
- 8009150174 Comments on proposed Revision 1 to Reg Guide 10 6: if requirements for details ere eliminated reg guide would be more useful aid to obtain license & would not require amends whenever supplier relocates &ur model number is changed CADENA, D. O Southwest Research Institute 80/08/08 ip
- 8009130225 Comments on proposed Reg Quide OH 902-4, "Instruction re Risk From Occupational Exposure " Hell done summary of radiation risk on fairly exphisticated level. Hati unlikely to be understood by some radiation workers

 DVERBERGER, C Q Kichigan, Univ of, 80/07/29 28p
- HO09150230 Comments on proposed Reg Guide DH 902-4, "Instruction re Risk From Occupational Rediation Exposure " Guide conclusion that spreading out dose may reduce risk is contrary to "Low Dose & Leukenta Rept "
 TUMA.A T Popular Bluff Hosp Popular Bluff.HO GO/07/24 2pp
- 8009180243 Comments on proposed Reg Guide OH 902-4. "Instructions re Risk From Occupational Radiation Exposure." Info must be presented in menner which can be understood & easily comprehended by worker.

 HICKS,M M Utility Horkers Union of America 80/07/25, App
- 8009150309 Comments on proposed Reg Guide OH 902-4, "Instruction re Rist From Occupational Radiation Exposure " Analogy between smoking & radiation exposure is inappropriate because smoking risk is much greater than redi
- 8009150320 Comments on proposed Reg Guide OH 902-4. "Instruction Re Risk From Occupational Radietion Exposure." Bias renders instruction meeningless & may invite cerelessness LENIS.H.I. Affiliation Unknown 80/07/23. 19
- B009160366 Addresses requirements of Reg Ouide 1,92 pertaining to ciasely spaced modes & lists supporting refe. Vendor will recommend SAR amend for plents under NRC review GANG. N.O Oeneral Electric Co MrN-137-BO. B0/09/08
- 8009190299 Responds to FOIA request for 15 documents listed in bibliography of NUREQ-0625, "Rept of Siting Policy Task Force." Documents 6-8 & 13 are available in PDR Forwards remaining documents. FELTON.J M. Division of Rulss and Records 80/09/04, ip
- --8009190587 BECY-79-362
 Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants. For determination of site acceptability & adequecy of engineered safety features MINGOUE, R B Diffice of Standards Development, Director 79/06/04
- --8009190612 Draft Reg Quide 88 724-4, "Atmospheric Dispersion Models for Potential Accident Consequence Assessments at Nuciear Power Plants " # Office of Btandards Development, Director 79/06/04 29pp.
- ---8009190624 Draft value/impact assessment of proposed Reg Quide SS 724-4. "Atmospheric Dispersion Models for Potential Accident Consequence Assessments at Nuclear Power Plants." Reg guide should be developed Documentation and Potential Potentia
- B009190703 Comments on proposed Reg Quide OH 902-4 re occupationel radiation exposure because amployers have conflict of interestricourses of instruction about be established which would be administered by agencies other than employer COLLINS.F. Oii.Chemical & Atomic Workers Intl. 80/09/14 3pp
- E009190717 Comments on proposed Reg Guide QH 902-4 suggests some specific rewording.
 LQVAAS.A Colorado State Univ 80/08/14 ip
- 8009190726 Requests proposed Reg Ouids OH 941-4. "Info re Ensuring That Occupational Radiation Exposures at U Mills Hill be ALARA " OHLGSON, K Affiliation Unknown 80/08/19. ip.

NONDOCKETED ITEMS

- 1009170732 Communts on proposed Reg Quide OH 710-4 favors publication wind major changes.
 BUSTRAVAGE, E M Affiliation Unknown 80/08/19 ip.
- EB RESEARCH AND TECHNICAL ASSISTANCE REPORTS
- 00000010 E0040010
 "Isaw Input for LDFT RELADS Calculations"
 KEE.E J. BHALLY, P. J., HINTERS, L. E040 Idaho, Inc. FIN A-6048.
 EE0-LDFT-3199, E07000E
- 009050200 Bubmits bi-monthly status ltr re LNR pressure vessel desimatry program for Apr & May 1980. Document clearance request publications release & charts of ABTM stds for surveillance of nuclear reactor pressure vessels encl PRESTONIC C. Hanford Engineering Development Laboratory 8002754 80007718 9pp.
- 2090000399 "LDFT Lwad Rod Test Results Evaluation," internal technical rest rest BRISKELL, W.E., TDLMAN, E.L. EO&O Idano, Inc., USNRC-P394 80/07/90 73pp.
- 109050405 *PRF-LOCA Test Series. Test LOC-6. Thermal Fuel Behavior Program. Experiment Predictions. "LOFEDRE. N. T. NATERMAN, M. E., YACKLE, T. R. EQ&O Idaho, Inc. FIN A-8041, EQQO-TFBP-3193 80/07/31. ip
- 09050409 "Multirod Burst Test Program Preliminary Results of 8-5 (0)8) Bundle Test, quick look rept CMPHAN,R,H, CROMLEY,U,L, HAYMES,R F. Oak Ridge National Laboratory. FIN 8-0120, DRML/M85-5. 80/07/14. 48pp.
- 09070132 "Physical Protection of Nuclear Facilities," monthly progress rapt for Jul 1780. HARKAN, L. D. Bandia Laboratories, FIN A-1060 80/08/19, 7pp
- 99090770 "Bafequards for Proliferation Resistant Fuels," progress rept for Jul 1980. Brookheven National Laboratory FIN A-3221. 80/08/20 389
- PSIGNABE POWER-Cooling-Mismatch Test Series Test PCM-7," quick look ept. PARKE, D. T., LEFEBRE, N. T., MCCARDELL, R. K. EOLG Idaho, Inc. FIN -6041. EOQ-TFBP-5218. BO/08/31. BBpp.
- 9100508 "Advanced Instrumentation for Reflood Studies Program," ereign trip rept. ADU.B. G.: IABRISKIE, W.L. Dak Ridge National Laboratory, FIN -0413. DANL/FTR-888. 80/08/11. 9pp.
- 7100520 "LDCA Test Heries: Test LDC-6: Thermal Fuels Behavior rogram: " Experiment operating spec. ACKLE, T.R.: WATERMAN:M E. EORG Ideho, Inc FIN A-6041 00-1589-5171, 60/07/01, 62pp.
- 1100530 "Cladding Craep (CCSTRN & CCSTRS) Fuel Behavior Hodel twilopment," interim rept.
 ORMANN D L. EO&O Idaho, Inc. FIN A-6050 EEQ-CDAP-5216
 1/07/31. 4708.
- '110416 "Bafeguards for Proliferation Resistant Fuel Cycles,"
 formal monthly progress rept for June 1980
 DRELLI J Brookhaven National Laboratory FIN A-3221 80/08/11
- lid417 "Accident Aerosol Characterization," informal monthly offers rept for Jul 1980 Institute, Pacific Northwest IARBKI.P.C. Battalie Memorial Institute, Pacific Northwest baratory. FIN 8-2287, 80/08/12 3pp
- 110421 "Acoustic Emission/Flaw Relationships for Inservice iltering of Nuclear Pressure Vessels," informal monthly igress rapt for Jul 1980 | Battelle Amerial Institute, Pacific TOW, P. II. KURTZ: R. J Battelle Amerial Institute, Pacific Town, II. KURTZ: R. J FIN B-2088. 80/08/20 Spp
- 10403 "Decontamination as Precureor to Decommissioning," Informal thly progress rept for Jul 1980.

 10404 D. Battelle Hemorial Institute, Pacific Northwest RIGO, L. D. Battelle Hemorial Institute, Pacific Northwest Print B-2303 80/08/14, Sep

- 8009110574 "Advanced Instrumentation for Reflood Studies," foreign trip rept LLOYD.D.B., DINKINS,M A Dak Ridge National Laboratory FIN 8-0413. DRNL/FTR-892. 80/08/08 5pp
- B009110634 "Bafeguards Analysis for Byproduct Matls & Small Quantities of BNN: "topical rept summary of docket file survey RANBOLPH:M.L. Oak Ridge National Laboratory FIN B-610B, GRNL/HASRD-89 80/08/05, 25pp
- BOO9110876 "Evaluation of Docket Files of Terminated Licenses," monthly progress rept for Jul 1980 HOLONAY.C.F. DICKENSON,H H. Dak Ridge National Laboratory. FOM A-9085-7 ORNL/HABRO-88 80/07/31 2166
- BOO9110885 "Program for Standardized Analysis of Fuel Shipping Containers," quarterly rept for Apr-June 1980 WHITESIDES O E., WESTFALL, R M Oak Ridge National Laboratory FIN B-0172 ORNL/CSD/INF/80 80/07/29, 1989
- BOG9120567 "Div of Reactor Safety Research-ORNL Programs, " monthly rapt for Jul 1980 HYNATT, F. R. Dak Ridge National Laboratory, 80/08/10 30ps.
- BOD9120571 "Definition of Parameters for Major Accidents at Hasts Bolidification & Spent Fuel Storage Facilities," sonthly progress rept for Jul 1980 FEDERICK, E. J. Dak Ridge National Laboratory FIN 8-0425. 80/09/15 3pp
- 8009120372 "Investigation of Ventilation Component Response to Large Pressure Puises," monthly progress rept for June 1980 OREGREYLM 8. Los Alamos Scientific Laboratory. FIN A-7028 WX-8-3775 80/08/08 2pp.
- 6009120581 "Steam Water Instrumentation Development Program & Modeling." Foreign trip rept.
 THOMAS.D. & Dak Ridge National Laboratory FIN 8-0427.
 ORNL/FTR-897 80/08/13 9pp.
- BOOP120590 "Integrated Geophysical & Geological Study of Tectonic Framework of 38th Parellel Lineament in Vicinity of Intersection Westension of New Madrid Fault Zone," annual progress rept FYGO.

 BRAILE, L. W. Purdue Univ, KELLER, C. R. Texas, Univ. of, El Paso. LIDIAK, E. O. Pittsburgh, Univ. of, FIN B-5971. NRC-04-74-323 BO/OB/31. 142pp.
- 8009120666 "Loft Monthly Progress Rept," for June 1980. KAUFHAN:N C. E010 Ideho, Inc LD-MR-007. B0/07/31. 10744.
- 8009320733 "Forecesting Electricity Demand by State & by Util Svc Area," montbly progress rept for June 1980, CHERN, W. S. Dak Ridge National Laboratory FOM 8-0190-8, ORNL/ED/EAB-80, 80/07/15, 5pp.
- 8009:503:: "Advanced Instrumentation for Reflood Studies (AIRS), " monthly highlights rept for June 1980. HYNATT,F.R Dak Ridge National Laboratory, 80/07/10, 30FP.
- 8009130843 Forwards agenda for 801027-31 eighth water reactor safety research info meeting at NBS in Gaithersburg MD. BUDNITZ-R J Office of Nuclear Regulatory Research, Director 80/07/28. 200p.
- 8009160492 "Investigation of Accident-Induced Flow & Matl Transport in Nuclear Facilities." monthly progress rept for Jul 1980 MARTIN.R A., GREGORY, W S. Los Alamos Scientific Laboratory. FIN A-7029. WX-8-3786. 80/08/14. 3pp.
- 8009140498 "Matl Control & Accounting Effectiveness Evaluation
 Development," monthly progress rept for May 1980.
 POGOID, A Lawrence Livermore Laboratory FIN A-0115. 80-80-08-02.
 80/08/07. 11sp
- 80Q9190401 "Evaluation of Alternative Packages for Solidified & Unsolidified (Dewatered) Low Level Ion-Exchange Resint & Filter Sludge Waster," informal rept MANAKTALA, H. K., NICOLOSI, S. L. Brookhaven National Laboratory FIN A-3158, BNL-NUREO-28199 80/08/31 163pp.
- 8009190768 "Containment Analysis Development," informal rept. DDYLE:R J., MINOS.W.J., RAMSTHALER, JA EOGO Idaho, Inc. FIN A-6042 E00-CDAP-5166, 80/05/31 157pp
- 8009240253 "Environ Assessments of Fuel Cycle Facilities," monthly progress rept for Jul.1980.
 IITTELH E. Dak Ridge National Laboratory. FIN 8-0279
 ORNL/ED/EI8-134 80/07/31 6pp

8007240291 "Application of Internal Friction Nondestructive Evaluation Tschnique for Detecting Incipient Cracking of Eupass Lines & Pipes in BHR Piping Bys." progress rept for 800623-0815, Repts 7 & 8

* Daedalean Associates, Inc NRC-04-78-242 80/08/15 7pp

BOOP2A0069 "Comparison of Computed Density Profiles from Transient Flow Callbr Facility, Using Three or Six Beam Messurements " MEACHUM, T. R. HAMBACH, J. L., HANSON, D. J. E0&0 Ideho, Inc USNRC-P374 80/08/14 3ipp

9007250075 "LOFT LTSF Thermocouple Thermal Analysis to Datermine Transient Temp Response "
HOMELL, S. K EQ&O Idaho, Inc RE-A-SO-055 80/06/23 17pp.

8009260099 "LOCA Test Beries.TC-3.Experiment Operating Spec "
YACKLE.T.R , NATERMAN.M E. EQ&O Idaho, Inc FIN A-6041
EQQ-TFBP-5221 80/08/31, 54pp

GOO7260542 "Analysis of Semiscale Mod-1 LOCE 8-04-6 Using TRAC-Pia Computer Program," preliminary assessment rept DEMMIE.P.N E0%0 Idaho, Inc FIN A-6047 EE0-CAAP-5181, B0/06/30, R2m.

8009260550 "Assessment of Radiation Doses Resulting from Releases of Rn-222 & Ra-226 from U Mining & Milling Activities "Monthly progress rept. Mar 1980 TRAVIS, C.C., MCDOMELL-BOVER, WATSON, A.P., Dek Ridge National Laboratory. Fin B-0281 ORNL/HABRD-76 80/04/22. Spp.

8009260538 "Measured Effects of Fuel Rod Internal Qas Pressure & Xenon Contentration in Operating Fuel Rode & Comparison H/Basic Theory & FRAP Calculatione," preliminary rept MILLER, N. . APPELMANS, A D ECOR Idaho, Inc. FIN A-6041. EQQ-TFRP-5222 80/08/31 93pp.

REVIEW ORP NRC RESEARCH REVIEW GROUPS

8009150562 Notifies of 800903 seminar In Bethesda. MD re matls aging. FEIT.R Division of Reactor Safety Research. 80/09/03 2pp.

RM RULEMAKING

BOO9100490 Commente on RM 50-5.public should be advised of advantages & disadvantages of implementing Pu recycle, NRC should not have terminated efforte on GESMO fuele.

DECHER.U. Affiliation Unknown. 60/09/03, 1p

8009160224 Requests GEBMO re fuel be completed. Info is needed for future dscielants re reprocessing of spent nuclear fuel. VILLEMY, Q. R. Affiliation Unknown. 45FR33933 003. 80/09/08, ip

BOO9160420 Comments on rulemaking 50-5 GEBMD proceedings should be respected to provide early procedural fremework for subsequent licensing.
RICHARDS,R.B. General Electric Co. 45FR53933 004, 80/07/08, 2pp.

6009170366 Commente on rulemeking 50-5 re mixed oxide fuel, GESMO & other recycle-related licensing proceedings should continue Poetitive affirmative action to approve licenses recommended. KIRK-H.F. Hilliam F Kirk. 80/08/28 4pp.

9009220231 Comments on rulemaking 50-5 GESMO proceedings should not be respended. Apposes any action which would be contrary to non-proliferation policy.
MCLAUGHLIN.M.T. Affiliation Unknown. 80/09/12. 1p.

8009220233 Commente on rulemaking 50-5; CEBMO proceedings should be respensed. Recycling of nuclear fuel is greater proliferation risk. Proceedings cen clear way for sensible nuclear policy LAMSREMONT, E. N. Affiliation Unknown 80/09/16, ip.

8009220237 Comments on rulemeking 50-5:0ESMG proceedings should be rasumed & completed Reprocessing & recycle of LWR fusl should be considered.
TROWLFANIBIS.N. Affiliation Unknown ED/09/15, ip.

8009220240 Comments on rulemaking 50-5.GESMO proceedings should be resumed immediately due to INFGE results & domestic public opinions.

BARRY.D. Affiliation Unknown. 80/09/14 1p.

BOO9220245 Comments on rulemaking 50-5-supports resumption of QEBMO proceedings, NRC should evaluate nuclear fuel recycling on technical/environ basis.

Octivizmanip. Affiliation Unknown 80/09/16 ip

SECY POSITION PAPERS BEFORE THE COMMISSION

8009030252 SECY-80-342
Notifies of proposed contract rensual to SRI Intl for continuod research in lifer technology No conflict of interset would result from award. Findings & determination

DONODHUE.D. J Office of Administration 80/07/23 6pp.

--8009030255 Findings & determination statement proposing research by SRI Intl on "Analysis of Atmospheric Diffusion Through Application of Lidar Technology "HORTON, K. V Research Contracts Branch HALMAN, E. L. Division of Contracts 80/06/19 3pp

S009040459 BECY-80-349

Bubmits semiannuel rept of 3D program cost 4 schedule Last of Core 1 3D ECCS reflood & refill teets in JAERI Cylindrical Core Yest Facility completed in May 1980. Facility ebut down until Jan 1981. Supporting mati enci BUDNITZ.R. J Dffice of Nuclear Regulatory Research, Director B0/07/25 Spp.

8009040461 SECY-80-253
Informs of Ofc of Nuclear Regulatory Research comments on ACRB rept to Congress - NUREO-0657, "Review & Evaluation of NRC Safety Research Program for FYB1." Annual ACRB raview is extremely valuable Specific comments encl. SUDNITZ, J. Office of Nuclear Haguletory Research, Director. 80/05/19 50p

8009050123 Add1 response to FOIA request for records pertaining to proposed fire protection rule FELTON, J M Division of Rules and Records. 80/08/05 ip.

--8009050126 Forwards Sandia Labs 790919 & 0904 memos re fire protein nuclear plants & SECY-79-478 updating status of NRC actions in response to UCB patitions
HANAUER, B. H THI-2 Unresolved Safety Issues 79/11/08 Spp.

--8007050131 SECY-77-478
Informs Commission of present statue of NRC actions in response to UCB petition for emergency & remedial action & petition for reconsideration Seven items have been completed
DENTON, H.R. Diffice of Nuclear Reactor Regulation, Director, 77/08/08, 4pp

8009230141 BECY-75-338
Recommends that Commission approve correspondence w/
concerned parties to obtain clarification of comments on
750308 FR notice re provisional view on Pv recycle
CHAPMAN, K R Office of Nuclsar Matsrial Safety & Bafsguards
75/07/03 5ps.

--B009230145 Responds to SECY-75-33B re comments received during Purecycle proceedings. Recommendation should be accepted w/ caution. Request for clarification will delay comment procedures.

BTRAUSS.P.L. Office of the General Counsel. 75/07/07. 2pp

--8009230274 BECY-75-638
Forwards draft FR notice re scope & procedures for generic
Pu recycle environ statement & interim licensing actions.
BHAPAR.H K Office of the Executive Legal Director. 75/11/10

8009090083 SECY-80-293
Weekly info rept for wk ending 800613
REHM.T A Office of the Executive Director for Operations.
80/06/18 40pp

8009090799 BECY-79-400
Informs of Ofc of Nuclear Regulatory Research comments on ACRB rest to Congress - RUREG-0476, "1978 Review & Evaluation of NRC Safety Research Program " ACRB comments & recommendations useful Specific comments encl LEVINES. Office of Nuclear Regulatory Research, Director, 3370 79/07/06, 26pp

8009150410 Forwards responses to 800527 questions re info provided by NRC on 800501 concerning differences in role of NRC & Executive Branch in processing export requests, Supporting documentation snc1
AHEARNE, J. F. Commission 80/08/22 13pp

---8009150418 BECY-78-216A

Forwards documents re proposed license for Transnuclear, Inc
to export high-enriched U to Bweden

SHEA.J.R Office of International Programs, Director. 78/05/11

Spo

- 8009180269 Transcript of 800904 public meating in Hashington. DC rediscussion & vote on enforcement policy Pp 1-91

 * Commission 80/09/04 93pp
- --8009180277 SECY-80-139A
 Recommends adoption of proposed policy of enforcement action as interim guidance Draft FR notice encl
 STELLD.V Office of Inspection & Enforcement. Office of the Director 80/08/27 50pp
- --8009180284 Summary of Commission 800319 meeting in Washington,DC re SECY-80-139 desling w/NRC enforcement progrem Revised policy discussed but no final conclusions reached CHILK.5 J Office of the Secretary of the Commission 80/03/28 in
- --8009180291 Comments on SECY-80-139 re enforcement policy NRC divs must submit elternatives to Executive Director of Operations AHEARNE.J F Commission 80/03/24. 4pp
- --8009i80298 Comments on proposes anforcement policy Policy paper is good first step but of little use if licenses commitments & NRC stds are not in anforceable form BRADFORD.PA Commission 80/04/09. 18pp
- 8009190299 Responds to FOIA request for 13 documents listed in bibliography of NUREG-0625. "Rept of Biting Policy Tack Force." Documents 6-8 & 13 ers available in PDR Forwards reseining documents FELTON.J H Division of Rules and Records 80/09/04 1p
- --8009190320 SECY-75-518
 Responds to Commission direction to develop alternative plans for revision of code re power reactor siting regulations. Forwards diagram of schaduling network.makeup of study panel & study & task scope of work
 MINOGUE.R B Office of Standards Devalopment, Director. 75/09/12.
 6pp.
- 8009190358 Forwards SECY-75-286 concerning reactor siting policy Issue is large & complicated NRC will prepare oral briefing to outline principal areas of concern & potential solutions. 908510K, L V Office of the Executive Director for Operations 76/05/25 ip
- --8009190366 SECY-76-286
 Forwards "Staff Review of Site Evaluation Policy &
 Practice "Recommends that Commission hold further
 discussions w/Directors of NRC ofcs to devalop basis for
 decisions concerning future site evaluation policy,
 MINIGUE,R D Office of Standards Devalopment, Director 76/05/25.
- ---B009190370 "Steff Review of Site Evaluation Policy & Practica." # Commission 76/05/25 55pp
- --8009190377 Provides recommendations from review of siting policies for licensing nuclear facilities Recommands that criteria be developed for other portions of fuel cycle, Related documents tion and KERR-W AGR8 - Advisory Committee on Reactor Bafeguards 75/12/10 35pp
- -8009190383 Informs that Commission has reviewed SECY-75-818 re reactor siting Program described re development of policy paper is not fully consistent wintent of Commission directive Lists Commission requests re program ANDERS, H A Office of the Executive Director for Operations 75/10/30 3pp.
- 30091903B6 Discusses review of 760301 memo ra reactor site evaluation & practice Paper needs significent improvement in defining further actions & providing basis for Commission decision on those actions

 HUBERHANN B. Office of Policy Evaluations 76/03/19 1p
- -8009190390 Discusses review of reactor site evaluation policy & practice Review is well written & makes persuasive statement for thorough ravision of existing site evaluation policy. Proposed actions re-siting policy issues encl STRAUSS.P.L. Office of the Ceneral Counsel 76/04/01 13pp.
- --B009190394 SECY-76-286A
 Requests Commission approval of development plan for nuclear facility siting policy & practice revision Recommends that Commission approve proposed plan & direct staff to proceed w/programs Related documentation encl
 HINDQUE,R B. Office of Standards Development, Director 76/12/14, 2400

- --B009190397 Forwards comments on development plan for nuclear facility siting policy & practice Requests that comments be reviewes, modified commented on & summarized REMA.T A Office of the Executive Director for Operations. 76/11/23 lp.
- --8009190400 Discusses development plan for nuclear facility siting policy & practice revision. Principal concern is whether NEPA considerations will receive adequate attention STRAUSS.P.L. Office of the General Counsel 75/11/23 2pp
- --8009190464 Comments on 761103 draft of "Davelopment Plan for Nuclear Facility Siting Policy & Practice Revision " Draft is not adequate response to Commission 760830 guidance Ofc of 8tds Development response encl HUBERHAN.8 Office of Policy Evaluations 76/11/11 13pp
- ---B0091904B0 Responds to 760831 request for comments on Commission review of BECY-76-286, "Staff Review of Reactor Bite Evaluation Policy & Prectice." Ofc of Stds Davelopment will produce program plen, re reformulation of siting policy MINGOUS, R B Office of Standards Development, Director. 76/09/24, 2pp
- --BOD7170484 Recommends public release of SECY-76-286 & BECY-76-286A on siting policy & practice Requests raview & concurrance in placement of documents in PDR.
 MINDGUE.R B Office of Standards Devalopment. Director. 77/03/02.
- --8009190498 Responds to 770302 request to review SECY-76-286 & SECY-76-2864 & concurs w/recommendation to place documents in PDR Release of documents should be coordinated w/Ofc of of General Counsel SHAPAR.H K Office of the Executive Legal Director 77/03/18.
- ---8009190514 SECY-77-288
 Forwards proposed general policy statement on nuclear reactor site evaluations Recommends that Commission provide guidance on proposed policy statement & directive re development of replacement regulation.
 MINOQUE, R. B. Office of Standards Development, Director. 77/06/07
- --8009190520 EECY-77-288
 Comments on general policy statement re nuclear reactor sita swaluations Paper is inadequate & does not set forth range of options open to Commission. Possible legal problems exist w/general policy statement approach as proposed KELLY.J.L. Office of the General Counsel. 77/06/02 3pp.
- --8007i90526 Forwards comments on 770527 draft of "General Policy Statement on Nuclear Reactor Site Evaluation Policy."

 General approach is inadequate for Commission decision re general reactor site evaluation policy

 TERRELL.N Office of Policy Evaluations. 77/06/02 iipp.
- --B009190532 BECY-77-433

 Bubmite policy statement on alternative site evaluations under NEPA for nuclear generating stations. Recommends that Commission require revism & approval of applicant site selection process prior to acceptance of CP application. MINOGUE.R. B. Office of Standards Davelopment, Director. 77/08/16
- --8007170537 Comments on draft of "Policy Statement on Alternative Sits Evaluation Under NEPA for Nuclear Stations " Paper is suitable for Commission review Value of paper could be enhanced by encl comments.

 PEDERSEN.K Office of Policy Evaluations 77/07/18 App
- ~-8009190544 Comments on proposed policy statement on evaluation of alternate sites. Policy statement does not clearly identify how Commission will act to enforce stds. Related documentation encl
 KELLEY.J.L. Office of the General Counsel 77/07/25 Spp.
- --8009190550 BECY-78-371
 Revises EECY-77-289, "General Policy Statement on Nuclear Power Reactor Site Evaluations " Recommends approval of general statement of current policy on nuclear power site evaluations for publication in FR & draft ltr.
 MINGOUS, R. B. Diffice of Standards Dayslopment, Director 78/07/03.
 GOpp.

- --G009190357 Lists Commission requests for further action to be taken on 8ECY-77-288 concerning siting policy & practice Four siting policy issue papers should be forwarded to Commission as proposed in schedula CHILK.8 J. Office of the Secretary of the Commission 77/06/30 Zee
- --8009190368 Comments on general policy statement on current nuclear reactor sits avaluation Lists items which should be considered before statement is adopted & published Ofc of Sids Development responses encl
 BHMPAR, M. K. Office of the Executive Legel Director 78/05/08
 Bpp
- --9009170587 SECY-79-362
 Informs Commission of proposed changes to meteorological addel used in essessing potential accident consequences for nuclear plants, for determinetion of site acceptability & adequacy of engineered safety features MINDOUS, R B. Office of Standards Development, Director 79/06/04, 780.

- B009240569 BECY-80-393
 Forwards Executive Branch response on pending Transnucleer,
 Inc application for license to export highly enriched U to
 Jegan.
 BHEA: J. R. Office of International Programs, Director. 80/08/22
 is
- B009238276 Transcript of 800904 Affirmation Bession 80-39 to discuss fees for withdrawl of applications for CPs & CLs in Washington. DC. Pp i-2. Dreft proposed rules encl. Cameission 80/09/04 20pp
- --BO09250280 BECY-80-344
 Recommende recovery of licensing review fees for applications denied, withdrewn, evepended or poetponed Dreft FR notice ent.
 DONOGHUE, D. J. Office of Administration. 80/08/04 lipp
- BOOP290021 Trenscript of 800916 public meeting in Washington, DC rediscussion & vots on Commission progrem to review DL applications. AM session, Pp 1-62 AMEARME, J. A. Commission. 80/09/16. 65pp.
- --3009270032 SECY-80-414
 Requests approval of conceptual draft plan re systematic eafety evaluation of all currently operating nuclear power reactors. Widnest 90-day status rept. considerations re identification of regulations & draft public announcement DENTON, H. R. Office of Nuclear Reactor Regulation, Director, 80/09/09 3ipp.
- 8009290405 SECY-80-408
 Informe Commission of Executive Branch response on pending export application XSNM-1666 for Kartini Research Resetor.
 Copies of original application & itrs of assurance encl SHEA.J.R. Office of International Programs, Director 80/09/04.
 20ss.

STATE PROQ STATE PROGRAMS

- BOO9020316 Submite review of draft NUREO-0696 re proposed nuclear deta link. Recommends that epecific provisions re determining potential for breaching barriers to radioactivity release & monitoring site meteorological data he added BHEALY. H G Bouth Carolina, State of. 80/08/27. 2pp.
- 800902050D Recommende that grants or contract program be developed to provide funding for mendetes to permit states to exercise responsibilities originally bestowed on AEC Meeting of Agreement States to Rould be appropriate AXELROD.D. New York, State of. 80/09/ii. ip.
- 8009030178 Expresses appreciation re Southern States Energy Board concern about future role of Ofc of State Programs Visua expressed in itr will be carefully considered in any reorganization affecting Ofc of State Programs. DIRCKS, N. J. Office of the Executive Director for Operations BO/08/04. 19

- --8009030184 Expresses concern on behalf of Bouthern States Energy Board re transferring of Agreement States Program to any licensing div. Oft of State Progress is most responsive & responsible organization in federal setablishment NEMETHIK J Southern States Energy Board 60/07/25 ip
- 8009050191 Confirms discussion following review of administrative & technical aspects of radiation control program No comments on areas examines.

 KERRO N Uffice of State Programs. Director 80/08/12 ip
- BO09050361 Forwards draft radiological emergency preparadness plan. addressing criteria in NUREG-0654 M/o anci DAVIDOFF, D. B New York, State of 80/09/02 2pp
- 8007080399 "Rept to President:State Redicington Emergency Planning & Preparedness in Support of Commercial Nuclear Power Plants "MAGY.J W. Federal Emergency Henegement Agency. 80/06/30 350pp
- BOO9080459 Confirme discussions w/K Schneider re review & evaluation results for regulation of egreement matls. Submits recommendations for review completion planned for and of yr Comments on recommendations requested KERR, Q. W Office of State Programs, Director BO/08/06 2pp
- ---B0090B0462 Confirms B007iB discussions w/K Schneider re review & eveluation results for redistion control program No recommendations on edaquacy will be made at this time Commentations requested KERR.9 N Office of State Programs: Director B0/07/30 Spp
- 8009100094 Forwards State of GA transportation surveillance program third quarterly (third yr) programs rept JANINEK.M Office of State Programs, Director. NRC-06-78-362 80/08/19 2p;
- --- 8009100097 Forwards State of QA transportation surveillance program third quarterly (third yr) programs rapt.
 INGRAM.W.D. Georgia, State of NRC-06-78-362. 80/08/14 49pp
- 8009150457 Act receipt of 800Bii ltr re results of NRC Jul 1980 review of rediation control program for egreement metle. Review will be completed by accompenying field inspectors during wk of 80090B Suggests meeting date for lete Sept 1980
 KERR.O.W Office of State Programs, Director 80/08/26 2pp.
- 8009190863 Submits esmiannual rept of ectivities performed through 800630 per UNTRCA grent to State of CA FESS.K.B. California. State of NRC-05-80-308. 80/08/27. 2pp
- 8009190874 Submits eamiennuel rept of activities in response to NRC B00612 request Reportable areas include preparation of legislation.regulations & development of administrative procedures HAZLE.A J Coloredo, State of NRC-04-80-311 80/07/28, 2pp
- ---8009170877 Forwards semiannual financial status rept Jan-June 1980 & request for reimbursement per UMTRCA grent to State of CO SWANSON,M V , HAZLE,A. Golorado, State of NRC-06-80-311. 80/08/01 39
- 8009190881 Submits technical performance rept re NRC-06-80-310 per eacond querter requirements.

 VADEN, J. Nevede, State of NRC-06-80-310. 80/06/30 ip.
- 8007190891 Submits semiannual rept of activities & forwards atetus rept through 800630 for UMTRCA grant to State of NM WOLFF, T. A. New Mexico, State of, NRC-06-80-074, 80/08/05, 4pp.
- BO09190894 Forwards program technical performance rept.800206-0630.per UNTRGA grent to State of TX BAILEY.E.D Texas. Stete of. NRC-06-80-307 80/08/20 5pp
- 8009230655 PNA-80-33 on 800903; Medical Research Foundation, Inc. shipped 4 vials of microspheres tagged w/Yh-90 Customer notified company of apparent tagging problem Eight patients treated OA will not resutherize shipments w/o FDA varification. MERR. O. N. MCGRATH. J. R. Office of State Programs. Director 80/97/18, 1p.
- 8009240260 Forwards status rept of activities & finencial rept through 800600 STRONG T R Washington, State of NRC-06-80-306 80/07/31. 3pp

8009260204 Discusses NRC review & evaluation of CO radiation control program Program for regulation of agreement matls adequate to protect public health & safety Requests comments on recommendations on technical aspects of program KERR.O W Office of State Programs. Director 80/09/08 2pp

TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE

- 8009020023 Discusses schedule for Alternate 2A ATHS plant mods proposed in Draft Vol 4 of NUREQ-0460 Proposed schedule unrealistic dua to non-ATHS mods Preliminary schedule of 3 5 yrs reached w/Middle South Bors is mora realistic SHERHOOD,0 Q General Electric Co MFN 146-80 80/08/22 2pp
- 8009020081 Forwards TVA-TR75-1A.Revision 4. "GA Program Description for Design. Const & Operation of TVA Nuclear Power Plants." in response to NRC 800818 ltr.
 MILLS-L N Tannessee Valley Authority. 80/08/26 Ip
- ---8009020103 TVA-TR75-IA R4

 "GA Program Description for Design.Const & Operation of TVA
 Nuclear Power Plants," Revision 4

 * Tennessae Vallsy Authority 80/05/31, 20pp.
- B009020128 Forwards second request for add1 info re MCAP-9500, "Ref Core Rept 17 x 17 Optimized Fuel Assambly " Requests submittal schedule to develop NRC review schedule, MILLER, J, R Standardization & Special Projects Branch 80/08/08 4pp
- 8009020237 Advises that SEP Owners Group has contracted w/URS/Blune to dayslop & implement program to saismically qualify cable trays at SEP plants. Anchorage will be addressed as part of program will require approx 18 months. SCHAFFSTALL.R. KMC, Inc. 80/08/28 2pp
- 8009020364 Supercedes 800807 ltr to NRC ra organizational change notification requirements. Info provided re recent organization changes made within nuclear power generation & angineering divs TAYLORJ H Babcock & Wilcox Co. 80/08/27 3pp.
- 6009030359 Forwards draft Revision 2 to "Corporate Operations Manual, Part IV Functional Manuals: Section I Nuclear GA Manual." RAUSCH-W P Burns & Roe Co 80/08/29. 1p
- --8009030364 BERDE-CDM4-1-NP R2
 Draft Ravision 2 to "Corporate Operations Manual, Part IV -Functional Manuals Section I Nuclear GA Manual "
 Burns & Ros Co 90/08/29, 73pp.
- B009030557 Forwards Revision 2 to QE rept.NEDO-11209-04A. "Nuclear Energy Business Group BWR QA Program Description."
 Revisions deal w/organizational changes per QE B00806 ltr & alternate position change per Reg Quide i 123.
 BREED.A. General Electric Co B0/08/26. 9pp
- 8009030463 86-1120838-00
 "Evaluation of Instrumentation to Detect Inadequate Core Cooling," prepared for 177 owners group.
 FROTH,D Babcock & Hilcor Co 80/08/15 18pp
- 8009040409 Notifies of organizational restructuring within Water Reactor Div. New Strategic Operations Div encompasses steam generator sys.matls angineering.plant margin improvement activities & man/machins interface product lins.

 ANDERSON T. M. Westinghouse Electric Corp. PAB-PTM-80-555 80/08/27 5pp.
- 8007050325 Forwards NEDD-24757, "Capreo Bafety Reliaf Valve Discharga Tests Phase II Test Rept." nonproprietary version, NEDE-24757-Ps.submittsd on 800703, BUCCHOLZ,R H Oansral Electric Go. MFN-145-80 80/08/25 ip.
- --8007050928 NEDD-24757
 "Caorso Safety Relief Valve Discharge Tests Phase II Tests
 Phase II Test Rept."
 " General Elsctric Co. 80NED056. 80/07/31 100pp.
- 8007050363 Forwards "Operator Training Bycs Instructor Requalification Program"

 JANECEK, D L., DIETZ, C. R Operal Electric Go CRD 80056 80/07/31
 19.
- --8009050965 "Operator Training Bycs Instructor Requalification Program " # General Electric Co 80/07/31. App

- BOO9100150 Bummary of 800627 mseting w/Westinghouse in Bathsada,MD re WCAP-9500, "Ref Core Rept 17x17 Optimized Fuel Assembly," MUNDY,J A. Core Performance Branch B0/08/13 4pp.
- BOO9100233 Forwards "Responses to NRC Questions on Topical Rept BAK-10133P.Revision 1. Mark C Fuel Assembly LOGA & Seismic Analysis.May 1979. "Responses withheld (raf 10CFR2 790) TAYLOR.J H Babcock & Wilcox Co. BO/09/05
- BOO9100532 Forwards CE-i-A. Revision 14 re GA program NAUGHTON N F Commonwealth Edison Co 80/09/05 1
- --B009100548 CE-i-A R14
 GA program, Ravision 14
 # Commonwealth Edison Co 80/09/09. 69pp
- 8009110333 Responds to FOIA raquest that specific listed documents be placed in FDR DO Eisenbut 760302 memo to K Goller Will be placed in FDR FELTON.J.H Division of Rules and Records 80/09/04 ip.
- --B009ii035i Topical rept evaluation of NEDE-2ii56, *Buppl Info for Flant Mod to Eliminate Bignificant In-Core Vibration * Mods are acceptable * Office of Nuclear Reactor Regulation, Director. 76/02/28 36pp
- 8009110436 Forwards "Generic Reload Fuel Application," Amend 8 for review & approval Changes incorporated include 12 new fuel bundle enrichment designs & C-lattice fuel bundles. Proprietary info withheid (ref 100FR2.790) ENGEL.R E General Electric Co. MFN-147-80 80/08/26 2pp.
- --8009110443 Forwards Amend 8 to, "Generic Reload Fuel Application" containing nuclear characteristics tables for 12 new fuel bundls designs. Amend 8 & affidavit withheld (ref 10CFR2 790).

 ENCEL.R E General Electric Co 80/08/22 1s.
- BOO9:20205 Submits review & analysis of BAFSTOR holding periods.Cost differences between 30 & 60-yr storage periods would not justify cost of performing analysis.

 SMITH.R.I. Battelle Memorial Institute, Pacific Northwest Laboratory 80/06/18 5pp.
- 8009120270 Confirms 800904 telcon re use of B&H TAFY code for fuel & ECCB analysis Transition will begin from TAFY to TACO2 for fuel & ECCB analysis. Current & revised LCCA limits provided. Reanalysis will be performed after NRC approval of TACO2. TAYLOR, J. H. Babcock & Wilcox Co 80/07/03. 2pp
- 9009120350 Forwards operational QA program description, Revision A, Draft 2. RENBEROGER, D. L. ELE-908-80-268. 80/09/02. 2pp.
- --8009120363 WPP88-GA-004 R4 GA program:Revision 4.Dreft 2. * Washington Public Power Supply System 80/09/02. 57pp.
- SOO9120584 "Analysis Summary in Support of Early Reactor Coolant Fuap Trip." # Babcock & Wilcox Co. 80/08/28, 51pp.
- BO09120664 Reaffirms NRC position on incorporating Lessons Learned Short-Term Requirement 2 i, 3 b in TMI action plan. Instrumentation & guidelines for indication of inadequate reactor core cooling do not satisfy long-term requirement. ROSS: D.F. Division of Systems Integration. 80/09/09. 2pp.
- BOO9160192 Forwards NEDE-24011-P-A.App D App D withheld (ref 10CFR2 790). ENGEL.R.E. General Electric Co MFN-186-80, 80/09/08. 1p.
- 8009160366 Addresses requirements of Reg Guide 1.92 pertaining to closely spaced modes & lists supporting refs. Vendor will recomment BAR amend for plants under NRC review. GANG. H. O General Electric Co MFN-187-80. BO/09/08. 3pp
- 8009160424 Forwards add1 info on NEDD-24289, "Generic Info for Barrier Fuel Demonstration Bundle Licensing," in response to NRC 800828 requests Requests NRC approval by 800930 so that hardware mfg can begin Oct 1980.
 ENGEL.R E. General Electric Co. MFN-154-80 80/09/11 33pp.

- --B009160436 GEAP-25163-2
 "Demonstration of Fuel Resistant to Pellet-Cladding
 Interaction Phase 2 Second Semiannual Rept.Jul-Dac 1979 "
 4 Affiliation Unknown ARMIHO.J B. ROSENMANN.B General
 Electric Co UC-78 80/03/31 87pp Available at NTIS \$4 00
- GOOGIGO341 Forwards corrected NECAN solution to NRC benchmark problem four Enci A discusses differences in two solutions. Enci B growlides summary results & addi solution is given in Encl C Enci B & C hard copies in Central Files only ANDERBON, T. M. Hestinghouse Electric Corp NS-TMA-2300. 80/09/03
- 8009190157 Notifies of review of util 800215 & 0715 submittals ra organizational changes within water reactor divs & product assurance dept. Encl changes are acceptable & should be incorporated into next revision of NCAP-8370 HAASB, H. P. Quality Assurance Branch 80/08/14 Bpp
- 9009190449 Forwards WCAP-9764 & WCAP-9765, proprietary & nonproprietary version of, "Documentation of Westinghouse Core Uncovery Tests & Small Breat Evaluation Model Core Mixture Level Hodel," Proprietary version withheld (ref 10CFR2, 790) ARGENSEN, R W. American Electric Power Co., Inc., 09-40, 80/09/15, 1182.
- --8009190453 HCAP-9765
 Nonproprietary version of "Documentation of Hestinghouse Core Unrovery Yests & Small Break Evaluation Model Core Hixture Layel Model."
 ANDERSON.T M Hestinghouse Electric Corp , Nuclear Energy Systems. 60/07/31 27pp.
- SOO9190457 Forwards proprietary & nonproprietary versions of responses to NRC request for additinfo on Addendum 1 to MCAP-8720 Proprietary version withheld (ref 10CFR2 770).
 AMDERBON, T.M. Westinghouse Electric Corp., PMR Systems Div. MS-TMA-2303. 80/09/09 28pp
- 900919037B Notification of 800911 meeting w/C-E & Cmaha Public Power in Satheada.MD to discuss guidelines for plant emargancy procedures. SHEMON.B. Reactor Systems Branch. 80/09/05. 3pp.
- 8009220139 Forwards proprietary & nonproprietary version of, "Dow Bys for Solidification of Low Level Radwaste from Nuclear Power Plants," revising 780331 rept to include Amends 1 through 3. OMEN.J.S. Dow Chemical Go 80/09/18. 1p
- 8009220275 Documents comments made at NRC B00B27 meeting w/industry representatives re NUREO-0577, NUREO-0577 does not distinguish between integral & nonintegral supports. Integral supports have had more restrictive requirements. ANDERBON.T.M Westinghouse Electric Corp. NB-TMA-2304 60/09/09.
- SOC9220345 BNL-NUREO-28060
 "Bensitivity of Rist Parameters to Human Errors for PHR."
 SAMANTA.P., HALL,R.E. Broothaven National Laboratory, KERR.H
 Hichigan, Univ. of 80/09/11, 12pp.
- 8009230308 Forwards add1 data to NEDO-24708, prepared by CE on behalf of BLR owners group. Republication of NEDO-24708 anticipated incorporating prepublication mat1 euhmitted since original publication.

 BUCHMOLZ, R. H. General Electric Operating Plant Owners Group.
 MFN-162-80. 80/09/16. 135pp.
- BOO9230308 Forwards add1 data to NEDO-24708, prepared by OE on behalf of BAR buners group Republication of NEDO-24708 anticipated incorporating prepublication mat1 submitted since original publication.

 BUCHHOLZ, R. H. General' Electric Co RHE-074-80. 80/09/16. 135pp.
- BOC9230430 Forwards nonproprietary version of NEDD-24798, "Mark II Containment Program, Caorso Extended Discharge Test Rept, " on behalf of Mark II owners group as part of Tast 8-5 BUCHMOLZ, R H General Electric Operating Plant Gwners Group, MFN-158-80, 80/07/12, ip.
- ---B009230431 NEDO-24798
 Nebproprietary version of "Mark II Containment Program, Caprao Discharge Test Rept."
 HOLAN, J.: NINTZ, B.: MUZZY, R. J. Ganeral Electric Co. BONED282, 80/08/31 35pp.
- 8009230472 Forwards nonproprietary version of NEDO-24811. "4T Confensation Oscillation (4TCO) Test Program Finel Test Repts" on behalf of Mark II owners group as part of Tesk A-17.
 BUCHROLZ, R H General Electric Operating Plant Owners Group. MFN 183-90 80/09/03. ip.

- --8009230475 NEDD-24811
 Nonproprietary version of "4T Condensation Oscillation (4TCO) Teet Program Final Test Rept "
 BYRD.P K , FITZEIHKONS, G , ROCERS, A E General Electric Co
 BONEDD57 B0/07/31 100pp
- BOO9230581 Advises of new owners group organized to address generic engineering licensing & operational issues & completion of projects begun under owners group on post-TMI efforts KP Baskin of Bouthern CA Edison was elected chairmen LIEBLER.O E C-E Operating Plants Owners Group BO/09/04 ip.
- 8009230672 Forwards revised pages to GA program CE-1-A NAUDHYON W.F. Commonwealth Edison Co 80/09/18, 1p
- --E009230684 CE-1-A R14
 Revised Pages i-3i,i-4: & 1-24 to GA program CE-1-A,Revision 14
 Commonwealth Edison Co 80/09/09 3pp
- 8009230585 Forwards responses to NRC 790725 questions on MCAP-9292 re fracture toughness of ABME matl Review & consideration of rept & encl info in conjunction w/safety enalyses rept rafs requested ANDERSON-T. H ~ Westinghouse Electric Corp. NS-TMA-2312 80/09/18
- 8009240520 Forwards CENPD-234-NP-A & CENPO-254-P-A monproprietary & proprietary versions of "Post-LOCA Long-Term Cooling Evaluation Model" Affidavit to proprietary neture of CENPD-254-P-A encl 8CHERER.A.E. C-E Power Bystems. LD-80-043 80/08/04. 5pp
- --8009240527 CENPD-254-NP-A
 "Post-LOCA Long-Term Cociing Evaluation Hodel,"
 nonproprietary varsion
 " C-E Power Systems. B0/06/30, 200pp.
- 8009250462 Ack receipt of 800324 & 0801 ltrs urging Commission to require inerting of Mark I & Mark III containments Commission will consider views in reaching Section CHILK.S. J. Office of the Secretary of the Commission 80/08/25.
- --B009250467 Requests containment inerting at all Merk I & Mark II containments w/o delay JORDAN, W. S., WEISS, E. R. Sheldon, Hermon & Weiss 80/08/01, 2pp.
- ---B009250471 Requeste approval of NRC staff recommendation to require immediate inerting of Mark I & Mark II containments.
 JORDAN-M B. WEIGBLE R. Sheldon, Haron & Welts. B0/03/24. App
- 8009260477 Forwards nonproprietary Exron Nuclear Co topical repts: XN-NF-79-59(NP); XN-NF-79-71(NP), Revision 1: XN-NF-80-19(NP), Vol 1: XN-NF-80-19(NP), Vol 2: XX-NF-80-19(NP), Vol 28. XN-NF-80-19(NP), Vol 28. XN-NF-80-19(NP), Vol 28. XN-NF-80-19(NP), Vol 28. XN-NF-80-19(NP), Vol 29. Nonproprietary version of three addl repts to follow. OHBLEV.O.F Exxon Nuclear Co , Inc. (subs. of Exxon Corp.) OFD: 136:80 80/09/19 ip.
- --8009260482 XN-NF-79-89(NP)

 "Methodology for Calculation of Pressure Drop in EWR Fuel
 Assemblies," nonproprietary version,
 ADAMS,F,T, PATTEN,T M. Exxon Nuclear Co., Inc. (subs. of Exxon
 Corp.) 80/08/13. 59pp
- --80092604B7 XN-NF-79-71(NP) R1
 "Exton Nuclear Plant Transient Model for Jet Pump EMRs."
 Revieion i, nonproprietary version
 KELLEY:R H. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.),
 80/08/14, 59pp.
- --8009260493 XN-NF-80-19(NP) V1
 "Exton Nuclear Methodology for BWRs; Neutronics Methods for Design & Anaiyais." Vol 1.nonproprietary version # Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 80/08/07 217sp.
- --G009260504 XN-NF-B0-19(RP) V2B
 "FLEX.Computer Code for Jet Pump BLR Refill & Reflood
 Analysis:" Vol 2B:nonproprietary varsion.
 BUGRNARD, T.A. ZIRMERMAN, L.R. Exxon Nuclear Co., Inc. (subs. of
 Exxon Corp.). B0/07/31, 98pp

- 800930003B Notification of 800919 meeting w/BWR owners group representative.GE & NRC in Bathasda.MD to discuss proposed criteria for plant-specific mods re-screm discharge vol HANNOM, J N: Operating Reactors Branch 2 80/09/12 2pp
- 8009300394 Requests reply to 800221 & 0625 ltrs re-status of technical review of topical rept on Fox-Howlett rebar couplare DEUBERT-J R Fox Industries 80/09/23 1p
- 8009300477 Forwards modified App 8 of NEDD-10329, "LOCA & ECC8 Models for GE BURs:" re technical description of computer code SAFE.to euppl 800625 ltr GAMERON.C A General Electric Co MFN-164-80 80/09/23 ip
- --9009300483 NEDO-10329 Modified App B of "LOCA & ECCB Modele for GE BHRS " * General Electric Co 80/09/23 48pp

WASTE HOT NUCLEAR WASTE HANAGEMENT

- 8009090748 Forwards "Environ Assessment of Dawn Mining Co Below-Orade Tailings Mgt PlannFord: WA." conforming to contente of Bapt of Social & Heelth Svcs 800026 ltr re schedule & ecope SCARANG.R A Uranium Recovery Licensing Branch. 80/08/29. 1p
- --8007090769 "Environ Assessment of Dawn Mining Co Proposed Below-Grade Tailings Hgt Plen.Ford.WA" • Uranium Recovery Licensing Branch, 80/08/31 100pp
- G007100135 Summary of G00814 meeting w/SNHL in Silver Spring.MD re requirements for resadial action program for Edgemont.SD EADIE.O G. Uranium Recovery Literaing Branch SO/OB/19 2pp.
- 8009100478 Forwards proposed egendas for 800902 & 03 meetings in Edgemont & Repis City.8D re Edgemont cleanup action program SCARANO,R A Uranium Recovery Licensing Branch 80/08/21 ip
- 8009100491 Forwards proposed agendas for 800902 & 03 meetinge in Edgemont & Rapid City, 8D re Edgemont cleanup action program SCARANO.R A Urenium Recovery Licensing Branch 80708/21 3pp
- 8009100940 Summary of 800818 meeting w/Cyprus Mines Corp in Silver Spring.MD re tellings mgt elternatives. TRAGER.E A Uranium Recovery Licensing Branch 80/08/22 App
- 8009110550 Ack receipt of 800811 submittal of discussion paper & research proposal re U mill teilings eits at Edgemont, 80 Research proposel unnecessary due to recent congressional ection Supplemental appropriations & receission bill encl MILLER, H J Urenium Recovery Licensing Branch. 80/08/27. 3pp
- 8009110847 Forwards invoice re star tabulation & rept. "Beasonal Hind Dietribution by Pesquill Stebility Clasees (6) (Star Progrem)" " Commerce.Dept.of.Nationel Oceanographic & Atmospheric Adminstration 17107 80/08/13 19pp
- B009150535 Responds to 800401 request for review of autline re U mill tailings remedial action. Dutline meets Council on Environ Quelity requirements Apress w/EIB MILLER, H J. Uranium Recovery Liceneing Branch 80/08/28 3pp
- 8009160475 Forwards plan developed for offsite remedial action program at Edgemont,80 Oreb working level measurements are compatible w/HUD/80 rediation survey protocol Requeste concurrence by 800902 MARTIN, J B. Division of Waste Management 80/08/19 2pp
- --B009160479 Bubmite remedial ection program for Edgemont, BD. Program consists of grab working level measurements, gamme radiation steasurements, long-term radon progeny sampling, soil mempling, angineering essessment & remedial action/verification EADIE, 0 o. Urenium Recovery Licensing Branch FIN B-2217 B0/0B/12 ilpp
- 8007160486 Forwards epplication for matla license Vols 1 & 2 filed w/CO Dept of Health.Radiation & Hazardous Waete Control Div on 800715.
 VINYCH.V. Dravo Corp. 17322, 80/07/28, 4i6pp
- 8009160549 Forwards examiner rept & proposal for decision re application by Anaconda Copper Co for U surface mining operation permit. BLEVING: G N Texas: State of 17043, 80/07/17 19pp.

- B009170250 Bubmits priority list of structures scheduled for remedial action & residences requiring further radiological assessments.

 EADIE, G G , BCARANO, R. A. Uranium Recovery Licansing Branch FIN B-2217. B0/08/14, 2pp
- 8009180321 Forwarde Geophysical Loge WW-78-2,M-78-2,M-78-3 & M-78-4, W/o encis WILLERT.R L Pionser Uravan,Inc 17259. 80/08/21. 1p.
- 8009180494 Forwards rept of tailings mgt evaluation of Oulf Mineral Resources Co Taylor U mill project Completes NRC assistance as agreed in 800303 meeting BCARANO.R. A Uranium Recovery Licensing Branch 80/05/16. 40pp.
- B009190762 Forwards into on 26 properties in area of processing site under DOE consideration for determination as remedial action properties Identification & evaluation of approx 100 add1 properties ongoing. H/o encl HOTT. H E Energy. Dept of. 17120. 80/06/12, ip
- 8009220046 Forwarde info developed on 30 properties in vicinity of Salt Leke City site Properties may be designated for remedial action due to contamination w/residual radioactive mat1 derived from site Requests comment. MOTT, W E Energy, Dept of 17076 80/07/24. 1p
- 8009220116 Forwarde decision upholding 790427 affirmation of Forest Byc approval of operating plan of Homestake Mining Co Pitch project PETERSON.R M Agriculture, Dept of, Forest Service 17106 80/08/15 7pp.
- 8009260085 Bummarizes purpose & function of diversion structurss associated w/tmilings disposal Diversion ditch will be constructed along north aids of tailings isolation area to prayent runoff from entering trenches during excepation LANGE, 8 L Pioneer Nuclear, Inc 17209. 80/08/14 2pp.
- 8009290499 "Tailings Disposal Facility, Dawn Mining Co. Addl Info for DSHB." Aug 1980.

 # Dawn Mining Co. 17295 B0/08/31. 17pp.
- --8009290501 "Addl Info for DSH8," Sept 1980 * Dewn Mining Co. 17295 80/09/30. 25pp.
- 8009300232 Responds to request for info concerning characteristics of U mill tailings & transportation to pit from mill at Rhode Ranch Includes description of transportation to pit & radiometrics in tailings. Releted date encl DAVIB. OR Anaconda Co., Anaconda Copper Co. Div 17225. 80/08/20. 2pp.

XPORTLIC EXPORT AND IMPORT LICENSES

- 8009020120 Providee add1 info re 800730 ltr requesting viewe on proposed emends to Edlow Intl export license, Federal Inst for Reactor Research, Switzerland, ie proposed storage facility for U hexafluoride mstl.
 PETERSON, N. R. Assistant Director for Export/Import & Internetional Safeguards 80/08/22. ip.
- 8007020129 Forwards license application & proposed license for export of depleted U to Canada.per Commission 800720 decision re delegations of authority in export-related areas W/o encl. PETERSON.H.R. Assistant Director for Export/Import & International Bafeguards. 80/08/22 ip
- 8009020162 Forwards Exxon Nuclear Co Inc 800729 eddl end use info on export license application W/o enci DEVINE, J.B. Assistant Director for Export/Import & International Bafeguards. 80/08/13 1p.
- 8007020464 License for QE to export 4.000 kg U-235, contained in 140.000 kg U dioxide to Taiwan. PETERBON-M R. Assistant Director for Export/Import & International Safeguards. BDW 79201. 80/08/26. 2pp.
- 800902047i Amend 2 to License for Transnuclear, Inc. extending expiration date from 801201 to 811201.
 PETERBON.K.R. Assistant Director for Export/Import & International Bafeguards MISC-24i 78-073. 80/08/25. ip
- 8009020478 Amend 3 to license for Hestinghouse, extending expiration date from 800930 to 821231.
 PETERSON.H R. Assistant Director for Export/Import & International Safeguards. PC-AEC-19. 80/08/25 1p.

- 8009020480 Forwards application by Transnuclear, Inc for license to export 11.03 kg U to France.
 MATSON, V. Transnuclear, Inc. 80/08/20 1p
- --B009020486 Application by Transnuclear, Inc for license to export
 11 03 kg U.anriched to max 2 2286% U-235 to France
 MAT60N, V Transnuclear, Inc. 80-173/01 TNP-3 80/08/20 1pp.
- 8009020492 Forwards application by Westinghouse for license to apport 312,000 kg U to Taiwan HESS.R J. Westinghouse Electric Corp. ICS-0718 80/08/14 ip
- --B007020479 Application by Mestinghouse for license to export 312,000 kg U. containing 12,480 kg U-235, to Taiwan HESS.R.J. Mestinghouse Electric Corp ICS-0718 80/08/14 2pp.
- 8009030697 Application by Honeywell Defense Sys Div for license to export rod ands k/or scrap piece parts to Canada * Honeywell, Inc. 80/07/29 ip
- --8009030498 Supports application for license to export rod ends &/or scrap piece parts to Canada BARRY.C.S Honeywell, Inc. 80/07/29 2pp
- 8009050442 Forwards Cabot Corp application for license to export sircunium tubing to Canada, TUFPER,K F Cabot Corp 80/08/08 ip
- --8009030446 Application by Cabot Corp for license to export sirconium Grade 2 seamless tubing to Canada.
 TUPPER, K Cabot Corp i-9817(19-28012 80/08/08. ip
- 8009050449 Requests Executive Branch position re GA Co application for license to export replacement parts & components to West Germany, DEVINE, J. B. Assistant Director for Export/Import & International Bafeguards 80/08/19. 1p
- BOO9050466 License for Canada Dept of Supply & Svcs to export 0 0002 microgram Pu-239 to Canada DEVINE:J B Assistant Director for Export/Import & International Bafeguards 23233-0-0314, 80/08/27 2pp
- 8009050469 Submits application to amend export & import licenses, satending expiration dates.

 MATSON.V. Trensucless. Inc. 80/08/18 ip
- BOOPOSOSIS Requests Executive Branch position re Ediow Intl Co application for license to export BNM to Taiwan DEVINE. J.B. Assistant Director for Export/Import & International Bafeguards. BO/OB/15. ip.
- 800908-0279 Executive Branch position re Reactor Experiments, Inc application for license to export 0.033 mg PU-239.0.098 mg U-235 & 0 1007 mg Np-237 to Saudi Arabia License should be granted. NOSENIG.L.V State.Dept.of, Bureau of Oceans & Internati Environ & Scientific Affairs 80/08/14 2pp
- BOOTOBO347 Executive Branch position re Transnuclear. Inc application for license to export 10.033 kgs U-235.contained in 22 142 igs U, to Japan, License should be granted. Ltr of assurance encl.
 NOBENZO, L. V. State, Dept. of, Bureau of Oceans & Internati, Environ & Gcientific Affairs 80/08/13 5pp.
- BOOTOFO&&& Application by CERAC. Inc for license to export 20 kg thorium metal powder to The Netherlands.
 COLTON.E Carac. Inc. 80/09/08, ip.
- BOOGOPD202 Forwards application by Sandvik Special Metals Corp for license to export zirconium tubes to Japan DUSOMSKY.E. George S. Bush & Co. 80/08/12. 1p.
- ~-BOOGO7020B Application by Sandvik Special Metels Corp for license to support 2R-4 caterpillar thimble tubes to Japan.

 + Sandvik Special Metals Corp. 0392, 80/08/12, ip.
- 8009070213 Forwards application by Sandvik Special Hetals Corp for license to export zirconium tubes to Japan QUSCHSKY.E George S. Bush & Co 80/08/12. ip.
- ---B009090215 Application by Sandvik Special Metals Corp for license to export zirconium tubes to Japan.

 * Sandvik Special Metals Corp 0391 80/08/11 2pp.

- 8007070614 Forwards application for licenses to export 395 71 g U, contained in U oxide fuel rod, to West Cermany OLSEN, R N National Nuclear Corp. 80/07/31 1p
- --8007090619 Application by Natl Nuclear Corp for license to export 395 71 g U.contained in U oxide fuel rod, to West Germany End use statement encl ** National Nuclear Corp 80/07/02 3pp
- ---8009090630 License for Natl Nuclear Corp to export 7,85 g U-235, contained in 395 71 g U-to West Germany OUHIN.M A Assistant Director for Export/Import & International Bafaguerds 76/09/24 5pp
- ---8009070634 License for Natl Nuclear Corp to import 395 6 g U.enriched to 2% in form of U oxide fuel rod from West Garmany OUHIN.M A Assistant Director for Export/Import & International Safeguards 76/08/20 ip
- 8007070657 Application by Edlow Intl Co for license to export 5 tons depleted U tetrafluoride for penetrators for non-nuclear end use to United Kingdom.

 MARMON D. W Edlow International Co 80/08/27. 1p.
- 8007090663 Application by Marubeni America Corp for license to export 50 kg spacer pisce parts * Marubeni America Corp. (subs. of Merubeni Corp.). INQY-1968 80/08/23 ip
- GOO9100032 Submits application to amend license to export add1 2 tg U dioxide in powder form to Talwan.
 WILLGUM.D.D. General Electric Co. BDM-80076 GO/08/ii ip.
- 800910004B Bubmits application to amend export license changing coneignee address & proposed expiration data.
 RODI.J.P. Hestinghouse Electric Corp TFG/NRC-5162 80/08/13
- 8009100096 Forwards application for licenss to export four sources, totalling 904 micrograms Cf-252, to Talwan HE88.R J. Westinghouse Electric Corp ICS-0721 80/08/14. 1p.
- --BO09100101 Application by Hestinghouse for license to export four sources, totalling 904 micrograms Cf-252, to Taiwan, HESS,R J Wastinghouse Elsctric Corp [CS-0721 80/08/14 2pp
- --8009100119 Forwards application for license to export 240 mg Np-237, conteined in 12 radiation surveillance capsules to Talwan HEBB, R J. Westinghouse Electric Corp. ICB-0722 80/08/14. ip.
- --B009100131 Application by Westinghouse for license to export 240 mg Np-237, contained in 12 radiation surveillance capsules, to Taiwan.
 HEBB,R.J. Westinghouse Electric Corp. ICB-0722. B0/0B/14. 2pp
- 8009100155 Executive Branch position re OA to application for license to expert low enriched U to Indonesia for use in Kartini Research Reactor, License should be granted Ltr of assurance required NOGENIO, L.V. Blats, Dspt. of, Bureau of Ocsans & Internatl, Environ & Scientific Affairs 80/08/28 17pp
- 8009100198 Requests Executive Branch position re Westinghouse application for licenes to export radiation cassules containing Np-237 & primery neutron sources containing Cf-252 to Taiwan.
 PETERBON M.R. Assistant Director for Export/Import & International Bafeguards. 80/08/25, ip.
- 8009100493 Application by Westinghouse for license to export one compensated ionization chamber to France.
 POCHAL, W. F. Westinghouse Electric Corp. 2E-20293-5 80/08/08, ip
- 8009110028 Response in apposition to Friends of Koraan People Aug 1980 motion to amend petition to intervene & request for hearing Interest may be represented by Ctr for Development Policy, if intervention allowed Certificate of Svc encl COWAN, B Z , KENRICK, J. R. Westinghouse Electric Corp. COWAN, E Z Eckert, Seamens, Cherin & Mellott. 80/07/14, 4pp
- 8009110234 License for Edlaw Intl Co to export 347 kg U-235 for fuel fabrication to Japan DEVINE, J. B Assistant Director for Export/Import & International Bareguards. SUM 13 80/09/02 2pp.
- 8009110260 Licenss for Westinghouse to export 8.845 kg U-235.contained in 325.822 kg U. to Taiwan.
 DEVINE, J. B Assistant Director for Expert/Import & International Safeguards ICS-7823. 80/08/29. 2pp.

- 8009110264 Bubmits application to amend export license changing consigner address & proposed license expiration date RODIL P Mestinghouse Electric Carp TFO/NRC-5162 80/08/13 ip.
- 8009ii0270 Submits application to amend export license to increase quantity of goods from 10 to 20 pieces of Hodel RB-CA-020i-23i EECKHOUT. A Reuter-Stokes, Inc. 80/08/i5 lp
- 8009110273 Bubmits application to amend export license, reflecting changes in form of licensee name & address deleting five intermediate consignees & changing address of remaining intermediate consignee.

 WILSON, B D General Electric Co BDW 80099 80/09/13. 2pp.
- 8009110403 Bubmits application to amend Licenses IGNM-79010, XSNM-1559, XSNM-1483 & XT-8429, extending expiration dates to 810901. 811201.810901 & 811201.respectively HATEON, V Transnuclear, Inc 80/08/18 ip
- 8009110406 Requests that review of application for license to export utilization facility to Taiwan be expedited for issuance prior to Mar 1981 HESB.R J. Westinghouse Electric Corp. ICS-0724 80/09/14 1p
- 8009110492 Forwards application for license to export 25,000 lb depleted U solid metal to Canada SCHAEFFER, M. R. RHI Co., RK1 Titanium 80/08/25. lp.
- --8009110587 Application by RMI Co for license to export 25,000 16 U solid metal to Censes SCHAEFFER. NR. RMI Co., RMI Titanium 80/08/25, 2es
 - 7110474 Requests cancellation of License XBNM-1597 ICKHOUT, A Reuter-Stokes, Inc. 80/08/28 ip
 - 9110497 Forwards application for license to export 7 508 kg V to lest Cermany.

 43780N.V. Transnuclear, Inc. 80-180/01 80/08/25 1p.
- -8009i10502 Application by Transnuclear Inc for license to export 7.308 kg U, in form of U hexafiuoride, to Germany a Transnuclear Inc MWH-309 00-180. 80/08/25 2pp
- 8009110559 Certifies that mati in Westinghouse 800612 application to export 3 7 kg U-235 to Italy will be subj to 600725 Addl Agreement for Cooperation & that ultimate consignee is authorized to receive & possess matl. MARCHALL European Communities, Commission of. 80/09/28. 1p
 - 79110564 Certifies that math in Nath Nuclear Corp 800702 application a export 395,71 g U to West Germany with be subj to 600723 dl Agreement for Cooperation & that ultimate consignee is thorized to receive & possess math
 - 110580 Certifies that math in Hestinghouse 800612 application to port 6,000 g U to Belgium will be subj to 600725 Addl reament for Cooperation & that ultimate consignee is thorized to receive & possess math.

 RCHAL. J European Communities, Commission of. 80/08/27. ip
 - 110585 Forwards Executive Branch response on pending export cense application requiring Commission review. Ofc should itiate final review of case to facilitate early response forthcoming action paper.

 EArJ.R Office of International Programs, Director, 80/08/21.
 - 110591 Requests Executive Branch position re Westinghouse plication for emend to License XR-0083, extending piration date to 201231, W/o enci TERSON, NR. Assistant Director for Export/Import & International Ifeguards 80/08/27, 1p.
 - 9110592 Forwards application for license to export 1 kg deuterium o Mexico DELSTEIN:B Aldrich Chemical Co., Inc. (subs. of Bigma-Aldrich orp.). BO/08/25 ip.
 - .009110595 Application by Aidrich Chamical Co. Inc for license to export 1 tg deuterium.contained in 5 kg deuterium oxide, to Nesico EDELSTEIN, B. Aldrich Chamical Co., Inc. (subs of Bigma-Aldrich Corp). 16/80. 80/08/25. 1p.

- 8009110593 Advises that Commission has accepted recommendation to amend QA Co license to export addl nuclear components, including control rod elements, fission & ion chambers & electronic amplifiers, to Taiwan HOYLE, U C Office of the Secretary of the Commission 880-390 80/09/03 ip
- 8009110600 Application by Matheson Qas Products for license to export 500 liters deuterium to Australia WOQD,L D Matheson Qas Products 101-96919 80/09/21. 1p
- 8009110602 Application by Mitsubishi Intl Corp for license to export 500mCi encapsulated cement wire of Cf-252 to Japan KUDE. Y Mitsubishi International Corp (subs of Mitsubishi Corp.) 64-7276-79. 80/08/22 jp.
- 8009110606 Forwards Westinghouse 800814 ltr re license to export two power reactors to Taiwan If license not issued by Mar 1981. bid will be disqualified M/o encl PETERSONAM R. Assistant Director for Export/Import & International Safeguards 80/08/27 lp
- 8007110607 Amend 3 to license for Hoke, Inc increasing value of exported items & extending expiration date to 830630 PETERSON, H R. Assistant Director for Export/Import & International Bafeguards. 1126-81. 80/08/27. 1p.
- 8009110529 Submits application to amend license to export addl quantities of U & U-235 MATSON,V Transnuclear, Inc. 80/08/15, ip
- 9009110632 Forwards application to export 60,500 ft zirconium seamless tubing to Canada. TUPPERIN.F. Cabot Corp. 80/08/08 ip.
- --8009110635 Application by Cabot Corp for license to export zircunium Orade 2 seamless tubing to Canada TUPPER.K Cabot Corp. 1-9816.9818.529 80/08/08. 1p
- B009:10689 Forwards RMI Co 800829 ltr confirming Iraq as ultimate destination re export license application XU-8505. H/o encl. DEVING. J. B. Assistant Director for Export/Import & International Bafeguards 80/09/03, ip
- --8009110214 Bupple 800825 export license application for shipment of 347 kg U-239 to Canada, SCHARFFER M. R. RMI Co., RMI Titanium 80/08/29, is
- 8007i10695 Forwards UNC Recovery Sys 800818 ltr re discontinuance of highly enriched U operations.Ltr requests info re plans for mat1 being stored for MUKEM.

 MAT80M:V. Transnuclear, Inc. NUK-273 80/08/25. 3pp
- 8009110700 Requests quantity of matls on 790124 export license application to 790213 amend be changed to 10 364 kg U containing 9 670 kg U-235.
 MATSON, V. Transnuclear, Inc. NUK-264. 80/08/25. ip.
- 8007110723 License for Hastinghouse to export 3 70 kg U as U oxids for fabrication of BHR fuel to Italy.
 DEVINE. J B Assistant Director for Export/Import & International Bafeguards 108-0417. 80/09/03. 2pp.
- B009i1074i Amend i to OA Co export License XCOM-0300, increasing value of Items to be exported & authorizing export of addl components
 DEVINE, J B Assistant Director for Export/Import & International Bafeguards IEL-1106. 80/09/03 1pp.
- 8009110743 Bubmits application to smend license to export to include 1.144 kg U as U-308.containing 5 kg U-235. MATSON, U Transpuclear, Inc 79-211/01. 80/07/02, ip
- BO09i10755 Requests Executive Brench position re GE application for license to export addl 2 0 kg U.enriched to 11 w/o max.for use in Taiwan. PETERBONN R. Assistant Director for Export/Import & International Bafeguards. 80/08/27. 1p
- 8009110830 Submits application to amend license to export increasing value limitation from \$100,000 to \$250,000.

 MILBON, BD General Electric Co., Nuclear Energy Products Div. BDM-80100 80/08/21. 1p.
- 8009120036 Notifies of Edlow Intl Co 800819 request for withdrawal of export license application XBNM-1383. DEVINE.J B Assistant Director for Export/Import & International Bareguards. 80/08/29. ip.

- B009120062 Ltr of assurance re Kansai Electric Power Co. Inc application for license to export 347 kg of U-235. contained in 13,090 tg U to Japan HIYABAYASHI, M Japan 80/08/14 ip
- 8009120574 Submits application to amend license to export Zircaloy-4 fuel channels to ENEL BWR power station located at Caorso, Italy.

 WOINIAK, D. R Carpenter Technology Corp 80/08/26 3pp
- 80091204-03 Submits application to amend license, increasing export value limitation & sitending expiration date BRUSH.P.N Hoke, Inc. 80/08/20 1p
- 8004120607 Ltr of assurance re export license application X8NM-1700 MULLER-R E., HOFMAN,R. Switzerland 80/08/11 1p
- 8007120624 Forwards application to export 1 kg deuterium, in 5 kg deuterium axide to chile EDELBTEIN, B Aldrich Chemical Co., Inc (subs. of Sigma-Aldrich Corp.). 80/08/25 ip
- --8009120527 Application by Aldrich Chamical Co.Inc for license to export its deuterium in 5 kg deuterium oxide to be used in lab quantities for R&D in deuterium nuclear magnetic resonance work to Chile.
 EOELSTEIN.S Aldrich Chemical Co., Inc (subs of Sigma-Aldrich Corp.). 17780. 80/08/25 ip.
- 8007130029 Forwards Executive Branch response on pending export license application XSRM-1342. Commission action paper will be forwarded Requests initiation of final review to facilitate early response. W/o encl SEEA.J R Office of Internetional Programs, Director. 80/08/26. is.
- 8009130072 Informs that NRC has not completed licensing action on expert license application to expert low enriched U to Taiwan Favorable Executive Branch reviews received 790616 Final Commission action expected shortly SHCA.UR Assistant Director for Export/Import & International Bafeguards. 80/08/14. 1p
- BOO9150410 Forwards responses to 800527 questions re info provided by NRC on 800501 concerning differences in role of NRC & Executive Branch in processing export requests Supporting documentation encl AMEARNC, J.F.. Commission. 80/08/22, 13pp.
- --BOG9150418 BEGY-78-216A
 Forwards documents re proposed license for Transnuclear, Inc
 to export high-enriched U to Sweden.
 BMEA, J. R. Office of International Programs, Director. 78/05/11
 35p.
- --BO09150423 Provides comments on proposed license for Transnuclear, Inc to export high-enriched U to Sweden Supporting documentation encl. TARNOFF, P. State, Dept. of. 78/03/03 Spp
- -- B009150428 Forwards revised analysis of Transnuclear, Inc application to essort high-enriched U to Sweden NOSEATZOL U. State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 78/05/08, 17pp
- -- BOO9180433 Application by Transnuclear, Inc. to export 21.053 kg U hasafluoride, enriched to max 93 90X U-235, to Sweden. End use statement encl.
 MATSON, V. Transnuclear, Inc. 77/01/25, 2pp
- --800915043B Forwards application for license to export 17.642 kg U-235, contained in 21 053 kg U as U hexafluoride enriched to 93.5%, to Bweden, H/o encl Proposed license encl. #ATBON, V. Transnuclear, Inc. 77/01/23, 4pp
- --BO09150442 Submits conclusions re Edlow Intl Co application to export SMM to Sweden No meth changed circumstances re application from those wristing at time of issuance of XGNM-1074 & XGNM-1248, License may be issued.

 MOORE, N. Office of International Programs, Director, 79/09/06.

- --8009150446 Advises of no matl changed circumstances re application from those existing at time of issuance of XBNM-1532 License may be issued. HORELR N Office of International Programs, Director 90/02/28
- 8009160191 Amend to license for GE, increasing value of items to be exported to \$250,000.
 PETERBON.M.R. Assistant Director for Export/Import & International Bafeguards. BDM-102-78:8010 B0/08/27 1p
- 8009160193 License for Hestinghouse to export one unit proportional counter to Belgium.
 DEVING.J B. Assistant Director for Export/Import & International Safeguards. ZE-20351 80/08/27 ig
- 8009160194 License for Honeywell to export 555,800 kg depleted U.in rod ands or scrap pieces:to Canade DEVINE.J B Assistant Director for Export/Import & Internetional Safeguards 80/08/27 2pp
- BO09140239 License for Reuter-Stokes, Inc to export one unit Model RB-Ci -2514-iiJ compensated ionization chamber & two RB-C2-2510- i04 uncompensated ionization chambers to Sweden PETERBONNH R Assistant Director for Export/Import & International Bafeguards. V-8627. B0/09/02 ip
- BOO9160236 Forwards application for license for minor nuclear export
 Lip of assurance required, N/o encl
 DEVINE, J. B. Assistant Director for Export/Import & International
 Safeguerds BO/08/27 ip
- 8009160274 Amend 1 to Bandvik Special Hetals Corp export license, extending expiration data from 800901 to 801130. PEYERSON, H R. Assistant Director for Export/Import & International Safsypards 9314 80/08/22 lp.
- 8009160278 Response in opposition to Ctr for Development Policy 800620 petition to intervene & request for heering Environ impacts in Taiwam are beyond Commission authority Effects on global commons already decided Hyappearance & Certificate of Syc DANKMEYER, T R General Electric Co 80/09/08 12pp
- 9009160287 Application by Westinghouse for license to export two incore neutron detectors Model WC-23465, each containing 0 025 g U, contained in 0 026 g enriches U-235, to Ewitzerland POCHAL.W F. Westinghouse Electric Corp. ZE-10327. 80/08/20 1p.
- BOO9160459 Submits application to amend license to export increasing amount to be exported to 5,000 ib depleted U to China, Albania & Romania as shielding in packaging, License currently limits U exports to 250 kg
 HUNRO, J J Tach/Ops (Technical Operations, Inc.) 80/08/18 2pp
- 8009:70195 Notifies of review of SECY-80-383 re Westinghouse application for license to export components to Korea. Commission accepts recommendation to export specially designed nuclear equipment to Korea
 HDYLE, J. C Office of the Becretary of the Commission 880-383-80/09/05 ip.
- BOO9180296 Executive Branch position re QA Co application for license to export low enriched U fuel to Indonesia Recommenda issuance of license Supporting documentation encl NOSENZO, L.V. Beate. Dept. of. Bureau of Oceans & Internati Environ & Brientific Affairs, B0/09/03 27pp.
- BOO9180420 Requests Executive Branch position re Westinghouse application for license to export initial cores. spares & three reloads each for Taiwen Units 7 & 8, PETERSON, M.R. Assistent Director for Export/Import & International Bafeguards. 80/08/27 ip
- 8009190126 Forwards notice of receipt of application by Honeywell Defense Sys to export 535,800 kg of depleted U to Canada. LAFLEUR, J D. Office of International Programs, Director 80/08/12, 19.
- --8009190128 Notice of receipt of application by Honeywell Defense Sys to export 535,800 kg of depleted U to Canada LAFLEUR:J D Office of International Programs, Director. 80/08/12, 2pp
- BOOP190245 Hithdraws application for License XBNN-15B5 on behalf of BAM. Requests advisement of receipt of request for cancellation of License IBNN-79015, EDLOW-J Ediow International Co. 80/08/19 1p

- 8009190258 Ltr of assurance re Transnuclear application for license to export 11,054 tg U.enriched to 4 3X U-235 to France MARCHAL.J European Communities, Commission of 80/08/25 ip
- 8009190571 Ltr of essurence re license to export BNM to Jepan Japan Nuclear Fuel Coultd has been appointed authorized person. HIYABAYASHIM Japan 80/08/25 ip
- 8009190687 Amend to license for QE & QE Technical Svcs Co. Inc. changing licenses name & address, deleting consignees, changing intermediate consignee address & deleting other export

DEVINE, J B Assistant Director for Export/Isport & International Safeguards BDH-79001 80/08/27 ip

8009190746 Requests Executive Branch position re RMI Co. Extrusion Plant application for license to export ii.340 kg depleted U enlid metal to Cenede
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/09/02 ip

- 8009190752 Requests Executive Brench position re Transnucleer application for license to export SAM to West Germany DEVINE, J B Assistant Director for Export/Import & International Sefaguards 80/08/29 ip
- 8009190755 Advises that Licenee X8NM-16B1 may be issued since no meth circumstances associated w/epplication have changed since issuence of License X8NM-1674.

 NORE.R. N Assietant Director for Export/Import & International Sefaguerds, 80/08/29 1p
- 8009230119 Advises that License XSNM-1678 may be lesued No methodanges occurred since issuance of XSNM-1895 MORECR N Assistant Director for Export/Import & International Safeguarde 80/08/29 ip
- 8009230417 License for Reactor Experiments, Inc to export 0 190 mg U-235 to Japan DEVINE.J. B Assistant Director for Export/Import & International Bateguards JAP 80253 80/08/29 2pp
- 8009230420 License for Westinghouse to export one unit campensated innixetion chember. Model ML23944, to Frence DEVING.J.B Assistant Director for Export/Import & International Safeguerds ZE-20203-5, 80/09/02, ip
- 8007230425 License for Cabot Corp to export 140,040 ft zirconium Orade 2 seamless tubing to Cenada. DEVINE, J.B. Assistant Director for Export/Import & International 84*eguards 1-9817(19-28012, 80/07/02 ip
- 8009230427 License for Sandvik Special Metals Corp to export 525 pieces nirconium metal tubes to Japan. DEVINELJ B Assistant Director for Export/Import & International Safeguards 0392 80/09/02 ip.
- 8009230428 License for Cabot Corp to expert 60,500 ft zircomium Grade 2 NYESO428 License for Casos corp to wager to 5.555
 seanless tubing to Cenada
 DEVINE J.B Assistant Director for Export/Import & International
 Bafeguards. 1-9816, 9818, 529. 80/09/02 1p.
- D09230429 Amend 1 to license for Trensnuclear, Inc to import 39,500 kg enriched U from France, extending expiration date from 800901 to 810901.
 DEVINE, J.B. Assistant Director for Export/Import & International Safeguards 80/08/28, ip.

- 1009230754 Advises of Reuter-Stokes withdrawal of License Application NYSON-1597
 DEVINE, J B. Assistant Director for Export/Import & Internetional Safeguards 80/09/08 ip.
- 007230781 Forwards application for export license for minor nuclear export Ltr of assurence required W/o encl. DEVINE, J B Assistant Director for Export/Import & International Safeguards. 80/08/29, ip.
- 009230783 Application by Westinghouse for license to export three ML-23448 incore radiation datectors to Japan, POCHAL, M. F. Westinghouse Electric Corp. ZE-60191 80/08/26 5pp
- 8007230777 Application by Edlow Intl Co for license to export 5 g U-010 & 5 g U-019 to Jepen HARMON, D W Edlow International Co SIB 8(8-97-90) 80/08/27 ip

- B009230800 Amend 1 to Transnuclear, Inc export license, extending expiration date from B01201 to B11201. DEVING.U B Assistant Director for Export/Import & International Bafeguards TNP-297 77-241/ 80/08/28 1p.
- 8009230801 Amend 2 to Transnuclear, Inc export license extending expiration dete from 800901 to 810901.
 DEVINE: J B Asistent Director for Export/Import & International Safaguards NUK 274 79-102. 80/08/29 lp
- 8007230803 License for Bandvik Special Metals Corp to export 3,315 pieces rirconium metal tubes to Japan.
 DEVINE. J B. Assistent Director for Export/Import & International Sefaguards, 0391 80/09/02 ip
- 80092405A9 RECY-80-393 Forwarde Executive Branch response on pending Transnucles. Inc application for license to export highly enriched U to SHEA, J R Office of International Programs, Director 60/08/22
- 8009250009 Mamorandum & order denying Ctr for Development Policy & Friends of Koreen Paople petition to intervene. Application for export of two reactors to Bouth Korea meets Atomic Energy Act criteria JF Abserne & JM Hendria opinion encl CHILKS.J Office of the Secretary of the Commission. CLI-80-34. B0/09/22.
- 9007250333 Forwards Transnuclear, Inc 800815 emend application to increase quentity of matl authorized for export.W/o enci PETERSON.M.R. Assistant Director for Export/Import & International Befeguerds 80/08/22, 1p.
- 8009250058 Confirms 800908 telcon re NRC review of license to export dauterium oxide to West Dermeny & urges action to effect shipment under convenient weather conditions MERNER, M. Deorge Une Co., Inc. 80/09/08 ip.
- 8009260195 Ltr of assurence to Westinghouse application to export 5,746 g U to Bweden ALLOARDH.O Sweden 80/09/04 ip.
- 8009260218 Forwards application for license to export 1,840 kg U. containing 0.016 kg U-235.to France
 MATBON.V. Transnucleer, Inc. 80-184/01, 80/09/03 ip
- --8009260224 Application by Transnucleer, Inc for license to export 1,840 kg U, containing 0,016 kg U-235, to Frence.
 MATBON, V Transnucleer, Inc 80-184/01 80/09/03 ip
- 8009270061 Requests Executive Branch position re United Nuclear Corp application for license to export 7,926 kg U to Hest Germany & other Europeen customers DEVING.J.B. Assistent Director for Export/Import & International Bafeguarde. 80/09/12 1p
- 8009290130 Executive Branch position re OA Co application for license to export electronic control console including instrumentation & power level control components to Belgium.
 License should be issued.
 NDSENZO.L. V State.Dept of. Bureau of Oceans & Internati Environ & Bcientific Affairs. 80/09/09 2pp.
- 8009290136 Executive Branch position re Transnuclear, Inc application for license to export 2 799Kg U-235 to West Germany. License should be issued, MOSENZO, L. V. State, Dept of, Bureau of Oceans & Internati, Environ & Scientific Affairs, 80/09/03, 4pp.
- 8009290147 Requeste Executive Branch position re Edlow Intl Co application for license to export 117,319 Kg U to West Oarmany. DEVINE.J.B. Assistent Director for Export/Import & International Safeguards. 80/09/11, ip
- 8009290149 License for Westinghouse to export three units in-core radiation detectors. Hodel NL-23448, to Japan. DEVINE. J. B. Assistant Director for Export/Import & International Bafeguards. ZE-60191, 80/09/12 ip.
- BO09290151 License for Aldrich Chemical Go to export 1.0 kg dauterium, contained in 5.0 kg deuterium exiderto Mexico DEVINE.J.B. Assistant Director for Export/Import & Internetional Safeguerds, 16/80. BO/09/12. ip.
- 8009290133 Forwards application for export license for minor nuclear export.Ltr of assurance required. M/o encl. DEVINE.J.B. Assistant Director for Export/Import & Internetional Safeguards. 80/09/ii jp

- 8009290137 End use statement for export of depleted U to Great Britain. HARMON D W Edlow International Co 80/09/08 ip
- BO09290259 Application by Mitsubishi Corp for license to apport 500 mCi snrapsulated cereet wire to Japan KU06. T Mitsubishi International Corp (subs of Mitsubishi Corp). 04~7462-80 B0/09/03 ip
- 8009290395 License for Matheson Oas Products to esport 90g deuterium to Avetralia. DEVINE.J B Assistant Director for Esport/Import & International Safeguards. 101-96919 80/09/11. 1p
- 8007270405 BECY-B0-40B Informs Commission of Executive Branch response on pending sugart application XBNM-1666 for Kartini Research Reactor Copies of original application & ltrs of assurance encl BHEALJ.R. Office of International Programs, Director 80/07/04
- 8009290476 License for CERAC, Inc to esport 20,0 kg thorium metal powder to Mest Germany.
 PETERSON, M R Assistant Director for Export/Import & International Safaguards. 80/09/17. 2pp
- 8007270485 Application by Sigma Chemical Co for license to export equivalent of 10 kg deuterium oxide to Brazil STERN, N. C. Sigma Chemical Co. (subs of Sigma-Aldrich Corp.) D-53. 80/07/12. 1p
- 8009290488 Application by Sigma Chemical Co for license to export squivalent of 10 kg deuterium to Singapore.

 BTERN.M.P. Sigma Chemical Co. (subs of Sigma-Aldrich Corp). D-52 BO/09/12. ip.
- 8007290581 Application by Bigma Chemical Co for license to export equivalent of 10 kg deuterium oxide to India.

 8TERN, M.C. Bigma Chemical Co. (subs of Bigma-Aldrich Corp.), D-51 B0/09/12. lp.
- BO07300024 Application by Sigma Chemical Co for license to export squivalent 10 kg deuterium oxide to New Zealand STERM.M.C. Sigma Chemical Co (subs. of Sigma-Aldrich Corp). D-50 80/09/12. ip.
- 8009300028 License for Westinghouse to export 146 kg U-235, contained in 5.746 kg U. to Sweden. PETERSON, M.R. Assistant Director for Export/import & international Bafsyuards. ICB-0292, 80/09/17. 2pp.
- 8009300032 License for DOE to import 245 kg U.enriched to 2.95% U-235, from Cânada. DEVINE.J.B. Assistant Director for Export/Import & International Bafaguards. 80/09/17. ip
- 8009300059 Requests Esscutive Branch position re Monsanto Research Corpapplication for amend to license to esport Cf-252 & Cm-242 & 244 to New Zealand.

 DEVINE, J. E. Assistant Director for Export/import & international Safeguards. 60/09/17 ip
- 8007300062 Forwards application to amend license to export Pu-238 sealed rediation sources, adding New Zealand to list of countries.
 TAYLOR, R. R. Monsanto Co. 80/07/08, 2pp
- ---8009300064 Application by Monsanto Research Corp to emend license, adding New Zealand to list of countries TAYLOR, R.R. Monsanto Co. 80/09/08, 4pp.
- BOO9300071 Requests Executive Branch position re Edicu intl Co application for license to export 5,000 kg depleted UF4 to Great Britain. DEVINE, J. B. Assistant Director for Export/Import & international Safeguards. BO/09/16. 1p.
- 8009300074 Executive Branch position re B&W application to export 430 kg depleted U to Japan, License shhould be issued Ltr of assurance encl.
 NOSENZO,L.V. State, Dept. of, 80/09/08 3pp.
- 8009300078 Application by Transnuclear, Inc for license to import 1510 tg U from West Osrmany. MATBON, V. Transnuclear, Inc. 80-178/02, 80/09/05. 2pp.
- 9007300077 Forwards application by Transnuclear, Inc for license to apport 4.371 kg U to Austria Related end use statement & reactor checklists encl.

 MATSON, V Transnuclear, Inc 80/09/08 ip.

- --8009300084 Application by Transnuclear, Inc for license to export 4 371 kg enriched U to Austria MATSON, V. Transnuclear, Inc NUX-345 80-188 80/09/08 3pp
- 8007300088 Application by GA Co for license to export components & replacement parts to Italy MOMRY,M.R General Atomic Co (subs of Gulf Dil Corp.) IEL-2012 80/09708 3pp
- 8009300650 Executive Branch position re Coordination Council for North American Affairs application for license to export 4,000 kg of heavy water to Taiwan License should be granted Ltr of assurance encl.

 NOSENIG.L V. Btate, Dept of 80/09/05 3pp
- 8009300652 License for 84W to export reactor vessal O ring gastets, gasket retaining clips & clip screws, all specially designed for use in nuclear reactor, to South Korea DEVINE, J B Assistant Director for Export/Import & International Refeguards 768-988052-51 80/09/05 ip
- 8009300655 Requests Executive Branch position re Transnuclear, Inc request for amend to license to export add1 1,144 kg of normal U oxide.as U oxide.to West Germany DEVINE.J.B Assistant Director for Export/Import & International Safeguards 80/09/08 tp.
- 8009300557 Amend 1 to license for Reuter-Btokes, inc to export 10 add1 radiation detectors, Models RS-C6-0201-231, to South Korsa DEVINE, J.B. Assistant Director for Export/Import & International Safeguards. UE-8025, V-8636. 80/09/09 1p
- B009300660 Executive Branch position re George Uhs Co. Inc application for license to export 2,250 lbs of heavy weter for uss in nuclear resonance spectroscopy to Hest Germany License should be granted.

 NOSENZO,L V Btate. Dept of. 80/09/05. 2pp
- 8009300662 License for Dept of Navy to export 5.076 Kg depleted U.as component of 74,000 rounds of ammunition to Bingapore DEVINE, J B Assistant Director for Export/Import & International Bafeguards SER 63/779123 80/09/08 ip
- 8009300664 Executive Branch position ra Dept of Navy application for license to export 5,076 kg depleted U to Bingapore Proposed export may be made w/o being sub; to terms of Agreement for Cooperation License should be granted NOSENZO,L V State, Dept of. 80/09/03, 2pp
- 8009300666 License for Mitsui & Co to export 0 325 g U-235, contained in 30 g U-to Japan DEVINE, J. B. Assistant Director for Export/Import & International Bafeguards. 80/09/08. 2pp.
- 8009300668 Application by Edlow Intl Co for license to export i17.319 by U.contained in 138.348 by U-308, to West Germany.
 HARMON, D. W. Edlow International Co NUEX-1 80/09/02 ipp
- 8009300670 Application by Mathsson Gas Products for license to export 500 liters deuterium in Bize 3 cylinder to Venezuela JAROD, L. Matheson Gas Products. i01-94099-A. 80/08/28 ipp

			I

PERSONAL AUTHOR INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCEBBION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUTJECT
AREL, J 8	6009150399	71-9113	AKER, R. E	8007020401*	50-275 B	ARNOLD, R. C.	B009300014	50-320 G
ABEL, J. 8.	8009110737*	50-254 G	AKERIR, E.	80070204574	50-275 6	ASH, R. F.	8009080350	50-317 F
ABEL, J. S.	E007110545	50-237 Q	AKI,K	2009120514*	50-20& P	ABH, R. F.	8009160453	50-317 P
ABEL, J. B.	E009160681	50-237 9	AKIN, R. C.	8007170378*	50-204 P	ASHENDEN, M. C.	B009030281#	50-390 G
ABEL: J. 8	8007120453	50-10 F	ALBERT, O	8007220204*	50~287 H	ASHELL, D. L.	8009170368	50-392 4
ASERCROHBIE, H	8009170277*	50-259 R	ALDEN, N H	04E0B07008	50-277 R	ASHELL, D. L.	8009190158	50-382 Q
ABERCROHBIE, H	8009170274	50-259 R	ALDEN, H. H	8009160296*	50-277 R	ABHELL, D. L.	6009190153	50-382 Q 50-382 B
, A . BHAREA	6007050429	PR	ALGER, D H	8007040419*	50-196 8 50-278 8	ABHELL, D. L.	8009300342 8009300092	20-385 0
ACKERMAN, W C.	8007100288	40-8102	ALLEN, M. D	2007050331*		ASHELL, D. L.	8009300212	50-382 0
ACKERHAN, H. C.	8009170134	40-8745	ALLQARDH, O	8007260175	XPORTLIC	ABHELL, D. L.		
ACOSTA, A. P.	8009110850	40-9584	ALL ISON, D. P	8009290143	50-10 P 50-10 P	ABHELL, D L.	8009190491 8009290394	50-382 H 50-382 B
ACOSTA, A P	8009030470	40-8584	ALLISON, D. P.	8009240022	50-10 P 70-2909	ABHELL, D. L. ATKINSON, E. V.	B009020323+	50-320 H
ADAM: H. J.	8005300695*	PT9	ALLRED, D. L.	8009040242 8009190024#	QA999	ATTERIDOE, D. Q.	8009020219	50-445 A
ADAM, L. E.	E009220190*	50-289 K	ALMEDA, D. C. ALMEDA, D. C.	8007170024*	QA999	AUSTIN M A.	8007110244	70-135
ADAMB, D.P.	6009190779	40-4492						
ADAHS, F. T.	8009260482*	TOPREP	ALTERMAN, I. D.	8009170639*	50-133 P	AUSTIN H A	8009230138 8009090876	70-364 70-135
A BHADA	8009030427*	50-255 Q	ALTHOUSE, V	B009030480=	30-289 H 50-293 G	AUSTIN, M. A. AUSTIN, M. A.	8007190183	70-135
ADLER: T. A	8009240535	50-289 Q	ALUKONIB, J	8009050484 8009150411	70-273 G	AUSTEN, M. A.	8007180196*	70-135
ADLER, T A	8007240538*	50-287 Q 50-287 Q	AMOB, M R	6007190383*	FOIA	AUSTIN, M. A	E009150480	70-135
ADLER, T. A.	800924053B*	50-289 Q	ANDERS.W A					
ADLER, T. A	8009300629	50-287 O	ANDERSON, J. O.	#A&&OPOPO&36#	50~275 T	AUSTIN M A.	8009150019	71-6400
ADLER, T. A.	8009300632*	50-289 0	ANDERSON, T. K	8007080274	50-34B P	A .H .HIYEUA	8007150553	71-5442
ADLER, T A.	8009300629	50-287 0	ANDERBON, T. H	8009190453*	TOPREP	AUSTIN, J. H	8009290026* 8009110329	50-327 T 50-29 B
AGEE, J. R.	B009120335*	GA777	ANDERSON, W. E.	8009020219	50-445 A	AUTIO, H. A AXELRAD, M	6007110327	PR PR
AQUILERA H F.	8007100407*	CONTRACT	ANDERSON, T. M.	8009040409	TOPREP			
AHEARNEI J. F.	8009180291*	10CFR	ANDERSON, C.	B00911074R	50-322 A	AXELROD, D.	9007020500 8007050434	State Prop
ANEARNE, J F	8007080573	COMMISSION	ANDERBON, T. V	8009300197*	50-243 R	AXECRAD, M.	8007050434	PR
AHEARNEI J. F.	OEEO90900B	50-339 P	ANDEREON, D. R.	8007160481	NUREQ 50-244 P	AXELRAD, M AXELRAD, M	8007180148	50-376 9
AHEARNE, J. F.	8007070346 8007070338	50-339 P 50-339 U	ANDERSON, C. R. ANDERSON, F.	8007070382* 8007270171*	50-170 F	AXELRAD, H	8009160151+	80-376 9
						AUTI BAD M	8009160148	50-376 9
ahearne, J. F	800902036B	COMMISSION	ANDERSON, T M	8009180341	TOPREP NUREQ	axelradim Axelradim	8009160181*	50-376 Q
AHEARNE, J F	8007070637	COMMISSION	ANDERBON, T. M.	9009220275 9009190457	TOPREP	AXELRAD, H.	B007300462	50-376 0
AHEARNE, J. F	8007110408	COMMISSION	ANDERSON, T. M.	8009190374*	50-206 P	AYER, J. E.	B009100232	70-1257
AHEARNE, J. F. AHEARNE, J. F.	8009140444 8009100073	COMMISSION 50-352 U	ANDERSON, T. H ANDERSON, T. M	0007230485	TOPREP	BACHHANN, R. Q.	B007110015	70-1308
AHEARNE, J. F	800910007E*	50-352 U	ANDOONINI. Q G	B00909004B*	50-293 G	BACHHANN, R. Q	8009170126	70~2909
AHEARNE, J. F	8007100075*	COMMISSION	ANDOONINI. O. C.	6009190076*	50-273 G	BACHMANN, R. G.	8009170160	50-54 0
ANEARNE J. F	8009100098	COMMISSION	ANDOONINI. O C.	8009020110	50-293 0	BACHMANN, R. Q.	B009300018	70-1308
AHEARNE, J. F.	8009100102*	COMMISSION	ANDOONINI. O. C.	8009080546	50~293 0	BACHHANN, R. O.	6009300049	70-1308
AHEARNE JF.	8007100111	COMMISSION	ANDOONINI. O. C	8007070860	50-293 @	BACKUB, R. A	8009020034	50-443 9
AHEARNE, J. F	8009100114*	COMMISSION	ANDCONINI. C. C.	8009120036	50-293 G	HAER, T. S.	8009260169	71-605B
AREARNE, J. F.	8009100116*	COMMISSION	ANDOONINI, O C	8009160516	50-273 G	BAER, D. K.	8009020358	NURED
AREARNE, J. F.	8009100122*	COMMISSION	andognini. Q. C.	8009160519	80-293 Q	BAOAOLIO, M.	8009230219#	80-275 G NURED
AMEARNE, J. F	B009100124*	COMMISSION	anddonini. G. C.	8007170740	50-293 @	BAILEY, R. D.	8007120337	50-220 G
AHEARNE, J. F	8009100126*	COMMISSION	ANDOONINI. G C	8009090034	50-293 G	BAILEY, R J	8009160242#	4# ··
AHEARNE, J. F.	8009120477	COMMISSION	ANDRENS, C. L	8007070384	50-280 J	BAILEY, E. D.	8009190894 8009100242#	State Prop 50-344 R
AHEARNEI J. F.	8009120480*	COMMIBBION	ANDRUS, N. J.	8009100654	40~4492 50-369 G	Bair, O. O. Baisden, L.	8009040468	CONTRACT
AHEARNE, J. F	8009120483*	COMMISSION	ANG. H P	8009240241#	30-348 G	BAIEDEN, L	8007110001	CONTRACT
AREARNE, J. F	8007120484*	COMMISSION	ANO, H. P.	#9009190609# #1011909	50-345 G	BAISDEN, L.	8007100034	CONTRACT
ALIEARNE, J. F	8009120485*	COMMISSION	ANG. W. P.					
AHEARNE, J. F	8009120489*	COMMISSION	ANTHONY, B	8009120494*	COMMISSION	Baisden, L. Baisden, L.	8009240073	CONTRACT
AHEARNEI J. F.	8007150410	COMMISSION	APPELHANS, A D.	800926055B 8009290331	50-320 H	BATEDEN, L.	8007110346	CONTRACT
AHEARNE, J. F	8009300250	COMMISSION	AREHART, T.	B009140436#	TOPREP	BAIBOEN, L.	8009120048	CONTRACT
AHEARNE, J. F.	8009290023*	50-327 T 50-327 T	ARNOLD, R C.	8009020037	50-320 P	BAISDEN, L.	8007270137	CONTRACT
AHEARNE: J. F	8009290021	40-9 €/ 1	COULDAND III DA	44-14-641				

AUTHOR	ACCESSION NUMBER		ECT	AUTHOR	ACCESSION NUMBER	CATEO	T RY	AUTHOR	ACCESSION NUMBER	BUBJE CATEO	
BAKER, K R. BAKER, K R BAKER, K R BAKER, C E BALL, S. J	8009260420 8009100140 8009290436 8009300409 8009100953	\$ 50-25 \$ 50-29	5 Q 5 Q 81	Bayne, J, P Bayne, J, P Bayne, J, P Bayne, J, P Bayne, J, P	8009220379 8009040420 8009050273 8009120362 8009150254	50-284 50-286 50-236 50-333 50-286	9 P P P	BISHOP.C J BISHOP.C J BISHOP.C J BISHETT.P H BISHETT.P H	8007260469 8007270043 8007260445 8007160186* 8007150358*	50~275 50~387 50~409 70~135 70~135	•
BALLARD, R L. BALLENTINE, J M BALLENTINE, J M BALLINGER, P. L BALOUGH, R. C.	90091500644 9009170262 9009170261 90091602644 9009160332	50~32 50~32	7 R 7 R 8 R	BAYNE, J. P BAYNE, J. P BAYNE, J. P. BAYNE, J. P. BAYNE, J. P.	8009170325 8009180384 8009230451 8009260442 8009260446	50-286 50-286 50-247 50-286 50-333	ቴ ዩ ዩ	BITNER, J L BIXLER, Q BIXLER, E BJORKLUND, P. P BJORNARD, T A	8009020017* 8009020314* 8009220346 8009020194 8009260504*	50~537 50~320 50~320 50~320 TOPREP	H
Balter, J Bandazza, J. B Bandorth, C. S. Bari, R. A Barker, M. R	9009050370 90092305914 90092200374 90082106184 9009150228	50-33 50-32	9 P 9 H 7 P	BEACH, A B BEACH, A B BEACH, A. B, BEARD, E P BEATTY, D,	8009150357* 8009250398* 8009150362* 8009110267 8009220128*	50-458 50-458 50-458 70-820 HIBG	G G	BLACK,R L. BLACK,R L BLAKE,J J BLAKE,E.L. BLAKE,E.L.	8007110014 8007300012 8007240374* 8007110020 8007300011	50~466 50~466 50~324 50~289 50~289	0 0
BARKER, N.R. BARKER, J.L. BARKER, N.R. BARKER, D. Q. BARKER, J.L.	8009150226* 8009100148* 8009150223* 8009180473 8009260404*	50-10 GA797 50-498	a 9 q 0	Beghhoefer, C. Bechhoefer, C Bechhoefer, C. Bechhoefer, C Beck, O.P.	8009220413 8009250012 8009250001 8009300030 8009150456	50-358 50-409 50-409 50-498 50-356	9 9 9 R	BLEVING, C.N. BLOND, R.M. BLOSBOM, J.N BLUMBERG, N. BLUMBERG, N.	8009160543 8009120626 8009030462 8009100399* 80091103()*	Waste 1 50-247 40-845; 50-334 50-333	ş
EARLEY, R. BARNES, I. BARNES, I. BARR, D. W BARRACK, T.	8007250414# 8007170031# 8007170158# 8007300286# 8007170046	GA999 GA999	,	Beckman, D. A. Becksted, W F Beecle, C. W Beers, F. C Beers, F. C.	8009110050* 8009120699 8009110361 8009160301* 8009160259*	50-334 PT21 FOIA 50-271 50-309	Q R R	BLUME, J A BLUME, M B. BOBLINGER, L. H. BODTKE, P. J. BOODEN, O	8007020100* 8007070337 8007070537* 8007120462* 8007260041	50-206 50-348 50-458 50-255 40-1163	р Н Б В
BARRETT, P. A BARRY, L. H. BARRY, C. B. BARRY, D. BARTH, C. A	9007110661* 9007050455* 9007030678* 9007220240 9007020445	FOIA	_IC	BEERS, F. C. BELISLE, Q. A BELISLE, Q. A BELL, D. A. BENDA, B. J.	8009160303* 8009050441* 8009120071* 8009250456* 8009120338	50-29 50-280 50-348 50-341 NUREO	R Q Q A	Boden, o Boden, o Boden, o Bohn, r. J Bohn, r. J.	8007180417 8007150550 8007300141 800702005 8007020051	40~1162 40~1162 40~1162 50~367 50~367	2
BARTH, C. A. BARTH, C. A. BARTH, C. BARTH, C. A. BARTH, C. A.	8009110023 8009160176 8009300039 8009260251 8009300007	50-282 50-486 50-282 50-486 50-237		BENDER, B. BENDER, B. BENEDICT, D. E. BENNETT, T. J. BENNETT, S. L.	8009290398* 8009290401* 8009020431 8009020483 8009300197*	50-382 50-382 50-30 NUREO 50-243	8 8 8	BOHN, R. J. BOHN, R. J. BOHN, R. J. BOHN, R. J. BOHN, R. J.	8009090429 8009090489 8009150474 8009250297 8009200446	50-367 50-367 50-367 50-367 50-367	A A A R
Bartlett, J. Baskin, K. P. Baskin, K. P. Baskin, K. P. Baskin, K. P.	8009180268 8009160626 80090200278 8009020063 8009020082	50-220 50-361 50-361 50-206 50-206	Q F P	BENNETT, R. C. BERGER, D BERGGUIST, R. G. BERKLEY, J. BERHAN, M.	8009150168 8009020050 8009260018 8009170332 8009190743	50-324 50-266 50-440 50-352 NUREO	9 U 8 F	BOHN, R. J. BOLON, A E BONZON, L. L. BOODY, F. P. BOOK, H E	8009300419 8009240441 8009190398 8009120414# 8009080544#	50-367 50-201 NUREO 70-258 50-298	A P
Baskin, K. P. Baskin, K. P. Baskin, K. P. Baskin, K. P Baskin, K. P	9009020006 9009300017 9009030387 9009080343 9009090463	50~361 50~361 50~206 50~206 50~206	F	BERMAN, M. BERNERO, R. M. BERNREUTER, D. L. BERNREUTER, D. L. BERNRETEIN, D. L.	8009240469 8009120624 8009180434 8009180444 8009100429	NUREO 50-247 NUREO NUREO 50-282	P O	800K, H E 800K, H, E, 800K, H, E 800K, H, E	B007080567* B007020254 B007020261* B007240407 B007240533*	50-298 70-734 70-734 50-147 50-147	0 0
Baskin, K.P Baskin, K.P Baskin, K.P. Baskin, K.P. Baskin, K.P.	8009190361 8009090352 8009050286 8009030302 8009160230	50-206 50-206 50-206 50-361 50-206		Bernstein, D L Berry, O. T. Beshear, B. L. Bettenhausen, L. Bevill, T.	8007100427 8007120376 8007100575 8007100861* 8007120474*	50-282 50-264 50-358 50-277 COMMISSI	0 0 0 1	800K, H. E 800K, H. E 800K, H. E, 800K, H. E 800K, H. E	8007020237* 8007020235 8007270131* 8007200324* 8007300318*	70-984 70-984 50-254 50-344 50-344	0 0
Baskin, K. P. Baskin, K. P. Baskin, K. P. Baskin, K. P. Baskin, K. P.	9009080322 9009180421 9009190402 9009170336 9009290348	50-206 50-361 50-206 50-206 50-206	P P P	BEYER, J M BEZLER, P, BIALIK, E, I, BIALIK, E, I, BIALIK, E I	B009050498# B009240686 B009050429 B009300525 B009300525	50-320 NUREO PR 50-201 50-564	ы 6	BDOK, H E BOOK, H, E. BOOK, H E BOOKB, P. A BORDAN, A. J.	8009120214 8009300162 8009300312 8009180381 8009090537*	I&E 1&E 50-344 50-320 50-458	Q 원 본
Baskin, K. P. Baskin, K. P. Baskin, K. P. Bassin, N. Bateman, N. H.	8009300377 8009300362 8009300448 80090805664 8009190223*	50-206 50-206 50-298 50-254	P P G G	BIALIK, E. I BICKWIT, L. BIELAWSKI, A BIELAWSKI, A P BIELAWSKI, A, P.	8007300525 8007080261* 8007060256 8007070233 8007070233	70~1432 FOIA FOIA 50~559 50~599	0	BORDENICK, B. M BORDENICK, B. M. BORDENICK, B. M. BORDENICK, B. M. BORDENICK, B. M.	8009020411 8009040248 8009040261 8009170231 8009250003	50-322 50-322 50-498 50-322 50-322	0000
BATEMAN, H. H BAUER, E. G. BAUM, E. A BAUM, E. A	8009150190# 8009180316# 8009030184 8009090274	50-354 50-277 50-280 50-133 50-290	O P R F	Bieniarz, P. P. Bierman, B. R Bigiarelli, M. J Birkel, R. A Birkel, R. A.	8009260669 8009100413 8009020383* 8009030069 8009300043	NUREO NUREO 50-245 50-349 50-389	8 A A	BORDENICK, B. M BORDENICK, B. M BORES, R. J. BORES, R. J. BORES, R. J.	8009250020 8009300001 8009190056# 8009150124# 8009150137#	50-498 50-322 50-352 50-219 50-271	0000
BACHACK, M BAUSER, M. A. BAXLEY, S. X. BAXLEY, S. X.	9007160429 90071003999 9007230644 9007020469# 9007150283#	50-338 50-334 FR 50-321 50-321	P Q 6 8	Birkel, R. A. Birkel, R. A Birkel, R. Bibcoff, C. A. Bibcoff, C. A.	8009300644 8009300667 8009290175 8009030714 8009030714	50-249 50-389 50-347 50-528 50-528	A A F O O	Boromann, e. a. Boromann, e. a. Boromann, e. a. Boromann, e. a. Boromann, e. a.	8009300126* 8009250227* 8009290460* 8009030588 8009170422	FOIA 50-358 50-358 50-358 50-358	9 9 F 9
BAXTER, T. A.	8009090784 8009090788# 8009090784 8009090788# 8009090570	50-312 50-312 50-312 50-312 50-483	0	BISHOP, T W BISHOP, T W. BISHOP, C. J. BISHOP, C. J. BISHOP, C. J.	8009150378# 8009040482# 8009030112 8009050432 8009050437		a a o o	Boromann.e a. Boromann.e a Bosnak.r J. Bobbenmaier, u. Bobbell. J., M	8009170429 8009260137 8009180506 8009260472 8009120540	50-358 50-358 50-219 50-312 RECOD	9 8
BAXTER, T. A. BAYMARD, P. Y. BAYMARD, P. BAYMARD, P. Y. BAYMARD, P. Y.	9009300570 9009190786 9009030206# 9009030230 9009090442	50-483 50-302 50-302 50-302 50-302	0 0 R F P	Bishop, C. J. Bishop, C. J. Bishop, C. J. Bishop, C. J. Bishop, C. J.	8007080518 8007070395 8007120403 8007160438 8007160525	50-263 50-219 50-263 50-155	0 0 0 0 0	ROWNING ROWN ROLL OF THE ROLL	9007300287 9007160033 9007160041* 8007160033 9007160041*	FOIA 50-389 50-389 50-389 50-389	H H H
BAYNARD, P. Y. BAYNARD, P. Y. BAYNARD, P. Y. BAYNARD, P. Y. 'AYNARD, P. Y.	9009090278 9009300143 9009170288 9009180285 9009220361	50-302 50-302 50-302 50-302 50-302	e e e e e e	BISHOP, C. J. BISHOP, C. J. BISHOP, C. J. BISHOP, C. J. BISHOP, C. J	8007170116 8007180537 8007190187 8007190417 8007280032	50-488 50-488 50-344 50-367	00000	Bouknight, J. A. Bouknight, J. A. Bouknight, J. A. Bouknight, J. A. Bournia, A.	8009170232* 8009170235* 8009300476 8009300476 8009310420	50-445 50-445 50-250 50-250 50-273	H

AUTHOR	ACCEBBION NUMBER	GUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION	SUBJECT CATEGORY
Bournia, a	8009150016	50-438 A	Brown, W F	8009030676	FR	BUDNITZ,R J BUDNITZ,R J BUDNITZ,R J BULLINOTON,R L BURCHETTE,W H	8009190205*	HISC
Bournia, a.	8009110715	50-373 A	Brown, O D	8009100205*	40-6659		8009040459	SECY
Bournia, a.	8009180540	50-373 A	Brown, W F	8009160209	PRM		8009150543	RES
Bournia, c.	8009180527	70-820	Brown, O	8009180093*	40-8594		8009120662*	CONTRACT
Bournia, c. E.	8009110221	70-820	Brown, O D	8009180203*	40-1162		8009170361	50-445 O
Bomere: C e Bomere: C. e Bomere: C. e Bomere: C. e. Bomyer: J. e	8009110235 8009170005* 8009110252* 8009110230 8009290085*	70-820 70-820 70-820 70-820 FOIA	Brown, W, K Brownlee, V L Brown, H H Brown, O, D	8009050214* 8009150304* 8009020337* 8009190629 8009180027	71-9508 50-438 Q 50-327 Q FDIA 40-2259	BURCHETTE, W H BURCHETTE, W H BURDETTE, T E BURDEN, R. E BURDER, A C	8909170232* 8009170364* 8009110427* 8009290039* 8009150355*	50-445 M 50-445 M 50-413 G FOIA 50-320 H
BDYD, R. B.	8009150044*	50-271 U	erown. C. D	8009180089	40-8584	Burger, F J	8009260271*	50-282 0
BDYD, D. C.	8009050216*	50-255 G	Brown. C D	8009180193	40-1162	Burke, D. J	8009160301*	50-271 R
BDYD, D. C.	8009300224*	50-255 G	Brown. C	8009180033*	40-2259	Burke, D. J	8009240713*	50-280 0
BDYER, V. B	8009300367	50-277 P	Brown. C D	8009180081*	40-8452	Burke, D. J	8009020220*	50-280 0
BDYER, V. B.	8009290380*	50-352 B	Brown. C D	8009180072	40-8452	Burkhardt, W	8009100232	70-1257
BRADEURY, V. A	8009110382	50-275 H	BROWN, O. D.	8007240729*	40-299	Burmaster, M	8009230004*	50-409 Q
BRADEDRD, P. A.	8009180298*	10CFR	BROWN, O. D.	8007240721	40-299	Burmett, R. F	8009120170	70-33
BRADEDRD, H. H.	8009110202*	50-348 G	BROWNEWELL, R. P	8007170317*	50-320 P	Burmett, R. F	8009150524	70-364
BRADEORD, P. A.	8009270021	50-327 T	BROWN, O. D.	8007080472	40-3453	Burmb, B. O	8009030134	50-409 Q
BRADCEY, B.	8009020191*	50-219 H	BROWN, M. E.	8007180064*	QA999	Burmb, B. O	8009110017	50-255 Q
BRADCEY, J. P.	8009030440*	50-295 P	erown, J. F	8009160488*	CDNTRACT	Burrell, A	8007260646*	50-201 Q
BRADCEY, E. J.	8009150478	50-277 F	Brown, B. C.	8009020236	50-404 Q	Burris, L	8007300540	50-201 Q
BRADCEY, E. J	8009180304	50-277 P	Brown, B. C.	8009020399	50-404 Q	Burstein, S	8007020477	50-266 P
BRADCEY, E. J	8009180316*	50-277 P	Brown, B. C.	8009020416	50-404 Q	Burstein, S	8007030542	50-266 F
BRADCEY, E. J.	8009290378	50-352 B	Brown, B. C.	8009250087	50-404 G	Burstein, S	8007160442	50-266 P
BRADSHAW, J.L.	8009090343*	50-339 U	BROWN, P	8009120444	50-206 H	BURBTEIN, B	8009300305	50-266 P
BRADY, R.W.	8009230777*	CONTRACT	BROWN, B.	8009160276*	50-254 R	BURBTEIN, B	8009250249	50-266 F
BRAILETT, L.W.	8009120590	RES	BROWN, C. F.	8009100590	PR	BURBTEIN, B	8009290177	50-266 F
BRAMLETT, L.S.	8009090568*	50-313 S	BROWN, R. H	8009110019	50-275 Q	BURBTEIN, B	8009290341	50-266 P
BRAMLETT, L.S.	8009230700*	50-313 R	BROWN, R. H	8009110019	50-275 Q	BURTBAVAGE, E M	8009190732	RECOD
BRANDETT, E. B. BRAND, M. E. BRAND, H. E. BRAND, H. E. BRAND, M. E.	8009230715# 8009020468# 8009150312# 8009140337 8009150307	50-313 B 50-395 M 50-395 M 50-395 O 50-395 M	BROWN, W. J BROWN, H. H BROWN, H. H BROWN, M. H. BROWN, O. F	8009100444 8009150404 8009150404 8009220406 8009190529	FR 50-275	BURKELLIS.B BUSCHIR W. BUTLERIW A BYTNOTONIJ H	8009100004 8009180528 8009300190 8009240070* 8009230499	50-445 A 50-522 G 1&E FOIA 50-412 I
Braulke, o r	8009260396*	50-289 T	BROWN, H H	8007230616	50-275 Q	BYRD: P K	8007230475*	TOPREP
Bray, y. c.	8009020356*	50-297 R	BROWN, H H	8007230616	50-275 Q	CADENA: D O	8007150174	REGOD
Braiill, o J	8009260396*	50-289 T	BROWN, O F.	8007240563	PR	CADWELL: J	8007110416	RES
Breed, A.	8009030557	TOPREP	BRUQQER, R M	8007040406	50-186 B	CADWELL: J. J	8007070770	RES
Brennan, J. E	8009170345	50-309 F	BRUQQER, R M	8007040418	50-186 B	CAHN: A L.	8007170672	NUREO
Brickley, R. H	8009120335*	GA777	BRUGGER, R. H	8009190594	71-5088	CAIN.C L	8009100199*	40-4659
Brickley, R. H	8009120657*	GA797	BRUGGER, R. H	8009230586	50-186 P	CAIN.C L	8009080487*	40-3453
Brickly, R. H.	8009290101*	50-346 G	BRUNNER, E. J	8009100392*	50-334 Q	CALDWELL.R A	8009170174*	50-313 0
Bridenbaugh, D.	8009160284*	PR	BRUNNER, E. J	8009110301*	50-333 Q	CALDWELL.R A	8009170183*	50-392 0
Briemmurby, L. J.	8009030728*	50-282 G	BRUNNER, E. J	8009190078*	50-273 Q	CALDWELL.H A	8009110387	50-327 H
BRIOGS, L. BRIONT, R. M. BRINKLER, J. E. BRINKLER, J. E. BRISCOE, Q. A	8007110663 8007100733 8007260642* 8007260503* 8007230202*	50-272 8 50-302 0 50-307 8 50-307 8 50-287 H	BRUNNER, E J. BRUNNER, E J. BRUNNER, E. J. BRUNNER, E J BRUNNER, E J	8009090244# 8009120195 8009150082 8009150137# 8009160229#	50-267 Q 50-247 Q 50-245 Q 50-271 Q 50-277 Q	CALHOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J R	8007030367 8007030517 8007030488 8007030597 8007070547	50-327 8 50-327 8 50-259 8 50-276 B 50-327 8
BROCKETT, T. W	8008210619	1&E	BRUNNER, E. J	B009100B47	50-247 @	CALHOUN: J R.	8009080354	50-327 8
BROCKETT, T. H.	8009040591	50-333 &	BRUNNER, E. J	B0091B0001	50-334 @	CALHOUN: J R	8009080360	50-327 8
BROCKETT, T. H.	8009020510	50-286 &	BRUNNER, E. J	B009100B74	50-293 @	CALHOUN: J. R	8009080373	50-327 8
BROCKETT, T. H.	8009190418	1&E	BRUNNER, E. J	B009150159	50-322 @	CALHOUN: J R	8009090467	50-240 8
BROCKETT, T. H.	8009190565	50-285 &	BRUNNER, E. J	B0091501B0	50-277 @	CALHOUN: J R	8009030558	50-259 8
BROCKETT, T. W.	8009300048	I&E	BRUNNER, E J.	8007110663	50-272	CALHOUN, JR	8007080382	50-327 8
BROCKETT, T.	8009300166	I&E	BRUNNER, E J	8007100837		CALHOUN, JR	8007070527	50-327 8
BROEHL, D. J.	8009020039	50-344 P	BRUNNER, E J	8007110047		CALHOUN, JR	8007070531	50-327 8
BROEHL, D. J.	8009100449	50-344 B	BRUNNER, E J	8007110507		CALHOUN, JR	8007070314	50-296 8
BROMBERO, B.	8009230354	CONTRACT	BRUNNER, E J	8007070237		CALHOUN, JR	8007070443	50-260 8
BROMBERO, B.	8009230364	CONTRACT	BRUNNER, E J	8007100384	50-334	CALHOUN, J. R.	8007070557	50-259 B
BROMBERO, B.	8009120010	CONTRACT	BRUNNER, E J	8007150430		CALHOUN, J. R.	E009120411	50-327 B
BROMBERO, B.	8009120023	CONTRACT	BRUNNER, E, J	8007170073		CALHOUN, J. R.	E009120412	50-327 B
BROMBERO, B.	8009260232	CONTRACT	BRUNNER, E, J	8007020501		CALHOUN, J. R.	8009140325	50-327 B
BROOMS, E. H	8009150115*	50-302 Q	BRUNNER, E J	8007170575		GALHOUN, J. R.	8009160375	50-327 B
BROOKS, R. BROOMFIELD, N. S. BROWSHTON, T. O. BROWSHTON, T. O. BROWSHTON, T. O.	8009190046 8009110288* 8009260322* 8009260411* 8009260439*	50-250 9 50-320 H 50-289 T 50-289 T 50-287 T	BRUNNER, J.E. BRUNNER, E. J. BRUSH, P. N. BRYANT, W. H. BRYANT, W. H.	8009190420 8009300600 8009120605 8009120413* 8009120417*		CALHOUN, J. R GALHOUN, J. R CALHOUN, J. R CALHOUN, J. R CALHOUN, J. R	8007070332 8007070470 8007160416 8007160421 8007160432	50-296 B 50-260 B 50-296 B 50-327 B 50-260 B
BROWN, F. R. BROWN, M. BROWN, K. H. BROWNING, M BROWNING, M	8009180237* 8009170286* 8009260419* 8009270156* 8009080335*	50-546 0 50-320 H 70-1167 FOIA 50-133 R	eryan, J. K. Eryant, J. C Bryan, J. K. Eryan, J. K. Bryan, J. K.	8009100080* 8009180459* 8009090546 8009230451 8009230462	50-400 Q 50-483 B 50-483 B 50-483 K	Calhoun, J. R.	8009160454 8009160390 8009160406 8009160463 8009190471	50-260 S 50-327 B 50-327 S 50-327 S 50-327 S
BROWN, O. D.	8007080552*	50-278 G	BRYAN, J K	800 9300447	NUREO	CALHOUN, J. R	8009190440	50-260 8
BROWN, O. D.	8007080557	50-278 Q	BRYAN, B, E	800 9240260	30-255 C	CALHOUN, J. R	8009190465	50-259 8
BROWN, O. D.	8007100177*	40-6659	BUCCHOLZ, R H	800 9050325	TOPREP	CALHOUN, J. R	8009190467	50-259 8
BROWN, R. L.	8007150021*	GA779	BUCHHOLZ, R H	800 9230 472	TOPREP	CALHOUN, J. R	8009190540	50-327 8
BROWNRIGO, D. L.	8007080336*	50-133 R	BUCHHOLZ, R. H	800 9230 430	TOPREP	CALHOUN, J. R.	8009230706	50-259 8
BROWN, R. A.	8009040068*	27-39	BUCHHOLZ, R. H	8009230308	TOPREP	CALHOUN, J R	9009230716	50-259 8
BROWN, Q. D.	8009080487*	40-3453	BUCHHOLZ, R. H.	8009230308	TOPREP	CALHOUN, J R	8009230587	50-327 8
BROWN, Q. D.	8009080475*	40-3453	BUCHOLZ, J. A	8009110372	NUREO	CALHOUN, J, R	8009230674	50-296 8
BROWN, H. L.	8009170159*	GA999	BUCHOLZ, J. A	8009140202	NUREO	CALHOUN, J, R	8009230669	50-296 8
BROWN, EE, V. L.	8009110427*	50-413 G	BUDNITZ, R. J	8009040461	BECY	CALHOUN, J P.	9009230730	50-327 8

AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	41171/02	ACCESSION	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEORY
CALHOUN, J R	8007270345 8007300562 8007300767* 8007300451 8007300516	50-259 B 50-259 B 50-259 B 50-259 B 50-327 B 50-259 B	AUTHOR CARTHRIGHT H R	NUMBER 8007030619* 8007030629 8007030632* 8007030642 8007030649*	50-337 B 50-338 B 50-338 B 50-338 B 50-338 B	CHANANIA, F D CHANANIA, F D CHANANIA, F D CHANANIA, F D CHANANIA, F D	8007030721 8007040289 8007170232* 8007170239* 8007170364*	50-443 K 50-443 K 50-443 K 50-443 K 50-445 K
CALHOUN, J R CALKING, O D CALKING, O D CALLAN, L J CAHERON, C A	8009300344 8009300548 8009110639 8009180481 *	50-294 6 50-260 8 NUREO 50-313 G TOPREP	CARTHRIGHT, W R	8009030653 8009030658* 8009030612 8009030623* 8009050335*	50-338 8 50-338 8 50-338 8 50-338 8 50-338 R	CHANANIA.F D CHANANIA.F D CHANDLER.L J CHANDLER.L J CHAPLIN.B D	8009170229 8009160160* 8009090774 8009100448 8009020387*	50~445 K 50~445 H 50~361 P 50~361 H 50~320 B
CAMPBELL, M CAMPBELL, J E CAMPBELL, D O CAMPBELL, D O CAMPBELL, B O	8007270064 * 8007020347 8007020080 * 8007030334 * 9007050087 *	FOIA NUREO 50-320 P 50-320 P 50-369 O	CARTURICHT.U R CARTURICHT.U R CARTURICHT.U R CARTURICHT.U R CARTURICHT.U R	8007070477 B007070512> B00707053B 8007070541 B007070584+	50-338 8 50-338 8 50-339 8 50-338 8 50-339 8	CHAPLIN, B. D CHAPLIN, B D CHAPLIN, B D CHAPLIN, S D CHAPLIN, B D	8009030361* 8009120406* 8009180426* 8009120452* 8009180408*	50-320 8 50-320 8 50-320 8 50-320 8 50-320 8
CANNON, J M CANNON, J M CANTER, H L CANTER, H L CANTRELL, F B	8009090331 8009090331 8009170244* 8009120490* 8009030040*	27-39 27-39 50-312 P 50-312 Q 50-390 Q	CARTURIONT, H. R CARTURIONT, H. R CARTURIONT, H. R CARTURIONT, H. R CARTURIONT, H. R	8009090586* 8009180412 8009180417* 8009220239 8009220241	50-338 8 50-339 8 50-339 8 50-339 8 50-339 B	CHAPMAN, K R CHAPMAN, K R CHAPMAN, K R CHAPMAN, K R. CHAPMAN, K. R	8007230141* 8007230170* 8007230175* 8007230272* 8007230283*	FOIA FOIA FOIA FOIA
CANTRELL, F 8 CANTRELL, F 8 CAPAWANA, 8 CAPHTON, D L	8007070257# 8007110177# 8007250114# 8007270447 8007170081#	50-553 @ 50-516 @ 50-566 @ FDIA 50-273 @	CARTURIOHT, UR CARTURIOHT, UR CARTURIOHT, UR CARTURIOHT, UR. CARTURIOHT, UR.	8009220243 8009220251 8009220306* 8009220319* 8009220324*	50-338 8 50-338 8 50-338 8 50-339 8 50-338 8	CHAPMAN, R. H. CHAPMAN, L., D. CHAPMAN, L. D. CHAPMAN, R. H. CHARNDEF, G.	8009050409 8009020341 8009090132 8009100954 8009300570	RES NUREO RES NUREO 50-480 9
CAPHTON, D. L. CAPHTON, D. L. CAPPUCCI, A. J. CARDONA, T. H.	8007150184* 8007100861* 8007110518* 8007150018* 8007180364	50-277 Q 50-277 Q 50-217 Q 50-438 A 50-376 Q	CARTHRIGHT,H R CARTHRIGHT,H R CARTHRIGHT,H R CARTHRIGHT,H R CARTHRIGHT,H R	8007220355 8007220360* 8007220367 8007220373* 8007230587	50-339 B 50-339 B 50-338 B 50-338 B 50-339 B	Charnoff, O Chabe, J. N Chabe, O Chaudhary, 8 K. Chaudhary, 8	8009300570 8009300081* 8009150167 8009090232* 8009100899*	50-483 9 50-259 9 REQOD 50-352 9 50-207 9
CAREY, J, J CARLEON, R, T CARLEON, R, T CARLEON, R, T CARLEON, R, T	8007070412* 8007170100* 8007170277* 8007170254* 8007070227*	50-334 P 50-443 Q 50-387 Q 50-387 Q 50-352 Q	CARTHRIGHT, W.R. CARTHRIGHT, W.R. CARTHRIGHT, W.R. CARTHRIGHT, W.R. CARTHRIGHT, W.R.	8007230600 * 8007230554 8007230577 * 8007230605 8007230615 *	50-339 8 50-339 8 50-339 8 50-339 8 50-338 8	CHAUDHARY.8 K CHECK.P S CHECK.P S CHECK.P S CHECK.P.S	8009050593# 8009050029 8009050032 8009050033 8009050343	50-478
CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T	8007070058* 8007170214* 8007100025* 8007050482 8007250279	50-293 Q 50-354 Q 50-352 Q 50-410 Q 50-387 Q	CARTWRIGHT, N R CARTWRIGHT, N. R. CARY, C. N CASE, E Q CASE, E. Q	8009230622 8009230636* 8009160198 8009030501* 8009040279	50-330 8 50-330 8 NUREO 50-266 P 50-266 P	CHECK, P 8. CHERBA, R 8. CHERN, W 8 CHEBTER, R D CHIANGI, N J	8007050026 8007030627# 8007120733 8007110478 8007100465	10-338 8 50-255 9 RES RES 50-400 8
CARLEON, R T CARLEON, J D CARLEON, R T CARLEON, R T CARLEON, R, T	8009190231 8009020240* 8009150092 8009100881 8009100889	50-387 Q 50-397 Q 50-410 Q 50-352 Q 50-387 Q	CASEY. B. B. CASEY. S. B. CASHWELL. R. J. CATCHPOLE. O. J. CATCHPOLE. O. J.	8009190083 8009190083 8009040397 8009050362 8009150352	50-361 0 50-361 0 50-156 8 40-8745 40-8745	CHIANOI,N.J CHILDB,H.V. CHILDB,H V CHILDB,H V. CHILDB,H V	8007080254 8007030414* 8007030423* 8007020357* 8007020403*	50-400 8 50-303 8 50-333 8 50-333 8 50-303 9
CARLEON, R T CARLEON, R T CARLEON, R T CARLEON, R T CARLEON, R T	8009100895 8009240259 8009100865 8009150187 8009090041	50-287 Q 50-317 Q 50-412 Q 50-354 Q 50-293 Q	CATCHPOLE, O J CATCHPOLE, O J CATCHPOLE, Q J CATCHPOLE, O J. CATCHPOLE, O J.	8007300202 8007030476 8007030455 8007030385 8007160383	40-8745 40-8745 40-8693 40-8745 40-8745	CHILDS, W V CHILDS, W V CHILDS, W V CHILDS, W V	8009020422* 8009090361* 8009120415* 8009120365* 8009160449*	50-333 8 50-333 8 50-333 8 50-333 6 50-333 6
CARLEON, R. T CARLEON, R. T CARLEON, R. T CARLEON, R. T CARLEON, R. T	8009090450 8009110401 8009120120 8009120128 8009120711	50-387 8 50-387 8 50-322 8 50-387 8 50-387 8	CATCHPOLE, O J CATCHPOLE, O J CATCHPOLE, O J, CATCHPOLE, O J CATCHPOLE, O, J,	8009140442 8009140384 8009140330 8009140331* 8009140333*	40-8745 40-8745 40-8745 40-8745 40-8745	CHILDB, W V. CHILEB, L. CHILK, B. J CHILK, B. J, CHILK, B J	8007160476* 8007020375* 8009190326* 8009230156* 8009230159*	50-939 B CONNIBBION FOIA FOIA FOIA
CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T	8009190247 8009120704 8009090222 8009100022 8009150193	50-387 Q 50-387 B 50-352 Q 50-352 Q 50-482 B	CATCHPOLE, Q, J CATCHPOLE, Q J CATCHPOLE, Q J CATCHPOLE, Q J CATCHPOLE, Q J	8009160334* 8009160336* 8009160345* 8009160350*	40-8745 40-8745 40-8745 40-8745 40-8745	CHILK, B. J. CHILK, B. J. CHILK, B. J. CHILK, B. J. CHILK, B. J	B009230164* B009190470* B009190357* B009180284* B009030150*	FOIA FOIA FOIA 10CFR 50-409 0
CARLSON, R T CARLSON, R, T, CARLSON, R, T CARLSON, R T CARLSON, R, T,	8009190203 8009190244 8009190089 8009090839 8009090844	50-354 Q 50-387 Q 50-443 Q 50-410 8 50-410 8	CATCHPOLE, Q J, CATCHPOLE, Q J, CATCHPOLE, Q J, CATCHPOLE, Q J CATCHPOLE, Q, J.	8009160354* 8009160356* 8009160357* 8009190389 8009190392	40-8745 40-8745 40-8745 40-8745 40-8745	CHILK, 8. J CHILK, 8. J CHILK, 8. J, CHILK, 8. J, CHILK, 8. J,	8009030079* 8009030074 8009030082 8009030093 8009100632	10CFR 10CFR DRO 10CFR MISC
CARLSON, R T CARLSON, R, T, CARPENTER, M CARPENTER, K CARPENTER, T O	8009150037 8009220325 8009020178* 8009150164* 8009230771*	50-354 8 50-423 8 50-320 H 40-8743 CONTRACT	CATCHPOLE, Q. J CATCHPOLE, Q. J, CATTON, I. CATTON, I. CAVANAUOH, W	8009220332 8009300457 8009230113 8009240028 8009170241	40-8745 40-8745 ACRB NUREQ 50-313 V	Chilk, B. J. Chilk, B. J. Chilk, B. J. Chilk, B. J. Chilk, B. J.	9009190241 8009150449 8009160509 8009100917 8009080048*	ACRS ACRS ACRS ACRS PR
CARR.J.C CARR.E W CARROLL.D CARTER,R B. CARTURIGHT,W R	8009300136* 8009110500 8009180370 8009100504 8009030555	FDIA NUREO 50-289 I 50-184 F 50-338 8	Cavanaudh, u Cavanaudh, u Cavanaudh, u Cavanaudh, u Cavanaudh, u	8009150287 8009090482 8009180424 8009260453 8009300242	50-369 P 50-313 P 50-369 P 50-368 P 50-368 P	Chilk, B. J. Chilk, B. J. Chilk, B. J. Chilk, B. J. Chilk, B. J.	8007080036 8007020527 8007020544 8007030052 8007030061	PR REOOD PR NUREO REOOD
CARTWRIGHT, H. R.	8007030561* 8007030567 8007030571* 8007030576 8007030586*	50-338 8 50-339 8 50-339 8 50-339 8	CAVE, L CAYOT, R F. CAYOT, R F CERNE, A C CHADHELL, H. M	8007240603 8007080333* 8007080336* 8007170106* 8007070508*	NUREO 50-133 R 50-133 R 50-443 G 50-315 B	Chilk, B. J. Chilk, B. J. Chilk, B. J. Chilk, B. J. Chilk, B. J.	8007030667 8007240364* 8007030648 8007250462 8007020417	NUREO 50-327 # ACRB TOPREP 50-309 Q
CARTHRIGHT, H R. CARTHRIGHT, H R CARTHRIGHT, H R 'ARTHRIGHT, H R ARTHRIGHT, H R	8007030593 8007030606 8007030608* 8007030614* 8007030615	50-337 8 50-338 8 50-339 8 50-339 8	CHADHELL, H. M CHADWELL, H M CHAFFEE, A E, CHAN. C K CHANANIA, F D	8009110348* 8009130328* 8009120478* 8009260028 8009020459	50-315 8 50-315 8 50-326 0 NUREO 50-395 M	Chilk, 8. J Chilk, 8. J Chilk, 8. J Chilk, 8. J. Chilk, 8. J.	8007040263 8007040355 8007070404 8007160347* 8007120244	50-344 Q 50-389 Q 50-458 Q 50-349 Q 50-344 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCEBBION NUMBER	GUBJECT CATEGURY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEOURY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CHIEKI B J CHILKI B J CHILKI B J CHILKI B J CHILKI B J	B009120394 B009120398 B009140142 B009140522 B009180544	50-3	CLAYTON.F L CLAYTON.E.D CLAYTON.F L CLAYTON.F L CLAYTON.F L	8007110258 8007100413 8007050092 8007020271 8007170593*	50-348 Q NUREO 50-348 Q 50-348 Q 50-348 Q	COHN, D D COHN, D H COLE, R F COLEHAN, R COLEHAN, R	8009030149 8009030152* 8009300439 8009300405 8009250250	50-367 0 50-367 0 50-376 0 CONTRACT CONTRACT
CHILK: 8. J CHILK: 8. J CHILK: 8. J. CHILK: 8. J. CHILK: 8. J	8009220427 8009250009 8009250010 8009250028 8009250039	50-327 0 XPGRTLIC 50-554 0 50-445 M 50-458 0	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8009020301 8009100324 8009020030 8009020045 8009100363	50-364 G 50-364 F 50-364 A 50-364 A 50-364 B	COLEMAN, L. R COLEY, J. L COLLINS, B. J COLLINS, E. D	8009100590 8009190529 8009240313* 8009150137* 8009020080*	PR PR 50-413 G 50-271 G 50-320 P
CHILK, 8. J CHILK, 8. J CHILK, 8. J CHILK, 8. J CHILK, 8. J.	8009280042 8009280045 8009250059 8009260467 8009260639	50-498 0 50-498 0 70-143 50-546 0 50-556 0	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8007020038 8007020062 8007100237 8007030427 8007030471	50-364 A 50-348 B 50-364 Q 50-348 B 50-348 R	COLLINS, E D COLLINS, J T COLLINS, J T COLLINS, S E	8009030534* 8009090603 8009110678 8009020135 8009300282*	50-320 P 50-320 P 50-320 P 50-320 R 50-267 G
CHILK, B. J. CHILK, B. J. CHILK, B. J. CHILK, B. J. CHILK, B. J.	8007260639 8007260463 8007300019 8007300037 8007300320	50-556 0 50-387 0 27-39 50-443 0 50-3 0	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8009030492 8009080387 8009110687 8009040246 8009040386	50-364 A 50-349 P 50-348 Q 50-364 A 50-364 A	COLLINS.F COLLINS.P F COLLINS.J T COLLINS.J T	8009190703 8009080485 800909796 8009120677 8009100375	RECOD M18C 50-289 R 50-320 P 50-320 R
Chilk, 8. J. Chiledn, V. T. Chilton, A. B Chin, H. Y. Chong, L. K	8009300560 8009170281* 8009150456 8009110328 8009170059	50-375 M 50-250 R 50-356 R 50-320 P FOIA	CLAYTON, F L CLAYTON, F, L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8007080273 8007070566 8007070585 8007120425 8007100318	50-364 A 50-348 P 50-348 F 50-348 P 50-348 V	COLLINS, J T COLLINS, P F COLLINS, P F. COLLINS, J T COLLIER, R P	8009150539 8009190745 8009150447 8009150532 8009100043	50-320 R 50-282 P HISC 50-320 R NUREO
CHOULES, N. G. CHOULES, N. C. CHON, E. T. CHRISTIANSON, F. CHRISTENSURY, E.	8007160616# 8007270118# 8007270118# 8007100161# 8007110603	50-303	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8009150484 8009160320 8009160415 8009160358 8009160268	50-364 A 50-348 B 50-364 A 50-348 P 50-348 R	COLLIER R P COLLINS, P F COLLINS, J T COLLIER, L B COLLINS, J. T	8007300164 8007110317 8007180204 8007240557* 8007230126	NUREO 50-144 V 50-289 R 50-395 G 50-320 H
Christoffer, O. Christensen, J. K. Chrchif. Chrchill, R. L. Chrchill, R. L.	8009030133* 8009260417* 8009110413* 8009150078 8009110702	50-275 G 50-289 T COMMISSION 70-33 70-33	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8009160307 8009170353 8009150259 8009150260* 8009170214	50-348 8 50-364 A 50-348 K 50-348 K 50-364 A	COLLING, J T COLLING, R W COLONDO, R W COLONDO, R W COLONDO, R W	8009250440 8009290481 8009180441 8009180272* 8009160297*	50-320 P 50-320 R 50-274 B 50-312 B 50-312 R
CIESIKIEHICZ, 8 CIESZKIEHICZ, B CIMOUEKANI, D K CIPOLLA, A J CLARDY, L.	8009020388* 8009230720* 8009040404 8009300241 8009100161*	50-237 6 50-10 R 50-3 H 40-3392 50-331 Q	CLAYTON, F L CLAYTON, F L CLAYTON, F, L CLAYTON, F L CLAYTON, F L	8009230445 8009230546 8009230448 8009230722 8009230710	50-364 A 50-364 R 50-364 A 50-348 B 50-348 S	COLOMBO, R W COLTON, E COMBS, C COMER, F M COMER, F M	8009260476* 8009090665 8009180191* 7912040156* 8005160029	50-312 & XPORTLIC CONTRACT PT9 Bocket 30
CLARK, A T CLARK, R A CLARK, R, A CLARK, R, A CLARK, R A	8009120543 8009110610 8009170264 8009170267* 8009020336	70-1308 50-338 P 50-309 P 50-309 P 50-317 P	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L GLAYTON, F L	8007270327 8007300381 8007300534 8007300435 8007270371	50-364 A 50-348 P 50-348 Q 50-348 H 50-364 A	COMPTON, R M CONKLIN, J C CONLON, T. E CONLON, T E CONLON, T E	8009180162* 8009100953 8009100149* 9009120539* 8009120141*	50-280 G NUREO 50-389 G 50-250 G 50-414 G
CLARK, R. A CLARK, R. A CLARK, R. A CLARK, R. A CLARK, R. A.	8009120107 8009150418 8009180213 8009030048 8009150380	50-285 F 50-317 P 50-336 P 50-336 P 50-317 P	CLAYTON, F L GLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8009300458 8009300572 8009300463 8009300523 8009300424	50-364 V 50-348 B 50-364 V 50-348 B 50-348 P	CONLON, T E	8009150370* 8009110427* 8009240276* 8009100307* 8009020337*	50-321 G 50-413 G 50-370 G 50-364 G 50-327 G
CLARK, A. T. CLARK, L. CLARK, R. A. CLARK, R. A. CLARK, L.	8007080409 8007030565 8007170082 8007170088* 8007080178	50-201 U 50-20 R 50-282 P 50-282 P 50-20 F	CLAYTON, F L CLEMDNS, P CLEVELAND, C J CLEVELAND, C J CLCVELAND, C J	8009300511 8009290068* 8009120579 8009120639 8009260110	50-348 6 FDIA 50-263 P 50-315 P 50-263 P	CONLON, T E CONLON, T E CONLON, T, E CONNER, T B CONNER, T B	8009050176* 8009100258* 8009250343* 8009050272 8009050272	70-1151 50-400 G 50-413 G 50-358 G
CLARK. R A CLARK. R A CLARK. B. A CLARK. R. A CLARK. R. A.	8007170011 8007170175 8007170177* 8007170185* 8007170275	50-318 P 50-205 P 50-205 P 50-205 P 50-262 0	CLEVELAND, C J CLEVELAND, J C CLOUD, R L CODB, A B COCHRAN, T B	8009260568 8009100953 8009020096 8009100003 8009050179		CONNER, T B CONNER, T B CONNER, T B CONNER, T B	8009190451* 8009230027 8009230027 8009300016 8009300016	50-286 R 50-395 O 50-396 O 50-358 O
CLARK, R. A. CLARK, R. A. CLARK, R. A. CLARK, R. A. CLARK, R. A.	8009190297 8009190308 8009190322 8009190336 8009190352	50-335 0 50-344 0 50-336 0 50-285 0 50-266 0	COCHRAN, R. Q. COCHRAN, T. COCHRAN, T. B. COCKRELL, R. G. COCKRELL, R. Q.	8009030548 8009160046 8009300004 8009020352 8009020356		CONNOR, L CONSTABLE, O L CONVAY, H F CONVAY, H F	8009110339 8009170172* 8009180385 8009160291 8009240207	FOIA 50-382 G 50-349 H 50-271 R 50-271 P
CLARKIR A CLARKIR A CLARKIR A CLARKIR A CLARKIR A	8007240520 8007240535 8007240402 8007260415 8007120575	50-317 Q 50-368 0 50-307 0 50-338 0 50-244 P	COGOTN, C. L. COGOTN, C. L. COGOTN, C. L. COGOTN, C. L. COGOTN, C. L.	8007030461 8007030447 8007020367 8007020414 8007070438	* 50-366 8 * 50-366 8 * 50-321 B	COOK, L. COOK, J. H COOK, J. H COOK, J. H	8009160647# 8008080297 8009180240# 8008190605 8009230110	50-327 S 50-327 Q
CLARKI R. A CLARKI R. A CLARKI R. A. CLARKI R. L.	8007260032 8007260177 8007270421 8007270467 8007300077	50-344 P 50-309 P 50-282 P 50-285 P 50-317 P	COOOIN, C. L. COOOIN, C. L. COHEN, H. COHEN, H. COHEN, I	8007150278 8007150274 8007020332 8007150147 8007150358	# 50-321 B # 50-320 H # CONTRACT	COCK, J ₩ COCK, J ₩ COCK, J ₩ COCK, J ₩	909040275 9007270475* 9007070397 9007070278* 8007230275	50-327 A 50-275 R 50-327 S
CLARK, R. A CLARK, R. A CLARK, B CLARK, R A. CLARK, R A. CLARK, R. A	8007300080* 8007300085* 800730085* 8007230126 8007230130*	50-317 P 50-317 P 50-275 B 50-368 P 50-368 P	COMEN, E. COMEN, P COMN, D B COMN, D D COMN, D. B	8009120183 8009030350 8009090633 8009090633 8009090623	90-206 H 9 50-367 9 9 50-367 9	COOK.J W COOK.J W COOK.J W COOK.J W	8009170259 8009290368 8009220238 8009230350 8009190218	50-329 A 50-329 A 50-329 A 50-329 A 50-329 K
CLARK, R. A CLARK, P. R CLAUSEN, D. H CLAY, R. V. CLAY, E. L.	8009250137* 8009260394* 8009180560* 8009170284* 8009100795*	50-368 P 50-209 T 50-320 H 50-320 H	COHN, D. H COHN, D. B. COHN, D. B. COHN, D. B. COHN, D. H	8007070633 8007070627 8007070633 8007030147 8007030153	7* 50-367 0 3* 50-367 0 7 50-367 0	COOK.J H COOK.J H COOK.J H COOKE,H D	8009250268 8009250284 8009290360 8009290507 8009230643	50-329 8 50-329 8 50-329 8 50-329 A 50-157 P

PERSONAL AUTHOR INDEX

AUTHOR	ACCEBBION NUMBER	SUBJECT CATEODRY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCEBBION NUMBER	BUBJECT CATEGORY
COONEY, H J COOLEY, H J COOLEY, H J	9007020261# 9007020239# 9007040576 9007160561 9007250274	70-734 70-984 70-734 70-734 50-171 F	COWHEY, J COX. E L COX. F Y COX. F T COX. F T	8009170243* 8009270296 8009090455* 8009090462* 80090904651*	50-289 H NVREO COMMISSION COMMISSION COMMISSION	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8007110612 8007110575 8007110581* 8007110594* 8007020456	50-409 P 50-255 P 50-255 P 50-255 P 50-10 P
M.YENDDO W.YENDDO H.YENDDO H.YENDDO J.YENDDO	9009030635 9009120330 9009120369 9009160439 9009160441	50-277 8 50-278 8 50-278 8 50-278 8 50-278 8	CRACRAFT, T M CRAIO, L L CRANE, P A CRANE, P. A CRANE, P. A	8009150178# 8009040099# 8009050082 8009110754 8009080321	CONTRACT 40~2061 50~193 Q 71~9096 50~133 V	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8009040088 8009050497 8009120279 8009120281 8009180040	50-155 P 50-27 P 50-237 P 50-237 P 50-237 P
COONEY, M J COONEY, M J COONEY, M J COONEY, M J	8009260621 8009160294 8009180439 8009190482 8009260616	50-278	CRANE, P A	8009020263 8009030699 8009090514 8009090544 8009080333	50-275 A 50-275 O 50-275 K 50-275 A 50-133 R	CRUTCHFIELD.D CRUTCHFIELD.D CRUTCHFIELD.D CRUTCHFIELD.D CRUTCHFIELD.D	8009180312 8009180428 8009240593 8009240596 8009120284	50-237 P 50-10 P 50-219 P 50-245 P 50-29 P
COOPER.J COPELAND.R L COPELAND.J O COPELAND.J O COPELAND.R L	8009110831 * 6009020014 8009040271 8009040271 8009020002	40-4826 50-537 A 50-466 O 50-537 B	CRANE, P A CREWS, J L	8009120349 8009230551 8009180486 8009250288 8009100151*	50-133 S 50-133 R 50-275 A 50-275 A 50-320 P	CRUTCHFIELD, D GRUTCHFIELD, D GRUTCHFIELD, D GRUTCHFIELD, D GRUTCHFIELD, D	8007230757 8007170655 8007300247 8007300253 8007300265	50-244 F 50-244 F 50-244 Q 50-206 O 50-219 Q
COPELAND, R L COPELAND, R L COPELAND, J O COPELAND, J O COPELAND, J O	8009090549 8009090575 8009180475 8009180475 8009160201	50-537 B 50-537 B 50-466 Q 50-466 Q 50-466 Q	CREWS, J L CREWS, J L CREWS, J L CREWS, J L	8007120474* 8007020233 8007020244 8007120470* 8007120475	50-326 Q 50-397 Q 50-344 Q 50-326 Q 50-361 Q	CRUTCHFIELD, D CULP, R. H CULP, R. H CULP, R. H CULP R. H	8007300651 8007160201 8007160201 8007240565 8007230671	50-29 9 50-466 9 50-466 9 50-466 9 50-466 9
COPELAND, J 0 COPELAND, J 0 COPELAND, J, 0 COPELAND, J 0 COPELAND, J 0	8009160201 8009160157 8009160157 8009300469 8009300469	50-466 Q 50-445 M 50-445 M 50-466 Q 50-466 Q	CREWS. J L CREWS. J L CREWS. J L CREWS. J L CRNICH. J	8007230212 8007120487 8007170243 8007120457 8007270376*	50-275 Q 50-312 Q 50-312 P 50-324 Q 50-382 B	CULVER, M N CUNNINGHAM, O E, CUNNINGHAM, O E CUNNINGHAM, O E CUNNINGHAM, O, E	8009220365 N 8009190751 8009150001 8009110225 8009180509	50-302 8 70-754 71-5790 70-754 70-1007
CORBETT, J S CORCORAN, T CORDANI, R A CORDANI, R A CORDERO, Z C	8009220172 80090202174 8009030001 8009110767 8009180402#	71-9080 CDMM18810N 70-27 70-27 50-546 Q	CROCKER, H W CROCKER, H W CROCKER, H W CRONENBERG, A CROSBY, P J	8007230150* 8007250336* 8007110274 8007150576 8007300528*	70-1417 70-820 70-820 NUREO 30-219 8	CUNNINGHAM, O E CUNNINGHAM, R E CUNNINGHAM, A L CUNNINGHAM, R E CUNNINGHAM, O E	8007110227 8007160136 8007120271* 8007100681 8007300227	70-754 70-1100 50-370 G 70-1151 71-6400
CORE.M R CORREA.J H CORREA.M A CORWIN.J W CORYELL.O P	8007070536# 8007260400# 8007260460 8007050427 8007080238#	50-285 8 50-287 T 50-311 J PR 50-332 Q	CROBEMAN, W A	8009150046* 8009150071* 8009150077* 8009150080* 8009150083*	50-445 Q 50-445 Q 50-445 Q 50-445 Q 50-445 Q	Cunningham, o e Cunnignham, o e Cunningham, o e Cunningham, o e. Cunningham, o e	8009240703 8009260051 8009260106 8009260391 8009260581	71-5926 71-5998 71-5971 71-9044 71-9049
CORYELL, O P COSTALUPES, Y COSTELLO, F M COSTELLO, F COTTLE, H	6007150605* 6007230021* 6007270041* 6007100372 6007040330*	70-1113 50-142	Crobeman, W A Crobeman, W A Crobeman, W A Crobeman, W A Crobeman, W A	8009150087* 8009150093* 8009150105* 8009170385* 8009170387*	50-445 0 50-445 0 50-445 0 50-498 0 50-482 0	CUNNINGHAM, J D. CUNNINGHAM, J D CUNNINGHAM, J D CUNNINGHAM, J D CUNNINGHAM, J D CURRAN, J. M	8009040278 8009040278 8009180436 8009180571 8009020083*	50-289 0 50-289 0 50-289 0 50-289 0 50-206 6
COUNBIL, W 0 COUNBIL, W 0 COUNBIL, W 0 COUNBIL, W 0	8007120177 8007120247 8007220330* 8007230747 8007110482	50-245 G 50-213 G 50-423 8 50-245 G 50-336 G	Croesman, W A Crossman, W A Crossman, W A Crossman, W A Crossman, W A	8007070648* 8007150367* 8007150348* 8007250378* 8007250405*	50-482 G 50-443 G 50-482 G 50-458 G 50-498 G	CURRAN, J M CURRAN, J, M CURTIB, N, W CURTIB, J R CURTIB, N W	8009070265 8009260513* 8009090654* 8009240533* 8009110414*	50-206 R 50-206 B 50-387 B 50-147 Q 50-387 B
CONNSIL. H O CONNSIL. H O CONNSIL. H O CONNSIL. H O	8009110474 8009100113 8009090017 8009100109 8009020231	50-213 Q 50-423 Q 50-245 Q 50-336 Q 50-213 P	Croebhan, Wa Crossman, Wa Croes, JL. Croeb, JL.	8009300102* 8009190340* 8009300096* 8009030631 8009050257	50-498 Q 50-382 Q 50-382 Q 50-296 P 50-327 P	CURTIS, N W CURTIS, N. W CURTIS, N W CURTIS, N W CURTIS, N W CURTIS, N W	8009030006 8009120142 8009190936 8009090616 8009130309	NUSEO 50-387 Q 50-387 Q 50-387 Q RECOD
COUNSIL, W O COUNSIL, W O COUNSIL, W O COUNSIL, W O	8009020286 8009030195 8009030641 8009030532 8009150247	50-245 P 50-336 P 50-213 P 50-213 P 50-336 P	CROSS, J. L CROSS, J. L CROSS, J. L. CROSS, J. L CROSS, J. L	8009090347 8009090555 8009080259 8009090370 8009090522	50-259 P 50-259 P 50-327 P 50-327 P 50-438 A	CURTIG.N W CURTIB.N. W CURTIB.N W CURTIB.N W CURTIB.N W	8007070036 8007120660* 8007080364 8007070472 8007150470	50-387 Q 50-387 A 50-387 A 50-387 B 50-387 A
COUNSIL, W O COUNSIL, W O COUNSIL, W O COUNSIL, W O	8009030378 8009030378 8009030103 8009110245 8009190434	50-213 P 50-213 P 50-336 P 50-245 P 50-245 P	CROSS.J.L. CROSS.J.L. CROSS.J.L. CROSS.J.L.	8009090543 8009120245 8009120261 8009120389 8009230480	50-259 I 50-296 P 50-327 V 50-327 P 50-327 O	URTIB,N W URTIBUD R GEITRUD H LAIHOTUD H LAIHOTUD	9009160310 9009170290 9009220425 8009110787 9009110016	50-387 A 50-387 A 50-349 Q 50-387 Q 50-387 Q
Counsil, H. O Counsil, H. O Counsil, H. O Counsil, H. O	8009120257 8009090636 8009300297 8009180445 8009240571	50-213 P 50-245 P 50-245 P 50-336 P 50-245 P	CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R, P	8009030012 8009150067 8009220176 8009110504 8009260097	NUREQ 50-346 Q 50-346 Q 50-346 Q 50-346 Q	Cutchin, J. H Cutchin, J. H Cyr. K. D. Cyr. K. D D'AHORE, M	8009180131 8009170346 8009030134 8009230255 8009110135*	50-289 0 50-289 T 50-409 0 50-266 0 70-1151
COUNSIL, W O COUNSIL, W O COUNSIL, W O COUNSIL, W. O	8009190427 8009180337 8009230621 8009180357 8009290351	50-245 P 50-213 P 50-213 P 50-213 P 50-213 P	CROUSE.R P CROUSE.R P CROUSE.R P CROUSE.R P CROUSE.R P CROW.W T.	8009120430 8009100172 8009220297 8009220301* 8009170084	50-346 F 50-346 P 50-346 P 50-346 P 70-33	DABES, R D DAIL, L, C DAIL, L C DAIL, L C DAIL, L C	8007100744 8007020211 8007020137 8007120574 8007120212	NUREO 50-498 Q 50-498 Q 50-498 Q 50-498 Q
COUNSIL, W O COUNSIL, W O COUNSIL, W O COUNSIL, W O	8009290351 8009300239 8009300179 8009300239 8009300403	50-213 P 50-245 P 50-336 P 50-245 P 50-423 A	CROW, W. T CROW, W. T. CROW, W. T. CROW, W. T. CROW, W. T.	8007250478* 8007160132 8007170001 8007240337* 8007150183*	70-1237 40-2061 70-820 70-33 70-258	DAILY,L DALE,L,F. DALE,L F DALE,L.F. DALE,L F	8009020317* 8009230642* 8009020218 8009020292 8009230092	50-320 H 50-416 S 50-416 Q 50-416 Q 50-416 Q
GOUNSIL, M. O COUNSIL, M. O COHAN, B Z COHAN, B Z COHOILL, C J	8007300271 8007300443 8007110028 8007110028 8007160227*	50-336 P NUREO XPORTLIC XPORTLIC 50-277 G	CROWLEY, J. L CROWLEY, J. L CROWLEY, B. R CROWLEY, B. R	8009250470* 8009120334 8009050409 8009050421* 8009300041*	70-1151 NUREO REB 50-364 Q 50-416 Q	DALE, L F DALE, L. F, DALE, L F DALE, L F, DALLINGER, J F	8009110681 8009050352 8009150489 8009300437 8009170136	50-416 Q 50-416 A 50-416 H 50-416 A 71-6717

AUTHOR	ACCESSION NUMBER	SUBJECT CATEOURY	AUTHOR	ACCESSION NUMBER	TDELEU2 YRQQATAD	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOORY
DALOUOH, R. C. DALTON, J. N. DALTROFF, B. L. DALTROFF, B. L. DALTROFF, B. L.	8007040287 8007090333* 8007220374 8007080533 8007180502	50-449 M 50-339 P 50-277 Q 50-277 Q 50-277 Q	OE SANTIS, N DEALE, V B DEARDORFF, P E DECHER, U DEEDS, W	8004110323 8009240125* 8009020111* 8009100490 8009030671	Docket 30 50-253 0 50-237 P 50-5 H NUREO	DEVINE. J B DEVINE. J B DEVINE. J B DEVINE. J. B DEVINE. J. B	8009110260 8009120056 8009190752 8009230417 8009230781	XPDRTLIC XPDRTLIC XPDRTLIC XPORTLIC XPORTLIC
DALTROFF.B.L. DALTROFF.B.L. DALTROFF.B.L. DALTROFF.B.L. DALTROFF.B.L. DANCE.H.C	8009100121 8009090015 8009100090 8009110251 8009030281*	50-277 Q 50-278 Q 50-277 Q 50-277 Q 50-390 Q	DEL GEORGE, L O DELAPORTE, C T DELGEORGE, L O DELGEORGE, L O, DELGEORGE, L O	8009160585 8009030314* 8009120446 8009240555 8009180406	50-373 A 50-387 A 50-454 F 50-10 P 50-373 A	DEVINE, J. B DEVINE, J. B DEVINE, J. B DEVINE, J. B DEVINE, J. B	8009230801 8009110254 8009190746 8009230420 8009230425	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
DANCE: H. G. DANCE: H. G. DANCE: H. G DANCE: BON: L. J DANCE(BON: D. H	8009300081* 8009220341* 8009020225* 8009170376* 8009100124*	50-259 Q 50-321 Q 50-259 Q 40-299 50-440 Q	DELGEOROE, L O DELGEORGE, L O DELONO, 8 D DELVIN, J W DELVIN, J	8009290399 8009260511 8009300517* 8009160242* 8009160246*	50-373 8 50-373 A 50-313 8 50-220 9 50-334 0	DEVINE. J B DEVINE. J B DEVINE. J B DEVINE. J B	8009230427 8009230428 8009230803 8009110689 8009110723	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
DANIELSON, D. H DANIELSON, D. H DANIELSON, D. H, DANIELSON, D. H, DANIELS, F. T,	8009150203# 8009110627# 8009020200# 800915050B# 8009160514#	50-327 0 50-282 0 40-4472 50-344 0 50-358 0	DEMMIE, PN DENECOUR, C, DENYON, HR DENTON, HR, DENTON, HR,	8009260542 8009120439 8009050131* 8009030448 8009030285	RES 50-361 H FOIA 50-3 H 50-387 A	DEVINE, J. B DEVINE, J. B DEVINE, J. B DEVINE, J. B	8009110741 8009300652 8009330754 8009300655 8009300662	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
DANTELBON, D. H. DANTELBON, D. H DANTELBON, D. H DANTELBON, D. H DANTELBON, D. H	8007180021* 8007260286* 8007270101* 8007270114* 8007160247*	50-275	DENTON, H R DENTON, H R DENTON, H R. DENTON, H R, DENTON, H R	8009300246 8009150070 8009150413 8009080331 8009090599	50-320 H 50-269 P 50-320 H 50-320 H COMMISSION	B F. JANIAGO B F. JANIAGO B F. JANIAGO B F. JANIAGO	8009300666 8009300687 8009290147 8009290153 8009290385	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
DANIELBON, D. H. DANNHEYER, T. R. DANTZLER, H. U. DARHITZEL, R. W. DARHITZEL, R. W.	8007180034* 8007160278 8007270142* 8007030637 8007040255	50-373	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8007070783 8007020108 8007180505 8007150084 8007150087*	50-320 P 50-445 H 50-224 P 50-250 Q 50-250 Q	DEVINE, J F DEVINE, J B DEVINE, J B DEVINE, J B. DEVINE, J B	8009160363* 8009290061 8009290149 8009290151 8009200071	SO-275 Q XPORTLIC XPORTLIC XPORTLIC XPORTLIC
DARMITZEL,R.W DARMITZEL,R.W DAVIDBON,D.R. DAVIDBON,D.R DAVIDBON,D.R.	8009180474 8009250245 8009100112* 8009160636 8009020067	50-70 P 50-70 P 50-440 Q 50-440 Q 50-440 S	DENTON, H R DENTON, H, R DENTON, H R DENTON, H R DENTON, H R	8009220125 8009120736 8009180548 8009110332 8009140657*	MISC 50-320 H 50-320 H 50-327 P 50-339 P	DEVLIN. J B DEVLIN. J W DEVLIN. J W DEVLIN. J	8009300032 8009300059 8009100652* 8009250363* 8009160625*	XPORTLIC XPORTLIC 70-371 50-201 G 50-277 G
DAVIDBON.D R DAVIDDEF, D B. DAVIDBON.D.R. DAVIDBON.D.R. DAVIES, D.L.	8009120297 8009050361 8009170133 8009190431 8009180327#	50~440 8 State Prog 50~440 K 50~440 A CONTRACT	Denton, H. R Denton, H. R Denton, H. R Denton, H. R Denton, H. R	8007130104 8007130107* 8007070621 8007100145 8007150316	50-311 P 50-311 P 50-347 Q 50-320 P 50-352 H	DEVLIN, J DEWEY, L S DEMEY, L S DEXTER, W D DEYOUNG, R C	8009300633 8009160033 8009160041# 8009150212# 8009170417#	50-272 8 50-389 M 50-389 M 40-8745 50-438 0
DAVIS.D. DAVIB.J.B DAVIS.A B DAVIS.J. DAVIB.A.B	8009100471 8009290092* 7911090069 8009290087* 7912040149	40-8502 FOIA PT9 FOIA PT9	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	B007240562 B007030142* B007170409 B007240104 B007240560	PR 50-409 Q 50-364 A 50-313 B 50-327 P	DHIR.V K D1AZ.N J DICKERSON.H W DICKERSON.H W DICKERSON.H W	8009260028 8009160389 8009150075* 8009150080* 8009100055*	HUREG 50~83 P 50~445 O 50~445 O 50~267 O
DAVIB.A.E. DAVIB.A.B. DAVIB.A.B. DAVIB.A.B. DAVIB.A.B.	8009270046* 8001270275 9009270116* 8009270102* 8005300691	FOIA PTP FOIA FOIA PT P	Denton, H R Denton, H R Denton, H R Denton, H R. Denton, H R.	8009180226 8009180232* 8009180242* 8009110349 8009090436		DICKENSON.H W DICKEON.H O DIECKAMP.H DIECKAMP.H	8009110874 8009300282 • 8009230912 8009140361 • 8009170245	RES 50-267 Q 50-255 R 50-320 P 50-320 P
DAVIS.A B. DAVIS.J.H DAVIS.P.B DAVIS.A B. DAVIS.A.B.	8006120881 8009240646* 8009050480 8009150121* 8009030323	PT9 70-143 70-143 40-2061 50-305 Q	OENTON, H R DENTON, H R. DENTON, H. R DENTON, H R. DENTON, H R	8009290057# 8009290220 8009290235 8009290032# 8009190369	50~443 H 50~320 P	DIETCH, R DIETCH, R DIETCH, R DIETZ, C R DIOOS, R M	8009030634 8009030637 * 8009190338 8009050363 8009050194	50-206 P 50-206 P 50-361 K TDPREP 50-443 A
DAVIS, A. S DAVIS, A. S. DAVIS, A. S DAVIS, D. DAVIS, A. S.	8007100085 8007150166 8007120506 8007150177* 8007020227	50-87 G 70-36 50-155 G QAF97 50-315 G	DENTON, H. R DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R.	8007270081 8007270384 8007300274 80072700304 8007300157	COMMISSION 50~289 H 50~327 P 50~327 T 50~289 H	D1009, R M D1009, R M D1009, R M D1009, R. M D1008, R M	8009180525 8009150031 8009070645 8009220384 8009190670	50-334 P 50-219 P 50-346 P 50-277 P 50-245 P
DAVIB. R. J. DAVIB. A. B. DAVIB. A. B. DAVIB. A. B. DAVIB. Q. R.	8009190313 8009290090 8009290123 8009290017 8009300232	FOIA 70-1308 50-254 G 50-266 C Waste Mot	DERRICK, B DERRICK, B DESANTIB, N DESANTIS, N DESANTIS, N.	8009020217* 8009090570 8009290127* 8009290122* 8003260087	50-320 U FOIA	DIGOS.R M DIGOS.R M DIGNAN.T G DIGNAN.T G DILL.J	8009100617# 8009160433# 8009250049 8009250049 8009030438#	50-334 P 50-338 P 50-471 Q 50-471 Q 50-327 P
DAVIS,A B DAVIS,A B DAVIS,A.B. BAVIS,L.D	8007170118 8007260657 8007260628 8007160337 8007030547#	40-2061 50-346 G 50-315 G 50-361 G 50-318 B	DESSEL, S. DESSEL, S DESSEL, S DESSEL, S DESSEL, S	7912190067 7912190047 7912190023 8003050232 8003050219	# PT 9 # PT9 * PT9	DINKING, MA DIPIAZZA, RP DIPIAZZA, RP DIRCKG, WJ DIRCKG, WJ	8009110574 8009100187 8009250257 8009080448 8009020127	RES 70-1143 50-22 G 50-201 G 50-483 H
DAVIS, B. H DAVIS, B. H. DAVIS, E. H. DAVIS, L. D. DAVIS, J. F.	8007300404 8007120455* 8007140341 8007170337 8007170034	70~1377 50~317 8 50~361 0 50~312 P 50~275 0	DEUBERT.JR OEVINCENTIB.J DEVINCENTIB.J OEVINE.JB DEVINE.JB	8009300394 8009190094 8009110478 8009020162 8009030313	* 50-443 G 50-443 G XPORTLIC	DIRCKS.WJ DIRCKS.WJ DIRCKS.WJ	8007030178 8007020151 8007020166 8007020187 80070205464	State Prog 50-320 H 50-320 H 50-217 H PR 50-397 U
DAVIS, E. M DAVIS, E. M DAVIS, L. D DAVIS, S. M DAVIS, S. M	8007270033 8007230545* 8007230675* 8007300450* 8007110489	50-317 8 50-341 H 50-317 8	DEVINE, J B DEVINE, J, B DEVINE, J, B DEVINE, J, B DEVINE, J, B,	8009030449 8009030553 8009030466 8009160193 8009160194	SO-443 B XPORTLIC XPORTLIC	DIRCKS, N J DIRCKS, N J DIRCKS, N J DIRCKS, N J	8009110241 8009020320 8009020118 8009020328 8009020476	50-320 H 50-320 H 50-320 H 50-320 U
Dahron, D. M Dahron, D. M Dahron, D. M Dahron, D. M De Polx, V. P.	8007070457 8007070073 8007070073 8007300585* 8007120125	70-1308 71-9033 70-1308	DEVINE, J B. DEVINE, J B DEVINGENTIS, J DEVINE, J B DEVINE, J B	8009160236 8009190687 8009090419 8009230429 8009230800	P SO-443 B XPORTLIC	DIRCKS.W J DIRCKS.W J DIRCKS.W J DIRCKS.W J	8009020482 8009020487 8009020496 8009100082 8009110268	50-320 U 50-320 U 50-387 D 50-320 H

AUTHOR	ACCESSION NUMBER			ACCEBSION	SUBJECT		ACCESSION	GID. HAT
DIRCKS.W J	8009180101	DISCLOSURE	AUTHOR DUNN, C, N	RAGESPOOR	CATEGORY 50-334 P	AUTHOR	NUMBER	SUBJECT
DIRCKS.W J	8009110501 8009110514 8009110494 8009110486	50-320 H 50-275 U 50-320 H 50-320 U	DUNN. C. N DUNN. C. N DUNN. D DURR. J P	6007300357 6007300357 6007300370 6007270062 6007100873*	50-334 P NUREO NUREO	EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G	8009190140* 8009190115 8009190240* 8009190275* 8009190289*	50-247 P 50-461 A 50-284 Q 50-250 Q 50-272 Q
DIRCKS, H J DIRCKS, H J DIRCKS, H J DIRCKS, H J DIRCKS, H J	8009110280 8009110314 8009110212 8009110218 8009120301	50-320 H 50-320 H 50-320 H 50-3 H 50-327 H	DUTTON, D. DUTTON, D DUTTON, D DUTTON, D, DUTTON, D.	8007040635 8007040637 8007030487 8007040458 8007220133	50-424 G 50-424 G 50-424 S 50-424 S 50-424 G	EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q	8009190302* 8009190304* 8009190310* 8009190311* 8009190324*	50-335 0 50-262 0 50-313 0 50-344 0 50-312 0
DIRCKS, W J DIRCKS, W J DISE, D P DISE, D P	8007220255 8007240540 8007120408 8007180344 8007260403	50-220 P	DUTTON. D DUTTON. D DUTTON. D DHDRAK. J A DYM. H	8009240389 8009190493 8009300110 8009100043 8009160033	50-424 Q 50-424 B 50-424 Q NUREQ 50-387 M	EIBENHUT, D O EIBENHUT, D O EIBENHUT, D O EIBENHUT, D O EIBENHUT, D O	8009190328* 8009190343* 8009190359* 8009190369* 8009190380*	50-336 0 50-285 0 50-266 0 50-277 0 50-302 0
DISTEFAND, J DISTEFAND, J DIXGN, O DOAN, P F DODD, C V	8009100590 8009190529 8009050424× 8009050289× 8009030471	50-298 8 NUREO	DYM, H, DYM, H DYM, H DYM, H, DYM, H	6009160041* 6009170162 6009170162 8009300476 6009300476	50-389 M 50-389 M 50-389 M 50-250 M 50-250 M	EISENHUT.D Q EISENHUT.D Q EISENHUT.D Q EISENHUT.D Q EISENHUT.D Q	8009190581* 8009190754 8009220011* 8009220014* 8009220017*	30-346 Q 30-461 A 50-247 Q 50-220 Q 50-249 Q
DODDS.R T DODDS.R T DODDS.R T DODDS.R T DODDS.R T	8009110429# 8009120472# 8009120631# 8009120296# 8009120309#	50-397 Q 50-460 Q 50-528 Q 50-460 Q	EADIE, Q. Q EADIE, Q. Q EADIE, Q. Q EADIE, Q. Q EADS, B Q	8009160479* 8009170280 8009100135 8009190747 8009100508	WASTE MGT WASTE MGT WASTE MGT 40-8348 RES	EIGENHUT.D C EISENHUT.D C EISENHUT.D C EIGENHUT.D C EIGENHUT.D C	8007220019* 8007220071* 8007220074* 8007220101* 8007220107*	50-259 9 50-295 9 50-334 9 50-243 9 50-333 9
DODDS,R T BODDS,R T BODDS,R T BODDS,R T BOOGETT,8 A	8009120500* 8009040482* 8009190178* 8009300054* 8009140527	50-397 Q 50-528 Q 50-312 Q 50-446 Q	EAST.D J EASTERLING.R Q EBERLEIN,F EBNETER.B D EBNETER.S D	E009020508 E009300140 E009020185 E009090232* E00909066*	40-8745 NUREQ FOIA 50-352 Q 50-293 Q	EISENHUT, D. O EISENHUT, D. O EISENHUT, D. O EISENHUT, D. O EISENHUT, D. O	8009220112* 8009220117* 9009220123* 8009230117* 8009230127*	50-331 0 50-271 0 50-324 0 50-348 0 50-267 0
DOLAN, Y R DONAT, T J DONATH, F A DONAT, T DONO, R O	8007070216* 8007030550* 8007130585 8007240481 8007120337	50-289 H 50-349 Q NUREO 50-349 B NUREO	EBNETER, 8. D EBNETER, 9. EBNETER, 8 D ECKERT, J P ECKERT, R M	8009250302* 8009100899* 8009240245* 8009090885 8009110323	50-387 Q 50-289 Q 50-317 Q 70-27 50-272 V	EISENHUT, O, O EIGENHUT, D O EIGENHUT, D O EIGENHUT, D O EIGENHUT, D, O	8009230130* 8009230132* 8009230134* 8009240403* 8009260532*	50-261 9 50-260 0 50-305 9 50-321 9 50-317 9
DONOCHUE, D J DONOCHUE, D J DOTEDN, C W DOUGHERTY, D J. DOUGHERTY, D J.	8007030252 8007250280* 8007100403 8007170070* 8007120083*	SECY 10cfr Nureo Foia Contract	ECKHARDT, J H ECKHARDT, J H ECGNOMOS, N ECGNOMOS, N	8007020267# 8007120500# 8007170178# 8007160552# 8007120477#	50-361	EIBENHUT, D. Q EIBENHUT, D. Q EIBENHUT, D. Q EIBENHUT, D. Q, EIBENHUT, D. Q	8009260540* 8009260597* 8009260601* 8009260607* 8009260613*	50-348 0 50-289 0 50-299 0 50-309 0 50-315 0
DOUGHERTY, D J. DOUGHERTY, D J. DOUGHERTY, D J DOUGHERTY, D J DOUGHERTY, D J	8009150149* 8009160515* 8009260680* 8009200595* 8009200286*	CONTRACT CONTRACT CONTRACT CONTRACT 40-299	EOELBTEIN, B EDELBTEIN, B EDELBTEIN, D EDELBTEIN, B EDLGW, J.	8009110596+ 8009110392 8009120627+ 8009120624 8009190245	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	EIBENHUT, D Q EIBENHUT, D Q EIBENHUT, D Q EIBENHUT, D Q EIBENHUT, D Q	8009240624* 8009240667* 8009300251* 8009300258* 8009300269*	50~338 0 50~269 0 50~244 0 50~206 0 50~217 0
DOUGHERTY, J B DOUGHERTY, J B DOYLE, R J DOYLE, B C	8009230013 8009230013 8009230013 8009190768 8009110338*	50-280 G 50-280 G 50-280 G RES CONTRACT	EECKHOUT, A EECKHOUT, A EENIGENBURO, J EICH, E EICHHORN, W H	8009110270 8009110494 8009030194* 8009230571* 8009040281	XPORTLIC XPORTLIC 50-320 H 50-247 R 50-367 Q	EISENHUT, D Q EISENHUT, D, Q EISENHUT, D, Q EISENHUT, D Q EISENHUT, D Q	8007300453* 8007240137 8007240134 8007300584 8007300588*	50-29 0 50-309 H 50-275 H 50-293 0 50-293 0
DRAPER, E L DRAPER, E L DRAPER, E L DRAPER, E L DRAPER, E L	80090505224 80092903264 8009250412 8009090409 8009090532	50-458 Q 50-458 G 50-459 Q 50-459 A 50-459 F	EICHHORN, W H EICHHORN, W H EICHHORN, W H EICHHORN, W H EICHHORN, W H	8007040281 8007080507 8007080511 8007080507 8007080511	50-367 0 50-367 0 50-367 0 50-367 0 50-367 0	EISENHUT, D Q. EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q	8009170293* 8009300591 8009300598* 8009300603 8009300614*	50-289 P 50-271 Q 50-271 0 50-249 Q 50-249 0
DRAPER,E L DRAWBRIDGE,B L DRAZ,Z DRAZ,Z DRAZ,Z	8009300086 8009110334# 8009230239# 8009230242# 8009230245#	50-458 Q 50-27 S 50-320 H 50-320 H 50-320 H	EICHHORN, W H EICHHORN, W H EICHHORN, W H EICHHORN, W, H EICHHORN, W, H	8009110808 8009110808 8009190039 8009230035 8009190039	50-367 0 50-367 0 50-367 0 50-367 0 50-367 0	EISENHUT, D Q EL-ABHRY, H T EL-BASBIONI, A ELDER, K ELIN, J, O	8007300617* 8007030377 8007160473 8007110763 8007120472*	30-249 0 50-327 R NUREO 70-2786 50-397 0
DRAZ, Z DREYER, E P DRISKELL, W E DROMERICK, A W DROMERICK, A W	8009230247* 8009170301* 8009050399 8009190658 8009300056	50-320 H 50-244 P RES 50-339 P 50-339 F	EICHHORN, W H EICHHORN, W H EICHHORN, W H EICHHORN, W H EIGENHUT, D O	8009230035 8009300025 8009300576 8009300576 8009110347*	50-367 0 50-367 0 50-367 0 50-367 0 FOIA	ELIN, J O ELLERBHAW, L E ELLIB, J, ELLIB, J,	8007020267# 8007170031# 8007070379 8007070577 8007110034	50~361 0 0A979 50~123 p 50~445 0
DUBIEL, R W DUBONSKY, E DUBONSKY, E, DUCKWORTH, J P DUCKWORTH, J P	8007260437* 8007070202 8007070213 8007150132* 8007120601	50-289 T XPORTLIC XPORTLIC 50-201 U 50-201 R	EIBENHUT, D O EIBENHUT, D, O, EIBENHUT, D O EIBENHUT, D O EIBENHUT, D O,	8006300604 8008060358 8009240158* 8009110554 8009020157	50-10 P 50-320 P 50-313 8 50-10 P 50-245 P	ELLIB, J. EMDRY, K EMPBON, F. M ENGELKEN, R. H ENGELKEN, R. H	8007110044* 8007180462* 8007180408 8009180078*	50-445 0 50-3 H 70-1308 50-201 U 50-201 U
DUCKWORTH, J. P DUCKWORTH, J. P DUCKWORTH, J. P DUNYER, O. H DUMMER, O. H	9009120604* 8009170378 8009110648 8009230359* 8009300264*	50-201 R 50-201 R 50-201 R CONTRACT CONTRACT	EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q	8009110616 8009110619 8009020297 8009080080 8009230052	50-344 F 50-264 F 50-3 P 50-3 P 50-3 P	ENGELKEN, R H ENGELKEN, R H ENGELKEN, R, H ENGELKEN, R, H. ENGELKEN, R, H	E0091901E3* E009090052 E009150326 E009150378* E009030338	50-528 q 50-397 q 50-397 q 50-397 q 50-397 q
DUNAVONT, D H, DUNAVONT, D H DUNN, C. N DUNN, C. N, DUNN, C. N, DUNN, C. N	8009110299* 8009110304* 8009100389* 8009080309 8009070374	50-293 Q 50-293 Q 50-334 Q 50-334 Q 50-334 Q	EISENHUT, D. Q EISENHUT, D. Q EISENHUT, D. Q EISENHUT, D. Q,	8007030667* 8007020311 8007020318 8007020322 8007020327	NUREO 50-245 P 50-257 P 50-313 P 50-317 P	ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	8007260277 8007260278 8007260279 8007260300 8007260303	50-206 q 50-312 q 50-312 q 50-344 q 50-397 q
DUNN, C. N. DUNN, C. N. DUNN, C. N. DUNN, C. N.	8009090405 8009190444* 8009160374 8009180188 8009190446	90-994 P 50-280 R 50-394 G 50-394 R 50-994 R	EISENHUT, D O	8007140456 8007070863 8007070040 8007170587 8009170134	50-339 P 50-339 P 50-329 H 50-334 P 50-247 P	ENOELKEN, R. H ENOELKEN, R. H ENOELKEN, R. H ENOELKEN, R. H ENOELKEN, R. H	8007030262 8007030267 8007030318 8007030327 8007030337	50-528 F 50-397 F 50-312 F 50-344 F 50-133 F

AUTHOR		SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUYHOR	ACCESSION NUMBER	SUBJECT	
engelken. It h engelken. It. h engelken. It h engelken. It h engelken. It. h	8007020528 5 8007030276 5 8007030278 5	Q-206 F Q-528 8 Q-528 Q Q-275 Q Q-361 Q	FABRIKANT, R FABRIKANT, R FAHNER, T C FAHNER, T C FAHNER, T C	B009170239* 8009160160* 8009020048 8009020084 8009040208*	50-445 H 50-445 H 50-367 O 50-367 O 50-237 O	FELTON. J M	8009170236 8009170242* 8009170614 8009110286 8009110335	50-369 A 50-369 A FOIA FOIA FOIA	
engelken R H engelken R H engelken R H engelken R H engelken R H	8009030287 8009030288 8009030270	80-206	FAHNER, T C FAHNER, T C FAHNER, T C FAHNER, T C FAHNER, T C	8009040218* 8009110783 8009160281 8009150400 8009160247	50~237	FELTON, J M	8009190299 8009110354 8009110359 8009110527 8009110538	50-219 ¢ FOIA FOIA FOIA FOIA	
engelken R. H Engelken R. H Engelken R. H Engelken R. H Engelken R. H	8007270302 8007270305 8007270307	50-397	FAHNER,T C FAHRNER,U J FAHRNER,U J FAIRTILE,M B FALK,K M	8009220177 8009040455 8009160417 8009160505 8009030498	50-367	FELTON: J M FELTON: J M FELTON: J M FELTON: J M	8009110546 8009110567 8009290025 8009260187 8009150302	FOIA FOIA 50-266 H FOIA	
engelken, R. H Engelken, R. H Engelken, R. H Engelken, R. H Engelken, R. H	8009290457 8009190169* 8009150379*	50-312 0 50-206 0 50-528 0 50-397 0 70-734	FALK:K M FANKHAUSER:D FARNELL:A B FARNELL:A B FARNELL:A B	8009080348 8009030693 8009030718 8009030718 8009160397	50-286 0 50-358 0 50-329 0 50-329 0 50-329 0	Felton, J. M Felton, J. M Felton, J. M Felton, J. M	8009240141 8009240606 8009300109 8009250484 8009250448	FOIA 50-302 P FOIA FOIA	
engelken, R. H Engelken, R. H Engelken, R. H Engellen, R. H	8009230370 8009230371 8009230375	70-1257 70-754 70-25 70-984 TOPREP	FARNELL, A 8 FARNELL, A 8 FARON, R 8 FARRAR, A 0 FABIG, F	8009300023 8009300023 8009040413 8009110256* 8009300163*	50-329 G 50-329 Q 50-244 P CONTRACT 50-287 H	FELTON.J M FELTON.J M FELTON.J M FELTON.J M	8009300520 8009270414 8009270443 8009300284 8009300330	FOIA FOIA FOIA FOIA	
engelken, R. H Engelken, R. H. Engelken, R. H Engelken, R. H Engelken, R. H.	8009120029 8009120030 8009180374 8009140178 8009140181	50-133	FAULKENBERRY, B FAULKENBERRY, B FAULKENBERRY, B FAULKENBERRY, B FAY, C W	8009120478* 8009170244* 8009120479* 8009120490* 6009110557	50-326	FELTZID E FEROUSONIJ H FERGUSONIJ H FERGUSONIJ H FERGUSONIJ.H	8009030350 8009020437 8009030426 8009090344 8009220134	50-128 R 50-280 P 50-338 P 50-338 P 50-280 P	
Engelken, R. H. Engelken, R. H. Engelken, R. H. Engelken, R. H. Engelken, R. H	8007140183 8007140184 8007140185 8007140187 8007170157	50-344 G 50-206 G 50-312 G 50-397 G 50-528 G	FAY,C W FAY,C W FAY,C W. FAY,C W FAY,C W	8007070537 8007180159 8007160304# 8007260215 8007160302	50-266 R 50-266 Q 50-266 R 50-266 F 50-266 R	FERNOS, O FERNOS, O FERNOS, O FERNOS, O FERNOS, O	8007040225 8007040233 8007110010 8007110055 8007260670	50-376 0 50-376 0 50-376 0 50-376 0 50-376 0	
engelken, r h Engelken, r. h Engelken, r h Engelken, r. h. Engelken, r h	8009230327 8009230332 8009230334 8009230337 8009230339	70-984 70-1287 70-734 50-275 F 50-344 F	FAY.C.W FAY.C W FAY.C.W FEDERICK.E J FEE.W F	8009230660 8009230666 8009300461 8009120571 8009120197	50-266 P 50-266 P 50-266 P REB 50-245 Q	FERNOS, O FERNOS, O FEBS, K H FIDELL, E R FIELDER, J	8009260681* 8009260684* 8009190863 8009150371 8009030374	50-376 0 State Prog FOIA 50-327 J	
EHOELKEN, R H. ENGELKEN, R, H ENGELKEN, R H ENGEL, R. E. ENGELKEN, R. H	8007230342 8007230344 8007240587 8007110436 8007260307	50-206 F 50-312 F 70-25 TOPREP 70-2708	FEE. W F. FEE. W F FEE. W. F FEE. W. F FEE. W F	8009230749 8009020231 8009020285 8009030532 8009150247	50-245 G 50-213 P 50-245 P 50-213 P 50-336 P	FIELDS, BR FINFROCK, IR FINFROCK, IR FINFROCK, IR FINFROCK, IR	8007070020 8007070181* 8007120177 8007230104 8007070031	NUREO 50-219 Q 50-219 Q 50-219 Q 50-219 Q	
ENGELKEN, R. H. ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H.	8007260311 8007120456 8007120456 6007120460 8007120463	70-1470 50-528 0 50-133 0 50-344 0 50-206 0	FEE.W F. FEE.W F FEE.W F FEE.W F.	8009110245 8009190434 8009120237 8009090636 8009230621		FINFROCK, I R FINFROCK, I R FINFROCK, I R FINFROCK, I R FINFROCK, I R	8009160510 8009020379 8009020392 8009030340 6009020360	50-219 S 50-219 S 50-219 S 50-219 P 50-219 P	
ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H.	B009120468 B009120469 B009180130 B009180134 B009020412*	50-312	FEHRINGERJ M FEIERABEND,C D FEID,D FEIL.R, FEIT.R	8009180305 8009260271 8009300514 8009150097 8009150562	* 50-202 G 50-201 G 7* 50-410 G	FINFROCK, I R FINFROCK, I R FINFROCK, I R FINFROCK, I R	8009190421 8009220283 8009260440 8009300404 8009290355	50-219 P 50-219 B 50-219 B 50-219 P 50-219 P	
engel, R. E. Engel, R. E. Engel, R. E. Engel, R. E. Engel, L. B	8007170238 8007160172 8007160424 8007170273* 8007150112*	50-206 P TOPREP TOPREP 50-309 P 50-201 U	FELTON, J. H FELTON, J. H FELTON, J. H FELTON, J. H.	8007050123 800708025 8007050383 8007050363	F01A F01A 50-375 P	FINFROCK. 1 R FINFROCK. 1 R FINFROCK. 1 R FINFROCK. 1 R FINKEL. A E	8009300522 8009300564 8009300261 8009300270 8009240265	50-219 8 50-219 P 50-219 P 50-317 Q	
EPSTEIN, E. EPSTEIN, E. O ERB, C. M. ERB, C. M ERB, C. M	8007030554 8007180280* 8007180602* 8007260415* 8007270173*	50-320 P 50-373 G 50-546 G 50-327 G 50-454 G	FELTON, J. K FELTON, J. K FELTON, J. K FELTON, J. K FELTON, J. M	800705048 800705044 800702017 800702018 800705047	5 70-1308 5 FOIA 2 FOIA	FIDRELLI.0 FIDRELLI.0 FIDRELLI.0 FIDRELLI.0 FIDRELLI.0	8009110307 8009150194 8009250346 8009110620	50-454 Q 50-329 Q 50-461 Q 50-282 Q	
ERB.N.B. ERNOT.H.L. ERTEL.A E. EGKRIDGE.H E	8009220215 8009180144 8009080345 8009250422*	50-320 H 50-247 P 50-289 U 70-36 50-305 Q	FELTON, J. M FELTON, J. H FELTON, J. H FELTON, J. M FELTON, J. M	800909033 800905016 800903017 800903006 800903049	.8 70-143 7 70-143 5 50-466 9	FICRELLI.0 FICRELLI.0 FICRELLI.0 FICRELLI.0 FICRELLI.0	8009110655 8009150174 8009150504 8009170217 8009180246	50-546 Q 50-346 Q 50-456 Q 50-373 Q	
E8810, T. H. E8810, T. H. E8810, T. H. E8810, T. H. E8812, T. H. E8812, H. P.	8007030326* 8007120507* 8007270018* 8007240465* 8007040473	50-155 G 50-266 G 50-346 G 70-1257	FELTON, J M FELTON, J, M FELTON, J M FELTON, J M FELTON, J M	800912049 800902049 800902051 800924001 800908041	75 F01A 11 50-302 H 12 50-243 0	fiorelli.0 fiorelli.0 fiorelli.0 fiorelli.0 fiorelli.0	8007110764 8007020186 800718022 800702024 800715059	50-461 8 1• 50-546 Q 9 50-546 B 4 50-546 Q	3
ESTEY, H P. ESTEY, H P. ESTRADA, H. ETSEY, H. P. EURY, L. H	8009110278 8009160523 8009260417* 8009110718 8009110271	70-1257 50-261 G	FELTON, J M FELTON, J, M FELTON, J, M FELTON, J, M FELTON, J, M	80090804- 80091100- 80091500- 80091205- 80091503-	56 50-397 A 02 FO1A 82 50-320 P	FIGRELLI,0 FIGRELLI,0 FIGRELLI,0 FIGRELLI,0 FIGRELLI,0	800918001 800918004 800918023 800902016 800902033	3 50-461 Q 1 50-327 Q 5 50-327 A 1 50-483 8	1 A B
EVANG.A K. EVANG.T.P. EVANG.A. EVERBT.E.J. FABRIKANT.R FABRIKANT.R	6009240264 6009120033 6009190584 8009220352 8009240269 6009170232	CONTRACT 50-285 Q 50-295 B 50-445 M	FELTON, J H	80091205 80091203 80091700 80091700 80091700	91 FDIA 52* 50-369 G 49 FDIA 57 FDIA	FIGRELLI.0 FIGRELLI.0 FIGRELLI.0 FIGRELLI.0 FIGRELLI.0	80043504 80043092 800435905 800435905 80043505	57 50-329 8 79 50-373 8 19 50-461 0	8 8

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGURY	AUTHOR	ACCESSION NUMBER	SUBJECT CATECORY
FIGRELLIO FIGRELLIO FIGRELLIO FIGRELLIO FIGRELLIO	8009100105 8009110445 8009130491 8009300371* 8009300070	50-440 G 50-454 G 50-544 B 50-347 G 50-489 B	FROST, S R FROST, S R FROST, S R FROTH, D. FROTH, D.	8007070549 8007230440 8007240488 8007030563 8007080438*	50-255 0 50-255 P 50-255 8 TOPREP 50-312 P	GEIBZEWBKI,P GELBTON,A H GELBTON,A H GEGROIOU,B B	8009220245 8009120443* 8009160398* 8009160468* 8009110019	8M 50-327 8 50-327 8 50-327 8 50-275 0
FIGRELLI, O	8007270077	50-346 Q	FROTH, D J	8009100176#	50-346 P	OEORGIOU, B S	8009110019	50-275 9
FIGRELLI, O	8007270104	50-546 Q	FROTH, D J	8009290373*	50-329 A	OEORGIOU, B S	8009220406	50-275 9
FIGRELLI, O	8007270110	50-546 Q	FUHRER, E C	8009260443#	50-289 T	OEORGIOU, B S	8009230616	50-275 9
FIGRELLI, O	8007270188	50-454 Q	FULLER, J K	8009030540	50-267 P	OERBER, D A	8009020111*	50-237 P
FIGRELLI, O	8007270525	50-440 Q	FULLER, J K	8009240194	50-267 0	GERGELY, P	8009020353	NUREO
FIGRELLI, O	8007300565	50-367 Q	FURBUBH, M H FURR, B J FURR, B J FURR, B J FURR, B J	8009030589	50-275 G	GERSTNER,W C	8009100830*	50-461 G
FIGRELLI, O	8007100620	50-338 S		8009020198	50-261 Q	GERSTNER,W C	8009100833*	50-461 G
FIGRELLI, Q	8007160248	50-327 Q		8009030307	50-261 Q	GETTY,B G.	8009120419*	50-193 B
FIGRELLI, G	8007100664	50-329 S		8009020199	50-324 Q	GEYER,J C	8009240125*	50-263 Q
FIGRELLI, O	8007100826	50-461 Q		8009230059	50-324 Q	GIBBONS,T D	8009240276*	50-370 G
FIGRELLI.O	8009250205	50-461 G	FURR. B. J	8009230080	50-324	GIBEONS, T D	8007100307*	50-364 0
FIGRELLI.O	8009250230	50-460 G	FURR. B. J	8009230085		GIBSON, A F	8009240646*	70-143
FIGRELLI.O	8009250474	50-461 S	FURR. B. J	8009240348		GIBSON, A F	8009020477*	50-348 0
FIGRELLI.O	8009250483	50-546 S	FURR. B. J	8009120228		GIBSON, A F	8009240195*	50-302 0
FIGRELLI.O	8009250252	50-461 S	FURR. B. J	8009240370		GIBSON, G T	8009040330*	50-327 0
FIGRELLI.O	8007240229	50-440 8	FURR, B. J	8007110562	50-324 Q	GIBSON, A F	8009250200*	50-359 0
FIGRELLI.O	8007250479	50-544 8	FURR, B. J	8007120366	50-325 8	GIBSON, C I	8009160456	NUREO
FIGRELLI.O	8007290071	50-440 8	FURR, B. J	8007170186	50-324 P	GIBSON, J W	8009300563*	50-257 8
FIGRELLI.O	8007270065	50-341 8	FURR, B. J	8007260635	50-324 S	GIDD, R G	8009020161	NUREO
FIGRELLI.O	8007270448	50-358 0	GAGLIARDD, J. E	8007050477*	50-267 Q	GIDD, R G	8009100036	NUREO
FIORELLI.O	8009270472	50-329 Q	Gagliardo, je	8009100059*	50-267 @	GIDD.R Q	8009150599	NUREO
FIORELLI.O	8009270197	50-546 B	Qahm, ju	8009030640*	50-267 B	GILBERT,L,D.	8009170387*	50-482 Q
FIORELLI.O	8009270202	50-546 G	Qahm, ju	8009160288*	50-267 R	GILBERT,L D	8009150357*	50-458 Q
FISHER.W L	8009100091*	50-87 Q	Qahm, ju	8009260386*	50-267 R	GILBERT,L D	8009100279*	50-445 Q
FISHER.W L	8009150165*	40-3392	Qahm, ju	8009160299*	50-267 R	GILBERT,L D	8009190340*	50-382 Q
FIBHER,W L FIGHER,W L FIGHER,W L FISHER,W L FIBHER,B P	8009030495* 8009240255* 8009290094* 8009260634* 8009170178	50-243 F 50-282 F 70-1308 50-315 G MISC	QAHK, J. W QALLACHER, E J QALLACHER, E J GALLACHER, J W. QALLACHER, E J	# 7040EFP008 # 1400B	50-267	GILBERTS.D E GILBERTS.D E GILBERTS.D E GILBERTS.D E GILBERTS.D E	8009150076 8009150218 8009110534 8009110539 8009090019	50-282 0 50-282 0 50-282 0
FITTI.C FITZPATRICK.R FITZBIMMONB.O FLACK.W L FLACK.O	8009220420* 8009170349* 8009230475* 8009110297 8009300375	50-466 0 50-287 T TUPREP 50-293 0 50-424 0	CALLEN, K P. CALLEN, K P CALLO, R M CALLO, J CALLO, J	8007070334 8007070336 8007170241* 8007150344* 8007180344*	50-407	GILBERTS.D E GILBERTS.D E. GILBERTS.D E GILBERTS.D E GILBERTS.D E.	8009110499 8009250411* 8009170405 8009170441 8009180007	50-263 Q 50-263 Q 50-263 Q 50-263 Q
FLANDERB.W L. FLANIGAN.L J FLANIGAN.L J FLANNIGAN.R.D FLAXMAN.C A	8009300430* 8009100043 8009300164 8009050190* 8009190046	50-307 R NUREO NUREO 50-278 S 50-230 O	CALLO, J CALLO, J CANO, H Q CANTHNER, R W	8009130339 8009220185 8009220216* 8009160366 8009080438*	50-135 G 50-155 G 50-155 G TOPREP 50-312 P	GILBERTS, D E GILBERTS, J S GILBERT, J D GILINSKY, V GILINSKY, V	B009170413 B009150599 B009050335# B009230260# B009230289#	50-263 Q NUREO 50-338 R FOIA FOIA
FLAXMAN,C A	8009150075*	50~250 0	OARCIA,M	8009030581	50-275 H	OILINSXY,V	8009290021	50-327 T
FLEENDR,C H	8009150409	CONTRACT	GARNER,D J	8009170244*	50-312 P	OILLESPIE,F P	8009190651#	50-259 Q
FLEENDR,C H	8009300271	CONTRACT	GARNER,D J.	8009230765	50-312 F	OILLESPIE,F,P	8009100914#	70-143
FLEIBCHAKER,D	8009160234	50~275 0	GARRETT,E G.	8008120480	50-309 H	OILLESPIE,F P	8009110173#	50-250 G
FLEIBCHAKER,D	8009160234	50~275 0	GARRETT,E G	8008120525	50-309 H	OILLESPIE,F P.	8009120133#	70-143
FLEIBCHAKER, D	8009220262	50-275 0	GARRETT, E O GARRETT, E O GARRETT, E O GARRETT, C O GARRITY, J, H	6008120534	50-309 H	OILLESPIE,F P	8009110142*	70-1181
FLEIBCHAKER, D	8009220262	50-275 0		6008120547	50-309 H	OILLESPIE,F P	8009110191*	50-327 Q
FLEIBCHAKER, D	8009240344	50-275 0		8008120555	50-309 H	OILLEN,K T	8009190398	NUREO
FLYNN, M J	8009110022	CONTRACT		6008120548	50-309 H	OILLESPIE,F P	8009170152*	50-302 Q
FLYNN, M J	8009030030	CONTRACT		6007230455	50-309 R	OILLESPIE,F P	8009250439*	70-143
FLYNN,M J	8009120659	CONTRACT	QARRETY, J H	\$009300426	50-309 R	OILLEN, D M	8009100133	40-4492
FLYNN,P.O.	8009040289	50-445 M	QARY, R J	\$009170420	50-445 Q	OILLESPIE, F P	8009100795#	70-27
FLYNN,M J	8009300206	CONTRACT	QARY, R, J	\$009150213	70-2932	GILLESPIE, F P	8009250066#	70-1551
FODEB,R L	8009220289*	50-255 B	QARY, R, J	\$009150215*	70-2932	OILLETT, W, T	8009160277#	50-315 R
FOLK,J.	8009220200*	50-287 H	QARY, R, J	\$009150012	50-445 Q	OILLETT, W T	8009160283#	50-316 R
FONO, T,	8009300324*	50-344	QARY, R. J	8007270571*	50-445 Q	QILLMAN, D W	8009190344*	50-361 M
FORD, E J	8009120071*		QARY, R. J	8007180045	50-445 B	OILLOGLY, J	8009290423	FOIA
FOREMAN, H	8009160530		QARY, R. J.	8007180457	50-445 Q	GINSBURO, R A	8009290180	50-250 O
FOSTER, W E	8009150100*		QARY, R. J.	8007300035	50-445 Q	OIRARD, E H	8009030140*	50-375 G
FOSTER, J M	8009160511		QARY, R. J	8007070387	50-445 V	OITLEN, P H	8009110684	50-201 O
FOSTER. J M FOSTER. L, E FOSTER. J E FOUCHARD. J J FOUKE. R L	8009110375 8009240308* 8009240415* 8009050442* 8009240005	CONTRACT 50-314 Q 50-329 Q FOIA 50-445 Q	GARY, R. J GARY, R. J GARY, R. J GARY, R. J GARY, R. J	8007300070 8007140362 8007300065 8007300074 8007220334	50-445 Q 50-445 A 50-445 Q 50-445 Q 50-445 A	OITLEN, PH GIVEL, M8 GIVEL, M8 GLAGOLA, AF OLAGOLA, AF	8009120545 8009020517 8009240611 8009150140 8009150143*	50-201 P 50-302 H 50-302 P CONTRACT CONTRACT
FOX, D. F	8009150234*	GA999	QARY, R. J.	800723030i	50-445 8	GLAGOLA, A, F	8009160491	CONTRACT
Francis, K A	8009040437	NUREG	CABBER, E. R.	8007110222*	CONTRACT	GLAGOLA, A F	8009160495*	CONTRACT
Francois, E. 1	8009250313*	GA999	CABBER, E. R.	8007260242*	CONTRACT	GLAGOLA, A F	6009110379*	CONTRACT
Francis, C C	8009020358	NUREG	GAULKE, A. E	8007170422	50-315 R	GLAGOLA, A F	6009100012*	CONTRACT
Francis, O, P	8009020358	50-289 H	CAWRYCH, M. A	8007120275	50-397 0	GLAGOLA, A F	8009250497*	CONTRACT
FRANK, L	8007120337	NUREO	OAY.O M	8007070238	50-445 G	OLAODLA: A F	8007230161*	CONTRACT
FRANTZ, 8, P	8007170037	50-367 9	GAY.O M	8007070238	50-445 Q	OLANTZ; C.	8007230222*	50-320 H
FRANTZ, 8 P.	8007230035	50-367 0	GAY.O M	8007150045	50-445 Q	OLEASON: O L	8007170668*	FOIA
FRANTZ, 8 P.	8007300576	50-367 0	OAY.O M	8007150045	50-445 G	OLENN; J. E.	8007270087*	FOIA
FREEMAN, M D	8007150577*	40-8769	GEHR.A C	8007030687	50-275 Q	OLENN; J E	8007270152*	FOIA
FREEMAN, J	8009250486	F01A	OEHR, A C	8007030687	50-275 Q	QODDARD, R J,	8007260310	50-471 0
FREEMAN, M D	8009150575	40-9768	OEHR, A C	8007030714	50-528 Q	GODDARD, R J	8007300045	50-237 9
FRIESEMA, H P	8009100463*	50-275 H	GEHR, A. C	8007030714	50-528 Q	GOLDHERT, N. W,	8007040104#	40-2061
FRIZZLE, C D	8009230591*	50-307 P	OEHR, A. C	8007030677	50-275 Q	GOLDBERG, S C,	8007110018	50-347 0
FRONNE, R.	8009020374*	50-346 B	GEHR, A. C	8007030677	50-275 Q	GOLDBERG, S C	8007120416	50-320 p

AUTHOR	ACCEBSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGURY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
QCLOBERO, B C	8009170167 8009170282 8009230041 8009250024 8009300005	50-367 0 50-367 0 50-367 0 50-250 0 50-367 0	GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8007070074 8007070076 8007070101 8007070105 8007070106	50-387	GRIER.B H GRIER.B H GRIER.B H GRIER.B H GRIER.B H	8009180037 8009180042 8009180044 8009180048 8009180050	50-387 Q 50-272 Q 50-354 Q 50-443 Q 50-244 Q	
QOLDEN, J. C. QOLLER, K. R. QODHOPE, A. C. QODHOPE, A. C. QODLING, B.	8009030440* 8009020531* 8009120022 8009120409 8009030432	50-295 P RECOD 70-1308 27-39 50-289 H	ORIER.B H ORIER.B H ORIER.B H ORIER.B H ORIER.B H	8009090111 8009090113 8009090168* 8009100034 8009100037	50-245 Q 50-293 Q 50-219 Q 50-219 Q 50-293 Q	CRIER,# H ORIER.# H ORIER.# H ORIER.# H GRIER.# H	8009180051 8009180055 8009180057 8009180339 8009180478	50-485 G 50-271 G 50-27 G 50-3 G 50-334 G	
COODLING, B OCCOMAN, L. S. COODMAN, L. S COODMAN, L. S COODMAN, L. S	8009230442* 8009030457* 8009160253* 8009230657* 8009230664*	50-287 H 50-407 8 50-407 R 50-407 B 50-409 B	GRIER, BH ORIER, BH GRIER, BH GRIER, BH GRIER, BH	8009160621* 8009150130 8009160225 8009160220 8009090163	50-277 Q 50-271 Q 50-277 Q 50-244 Q 50-219 Q	GRIER.B H GRIER.B H GRIER.B H GRIER.B H GRIER.B H	8009180483 8009180948 8009230142 8009230145 8009230147	50-412 Q 50-293 Q 50-293 F 50-317 F 50-3 F	
COCCHAN.L S COCCHIN.C COCCHIN.H.L COCCHIN.C COCCHIN.C	8009260636* 8009160620 8009110135* 8009180009 8009180039	50-409 B 50-344 G 70-1151 50-344 G 50-344 G	GRIER.B H GRIER.B H GRIER.B H GRIER.B H GRIER.B H	8009120550 8009120709 8009120469 8009120101 8009110257	50-322 0 50-213 P 50-272 V 50-273 P 50-333 Q	ORIER, 8 H ORIER, 8 H ORIER, 8 H ORIER, 8 H	8009230169 8009230172 8009230174 8009230175 8009230178	50-213 F 50-334 F 50-219 F 50-289 F 50-309 F	
COODMIN. C COODMIN. C COODMIN. C COODMIN. C	9007170671 8007250337 8007300314* 8007240375 8007030575	NUREO 50-344 G 50-344 G 50-344 G 50-344 R	ORIER, B H ORIER, B H ORIER, B H ORIER, B, H ORIER, B H	8007120585 8007150465 8008280053 8008280056 8007030037	40-672 50-245	ORIER, BH ORIER, BH ORIER, BH ORIER, BH ORIER, BH	8007230180 8007230184 8007230165 8007230188 8007230189	50-220 F 50-285 F 50-333 F 50-171 F	
9000НIN- С 9000НIN- С. 9000НIN- С 9000НIN- С 9000НIN- С.	8007100507 8007110308 8007180377 8007180385 8007180468	50-344 F 50-344 G 50-344 B 50-344 P 50-344 P	GRIER, D. H ORIER, S. H GRIER, B. H ORIER, B. H ORIER, B. H	8007030042 8007030044 8007030047 8007030059 8007030060	50-363	GRIER.B H GRIER.B H GRIER.B H GRIER.B H	8009230191 8009230196 8009230199 8009230200	50-272 F 50-274 F 50-271 F 50-29 F	
ODDMIN.C OORDON.C.Z OORDONEA OOBBICK.L.V. COBBICK.L.V	E007220343 E007240727* E007160414 E007170358* E007170305*	50-344 P 40-299 50-387 Q FOIA FOIA	ORIER.B H GRIER.B.H GRIER.B H GRIER.B H GRIER.B H	80 09030063 80 09030066 80 09030070 80 090030070 80 090030073	50-29	GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8009230225 8009230220 8009230223 8009230225	50-201 F 70-33 70-371 70-820 70-1143	
ORAEGBER, K.L. ORAEGBER, K.L. ORAEGSER, K.L. ORAEGSER, K.L.	8007020447 6007030441 8007020395 8007020276 8007020452	50-275 8 50-275 R 50-275 8 50-304 8 50-275 B	ORIER.B H ORIER.B H ORIER.B H ORIER.B H ORIER.B H	8009030075 8009030076 8009030081 8009030083 8009030086	50-412	ORIER, BH GRIER, BH ORIER, BH ORIER, BH ORIER, BH	8007120166 8009120169 8009120171 8009120174	50-293 0 50-317 0 50-3 9 50-213 0	
GRAEBBER, K.L. GRAEBBER, K.L. GRAEBBER, K.L. GRAEBBER, K.L. GRAEBBER, K.L.	8009120299 8009120302 8009120305 8009090294 8009160293	50-295 8 50-295 8 50-295 8 50-295 R 50-304 8	GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8009030087 8009030089 8009030090 8009030091 8009030094	50-410 G 50-322 G 50-244 G 50-272 G 50-333 G	GRIER. B H GRIER. B H GRIER. B H GRIER. B H GRIER. B H	8009120177 8009120180 8009120184 8009120186 8009120190	50-363 Q 50-322 0 50-287 Q 50-307 0	
GRAEBBER, K. L. GRAEBBER, K. L. GRAEBBER, K. L. GRAEBBER, K. L. GRAEBBER, K. L.	8007160408 8009220274 8009220349 8009220281 8009230681	50-275 8 50-304 8 50-275 8 50-275 8 50-304 8	ORIER.B.H ORIER.B H ORIER.B H ORIER.B H ORIER.B H	8809030095 8009030099 8009030109 8009030111 8009030113	50-309 Q 50-220 Q 50-317 Q 50-293 Q 50-213 Q	GRIER. B H GRIER. B H GRIER. B H GRIER. B H	8007120173 8007120176 8007120200 8007120204	50-410 G 50-286 Q 50-352 Q 50-387 G	
ORAESSER, K.L. ORAHAM, E. T. ORAHM, P. ORANT, M. ORAVES, R. H.	80072703174 80071204744 80071501644 8007020015	50-293 8 COMMISSION	ORIER.B H ORIER.D H ORIER.B H ORIER.B H ORIER.D H	8009100454 8009230405 8009230406 8009230409	50-213 P 70-1100 70-1143 70-135 50-201 Q	GRIER, BH GRIER, BH GRIER, BH GRIER, BH GRIER, BH	8009120211 8009120213 8009120215 8009120216	50-443	
GRAYES R H GRAY, J R GRAY, J R GRAY, J R GRAY, J R,	8007040292 8007070232 8007160137 8007170165	50-142 Q 50-344 Q 50-287 Q	GREER, BH GRIER, BH GRIER, BH GRIER, BH	8009230413 8009230415 8009230416 8009230419 8009230421	70-33	ORIER, 8 H ORIER, 8 H ORIER, 8 H ORIER, 8 H	8009120229 8009120230 8009120233 8009120237	50-219 0 50-220 0 50-333 0 50-277 0	
oray, J. R Oray, J. R Oray, J. R Oreenman, E Oreenman, E	8009260003 8009260004 8009260006 8009110306 8009090250	* 50-287 0 * 50-287 0 * 50-333 G * 50-287 0	ORIER, B. H ORIER, B. H ORIER, B. H ORIER, B. H ORIER, B. H	8009120084 8009120087 8009120088 8009120090 8009120095	50-219 Q 50-322 Q 50-245 Q	GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8009120243 8009230490 8009230493 8009230493 8009230495	50-244 0 50-293 0 50-219 0 50-220 0	
Greenhan, e Green, e Green, e Greenkorn, r Greger, l, r	8009180005 8009120501 8009170277 8009240130 8009240255	50-277 S /* 50-257 R 0* CONTRACT	GRIER, B H GRIER, B. H GRIER, B H GRIER, B H	8009120097 8009120100 8009120100 8009120100	50-333 G 50-277 G 50-352 G	ORIER, BH ORIER, BH ORIER, BH ORIER, BH ORIER, BH	9009230499 8009230514 8009230519 9009230775	50-333 Q 50-271 Q 50-245 Q 50-293 Q	
Greodry, W B. Greodry, W B. Greuling, E Grew. P.	8009120572 8009160493 8009240123 8009030643 8009110023	2 RE8 2 RE8 3* 90-263 9 3* PR	ORIER, B H ORIER, B H ORIER, B H ORIER, B H	800712011 800712011 800718000 800718000 800718000	0 50-354 Q 4 50-271 Q 3 50-213 Q 4 50-363 Q	GRIER. BH ORIER. BH GRIER. BH GRIER. BH GRIER. BH	8009230776 8009230778 8009230775 8009230780 8009230780	50-3 Q 50-213 Q 50-334 Q 50-219 Q	,
GREW, P. G. GRIDLEY, C F GRIER, B. H. GRIER, B. H. GRIER, B. H.	8007110082 800703082 800718057 771217007 771217001 800305022	3* 50-327 8 2 50-317 0 3* PT9 4 PT9	ORIER, B. H ORIER, B. H GRIER, B. H. ORIER, B. H. ORIER, B. H.	800718000 800718001 800718001 800718001	9 50-322 0 3 50-289 0 5 50-309 0 7 50-245 0	GRIER, 8 H GRIER, 8 H GRIER, 8 H GRIER, 8 H GRIER, 8 H	8009230788 8009230799 8009230799 8009230799	50-289 Q 50-245 Q 50-220 Q 50-285 Q	
ORIER, B H ORIER, B H ORIER, B H ORIER, B, H ORIER, B, H ORIER, B, H ORIER, B, H	800305082 800305021 800305021 800929014 800909008 800909008	5 PT9 9 PT9 0* FOIA 5 50-322 Q 7 50-410 Q	ORIER, B.H ORIER, B.H ORIER, B.H ORIER, B.H ORIER, B.H ORIER, B.H	800418003 800418005 800418005 800418005	3 50-410 0 5 50-286 0 8 50-333 0 80 50-277 0	ORIER, B H ORIER, B H GRIER, B H GRIER, B H ORIER, B H	800923079 800923079 800923079 800923079 800924002	5 50-354 G 5 50-443 G 8 50-485 G	3

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBUECT CATEOORY
GRIER.B H	8009240030	50-309 0	HAASSIH P	8007290379	HISC	HARMON, D W	8009300668	XPORTLIC
GRIER.B H	8009240031	50-412 0	HACKNEY, B D	8007030563*	50-528 8	HARMON, D W	8009290157	XPORTLIC
GRIER.B H	8009240032	50-363 0	HAFERA, T	8007080427*	50-254 8	HARRAN, O	8009190459*	SO-245 R
GRIER.B H	8009240033	50-410 0	HAFFMAN, D P	8007190661	PRM	HARRIS, J R	8009100149*	SO-389 Q
GRIER.B H	8009240035	50-333 0	HAGA, P B	8007100586	50-437 A	HARRIS, J R	8009150370*	SO-321 Q
GRIER.B H	8009240043	50-277 Q	HAGAN, T. F	8009110215	CONTRACT	HARRIBON, J J	8007150177*	50-545 Q
GRIER.B H	8009240045	50-272 Q	HAGAN, T F	8009260229	CONTRACT	HARRIBON, J J	8009110769*	50-545 Q
GRIER.B H	8009240048	50-244 Q	HAGAN, T F	8009180167	CONTRACT	HARRIB, J R	8009180221*	50-546 Q
GRIER.B H	8009240050	50-29 Q	HAGAN, T F	8009300193	CONTRACT	HARRIB, J S	8009250343*	50-413 Q
GRIER.B H	8009240215	50-77 Q	HAGEY, H	8009110412	CONTRACT	HARRIB, J S	8009020285*	50-336 B
GRIER, B H ORIER, B H ORIER, B H ORIER, B H ORIER, B H	6009240218 8009240221 8009240225 6009240227 8009240231	50-208 0 50-97 0 50-199 0 50-20 0 50-5 0	HAGEY, H HAGEY, H HAGEY, H HAGEY, H	8007030209 8007020475 8007160485 8007110407 8007230768	CONTRACT 70-2313 CONTRACT CONTRACT CONTRACT	HARRIE, J F HARRIE, D R HARRIEDN, P HARRIEDN, P. HARRIE, J E	800712044B 8007300207 8007150266* 8007160467* 8007170531*	50-341 H 71-374 50-220 S 50-220 S 50-336 \$
ORIER, B H ORIER, B H ORIER, B H ORIER, B H ORIER, B H	8009240234 8009240238 8009240242 8009240247 8009240250	50-225	HAGEY, H Hagey, H Hagey, H Hagrman, D L Hairston, C A	8009230774 8009120004 8009240034 8009100530 8009100010	CONTRACT CONTRACT CONTRACT RES CONTRACT	HARRIB, J B. HARRIB, J B HARRIB, J, B HARRIB, J, B HARRIB, J, B	8009190537* 8009190543* 8009160461* 8009160464* 8009160469*	50-334 \$ 50-334 \$ 50-334 \$ 50-336 \$ 50-334 \$
GRIER.B H ORTER.B H ORTER.B H GRIER.B H GRIER.B H	8007240252 8007240268 8007240271 8007240275 8007240277	50-22 G 50-54 G 50-193 G 50-170 G 50-47 G	HAIRSTON, C HAIRSTON, C HAIRSTON, C HAIRSTON, C HAIRSTON, H O	8009250493 8009230157 8009190051 8009190057* 8009020068*	CONTRACT CONTRACT CONTRACT CONTRACT 50-348 B	HARRISON, P HARRIS, J E HARRISON, P HARRIS, V A HART, J, L,	8009180278# 8009260694# 8009300498# 8009300442 8009100435	50-220 8 50-234 8 50-220 8 50-445 6 50-445 9
ORIER.B H ORIER.B H ORIER.B H ORIER.B H	8007240278	50-184 Q	HAIRBTON, W O	8009030429*	50-348 8	HART, J. L.	8007240005	50-445 0
	8007240281	50-184 Q	HAIRBTON, C	8009260676	CONTRACT	HART, J.	8007260008	50-445 0
	8007240285	50-317 Q	HAIRBTON, W O	8009160270*	50-348 R	HART, J.	8007300338	50-382 6
	8007240303	50-293 Q	HAIRBTON, C	8009300593	CONTRACT	HARTMAN, D.	8007160346	40-8745
	8007240304	50-3 Q	HAIRBTON, W O	8009160323*	50-348 8	HARTMETT, R. A	8007270376#	50-302 6
ORIER.B H	8009240308	50-213 0	Mairston, C	8007300281	40-299	HARTZMAN, M	B0092406B6	NUREQ
ORIER.B H	8009240309	50-334 0	Mairston, W C,	8007160308*	50-348 8	HARVEY, J. L	B009150390	71-7044
ORIER.B.H	8009240311	50-363 0	Hairston, W C	8007230729*	50-348 8	HARNDOD, T P	B009090343*	30-339 U
ORIER.B.H	8009240315	50-322 0	Hairston, W C	8007230737*	50-348 8	HABBRDOK, R E	B009120012*	CONTRACT
ORIER.B.H	8009240316	50-287 0	Hairston, W C	8007300577*	50-348 8	HANKINS, F, C	B009110749*	80-846 Q
GRIER.B.H GRIER.B.H GRIER.B H GRIER.B H GRIER.B H	8009240319 8009240323 8009240324 8009240325 8009240328	50-245 Q 50-410 Q 50-333 Q 50-277 Q 50-387 Q	HAIRSTON, W O HAIRSTON, W O HALE, C J HALE, C J HALE, C. J	8009300527* 8009300515* 8009150234* 8009120335* 8009120557*	50-348 8 50-348 8 Ga999 Ga999 Ga999	HAWKINB.F.C HAWLEY,B.C. HAWTHORNE.B HAWTHORNE.B HAYEB.O.W.	8009290107* 8009030530* 8009090238 8009090238 8009110324*	50-546 Q 50-27 R 50-445 P 50-445 P
GRIER, B. H	8009240330	50-354 Q	HALL, R E	8009150093*	50-445 Q	HAYES, D. W	8009170221#	50-454 0
GRIER, B. H	8009240332	50-443 Q	HALL, R E	8009100950	NUREQ	HAYES, D. W	8009110769#	50-544 4
GRIER, B. H	8009240335	50-485 Q	HALL, R E	8009090569	50-293 F	HAYES, D. W	8009290107#	50-546 4
GRIER, B. H	8009240337	50-271 Q	HALL, R E	8009090364	50-171 F	HAYNES, R. C	8009020267#	50-361 0
GRIER, B. H	8009240338	50-27 Q	HALL, R E	8009050533*	50-498 Q	HAYNES, R. F	8009050409	REB
ORIER, B H ORIER, B, H ORIER, B H ORIER, B H ORIER, B H	8009240342 8009240345 8009240346 8009240349 8009240353	50-412	HALL,R E HALL,R E HALL,R E HALL,R E HALL,R E	8009170387* 8009100279* 8009230398* 8009250405* 8009190340*	50-482	HAYNEB, J. O HAZELRIGO, B HAZELTON, W B. HAZLE, A J HAZLE, A	8009260508 8009020455* 8009120337 8009190874 8009190877*	50-204 B 50-275 B NUREO Btate Frog Btate Frog
GRIER. 8 H GRIER. 8 H GRIER, 8 H. GRIMES, 8 K GRIMES, 8 K	8007240355 8007240341 8007240362 8007160570 8007070782	50-272 Q 50-244 Q 50-307 Q 50-287 Q 50-546 F	HALLIR E HALLIR E. HALLIR E HALLIR E.	8009300102* 8009150362* 8009020032 8009020053 8009090362	50-498 Q 50-458 Q 50-293 E 50-171 E 50-171 F	HEARN, P, C HEGNER, J D HEIDER, L H HEIDER, L H HEIDER, L H	8009170351* 8009110050* 8009230100 8009020021 8009080375	50-289 T 50-334 0 50-271 0 50-29 P 50-271 F
GRIMES, B K GROCE, R H GROHOL, M B GROSEHAN, K	8009120592 8009090468 8009100425 8009100219* 8009020505	50-349 F 50-309 R 50-309 P GA999 FOIA	HALL.R E HALL.R E. HALL.R E HALLER,N HALLER,N M	8009090564 8009090424 8009220395 8009230232* 8009240134*	50-285 F 50-171 F TOPREP FOIA 50-313 8	HEIDER, L H HEIDER, L H HEIDEL, C, M. HEINAMOY, V A HEINZ, J	8007120401 8007180451 8007240507# 8007030503# 8007150448#	50-271 # 50-271 # 50-341 A 50-302 B COMMIBBION
Groshan, H	8007020402	50-347 0	MALLICAN.T J	8009180394	50-387 0	HEIBHMAN, RF.	8009290020*	50-046 0
Oroshan, H	8007070420	50-347 0	MALMAN,E L	8009030255*	8ECY	HEIBHMAN, RF	8009260418	50-409 0
Grosshan, H	8007170175	50-155 0	MAMILTON,W P	8009260421*	50-289 T	HEIBHMAN, RF	8009030208	50-255 0
Grosshan, H	8007230030	50-155 0	MANAUER,B,M	8009250453*	FOIA	HEIBHMAN, RF	8009100132	50-255 0
Orosshan, H	8007300033	50-155 0	MANAUER,B,M	8009050126*	FOIA	HEIBHMAN, RF	8009100143	50-10 0
OROBBHAN, H	8009300036*	50-155 Q	HANCOCK, J. A	8009020197	50-302 B	HEISHMAN, R F.	8007020117	50-358 A
OROBBHAN, H	8009300331	50-367 Q	HANCOCK, J. A	8009240184*	50-302 Q	HEISHMAN, R F.	8009100154	50-331 Q
OROTENHUIB, M	8009190607*	50-334 P	HANCOCK, J. A	8009030200	50-302 R	HEISHMAN, R F	8009150022	50-373 Q
OROTENHUIB, M	8009120049	50-250 P	HANCOCK, J. A	8009030475	50-302 B	HEISHMAN, R F	8009160610	50-305 Q
OROTENHUIB, M	8009190908	50-250 P	HANCOCK, J. A	8009030497	50-302 S	HEISHMAN, R F	8009020183	50-310 P
GUAQUIL, L	8009120395	50-322 A	HANCOCK, J A	8007030600	50-302 8	HEIBHMAN, R F	8009160509	50-35B q
GUHIN, H A	8009090434*	XPORTLIC	HANCOCK, J A	8007050265	50-302 8	HEIBHMAN, R F	8009260304	50-316 q
GUHIN, H A	8009090630*	XPORTLIC	HANCOCK, J, A	8007110337	50-302 8	HEIBHMAN, R F	8009290109	50-255 q
GUILBERT, D E	8009180185*	QA999	HANCOCK, J A	8007150280	50-302 8	HEIBHMAN, R F	8009300238	50-346 q
QUILBERT, D E,	8009180177*	QA999	HANCOCK, D	8007300027	50-466 0	HEIBHMAN, R F	8009260263	50-282 q
GULBRANSEN, E A GULDEMOND, W G GURUNATHAN, S GURUNATHAN, S. GURUNATHAN, P	8009040412 8009290015* 8009120324* 8009120331* 8009240065	50-320 F 50-266 Q 50-275 B 50-275 S CONTRACT	HANCOCK, D HANCOCK, J, A HANNON, J N HANSEN, L E HANSEN, L E	8009300027 8009290290 8009300039 8009260184 8009260105	50-466 0 50-302 8 TOPREP 71-9022 71-6581	HEISHMAN, R.F. HEISHMAN, R.F HEISHMAN, R.F HEISHMAN, R.F HEISHMAN, R.F	8007250365 8007260375 8007270425 8007030115 8007300217	50-315 9 50-10 9 50-275 9 50-255 9
CUSTAVE, R. P	8009120013	CONTRACT	HANSON, D. J	8007260067	REB	HEISHMAN, R. F.	8009110727	50-255 Q
CUTHANN, P.	8009150143*	CONTRACT	HARDIN, A. K	8007240284*	50-324 G	HEISHMAN, R. F.	8009250338	50-275 Q
CUTHE IN. E. E	8009190123*	40-2061	HARDI, A. R	8007300041*	50-416 G	HEISHMAN, R. F.	8009290440	50-315 Q
HAASB, W. P	8008210180	50-261 P	HARNON, D. W	8007330777	XPORTLIC	HEISTAND, O. S.	8009020041	50-409 Q
HAASB, W. P	8009190157	TOPREP	HARMON, D. W	8007070657	XPORTLIC	HEISTAND, Q. S	8009020041	50-409 Q

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
EISTAND, O S ELVER, J. K ELVER, J. K ELVER, J. K ELVICK, C	8009300008 8009170011* 8009050216* 8009300224* 8009230016	50-407 0 50-289 H 50-255 G 50-255 G 50-142 Q	A L. GAIH A C. GAIH	8008280493* 8008280488 8009030133* 8009030126 8009110732	50-254 G 50-254 G 50-295 G 50-295 G 50-275 G 50-254 G	HOVEY, O K HOVEY, O K HOVEY, O K	8007020075 8009020241 8009030372 80090303529 8009030349	50-320 P 50-320 G 50-320 P 50-320 P 50-320 S
Endrie. J H Endrie. J H Endrie. J. H Endrie. J. M Endrie. J K	8009150032* 8009150035* 8009150039* 8009150047* 8009150054*	COMMISSION COMMISSION 50-271 U COMMISSION COMMISSION	HIND, J A HIND, J A HINES, E HINES, E HINES, E	8009150442 8009250419 8009180016 8009180029 8009090417	50~305 G 70~34 50~341 G 50~341 G 50~341 G	HOVEY, O K HOVEY, O K HOVEY, O K HOVEY, O K	8007030473 8009140384 8007070502 8007070554 6007140382	50-320 P 50-320 P 50-320 H 50-320 H 50-320 P
ENDRIE, J. H REXORIE, J. H ENDRIE, J. K HENDRIE, J. H HENDRIE, J. H	8009150030* 8009150056* 8009150061* 8009150074* 8009150090*	COMMISSION COMMISSION 50-293 U COMMISSION	HINEB, E HIRSCH, D. HIRSCH, D HJELMFELT, D C HJELMFELT, D C	8009250446 8009040203 8009240466 8009260662 8009260662	50-341 0 50-142 0 50-142 0 50-348 M 50-348 M	HONEA'O K HONEA'O K HONEA'O K HONEA'O K	8009140395 8009170334 8009180415 8009120402 8009120450	50-320 P 50-320 G 50-320 S 50-320 S 50-320 S
HENDRIE, J. H HENDRIE, J. H HENDRIE, J. H HENDRIE, J. K HENDRIE, J. K	8009150026* 8009190707 8009110417 8009090601 8009020202	COMMISSION PR COMMISSION COMMISSION COMMISSION	HOBBB: F T HOBBB: F T. HDCKER, H M HODDER, M H HODDER, M H	8009240086# 8009190638# 8009090971 8009190046 8009150099#	F01A F01A 50-320 H 50-250 G 50-250 G	HOVEY, O K HOVEY, O K HOVEY, O K	8009120454 8009150432 8009150554 8009160381 8009170314	50-320 P 50-320 P 50-320 P 50-320 P 50-320 P
HENDRIE, J. H HENDRIE, J. H HENDRIE, J. H HENDRIE, J. H HENDRIE, J. K	8007020204* 8007020206* 8007020207* 8007020210* 8007020212*	COMMISSION COMMISSION COMMISSION	HOFFMAN, D P HOFFMAN, D P HOFFMAN, D. P HOFFMAN, D. P	8009110820* 8009030117* 8008130378* 8009110730* 8009020070	50-155 Q 90-255 Q 40-299 50-255 Q 50-155 B	HOVEY, O K HOVEY, O K HOVEY, O K HOVEY, O K	6009170377 8009180404 8009220277 8009190490 6009220129	50-320 P 50-320 6 50-320 P 50-320 R 50-320 P
HENDRIX, G W HENDRIX, G W HENDRIE, J, K HENDRIE, J, K HENDRIE, J W	8007080442 8007150188 8007150020 8007110525 8007100597	71-4888 71-112 50-201 U COMMISSION 50-443 0	HOFFMAN, D.P. HOFFMAN, D.P. HOFFMAN, D.P. HOFFMAN, D.P.	8007020262 8007020265 8007030544 8007030583 8007030624	50-255 0 50-155 8 50-155 8 50-255 8 50-256 0	HOVEY, O K HOVEY, O K HOWARD, E K HOWARD, E K HOWARD, E, K	8009220294 8009200389 8009150050* 8009150087* 8009150063*	50-320 P 50-320 P 50-445 Q 50-445 Q 50-445 Q
HENDRIE, J M HENRY, J J HENRY, L O HENRY, L O	8009240459 8009050337 8009040374 8009140338 8009150027	50-389 Q PRM 50-57 P 50-57 I 70-143	HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, D. P. KOFFMAN, D. P. HOFFMAN, D. P.	8009100574 8009180102 8009030430 8009030490 8009040423	50~155 P 50-155 G 50-255 P 50-155 P 50-155 P	HOWARD, E H HOWARD, E H HOWARD, J E HOWARD, E M	8009150068* 8009150113* 8009150270 8009150284 8009300190	50-445 G 50-445 G 50-293 P 50-293 P 1&E
HENSLEY, X D HENSLEY, K D HERBETH, J O HERBETH, J O HERBETH, J O	8009240358 8009300475 8009030464 8009080240 8009030472	70-143 70-143 50-287 V 50-289 V 50-289 P	HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P	8007080406 8007080418 8007080432 8007100573 8007260125	50-255 8 50-255 8 50-255 8 50-155 P 50-155 0	HOWE, PW HOWE, PW HOWELL, BX HOWELL, BX	8009250351* 8009100241 8009180450 8009260075 8009120536*	50-400 G 50-400 G 50-400 G REB 70-343
HERBEIN, J O HERBEIN, J O HERBEIN, J O HERBEIN, J O HERBEIN, J O	8007020008 8007020013 8007030481 8007080367 8007110316	50-287 P 50-287 G 50-287 P 50-287 P 50-287 R	HOFFMAN, D. P.	8009260146 8009090438 8009090500 8009100321 8009120384	50-155 0 50-155 8 50-329 A 50-155 P 50-255 8	HOWELL, J C HOWELL, J C HOWETT, O H HOWEON, T O HOY, C E	8009110173* 8009170152* 8009230347* 8009180359 8009040115	50~250
HERBEIN, J O HERDTIA R, HERDTIA R HERDTIA R, HERDTIA R.	8009120341 8009240241* 8009240374* 8009240313* 8009120499*	50-287 8 50-367 9 50-324 0 50-413 0 50-250 0	HOFFMAN, D.P. HOFFMAN, D.P. HOFFMAN, D.P. HOFFMAN, D.P.	8009110428 8009160370 8009190098 8009230278 8009220285	50-255 F 50-255 R 50-155 B 50-155 P 50-255 B	HOYLE, J. C HOYLE, J. C HOYLE, J. C HOYLE, J. C	8007030102 8007030105* 8007120328 8007100635* 8007170266*	10CFR 10CFR 50~327 O MISC ACRS
HERDT, A R HERDT, A R. HERDT, A HERDT, A R. HERDT, A R	8007030140* 8007150377* 8007170607* 8008280126* 8007050421*	50-395	HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P. HOFFMAN, D P	8009230612 8009300231 8009230436 8009230458 8009290364	50-255 B 50-155 P 50-255 P 50-255 P 50-255 P	HOYLE, J C, HOYLE, J C HOYLE, J C HOYLE, A	8009100920* 8009150440 8009160079 8009160083 8009120104	ACRB ACRB ACRB 50-327 D CONTRACT
HERDY, A.R. HERDT, A.R. HERDT, A.R. HERDT, A.R. HERDT, A.R.	8009240320* 8009240421* 8009110198* 8009180162* 8009240071*	50-413	HOFFMAN, D HOFFMAN, D HOFFMAN, D HOFFMAN, D HOFMAN, R	8007300484 8007300487* 8007300472 8007300477* 8007120607	50-255 B 50-255 B 50-255 B 50-255 S XPORTLIC	HOYLE, J. C HOYLE, J. C HOYLE, J. C HOYLE, J. C HOYLE, J. C.	8009030650* 8009160074 8009110593 8009090400 8009090411	ACRS ACRS XPORTLIC 27-39 50-376 0
HERDT, A R HEREFORD, J. M HERHANN, R. HERHANN, R.	8007170163* 8007070570* 8007170547* 8007240057* 8007110372	50-328 Q 50-327 8 50-327 B 50-206 P NURE9	HOLAN, J HOLDEN, R B HOLDEN, R B. HOLIFIELD, C HOLLAND, F	8007230431* 8007080231 8007300547 8007240117* 8007030516*	TOPREP 50-332 Q 50-201 9 FOIA 50-237 B	HORBARD'H M HORPE'N O HORE'N O HORE'N O	8009090415 8009170195 8009150077* 8009090648* 8009120578	50-364
HERMANN, R. A. HERMANDEZ, Q. HERMANDEZ, V. A. HERMANDEZ, V. A. HERMANDEZ, V. A. HESS, R. J.	8009120337 8009120309* 8009050248* 80092270306* 8009020492	NUREO 50-440 G 50-302 B 50-302 B XPORTLIC	HOLLINGSHORTH ROLMAN J. F. HOLMAN Q. S HOLDDY D J HOLDHKA P.	8009230477 8009120083* 8009110500 8009180497* 8009020515*	50-312 R CONTRACT NUREO 70-33 50-320 H	HUBBARD, R B HUBERHAN, B HUBERHAN, B HUBERHAN, B HUBERHAN, B	8009240546# 8009230176# 8009230190# 8009190386# 8009190464#	59-275 0 FOIA FOIA FOIA FOIA
Hess, R. J Hess, R. J Hess, R. J Hess, R. J Hess, R. J,	8007020477* 8007100074 8007100101* 8007100117* 8007100131*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	HOLOWAY, C F HOOD, D HOOD, D, S HOPPER, D H HORIN, W A	8009110874 8009100005 8009300332 8009050335* 8009110048	RES 50-327 A 50-327 A 50-339 R 50-445 Q	HUBER, S A HUBER, S A HUBER, S A HUBER, S A	8003269087 8003250292 8004110323 8005300697* 8009170262*	Doctet 30 PT9 Docket 30 PT9 50-327 R
Hess, r J Heubner, a t Heuter, l J, Hickle, b J Hicks, h M	8009110406 8009190103 8009100091* 8009230351* 8009150243	XPORTLIC PR 50-97 G 50-285 R REGOD	HORIN: # A	8007110048 8007110781 8007110781 8007170141 8007170141	50-445	HUCK, K J HUDSON, O HUETER, J HUCKILL, H D	8009250313* 8009160446 8009260634* 8009290526* 8009160329	0A999 NUREQ 50-315 Q 50-440 Q 50-289 P
Hiertand, O. B Hiertand, D. B Higgins, J. C. Hilp, C. L. Hillman, R. E	8009090336 8009090336 8009130161* 8009020412* 8009160456	50-409 0 50-409 0 50-322 0 50-296 P NUREO	HORIN, W. A HORIN, W. A HOSKINS, W. HOSHER, C. HOVEY, O. K.	8009230005 8009230005 8009190046 8009240117* 8009020378	50-445	HUKILL, H D HUKILL, H D. HUMMEL, H H HUMMEL, H, H HUMMIGUIT, D H	8009160367 8009220268 8009020479 8009080392 8009180481*	50-287 P 50-289 R NUREO NUREO 50-313 G

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOURY	AUTHOR	ACCESE I ON NUMBER	GUBJECT CATEGORY
HUNNICUTT.D M HUNNICUTT.D M HUNNICUTT.D M HUNNICUTT.D M HUNSTAD.A A	8007140557 8007180147 8007170500 8007170500 8007160282*	50-313 8 50-369 9 50-369 6 50-313 8 50-313 8	IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A	8007240545 8009240548 8009240577 8009240601 8009240649	50-259 P 50-271 P 50-271 P 50-259 P 50-298 P	JOHN, D F JOHNSON, T C JOHNSTON, R 8 JOHNSON, I B JOHNSON, J M	8009300533 8009150412# 8009300185# 8009100672 8009150234#	50-498 M 70-1308 40-0092 ACRB 0A999
HUNSTAD, A A HUNSTAD, A A HUNSTAD, A A HUNTER, V H HUNTER, R S	8007080401# 8007230750# 8007300558# 80071805664 8007020232#	50-282 5 50-282 5 04999 50-315 0	IPPOLITO, T A IRELAND. R N IRELAND. J H IRELAND. J H IRUIN, R F	8007240515 8007070412* 8007180272 8007230443 7906010086*	50-220 F 50-334 P 50-255 J 50-159 J PT9	JOHNBON, P H JOHNBON, D F JOHNBTON, O W JOHNBON, A H JOHNBON, W D	009920240* 8009160223* 8009020251* 8009030199* 8009180481*	50-097 Q 50-244 Q 50-044 Q 50-389 Q 50-310 Q
HUNTER.V H HUNTER.R S HUNTER.R S HUNTER.R S HUNTER.R S	8009180085* 8009290444* 8009250373* 8009160195 8009260212	90799 50-315 0 50-315 0 50-315 0	IRWIN, R F IRWIN, R F ISLEY, T ISLEY, T	8001020083* 8001020073* 8007020061* 8007120356* 8007230680*	PT9 PT9 50-346 8 50-346 S 50-346 S	0 A MOENHOL JOHNBON, U JOHNBON, L JOHNBON, J M JOHNBON, W P	8009120479# 8009160557 8009090572 8009110356 8009090431	50-341 0 50-313 8 50-367 0 FOIA 50-309 9
HUNTER, R S HUNTER, M HUNTER, R HUNTER, R S HUNTER, H	8009170350 8009170168 8009170168 8009240369 8009300542*	50-315 V 50-445 M 50-445 M 90-315 P 50-498 M	ITSCHNER,L C ITSCHNER,W F JABLON,R A JABLON,R A JABLON,R A	8007070024* 8007260414* 800722023* 8007220223* 8007220222*	50-287 H 50-287 T 50-387 M 50-387 M	ЈОНИВОМ, Ј Е ЈОНИВОМ, А В ЈОНИВОМ, И В ЈОНИВОМ, И В	8009260233# 8009300197# 8009090487# 8009180149 8009190590	50-267 R 50-243 R 50-295 Q 50-368 B 50-369 B
HUNTER, K HUTTON, P H HUTTON, J C HYDE, K C IMAN, R L	6009300533 8009110421 8009020351* 8009070519* 8009020349	50-478 H RES 50-244 S 90-285 S NUREO	JASLON, R A JASLON, R A JASLON, R A JASLON, R A JASLON, R A	8009220221 8009220222* 8009170162 8009170091 8009170162	50-389 M 50-389 M 50-389 M 50-335 M 50-389 M	JOHNSON, W D JOHNSON, C JOHNSON, C JOHNSON, J H JOHNSON, J H	8009190600 8009170194# 8009170225* 8009120368 8009120374*	50-313 8 50-466 Q 50-466 Q PR PR
INGRAM, F INGRAM, F INGRAM, F INGRAM, H D. INGRAM, F	8009220033 8009220078 8009230143 8009100097* 8009090022	50-339 H 50-352 H 50-289 H State Prog 50-289 H	Jablon, R A Jablon, R A Jackbon, H H Jackbon, J F Jackbon, T J	8009190091 8009300013 8009100107* 8009110503 8009190056*	50-335 M 50-445 M COMMIESION NUREO 50-352 Q	JONES, M. C JOHNBON, M. P JOHNBON, M. P JOHNBRUD, J. H JOHNBRUD, J. H	8009120379* 8009170343 8009240644 8009240238* 8009020106	FR 50-304 P 50-287 Q CUNTRACT 50 285 Q
IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A	8007020144 8007040125 8007040307 8007040532 8007050450	50-331 P 50-263 P 50-324 P 50-271 P 50-273 P	JACKSON.R E JACOBS.A JACOBS.B JACOBS.A JACOBS.A	8009190637 8009150176 8009050280 8009230751 8009300259	50-133 P CONTRACT GA999 CONTRACT CONTRACT	JONES, D W JONES, J K JONES, J K	8009120133* 6007020358 6007030216* 8009110475* 8009300602	70-143 NUREQ CONTRACY 50-454 G 71-6144
IPPOLITO, T A	809170255 909170389 909040176 909150500 809150503	50-333 P 50-220 P 50-298 P 50-293 P 50-298 P	JAFFE, S JAKEL, E E JAMES, J JAMES, J JAMES, J	8009150003 8009240211 8009260408* 8009100577 8009260432	FD1A 71-9116 40-8180 50-112 R 50-112 R	JONES, J. A. JONES, J. A. JONES, J. L. JONES, J. L.	8009290193* 8009020321 8009110027 8009030449* 8009030474*	50~454
IPPOLITO, T A	8009180206 8009180252 8009190678 8009190697 8009190758	50-331 P 50-237 P 50-324 P 50-259 P 50-220 P	JAMEB, J W JANACEK, R F JANECEK, D L JANECEK, R F	8007300170 8007170411 8007040632 8007080363 8007110562	1&E 50-10 Q 50-237 Q TOPREP 50-237 Q	JONES, J L JONES, W C JONES, W C	8007030479 8007020440 8007250066* 8007070581 8007120431*	50-205 R 50 329 Q 70-1151 30-285 P 30-270 E
IPPOLITO, T A	8007170751 8007230237 8007230243 8007150437 8007070776	50-271 P 50-333 P 50-263 P 50-273 F 50-263 P	JANECEK, R F JANECEK, R F JANECEK, R F JANECEK, R JANECEK, R F	8009160216 8009090013 8009020105 8009030349 8009120404	50-237 P 50-237 G 50-237 P 50-237 P 50-10 P	DONES'N F N'ES'N C NONES'N C NONES'N C	8009120436# 8009180444 8009230349 8009160480# 8009180365	50-267 8 50-265 8 50-265 8 50-267 8 50-324 0
IPPOLITO, T A	8009090777 8009110259 8009110285# 8009110290# 8009120121	50-331 P 50-271 P 50-271 P 50-271 P 50-259 F	JANECEK.R F JANECEK.R F JANECEK.R F JANECEK.R F JANECEK.R F	9009080338 6009110376 6009170421 8009090394 8009250504	50-254 P 50-10 P 50-237 G 50-237 P 50-237 G	JONEB, R C JONEB, R C JONEB, R C JONEB, R C JONEB, W C	8007260320* 8007260322* 8007260388* 8007260400* 8007230721	50~209 T 50~209 T 50~209 T 50~209 T 50~205 R
IPPOLITO, T A	8007070778 8007220013 8007220015 8007220018 8007220078	50-333 P 50-220 Q 50-249 Q 50-259 Q 50-263 Q	JANECEK, R F JANECEK, R F JANECEK, R J JANECEK, R F JANECEK, R F	8009270335 8009220293 8009290334 8009230463 8009250292	50-10 P 50-10 P 50-10 P 50-10 P 50-10 P	JONES, J. L. JONES, J. L. JONES, J. L. JORDAN, W. S JORDAN, W. S	8007230517# 8007260455# 8007230504# 8007230471# 8007080444	50-270 S 50-297 S 50-270 S TOPRIP 70-820
IPPOLITO, T A	8009220104 8009220109 8009220115 8009220120 8009240594	50-333	Janinek. M Janueka. A o Janueka. A o Janueka. A o	8009100094 8009030326* 8009120509* 8009240255* 8009290018*	State Prog 50-305 G 50-155 G 50-282 F 50-266 Q	JORDAN, W B JORDAN, W B JORDAN, W B JORDAN, W B JORDAN, W B	8007220064 8007170002* 8007250467* 8007110802 8007110802	70 020 70-820 TDPRLP 50-155 Q 50-155 Q
IPPOLITO, T A	8009180531 8009180554 8009190001 8009190047 8009190084	50-293 P 30-333 P 50-331 P 50-324 P 50-263 P	JAPE, F JAPE, F JARDINE, E F JARDINE, E F JARDD, L	8009100816* 8009300640* 8009020525* 8009020522 8009300670	50-269 Q 50-269 Q 71-385 71-385 XPORTLIC	JORDAN, W 8 JORGENSEN, B L JORGENSEN, B L JOY, J M, JOYNER, J, H	8007110365 8007050216* 8007300224* 8007070268* 8007110281*	50-155 0 50-255 0 50-255 0 50-266 8 70-135
IPPOLITO, T A	8007220153 8007180541 8007180547 8007180501 8007180524	50-293 P 50-293 P 50-220 P 50-237 P 50-237 P	JENKINS.OR JENKINS.OR JENKINS.OR JENNINOS.PC	8007220184* 8007040330* 8007120271* 8007220278* 8007020091*	50-335 Q 50-327 Q 50-370 Q 50-304 S 50-206 P	JOYNER. J JOYNER. J H JOYNER. J H JOYNER. J H	8009110272* 8009180497* 8009160186* 8009120235* 8009120235*	70-137 70-33 70-135 70-371 70-135
IPPOLITO, T A	6009170166 6009240591 6009240641 6009240644	50-237 P 50-293 P 50-220 P 50-293 P 50-298 P	JEPPESEN, D JERMAN, P C JOHN, D F, JOHN, D F, JOHN, D F	8007260072 8007270072* 8007170188 8007170188 8007170188	NUREO FOIA 50-445 M 50-445 M 50-445 M	JOYNER, L L JULIAN, C A JURGENBEN, R W KAHLE, J B KAHLE, J B	8007260411# 8007040417# 8007170447 8007080238# 8007110150#	50-209 T 50-10A Q TOPREP 50-332 Q 70-1113
IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A	8009250272 8009260324 8009260331+	50-263 F 50-259 F 50-276 Р 90-296 Р 50-296 Р	JOHN, DF JOHN, DF JOHN, DF JOHN, DF	8009300542* 8009300542* 8009300542* 8009300533 8009300533	50-498 M 50-498 M 50-498 M 50-498 M 50-498 M	KAHLE, J II KAHLE, J B KAHLE, J, B KAHLE, J, B KALIMULLAH	8009050184* 8009120227* 8009100297* 8009150605*	70-143 70-143 70-1113 70-1113 RUREQ

	While Cyclodica	ROHTUA	NUMBER CA	JØJECT NTEGORY	AUTHOR		SUBJECT CATEGGRY
AUTHOR KALIPLANA KALIPLANAKISIN KALIPLANAKISIN KALIPLANAKISIN	0007000 172	RENNALU D RENNALU D RENNALU D RENNALU U RENNALU U	8009120227* 70- 80092504'15 70- 8009100297* 70- 8009100290 70- 8009120124 70	-143 -143 -1113 -1113 -1143	KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8009120044 5 8009120046 5 8009120050 5	00-440 Q 00-409 Q 00-341 Q 00-331 Q 00-441 Q
KALIVIANAKIO, N KALIVIANAKIO, N KALIVIANAKIO, N	0007080422 70 274 11 0007120 971 70 274 11 0007160272 70 274 8 000712025 70 274 R 000712025 70 278 11	KCHNA, H B KLNKA, H B KLNKA, H B KCHNA, H B	6009170603 90 6009100790 70 6009110110 50 6009110121 50	-1113 -259	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8009120057 5 8009120060 5 8009170407 5 8009170408 5	50-367
YALIVIANAXIIII II KALKHARFI D. N KAMPERENI G. KAN-B KAMEN	000928078111 RDRI 0 000927804441 70 289 31 00098094074 70 285 11 0009110787 70 3112 A 0009190010 70 70 70 70	MI (PIA. D) MEAPIACU () MENNACU () MENNACU () MENNACU ()	0009110126 76 0009230204 56 0009250062 76 0009170145 56	0-1151 0-1113 0-321	KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	8009170415 8009170418 8009170419 8009170426	50-440 Q 50-195 Q 50-327 Q 50-407 Q 50-341 Q
KANTER, H. A. KANTER, H. A. KANTOR, F. KAPLAN, A. L. KAPLAN, A. L.	1009090507# COMMT08111R COM9040274# 50 175 9 COM90910166 70 1133 1133 COM909111 71 113 1133 1	KERRA, U. R. KERREDY, II. T. KERREDY, D. B. KERRECK, J. R. KERRECK, J. R.	1009230281# F 1009120487 5 1009110020 X 1009110028 X	0-280	KEPPLER. J G	8009170428 8009170430 8009170432 8009170433 8009170435	50-331
KAPLANI B N KAPLANI B N KAPLANI A L KAPLANI B N	0000040040 50 244 F 0000110161 70 111 f 000050414 71 9010 000020000 50 244 f 0000150000 70 141 f	19 19 19 19 19 19 19 19 19 19 19 19 19 1	7904170409 7904170412 7904120000 7906290524 1	179 179 179 179 179	KEPPLER.J G KEPPLER.J G KEPPLER.J G KEPPLER.J G KEPPLER.J G KEPPLER.J G	8007170440 8007170440 8007180520 8007180524 8007180551	50-483 0 50-266 0 50-305 0 50-10 0
KAPLAN, A. L. KAPLAN, D. A. KAPO, P. B. KAPPLE, A. H. KATO, H. Y.	1009.1000.41	KEPPER, J. O. KEPPEER, J. O. KEPPEER, J. O. KEPPEER, J. O. KEPPEER, J. O.	0009190166 0009290113# 0009290113# 0009290105#	FOIA #0-284 0 #01A #01A	KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	8009230284 8009230288 8009230295 8009230300 8009230302	50-315 F 50-10 F 50-155 F 50-409 F
KATTENBÁCHER: F KAUTHAN: N C KAY: J A KAY: J A KAY: J A	00091200666 H10 0009030664 50 29 P 0009100191 50 29 P 0009100142 50 29 P	REPPETA-J G REPPETA-J G REPPETA-J G REPPETA-J G	1007040917 1007040531 1007040536 0007040340 1007070020	50-237 0 50-350 0 50-440 0 50-409 0 50-409 0	KEPPLER.J G KEPPLER.J G KEPPLER.J G	8009230305 8009230309 8009230314 8009230318	50-263 F 50-346 F 50-266 F 50-305 F
KAY, JA KEARHEY, J. J KEATEN, R. H KEATEN, R. H KEATEN, R. H	######################################	0 6.11319938 0 6.113199138 0 6.1131938 0 6.1131938 9 6.3334938	1007070027 1007070042 11007070043 11007070047 11007070000	50-341 0 50-331 0 50-461 0 50-367 0 50-263 0	KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	8009160430 8009180040 8009230057 8009230058	50-255 P 50-373 G 50-305 G 50-346 G
REATEN A W REAY.N B REE.E J REEBER, R FEIKKE, D	80094802044	КРББ 1 19 7 0 В Развита В Развита В Развита В Развита С	007240017 007040017 007020132 0007100211 0007030508	50 346	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8009230063 8009230066 8009230068 8009230071	50-315 Q 50-263 Q 50-440 Q 50-329 Q
REIHIO, R RELLEY, J L REILEY, J D REILEY, H D RELLEY, H D	0007130661 50 2/2 B 0007130664 1016 0007130764 1016 0007130664 1016	KENPLER, J C REPUTER, J C REPUTER, J C REPUTER, J C REPUTER, J C	11009040465 11009290011 11009240239 11009030190 11109030192	50 461 f 50-266 b 50-202 f 50-315 d 50-350 0	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8009230073 8009230074 8009230079 8009230081 8009230082	50-461 Q 50-367 Q 50-546 Q 50-359 Q
RELLEY, W D RELLEY, W D RELLEY, W D RELLEY, W H RELLER, O R, RELLOGO, R d	### 199 19	81791 EA. J 0 819] CHI, J 0 81091 (มี. J 0 81 934 (นี. J 0 81871 (R. J 0	80890'101'95 800'90301'96 800'90301'98 800'9030202 800'90'30204	50-440	KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	8009230067 8009230089 8009230093 8009230094	50-407 0 50-265 0 50-155 0 50-10 0
KELLOGO, P. J KELLOGO, P. J KELLOGO, P. J KELLOGO, P. J	1009246211#	REPPLER J 0 RIPPLER J 0 RIPPLER J 0 RIPPLER J 0	0007030207 000707070 000707070 000707070 000707070	50-367 0 50-263 0 50-548 0 50-348 0 50-463 0	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8007230483 8007230484 8007230487 8007230487	90-35B Q
ALITA'N KLITA'N D KEITA'N T KEITOOO'N N	10004 40 00 145 - 40 745 11 10004 40 240 + 1 11 tV	0 t. 13 1999 0 t. 13 1993 0 t. 13 1994 18 0 t. 13 1994 18	0004030831 0004030884 0004030884 0004030881	50-246 0 50-305 0 50-327 0 50 155 0 50-10 0	KEPPLER, J O KEPPLER, A W KEPPLER, J O KEPPLER, J O KEPPLER, J O	90090591 9009250499 9009250490 9009250408	* 50-272 5 50-373 8 50-358 5 50-255 P
FELLY, J A FELLY, J A FELLY, J A FELLY, J A	00091701114 50 1113 0 00091701174 50 113 0 00091701100 50 001 0 00091707014* 50 205 0	0 t.#1#91# 0 t.#1#91 0 t.#1#91	0009150401 0009260410 0009150484 0009150453 0009150459	50~10 P 70~327 G 70~135 G 50~407 G 50~331 G	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	800925047 800924009 800924009 800924009	50-358 d 50-358 d 50-440 d 6 50-155 d
KEHPER, J 8 KEHPER, J 8 KEHPER, J 8	0 454 6 404	0 A. API 144 18 4 A. API 444 18 5 A. API 444 18 4 A. API 144 18 4 A. API 144 18	0009150466 0009150469 0009150473 0009150479	50-263 0 50-440 0 50-350 0 50-341 0 50-461 0	KEPPLER. J O KEPPLER. J O KEPPLER. J O KEPPLER. J G	800724009 800724010 800724010 800724010 800724010	3 50-331 0 3 50-461 0 4 50-461 0
Kenka, H B Kenka, H B Kenka, H B Kenka, H D Kenka, H D	HOOVI 1018/4 70 270 G HOOVI 10190* 70 1113 HOOVI 1018A* 70 1113 HOOVI 2018A* 70 143	REPPERED O REPPERED O REPPERED O	8009150403 8009150485 8009150495 8009230376 8009230377	90-967 Q 50-10 Q 70-0 70-94	KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	800924011 800924011 800924011 80092401	50-263 0 15 50-387 0 16 50-546 0 18 50-346 0
repraso B Repraso B Xenraso B Xenraso B	1009/1010 50 99 0 1009/1010	6 F 18 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	0900120090 0007230300 0007230300 0007120032	50-152 G 50-155 G	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	80092401: 80092401: 80092401 80092401 80092401	22 50-256 a 24 50-305 a 25 50-327 a
KENIA, 44 B KENIA, 44 B KENIA, 44 B	800903011B 70 143 800905010A* 70 143 800914023A* 70 143	Krupi cu o Krupi cu o	0009120030 8009120030		View press		

AUTHOR	ACCESSION SUBJECT NUMBER CATEODRY	ROHTUA	ACCEBSION NUMBER	SUBJECT CATEOGRY	AUTHOR	ACCESS 1 OF NUMBER		ÆGT FORY
KEPPLER, J O KEPPLER, J O KERR, W KERR, O W KERR, O W	8009280454 50-295 q 8009300215 50-454 q 8009190377* FDIA 8009080452* State Prog 8009080457 State Prog	G L.STTONN B L.STTONN B L.STTONN B L.STTONN B L.STTONN	8009170359 8009170359 8009170369* 8009300009 8009300002	50-445 M 50-445 M 50-445 M 50-395 Q 50-395 N	LANTON, M D LANTON, R R LAZARUS, W J LAZO, R M LAZO, R M	8009300520 8009330591 8009390600 8009080514 8009110807	1* 50-30 50-30 50-52)7 P 17 8
KERR.O W KERR.O W KERR.O W KERR.U	8009050191 State Prog 8009150457 State Prog 8009110578 27-10 8009260204 State Prog 8009220395 TOPREF	KNOTTS.JB XNOTTS.JB KNOUFF.O KO.H KOCH.LJ	8009300009 8009300009 8009180391 8009080299* 8009250208*	50-375 Q 50-375 Q 50-320 P 50-348 P 50-461 Q	LAZO,R M LAZO,R M LAZO,R M LEACH,L J LEACIEUBK1.J S	8009180542 8009230625 8009250034 8009160450 8009230536	50-20 50-32 NUREO	3 6
KERR.O W KERR IOAN, J KERR IOAN, J KERR IOAN, J	800923054555 1&E 8009020335 50-528 A 8009120551 50-528 A 8009110725 50-311 P 8009180306 50-272 V	KOCH, L J KOCH, L J KOCH, L J KOCH, L J KOCH, L J	8007220130 8007080173 8007080202 8007090254 8007080347	50-461 A 50-461 A 50-461 C 50-461 K 50-461 H	LEAR, O LEBO, C D LEBO C. D LEDBETTER, L LEE, 8	8009020173 8009120665 8009180159 8009120075 8009260465	SO-DRY CONTRA CONTRA * CONTRA	9 A ACT ACT
KERRIGAN, J KERRIGAN, J D KERRIGAN, J D KESSLER, Q KETCHEN, E Q	8009120508 50-528 A 8009180534 50-528 A 8009160595 50-528 A 9009240063# F0IA 8009100103 50-369 H	KOCH.L J KOCHER.C R KOESTER.G L KOESTER.G L KOESTER.G L	8007270337 8007170083 8007150381* 8007150014 8007270218	50-461 8 50-361 0 50-482 0 50-482 0 50-482 8	LEE,E W K LEE,E W K LEE,O R LEE,O R	8007100126 8009150203 8009170169 8009170164 8009100841	* 50-440 * 50-329 * 50-461 * 50-267	9 0
KETCHEN, E O KETCHEN, E O KETCHEN, E O KETCHEN, E G KETNER, H H	80097090241 50-369 0 80097120252 50-369 0 80097160343 50-369 0 80097160360 50-275 0 8009020273 50-289 0	KOESTER,O L KOESTEL,A KOESTEL,A KOFFLER,H KOHLER,J E	8009300612* 8009020161 8009150599 8009100651* 8009290436*	50-482 Q NUREQ 70-312 50-295 Q	LEE, V. H LEE, V. H LEFEBRE, N. Y LEFEBRE, N. T LEHR, J. C	8007070672# 8007070664# 8007050405 8007100412 8007300340#	50-275 50-275 REB REB	Ţ
KETNER, M H KETZLACH, N KETZLACH, N KEY, H J KI£FER, N	8009170291 50-289 0 8009090124 70-27 8009240339* 70-33 8009180021* 50-295 0 8009230746 50-349 H	KOLESAR, D C KOLTAY, P S KOLTAY, P S KONKLIN, J E KOOI, M	8007260478* 8007070066* 8007250302* 8007110675* 8007220271*	TOPREP 50-273 Q 50-387 Q 50-454 Q 50-245 B	LEMBKE, B LEMPOES, T E LEMPOES, T E LEMPOES, T. E LEMPOES, T E	8007120565* 8007220158 8007090668 8007120263 8007160508	40~134: 50~220 50~220 50~220	1 0 0
KIMBALL, T L KIMSEL, J J KING, L J KING, L J KINNEMAN, J D	8007300004 50-367 0 9007300121* CONTRACT 8007020080> 50-320 P 8007030534* 50-320 P 8007250273 40-4348	KOPACZ, J KORCHYNBKY, H KORCHYNBKY, M KOTTAN, J J KOUTB, H J C	8009150124*	50-254 8 50-237 8 50-237 8 50-219 9	LEMPOES, T E.	8009160513 8009090281 8009300622 8009090264	20-550 20-550 20-550 20-550 20-550	0000
KINNEMAN, J D KINNEMAN, J D KINNEMAN, J D	8009120342* 70-343 8009250334* 70-820 8009150380* 40-8113 8009230142 70-1417 8009240712 70-2354	KRAUSKOPF,K B KROUT,K O KRUMPOS,P J KUOE,T KUOE,T	8007030375* 8007070388* 8007110602	PR 50-320 H 50-282 S XPORTL1C XPORTLIC	LEMPGEB, T E LEMPGEB, T E LEMPGEB, T E LEMPGEB, T J	8009150265 8009150265 8009150297 8009250331 8009300491	20~250 20~250 20~550 20~550	8 R A
KINNEMAN.J D KINNEMAN.J D KINNEMAN.J D KINNEMAN.J D KINNEMAN.J D	8009120201 40-2940 8009130344 40-8113 8009240044 70-710 8009100647* 70-312 8009100634 70-312	KURTZ,R J KUBHNER.W L LACEY,W B LACEY,W B LACEY,W B	8009110421 8009110281* 8009030254* 8009120386*	RE8 70-135 50-334 8 50-334 8	LEPPKE, D M. LEBH, L LEBSOR, L. C LEBSOR, L. C LEBSOR, L. C,	8009150164* 8009300398 8009220211* 8009050260 8009050326	40-6743 NURED 50-299 50-298 50-296	11 6 8
KINNEY, W W KINTNER, L KINTNER, L KINTNER, L KINTNER, L KINTNER, L	8009110294 70-820 8009220043 50-341 1 8009110541 50-364 A 8009230767 50-364 A 8009300051 50-364 A	LACEY, W B LACEY, W B LACEY, W B LACEY, W B	8009160313* 6009160451* 8009160472* 8009160411*	50-334 8 50-334 8 50-334 8 50-334 8	LESSOR, L. C. LESSOR, L. C. LESSOR, L. C. LESSOR, L. C.	8007050252 8007050187 8007050284 8007050177 8007140262	50-278 50-278 50-278 50-278 50-278	8 8 8 R
KINTNER, L KIPER, K L KIPER, K L KIRK, H F KIRK, H F	8009300288 50-364 A 8009110633 50-410 A 800924033 50-410 A 8009240648 70-371 8009170366 50-201 q	LACEY, W S LACEY, W S LACEY, W S LAFLEUR. J D LAFLEUR. J O	8007240458# 5 8007240461# 5 8007270257# 5 8007170126 X	60-334 B -0-334 B -0-334 B -0-314 B -0-8111C	LESSY, R P LESSY, R P LEVINE, B LEVINE, H R LEVIN, H. A,	8009250002 8009270034 8009090779 8009020112* 8009110746	27 - 39 50 - 463 6ECY 50 - 445 50 - 10	0 11 P
KIRK, O B.	8009080367# 50-327 S 800909090583# 50-327 S 8009120440* 50-327 B 8009160412* 50-327 S 8009230394# 50-327 B	LAGATTA.D P LAGIENSKI.J B LAGIENSKI.J S LAGIENSKI.J B	8009190057* C 8009030522* 5 8009120378* 5 8009230527* 5	ONTRACT 0-317 8 0-317 8 0-318 8 0-318 8	LEVINE, 8 H LEWALD, 0 H, LEWIS, R C LEWIS, R C	8009230601 8009230049 8009230049 8009030270* 8009100811*	50-5 50-471 50-471 50-370 50-269	P 0000
KIRKLAND, M W KIRKLAND, M W KIRKLAND, M W KIRKLAND, M W	B009230734* 50-327 8 B009030454 70-2784 B009120089 70-754 B009110279 70-754 B009080402 NUMEO	LAHTI.O P LAMBREMONT.E N LAMKIN.D E LANCABTER,K F LANCASTER,K F	8009030440* 56 8009220233 RI 8009020161 NI 8009030482* 50	D-295 P	LEWIS, R C. LEWIS, R C. LEWIS, R C LEWIS, M I	8009030264* 8009160637* 8009240706* 8009120143 8009150320	50-395 50-290 50-416 REQQD	9
KISTER, H KISTER, H KISTER, H B KISTER, H B KITTRELL, J O	8009120210+ 50-247	LANDSMAN.R M LANDSMAN.R M LANE.J R LANESE.L.C LANGE.S L.	8009190091 50 8009190091 50 8009100654 40 8009260412* 50	0-335 M 0-335 M 0-4472 0-289 T	LEWIS, R. C LEWIS, R. C. LEWIS, R. C. LEWIS, R. C LEWIS, R. C	8009150329 8009300072# 8009240669# 8009150104 8009220265	50-324 50-259 50-261 50-302	9 900
KITTS:R J KLEIMIO:R KLEIMIOROE:W P KLEIMFOROE:H P KLEIMFELDER.J	8009030438* 50-327 P 8009300533 50-272 8 8009240313* 50-413 0 8009240421* 50-518 0 8009230161* CONTRACT	LANPHER.L.C LANPHER.L.C LANPHER.L.C LANPHER.L.C LANPHER.L.C	8009110019 50 8009150404 50 8009150404 50 8009220406 50	8TE MOT -275 Q -275 Q -275 G -275 Q	LEWIS,R C. LEWIS,R C. LEWIS,R.C. LEWIS,R.C LEWIS,R C	8009220337# 8009030188# 8009050547# 8009110102	50-349 50-348	00 000
KLEIN, 8 KLIMBERO, 8. 8 KLINGER, 0 KNAPP, P J KNAPP, P J	8009110395 50-361 H 8009040250 50-54 0 8009190765 50-259 8 8009100044# 50-219 0 8009240205* 50-244 0	LANPHER, L C LARDCCA, J L LARDCCA, J L LAUDIO, B	8009230616 50- 8009110692* 50- 8009120549* 50- 8009250057 50-	-275 Q -275 Q -201 Q -201 P -367 Q	Lewis, R, C Lewis, R, C Lewis, R, C, Lewis, R, C, Lewis, R, C,	8007120045 8007300061	50-260 50-248	0 0
KNAVSMAN, E KNOP, R C KNOP, R C KNOP, R C KNOP, R C	G007220207* 50-289 H G007250352* 50-461 0 G007110661* 50-358 0 G007180061* 50-461 0 G007180240* 50-329 0	LAUTZENHEISER LAUTZENHEISER LAVERTY, J. H LAVERTY, J. H	8009110297 50- 8009110299* 50- 8009110304* 50- 8009180469 50- 8009230747 50-	-279 g -273 g -273 g -142 g -142 g -298 g	LEWIS, R C. LEWIS, R C. LEWIS, R. C. LEWIS, R. C. LEWIS, R. C. LEWIS, R. C.	8007300047 8007030157 8007100801 8007050425 8007140631 8007240652	50-261 50-275 50-269 50-269 50-395 50-261	00000

ROHTUA	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGURY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
LEWIS.R C	8007140161	PR	LUKZ:F J	8009100041#	CONTRACT	MADEDA, T J	8007030133*	50-275 Q
LEWIS.R C	6009300060	50-257 Q	LUKZ:F J	8009190738#	CONTRACT	MADIA, H J	8009150597	NUREO
LEWIS.R C	6009300616	50-269 Q	LUKZ:F J	8009180217#	CONTRACT	MADNI.I K	8009100947	NUREO
LI.C Y	6009150034	50-317 P	LUNDVALL:A E	8009020034	50-317 R	MADSEN, O L	8009150055*	50-445 Q
LIBRIZZI.F P	8009030585	50-311 8	LUNDVALL:A E	8009020020	50-317 P	MADSEN, O L	8009150060*	50-445 Q
LIBRIZZI,F P	8009030413	50-311 B	LUNDVALL, A. E	8007040301	50-317 P	MADGEN, Q L	8007150066*	50-445 0
LIBRIZZI,F P,	8007090447	50-311 B	LUNDVALL, A. E	8007150250	50-317 P	MADSEN, Q L	8009150071*	50-445 0
LIBRIZZI,F P	8009090542	50-311 B	LUNDVALL, A. E	8007230634	50-317 P	MADSEN, Q L	8009150075*	50-445 0
LIBRIZZI,F P	8009090554	50-311 B	LUNDVALL, A. E	8007300383	50-317 F	MADGEN, Q L	8009150116*	50-445 0
LIBRIZZI,F P	8009090593	50-272 B	LUNSFGRD, J. L	8007170036	NUREO	MADGEN, Q L	8009150120*	50-445 0
LIBRIZZE, F P	8007050270	50-272 R	LUSTY, E B	8009160481	NUREO	MADBEN, O L	8007050465	50-267 Q
LIBRIZZE, F P	8007070378	50-272 9	LUTKEN, D C	8009150425	80-416 A	MADBEN, O L	8009100033	50-267 Q
LIBRIZZE, F P	8007070437	50-311 8	LUTKEN, D C	8009150453	80-416 A	MADBEN, O L	8009170168	50-382 Q
LIBRIZZE, F, P	8007070587	50-272 8	LYNCH, M D	8009030121	80-397 A	MADBEN, O L	8009180470	50-313 Q
LIBRIZZE, F P	8007120357	50-272 B	LYONS, M D	8009290314*	GA999	MADBEN, O L	8009040039	50-313 Q
LIBREZZI, FP. LIBREZZI, FP LIBREZZI, FP LIBREZZI, FP LIBREZZI, FP	8009120375 8009120424 8009150264 8009160401 8009160393	50-272 B 50-272 S 50-311 B 50-272 P 50-311 V	MACARTHUR, T C MACARTOR, J. D MACDONALD, C E MACOONALD, C E MACOONALD, C E	8009110208* 8009100446 8009020114 8009020116 8009020119	27-39 PR 71-5450 71-9108 71-9108	MADGEN.O L MADGEN.O L MADGEN.O L MADGEN.O L MADGEN.O L	6009100842 8009300274 8009100835 8009160557 6009170185	50-298
LIBATZZI, F P LIBATZZI, F P LIBATZZI, F P LIBATZZI, F P LIBATZZI, F P	8009230368 8009160478 8009230678 8009250260 8009300513	50-272 V 50-311 E 50-311 E 50-272 P 50-311 P	MACOUNALD, C E MACDUNALO, C E MACDUNALO, C E MACDUUGALL, E A MACDUNALD, C, E	8009020121 8009020125 8009110570 8009250247* 8009080454	71-9094 71-9027 71-5957 50-327 P 71-9039	HADBEN, O L. HADBEN, O L. HAGEE, W HAKEPEACE, J H	8087180147 8087170570 808717060 8087030078* 8087120381*	50-348 8 50-348 8 50-313 6 10CFR 50-247 8
LIBRIZZI F P	8009300503	50-272 P	MACDONALD; C E	8009080457*	71-7039	MAKEPEACE, J M	8009160369*	50-247 8
LIBRIZZI F P	8009300512	50-272 P		8009110595	71-109	MALMROS, M H	8009020251*	50-344 0
LICHTENBERGER	8009150028	70-1100		8009110597*	71-109	MALDNEY, G P	8009110310	90-315 R
LICHTENBERGER	8009110706	70-1100		8009150405	71-394	MALDNEY, G P	8009260094	50-315 0
LIDIAK E O	8009120590	RC8		8009150407	71-370	MALSCH, M O	8009290452	90-344 0
Liebler, O. E	8009230581	TOPREP	MACODNALD, C E MACDONALD, C E MACDONALD, C E MACOGNALO, C E MACDONALD, C E	8009230754	71-9001	MALTEBE, M J	8009020252	50-286 F
Linareb, F	8009090147	REGOD		8009230761*	71-9001	MANAKTALA, M K	8009190401	RES
Linder, F	8009030239	50-409 P		8009090424	71-9076	MANCINI, A J	8009150555	40-8745
Linder, F	8009090008	50-409 G		8009090626*	71-9076	MANDEL, M	8009120611	70-258
Linder, F	8009090010	50-409 Q		8009180153	71-6400	MANGUBI, J	8009180512	70-2478
Linder F	8007030454	50-409 S	MACDONALD, C. E	8009230753	71-35	Hangus I, J	8009110240	70-2478
Linder F	8007260157	50-409 Q	MACOUNALD, C. E	8009230758	71-392	Hann, H M	8009190682*	F01A
Linder F	8007070529	50-409 P	MACDONALD, C. E	8009230766	71-9136	Hanry, M.	8009050291	50-321 V
Linder F	8007160250	50-409 R	MACOUNALD, C. E	8009230785	71-17	Hanry, M	8009030451	50-366 8
Linder F	8007220145	50-409 P	MACDONALD, C. E	8009230787*	71-17	Hanry, M	8009020369	50-366 8
LINDER.F.	8009230648	50-409 8	MACDONALD, C E MACDONALD, C E MACOONALD, C E MACDONALD, C, E MACOONALD, C E	8009190692	71-244	HANRY, M	8009020400	50-344 8
LINDER.F.	8009240343	50-409 P		8009230752	71-138	HANRY, M	8009020436	50-321 8
LINDER.F.	8009260630	50-409 8		8009240127	71-4984	MANRY, M	8009020439	50-321 8
LINEMAR.J.J	8009020193	40-4492		8009240132*	71-4986	MANRY, M	8009030442	50-344 8
LINEMAR.J.J	8009030390	40-299		8009110750	71-9009	MANRY, M	8009020461	50-321 6
LIMENSEROER, O	8009190229	50-466 0	MACDONALD, C E MACDONALD, C E, MACOONALD, C E MACDONALD, C E MACDONALD, C E	8007110759*	71-7009	Manry, M	8009020362	50-344 8
LIMENSEROER, O.	8009250058	50-466 0		8007150542	71-18	Manry, M	8009020404	50-321 8
LIMENSEROER, O. A	8009300456	50-466 0		8007170544	71-6357	Manry, M	8009020419	50-346 8
LIMYILLE, J C	8009150161*	50-322 G		8007170548	71-9039	Manry, M	8009030415	50-321 R
LITFIN, K	8009050359	50-206 H		8007170552	71-6458	Manry, M	8009090469	50-321 8
LTITLEFIELD, J LTTTLE, H. B LTTTLE, M. B LTTTLE, H. LTTTLE, H	8007180475* 8007100161* 8007260271* 8007180470* 8007180470	QA999 50-331	MACDONALD, C, E. MACDONALD, C E. MACODNALD, C, E. MACDONALD, C E. MACDONALD, C E.	9009190555 9009190561 9009250496 9009250498* 9009250500	71-9108 71-9081 71-108 71-108 71-192	MANRY, M MANRY, M MANRY, M. MANRY, M. MANRY, M	8007070428 8007070443 8007070486 8007150295 8007150281	50-366 S 50-321 S 50-366 S 50-321 S 50-321 S
LITTLE, H LITTLE, L. H LITTLE, L. W LLOYD, D B LO. R	8007240052 8007110803 8007110813 8007110574 7710110018	50-206 P 50-510 Q 50-237 Q RES 50-10 P	MACOONALD, C E MACDDNALD, C, E MACDDNALD, C E MACDDNALD, C E MACDDNALD, C E	8007250502* 8007260521 8007270237 8007300122 8007300125*	71-5740 71-198 71-5980	Manry, M Manry, M Manry, M. Manry, M Manry, M	8009150291 8009150331 8009150382 8009150384 8009180199	50-321 8 50-366 8 50-321 8 50-321 8 50-321 R
LOCEFF, F	8009170276*	50-244 P	MACDONALD, C. E	8009300127	71-9034	Manry, M	8009180498	50-386 R
LOCEFF, F	8009170301*	50-244 P	MACDONALD, C E	8009300130*		Hanry, M	8009160285	50-386 S
LOCEFF, F	8009170314*	50-244 P	MACDONALD, C E	8009300135		Hanry, H	8009230316	50-386 S
LOCHSTET, W. A,	8009180522	PR	MACDONALD, C E,	8009300137*		Manry, K	8009290278	50-386 S
LOCHSTET, W. A.	8009160190	50-320 0	MACHON, R D.	8009030611		Kanry, M	8009300497	50-321 S
LOEFFLER, T. LOEHRB, J D LOFY, R A LORO, F J LORO, F, J	0009170268	50-466 U	HACHON, R. D	8007070422	50-293 S	MANRY, M	8007300517	70-143
	8009130468*	50-438 A	MACHON, R. D.	8007070430	50-293 S	MANSER, W C	8007100706*	70-143
	8009040470*	CONTRACT	MACHON, R. D	8007070367	50-293 S	MANSER, W C	8007240631*	70-143
	8009240273	50-324 Q	MACHON, R. D	8007160452	50-293 B	MANSER, W C	8007120126*	70-143
	8009240284*	50-324 Q	MACHON, R. O	8007160267	50-293 R	MANSER, W C	8007120147	70-143
LONO, F J	8007150300	50-438	MACHON-R D	8009160404	50-293 8	Manser, W C	8007070465	70-143
LONO, F J	8007150304*		MACHON-R, D	8009160447	50-293 9	Manser, W C	8007110372	70-143
LOOK, J.	8007150445*		MACHON-R D	8009290284	50-293 9	Marchal, J.	8007170258	XPORTLIC
LOOMIS, J B	8007180443		MACHON-R D	8009230732	50-293 8	Marchal, J.	8007110580	XPORTLIC
LORENZ, R, M	8007080335*		MACHON-R D	8009240462	50-293 8	Marchal, J.	8007110557	XPORTLIC
LORENZ, R. W LOVAAS, A LOVENDALE, P. G LOVENDALE, P. G LOVENBERG, H	8007080336# 8007170717 8007270131# 8007030675# 8007230271#	50-133 R REGOD 50-254 Q 50-263 F FOIA	MACHON: R. D MACHON: R. D MACHON: R. D MACHON: R. D MACHON: R. D	8007240457 8007260470 8007260481 8007260480 8007300500	50-293 8 50-293 8 50-293 8 50-293 8 50-293 R	Marchal, J Maribi, A V Marker, J L Marrack, D Marrack, D	8009110564 8009170329 8009110542 8009090451 8009180418	50-293 F F01A 50-466 Q 50-466 Q
LOWENBERO, H LOWENBERO, H LUBENAU, L O LUCO, J E. LUCO, E	9009230183* 9009230277* 9009110378 9009150424* 9009090779	FOIA FOIA 27-10 50-206 P 50-275 T	MACHON, R. D MACHON, R. D. MACY, J. H HADDEN, H MADDEN, J. J.	8007270283 8007300531 8007080377 8007100652 8007020277		MARRACK.D MARRIOTT,D MAREH.R.J MARSHALL.H H MARSGLAIS,L D	8009250007 8009020217* 8009240284* 8009050423 8009110467	COMMIBSION 50-324 Q 50-327 Q 50-271 Q

AUTHOR	ACCESSION NUMBER	EUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	EUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEFORY
MARSQLAIS, L D	8009260458	50-271 P	MATTHENS.E R	8009240495	50-303 8	MCCLINTOCK, R O	8004240527	Dacket 30
MARTIN, W O	8009100646*	70-371	HATTIA.J C.	8009100030+	50-352 0	MCCLUNG, R H	8009030471	NURED
MARTIN, J B	8009020111*	50-237 P	MAFTIMOE.J J	8009030189	50-312 9	MCCOLL, A. C	8009100435	50-445 p
MARTIN, R D	8009100816*	50-249 Q	HATTIA.J C	8009100884*	50-352 0	MCCOLL, A. C	8009240005	50-445 g
MARTIN, T T	8009100038*	50-293 Q	MATTIA.H J	8009110025*	CONTRACT	MCCOLL, A	8009240008	50-445 g
MARTIN H 0 MARTIN H 0 MARTIN H 0 MARTIN H 0 MARTIN H 0	8009250359* 8009110274* 8009110269* 8009180491* 8009160179	50-201	MATTIA,H,J MATTIA,H J MATTIMOE,J J MATTIMOE,J J MATTIMOE,J J	8009110222* 8009260242* 8009160628 8009050240 8009050339	Contract Contract 50-312 0 50-312 P 50-312 R	MCCOOL, H B MCCOOL, H B MCCOOL, H B MCCOOL, H B	8009160588 8009190701* 8009240047* 8009240024* 8009240021*	50-395 F FOIA FOIA FOIA FOIA
MARTIN.H O HARTIN.T T MARTIN.T J MARTIN.L C MARTIN.H O	8009120150 8009100877* 8009190210* 8009120070 8009160240	70-371 90-293 G 50-354 G CONTRACT 50-220 G	MATTIA: M MATTIA: M J MATTIA: M J MATTIA: M J	8007030085* 8007100407* 8007120662* 8007180150* 8007170170*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MCCOOL. W. B MCCOOL. W. B MCCOOL. W. B MCCOOL. W. B	8007170653* 8007240075* 8007240072* 8007240113* 8007170634*	FOIA FOIA FOIA FOIA FOIA
MARTIN, W O MARTIN, W O MARTIN, L E MARTIN, R D MARTIN, R D	8009160244 8009150347 8009150348* 8009110202* 8009050505	50-334 0 70-135 50-482 0 50-348 0 50-389 0	MATTIA, M J MATTIMDE, J. J MATTIA, M J MATTIMOE, J J	8009250263* 8009150269 8009300121* 8009300097* 8009150540	CONTRACT 50-312 B CONTRACT CONTRACT 50-312 P	McCormack, M, McCorkle, O W McCorkle, O W McCorkle, O, W McCorkle, O, W	8009020217* 8009120644 8009090879 8009090880 8009150049	CDHHISSION 70~734 50~219 P 50~206 P 50~268 P
MARTIN.R D	6007300640=	50-269 @	MATTIA, M J	8009180165*	CONTRACT	MCCORKLE, O W	8007120127	70-2322
MARTIN.T J	8007110472	50-354 @	MATTIA, M J,	8009180327*	CONTRACT	MCCORKLE, O W	8007120132	40-2940
MARTIN.L E	8007100279=	50-445 @	MATTIA, M J	8009300178*	CONTRACT	MCCORKLE, O W	8007120136	70-2478
MARTIN.J E	8007120144=	27-48	MATTIA, J	8009160388	50-312 P	MCCORKLE, O M	8007120137	70-687
MARTIN.R Q	8007110262	70-135	MATTIA, M J	8009180191*	CONTRACT	MCCORKLE, O W	8007120147	70-754
MARTIN, W Q	8009180487	70-32	MATTIA: M J	8009300209*	CONTRACT	MCCORKLE, O H	8009120691	70-9
MARTIN, W Q	8009250354	50-201 0	MAURA: F	8009150025*	50-373 G	MCCORKLE, O W.	8009230731	50-287 F
MARTIN, T J	8009180043*	50-354 8	MAURIN: L V	8009300100	50-382 G	MCCORKLE, O H	8009120157	70-27
MARTIN, T J	8009120218	50-354 8	MAURIN: L V	8009230437	50-382 A	MCCORKLE, O H	8009150392	70-2823
MARTIN, W Q	8009100442	70-371	MAXWELL: J C.	8009230111	ACRB	MCCORKLE, O H	8009120152	70-2786
MARTIN, H G	8009160619	50-277	HAXWELL.OF	6009180459*	50-400 Q	McCorkle, O W.	8007150403	70–13\$
MARTIN, R A	8009160492		HAYER.P.	8009220081*	50-352 H	McCorkle, O W	8007120161	70–25
MARTIN, B E,	8009030627#		HAYER.L O	8008200282	50-282 F	McCorkle, O W	8007120043	70–600
MARTIN, H G,	8009110263		MAYER.L O	8009030381	50-263 F	McCorhack, M	8007120474*	CDMISSIDS
MARTIN, J B	8009160475		MAYER.L O	8008260337	50-263 F	McCorkle, O W	8007120155	70–820
MARTIN, T J	8007070557	50-354 Q	MAYER,L O	8007030524	50-263 F	MCCORKLE, O W	8007260527	50-349 F
MARTINEZ, P R	8007110378	50-204 H	MAYER,L O	8007020055	50-263 F	MCCORKLE, O W,	8007110448	70-344
MARTIN, T J	8007160650	50-354 B	MAYER,L O	8007020072	50-282 F	MCCORKLE, O W	8007150206	50-391 F
MARTIN, D K	8007100575	50-358 Q	MAYER,L.O	8007020007	50-263 F	MCCORKLE, O W,	8007120076	70-143
MARTIN, T T	8007170575	50-271 B	MAYER,L O	8007030380	50-263 8	MCCORMACK, M	8007260452*	50-201 \$
HARTIN, W	8009300433	50-272 E	MAYER, L O	8007070277	50-282 R	MCDAYITT, D. F	8009020255	70-33
MARTIN, R.	8009300334	50-282 P	MAYER, L O	8007070375	50-263 P	MCDEGWN, L. M	8009250363*	50-201 0
MARTIN, M	8009230437	50-351 H	MAYER, L O	8007050348	50-263 R	MCDONALD, M E	8003240038	PT9
MARTIN, T. T	8009300400	50-309 B	MAYER, L, O.	8007080375	50-306 8	MCDONALD, R. J.	8009250497*	Contrac?
MARTORE, J. A	8009110543	50-416 A	MAYER, L O	8007100500	50-282 Q	MCDOWELL-BOYER	8009260550	Res
MARTORE, J A	8009230235	50-416 A	MAYER.L O	8009090282	50-263 R	hcduffie, m a	8009020203	50-400 Q
MARTORE, J A	8009180002	50-416 F	MAYER.L O	8009090354	50-282 8	mcduffie, m a.	8009230067	50-400 Q
MASON, E A	8009230187*	FOIA	MAYER.L O	8009140279	50-282 R	mcduffie, m a.	8009120593	50-400 Q
MASON, E A	8009230201*	FOIA	MAYER.L O	8009170341	50-282 F	mcduffie, m a	8009300591	50-400 Q
MASON, E A	8009230234*	FOIA	MAYER.L O	8009190475	50-263 F	mcduffie, m. a	8009260497	50-400 Q
Magbie.W A Magbie.W A Magbie.W A Magter.W Mathewb.e R	8009170276# 8009170301# 8009170314# 8009030258 8009150464#	50-244 P 50-244 P 50-244 P 40-8745 50-305 G	MAYER, L. O MAYER, L. O MAYER, L. O MAYER, L. O. MAYER, L. O.	8007170481 8007170484 8007230632 8007230738 8007230620	50-282 P 50-263 P 50-263 B 50-282 B 50-282 B	McOarry, J M McOarry, J M McOarry, J M McOarry, J. M McOarry, J M.	8007050086 8007050086 8007260010 8007260010	50-369 0 50-369 0 50-369 0 50-369 0
Matheus, e. r Matheus, e. r Matheus, e. r Matheus, e. r Matheus, e. r	8009030506 8009090355 . 8009260061 8009260681 8009090273	50-305 R 50-305 P 50-305 G 50-305 G 50-305 R	MAYER, L O. MAYER, L O MAYER, L O MAYER, L O MGBREARTY, R A	8009230743 8009230244 8069260826 8009300551 8009190259*	50-282 8 50-262 P 50-263 8 50-282 8 50-387 0	McGarry, J M. McGarry, J M. McGarry, J M. McGarry, J. M McGarry, J. M	8009240273 8009240273 8009240273 8009290028 8009290028	50-364 0 50-364 0 50-364 0 50-488 0
Matheng. e r	8009110378	50-305 P	HCBREARTY, R A.	8007050484*	50-410 G	McDauchy, R W	8009190106*	50-443 0
Matheng. d	8009290370*	50-346 S	MCBREARTY, R	8007100877*	50-269 G	HcDauchy, R. W	8009100030*	50-352 0
Matheng. e r	8009290173	50-305 F	MCCABE, E. C	8007160227*	50-277 G	McDauchy, R W	8009190223*	50-354 G
Matheng. e r	8009300425	50-305 R	MCCABE, E. C	8007110050*	50-334 G	McDauchy, J. P	8009100366	50-416 S
Matheng. c J	8009030407*	50-273 S	MCCALLIBTER, P	8007020179*	50-329 A	McDauchy, J. P	8006270284	50-416 E
Mathis, C. J.	8009090433*	CDHN18810H	McCarten; J B	8009190171*	50-254 G	HCGAUGHY, J P	8009100333	50-416 9
Hathis, C. J.	8009220250	50-553 &	McCardell: R K	8009100412	RES	HCGAUGHY, J P.	8009100436	50-416 8
Hathis, C. J.	8009260485*	20-553 A	McCarrel: B, F	8009110011	50-344 G	HCGAUGHY, J P.	8009100558	50-416 B
Mateon, V.	8009150433*	50-553 &	McCauley: E W	8009110500	NUREO	HCGAUGHY, J. P.	8009100519	50-416 8
Hatson, V.	8009150438*	50-553 8	McClain; C. M	8009230544*	50-217 R	HCGAUGHY, R H	8009190241*	50-387 0
Matson, E. Matson, V Matson, V. Matson, V Matson, V	8009290079# 8009110629 8009050469 80090110403 8009020480	FOIA XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	MCCLINTOCK, R O MCCLINTOCK, R O, MCCLINTOCK, R, O, MCCLINTOCK, R O MCCLINTOCK, R O	8007270048* 7704010088* 7704010084 8007270077* 8007270044*	FOIA PTP PTP FOIA FOIA	HCOAUGHY, R H HCOAUGHY, R. H. HCOAUGHY, R H, HCOAUGHY, J. P HCOAUGHY, J. P	8009100884* 8009100893* 8009150097* 8009100592 8009040489	50-352
Mateon. V	8009020486*	XPORTLIC	MCCLINTOCK, R. O.	8001020105*	PT9	McCauch, J. L.	8009120471*	50-324 0
Mateon. V	8009110497	XPORTLIC	MCCLINTOCK, R. O	7912180910	PT9	McCauchy, R. W	8009130190*	50-354 0
Mateon. V.	8009110495	XPORTLIC	MCCLINTOCK, R. O	8009290092*	FOIA	McCauchy, R. W	8009100870*	50-412 8
Mateon. V	8009110700	XPORTLIC	MCCLINTOCK, R. O	8001020078*	PT9	McCauchy, J. P	8009240331*	50-414 0
Mateon. V.	8009110743	XPORTLIC	MCCLINTOCK, R. O	8009120222*	40~2940	McCauchy, J. P	8009100303	50-414 8
Hatson, V.	8009260218	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	MCCLINTOCK, R. O	8009240055*	70-710	HCOAUOHY, J. P	8007100347	50-416 8
Hatson, V	8009260224#		MCCLINTOCK, R. O,	8009270041*	FOIA	HCOAUOHY, J. L	8007120466*	50-326 0
Matson, V	8009300078		MCCLINTOCK, R. O,	8001020069	PT9	HCOAUOHY, J. P	8007020064	50-416 8
Hatson, V	8009300079		MCCLINTOCK, R. O.	8009290152*	FOIA	HCOAUOHY, J. P	8007020413	50-416 A
Matson, V	8009300084#		MCCLINTOCK, R. O.	8009160217	70-375	HCOAUOHY, J. P	8007080247	50-416 B

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
HCGAUCHY, J.P. HCGAUCHY, J.P. HCGAUCHY, J.P. HCGAUCHY, J.P. HCGAUCHY, J.P.	8007080328 8007080376 8007300027* 8007100486 8007150301	50-416 Q 50-416 S 50-416 Q 50-416 S 50-416 S	METLAY, D MEURINNEY, J A MEYER, K A. MICHELSON, C MICHELSON, C	8007030492 8009100033 8009300113 8009150079* 8009190733	FOIA NUREO FOIA 50-249 P 50-259 B	HILLS, L M HILLS, L M HILLS, L M HILLS, L M HILLS, L M	8009100284 8008130476 8008150212 8009040401	50-328 8 50-390 6 50-390 5 50-390 6 50-390 6
MCGAUCHY, J. P. MCGAUCHY, J. P. MCGAUCHY, J. P. MCGAUCHY, J. P. MCGAUCHY, J. P.	8007160571 8007250417 8007260473 8007160387 8007230556	50-416 S 50-416 S 50-416 S 50-416 S 50-416 S	MICHEL, C. J. MICHELBON, C MICHEL, C. J. MICHEL, C. J MIDURA, H. J	8007070304 8007110377 8007110371 8007120421 8007070313	70-143 Hisc 70-143 70-143 50-311 R	MILLS, L M HILLS, L M MILLS, L M MILLS, L M HILLS, L M	8007100526 8007150571 8008170458 8008170463 8007100576	50-518 8 71-7074 50-370 8 50-328 8 50-328 8
HCGAUCHY, J.P. HCGAUCHY, J.P HCGAUCHY, J.P HCGAUCHY, J.P HCGAUCHY, J.P	8009230471 8009230627 8009230595 8009240438 8009240480	50-416 8 50-416 8 50-416 8 50-416 8 50-416 8	MIDURA.H J. MIDURA.H J. MIDURA.H J MILES.E MILHIBER.R J	8009160351 8009160298 8009180249 8009120028 8009290396#	50-311 P 50-272 R 50-311 R CONTRACT 50-382 8	HILLS,L M HILLS,L M HILLS,L M HILLS,L M HILLS,L M	8009220038 8009190610* 8009020104 8009020133 8009240600*	40-1341 50-259 Q 50-327 Q 50-259 Q 50-586 Q
HC GAUGHY, J P HC GINNIB, J A HC GINNIB, J A HC GOORY, R, J.	8007230456 8007270097* 8007270087* 8007270152* 8007260443*	50-416 A FOIA FOIA FOIA 50-287 T	MILHIBER, R. J MILLER, R. N MILLER, D R MILLER, W H MILLER, M E	800930033B 8009150139* 8009110827 8009120539* 8009050451	50-382 8 50-201 U 40-4824 50-250 G 70-1308	MILLS, L M MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8009030406 8009300067* 8009110181* 8009240387* 8009020046	50-259 P 50-259 Q 50-327 Q 50-318 Q 50-390 S
MCORATH, E.T. MCORATH, J.R MCOREGOR, L. MCOUTRE, J. MCOUTRE, P. J.	E009300188 E009230455 E009150025* E009300218 E009090389	70-2705 1&E 50-373	MILLER, W.D. MILLER, W.D. MILLER, W.D. MILLER, W.O MILLER, W.O	8009110835* 8009030675* 8009050379 8009090835 8009090836	40-4826 50-263 F 71-3942 70-25 70-27	HILLB, L M HILLB, L M MILLB, L M MILLB, L M MILLB, L M	8007020056 8007040484 8007100472 8007240357 8007020281	50-390 S 50-553 A 50-553 A 50-518 Q 50-327 S
ACQUIRE, P. J. ACQUIRE, P. J. ACQUIRE, P. J. ACQUIRE, P. J. ACQUIRE, D. R.	8009020382 8009030477 8009030596 8009030603 8009230210*	50-293	MILLER, J.R MILLER, J.R MILLER, J.R MILLER, W. O MILLER, W. O MILLER, W. H	8007020128 8007080474 8007080478* 8007110560 8007050176*	TOPREP 50-166 P 50-166 P 50-311 P 70-1151	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8009020069 8009020081 8009020094 8009030560 8009030574	50-294 P TOPREP 50-390 K 50-327 K 50-390 K
HCOUIRE, D.R. HCOURREN, H.J. HCOURREN, H.J. HCOURREN, H.J. HCOURREN, H.J.	8009250360* 8009040276 8009050083 8009110021 8009230038	50-280 Q 50-528 Q 50-528 H 50-376 Q 70-1729	MILLER, W. D. MILLER, W. O. MILLER, W. O. MILLER, H. J MILLER, W. O	8007020154 8009030677 8009080483 8009190781 8009030248	50-277 P 50-344 P 50-313 P 40-8492 50-313 P	HILLS, L M HILLS, L M HILLS, J M HILLS, L M HILLS, L H	8009250075 8009020404 8009090524 8009090427 8009090530	50-259 Q 50-296 P 50-438 Q 50-518 8 50-518 8
McOurren. H. J Hcourren. H. J. Hcourren. H. J Hckibben. J. C. Hckibben, J. C.	8009230049 8009250007 8009250022 8009030212 8009040406	50-376 Q 50-376 Q 50-376 Q 50-186 R 50-186 B	MILLER, W. O MILLER, W. O MILLER, W. O MILLER, W. O. MILLER, W. O.	8009110696 8009160020 8009090881 8009220394 8009220388	50-309 P 40-8743 50-338 P 50-409 P 50-286 P	MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8007030436 8007030508 8007030536 8007030548 8007070414	50-327 P 50-260 P 50-327 F 50-391 F 50-327 R
MCK 18BEN, J. C. MCK 18BEN, J. C. MCLAUGHLIN, J. P MCLAUGHLIN, H. T. MCLAUGHLIN, H. T.	8009040418 8009230586 8009240051* 8009030599* 8009220231	50-186 B 50-186 P 70-710 50-293 B RM	MILLER, H. J. MILLER, J. R. MILLER, H. E. MILLER, H. J. MILLER, H. J.	8009100473 8009160434 80090200=4 800914	40-8768 50-131 F	HITTE'T H	8009090434 8009090440	50-518 S 50-518 S
MCLAUGHLINM T MCLAUGHLINM T. MCLAUGHLINM T MCLENNANJJD. MCLOUGHLINM T	8009160402* 8009230739* 8009290313* 8009190248 8009090401*	50-293 \$ 50-293 \$ 50-293 \$ 50-440 K 50-293 \$	MILLER, J. A. MILLER, J. A MILLER, H. J. MILLER, J. R MILLER, J. R	80091 80091 80091 80090				
HCLOUGHLIN M T MCLOUGHLIN M T MCLOUGHLIN M T MCLOUGHLIN M T MCLOUGHLIN M T	8009090376# 8009160483# 8009160410# 8009160455# 8009170381	50-273 8 50-273 8 50-273 8 50-273 8 50-273 8	MILLER, M. I. MILLER, L. K. MILLER, J. R. MILLER, R. W. MILLER, W. O.	80090 80090 80092 80091				
HCLOUGHLINM T HCLOUGHLINM T. HCLOUGHLINM T HCLOUGHLINM T HCLOUGHLINM T.	8009240463* 8009240468* 8009260475* 8009260484* 8009300535*	50-273 8 50-273 8 50-273 8 50-273 8 50-273 8	MILLER, W. D. MILLER, M. E. MILLER, M. E. MILLER, W. O. MILLER, W. O	80091 80091 80092 80092				
HCMTLLENIN H HCMTLLENIN.H HCMETLLI H H HCMETTYI A HCPHERSONIH	8009100261 8009180460 8009180119* 8009120505 8009150178*	50-445 M 50-445 M 0A999 50-206 P GONTRACT	MILLER, M. E. MILLER, M. E. MILLER, L. K. MILLER, L. K. MILLER, L. K.	80091 80091 80091 80091 80092				
HCVEIN, J HEACHUM, T R HEAMS, D B HECH, B J. HECHON, R. D.	8009240069* 8009260069 8009180528 8009090020 8009160396	CONTRACT REB 50-522 9 NUREO 50-293 8	MILLER, W. D. HILLER, J. R. HILLER, J. R. HILLER, J. R. HILLER, J. R.	80071 80073 80073 80075 80072				
HEDROW, L. A.K. HEDROW, L. A.K. HEDROW, L. A.K. HEEK, W. E. HENARD, H.W.	8009180143 8009190188 8009180320 8009260417* 8009300646	CONTRACT CONTRACT CONTRACT 50-287 T NUREO	MILLER, M. I. MILLE, L. M.	80071 80071 80071 80071				
MENCZER, W B MENEFEE, K B. MERGER, W. MERRIWEATHER, N MERRIWEATHER, N	8009170070* 8009170365* 8009180255 8009240276* 8009100307*	FOIA 50-320 H PT21 50-370 Q 50-364 Q	MILLS, L. M MILLS, L. M, MILLS, L. M MILLS, L. M. MILLS, L. M.	8009C 8009C 8009C 8009C				
MERRITT, 0, J. MERBON, 8, D. MERBON, 8 D. MEBCHER, M. C. MEBBINGER, M	8007050354 8007270246 8007270248* 8007180366 8007050174*	50-329	MILLE, L. M HILLE, L. M. MILLE, L. M. HILLE, L. M. MILLE, L. M.	80070 80071 80070 80070 80071				

AUTHOR	ACCESSION NUMBER	EUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	EUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODS:
HILLS, L M MILLS, L M MILLS, L H MILLS, L M	8009240425 8009300195 8009220210 8009230611 8009190488	50-518 8 50-327 0 50-259 P 50-390 8 50-259 P	MODENOS, L MOELLER, D W MOMBOIGSE, R M MOMBOISGE, R M MONROE, J D	8007020337 8007100158 8007110012 8007110012 8007240557	NUREO PR PR	MORTON, K V MORTON, K V MORTON, K V MORTON, K V MORTON, K V	8009180217 8009240028 8009240238 8009240130 8009240130	# CONTRACT # CONTRACT # CONTRACT
HILLS, L M HILLS, L M HILLS, L M HILLS, L M	8009230333 8009230549 8009240392 8009250254 8009250273	50-327 F 50-327 P 50-518 S 50-438 S 50-390 S	MONTODHERY, D M MOODY, D E MOODY, D E MOODY, D E	80071604974 8009080526 8009080541 8009120275 8009080522	* 50-280 Q 50-29 Q 50-309 Q 50-309 Q 50-29 Q	MORTON, K V MORTON, K V MORTON, K V MORTON, K, V MOSCHNER, R A	8009270142: 8009300597: 8009260247: 8009300264: 8009190751	CONTRACT
MILLS, T MILLS, L M MILLS, L M MILLS, L M	800924000B 8009230540 8009230410 8009250240 8009290324	50-445 Q 50-390 B 50-390 B 50-438 B 50-390 B	MODDY, D E MODDY, D E MODDY, D E	8009080528 8009120207 8009020050 8009160257 8009160289	50-307 G 50-307 G 50-266 U 50-309 R 50-27 R	MOBBLL B MOTT.W E MOTT.W R MOURY.W R MROCZKA,E J	8009020174 8009190742 8009220044 8009300088 8009020377	FO1A HABIE MOT HABIE MOT XPDRTLIC 50-245
HILLS, L H HILLS, L H HILLS, L H	8007270327 8007270332 8007270344 8007270346 8007270355	50-390 8 50-328 8 50-390 8 50-438 8 50-553 8	KOON, C H. KOONEY, O KOONEY, O MODRE, R N KOORE, R L	8007020058 8009110327 8009170423 8009150422* 7909040723	50-466 G 50-454 A 40-8692 COMM1881ON RECOD	MROCZKALE J MROCZKALE J MROCZKALE J MROCZKALE J MROCZKALE J	8007020284 8007170456 8007170460 8007160437 8007260647	50-336 E 50-245 & 50-336 £ 50-336 £
MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8009290375 8009290333 8009290350 8009300226 8009300400	50-518 S 50-327 P 50-328 B 50-327 P 50-259 P	MODRE, N MODRE, R N MODRE, G W MODRE, G W MODRE, R N	8007150442* 8007150446* 8007030370 8007030375* 8007170755	COMMISSION COMMISSION 50-334 R 50-334 R XPORTLIC	MROCZKA.E J MUCHNICKI,E D MUELLER.A J MUELLER,R J MULLER.R E	9009230345 9009100444 9009150204* 9009300539* 9009120607	50~336 R PR GA799 50~265 B XPORILIC
MILLS, L M MILLS, L M MILLS, L K MILLS, L H	8009300411 8009300429 8009300480 8009290262 8009300147	50-438 S 50-274 P 50-438 B 50-327 P 50-259 P	MOORE, R N MOORE, J. E MOORE, O W MOORE, O E MOORE, V A	8009230119 8009040262 8009100609 8009230360* 8009180170	XPORTLIC 50-135 0 50-334 P 50-280 G 50-311 E	MULLHOLLAND, J MUNDY, J A MUNEO, J J MUNEO, J J MUREO, J J	8009110410* 8009100150 8009160204 8009020813 8009160459	CONTRACT TOPREP PRH 71-9039 XPORTLIC
HILLS.L H MILLS.L H MILLS.L H MILLS.L H	8009300348 8009300353 8009300427 8009300445 8009300395	50-438 S 50-259 P 50-438 S 50-510 S 50-328 8	MOGRE, J MORAN, D M MORIARTY, J M MORIBI, A V MORIBI, A V	8009260414* 8009040361 8009040425 8009090261 8009160346	50-289 T 50-289 Q 50-352 B 50-293 R 50-293 P	MUNTE, M. L MUNTZINO, L. M MUNTZINO, L. M MURFIN, H. B MURPHY, C. E.	8009240490 8009150052# 8009150055# 8009180502 8009240228#	50-245 U COMMISSION 50-293 U 50-3 P 50-369 Q
MILLS, L M MINECK, D L MINECK, D L MINECK, D L MINECK, D L	8009300467 8009030466 8009170315 8009170324 8009170348	50-328 8 50-331 8 50-331 8 50-331 8 50-331 8	MORIBI, A V MORRIB, P A MORRIBON, H P MORRIB, M D MORROW, D	8007230453 8007070348± 8007020462± 8007260405± 8007020470	50-293 P FOIA 50-375 M 70-2560 40-8502	MURPHY, C E MURPHY, C E MURPHY, C E MURPHY, C E MURPHY, C E	8009160337# 8009240363# 8009100130 8009240302# 8009120526#	50-269 Q 50-324 Q 50-369 Q 50-413 Q 50-250 Q
HINECK, D L	8009170355 8009170363 8009190499 8009300493 8009190768	50-331 8 50-331 8 50-331 R 50-331 8 RE8	MORROH, P. E MORBE, A. K MORBE, A. K MORBE, A. K MORBE, A. K	9007160430 8009230001 8009230002# 9009260672 8009260677#	NUREO 50-409 Q 50-409 Q 50-409 Q	MURPHY, C. E. HURPHY, C. E. HURPHY, C. E. HURPHY, C. E. MURPHY, C. E.	8007120475# 8007140535# 8007030032 8007030138 8007150372#	50-250 Q 50-269 Q 50-390 Q 50-395 Q
MINOQUE, R B MINOQUE, R B MINOQUE, R B MINOQUE, R B MINOQUE, R B	8009190320* 8009190366* 8009190480* 8009190394* 8009190484*	FOIA FOIA FOIA FOIA FOIA	MORTENSEN, H KORTON, K V MORTON, K V, MORTON, K V MORTON, K V	8009240480 8009230359* 8009100071 8009100077* 8009030253*	70-2786 CONTRACT CONTRACT CONTRACT BECY	MURPHY, C. E MURPHY, C. E MURPHY, C. E MURPHY, C. E MURPHY, C. E	8007070253 8007120135 8007110425* 8007150332 8007170388*	50~370 Q 50~553 0 50~416 0 50~413 Q 50~321 Q
MINOQUE, R B MINOQUE, R B MINOQUE, R B MINOQUE, R B MINOQUE, R B	8009190514# 8009190532# B009190550#	FOIA FOIA FOIA FOIA	MORTON, K. V. MORTON, K. V. MORTON, K. V. MORTON, K. V. MORTON, K. V.	8009040470* 8009240079* 8009110002* 8009110003* 8009110004*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MURPHY, C E MURPHY, C E MURPHY, C, E HURPHY, C E MURPHY, C E	8008280106 8007050415 80092402664 8009240307#	50-346 0 50-400 0 50-384 0 50-370 0 50-413 0
MINOQUE,R B MINOQUE,R B MINTZ,S MIRAQLIA,F MIRAQLIA,F	8009030047# 8009230431# 8009300220	PR REGOD TOPREP 50-458 A 50-275 H	MORTON, K V MORTON, K V MORTON, K V, MORTON, K V, MORTON, K, V	8009120017 8009120019* 8009110003* 8009100035 8009100041*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MURPHY, G E MURPHY, C. E. MURPHY, C E MURPHY, C. E MURPHY, C. E	8009110111 8009240398* 8009110107 8009100300* 8009250109	50-518 Q 50-518 Q 50-375 Q 50-364 Q 50-566 Q
HITCHELL, D B HITCHELL, D Q HITCHELL, D Q HITTL, R, L HITTL, R, L	80091203424 8009220291# 8008280311 8009040352	CONTRACT 50-287 8 50-289 R 50-311 F	Morton, X V Morton, K V Morton, K, V Morton, K V Morton, X V	8009240049* 8009030216* 8009120014* 48009020481*	CONTRACT CONTRACT CONTRACT 70-2313 CONTRACT	MURPHY, C E MURPHY, C E MURPHY, C E MURPHY, C E MURPHY, C E	8009180148 8009240066 8009300031* 8009170161 8009050173	50-280 0 50-335 0 50-416 0 50-328 0 70-1151
MITTLER L MITTLER L MITTLER L MITTLER L MITTLER L MITTLER L	8007050332 8007070312 8007170213 8007180145	50-311	MORTON, K V MORTON, K V. MORTON, K, V MORTON, K V MORTON, K V	8009110253 **2000110008 **C00010008	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MURPHY, C E MURPHY, C E. MURPHY, C E. MURPHY, C E. MURPHY, C E	8009150366 8009110824	50-413
HITTL.R L MITTL.R L MITTL.R L MITTL.R L MITTL.R L	8009190392 5 8009190479 5 8009190515 5 8009190527 5	0-311 P 0-311 Q 0-311 P 0-311 P 0-311 P	MORTON, K. V MORTON, K. V MORTON, K. V MORTON, K. V MORTON, K. V	8009160488* 8009110331 8009110338* 8009110410*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MURPHY, C E MURPHY, C. E MURPHY, C E MURPHY, C E	8009120515 8009250341* 8009240201 8009240256	50-250 Q 50-250 Q 50-413 Q 50-369 Q 50-370 Q
MITTL,R L MITTL,R L MITTL,R L MITTL,R,L MITTL,R,L	8009180455 50 8009180458 50 8009180458 50	0-311 P 0-311 P 0-311 Q 0-311 P	MORTON, K, V MORTON, K, V, MORTON, K, V MORTON, K, V, MORTON, K, V,	8009120012* 8009230755* 8009230771* 6009120033*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MURPHY, J. R MURPHY, W P. MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. MURPHY, C. E.	8007020483 8007050318 8007050322* 8007240282 8007240292	NUREQ 50-271 8 50-271 8 50-410 0
MITTLIR L MITTLIR L MIYABAYASHI, M MIYABAYASHI, M	8009220280 50 8009290361 50 8009120062 XP	-311 P -311 P -272 P GRTLIC GRTLIC	MORTON, K. V. MORTON, K. V. MORTON, K. V MORTON, K. V MORTON, K. V	8009190727 8009190738* 8009230777* 8009120007*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MURPHY, C E MURPHY, P, M HURPHY, C E HURPHY, C E, HURPHY, M J	8009240380 8009240383 8009090446 8009190576 8009240329	50-510 0 50-566 0 50-255 0 50-318 0 50-324 0 50-311 8

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
PRRPHY, H J PRRPHY, H J MURPHY, G E MURPHY, H J	8009120372# 8009120392# 8009120428# 8009160533 8009150267#	50-272 8 50-272 8 50-272 8 50-269 0 50-311 8	NEUMAN, R J NEUMAN, R J NEUMAN, J R NEUMAN, J R NEUMAN, J R	8007070558* 8009070575* 8009070675* 8009180475 8009180475	50-311 B 50-272 S 50-466 0 50-466 0 50-466 0	NORDERHAUGIL R NORDERHAUGIL R NORDLINGERIH B NORDLINGERIH B NORDLINGERIH B	6009170209 6009180289 6009020071 6009090779 6009090452	70-734 70-754 50-275 0 50-275 T 50-275 T
HURPHY, C E HURPHY, H J HURPHY, C. E HURPHY, J HURRAY, T. D	8009250347 8009160482* 8009300026 8009190256* 8009080317	50-400 G 50-311 B 50-416 G 50-440 K 50-346 R	NEHMANI J R NEHMANI J R NEHMANI J R NEHMANI J R NEHMANI J R.	8009170169 8009170169 8009170171* 8009300027 8009300027	50-582 0 50-582 0 50-582 0 90-466 0	NORELIUS, C E NORELIUS, C E NORTON, B NORTON, B NORTON, B	8009190171# 8009260415# 8009220213 8009030689 8009030689	50-254 G 50-329 G 50-323 G 50-275 G
MURRAY, T. D. MURRAY, M. J. MURRAY, M. J. MURRAY, T. D. MURRAY, M. J.	8007020333 8007020048 8007020084 8007020057 8007160281	50-346 8 50-367 0 50-367 0 50-346 B PR	NEWMAN, J R. NO.C NO.C NICHOLE.D L	8009300469 8009300469 8009170296* 8009170314* 8009040269*	50-466 0 50-466 0 50-244 P 50-244 P 50-155 Q	NORTON, B NORTON, B NOSENZO, L V NOSENZO, L V	8007030677 8007030679 8007150428* 8007080547 8007080277	50-275 0 50-275 0 COMMISSION XPORTLIC XPORTLIC
HURRAY, T D. HURRAY, T D IRURRAY, J P. HURRAY, J P HURRAY, J P.	8009150276 8009160391 8009290002 8009290004# 8009290005#	50-346 R 50-346 8 50-266 U 50-266 U 50-266 U	NICHOLBON, N A NICHOLB, T C NICHOLB, T C NICHOLB, T C NICHOLB, T C.	8009190121* 8009180634* 8009100427 8009180511 8009020031	40-2061 50-375 0 50-375 8 50-375 0 50-375 0	NOSENZO, L V NOSENZO, L V NOSENZO, L V NOSENZO, L V, NOSENZO, L V	8009100155 8009300464 8009180296 8009290136 8009300650	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
HURRAY, T D HURRAY, H J HURRAY, T D HURRAY, T D HURRAY, T D	8007120351 8007220177 8007230682 8007230686* 8007230670	50-346 8 50-367 0 50-346 8 50-346 8 50-346 8	NICHOLB, T C NICHOLB, T C. NICHOLB, T C. NICHOLB, T C NICHOLB, T, C	8007020065 8007250072 8007030460 8007030473 8007110717	50-395 M 50-395 Q 50-395 Q 50-395 A 50-395 Q	NOSENIO, L V NOSENIO, L V NOSENIO, L, V NOVAK, T M NOVAK, T H	8009300660 8009300074 8009290130 8009110563 8009090794	XPORTLIC XPORTLIC XPORTLIC 50-320 P 50-286 P
HURRAY, K J HURRAY, T D HURRAY, J. F HURRAY, T D HUSTAIN, H J	8009220173 8009230671 8009230447 8009290363 8009240729#	50-367 Q 50-346 8 50-266 Q 50-346 8 40-277	NICHOLS.T C NICHOLS.T C NICHOLS.T C. NICHOLS.T C. NICHOLS.T C	8007030621 8007080337 8007180129 8007100320 8007110211	50~375 8 50~375 8 50~375 0 50~375 A	NOVAK, T. M NOVAK, T. M NOVAK, T. M NOVAK, T. M NOVAK, T. M	8009110553 8009030201 8009040076 8009040085 8009040114	50-336 P 50-289 I 50-265 F 50-269 P 50-293 P
MUZZY.R J MYERB.J A MYHATT, F R. MYHATT, F R MAIDU, K R	8007230431* 8007070380 8007150311 8007120967 8007110324*	TOPREP 50-320 H REB RES 50-454 Q	NICHOLS, T C NICHOLS, T C NICHOLS, T C NICHOLS, T C NICHOLS, T, C	8009120347 8009300590 8009150314 8009170294 8009230282	50-395 A 50-395 Q 50-395 K 50-395 A 50-395 F	NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T, M	8007020330 8007030344 8007100178 8007170774 8007150427	50-312 F 50-312 P 50-295 P 50-3 P 50-250 P
NAIDU, K R NAIDU, K R NAPUDA, Q NAPUDA, Q NARBUT, P, F	8007170221* 8007110475* 8007070250* 8007180005* 8007120500*	50-456 Q 50-454 Q 50-287 Q 50-334 Q 50-528 Q	NICHOLS, T C NICHOLS, T C NICHOLS, T C NICHOLS, T, C	8009230296 8009240552 8009290337 8009300168 8009260516	50-395 A 50-395 Q 50-395 A 50-395 A 50-395 A	NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M	800722006/ 8009180549 8009240093 8009300878 8009260529	50-307 H 50-321 P 50-309 H 50-271 P 50-338 P
NARBUT, F, P. NARROW, L. NAUGHTON, U, F. NAUGHTON, U, F. NAUGHTON, U, F. NAUGHTON, U, F.	8009300054* 8009100870* 8009250344* 8009020109 8009030439	50-312 Q 50-412 Q 50-295 Q 50-10 Q 50-295 P	NICOLOSI, B L NIEHAUS, P W NIERODE, C F. NIMITZ, R. L NIMITZ, R. L	8009190401 8009150042 8009260640* 8009090189* 8009100044*	RES 50-358 S 50-263 S 50-217 Q 50-217 Q	NOVAK, T M NOVARRO, J P NOVARRO, J P NOVARRO, J P. NOVARRO, J P	8009170256# 8009120254 8009030433 8009020425 8009030437	50-289 0 50-322 0 50-322 A 50-322 A
NAUGHTON, I/F NAUGHTON, I/F NAUGHTON, I/F NAUGHTON, I/F NAUGHTON, I/F	8007080355 8007110300 8007100532 8007170468 8007170403	50-275 P 50-275 P TOPREP 50-275 P 50-275 P	NISHITA,H NIX,R T NIX,R T NIX,R T NIX,R T	8007170405 8007020374* 8007020405* 8007020444* 8007020446*	NUREO 50-366 S 50-366 S 50-321 S 50-321 S	NOVARRO.JP NOHIGKI,8J NOHIGKI,8J NOMIGKI,9J NUGENT,EL	8009230590 8009020448 8009100008 8009120547 8009260045	50-322 A 50-206 Q 50-206 P 50-206 P 40-2259
NAUCHTON, H F NAUCHTON, H F NAUCHTON, H F, NAUCHTON, H F, NAUCHTON, H F	8007300287 8007230672 8007260213 8007300267 8007300488	50-10 V TOPREP 50-295 P 50-295 P 50-454 A	NIX.R T NIX.R T. NIX.R T. NIX.R T NIX.R.T	8007020433* 8007070480* 8007070475* 8007150335* 8007150385*	50-346 8 50-321 8 50-346 8 50-346 8 50-321 6	NUSENT, E L NUSENT, E L NUSENT, E L NUSENT, E L	8009030510 8009110402 8009160349 8009190393 8009110411	40-2259 40-2259 40-2259 40-2259 50-246 H
NAVARRO, J. P. NEALE, J. B. NEEL, J. N. NE LOHBORB, J. D. NE LOHBORB, J. D.	8007120123* 8007160305* 8007120156* 8007100645* 8007150248*	50-322 S 50-304 B 27-48 50-247 P 50-334 P	NIX,R T NIX,R.T NIX,R T NIX,R T, NIX,R T	8007150386* 8007160306* 8007290281* 8007300502* 8007300526*	50-321 8 50-355 8 50-356 8 50-321 8 50-365 8	NYGOARD, G R O'ERIEN, J P O'HANLON, J P O'HANLON, J P O'NEILL, B	8007230001 8007120470# 8007030330 8007020458# 8007270068#	50-407 0 50-312 0 50-313 V 50-358 8 FOIA
Neighborb, J. D Neighborb, J. D Neighborb, J. D, Neibler, J. Neibler, J. H.	8007180122* 8007180552* 8007240077* 8007250352* 8007180280*	50-261 P 50-280 P 50-315 P 50-461 G 50-373 G	NIXON, W A NOELL, P N NOELL, P. N NOELL, P. N NOELL, P N	8007180440 8007020148# 8007020463# 8007020467# 8007020470#	40-2061 50-331 P 50-10 P 50-10 P 50-10 P	O'NEILL.B O'NEIL.R.A O'NEIL.R.A O'NEIL.R.A O'NEIL.R.A	8009290097# 8009040196 8009040196 8009300496# 8009300035	FOIA 50-445 H 50-445 H 50-446 H 50-440 H
NEIBLER, J.H. NELBON, P.R. NELBON, P.R. NELBON, P.R. NELBON, C.C.	8007270465* 8007150118* 8007150121* 8007150138* 8007050487	50-373 Q 50-201 U 50-201 U 50-201 U 50-70 P	NOELL, P N NOELL, P N NOELL, P N NOELL, P N NOELL, P N	8009020473* 8009020474* 8009040103* 8009040129* 8009040315*	50-10 P 50-10 P 50-155 P 50-263 P 50-324 P	O'NEIL, RA O'NEIL, RA O'NEIL, R, A O'NEILL, JH O'REILL, Y, J, P	8009300488 8009300476* 8009300035 8009300410 8009150094*	50-445 M 50-445 M 50-445 M 50-266 O 50-201 U
NELSON, P. R NELSON, P. R NEHETH, K. J NEUFER, A. G NEUFER, A. G	8007020012 8007300207 8007030184* 8007230360* 8007270321*	50-225 F 71-394 State Prog 50-338 R 50-338 R	NOELL, P N NOELL, P N NOELL, P N NOELL, P. N NOELL, P. N	8007040544# 8007030456# 8007030301# 8007130426# 8007170260#	50-271 P 50-293 P 50-29 P 50-317 P 50-333 P	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009090055 8009090057 80090900069 8009090073 8009090075	50-324
MEUMANN, M.R. MEUMANN, M.R. MEUMANN, M.R. MEUMANN, M.R. MEUBCHAEFER, E	8008110042 8007260153 8007260024 8007170237 8007030607*	40-8721 40-8380 40-8380 40-8380 50-302 8	NOELL, P. N. NOELL, P. N NOLAN, F. NOON, F NOON, F	8009170402* 8009180217* 8009190765 8009170295 8009170298	50-220 P 50-336 P 50-259 8 50-244 P 50-244 P	O.WEILTA' Y b O.WEITTA' Y b O.WEITTA' Y b O.WEITTA' Y b	8009100910× 8009050431× 8009100040 8009100042 8009100044	70-143 50-280 50-348 50-261 50-302
NEUSCHAEFERIE NEWHANIR, J. NEWHANIR, J. NEWHANIR J. REWHANIR J.	8007110342* 8007030571* 8007030620* 8007070455* 8007070550*	50-302 8 50-311 8 50-311 8 50-311 8 50-311 8	NOON, F NORDERHAUD, L. R NORDERHAUD, L. R NORDERHAUD, L. R NORDERHAUD, L. R.	8009170312 8009170212 8009050188 8009150510 8009150545	50-244 P 70-734 70-25 50-312 G 70-1737	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009100049 8009100051 8009100058 8009100058 8009100063	90-250 50-327 50-280 50-269 90-328

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACC
O'REILLY, J P	8007100065 8007020303 8007020222 8007100702 8007030123	50-404	O.WEITFA' O b O.WEITFA' O b O.WEITFA' O b O.WEITFA' O b	8009290276 8009290277 8009290282 8009290287 8009290293	50-348	PACE.P L PACE.P L PACE.P L PACE.P L PACE.P L	8009 8009 8009 8009
O'REILLY, J P D'REILLY, J P D'REILLY, J P O'REILLY, J P O'REILLY, J P	8007030125 8007030128 8007030129 8007030130 8007030137	50-302 0 50-416 0 50-395 0 50-395 0 50-488 0	O'REILLY, J P O'ROURKE, S A OBERG, C T OBERG, C R OBERG, C R	8007270277 8007050453 8006120884= 8007070646+ 8007150348=	50-269	PACE.P L PACE.P L PACE.P L PACAND.F G PAGE.R O	8003. 8003. 8002; 8003; 8003.
O.WEITTA'D b O.WEITTA'D b O.WEITTA'D b O.WEITTA'D b D.WEITTA'D b	8009030141 8009030146 8009030154 8009030158 8009030163	50-280 0 50-259 0 50-321 0 50-250 0 50-261 0	OBERO, CR OEBTMANN, MJ OHLBBON, K OLLER, RE OLBEN, RN.	8009150362* 8009260665* 8009190726 8009150173* 8009090614	50-458 0 50-345 0 REOOD GATTT XPORTLIC	PAGE.R O PAGE.R O PAGE.R O PAGE.R O PAGE.R O	8009; 8009; 8009; 8009;
O.KEITTA'1 b O.KEITTA'1 b O.KEITTA'1 b O.KEITTA'1 b O.KEITTA'1 b	8007030175 8007030181 8007160036 8007160037 8007160040	50-269	OLBEN, A F OLBEN, A F OLBEN, F M OLBEN, L. N OLBON, R C	8007110667 8007030443 8007260014 8007230230 8007030014	70-824 50-99 P 50-409 0 50-286 P Nureo	PAGLAIRO, J, PADLINO.R PAPAY, L T PAPAY, L T PAPERIELLO, C J.	80092 57008 57008 57008
D'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009140049 8009230389 8009230391 8009230396 8009230397	50-259	OLSON,N J OLSON,J F OLSON,J.F. OPREA.O W OPREA.O W	8009020219 8009030726 8009300039 8009030170# 8009180479	50-445 A 50-282 0 50-282 0 50-498 0 50-498 8	PAPERIELLO, C J PAPERIELLO, C J PAPERIELLO, C J. PAPERIELLO, C, J PAPPAS, H	80092 80092 80053 80061 80090
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009230398 8009230400 8009230404 8009050422 8009120066	70-1201 50-332 G 70-143 50-280 Q 50-518 Q	OPREA, O. W OPREA, O. W OPREA, O. W OPREA, O. W OPREA, O. W	8009190147 8009180447 8009180441 8009020288 8009020290	50-478 8 50-478 0 50-478 0 50-478 8 50-478 8	PAPPAB, H PAPPAB, H PAPPAB, H PAPPAS, H, PAPPAB, H	80090 80091 80092 80091 80091
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007120072 8007120077 8007120080 8007120082 8007140108	50~324 G 50~321 G 50~416 G 50~259 G 50~437 G	OPREA.O W OPREA.O W OPREA.O W OPREA.O W OPREA.O W	8009300545 8009300555 8009040377 8009050364 8009110384	50-498 Q 50-498 Q 50-498 8 50-498 Q 50-498 B	Pappas, H Pappas, H Pappas, H Pappas, H Paris, O H	800우1 800우교 800우교 800우교 800우1
O'REILLY, J P D'REILLY, J P O'REILLY, J P O'REILLY, J, P O'REILLY, J, P	8009160110 8009160113 8009160115 8009160118 8009160120	50-34B Q 50-302 Q 50-416 Q 50-395 Q 50-395 Q	OPREA.Q W OPREA.Q W OPREA.Q W OPREA.Q W OPREA.Q W	8009080201 8009110367 8009300536 8009230603 8009230617	50-498 A 50-498 B 50-498 Q 50-498 8 50-498 8	PARKER, W O	80072 80071 80071 80072 80072
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	E007160124 8007160133 8007160137 E007160143 E007160147	50~261 Q 50~488 G 50~267 Q 50~250 Q 50~321 Q	OPREA, O W OPREA, O W OPREA, O, W OPREA, O W. OPREA, O W	8009150559 8009230658 8009240439 8009230402 8009300161	50-498 K 50-498 S 50-498 S 50-498 B 50-498 B	PARKER, W. O PARKER, W O PARKER, W O PARKER, W O PARKER, W, O	800924 800924 800914 800911
G'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P,	8009160153 8009160172 8009230249 8009230252 8009230256	50-259 Q 50-280 Q 50-348 F 50-261 F 50-269 F	OPREA, O. W ORDERB, W ORLOSKY, P M ORMONDE, S ORNICH, J	8009300453 8009300640* 8009160340* 8009120594 8009300338	50-498 8 50-269 0 50-57 I FOIA 50-382 8	PARKER, W O PARKER, W O PARKER, W O PARKER, W, O PARKER, W, O	800711 800701 800701 800717 800724
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P. O'REILLY, J P	8009230258 8009230261 8009230265 8009230267 8009230273	50-302 F 50-250 F 50-321 F 50-259 F 50-280 F	ORTENBERG, L I GBANN, E, W OBANN, E # OBANN, E # GBANN, E #,	8007080279* 8007030703 8007030710 8007030703 8007030710	50-348 P 50-367 0 50-367 0 50-367 0 50-367 0	PARKER, W O	800924 800914 800914 800917 800924
O'REILLY, J P	8009230277 8009230323 8009230325 8009260274 8009260277	70-824 70-27 70-143 70-1349 70-2892	H 3 ,MARBO W 3 ,MARBO W 4 ,MARBO W 5 ,MARBO W 5 ,MARBO	8004530385 8004530383 8004530385 8004530008	50-367	PARKER, W. O PARKER, W. O PARKER, W. O PARKER, W. O PARKER, W. O	\$00902 \$09003 \$09003 \$09000 \$09002
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009260314 8009260316 8009260317 8009120248 8009120251	70-2621 70-2520 70-1397 50-437 G 50-348 G	OBANN, E, W OBANN, E W. OBANN, E W OBTRANDER, F. W OTT, L. J	8009230393 8009240011 8009240011 8009300544 8009100944	50-367 9 50-367 0 50-367 0 50-344 9 NUREO	PARKER, W O PARKER, W O, PARKER, W O, PARKER, W O, PARKER, W O	800902 800911 800912 800925 800904
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	800912025B 8009120265 8009120286 8009120290	50-302 0 50-416 G 50-375 G 50-375 G 50-261 G	OTT, R F OTT, W R. OTTINGER, R. L OTTOSON, H L OTTOSON, H L.	6009300595* 8009300303 8009110491* 8009090811 8009170207	CONTRACT NUREO 50-320 U 50-206 Q 50-206 Q	PARKER, W O	800708 800712 800712 800703 800703
O'REILLY, J P O'REILLY, J P O'REILLY, J, P O'REILLY, J, P	8007120300 8007120308 8007120311 8007120314 8007120340	50-488 G 50-250 G 50-321 G 50-260 G 50-259 G	OTTOSON, H.L. OTTOSON, H.L. OTTOSON, H.L. OTTOSON, H.L. OTTOSON, H.L.	8009130011 8009140630 8009160321 8009020078 8009030533	50-206 Q 50-206 Q 50-206 Q 50-206 S 50-206 R	FARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	800707(800710(800712(800714(800712(
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009120343 8009230521 8009230525 8009230526 8009260375	50-267 Q 50-257 Q 50-321 Q 50-324 Q 50-257 Q	OUZTS, J E OVERBERGER, C. O ' OVERLID, T. W OVERLID, T. W OVERLID, T. W	8009150375* 8009150225 8009030401* 8009230641* 8009230630*	50-324 0 REGOD 50-263 8 50-263 8 50-263 8	PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W. O	800711C 800715C 800715C 800915C 800925C
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009260397 8009260517 8009290269 8009290271 8009290274	50-395 Q 50-280 Q 50-437 Q 50-414 Q 50-302 Q	OWEN.J B OWSLEY.O F OWSLEY.O F OWZARSKI.P C DIKER.D	8009220139 8009040490 8009260477 8009110419 8009220242*	TOPREP 50-395 P TOPREP RES 50-329 A	PARKER, W O PARKER, W O, PARKER, W. O PARKER, W. D PARKER, W O	8009160 8009160 9009360 8009180 8009180

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PARKER, W O	8009170462 8009180322 8009190399 8009190506 8009230724	50-269 R 50-369 A 50-369 A 50-369 A 50-369 P	PENDERGRAFT: R PEOPLEG. D L PEOPLEG. D L PEOPLEG. D L PEOPLEG. D L	9007230748* 8007180261 8007110217 8007020294 8007170230	50-368 B 70-2609 70-2609 NUREO 50-237 Q	PLESSET, M S PLESSET, M S PLESSET, M S POCHAL, W F POCHAL, W F	8009150238 8009150245 8009150249 8009100493 8009160287	50-327 D ACRS ACRS XPORTLIC XPORTLIC
PARKER. H O	8007240409	50-369 A	PERANICH, M W PERDIKARIS, P C PERKINS, T J PERKINS, T J PERKINS, M A	8009150055*	50-445 Q	POCKAL,WF	8007230783	XPORTLIC
PARKER. H O	8007230476	50-270 S		8009020355	NUREO	POOALIES,JK	8007100406	50-341 0
PARKER. H O	8007230507	50-270 S		8009120413*	50-220 V	POOALIES,JK	8007100406	50-341 0
PARKER. H O	8007240448	50-369 V		8009120417*	50-220 V	POGOIO.A	8007160478	RES
PARKER. H O	8007240489	50-369 A		8009050243	90-320 B	POIRIER,LJ	8007080352*	50-317 F
PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8009290371 8009260450 8009290303 8009300428 8009300434	50-349 A 50-287 8 50-349 A 50-249 J 50-349 A	PERLMAN, J PERLMAN, J PERLMAN, J PERLMAN, J	8007300010 8007120514* 8007120037* 8007120115* 8007130414*	50~289 G 50~206 P CONTRACT CONTRACT CONTRACT	POIRIER, M R POIRIER, M R POIRIER, M R POIRIER, M R POIRIER, M R	8009040453 8009150417 8009150417 8009160275 8009160275	50-498 M 50-445 M 50-445 M 50-445 M 50-445 M
PARKER, H. O	B009300486	50-269 P	PERLMAN, J	8009150424#	50-206 P	POIRIER, M R	8009160182	50-445 H
PARKINSON. T F	B009300459	50-124 P	PERLMAN, J	8009240057#	50-206 P	POIRIER, M R	8009160182	50-445 H
PARSONS. E M	B009110411	50-266 H	PERLMAN, J	8009300276#	CONTRACT	POIRIER, M R	8009260318	50-445 M
PARTLON. J. O	B009230168	70-1143	PERNY, C D	8009250439#	70-143	POIRIER, M R	8009260318	50-445 M
PARTLON. J. O	B009030046	70-1120	PERRIOO, L D	8009110483	RE6	POLANSKI, X	8009160426*	50-295 S
PARTLOW, J O	8007080487 8009150340 8009170242 8009140235 8009150389	70-687 70-1143 70-1113 70-754 70-1257	PERROTTI, D J PERRY, J C PERRY, J C PETERBON, K PETERBON, R M	8009220184* 8009100467* 8009260510* 8009160583 8009220116	50-335	POLK:P J POLLACK:B POLLARD:R D POLLARD:R D POLLARD:R D	8009190770 8009120435 8009230011 8009200420* 8009300422*	50-220 P 50-361 H 50-289 T 50-289 G 50-289 G
PARTLOH, J O	8009150395	70-143	PETERSON, H R PETERSON, M R PETERSON, M R PETERSON, M R PETERSON, M R	8009020120	XPORTLIC	POLLEIT, R	8009120442	50-341 H
PARTLOH, J O	8009290266	70-1201		8009020129	XPORTLIC	POND, O D	8009280478	50-213 P
PARTLOH, J O	8009290374	70-143		8009160274	XPORTLIC	POOLE, D.	8009030206*	50-302 R
PASSAHANI, B,	8009170181*	MISC		8009250333	XPORTLIC	PORTER, S W	8009300399	50-289 R
PASTERNAK, R J	8009110298*	50-333 G		8009020471	XPORTLIC	PORTER, W L.	8009260010	50-349 O
Pagternak, r Pagternak, r Pagternak, r Pagternak, r Pagternak, r J	8009190936 8009020115 8009090014 8009100117 8009100268	50-333 0 50-333 0 50-333 0 50-333 0 50-333 R	PETERSON, M R	8009020478 8009100198 8009020464 8009110591 8009110606	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PORTER, W.L. PORTER, M.L. PORTER, M.L. POTAPOVS, U. POTAPOVS, U.	8009240246 8009240273 8009290028 8009150207* 8009150229*	50-357 Q 50-359 Q 50-488 Q QA999 QA999
Pasternak, r Pasternak, r J Pasternak, r Pasternak, r J Pasternak, r J	8007030405 8007030418 8007020354 8007020374 8007020407	50-333	PETERBON, M R	8009110609 8009110755 8009160191 8009180420 8009160233	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8009180300# 8009150200# 8009150227# 8009190031# 8009190027#	QA999 QA999 QA999 QA999 QA999
Pasternak, r j Pasternak, r j Pasternak, r j Pasternak, r j Pasternak, r j	8007070357 8007070303 8007120410 8007120357 8007160445	50-333	PETERBON, J M PETERBON, M R PETERBON, M R PETRICK, N A PETRICK, N A	8009220342 8009270476 8009300028 8009170442 8009150196*	50-320 P XPORTLIC XPORTLIC 50-482 8 50-482 8	U "BVOGATOG U "BVOGATOG U "BVOGATOG U "BVOGATOG U "EVOGATOG	8009180104* 8009290320* 8009100223* 8009110613 8009250325*	04797 04799 04799 04799 04799
PASTERNAKIR J	8007160458	50-333 8	PETRICK, N A PETRICK, N A PETRICK, N A PETRONE, C D PETRONE, C D	8009170416	50-482 G	POTAPOVB. U	8007180562	QA999
PASTERNAKIR. J	8009190489	50-333 9		8009030541	50-482 A	POTAPOVB. U	8007180527	QA999
PASTORE, J	8009240014*	FOIA		8009190441	50-482 K	POTAPOVB. U	8007080465	QA999
PATER J,	8009120479*	50-361 0		8009100861*	50-277 G	POTAPOVB. U	8007120334	QA999
PATONIH D	8009020429	50-329 0		8009020472*	50-289 H	POTAPOVB. U	8007120654	QA999
PATON, W D	8009250004	50-329 0	PFAFF,8	8009100069	40-4659	POTAPOVB, U POTAPOVB, U POTAPOVB, U POTAPOVB, U POTAPOVB, U	8009150173=	04799
PATON, W D	8009260009	50-389 0	PFAFF,8 J	8009100212*	40-6659		8009150017	04799
PATON, W D	8009290039	50-329 0	PFAFF,8 J	8008080167	40-6659		8009150171	04799
PATTEN, T W	8009260482*	TOPREP	PFAFF,8 J.	8009100222*	40-6659		8009150224=	04799
PATTERSON, E S	8009260394*	50-289 T	PFEFFERKORN,U	8009030494	50-488 0		8009190020=	04799
PATTI.F.J	8009190684	NUREO	PFEFFERKORN.W	8009250015	50-488 0	POTAPOVS, U	8009170155	0A999
PATTON.L.H	8009120007*	CONTRACT	PHILLIPS.H B	8009170385*	50-498 0	POTAPOVS, U	8009170196	0A999
PAUL.P.A.	8009290037*	FOIA	PHILLIPS.H P	8009260665*	50-344 0	POTAPOVS, U	8009180070#	0A999
PAULEON.H.A	8009020340	50-155 P	PHILPOTT.F T	8009180409*	50-287 9	POTAPOVS, U	8009150221	0A999
PAULEON.H.A	8009050500	50-155 P	PICKLE.J J	8009110322*	50-320 H	POTAPOVS, U	8009250307	0A999
PAULBON, W A PAULBON, W A PAULBON, W A PAULBON, W A PAULBON, K	8009050504*	50-155 P	PICKLE, J J.	8009110319*	50-320 H	POTAPOVS, U	8007100208	GA999
	8009050509*	50-155 P	PICKLE, J J	8009240485	50-466 U	POTAPOVS, U	8007150175	GA999
	8009150042	50-155 P	PIERCE, R. L	8009100061*	CONTRACT	POTAPOVS, U	8007180072	GA999
	8009150046	50-219 P	PIERSON, G W	8009170234	40-4492	POTAPOVS, U	8007180484	GA999
	8009120188	50-361 H	PIERSON, G W	8009110266	40-4492	POTAPOVS, U	8007180036	GA999
PAWLICKI, 8, 8	8007160572	50-375 E	PIODIT, D R	8009110399*	50-361 0	POTAPOVA, U	8009190014	GA999
PECK, C C	8007150165*	40-3372	PIODIT, D R	8009110399*	50-361 0	POTAPOVA, U	8009180169	GA999
PECK, C. C,	8007270074*	70-1308	PIODIT, D, R	8009110399*	50-361 0	POTAPOVA, U	8009290310	GA999
PEDERSEN, K	8007170537*	FOIA	PIODIT, D, R	8009110396	50-361 0	POTTER, M F	8003190525*	PT9
PEET, W, J	8007180064*	QA777	PIODIT, D R	800919083	50-361 0	POTTER, J P	8009040068*	27-39
PELLID M.	9009120224	50-289 0	PICATT.D R	8007170083	50-361 0	POTTER.J P	8007110208*	27-39
PELLID M.	8009120232	50-289 0	PILANT.J M	8007100031	50-298 0	PRATT.C M	8005210547	PR
PELLID M.	8009120224	50-289 0	PILANT.J M	8007020102	50-298 0	PRESTON.C C	8009050200	RES
PELLID M.	8009120232	50-289 0	PILANT.J M	8007020078	50-298 0	PREVENSLIK,T.V	8009020017*	50-537
PELLID M.	8009230439	50-289 0	PILANT.J M	8007020101	50-298 0	PRICE,H L	8009240054*	FOIA
PENCE, W B	8009030922*	50-317 8	PILANT, J. M	8009100844*	50-278 G	Price, H L.	8009190595*	FOIA
PENCE, W B	8009230536*	50-317 8	PILANT, J. M	8009190478	50-278 P	Price, H L	8009240041*	FOIA
PENCE, W B	8009230544*	50-317 8	PILANT, J. M	8009030551	50-278 F	Price, H L	8009240026*	FOIA
PENCE, W B	8009230592*	50-317 8	PILANT, J. M.	8009260282	50-278 R	Price, H L	8009240018*	FOIA
PENCE, W. B	8009300470*	50-317 8	PILANT, J. M	8009170287	50-278 P	Price, H L	8009240059*	FOIA
PENDERORAFT, R.	8007030546*	50-348 \$	PISH, M D	8007080352*	50-317 F	PRICE, H L	8009190659#	FOIA
PENDERORAFT, R.	8007030417*	50-348 \$	PLATO, P	8007160446	NUREO	PRICE, A L	8009190647#	FOIA
PENDERORAFT, R.	8007150271*	50-348 \$	PLAYTON, 8 J	8006080173*	40-8659	PRICE, H L	8009190642#	FOIA
PENDERORAFT, R.	8007150275*	50-348 \$	PLESSET, M. 8	8007170766	50-327 O	PRICE, H L	8009240108#	FOIA
PENDERORAFT, R	8007230410*	50-348 R	PLESSET, M 8	8007100628	RECOD	PRICE, J E	8009300561	50-201

AUTHOR	ACCESSION NUMBER	CATE		AUTHOR	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR	ACCESSION NUMBER	SUBJE	CT ORY
4 C'ATTIBA,D A C'ATTIBA,D A C'ATTIBA,D A C'ATTIBA,D A C'ATTIBA,D	8007030123 8007020303 8007020222 8007100702	50-404 50-327 50-259 70-143 50-346	, a , a	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007270274 8007270277 8007270282 8007270287 8007270273	50-348 50-250 50-321 50-261 50-488	0 0 0 0 0	PACE,P L PACE,P L PACE,P L PACE,P L PACE,P L	6007020372* 8007120315* 8007120316* 6007120395* 6007120318*	50-335 50-251 50-335 50-250 50-335	8
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009030125 8009030128 8009030129 8009030130 8009030137	50-302 50-416 50-395 50-395 50-486	0 0	O'REILLY, J P G'ROURKE, S A OBERG, C T OBERG, C R OBERG, C R	8009290297 8009030493 8006120884* 8009090646* 8009150348*	50-269 71-9853 PT9 50-482 50-482	a a	PACE.P L PACE.P L PACE.P L PAGAND,F O PAGE.R O	8009150290 \\ 8009300494\\ 8009300485\\ 8009100378\\ 8009170079	50-335 50-250 50-335 50-10 70-115	8 8 F
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007030141 8007030146 8007030154 8007030158 8007030163	50-280 50-259 50-321 50-250 50-261	G G	DEERG.C.R DESTMANN.M J OHLSSON.K OLLER.R E OLSEN.N N	8007150362* 8007260665* 8007170726 8007150173* 8007070614	50-458 50-346 REGGD QA999 XPORTL I	e e c	PAGE.R O PAGE.R O PAGE.R O PAGE.R O PAGE.R O	8007240334 8007150181 8007250472 8007250476* 8007250464	70-33 70-258 70-125 70-125 70-115	7
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	6007030175 8007030181 8007160036 8007160037 8007160040	50-269 50-437 50-416 50-321 50-324	a	OLSEN, A F OLSEN, A F OLSEN, F M OLSHAN, L N OLSON, R C	8009110667 8009030443 8009260014 8009230230 8009030014	70-824 50-99 50-409 50-286 NUREO	P O P	PAGLAIRO, J PADLINO, R PAPAY, L T PAPERIELLO, C J	8009290031* 8009090250* 8009090470 8009300431 8009290079*	FOIA 50-289 50-361 50-361 FOIA	9 8
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009230388 8009230391 8009230391 8009230394 8009230397	50-259 70-824 70-27 70-115		OLBON, N J. OLBON, J F. OLBON, J F. OPREA, O W OPREA, O W	8007020219 8007030726 8009300039 8009030170* 8009180479	50-445 50-282 50-282 50-498 50-498	0 0 0	PAPERIELLO,C J PAPERIELLO,C J PAPERIELLO,C J PAPERIELLO,C J PAPPAB,H	8009290037* 8009290059* 8005300695* 8006120884* 8009090117	FOIA FOIA PT9 PT9 OR0	
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009230378 8009230400 8009230404 8009050422 8009120048	70-120: 50-332 70-143 50-280 50-518	1 @ @ @	OPREA.O W OPREA.O W OPREA.O W OPREA.O W OPREA.O W	B009190147 B009180467 B009180461 B009020288 B009020290	50-498 50-498 50-498 50-498 50-498	8 9 8 8	Pappas, H Pappas, H Pappas, H Pappas, H Pappas, H	8009030305 8009160052 8009230423 8009180062 8009120117	ORQ ORQ ORQ ORQ 50-10	0
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009120072 8009120077 8009120080 8009120082 8009160109	50-324 50-321 50-416 50-259 50-437	œ , œ , œ ,	OPREA.O W OPREA.O W OPREA.O W OPREA.O W OPREA.O W	8007300945 8007300555 8007040377 8007050364 8007110384	50-498 50-498 50-498 50-498 50-498	0 3 5 0 8	Pappab, H Pappab, H Pappab, H Pappab, H Paris, D	8009180123 8009230104 8009240384 8009230537 8009170175	ORO ORO ORO ORO 50-155	٠
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009160110 8009160113 8009160115 8009160118 8009160120	50-348 50-302 50-416 50-395 50-395	a a a a	Oprea. O W Oprea. O W Oprea. O. W Oprea. O W Oprea. O W	B0090B0201 B009110367 B009300B36 B009230603 B009230617	50-498 50-498 50-498 50-498 50-498	A 8 0 8	PARKER, W O	8009240220* 8009100807* 8009160341* 8009240212* 8009110275	50-369 50-269 50-269 50-369 70-2623	0 0 0
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P,	8007160124 8007160133 8007160137 8007160143 8007160147	50-241 50-489 50-269 50-250 50-321	0 0 0	OPREA, O. W OPREA, O. W OPREA, O. W OPREA, O. W OPREA, O. W,	8009150559 8009230658 8009240439 8009230402 8009230461	50-478 50-478 50-478 50-478 50-478	K 8 8 8	PARKER, W. O	8007240278* 8007240206* 8007040640 8007160540* 8007150367*	50-413 50-359 50-269 50-269 50-370	9 9 9
O'REILLY, J P O'REILLY, J P O'REILLY, J, P O'REILLY, J, P O'REILLY, J P.	8009160153 8009160172 8009230249 8009230252 8009230258	50-259 50-280 50-348 50-261 50-269	0 0 F F F	OPREA, O W ORDERS, W ORLOSKY, P M ORMONDE, S ORNICH, J.	8009300453 8009300440* 8009160340* 8009120594 8009300338	50-498 50-269 50-57 FOIA 50-382	8 1 8	PARKER, W O PARKER, W O PARKER, W O PARKER, W. O. PARKER, W O	8009110423 8009030183 8009050545 8009170371 8009240290*	50-413 50-369 50-369 50-413 50-413	0 0 0
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009230258 8009230261 8009230265 8009230267 8009230273	50-302 50-250 50-321 50-259 50-260	4 4 4 4	DRTENBERO,L 1 OBANN,E W OBANN,E W OBANN,E W OBANN,E W	B007080279* B007030703 B007030710 B007030703 B007030710	50-348 50-367 50-367 50-367 50-367	P Q Q Q Q	PARKER, H. O PARKER, H O PARKER, W D. PARKER, W D PARKER, W D	8009240297* 8009140642 8009160633 8009170233 8009240262*	50-413 50-413 50-369 50-269 50-370	G G G
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009230277 8009230323 8009230325 8009240274 8009240277	70-824 70-27 70-143 70-1349 70-2892		OBANN, E W OBANN, E W OBANN, E W OBANN, E W	8009230008 8009230008 8009230382 8009230393 8009230382	50-367 50-367 50-367 50-367	0 0 0 0	PARKER, W O, PARKER, W O PARKER, W, O PARKER, W O, PARKER, W O	8007020029 8007020044 8009030507 8009300626* 8009020025	50-369 50-269 50-287 50-269 50-269	F R P O P
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009260314 8009260316 8009260317 8009120248 8009120251	70-2621 70-2520 70-1397 50-437 50-348	Q Q	DBANN, E. W. DBANN, E. W. DBANN, E. W. DBTRANDER, F. W. DTT, L. J	8009230393 8009260011 8009260011 8009300566 8009100944	50-367 50-367 50-367 50-344 NUREQ	0 0 0	PARKER, W O	8007020371 8009110658 8009120262 8009250191 8009040383	50-369 50-269 50-370 50-369 50-369	A 9 9 9 9 9
O'REILLY, J. P O'REILLY, J. P O'REILLY, J. P O'REILLY, J. P	8009120258 8009120260 8009120265 8009120286 8009120290	50-302 50-414 50-375 50-395 50-261	G G G G	OTT,R F OTT,W R. OTTINGER,R L. OTTOBON,H L. OTTOBON,H L.	8009300595* 8009300303 8009110491* 8009090811 8009170207	CONTRACT NUREO 50-320 50-206 50-206	U Q q	PARKER, W. O.	8007080312 8007120587 8007120578 8007030445 8007030468	50-413 50-413 50-369 50-269 50-270	5 9 8
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009120300 8009120308 8009120311 8009120314 8009120340	50-498 50-250 50-321 50-280 50-259	0 0 0 0	OTTOSON, H L OTTOSON, H L OTTOSON, H L OTTOSON, H L OTTOSON, H L	8007130011 8007160630 8007160521 8007020078 8007030533	50-206 50-206 50-206 50-206 50-206	Q Q S R	PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8009090577 8009100489 8009120418 8009160261 8009120414	50-289 50-289 50-270 50-389 50-269	R P S A S
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007120343 8007230521 8007230525 8007230526 8007240375	50-269 50-259 50-321 50-324 50-259	@ @ @ @	OVERBERGER, C G.' OVERLID, T W OVERLID, T W OVERLID, T W	8007150375* 8007150225 8007030401* 8007230641* 8007230630*	50-324 REGOD 50-263 50-263 50-263	G B B B	PARKER, H. O PARKER, W O PARKER, W. O PARKER, W O PARKER, W O	8009110345 8009150383 8009150439 8009150548 8009250339	50-369 50-297 50-369 50-369 50-413	A B A Q
O'REILLY, J. P O'REILLY, J. P O'REILLY, J. P O'REILLY, J. P	8009260397 8009260517 8009290269 8009290271 8009290274	50-395 50-280 50-437 50-416 50-302	Q Q Q	OWEN, J B OWSLEY, O F. OWSLEY, O F OWZARSKI. P C OZKER, D	8009220139 8009040490 8009260477 8009110419 8009220242*	TOPREP 50-335 TOPREP RE8 50-329	P A	PARKER, W O PARKER, W O PARKER, W O PARKER, W D. PARKER, W O	8009140477 8009140400 8009300137 8009180395 8009180374	50-287	6 0 6 A

ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	
PARKER, U. O. PARKER, U. O. PARKER, U. O. PAPKER, U. O. PAPKER, U. O. PAPKER, U. O.	E009190462 E009180322 E009190399 E009190506 E009230724	50-269 R 50-369 A 50-369 A 50-369 A 50-269 P	PENDERGRAFT, R PEOPLES, D L PEOPLES, D L PEOPLES, D L PEOPLES, D L	8009230748* 8009180261 8009110217 8009020294 8009170230	50-368 8 70-2609 70-2609 NUREO 50-237 Q	PLESSET.H S PLESSET.M S PLESSET.M S POCHAL.W F POCHAL.W F	6009150238 8009150245 6009150249 8009100493 8009160287	50-327 ACRS ACRS XPORTLIC XPORTLIC	
Parker, W O Parker, W O Parker, W O Parker, W O Parker, W O	6009240409 8009230496 8009230509 8009240448 8009240489	50-369 A 50-270 B 50-270 B 50-369 V 50-369 A	PERANICH, M W PERDIKARIB, P C PERKINB, T J PERKINB, T J PERKINB, M A	8009150055* 8009020355 8009120413* 8009120417* 8009050243	50-445 G NUREG 50-220 V 50-220 V 50-320 S	POCHAL, W F POGALIES, J X POGALIES, J K POGGIO, A POIRIER, L J	8009230783 8009100406 8009100406 8009160498 8009080352#	XPDRTLIC 50-361 50-361 RES 50-317	0 0 F
PARKER, N O PARKER, N O PARKER, N O PARKER, N, O PARKER, N O	8009290371 8009260450 8009290303 8009300428 8009300434	50-349 A 50-287 8 50-369 A 50-249 J 50-369 A	PERKINS, J PERLMAN, J PERLMAN, J PERLMAN, J PERLMAN, J	8009300010 8009120514* 8009120037* 8009120115* 8009150414*	50-289 G 50-206 P CONTRACT CONTRACT CONTRACT	POIRIER, M R POIRIER, M R POIRIER, M R POIRIER, M R POIRIER, M R	8007070453 8007150417 8007150417 8007140275 8007140275	50-498 50-445 50-445 50-445 50-445	M M M
MAKER, 4 O MAKINSON, 7 F MASONS, E M MATLOW, J. O MATLOW, J. O	8007300486 8007300457 8007110411 8007230168 8007030046	50-269 P 50-124 P 50-266 H 70-1143 70-1120	PERLMAN, J PERLMAN, J PERLMAN, J PERNY, C D PERRIGO, L D	8009150424* 8009240057* 8009300276* 800930439* 8009110483	50-206 P 50-206 P CONTRACT 70-143 RES	POIRIER, M R POIRIER, M R POIRIER, M R POIRIER, M R POLANSKI, X	8009150182 8009150182 8009250318 8009250318 8009160425*	50-445 50-445 50-445 50-445 50-295	8 8 8
O L'HOLTSKI O L'HOLTSKI O L'HOLTSKI O L'HOLTSKI	8009080489 8009150360 8009170242 8009160235 8009150389	70-487 70-1143 70-1113 70-754 70-1257	PERROTTI.D J PERRY, J C PERRY, J C PETERSON, K PETERSON, R M	8009220184* 8009100467* 8009260910* 8009160583 8009220116	50-335 Q 50-344 6 50-344 S 50-227 P HABTE MOT	POLK, P J POLLACK, 8 POLLARD, R D POLLARD, R D POLLARD, R D	8009190770 8009120435 8009230011 8009300420* 8009300422*	50~220 50~361 50~289 50~289 50~289	P H T O O
ARTLOW, J O ARTLOW, J O ARTLOW, J O ASSAMANI, B ASTERNAK, R J	8009150395 8007270266 8007270374 8009170181* 8009110278*	70-143 70-1201 70-143 MISC 50-333 G	PETERBON, M R. PETERBON, M R PETERBON, M R PETERBON, M R PETERBON, M R.	8007020120 8007020127 8007160274 8007250333 8007020471	XPORTLIC XPORTLIC XFORTLIC XFORTLIC XFORTLIC	POLLEIT, R POND, Q D POCLE, D PORTER, B W PORTER, W L	6007120442 6007260478 6007030206* 8007300377 8007260010	50-361 50-213 50-302 50-289 50-369	H R R O
ASTERMAN, R. J. ASTERNAN, R. J. ASTERNAN, R. J. ASTERNAN, R. J. ASTERNAN, R. J.	8009190936 8009020115 8009090014 8009100117 8009100268	50-333 Q 50-333 Q 50-333 Q 50-333 R	PETERBON, M R	8009020478 8009100198 8009020464 8009110591 8009110606	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PORTER: W L PORTER: W L PORTER: W L POTAPOVS: U POTAPOVS: U	8009240246 8009240273 8009290028 8009150207# 8009150229#	50-349 50-349 50-488 GA999 GA999	0
ASTERNAK, R. J. ASTERNAK, R. J. ASTERNAK, R. J. ASTERNAK, R. J. ASTERNAK, R. J.	B009030409 B00903041B B009020354 B009020394 B009020409	50-333 8 90-333 8 90-333 8 90-333 8 50-333 8	PETERSON, M R	8007110607 8007110755 8007160171 8007180420 8007160233	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8009180500= 8009150200= 8009150227= 8009190031= 8009190027=	QA999 QA999 QA999 QA999 QA999	
ASTERNAK, R J ASTERNAK, R J ASTERNAK, R J ASTERNAK, R J ASTERNAK, R J	8009090359 8009090303 8009120410 8009120359 8009160445	50-333 8 50-333 R 50-333 8 50-333 8 50-333 8	PETERBON, J M PETERBON, M R PETERBON, M R PETRICK, N A PETRICK, N A	8007220342 8007270476 8007300028 8007170442 8007170196*	50-320 P XPORTLIC XPORTLIC 50-482 8 50-482 8	POTAPOVB, U POTAPOVB, U POTAPOVB, U POTAPOVB, U POTAPOVB, U	8009180104* 8009290320* 8009100223* 8009110613 8009250325=	QA999 QA999 QA999 QA999 QA999	
STERNAK, R. J STERNAK, R. J STORE, J. O NTE, R. J NTON, H. D	8007160458 8007170487 8007240014* 8007120479* 8007020429	50-333 8 50-333 8 FOIA 50-361 0 50-327 0	PETRICK,N A PETRICK,N A PETRICK,N A PETRONE,C D PETROBKY,J A	8009170416 8009030541 8009190441 8009100861* 8009020472*	50-482 Q 50-482 A 50-482 K 50-277 Q 50-289 H	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8009180562 8009180529 8009080465 8009120334 8009120654	0A999 0A999 0A999 0A999 0A999	
ITON: W D ITON: W D ITON: W D ITTEN: T W ITTERSON: E, 8	8009250004 8009260009 8009290039 8009260482* 8009260394*	50-329 0 50-389 0 50-329 0 TOPREP 50-289 T	PFAFF,8 PFAFF,8 J. PFAFF,8 J PFAFF,8 J PFEFFERKORN,U	8009100069 8009100212* 8008080187 8009100222* 8009030696	40-6659 40-6659 40-6659 40-6659 50-489 Q	POTAPOVB. U POTAPOVB. U POTAPOVB. U POTAPOVB. U POTAPOVB. U	8009150173# 8009150017 8009150171 8009150224# 8009190020#	QA999 QA999 QA999 QA999 QA999	
TITLIF J TTON,L W ULIP.A. ULSON,H A ULSON,H A	8009190684 8009120007* 8009290037* 8009020340 8009050500	NUREO CONTRACT FO1A 50-155 P 50-155 P	PFEFFERKORN, N PHILLIPB, H B PHILLIPB, M P PHILPOTT, F T PICKLE, J J	8007250015 8007170385* 8007260665* 8007180409* 8007110322*	50-488 Q 50-498 Q 50-246 Q 50-287 8 50-320 H	POTAPOVB. U POTAPOVB. U POTAPOVB. U POTAPOVB. U POTAPOVB. U	8009170155 8009170156 8009180070* 8009150221 8009250307	0A999 0A999 0A999 0A999 0A999	
ULSON, HA ULSON, HA ULSON, HA ULSON, H.A ULSON, K	8007050504* 8007050507* 8007150042 8007150046 8007120188	50-155 P 50-155 P 50-155 P 50-217 P 50-361 H	PICKLE, J J. PICKLE, J J PIERCE, R L PIERSON, O W PIERSON, O W	8009110319* 8009240485 8009100061* 8009170234 8009110266	50-320 H 50-466 U CQNTRACT 40-4492 40-4492	POTAPOVS. U POTAPOVS. U POTAPOVS. U POTAPOVS. U POTAPOVS. U	8009100208 8009150195 8009180092 8009180484 8009180056	GA999 GA999 GA999 GA999	
ULICKIJB.B CK.C.C. CK.C.C. CERBEN:K ET.H J.	8009160592 8009150165* 8009290094* 8009190539* 8009180064*	50-395 E 40-3392 70-130B FOIA QA979	PICOTT, D R PICOTT, D R PICOTT, D R PICOTT, D R PICOTT, D R	8007110377* 8007110377* 8007110379* 8007110376 8007170083	50-361 Q 50-361 Q 50-361 Q 50-361 Q 50-361 Q	POTAPOVA, U POTAPOVA, U POTAPOVA, U POTTER, M F POTTER, J P	8009190014 8009180169 8009290310 8003190525* 8009040068*	0A999 0A999 0A999 PT9 27-39	
LC+ D. H. LC+ D. H. LC+ D. H LC+ D. H LC+ D. H.	8009120226 8009120232 8009120226 8009120232 8009230639	50-289 0 50-289 0 50-289 0 50-289 0 50-289 0	PIGOTT, D R. PILANT, J M. PILANT, J M. PILANT, J. M. PILANT, J M	8009190083 8009100031 8009020102 8009020098 8009020101	50-361 0 50-298 0 50-298 0 50-298 0 50-298 0	POTTER, J P PRATT. C H PRESTON, C C PREVENSLIK, T V PRICE, H L	8009110208# 8005210447 8009050200 8009020017# 8009240054#	27-39 PR RES 50-537 FOIA	٨
KE. H B KE. H B KE. H B. KE. K B KE. K B	8009030522* 8009230536* 8009230546* 8009230592* 8009300470*	50-317 8 50-317 8 50-317 8 50-317 8 50-317 8	PILANT, J. M PILANT, J M PILANT, J M PILANT, J M PILANT, J M	8009100844* 8009190478 8009030551 8009260282 8009170287	50-298 Q 50-298 P 50-298 F 50-298 R 50-298 P	PRICE, H L PRICE, H L PRICE, H L PRICE, H L PRICE, R L	8009190695* 8009240041* 8009240026* 8009240018* 8009240059*	FOIA FOIA FOIA FOIA	
DERORAFT, R DERORAFT, R DERORAFT, R DERORAFT, R DERORAFT, R.	8007030346* 8007030417* 8007180271* 8007150275* 8007230410*	50-368 8 50-369 8 50-368 8 50-368 8 50-368 R	PISH.M.D PLATO.P PLAYTON.S J PLESSET.M.S PLESSET.M B	8007080352* 8007160446 8008080173* 8007170766 80071700628	50-317 F NUREQ 40-6659 50-327 Q REGOD	PRICE.H L PRICE.A L PRICE.H L PRICE.H L PRICE.J E	8009190659* 8009190647* 8009190642* 8009240108* 8009200561	FOIA FOIA FOIA FOIA 50-201	o

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
PRIHE,W J PRIHE,W J PRINTZ,T A PRITCHARD,W C PUCKETT,J M	8009100077* 8009120019* 8009230704* 8009120626 8009240195*	CONTRACT 50-304 8 50-247 P	REID, R W REID, R W REID, R W REID, R W REID, R W	8009230763 8009150033 8009050275 8009050238 8009300046	50-321 P 50-277 P 50-289 P 50-312 F 50-346 P	REYNOLDB, N S	8009110048 8009110781 8009110781 8009110781 8009170141	50-445 50-445 50-445 50-445 50-445
PULIDO, M PULLINS, C PUNT, N A PURCELL, J PUSCHEL, K A	8007110430 8007030563* 8007070380 8007030424 8007170065	50-320 H 50-367 R FOIA	REID,R.W REID,R W REID,R W REID,R W REID,R W	8007300052* 8007300057* 8007170304 8007170316 8007170362	50-346 P 50-346 P 50-313 0 50-312 0 50-277 0	REYNOLDS, N S REYNOLDS, N S RHODDS, O O RHODE, O K RHODE, O K	8007230005 8007230005 8007170241* 8007070848* 8007230078	50-445 50-445 50-397 50-410 50-410
QUICK, D QUIGLEY, T W QUIGLEY, T W QUINTENZ, T E	8009130113 800930063* 8009090198 8009150158 8009300569*	50-261 9 40-8743 40-8743 50-219 8	REID,R W REID,R W REID,R W REID,R W REID,R W	8009190375 8009190572 8009240597 8009260592 8009260664	50-302 Q 50-346 Q 50-321 Q 50-287 Q 50-269 Q	RHODE, O K RHODE, O K RIGCITELLI, J RICE, T	8009020248 8009150851 8009100093* 8009240121* 8008130378*	50-410 A 50-410 A COMMISSION 50-320 H 40-299
RABUCK, B RADER, R H RAFFELSON, C I) RAGER, M RAGER, M	8009150336* 8009230027 8009020552 8009030471* 8009170320*	50-289 H 50-395 Q 40-8745 50-331 S 50-331 6	REID.R W REID.R W REID.R W REID.R W REID.R W	8009120645 8009120648* 8009120653* 8009190582 8009180176	50-209 P 50-289 P 50-289 P 50-302 P 50-312 P	RICHARDS,R B RICHARDSGN,T F RICKARD,C L RIDGWAY,K R RIDGWAY,D A	8009160420 8009240038* 8009120697 8009260420* 8009030118	50-201 Q CGNTRACT 50-275 B 50-407 Q 50-320 Q
RACER.M RACER.M RACER.M RACER.M S RACER.M S	8009170328* 8009170352* 8009170360* 8009170367* 8009300501*	50-331	REID, R W REID, R W REID, R W REID, R W	8007170145 8007270242 8007260346 8007260353* 8007260364*	50-346 P 50-287 P 50-346 P 50-346 P 50-346 P	RIDOWAY, D. A RIETHLE, W E RIETHLE, W E RIOGS, M W RIOGS, M W	8007030118 8007240541 8007300550 8007110277 8007110277*	50-320 P 50-320 P 50-287 R 50-293 O 50-293 O
RAMEY, J T RAMSTHALER, J A RANOOLPH, M L RANDOLPH, H L RANDOLPH, J K	8009190688* 8009190768 8009110634 8009110498 8009230694*	F01A RES RES RES 50-311 8	REID, R W REID, R W REID, R. W REID, R W REID, R W	8007170154 8007250421 8007250425 8007250427 8007250430	50-249 P 50-321 P 50-313 P 50-302 P 50-277 P	RIGOS, M W RIGOS, R RITTER, D RIZZO, P O RIZZO, P O	8009110304* 8009240145* 8009110416* 8009030549* 8009120378*	50-293 Q 50-313 B COMMISSION 50-318 B 50-317 B
RASKIN, D B. RASKIN, D B RASKIN, D B RASKIN, D B RASKIN, D B	8007040271 9007040271 8007260207 8007260210* 8007260210*	50-466 0 50-466 0 50-466 0 50-466 0 50-466 0	REID,R W REID,R W REID,R W REID,R W	8009250434 8009250491 8009260200 8009260538 8009260559	50-269 P 50-346 P 50-289 H 50-312 P 50-289 P	RIZZO,P Q RIZZO,P Q ROBERTS,K ROBERTS,K P ROBERDS,H H	8009120455* 8009230695* 8009100036* 8009100877* 8009170158*	50-317 8 50-317 8 50-273 0 50-273 0 0A979
RATHKOPF, C L RATHKOPF, C L RATHKOPF, C L RAUSCH, H P RAUSCH, T J	8009100074* 8009150241* 8009300306* 8009030359 8009180466	50-289 H 50-320 H 50-275 H TOPREP 50-10 Q	REID,R W REID,R W REID,R W REID,R W	8009290077 8009300230 8009290155 8009300145 8009300148*	50-289 F 50-277 F 50-289 P 50-313 P 50-313 P	RDBERTS, H R ROBERTSON, J D ROBERTS, D ROBERTS, D ROBINSON, C R	8009170127 8009030085* 8009300237 8009100666 8009230147*	40-8681 CONTRACT 40-8681 40-8681 70-1417
RAUSCH.T.J RAUSCH.T.J RAUSCH.T.J RAUSCH.T.J RAYMOND.W	8009190007 8009250468 8009260109 8009300200 8009100877#	50-373 @ 50-373 @ 50-10 @ 50-10 @ 50-273 @	REID,R W REIDHAAR,D L REINHART,M REIS,H F REIS,E J	8009300155# 8009230016 8009170269# 8009020073 8009020420	50-313 P 50-142 Q 50-320 H 50-250 Q 40-1162	ROCKHOLD, H C RODY, J P RODI, J P, RODRIQUEZ, R J ROEDER, J R	8009180309 8009100048 8009110264 8009160295 8009080209*	50-336 P XPORTLIC XPORTLIC 50-312 R 71-9508
RAYMONO, H J REAVES, T. E REAVIS, J A REBELOWSKI, T. REBELOWSKI, T	B007170575 B007030504 B007170473* B007120210* B007100853*	50-271 8 50-416 H 50-269 R 50-247 Q 50-247 Q	REIS.E J REITLER,E K REIZEN.M B REKITO,N A REKITO,N A	8009270498 8009170108 8009110350* 8009190081* 8009150184*	M1SC 70-1151 Contract 50-293 G 50-277 G	ROEGIERS, J C ROOERS, R ROOERS, R F ROOERS, A E ROOERS, W H	8009190248 8009020304* 8009220341* 8009230475* 80090904460*	50-440 K 50-287 H 50-321 Q TOPREP 50-321 B
RECORD, D J REGER, M REED, C REED, J G REEVES, M	8007080371 * 8007080333 8007240458* 8007120268 8007020349	50-327 8 50-358 F 50-275 0 50-489 H NUREO	REKITO, W A REMICK, F J REMLEY, M E REMLEY, M E REMBEROER, D L	8009110518* 8009110813 8009120620 8009150394 8009030342*	50-217 Q 50-237 Q 70-25 71-5088 50-508 B	ROISMAN,A Z ROISMAN,A Z ROISMAN,A Z. ROMANO,A J ROMAN,T W	8009090342* 8009090342* 8009090363* 8009110321 8009120413*	50-247 0 50-247 0 50-247 0 NUREO 50-220 V
REEVES, E REGAN, H REHM, T A REHM, T A	8009100007 8009090155 8009190397* 8009090083 8009090632	50-295 P 50-320 P FOIA COMMISSION COMMISSION	RENBERGER, D L	8009100179 8009190677 8009110422* 8009020043 8009160622	50-508 G NUREO 50-460 G 50-397 K 50-460 G	ROMAN, T W ROMANO, F R ROMAN, T W ROMAN, T W ROMINE, D	8009120417* 8009020171* 8009160213 8009150299* 8009080380*	50-220 V 50-320 H 50-220 R 50-220 R 50-327 B
REHM, T A REHM, T A REIGHHOLD, W P REIGH, M	8009110753 8009180521 8009300188 8009160023 8009240686	COMMISSION COMMISSION 70-2599 NUREO	RENBERGER, D.L. RENBERGER, D.L. RENBERGER, D.L. RENBERGER, D.L. RENBERGER, D.L.	8009170393 8009030321 8009090630 8009090630	50-460 G 50-397 A 50-397 G 50-397 K 50-397 G	ROMINE ROMINE, D ROMOBTAD, F ROOD, H ROOD, H	8007070588* 8007160380* 8007180369* 8007100021 8007100417	50-327 8 50-327 8 50-320 H 50-361 T 50-206 P
REID,R W. REID,R W. REID,R W. REID,R W.	8007240617* 8007110642 8007220205 8007070212 8007110637	50-302 P 50-289 H 50-289 H 50-289 H 50-289 H	RENBERGER, D. L RENBERGER, D. L RENBERGER, D. L RENBERGER, D. L RENDERGER, D. L	8007120368 8007080321 8007070476 8007120360 8007140312	50-397 Q 50-397 A 50-397 A TOPREP 50-397 %	ROOD, H ROOD, H ROOD, H ROOD, H	6009140227 8009140252 8009240622 8009110547 8009120273	50-361 A 50-361 A 50-361 A 50-361 A
	8009220188 8009220198 8009220201 8009220202	50-289 H 50-289 H 50-289 H 50-289 H 50-289 H	RENBERGER, D L	8009230352 8009240465 8009230696 8009240464 8009300352	50-397 A 50-397 B 50-397 A 50-397 S 50-397 A	ROOD, H ROONEY, M A ROONEY, M A ROONEY, M A ROONEY, M A	8007170713 8007100325 8007070461 8007160374 8007300580	50-361 A 70-1308 70-1308 70-1308 70-1308
		50-289 8 50-277 P 50-277 F 50-278 P	RENBERGER, D. L. RENBERGER, D. L. RENBERGER, D. L. RENNELS, A. E. RENNELS, A. E.	8009300415 8009300346 8009300379 8009050358 8009260021	50-397 B 50-460 Q 50-397 B 40-2061 40-2061	ROOT, L D ROOT, L D ROOT, L D ROOT, L, D	8009020170 8009170061 8009090026 8009020289 8009040424	50-331 0 50-331 0 50-331 0 50-331 P 50-331 0
		50-278 P 30-229 P 10-249 P '0-249 P 0-277 P	REVELEY, W T REVELEY, W T REYMOLDS, L E REYMOLDS, N S	8009170194 8009170194 8009300243* 8009260039 8009110048	50-516 Q 50-516 Q 50-346 Q 71-7097 50-445 Q	ROOT, L D ROOT, L D ROOT, L D ROOT, L D ROOT, L D	8009120593 8009170409 8009170427 8009170333 8009190933	50-331 0 50-331 0 50-331 0 50-331 P 50-331 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ROOT, L. D ROOT, L. D ROSE, D. O. ROSENBERO, A. D ROSENBAUM, B	6007230284 6007180387 6007220220 6007150083# 6007160434#	50-331 P 50-331 F 50-275 F 50-445 O TOPREP	SARSTEN, O E SATTERFIELD, D SAVER, R. C SAUNDERS, O A SAUNDERS, B L	8009160645 8009120494* 8009240684* 8009030455 8009290180	50-443 S COMMISSION 50-281 Q 40-8693 50-250 G	Schhencer. A Bchhencer. A Bchhencer. A Schhendihan. L Bchhencer. A	8009110707 8009150527 8009090612 8009150597 8009220042	50-275 A 50-327 P 50-275 F NUREO 50-275 H
ROBENBERO, R ROSENBAUM, D, M ROSENTHAL, A B ROSENTHAL, W P ROSE, D A	8009220321 * 8009190775 * 8009300407 8009190376 * 8009090235	50-267 Q 10CFR 50-348 Q 50-206 P 50-219 Q	SAXION, H SCALETTI, D C SCARAKU, R A SCARANO, R A SCARANO, R A	8009170157* 8009250451 8009180494 8009180034 8009170099	50-466 O 50-361 A WASTE MOT 40-8681 40-2259	BCHVENCER. A BCHVENCER. A BCHVENCER. A BCHVENCER. A BCHVENCER. A	8007080417 8007180248 8007270383 8007250150 8007250466	50-327 E 50-275 H 50-461 H 50-361 A 50-528 H
ROSS, D. M ROSS, D. A. ROSS, D. A ROSS, D. A ROSS, D. A	8007050205 8007070354 8007070351 8007070365* 8007070381*	71-9508 50-217 8 50-217 8 50-217 8 50-219 8	ECARAND, R A ECARANO, R A ECARANO, R A ECARANO, R A ECARAND, R A	8009160651 8009170250 8009020498 8009180336 8009100478	40-8692 Waste Hot 40-299 40-8452 Waste Hot	SCHWENCER, A SCHWENCER, A SCHWOERER, F SCINTO, J SCOTT, D J	8009260254 8009300329 8009300397 8009190630* 8009030509	50-327 E 50-327 D 50-482 A 50-217 O 50-237 S
ROSS, D. A ROSS, D. A ROSS, D. A. ROSS, D. RDSS, D. F.	8009090393 8009090369 8009090373* 8009250065 8009120664	90-219 8 50-219 R 50-219 B DISCLOSURE TOPREP	SCARANO, R A SCARANO, R A SCARANO, R A SCARANO, R A SCARANO, R A	8009100491 8009100936 8009170373 8009090768 8009150117	WASTE MOT 40-8084 40-299 Waste Mot 40-8743	SCOTT, D J SCOTT, D J SCOTT, J H SCOTT, J J	80070203B1 8007030456 8007260027 8007150576 8007180480*	50~237 S 50~10 R 40~8698 NUREO 50~369 H
R099, D A. R088, D, A R088, D A R088, D A R088, M J	8007160471 8007160474* 8007230488* 8007230481 8007260388*	50-217 8 50-217 8 50-217 8 50-217 8 50-289 T	SCARANO, R A SCARANO, R A SCHAEFFER, M R SCHAEFFER, M R SCHAEFFER, M R	8009150123* 8009150530 8009110492 8009110587* 8009110214*	40-8743 40-8502 XPGRTLIC XPORTLIC XPDRTLIC	SCOTT.D J SCOTT.D J SCOTT.D J SCOTT.D J	8009170223 8009230713 8009230676 8009300468 8009300472	50-466 C 50-10 R 50-237 S 50-237 S 50-237 S
ROSS, M. J ROSS, D. A ROSS, D. A ROSSI, C. E ROBZTOCZY, Z. P	8009260394* 8009230361 8009260447* 8009080299* 8009100407	50-289 T 50-219 R 50-219 B 50-348 P NUREO	SCHAFFETALL.R SCHAPKER.J F, SCHAPKER.J SCHAPKER.J F SCHAUDEL.S L	8009020257 8009110324* 8009170221* 8009270114* 8009180359	TOPREP 50-454 G 50-456 G 50-546 G 50-320 P	SEABORO, O T SEABORO, O T SEAL, H M SEELEY, O T SEGEV, A	80092400B2* 8009240016* 800915031B* 8009300398 8009300164	FOIA FOIA 50~352 H NUREO NUREO
ROTH: A J. ROTH: A J ROTHFLEISCH: J ROTHFLEISCH: J E ROTHFLEISCH: J	8009220222* 8009300013 8009020190 8009020518 8009190781	90-389 M 90-445 M 40-8745 40-8745 40-8692	SCHEER, J L SCHEER, J L SCHERER, A E SCHERER, A E SCHERER, A E	8007050254* 8007050255* 8007240520 8007110325 8007240360	50-278 S 50-278 S TOPREP 50-335 P 50-317 P	SEIDLE, N C SEIDLE, N C SEIDLE, N C SEIDLE, N C	8009150122* 8009150125* 8009150129* 8009150133* 8009150136*	50-445 0 50-445 0 50-445 0 50-445 0 50-445 0
ROTHFLEIBCH, J ROTHBCHILD, M V, ROTHBCHILD, M V ROTHBCHILD, M V ROTHBCHILD, M. V,	8009150209 8009020432 8009080033 8009080039 8009110794	40-8745 50-445 0 70-1308 50-445 0 50-445 0	SCHMIDT, Q R SCHMIDT, A D SCHMIDT, A D SCHMIDT, A D SCHMIDT, A D	8009030563* 8009020365 8009120312 8009120313	50-52B	SEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W C	8009100047 8009180095 8009050525 8009170380 8009170384	50-482 Q 50-443 Q 50-498 Q 50-498 Q 50-482 Q
ROTHSCHILD, M V ROUSE, L C ROUSE, L C, ROUSE, L C ROUSE, L C	B007230044 B007180447# B007100235* B007100741 B007170078	70-1308 40-2061 70-1257 70-754 70-1308	BCHMIDT, A D. BCHMIDT, A D BCHMIDT, A D BCHMIDT, A D BCHMIDT, A D	8009120307 8009150288 8009170279 8009300490 8009300482	50-335 8 50-335 9 50-250 R 50-250 8 50-335 8	SEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W C	8007070844 8007150337 8007150340 8007150342 8007100267	50-482 0 50-445 0 50-458 0 50-482 0 50-445 0
ROUBE, L. C ROUBE, L. C ROWE, C. A ROWNEY, E. M AUBIN, M. P.	8009170083 8009170084 8009100647* 8009190405 8009160322*	70-1308 70-1308 70-312 NUREO 50-142 P	SCHNEIDER.F.W SCHNEIDER.F W SCHNEIDER.F W SCHNELL.D F SCHRAEDER.A L	8009080530 8009090230 8009020237 8009020093 8009080352*	50-272 Q 50-272 Q 50-311 P 50-483 A 50-317 F	SEIDLE, W C SEIDLE, W C SEIDLE, W C	8007270227 8007250402 8007250370 8007170333 8007030157	50-445 Q 50-478 Q 50-459 Q 50-382 Q 50-498 Q
RUHLMAN.W.A RUITER,Q H RULEY,E RUSSELL,L B RUSSELL,L D.	8007030441* 8007070277* 800713041&* 8007170665 8007030320	50-280 Q 50-305 R 50-320 H 50-317 S 50-317 S	BCHROEDER, F BCHROEDER, F BCHROEOER, F BCHVESSLER, W BCHVLTZ, W H	8009050402 8009190197 8009180353 8009160527 80092900314	H18C ORO 50-466 0	SEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W C	8009300089 8009050517 8009300098 8009150338 8009150334	50-382 Q 50-458 Q 50-478 Q 50-458 Q 50-482 Q
RUSSELL, L B RUSSELL, L B RUSSELL, L B RUSSELL, L B RUSSELL, L. D	8007030343 8007120354 8007120447 8007120344 8007160315	50-318 6 50-317 8 50-317 8 50-317 6 50-317 8	SCHULTZIN B SCHULZEIR T SCHULTZIN B. SCHULZIR D SCHULTZID F	8007070435 8007020156 8007070433 8007100140 8007150373	50-320 H 50-367 Q 50-255 G 40-8113	SEIDLE. H C SEIDLE. H C SEKULER. S N SEKULER. S N	8007270325 8007300408 8007020048 8007020084 8007040200	50-482 0 50-367 0 50-367 0 50-237 0
RUSSELL.L.B RUSSELL.L.B. RUSSELL.L.B RUSSELL.L.B RUSSELL.L.B.	8009250311 8009230531 8009230542 8009230583 8009230520	50-317 8 50-317 8 50-317 8 50-317 8 50-318 8	SCHULZ, R D. SCHULTZ, G SCHULTZ, W B SCHULTZ, W B. SCHULTZ, W B.	8007270436 8007030552 8007030147 8007030152 8007030147	50-367 0 50-367 0 * 50-367 0	SEKULER, S N SEKULER, S N SEKULER, S N SEKULER, S N	8007040208* E007040218* B007110783 B007150400 B007160403	50-237 0 50-367 0 50-367 0 70-1308
RUSSELL.L.B RUSSELL.L.B RUSSELL.L.B RUSSELL.L.B. RUTHERFORD.J F	8009230698 8009300441 8009300454 8009300464 8009110291	50-317 8 50-317 8 50-318 8 50-317 8 F01A	SCHULTZIN B BCHUMACHERIJ SCHUYLERIJ O SCHWARTZIF N BCHWARTZIF N	8007030152 8007050342 8007070520 800712033& 8007150585	50-275 H * 50-275 K NUREO	SEKULER. 8 N EELLS, D E SENCHYSHYN, J S SENECHAL. M E SERABIN, J A	8009150069# 8009090114 8009030726 8009240205#	COMMISSION 50-334 Q 50-282 (50-244 (
RYAN. M T BABOL. A. R BABOL. A. R BADAUSKAB, G. J BADDOCK, H Q	8007110478 8007170250* 8007170271* 8007260411* 8007220326	RE8 50-387 Q 50-387 Q 50-289 T 50-244 Q	BCHWEIKER, R. 8 BCHWEIKER, R. 8 BCHWEIBINZ, E. R BCHWEIBINZ, E. BCHWENCER, A.	8009020168 8009120317 8009180221 8009180221 8009090195	# 50-327 H # 50-546 G # 50-546 G	SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8009260363 8009260369 8009260390 8009260392 8009300180	70-1167 40-8180 70-2560 40-8092
Baltzhan, J Baltzhan, J Bahanta, P Bahpleg, M. D Bampleg, M. D	8007020131 8007170415 8007120375 8007170357	50-387 M 50-322 M TOPREP 50-445 M 50-445 M	BCHWENCER, A BCHWENCER, A BCHWENCER, A BCHWENCER, A BCHWENCER, A.	8009150494 8009120690 8009180168 8009110255 8009150114	50-341 A 50-354 A 50-358 A	SEYFRIT.K V BEYFRIT.K V SEYFRIT.K V SEYFRIT.K V	8009040511 8009040039 800990046 8009100188 8009100677*	50-458 Q 50-298 Q 40-6659
BANDERB, F D BANE, A D. SANTINI, J BARPKAYA, T. BARBOUR, B	8009170424 8009020017* 8009020217* 8009020519 8009150227*	50-249 J 50-537 A COMMISSION NUREO 50-346 R	Schwencer, a Schwencer, a Schwencer, a Schwencer, a Schwencer, a	8009170200 800910045 8009170174 800926005 800926005	7 50-275 M 4 50-364 A 9 50-341 M	SEYFRIT, K V	8007180115 8007180115 8007020334 8007180117 8007180143	50-278 G 50-458 G 50-278 G 50-313 G

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V	8009180147 8009020538 8009020539 8009180105 8009180108	50-285	Shea, J R Shea, J R Shea, J R Shea, K H Shea, K H	8009110586 8009240569 8009150029 8009040281 8009040281	XPORTLIC SECY XPORTLIC SO-347 Q 50-367 Q	SHULL.C D SHUM.E Y SHUMWAY.N D SIEDER.J D SIEDER.J D	6009170139 8009260525 8009110520* 8009090412* 6009230601	40-8491 70-1113 50-275 U 50-334 P 50-334 P
SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V	8009180138 8009180140 8009180152 8009180154 8009180157	50-313 Q 50-247 Q 50-247 Q 50-285 Q 50-298 Q	SHEA. J J SHEA. K H SHEA. K H SHEA. K H	8007030076 8007080507 8007080511 8007080507 8007080511	50-409	SIEBER, J D SIEBER, J D SIEBER, J D SIEGEL, S SIEGEL, S	8009230711 8009230454 8009230593 8009260219 8009240690	90-334 P 90-334 P 50-334 P ACRB ACRB
SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V	8009180160 8009260283 8009260286 8009260291 8009260294	50-313 Q 50-285 Q 50-267 Q 50-298 Q 50-313 Q	SHEA.JR SHEA.KH SHEA.KH SHEA.KH SHEA.KH	8009270405 8009090791 8009110808 8009110808 8009150463	SECY 50-367 0 50-367 0 50-367 0 50-367 0	SILDERO, JE SILDERO, JE SILVER, H SIMCHUK, J D	8009100429 8009100429 8009300039 8009090602 8009050458	50-282 0 50-282 0 50-282 0 50-289 I 71-7116
SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V	8009020130 8009020134 8009020137 8009020140 8009020143	50-313 F 50-458 F 50-556 F 50-482 F 50-445 F	SHEA, K. H. SHEA, K. H. SHEA, K. H. SHEA, K. H.	8009190039 8009230035 8009190039 8009230035 8009180259	50-367 0 50-367 0 50-367 0 50-367 0 50-367 0	SIMMONS, Q SIMMONS, Q SIMONETTI, Q SINGER, L N SINGER, L N	8009190224 8009190234 8009180005* 8009040227 8009090249	50-440 K 50-440 K 50-334 G 50-289 Q 50-289 Q
SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8007020147 8007020149 8007020153 8007020155 8007030263	50-498 F 50-285 F 50-267 F 50-298 F 50-482 Q	SHEA, K H SHEALY, H G SHEALY, H O SHEALY, H O	8009300574 8009300576 8009100072* 8009100076* 8009020316	50-367 0 50-367 0 27-47 27-47 Nureo	BINGER, L N BINGER, L N BINGER, L N BIGUR, B R BKGLDB, J L	8009110779 8009110789 8009110791 8009120430 8009160640#	50-320 Q 50-287 Q 50-287 Q 50-361 H 50-395 Q
SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V	8007030265 8007030266 8007030268 8007030271 8007230116	50-445 0 50-382 0 50-478 0 50-458 0 50-298 0	SHEDLOSKY, J T SHELDON, K P SHELDON, K P SHELDON, K P SHELLEY, W J	800915008B* 8009110B02 8009110B02 B009300004 B009180334	50-245 Q 50-155 Q 50-155 Q 50-367 Q 71-82	SKOLDS, J L BLOTT, N SMITH, O H SMITH, O H BMITH, O H	8009300073* 8009090334 7912190054* 8002150283 8005090552	50-261 G 50-275 H PT9 PT9 PT9
SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V	8009240735 8009250458 8009260526 8009160032 8009160035	50-313 Q 50-267 Q 50-285 Q 50-458 Q 50-298 Q	SHELLEY, W J SHELLEY, W J SHEPHERD, R SHERBONDY, B N SHERIDON, S F	8009300654 8009150233 8009020091* 8009260435 8009110531	40-8027 70-925 50-204 P 70-143 FOIA	SMITH, R I SMITH, R D SMITH, Q C SMITH, P D SMITH, R D	8009120205 8009100076* 8009160625* 8009120339 8009100067	TOPREP 27-47 50-277 G NUREG 27-47
SEYFRIT. K V SEYFRIT. K V SEYFRIT. K V SEYFRIT. K V	8009100217* 8009120025 8009120026 8009170390 8009170392	40-4639 50-458 Q 50-298 Q 50-313 Q 50-458 Q	SHERIDAN, T B SHERIDAN, T B SHERMAN, F L SHERMAN, M P SHERON, B W	8009240417* 8009300434 8009120668 8009260669 8009100407	50-289 T NUREO 70-33 NUREO NUREO	SMITH, 0 H SMITH, 0 H SMITH, 0 H SMITH, 0 H SMITH, P A	8007250334 8007150117 8007170047* 8007240176* 8007150144	70-820 50-217 G 50-352 G 50-244 G CONTRACT
SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8009170394 8009170395 8009170397 8009170399 8009170401	50-498 Q 50-482 Q 50-382 Q 50-298 Q	SHERDN, B SHERWOOD, O O SHERWOOD, G O SHIELDS, S W SHIELDS, B W	8007170578 8007020023 8007030505 8007020253* 8007180533	TOPREP NUREO 50-333 P 50-344 S 50-546 A	BMITH, O C EMITH, D R, EMITH, J D EMITH, O EMITH, O H	8007160246* 8007050214* 8007270015* 8007300322* 8007120325	50-334 0 71-7508 50-266 0 90-259 H 70-343
SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8009170403 8009170406 8009100362 8009120420 8009120422	50-267	SHIELDS, S W SHIELDS, S W SHIELDS, S W SHIELDS, S W	8007030480 8007250482* 8007270208* 8007180521 8007300074	50-546 8 50-546 9 50-546 9 50-546 0	9M1TH, 0 H 9M1TH, 0 H, 9M1TH, J W 9M1TH, T C 9M1TH, J, R	8007170044 8007240186 8007150344* 8007150557 8007230755*	50-352 0 50-244 0 50-289 H 40-8692 CONTRACT
SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8009120423 8009120424 8009120427 8009120429 8009120432	90-498	SHIELDS, S W SHIELDS, S W SHIELDS, S W SHIELDS, S W	8007030500 8007040427 8007250447 8007180344 8007070574	50-546 A 50-546 B 50-546 G 50-546 G 50-546 H	HITME HITME HITME HITME HITME HITME HITME HITME HITME	8007020057 8007110274 8007080356* 8007070478 8007100372	50-361 0 70-820 50-327 8 50-271 P
SEYFRIT. K V SEYFRIT. K V SEYFRIT. K V SHACKELFORD, B	8007120433 8007120434 8007180127 8007300505 8007020107	50-247 Q 00-445 Q 50-278 Q 50-278 Q 70-1738	SHIELDS, S W SHIELDS, S W SHIELDS, S W SHIELDS, S W SHIELDS, S W	8007100467 8007160400 8007160417 8007270511 8007240561	50-546 8 50-546 8 50-546 8 50-546 A 50-546 8	BM1TH, F A SM1TH, I W SM1TH, R D SM1TH, R D, SM1TH, R L	8009140450 8009050420 8009220179 8009230055 8009090535	NUREQ 50-287 0 27-39 27-39 50-271 R
SHAFER, W D SHALLY, P, J SHALLER, D V SHALLER, D V	800726030B* 8007030010 8007070501 8007110326 8007150323	50-316 G RES 50-315 S 50-315 S 50-315 S	SHIELDS, S W SHIPPER, P J SHIVELY, C N SHIVELY, C N SHIVELY, C N	8009300452 8009240407* 8009020458* 8009030425* 8009090385*	50-546 H 50-287 T 50-368 S 50-368 S 50-368 B	BMITH, I W BMITH, I W BMITH, I W BMITH, I W BMITH, I W	8009110799 8009140534 8009170137 8009170182 8009170198	50-289 0 50-289 0 50-289 0 50-289 0 50-289 0
SHALLER, D V SHALLER, D V SHALLER, D V SHALLER, D V	8009160273 8009160280 8009190517 8009190303 8009300510	50-315 R 50-316 R 50-316 B 50-315 S 50-315 S	SHIVELY, C N SHIVELY, C N SHIVELY, C N SHIVELY, C N	8009150296# 8009150261# 8009230712# 8009240504# 8009300544#	50-348 8 50-348 8 50-348 8 50-348 8 50-348 8	emith, b J emith, i W emith, i W emith, i, W emith, i W	8009240557* 8009180557 8009220408 8009220411 8009230024	50-375 Q 50-267 O 50-267 O 50-267 O 50-267 O
SHANAHAN, W P SHANAHAN, W P SHANNON, P C SHAPAR, H K SHAPAR, H K	8007120037* 8007110276* 8007070343* 8007230229* 8007230234*	CONTRACT FOIA 50-339 U FOIA FOIA	SHOEMAKER, C L SHOLLY, S C SHOLLY, S C SHOLLY, S C SHOLLY, S C	8009300438 8009020052 8009050427 8009030421 8009160169	50-317 J 50-289 0 50-289 0 50-289 P 50-289 0	6M1TH,C V 8M1TH,I W 8M1TH,I W 6M1TH,I W 6M1TH,R L	6007300164 6007240531 6007240532* 6007260453 6007260421	50-243 F 50-289 Q 50-289 Q 50-389 M 50-271 P
SHAPAR, H K SHAPAR, H K SHAPAR, H K SHAPAR, H K SHAPAR, H K	8007230266* 8007230268* 8007230274* 8007170478* 8007170568*	FOIA FOIA FOIA FOIA FOIA	SHOLLY, S C SHOLLY, S C SHON, F J SHOPENN, N M SHOPENN, N M	8007160030 8007300617 8007170175 8007180203* 8007180081*	50~289	Smith, I W Smith, O Emith, O, Smith, I, W Smith, I W	8009240645 8009300325* 8009300327* 800930003 8009300004	50-287 Q 50-257 H 50-257 H 50-297 Q 50-289 Q
Shapar, H K Shapar, H K Shatterly, L W Shea, J R Shea, J R	8007110450 8007110013 8007170121* 8007150418* 8007150072	50-289 C 50-389 M 40-2061 COMMISSION XPORTLIC	SHORB, E M SHORB, E M SHORB, E M SHORB, E M SHORB, E M	8007100165 8007110556 8007110569 8007230257 8007230466	50-367 Q 50-367 Q 50-367 Q 50-367 Q NUREQ	SMITH, I, W SMITH, I W. SMOKER, C S SMOKER, C S SNAIDER, R P	8009300015 8009300318 8009240501# 8009240508#	50-287 0 50-287 0 50-305 8 50-305 8 0EN TEC 18

AUTHOR	ACCEBSION NUMBER	SUBJECT CATECORY	AUTIOR	ACCESSION NUMBER	BUBJECT CATECORY	AUTHOR	ACCESION NUMBER	EUBJECT CATEGORY
ENIEXEK, J ENOW, C A ENYDER, B J ENYDER, B J ENYDER, B J	6007170745 6007110367 6007020152 6007070572 8007070540	50-257 B 50-344 H 50-320 P 50-320 P 50-320 H	SPECIALE, J R SPECTOR, L S SPENCER, O S SPENCER, O S SPENCER, O S	8007230527* 8007230238* 8007150378* 8007110424* 8007120467	50-318 8 F01A 50-397 0 50-460 0 50-397 0	STELLO, V STEPHENS, C W STEPTOE, P P STEPTOE, P P STERNBERO, D M	8007300316 8005070553* 8007070471 8007220217* 8007020240*	50-259 H PT9 50-293 O 50-185 O 50-397 G
ENYDER, B J SNYDER, B J SNYDER, B J SNYDER, B J SNYDER, B J	8007240107 8007020172 8007020315 8007020465 8007030368	50-320 H 50-320 H 50-320 H 50-287 H 50-320 H	BPENCER. O 8 BPENCER. O 8 BPENCER. W C BPENCER. O 8 SPENCER. O B	B009020256 B009120616* B009050056 B009120292 B009120204	50-361 G 50-460 G 50-281 G 50-328 G 50-460 G	STERNBERG, D H STERNDERG, D H STERN, A STERN, W C STERN, W P	8007020251* 8007230217* 8007240147 8007270485 8007270488	50-344 Q 50-275 Q FOIA XPURTLIC XPORTLIC
SNYDER. D. J SNYDER. D. J. SNYDER. D. J. SNYDER. D. J. SNYDER. B. J.	8007030678 8007030681 8007050379 8007070604* 8007100062	50-289 H 50-289 H 50-320 H 50-320 P 50-289 H	SPENCER. O B SPENCER. J B BPENCER. O B SPENCER. O B SPENCER. U C	8009120476 8009180575 8009110415 8009190169* 8009240180	50-528 G 50-461 A 50-460 G 50-528 G 50-280 G	STERN, W C STERN, W C STEVENSON, M O STEVENSON, M O STEVENS, S C	8009290581 8009300024 8009300169 8009110503 8009090525	XPORTLIC XPORTLIC 50-3 P NUREO 50-285 8
SNYDER. B. J SNYDER. B. J SNYDER. B. J SNYDER. D. J SNYDER. B. J	8009170170 8009170266 8009170272 8009240100 8009170619	50-320 H 50-320 H 50-320 H 50-320 H 50-320 P	BPENCER, O B SPENCER, O B SPENCER, O B BPESSARD, L SPESSARD, R L	8009300047 8009120609 8009120173 8009190171* 8009100148*	50-312 @ 50-460 @ 50-50B A 50-254 @ 50-10 @	STEVENS, S. C. STEVENS, B. C. STEVENSON, R. L. STEVENS, S. C. STEWART, R. C.	8007030486* 8007070505 8007250470* 8007300532 8007150066*	50-285 R 50-285 8 70-1131 50-285 8 50-445 0
SNYDER.B.J. SNYDER.B.J. SNYDER.B.J. SNYDER.B.J. SNYDER.B.J. SNYDER.B.J.	8007050386 8007020273 8007020277 8007020310 8007050367	50-320 H 50-287 H 50-287 H 50-320 H 50-320 H	SPEGSARD, R L SPETH, O SPETH, O SPIECEL, V SPIECEL, O	8007240404* 8007240550* 8007070778* 8007270263 8007020282	50-10 G 50-275 O 50-367 Q 71-5740 50-445 H	STEWART, R C STEWART, R C STEWART, R C STEWART, R C STEWART, R C	8009150071* 8009150075* 8009150077* 8009150080* 8009150083*	50-445 O 50-445 G 50-445 G 50-445 O 50-445 O
BAYDER, D J BAYDER, B J BAYDER, B J BAYDER, B J BAYDER, B J	8007050496 8007090611 4 8009100060 8009170288 8009170362	50-320 H 50-320 P 50-287 H 50-320 H 50-320 H	SPIECEL, Q SPIECEL, Q, SPIECEL, Q SPIECEL, Q SPIECE, P	8009020282 8009130417 8009150417 8009300013 8009080453	50-445 M 50-445 H 50-445 H 50-445 H 40-8697	STEWART, R C STEWART, W P STEWART, R C STIEFELD, B STILWELL, T C	8007150087* 8007240628* 8007300076* 8007260072 8007020148*	50-445 0 50-302 P 50-382 Q NUREQ 50-331 P
ENYDER, B J ENYDER, B J ENYDER, B J ENYDER, B J ENYDER, B J	8007230760 8007020487 8007020488 8007020502 8007050366	50-320 H 50-320 H 50-287 H 50-320 H 50-287 H	EPRENCEL, J F EPRINGER, D EPRINGER, D EPRINGER, D BTAGK, D W	8009190713* 8009030297 8009030300* 8009050303* 8009040437	CONTRACT 50-488	STILWELL, T C STILWELL, T C STILWELL, T C STILWELL, T C	8007020463* 8007020467* 8007020470* 8007020473* 8009020474*	50-10 P 50-10 P 50-10 P 50-10 P 50-10 P
BNYDER, B J BNYDER, B. J BNYDER, B J BNYDER, B J BNYDER, B J.	8009220049 8009230233 8009030187 8009150324 8009150330	50-289 H 50-320 H 50-320 H 50-289 H 50-289 H	BTAGOERS, H O BTAHL, D M STAHL, D STAHL, D, M BTAHL, D M	8009100108* 8009110369 8009170369* 8009170235* 8009170239*	COMMISSION 50-445 Q 50-445 M 50-445 M 50-445 M	STILWELL, T C STILWELL, T C STILWELL, T C STILWELL, T C	8007040103* 8007040315* 8007040544* 8007050456* 8007050501*	50-155 P 50-324 P 50-271 P 50-273 P 50-27 P
BNYDER, B J. BNYDER, D J BNYDER, B J. BNYDER, B. J. BNYDER, B J	0009150343 0009150441 0009150452 0009160101 0009170287	50-289 H 50-320 H 50-320 H 50-289 H 50-287 H	STAIL.D STAIL.D M STAIL.D M STAIL.D STAIMER.F	8009170369# 8009170177 8009170177 8009160160# 8009120320#	50-445 M 50-445 H 50-445 M 50-445 M 50-295 8	STILWELL, T C STILWELL, T C STILWELL, T C STILWELL, T C	8009150426* 8009170260* 8009170402* 8009180219* 8009040129*	50-317 P 50-330 P 50-220 P 50-336 P 50-260 P
BNYDER, B J BNYDER, B J BNYDER, B J BNYDER, B J BNYDER, D, J	8009170271 8009230194 8009230216 8009100206 8009180321	50-287 H 50-287 H 50-320 H 50-320 H 50-289 H	STAMIRIS.O STARK, R. H STARKEY, R. E STARKEY, R. R. STARK, R. M	8007260001 8007130478 8007030437 8007030463* 8007170773	50-327 0 50-387 A 50-261 B 50-261 B 50-482 A	STODRATIP O STOHRIJ P STOHRIJ P GTOHRIJ P	8009170398* 8003190829* 8003190817 8009220182 8009240637*	50~289 T PT9 PT9 50~335 Q 70~143
BNYDER.B J BNYDER.D J, BNYDER.B. J BNYDER.B J BNYDER.B J	8009150351 8009190750 8009170004 8009170283 8009150546	90-320 H 90-320 H 90-287 H 90-320 H 90-320 H	STARK, R H STARK, R. H STARK, R H STARKEY, R D, STARKEY, R D	8009230770 8009120651 8009180464 8009150286 8009150289*	50-483 A 50-387 A 50-397 A 50-261 S 50-261 B	STOHR, JP STOHR, JP STOHR, JP, STOHR, JP,	809160487* 8099160490* 8009020464 8009040317 8009240189*	50-280 Q 50-280 Q 50-348 Q 50-327 Q 50-302 Q
SNYDER, B J SNYDER, B J SNYDER, B J SNYDER, B J GNYDER, B J	8009150547 8009260050 8009260083 800926093 8009300601	90-320 H 50-320 P 50-320 P 50-320 P 50-320 H	STARKEY.R B. STARK.R M STARKEY.R B STARKEY.R.B STARKEY.R.B	0009160255 0009300669 0009190469 0009190477* 0009250301	50-261 ft 50-387 F 50-261 ft 50-261 B 50-261 B	970HR, J P 870HR, J P 870HR, J P 870HR, J P 870HR, J P	8007040055 8007110079 8007250176* 8007160473 8007240176	27-39 27-39 50-349 90-280 90-302 6
BNYDER, B J, BNYDER, D J BNYDER, D, J, BNYDER, D, J, BONINKI, B H	8009300610 8009300636 8009300639 8009290149 8009020066	50-320 H 50-320 H 50-320 H 50-320 H 50-466 0	STARKEY.R B STABZESKY.F H STAUDER.S J STAUDER.W STEFFES.C	8007250304* 8007150081* 8007230372* 8007240028* 8007020376*	50-261 8 50-293 U CONTRACT CONTRACT 50-254 8	STOHR, J.P STOICK, A.F STOICK, A.C STRAVSS, P.L	8009240318 8009240624 8009260495* 8009160399* 8009230145*	50~416 Q 70~143 40~8663 50~346 B FOIA
BOHINKIJO H BOHTRILJJR, BODNO,A,L BODNO,A,L BOUDER,JL	8007040297 8007080438* 8007250478* 8007150183* 8007070082	50-466 0 50-312 P 70-1257 70-258 50-483 A	BTEFFEB.C BTEINER.OR BTECLO.V BTECLO.Y.	8007080417* 8007030397 8009160530 7910020407 8009290163*	50-265 S 50-327 R 70-2709 PT9 FD1A	STRAUSS, P L STRAUSS, P L STRAUSS, P, L STREETER, J, STREETER, J F	8007230224* 8007170370* 8007170400* 8007150025* 8007270118*	FOIA FOIA FOIA 50-373 G 50-259 G
BOUDER, J L BOUDER, J L BOUDER, J L BOUDER, J L BOUDER, J L	8009050424 8009110528 8009100922 8009100924 8009120091	50-266 H 50-287 0 50-335 F 50-337 F 50-454 F	STELLO, V STELLO, V STELLO, V STELLO, V	0005230854 0009080268 8009170410 0009170414* 0009170417*	PT9 50-333 Q 50-458 Q 50-458 Q 50-458 O	STREETER, J F STROHL, J STROND, T R STRONDE, W S SULLIVAN, R C	8009260404* 8009020050 8009240260 8009170130 8009380081*	50-10 (50-244 (5tate Pro; 40-8745 50-257 (
SQUDER, J L SQUDER, J L SQUDER, J L SQUDER, J L SQUDER, J L	8009120094 8009240347 80092100930 8009260016 8009260017	50-454 F 50-361 F 50-282 F 50-282 F 50-263 F	81ELLO, V 81ELLO, V 81ELLO, V 81ELLO, V	8007070638 8007100066 8007150303 8007180277* 8007100657	50-324	E T WANTENERS TO THE TOTAL TO T	8007120533 8009160186* 8009290096* 8009150217* 8009100231*	RECOD 70-135 FO1A GA999 GA999
BOUDER, J L. BOHDON, T L BPAETIN, M E EPANNAUS, W EPARXB, D T	8009240043 8007090267* 8009240312 8009030724 8009100412	90-280 F 30-293 R 70-1113 50-282 0 RFB	STELLO, V STELLO, V STELLO, V STELLO, V	8007300042 8007270160 8007250047 8007300345 8007260289	50-324 0 50-255 0 50-317 0 50-219 0 50-490 T	Button, J H Bhan, R W Bwandy, O T Bhandy, G T Bhandy, G. T	8007180536* 8007110177* 8007080480* 8007110737 8007170143	0A999 50-518 (40-3453 40-3453 40-3453

AUTHOR	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR	ACCEBBION NUMBER	SUBJEC CATE O C	
Svanger, H J Svangon, E R Svangon, H V Svangon, D T Svart, F E	8009020483 8009100140 8009190877 8009170122 8009020221		Q rog Q Q	TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L	8007030672 8007030685 8007030272 8007070789 8007020471	50-483 50-482 50-478 50-395 50-445	A A A A	THOMAS.D.O THOMAS.R.D. THOMAS.E.L. THOMAS.E.B. THOMAS.E.B.	8007120581 8007160561 8007040485 8007180340 8007240502	RES 70-734 NUREO 50-220 50-341	P
SWART, F E SWART, F E SWART, L L SHEARINGEN, J D SWEENEY, A A	8009260227 80092602333 8009230628 80091603273 80090306834	50-289 50-327 50-289	R R S H	TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L	8009040506 8009040509* 8009120113 8009040434 8009040464	50-267 50-267 50-458 50-369 50-319	P P A A	THOMPSON, D THOMPSON, D THOMPSON, D THOMPSON, D THOMPSON, D	8008210619 8009040591 8009020510 8009190418 8009190865	1&E 50-333 50-286 1&E 50-255	8
SHEENEY, L E SHEENEY, L E SHEENEY, L E SHEENEY, L E	8009020428 8009020421 8009020087 8009080332 8009030431	50-287 50-287 50-289 50-289 50-289	I C T C T	TEDESCO, R L TEDESCO, R L TEDESCO, R L TEDESCO, R L TEDESCO, R L	8009040467 8009120116 8009090128 8009090842 8009090851	50-390 50-369 50-364 50-389 50-389	A A A	THOMPSON, D. THOMPSON, D. THOMPSON, T THORNEURO, H D THORNTON, P	8007300048 8007300166 8007230692* 8007110061* 8007220218*	50-397	E A
SMEENEY, L E SMEENEY, L E SMEENEY, L E	8007030372 8007030582 8007150252 8007110374 8007110405	50-269 50-289 50-289 50-289 50-289	T T Q T	TEDEBCO, R L TEDEBCO, R L TEDEBCO, R L TEDEBCO, R L TEDESCO, R L	8009090877 8009150427 8009150490 8009180489 8009090875	50-369 50-267 50-267 50-369 50-395	A G A A	THURLOH,E W TIEPEL.E W. TIERNAH,J.A. TIERNEY,F P TILLMAN,A.	8009230584 8009150023 8009160504 8009180422 8009190651#	50-309 40-8502 50-317 50-282 50-259	P Q 8 Q
SWEENEY, L E SWEENEY, L E SWEENEY, L E SWEENEY, L E	8009160371 8009250270 8009170292 8009290357 8009230445	50-289 50-289 50-289 50-289 50-289	Ç T P I T	TEDESCO, R L TEDESCO, R L TEDESCO, R L TEDESCO, R L TEDESCO, R L	8009120108 8009120112 8009120501 8009120619 8009120623	50-311 50-311 50-311 50-438 50-369	P P A A	Tillman, a Timko, d r. Ting. W. H Tobin. H. J Tobin. H. J	8009110173* 8009180194* 8009100202 8009190651* 8009110191*	50-250 50-334 50-201 50-259 50-327	0 R P 0
SHEENEY.L E SHEENEY.L E SHEENEY.L E SYLVIA.B R SYLVIA.B R	8009260175 8009230449 8009230434 8009020242 8009240701*	50-289 50-289 50-289 50-280 50-280	0 0 0	TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L	8009150565 8009190131 8009110523 8009110529 8009120099	50-275 50-311 50-423 50-438 50-460	F P A A	TOBIN,W J TOBD, Q. A TODD, O. A. TODD, O. A.	8009250439* 8009230210* 8009100914* 8009110142* 8009100795*	70-143 50-321 70-143 70-1151 70-27	Q
SYLVIA, B R SYLVIA, B R SYLVIA, B R SYLVIA, B R SYLVIA, B R	8009120702 8009230097 8009240661* 8009120031 8009050329	50-338 50-338 50-281 50-280 50-338	8 Q Q Q R	TEDESCO,R L TEDESCO,R L TEDESCO,R L TEDESCO,R L TEDESCO,R L	8007120102 8007120177 8007160649 8007170404 8007170776	50-508 50-329 50-369 50-445 50-395	A A A A	TOLLIBON, A C	8007240356# 8007240340# 8007020380 8007020371# 8007100433	50-324 50-324 50-324 50-324 50-324	0 8 8
SYLVIA.B R SYLVIA.B R SYLVIA.B R SYLVIA.B R SYLVIA.B R	8009080394 8009090528 8009240399 8009110431 8009150257	50-339 50-280 50-280 50-338 50-338	P G G P O	TEDESCO,R L TEDESCO,R L TEDESCO,R L TEDESCO,R L TEDESCO,R L	8009090035 8009090037 8009090103 8009110250 8009150333	50-410 50-491 50-397 50-10 50-369	A A P A	TOLLISON, A C	8009120371# 8009180570 8009160260 8009230624 8009230635#	50-325 50-324 50-324 50-325 50-325	8 8 8
SYLVIA, B R SYLVIA, B R SYLVIA, B R SYLVIA, B R	8009160324 8009180251 8009190437 8009290319 8009300116	50-281 50-280 50-280 50-338 50-280	J P R Q	TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L	8009170192 8009190099 8009220050 8009120119 8009180172	50-142 50-416 50-311 50-395 50-327	0 A P F 0	TOLLIBON, A.C. TOLLIBON, A.C. TOLLIBON, A.C. TOLLIBON, A.C. TOLLIBON, A.C. TOLLIBON, A.C.	8007230717 8007230725 8007230727* 8007230735* 8007230736	50-324 50-325 50-324 50-325 50-325	8 8 8
BYLVIA, B R SYLVIA, B R BYLVIA, B R BYLVIA, B R	8009170321 8009190525 8009230287 8009230356 8009230292	50-338 50-338	P P R P	TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L	8009180569 8009240087 8009250243 8009150538 8009150541	50-395 50-369 50-327 50-528 50-395	A V P A A	TOLLIBON, A C	8009230740* 8009230459 8009230470 8009230683* 8009230709	50-325 50-324 50-325 50-325 50-325	6 6 8 8
SYLVIA.B R SYLVIA.B R SYLVIA.B R SYLVIA.B R SYLVIA.B R	8007230320 8007230343 8007230627 8007260182 8007260278	50-280 50-338 50-338 50-280	F G F P	TEDESCO,R L TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L	8007170227 8007180330 800724054B 8007070640 8007100484	50-329 50-361 50-382 50-339 50-387	Q A A P A	Tollison, a c Tollison, a c Tollison, a. c, Tollison, a. c Tollison, a. c.	8009230717* 8009230718 8009230745* 8009250265 8009260638*	50-325 50-325 50-325 50-324 50-324	6 6 8 8
SYLVIA, B R SYLVIA, B R SYLVIA, B R TAGGART, D W TAIT, L	8009290349 8009300255 8009300249 8009220242# 8009100515	50-339 50-338 50-329 50-367	P d P A Q	TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L	8009150191 8009150560 8009240531 8009180515 8009240510	50-27 50-410 50-416 50-373 50-395	P A A G	TOLLISON, A. C TOLLISON, A. C TOLLISON, A. C. TOLLISON, A. C. TOLLISON, A. C	8009290286 8009290288 8009290309* 8009290311* 8009300489	50-325 50-324 50-324 50-325 50-325	8 8 8
TALWANI,P TAMBLING,T N TAMBLING,T N TAPIA,J I TAPIA,J I	8007050418* 8007270020* 8007160616* 8007150087* 8007050533*	50-346 50-305 50-445 50-498	A G G G	TEDESCO, R L	8009240551 8009250146 8009250267 8009260671 8009270049	50-364 50-358 50-358 50-358 50-275	A Q E A F	TOLLIBON, A C YOLLIBON, A C YOLLIBON, A C TOLLIBON, A C TOLLIBON, A C	8009300509* 8009300474 8009300479* 8009300559 8009300568*	50-325 50-324 50-325 50-325 50-325	8 8 8
TAPIA.J I TARNOFF,P TAUBER.H, TAYLOR.J H TAYLOR.R O TAYLOR.R O	8007250405* 8007150423* 8007030602 8007240634* 8007150073*	COMMISSION 50-341 50-302 50-445	4	TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L	8007270001 8007250141 8007260071 8007270086 8007300227	50-369 50-400 50-546 50-358 50-311	A A A P	TOLMAN, E L TOMLINSON, D P TOMLINSON, D P. TOMDI, D. TOMDI, D	8007050397 8007150357* 8007300102* 8007040457 8007030055*	RES 50-458 50-478 NUREO NUREO	a a
TAYLOR, R O TAYLOR, R O TAYLOR, J H TAYLOR, J H TAYLOR, J H	8009150100* 8009150105* 8009150367* 8009020364 8009100233	50-445 (50-445 (50-445 (TOPREP TOPREP)	TEDESCO, R L TEDESCO, R L TERRELL, N THATCHER, D F THIES, A C	8007270157 8007300307 8007170526* 8007170354* 8007030605	50-395 50-329 FOIA 50-289 50-269	A A T G	TONDI.D. TONEATTI.V W. TONEATTI.V W. TONEATTI.V W TONEATTI.Y W TONGUE,T M.	8007240171 80072703184 8007270315* 8007270312* 8007100148*	NUREO QA777 QA777 QA777 50-10	a
TAYLOR, R R TAYLOR, R R TAYLOR, J H TEDESCO, R L TEDESCO, R L	8007120270 8009300062 8009300064* 8009230707 8009110604	TOPREP XPORTLIC XPORTLIC 50-287 P 50-327 P		THOM.T. THOMAS.R D THOMAS.R D, THOMAS.R D THOMAS.R D THOMAS.N D	8009170277* 8009080566* 8009020261* 8009020239* 8009030040*	50-259 50-298 70-734 70-984 50-390	R G	TOOLE, R, J TOOLE, R, J, TORCIVIA, J A TOTH, R D TOTH, A D	8007260431# 8007300506 8007260407# 8007110427# 8007120631#	50-287 50-287 50-287 50-460 50-460	T 8 T Q
TEDESCO. R. L. EDESCO. R. L.	8009110636 8009020126 8009020122 8009030332 R009030440	50-369 A 50-373 A 50-369 A 50-395 A 71-445 A		THOMAS, R D THOMAS, R D, THOMAS, M THOMAS, E L THOMAS, R D	8009290131* 8009110650 8009250114* 8009140206 8009040596	50-254 27-48 50-366 PRM 70-734	G G	TOTH, A. D TOTH: A. D TOURTELLOTTE, J TOY: H. L TRAGER, E. A	8007040482* 8007150377* 8007170254 8007070886 8007100740	50-397	G G

RDHTUA		BUBJECT CATEOORY	AUTHOR	NUMBER (TOJECT YRDOJTAD	AUTHOR	ACCESSION NUMBER	SUBJECT CATECORY
TRAGERIE. A TRAMELLIC TRAMELLIC M TRAMELLIC M TRAMELLIC M	8007030054* 50 8007030062* 50 8007150356* 50	0-1341 0-334 P 0-336 P 0-317 P	TUPPER, K F TUPPER, K TUPPER, K F TUPPER, K TURCOTTE, R L	8009050442 XI 8009050446* XI 8009110632 XI 8009110635* XI	PORTLIC PORTLIC PORTLIC PORTLIC PORTLIC	VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8009160373 8009230653 8009230701 8009240422	50-528 C 50-528 T 50-528 S 50-528 C 50-528 A
TRAMMELL, C. M TRAMMELL, C M TRAVIEZO-DIAZ TRAVIEZO-DIAZ TRAVIEZO-DIAZ	8009290117 5 8009260550 8 80090907689* 5	0-344 P 0-344 P E8 0-312 0 0-312 0	Turk, 8 e Turk, 8 e Turk, 8, e Turnage, k c Tutleman, J 8	8009170129* 7 8009170131* 7 8009260536 N	0~2909 0~2909 '0~2909 IURE0 i0~320 H	VAN BRUNT, E E VAN BRUNT, E E VAN BICKEL, J VAN VRANKEN, J VAN VRANKEN, J	8009300355 8009300402 8009190504= 8009160281 8009140247	50-529 6 50-528 K 50-331 R PR 50-367 Q
TREAT, E. H. TREBY, B. A TREVINO, T TRIBBLE, J. E TRIBBLE, J. E.	8009070245 5 8009110379* C 8009020113 5	0-289 H 0-510 0 0NTRACT 10-271 0 50-271 9	TYLER.P E TYLER.P E TYLER.P E TYLER.P E UDY.A C	8007170175 5 8007270357 5 8007270148 5	30-170 P 30-170 V 30-170 P 30-170 F 50-316 P	VANDELL, T D VANDODRN, P K VANDODRN, P K VARANINI, E E VARANINI, E E	8009020123 8007240320* 8007240071* 8009030638 8009030643*	40-8102 50-413 Q 50-335 G PR PR
TRIBBLE, J. E TRIBLE, P. TRIFUNAC, H D TRIFUNAC, H D TRIFUNAC, H. D	8007150182 F 8007070456* S 8007070672*	50-271	UOY, A C VHRIO, R, E UHRIO, R E VHRIO, R E, VHRIO, R E	8007290624 8007120520# 8009030320	50-315 P 50-335 F 50-250 Q 50-335 Q 50-250 Q	Varanini.e e Varela.a a Varoa.b a Varoa.b a Varoa.b.a	8009030647* 8009190106* 8009070792 8009050460 8009050464*	PR 50-443 Q 50-272 P 50-315 P 50-315 P
TRIFUNAC, M D TRIFUNAC, M TRIMBLE, D. C. TRIMBLE, D. C TRIMBLE, D. C	8009150234 8009090652 8009020224 8008280022	50-70 D 50-275 T 50-313 Q 50-313 Q 50-313 Q	UHRIQ.R E UHRIQ.R E UHRIQ.R E UHRIQ.R E UHRIQ.R E	8009100385 8009110166* 8009020195	50-335 Q 50-367 S 50-250 Q 50-250 Q 50-250 Q	VARGA, B A VARGA, B A VARGA, B A VARGA, B A VARGA, B A.	8009050471* 8009120039 8009120048* 8009120065* 8009030167	50-315 P 50-315 P 50-315 P 50-315 P 50-334 P
TRIMBLE, D. C.	8007020042 8007020447 8007030373 8007020001	50-313 P 50-348 8 50-313 P 50-313 R 50-368 8	UHRIG,R.E UHRIG,RE UHRIG,RE UHRIG,R.E UHRIG,RE	8009170374 8009160639 8009160639	50-335	VARQA, S. A. VARQA, S. A. VARQA, S. A. VARQA, S. A. VARQA, S. A.	8007030174 8007100473 8007100475* 8007030505 8007030510*	50-247 P 50-280 P 50-281 P 50-281 P
TRIMBLE, D. C. TRIMBLE, D. C. TRIMBLE, D. C. TRIMBLE, D. C.	8009030539 8009120387 8009030622	50-368 8 50-313 P 50-368 8 50-368 9 50-368 9	UHRIG,R.E UHRIG,R.E. UHRIG,R.E. UHRIG,R.E. UHRIG,R.E.	8009240174 8009030236 8009110693 8009120671 8009190137	50-389 G 50-250 P 50-250 G 50-250 G 50-335 G	VARQA: B. A. VARQA: B. A. VARQA: B. A. VARQA: B. A. VARQA: B. A.	8009050519* 8009050528 8009050531* 8009050538* 8009090785	50-281 P 50-295 P 50-295 P 50-295 P 50-280 P
TRIMBLE, D. C.	8007030537 8007030550 8007070326 8007070425 8007070378	50-313 J 50-313 J 50-313 F 50-313 R 50-348 8	UHRIO, R. E UHRIO, R. E UHRIO, R. E UHRIO, R. E UHRIO, R. E	8009090290 8009110853 8009240412 8009090257 8009250209	50-250 R 50-250 Q 50-250 G 50-250 P 50-250 Q	VARGA.8 A VARGA.8 A VARGA.8 A VARGA.8 A VARGA.8 A	8007090862 8007090862 8007070884 8007100174 8007110030	50-250 F 50-272 F 50-247 F 50-305 P 50-348 P
TRIMOLE, D. C.	8009090562 8009150293 8009160251 8009150258 8009150268	50-313 8 50-348 9 50-313 R 50-346 8 50-348 8	UHR 10. R C UHR 10. R E. UHR 10. R. E UHR 10. R E UHR 10. R E	8009150251 8009150262 8009160200 8009160378 8009180444	50-335 P 50-389 A 50-335 P 50-250 P 50-335 P	VARGA,8 A VARGA,8 A VARGA,8 A VARGA,8 A VARGA,8 A	8007110031* 8007110035* 8007170228 8007170737 8007100125	50-348 P 50-348 P 50-315 P 50-280 F 50-305 P
Trimble, D. C. Trimble, D. C Trimble, D. C Trimble, D. C. Trimble, D. C. Trimble, D. C.	8009150273 8009160228 8009170322 8009230407	50-368 8 50-319 P 50-319 F 50-368 R 50-313 R	UHRIO: REUHRIG: REUHRIG: REUHRIG: REUHRIG: REUHRIG: REUHRIG: REUHRIG: RE	8009190206 8009300152 8009300040 8009230306 8009300372	50-250 P 50-335 Q 50-387 Q 50-335 P 50-335 Q	VARGA, B.A.VARGA, B.A.VARGA, B.A.VARGA, B.A.VARGA, B.A.VARGA, B.A.VARGA, B.A.	9009110579 9009150511 9009090091 9009100060 9009100106	50-315 P 50-272 P 50-250 P 50-247 P 50-316 F
TRIMBLE, D.C. TRIMBLE, D.C. TRIMBLE, D.C. TRIMBLE, D.C. TRIMBLE, D.C.	8009230697 8009230708 8009230705 8009230744 8009240496	50-313 8 50-368 8 50-369 8 50-369 8 50-313 P	UHRIO, R.E. UHRIO, R.E. UHRIO, R.E. UHRIO, R.E. ULLRICH, H. T. UNDERHILL, D. H.	8009290343 8009300129 8009300177 8009080342* 8009100158	50-250 P 50-250 P 50-250 P 50-277 R NUREO	VARQA:S A VARQA:B A VARQA:B A VARQA:B A VARQA:B A	8009110512 8009110773 8009150515 8009150519 8009100064	50-315 F 50-295 F 50-286 F 50-247 F 50-305 F
TRIMBLE, D. C TRIMBLE, D. C. TRIMBLE, D. C TRIPPLETT, M. P. TRIPPLL, E,	8009300278 8009300538 8009300173 8009050412* 8009190259*	50-368 8 50-313 P FOIA 50-387 Q	UNDERWOOD, PRUNDERWOOD, PRUNDERWILL, DWURRIGHT, CM. UPRIGHT, CM. UPRIGHT, CM	8009180208* 8009180235* 8009300276* 8009030441* 8009030199*	50-321 R 50-366 R Gentract 50-280 G 50-367 G	VARGA, B A VARGA, B A VARGA, B A VARGA, B A	8009120511 8009150435 8009120513 8009180516 8009300518=	
TRIPP, L. E TROUP, Q. L. TROUP, Q. L. TROUTMAN, M TROUBRIDGE, Q. F	8009050486* 8009160497* 8009250200* 8009190123* 8009260301	50~280 Q 50~267 Q 40~2061 50~287 Q	UPRIGHT.C.M URBAN,JR URBAN,JR URQUHART.OT UTLEY.E E	8009120071* 8009160033 8009160041* 8009260400* 8008280370	50-348 Q 50-389 M 50-389 M 50-289 T NUREO	Varga, 8 a Varga, 6 a Varga, 5. a Varga, 5 a Varga, 5. a	900909773 9009090781 9009190596* 9009100631 9009100638*	50-247 50-247
TROWBRIDGE, OF TROWBRIDGE, OF, TROWBRIDGE, OF, TROWBRIDGE, OF, TROWBRIDGE, OF,	8007260301 8007030118 8007030118 8007040365 8007040365	50-320 0 50-320 0 50-289 0 50-289 0	UTLEY, E E. UTLEY, E E UTLEY, E E UTLEY, E E UTLEY, E E	8007070402 8007070448 8007160374 8007170425 8007230438	50-324 F 50-324 P 50-324 P 50-325 P 50-324 P	Varga, S A Varga, B A Varga, B A Varga, B A Varga, S A	8009190151 8009120042 8009090771 8009120181 8009150219	50-247 50-286 50-286 50-334
TROUBRIDGE, O. F.	8009100431 8009100431 8009170219 8009170302 8009170219	50-289 0 50-289 0 50-289 0 50-289 0 50-289 0	UTLEY. E E. UTLEY. E E UTLEY. E E UTLEY. E E VADEN. J	8009230493 8009250262 8009260509 8009300357 8009190881	50-324 Q 50-261 P 50-400 H NUREO State Prog	Varoa, 9 a Varoa, 9 a Varoa, 9 a Varoa, 8 a Varoa, 8 a	8009150244 8009180107 6009180113 8009180538 8009180545	50-241 50-241 50-280 × 50-280
TROMBRIDGE, OF TROMBRIDGE, OF TROMBRIDGE, O. F. TROMBRIDGE, OF. TROMBRIDGE, OF	8009170302 8009240313 8009240313 8009240313 9009300020	50-287 T 50-287 T 50-287 T 50-287 T	VAKERIGS, T V. VAKERIGS, T V. VALENTE, F A VAN BRUNT, E E VAN BRUNT, E E	8009270176* 8002190229 8009040240 8009030474 8009030499	FOIA PT9 50-139 F 50-529 G 50-528 Q	Varca, 8 A Varca, 9, A Varca, 8 A Varca, 9 A Varca, 8 A	8009190255 8009190267 8009190283 8009220009 8009220088	50-250 50-272 50-247 50-295
TROUBERIDOE, O. F. TROULFANIDIS, N TUBES, B. TUMA, A. T. TUNSTALL, J. E. TUNSTALL, J. E.	8009300020 8009220237 8009160276* 8009150230 8009300198* 8009300198*	50-289 9 RM 50-254 R REGOD GONTRACT CONTRACT	VAN BRUNT, E E. VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E, E VAN BRUNT, E E.	8009020532* 8009120234 8009030511 8009030556 8009090523	50-528 8 50-528 Q 50-528 A 50-528 8 50-528 A	Varoa, e a. Varoa, e a Varoa, e a Varoa, e a Varoa, e a	90922093 8009230115 8009230126 8009230126 8009230124	50-348 50-305 50-280

AUTHOR	ACCESSION	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
VARGA.8 A VARGA.8 A VARGA.8 A VARGA.8 A VARGA.8 A	8009240078 8009240094* 8009260609 8009120191 8009180304	50-315 P 50-315 P 50-315 Q 50-305 P	Hard.P C Marembourg. D Warembourg. D Warembourg. D Warembourg. D	8009300573 8009220318 8009030625 8009160290 8009160292	50-282 8 50-247 9 50-247 8 50-267 8 50-267 8	WERLING, J A	8007140444 8007140470 8009140405 8009190500 8009240450	50-334 8 50-334 8 50-334 8 50-334 8
VARGA, B A	8009180544 8009290439 8009290446* 8009290461 8009290461	50-286 P 50-280 P	Waremeduro, D Warembouro, D Warembouro, D Waremeduro, D Waremeduro, D	8007160344 8007160364 8007160286 8007160314 8007230578	50-267 P 50-267 P 50-267 R 50-267 P 50-267 8	WERLING, J A WERLING, J A WERNER, W WERNER, R WEBCOTT, H M	8007270251 8007300412 8007260068 8007230423 8007250352*	50-334 8 50-334 8 XPORTLIC 50-445 A 50-461 Q
VAROA, B A VAROA, B A VAROA, B A VAROA, B A	8007230385 8007230385 8007230370* 8007230377*	50-280 P 50-295 P	Warembourg, d Warembourg, d Warembourg, d Warembourg, d Warembourg, d	800923060B 8009230723 8009230689 8009240369 8009260378	50-247 8 50-247 R 50-247 P 50-247 R 50-247 R	WESCOTT.H M WEST.J B WESTERMAN.T F WESTERMAN.T F WESTERMAN.T F.	8007180061* 8007230764* 8007050477* 8007100055* 8007170172*	50-461 Q 50-320 H 50-267 Q 50-267 Q 50-382 Q
VAROA, S A	8007250155 8007250181 8007250172* 8007300077 8007300077	50-334 P 50-334 P 50-334 P 50-295 P 50-250 P	WAREMBOURG, D. WAREMBOURG, D. WARNICK, R F WARNICK, R F WARNICK, R F	8007230577 8007300554 8007150055* 8007150060* 8007160616*	50-267 8 50-267 8 50-445 0 50-445 0 50-305 0	WESTERMAN,T F WESTFALL,R M WESTFALL,R M WESTERMANN,M J WESTERMANN,M J	8009300282* 8009110885 8009110372 8009300119* 8009230027	50-267 Q RES NUREQ FOIA 50-375 O
VARQA,8 A VARQA,8 A VEATCH,H D VERDERBER,J J	B007260537 B007260541* B007260545* B007220277 B007030403	\$0-284 P 50-286 P 50-286 P NUREO 50-397 A	WARNICK,R F. WARNICK,R F WARRICK,R F WARREN,8 K WATERMAN,M E	8007160514* 8007270015* 8007300243* 8007260001 8007050405	50-358	WETTERHAHM, M J WETTERHAHM, M J WHARTON, R J UHARTON, R J WHARTON, R J	8009300014 8009300016 8009110399# 8009110399# 8009100406	50-35B 0 50-35B 0 50-361 0 50-361 0 50-361 0
VERRELLI, D M VEVE, H E, VILLALVA, I VILLEMY, Q R VINYCH, V	8007180163 8007270027 8007230767 8007160224 8007160486	50-366 F FOIA 50-255 P 50-201 Q HARTE MOT	WATERMAN, M E WATERMAN, M E WATERS, D. B WATERS, D. B. WATERS, M. B.	8007100520 8007260079 8007120437 8007120437 8007160258*	RE8 RE8 50-261 H 50-261 H 50-261 R	WHARTON, R J WHIYESELL, D E WHITESELL, D E WHIYESELL, D E WHIYESELL, D E	8007100406 8007190217* 8007180508* 8007270323* 8007100231*	50-361 Q Qa999 Qa999 Qa999 Qa999
VOEGELI, R J VOIGHT, B VOLLEN, R J VOLLEN, R J	8007270040 8007170263* 8007030703 8007030710 8007030703	50-313 P 50-440 K 50-367 O 50-367 O 50-367 O	HATSON, A P HATSON, M HATT, C H HAMZYNIECKI, P WEDER, D A	8009260550 8008250025 8009180371 8009300537 8009020366	RE8 50-574 0 50-320 P 40-791 50-312 P	WHITEBELL.D E WHITEBELL.D E WHITEBELL.D E WHITEBELL.D E	8007180119# 8007110618# 8007250327# 8007180536# 8007180566#	98989 98989 98989 98989 98989
VOLLEN, R J VOLLEN, R J VOLLEN, R J VOLLEN, R J	B009030710 8009120392 B009120445# B009120392 B009120445#	50-367 0 50-367 0 50-367 0 50-367 0 50-367 0	WEEKS,E D WEGENER,D HEGST,W F WEISLER,J,H WEISS,L A	8007120447 8007070287* 8007160321 8007040577 8007230206*	50-133 R 50-243 R 50-142 P 50-373 B FOIA	WHITE.C E WHITESELL.D E WHITESELL.D E WHITESELL.D E	8009190024* 8009080467* 8009150021* 8009170159* 8009180085*	QA777 QA797 QA777 QA777 QA777
VOLLEN, R J VOLLEN, R J VOLLEN, R J VOLLEN, R J VOLLEN, R J	6007230008 6007230308 6007230382 6007230373 6007230382	50-367 0 50-367 0 50-367 0 50-367 0 50-367 0	WEI88.L A WEI88.L A WEI88.E. R WEI88.E. R	8009230209* 8009230213* 8009230218* 8009250471* 8009080575*	FOIA FDIA FOIA TOPREP COMMISSION	WHITESIDES,O E WHITE,R N WHITE,C E WHITE,C,D WHITE,L D	8009110885 8009020355 8009190017# 8009110485 8009190667	RE8 NURE0 GA777 50-244 G PR
Vollen, R. J Vollen, R. J Vollen, R. J Volmer, G. J Vorderbruegoen	8007230373 8007240011 8007240011 8007180077# 8007120274#	90-347 0 50-347 0 50-347 0 48799 50-528 0	WEISS, D WEISS, D WEISS, E WEISS, E WEISS, D.	8009260176* 8009110246* 8009110249* 8009250467* 8009260170*	71~4058 70~754 70~820 TOPREP 71~4059	WHITE, L D WHITENER, H L WHITE, J, W WHITE, L D	8007240172# 8007300063* 8007050274 8007150414* 8007020026	50-244 Q 50-261 Q 50-244 V CONTRACT 50-244 P
VORDERBRUEGOEN VORDERBRUEGOEN VUHBACO, F. J HAGNER, A. O. WAGNER, H. J	8009190169# 8009190178# 8009120220# 8009120240# 8009120309#	50-52B Q 50-52B Q 40-2940 50-416 Q 50-460 Q	WE189, E.R WE189, E.R WE189, D. WE189, D. WE189, E.R	8009110549 8009120583 8009150476 8009150434 8009250452	FOIA FOIA 40-8584 50-275 P FOIA	WHITE, LOWHITE, LDWHITE, LDWHI	8009020086 8009020346 8009030494 8009030545 8009030485	50-244 V 50-244 B 50-244 P 50-244 P 50-244 P
WAGNER, F. T WAGNER, P. C HALBRIDGE, H C HALBRIDGE, H C WALBRIDGE, H C	8007180523 8007030347 8007070812 8007070813# 8007040400	71-6717 50-285 D 50-312 Q 50-312 Q 50-312 P	WE188, E R WE188, E R WE188, E, R WE188, D	8009040258 8009040358 8009040258 8009040358 8009190760	70-143 50-287 0 70-143 50-289 0 70-1193	WHITE, L D WHITE, L, D, WHITE, L, D, WHITE, L, D, WHITE, E, B	8007040414* 8007180265 8007070513 8007070377 8007110012	50-244 P 50-244 R 50-244 P 50-244 P PR
WALBRIDGE, W. C. WALBRIDGE, W. C. WALBRIDGE, W. C. WALKER, R. B. WALL, L. B.	8009240378 8007080433 8009290353 8009260205 8009160545	50-312 @ 50-312 P 50-312 P 50-320 H 40-8681	WE188, D WE188, E R WE188, E R WE188, E R WE188, E R	8009240742 8009110802 8009160046 8009160046 8009150041	70-140 50-155 Q PR FR 50-289 Q	WHITE, LD WHITE, LD WHITE, LD WHITE, LD WHITE, L, D,	8009070551 8009160539 8009170303 8009140317 8009170311	50-244 P 50-244 P 50-244 P 50-244 F 50-244 G
HALLACE.A HALLER.F & HALBH.E J HALBH.P.B WALBH.P.B	8009190405 8009190272 8009090421 8009260417# 8009260431*	NUREO 50-440 % 50-320 P 50-287 T 50-287 T	HEIBB, E R HEIBB, E R HEIBB, E R HEIBB, E R HEIBB, E R	8007150041 8009160046 8009300423* 8009300417 8009300423*	50-289 0 FR 50-289 0 50-289 0	MHITE,L D WHITNEY,O O WHITNEY,O O WHITNEY,O O	8009300369 8009030617* 8009020386* 8009030483* 8009090426*	50-244 P 50-293 8 50-293 8 50-293 8 50-293 8
HALBKE, C. WALTERB, D. K WALTERB, D. X WALTERB, P. W WALTON, Q. A	8007070347# 8007120141# 8007100238# 8007070330 8007050486#	50-339 P 50-416 G 50-400 G 50-289 H 50-410 G	WEITZBERO,A WENDERLICH,R L. WENDERLICH,R L WENDERLICH,R L WENDERLICH,R L	8007220226 8007120348* 8007160318* 8007230572* 8007300460*	50-201 0 50-317 8 50-317 8 50-317 8 50-318 8	WHITNEY, O, Q WICHERB, D L, WICHERB, D L WICHERB, D L WICHERB, D, L	8009160271# 8008110036 8008120614 8009170240 8009300191	50-293 R 40-8502 40-8502 40-8502 40-8502
WAMBACIEJ L HANATIB. M. HANATIB W HANOIC H HANOIC H.	8007260067 8007070331 8007070331 8007300172 8007300184	RE6 27-39 27-39 50-243 R 50-243 F	Wenslawski.f. Wenslawski.f Wenslawski.f Wenslawski.f. Weroard,a J.	8007240533* 8007300324* 8007180137 8007300615 8007030633	50-147 Q 50-344 Q 50-206 8 50-206 9 50-277 8	WICKHORST, P M WIDNER, W A WIDNER, W A WIDNER, W. A WIDNER, W A	8007160340* 8007110828* 8007050076 8007020287 8007020180	50-57 I 50-321 Q 50-321 Q 50-321 Q 50-321 Q
HARD, J. J HARD, K. D HARD, K. D HARD, E. C	8009150100* 8009110627* 8009150508* 8009160249* 8009300234	50-445 0 50-262 0 50-346 0 50-327 0 50-263 R	Werling, J A Werling, J, A Werling, J, A Werling, J A Werling, J A	8007050250 8009120377 8009150393 8009250251 8009160309	50-334 B 50-334 B 50-334 B 50-334 B 50-334 B	WIDNER, W A	8007020373 8007230105 8007110671 8007030484 8007110676	50-321 0 50-321 0 50-321 0 50-321 F 50-321 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	EUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	CATEGOI
HIDNER, HA HIDNER, HA HIDNER, HA HIDNER, HA HIDNER, HA	8009150162 8009240367 8009160448 8009300104 8009190423	50-321	MOLFE, 8 J MOLFE, 8 J MOLFE, 8 J MOLFE, 8 J	8009140530 8009110045 8009120407 8009140520 8009190229	70-2909 50-376 0 40-1162 50-466 0 50-466 0	YTHIER, P YUHAS, O YUHAS, O YUHAS, O YUNDT, C YUNDT, C P	8009300209* 8009180139 8009300615 8009250463 8009090410	CONTRACT 50-206 50-206 71-9016 50-344
Hiddeff, H P Hiddeff, H P, Higgins, J, T Higgins, E Higgins, E	9007020407 9007020407 9007150184* 8007300118 9007300073	50-289 0 50-289 0 50-277 G CONTRACT CONTRACT	MOCEE'S 7 MOCEE'S 7 MOCEE'S 7 MOCEE'S 7	8009260466 8009220417 8009220415 8009250058 8009260674	50-536 P 50-466 0 50-466 0 50-466 0 50-466 0	YUNDT.C P YUNDT.C P YUNDT.C P YUNDT.C P YUNDT.C P	8009150471 8009100453* 8009260506 8009100239 8009170309	50-344 50-344 50-344 50-344
HILBERT: R L HILBORN: L HILBORN: L HILBORN: L HILBUR: L. G	8009180321 8009080487* 8009180203* 8009180081* 8009020018	WABYE MOT 40-3453 40-1162 40-8452 50-134 F	HOLFE.8 J WOLFE.8 J WOLFE.8 J WOLFF.T A WOLTVEN.J	8009300439 8009300326 8009300456 8009190891 8009030693	50-376	YUNDT.C P ZABRISKIE.W L ZAHLER.R E ZAKLER.R E ZAKLER.R E	8009300471 8009100508 8009250017 8009250017 8009300022	50-344 RE8 50-289 50-289 50-289
HILKINSON, P. HILLCUTT, O.J. E. HILLCUTT, O.J. E. HILLIAHB, H. A. HILLIAHB, C. C.	8009160456 8009120589* 8009100036 8009020124* 8009150177*	NUREG 50-320 P NUREG 50-320 H 50-546 G	WOLLETT, 6 WOLLETT, 8 WOLLETT, 8 WOLLETT, 8	8007190702 8009180207 8009240023 8009240123 8009300592	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	ZAHLER,R E ZAJAG,L D ZAJAG,L D ZARAKAS,P ZARAKAS,P	8009300022 8009150377* 8009170143* 8009090242 8009120187	50-287 50-370 50-328 50-3 50-3
HILLIAMB, C C HILLIB, R, J HILLIAMBON, E L HILLIAMB, C C HILLIAMB, C C	8009180280* 8009300624 8009150304* 8009290465* 8009040599	50-373 Q F01A 50-438 Q 50-373 Q 50-373 B	WOLLETT, 8 HOLTKER, E WONG, T WONG, T WONG, T	8009260243 8009120235* 8008130375 8009160549 8009120390	CONTRACT 70-371 40-299 40-299 40-299	Zarakas, p Zarakas, p Zarakas, p Zarakas, p Zarakas, p	8009030416 8009030559 8009080329 8009030458 8009030610	50-247 50-247 50-247 50-247 50-3
HILLIAHB, R. L HILLIAHB, C. C HILLIAHB, C. C HILLIAHB, E. HILLIAHB, W. O	8009170144 8009290193* 8009290526* 8009160263* 8009190511*	40-8745 50-454	WOOD, L. D WOOD, J. C WOOD, E. C WOOD, E. C WOODHEAD, C. P.	8007110600 8007040287 8007260637 8007260494 8007020426	XPORTLIC 50-445 M 50-307 8 50-309 8 50-409 0	Zarakab, p Zarakab, p Zarakab, p Zarakab, p Zarakab, p	8009030387 8009090383 8009090484 8009090423 8009090306	50-3 50-3 50-247 50-3 50-247
WILLIENS, V H HILLSEY, W B HILLSEY, W B. HILLSEY, W B. HILLSEY, W B. HILSON, F R.	8009260439* 8009020245 8009160427 8009230569 8009190501	50-289 T 50-171 R 50-277 R 50-277 R 50-344 J	WOODLEY, 8 E WOODRUFF, R, L WOODRUFF, R W WOODS, Q R WOODSMALL, W A	8007150327* 8007270073* 8007070553 8007230016 8007270321*	50-289 H FOIA 50-317 P 50-142 Q 50-338 R	Zarakas, p Zarakas, p. Zarakas, p Zarakas, p. Zarakas, p	8009120353 8009160365 8009230432 8009230568 8009240452	50-247 50-247 50-3 50-247 50-3
Nileon, J. N Hilbon, J. L. Hilbon, B. D. Hilbon, B. D. Hilbon, B. D.	8009090631 8009100262* 8009100032 8009110273 8009110830	50-322 A 50-280 B XPDRTLIC XPDRTLIC XPDRTLIC	WOOLEVERIE, J WOOLEVERIE J WOZNIAK, D R WRAYIJ R WRAYIC	8009090114 8009090248 8009120574 8009020477* 8009050391*	50-334 @ 50-412 B XPORTLIC 50-348 @ 50-320 H	Zarakab, p Zarakab, p Zarakab, p Zarakab, p Zarakab, p	8009230451 8009250266 8009300384 8009300524 8009300481	50-247 50-3 50-247 50-247 50-247
HILBON, H E, HILBON, J L HILBON, J L HILBON, J L HILBON, J L	8009030528 8009020088 8009020090* 8009030525 8009020344	50-27 R 50-281 B 50-281 B 50-280 B 50-280 B	WRIGHT,R W WRIGHT,F 8. WULLER,O E WULLER,O E WULLER,O E	8009090259# 8009100421 8009090808 6009110631 8009040491	50-553 G 50-471 O 50-461 G 50-461 A	ZECH.O G ZEFF.D H ZEFF.D W ZEFF.D W ZELLNER,R J	8009190416 8009090874 8009180517 8009230457 80092304112	ACRS 70-1201 70-1201 70-1201 40-8724
Hilbon, J. T. Hilbon, J N Hilbon, J L Hilbon, J L Hilbon, J L	8007020350* 8009230772 8009080351 8009080366* 8009100252	50-280 8 50-324 P 50-281 8 50-281 8 50-280 8	WULLER, O E WULLER, O E WULLER, O E WULLER, O E WYATT, J	8009250457 8009020341 8009190513 8009240457 8009170383	50-461	ZGLICZYNSKI, J ZIBULBKY, H ZIBULBKY, H ZIEMIANSKI, E J ZIMMER, A M	8007030572* 8007110272* 8007120235* 8007070267* 7706270356*	50-59 70-135 70-371 50-293 PT9
Hilbon. 0, Hilbon. J. L. Hilbon. J. L. Hilbon. J. Hilbon. J. L.	8007160425* 8007150274 8007150278* 8007170444* 8007220248	50-327 B 50-280 B 50-280 B 50-280 R 50-281 B	WYDLER, J W WYDLER, J W YACKLE, T R YACKLE, T R YACKLE, T R	8007020217* 8007120494* 8007050403 8007100520 8007260077	COMMISSION COMMISSION RES RES RES	ZIMMERMAN,R P ZIMMERMAN,L R ZIRWAS,K ZITO,N ZITTEL,H E	8009150088* 8009260304* 8009230687* 8009150305 8009240253	50-249 TOPREP 90-237 FO1A RE9
WILSON, J. L. WILSON, J. L. WILSON, J. L. WILSON, J. L. WILSON, J. L.	8007220253 8007220258* 8007220240* 8007220263* 8007220307*	50-280 8 50-280 8 50-280 8 50-280 6 50-281 8	YANDELL, L A YERKES, R F YESSD, J D, YIN, I. T YIN, I T.	8007050477* 8009160363* 8009150597 8009120657* 8009290101*	50-267	ZOBEL,W ZUDANB,J ZULLA,B S ZULLA,B B ZULLA,B B	8007030438* 8007240179* 8007080537 8007220030 8007080323	50-327 50-313 30-286 50-286 50-286
WILEON, J. L. WILEON, J. L. WILEON, J. N. WILEON, J. L. WILEON, J. L.	8007220398* 8007220402* 8007170400 8007170553 8007170557*	50-281 8 50-281 8 50-324 P 50-280 8 50-280 8	YOUNGBLOOD, B J	8007180054# 8007110411 8007020474# 8007230217# 8007050172	50-373	ZULLA/B S ZUMBRUM/R A ZUMBRUM/R A ZWETZIG/G B ZWICK/E J.	8009190442 8009110012 8009110012 8009120478* 8009300333	50-286 PR PR 50-326 FOIA
Hilson J L Hilson J L Hilson J L Hilson J L	8009190566# 8009260091 8009230645 8009230661# 8009230673#	50-280 8 50-322 A 50-280 8 50-280 8	TO BE SECULARY OF SECULARY SEC	8007050176+ 8007050204+ 8007160659+ 8007120558 8007100152	50-337 P 50-337 P 50-337 P 50-373 Q 50-369 A			
HILBON, J. L. HILBON, J. HILBON, J. L HILBON, J. L HILBON, W. E.	8007240467 8007240470* 8007240471* 8007240473* 8007300371	50-281 8 50-281 8 50-281 8 50-281 8 50-27 P	ADONOSEODES 7 ADONOSEODES 7 ADONOSEODES 7 ADONOSEODES 7 ADONOSEODES 7	8009110187 8009110397 8009110400 8009110859* 8009110854	50-454 F 50-455 F 50-373 F 50-502 A 50-502 A			
WILEON, J. L. WILEON, J. L. WILEON, J. L. WILEON, J. L. WINTERB, L. WIZNER, D. O	8007300478 8007300304* 8007300308* 8007030010 8007170322*	50-281 8 50-281 8 50-281 8 RES 50-316 8	YOUNGBLOOD, B J. YOUNGBLOOD, B J. YOUNGBLOOD, B J. YOUNGBLOOD, B J.	8009240636 8009180336 8009130319 8009290169 8009260012*	50-337 E 50-367 H 50-337 P 50-369 A 50-389 0			
	C080180800*	80-01# G	YOUNGBLOOD, B J	8009260013*	50-389 Q			

50-315 71-2 71-394 50-320 50-237

8009190509* 8009260074 8009290024 8009040239 8009110813

WIINER, D. Q. HOLF, C. R. HOLF, C. R. HOLF, J. F. HOLF, J. F.

C 8. GOODAGNUDY C 8. GOODAGNUDY C 8. GONUDY C 8. GONUDY THIER, P

8009260013* 8009300105 8009300108* 8009290490 8009300198*

O A A P

50-389 50-389 50-389 50-339 CONTRACT

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketsd items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO	
ATCOR	8009260074	71-2			8009160308*	50-34B	В
	8007270024	71-396			8009140320	50-348	B
Advanced Energy Systems	E009240690	ACRS			8009160323#	50-348	8
	8007260217	ACRS			8009160358	50-348	Ē
Advisory Council on Historic Preservation	8009160545	40-8681			8009160415	50-364	Ä
Agriculture, Dept of, Forest Service	8009220114	WARTE MG			8009170214	50-364	A
Air Force Dept of	6007040269*	50-155	0		8009170353	50-364	A
Air Transport Association	8009160206	PRM			#6EE07170356*	50-364	A
Air and Water Pollution Patrol Al Stern Associates	8009020171* 8009240147	50-320 F01A	H		6009190583* 8009230448	50-348 50-364	G A
Nabama Power Co	8009020030	50-364	A				
A S D D M I D T B I C D	8007020038	50-364	Ä		8009230465	50-364	A
	8007020045	50-344	Ä		8009230566	50-34B	R
	8009020062	50-348	8		8009230710	50-34B	8
	8009020068*	50-349	9		6009230722 8009230729*	50~34B 50~34B	8
	8007020271	50-348	Q				
	8009020301	50-344	ā		8009230737#	50-348	B
	8009030427	50-348	8		8007270327 8007270371	50-364 50-364	A
	E009030429*	50-348	8		8009300381	50-348	P
	8009030491	50-348	R		1850055008	50-348	9
	8009030492	50-364	A	•	8009300424	50-348	P
	8007030495*	50-340	R		9009300435	50-34B	Ì,
	8009040246	50-364	Ą		800930045B	50-364	į
	8007040251*	50-364	Ą		B007300463	50-364	- 0
	8007040386	50-344	Α		8009300511	50-34B	8
	8009040387*	50-364	Ą		8009300515*	50-348	8
	8009040389*	50-364	A		B009300523	50-348	8
	8009040390*	50-364	Ą		8009300527*	50-348	8
	# FECO40000 # EFEC0400000	50-364 50-364	A		8009300534 8009300572	50-348 50-348	9
	200204000E#	50-364					
	8007040375* 8007050052	50-348	A Q		E009300577*	50-348	8
	8009080293	50-344	Å	Alabama, State of	8009150411	70~2909	
	8007080243	50-348	P		8009260238*	CONTRAC	Ţ
	8009080387	50-348	P	Aldrich Chemical Co , Inc. (subs of Bigma-Aldrich Corp)	8009110592	XPORTLE	C
	8009090366	50-348	P		B009110596*	XPORTLI	C
	8007070546	50-348	ė		0000000000	VEC	_
	B007070585	50-348	F		8007120624	XFORTLI YOUGH	
	8009100237	50-364	Ġ.	Allied Chemical Corp	8009120627# 8009300241	XPURTLI 40-3392	
	8009100318	50-348	Ý	Allied Congral Nuclear Services	B007300241	50-332	G
				utefan galistat Upriadi par Alras	8007300549	50-201	G
	8009100318	50-348	٧				_
	8009100324	50-364	F	American Electric Power Co., Inc	8009190422	50-315	R
	8007100363	50-344	a		6007170447	TOPREP	
	8007110258	50-34B	q	American Institute of Chemical Engineers	0009300540	50-201	G
	8009110697	50-348	Q	American Nuclear Society	8009110012	PR	_
	8009120425	50-348	þ	American Society of Mechanical Engineers	8009100409#	CONTRAC	
	8007150257	50-348	K	Ametak, Inc	*P90081500B	0A777	
	8009150259	50-348	ĸ	Anaconda Co , Anaconda Copper Co Div	8007300232	H STEAM	
	8009150260*	50-348	K	Anti-Nuclear Group Representing York	8009120226	50-269	G
	8009150263*	50-348	K	• • •	E007120232	50-289	Q
	8009150263*	50~34B	ĸ		8007230437	50-289	G
	8007150484	50-384	Α	Aptach Engineering Services	8007220247*	50-329	A
	8007150484 8007160268	50-348	R	Aptech Engineering Services Argonne National Laboratoru	8007220247* 8007020477	50-329 Nurec	A
	8007150484			Aptech Engineering Services Argonne National Laboratory	8007220247* 8007020479 8007040104*		A

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOUS	
Arizona Public Service Co	8007070364 8007070607* 8007300442 8007020532* 8007030511	50-171 COMMISS 50-445 50-528 50-528	F FIGN C B A		8009160296# 8009160256# 8009170241 8009170322 8009170322	50-313 50-313 50-313 50-313 50-313	RVFF
	8007030511 8007030511 8007030511 8007030556 8007030556	50-528 50-528 50-528 50-528 50-528	A A S S		8007180424 8007180427* 8007190494* 8007230407 8007230410*	50-368 50-368 50-382 50-368 50-368	Р Н Я
	800903055 <i>b</i> 8009030674 8009030714 8009050499 8009090392	50-528 50-528 50-528 50-528 50-528	8 0 0 0 0	n	8009230697 8009230700* 8009230705 8009230708 8009230712*	50-313 50-313 50-368 50-313 50-368	R # # 8
	8007070378* 8007070523 8007120234 8007160373 8007160373	50-528 50-528 50-528 50-528 50-528	C A Q T T		8009230715* 8009230744 8009230748* 8009240496 8009240504*	50-313 50-348 50-348 50-348 50-348	88988
	8009160373 8009160379* 8009160379* 8009160379* 8009230653	50-528 50-528 50-528 50-528 50-528	T T T S		8007260453 8007260456* 8007300173 8007300242 8007300278	50-368 50-368 50-313 50-368 50-313	P P P
	8009230453 8009230453 8009230701 8009230701 8009230701	50-528 50-528 50-528 50-528 50-528	6 6 C C	Army, Dept of, Corps of Engineers Army, Dept of, Office of Surgeon General Association of Community Organizations for Reform Now-Texas	8009300538 8009300546# 8009180237# 8009020179# 8009090238	50-369 50-369 50-546 50-327 50-445	8 9 0 4 0
	8009240422 8009300355 8009300402 8009300402 8009300402	50-528 50-529 50-528 50-528 50-528	A S K K K	Atlas Minerals Atomic Industrial Forum	8007150045 8007080480* 8007110737 8007170143 8007070347*	50-445 40-3453 40-3453 40-3453 50-339	o P
Thansas Power & Light Co	8009300405* 8009300405* 8009300405* 8008280022 8009020001	50-528 50-528 50-528 50-313 50-313	K K G R	Atwood & Morrill Co . Inc (subs of Foster Wheeler Corp)	8007070517 8007170668* 8007270312*	PR FOIA GA799	
	8009020001 8009020042 8009020244 8009020449 8009020458* 8009030393	50-313 50-313 50-313 50-368 50-313	P Q S 8 P	Austin, TX	8009290314* 8009290315* 8009290316* 8009290318* 8009040289 8009170239*	GA797 GA797 GA797 GA797 50-445 50-445	H
	8007030410 8007030417* 8007030422 8007030425* 8007030537	50-348 50-368 50-368 50-348 50-313	9 8 8	Australia BDM Corp Babcock & Wilcox Co	8008250025 8007110271 8007020364 8007030001 8007030004	50-574 FOIA TOPREP 70-27 70-1201	Q
	8007030537 8007030537 8007030546* 8007030550 8007030550	50-313 50-348 50-368 50-313 50-313	C C S B C C C S		8009030445* 8009030445* 8009030319* 8009080438* 8009100175*	50-99 50-99 50-287 50-312 50-346	ь ь ь
	8007030628 × 8007030628 × 8007040049 × 8007050330 × 8007070326	50-368 50-368 50-313 50-313 50-313	9 9 0 V		8009100233 8009110667 8009120270 8009120586* 8009180177*	TOPREP 70-824 TOPREP FOIA GA799	
	8007070324 8007070378 8007070385* 8007070425 8007070425	50-313 50-348 50-348 50-313 50-313	F		8007180185* 8007180517 8007230457 8007230707 8007240534*	0A999 70-1201 70-1201 50-287 50-302	b b
	8007070432* 8007070432* 8007070482 8007070491* 8007070562	50-313 50-313 50-313 50-313	R R P B		8007260335* 8007260335* 8007260352* 8007260352*	50-289 50-289 50-289 50-289 50-289	T T T T T
	8007120387 8007150258 8007150261* 8007150268	50-313 50-313 50-368 50-368 50-368	6 6 8 8	Dabcock & Wilcox Co Naval Nuclear Fuel	8007260366* 8007260380* 8007260402* 8007270373* 8007070885	50-289 50-289 50-289 50-329 70-27	T T A
	8009150271* 8009150273 8009150275* 8009150287 8009150292*	50-368 50-368 50-368 50-368 50-368	ន ន _P P	Div Babcock & Wilcox Co , Nuclear Material Div	8009110767 8009090876	70-27 70-135	
	8007150273 8007150276* 8007160228 8007160251	50-368 50-368 50-313 50-313	6 5 P R		8009110244 8009150019 8009150480 8009150553	70-135 71-6400 70-135 71-5442	
	B007160251	50-313	R		8009180183	70-135	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Babson College Bater & Sotts	8009180196# 8009230138 8009230139* 8009020176 8009040271	70-135 70-364 70-364 FOIA 50-466	Q	Bear Creek Uranium Co Bechtel Corp	8009140481 8009260688 8009030462 8009030465* 8009020427*	NUREG NUREG 40-8452 40-8452 50-416 A
	8009160157 8009160201 8009180475 8009300027 8009300469	50-445 50-466 50-466 50-466 50-466	ж е е	Bechtel National Inc	*05405070808 *4540507008 *85405070008 8007170672	50-416 A 50-416 A 50-416 A NUREO 50-528 S
Baltimore Cas & Electric Co	8007020020 8007020034 8007020034 8007020035* 8007020035*	50-317 50-317 50-317 50-317 50-317	P R R R	Bechtel Power Corp (subs of Bechtel Corp) Beltway Limousine Service, Inc Bergen-Patterson Pipe Support Corp Herle, Butzel, Kass & Case	8007080326* 8007030085* 8007120697 8007110484	50-206 P CONTRACT PT21 50-201 0
	8007030014 8007030520 8007030522* 8007030543 8007030547*	NUREO 50-317 50-317 50-318 50-318	\$ \$ \$ \$	Bertin, Roisman & Kessler Bernard C Dayle Bio-Tec, Inc	8007120543 8007070342* 8007070343* 6007110338* 8007110274* 8007110302*	50-201 P 50-247 0 50-247 0 CONTRACY FOIA
	8007040301 8007080350 8007120344 8007120348* 8007120354	50-317 50-317 50-317 50-317 50-317	8 8 8 8 8	Black & Veatch Black & Veatch Boeing Computer Services, Inc (subs of Boeing Co.)	8009120037* 8009290296 8009190782	CONTRACT NUREQ NUREQ
	8009120378* 8009120447 8009120455* 8009150250 8009160315	50-317 50-317 50-317 50-317 50-317	9 6 9 9 8	Boston College Boston Edison Cu	8007230755* 8007020110 8007020382 8007020386* 8007030477	50-293 S 50-293 S 50-293 S 50-293 S
	8007160318* 8007160453 8007160453 8007160504 8007170665	50-317 50-317 50-317 50-317 50-317	5 P Q 8		8007030594 8007030594 8007030597* 8007030403 8007030407*	50-273 S 50-273 S 50-273 S 50-273 B 50-273 B
	8009230520 8009230527* 8009230531 8009230536* 8009230542	50-318 50-318 50-317 50-317 50-317	8 8 8 8		8007030611 8007030617* 8007050484 8007080546 8007090034	50-273 6 50-273 8 50-273 0 50-273 0 50-273 0
	8007230946* 8007230583 8007230592* 8007230634 8007230640*	50-317 50-317 50-317 50-317 50-317	6 8 9 P		8007070048* 8007070261 8007070267* 8007070367 8007070374*	50-293 0 50-293 R 50-293 R 50-293 8 50-293 8
	8007230688 8007230675# 8007250311 8007250311	50-317 50-317 50-317 50-317 50-317	8 9 9 8 R		8007070387 8007070401* 8007070422 8007070426* 8007070430	50-273 S 50-273 S 50-273 S 50-273 S 50-273 S
	8007270246 8007270248* 8007270248* 8007300383 8007300383	50-317 50-317 50-317 50-317 50-317	R R R F		8007070433* 8007070660 8007120036 8007150081* 8007150270	50-293
	8009300438 8009300438 8009300441 8009300450* 8009300454	50-317 50-317 50-317 50-317	J S S		8009150279* 8009150284 8009150285* 8009160267 8009160271*	50-293 P 50-293 P 50-293 P 50-293 R 50-293 R
Barr Engineering Co	9007300460* 8007300464 8007300470* 8007110770	50-318 50-318 50-317 50-317 40-299	8 5 6		8007160346 8007160376 8007160402* 8007160404	50-293 P 50-293 8 50-293 8 50-293 8
Battatia Massalal Jackibuka Galamkus	8007110774* 8007300286* 8007070886	40-299 40-299 70-8			8007160410* 8007160447 8007160452	50-293 8 50-293 8 50-293 8
Battelle Memorial Institute, Columbus Leberatories	8007100041* 8007100043 8007150597	CONTRACT NUREO NUREO	г		8009160455# 8009160483* 8009160516 8009160519	50-273 S 50-273 S 50-273 Q 50-273 Q
Battelle Memorial Institute, Pacific Northwest Laboratory	8007180217* 8007190738* 8007240038* 8007300164 8007020219	CONTRACT CONTRACT CONTRACT NUREO 50-445	Γ		8009170329 8009170391 8009190076* 8009190940 8009220250 8009220252*	50-273 F 50-273 S 50-273 Q 50-273 V 50-273 V
	8009100403 8009100413 8009110419 8009110421 8009110483	NUREO NUREO RES REB RES			8009230453 8009230732 8009230739* 8009240462 8009240463*	50-293 P 50-293 S 50-293 S 50-293 S 50-293 S
	8009120205 8009150597 8009160456	TOPREP NUREO NUREO			8009240467 8009240468* 8009250049	50-293 S 50-293 S 50-471 O

AUTHOR AFFILIATION	ACCESS I ON NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJEC CATEGO	
	6009260470 6009260475* 6009260480 6009260481 6009260484*	50-273 50-273 50-273 50-273 50-273	555555	California, Univ of Irvine	8009230016 8009230018* 8009230021* 8009120466* 8009120471*	50-142 50-142 50-142 50-324 50-326	0 0 0
	8009260485* 8009290283 8009290284 8009290313* 8009290317*	50-293 50-293 50-293 50-293 50-293	5 5 5 9	California, Univ of, Los Angeles	8009150234 8009160321 8009160322# 8009190405 8009240605	50-70 50-142 50-142 NUREQ NUREQ	O P P
Brand & Hall	8007300500 8007300505* 8007300531 8007300535* 8007020448*	50-293 50-293 50-293 50-293 50-395	# # \$ \$ #	Carolina Power & Light Co	8009260028 8008280370 8009020198 8009020199 8009020203	NUREQ NUREQ 50-261 50-324 50-400	9
Brookhaven National Laboratory	8009150307 8009150312* 8009160337 8009210618* 8009020032	50-375 50-375 50-375 50-327 50-273	M H O P E		8007020321 8007020321 8007020380 8007020371* 8007030307	50-324 50-324 50-324 50-324 50-261	g 8 8 0
	8007020053 8007020053 8007020053 8007070342 8007070362	50-171 50-171 50-171 50-171 50-171	E E F F		8007030320 8007030457 8007030463* 8007080254 8007080254	50-335 50-261 50-261 50-400 50-400	9 8 8 8
	8007070362 8007070424 8007070487* 8007070564 8007070567	50-171 50-171 50-275 50-285 50-293	F 0 F F		8007080254 8007080254 8007070402 8007070402 8007070448	50-400 50-400 50-324 50-324 50-324	8 F F
	8007070770 8007100747 8007100750 8007110321 8007110416	RES NUREO NUREO NUREO REB			800707044B 8009100241 8009100433 8009100465 8009100465	50-324 50-400 50-324 50-400 50-400	P G B B
Brownsville, TX	8007170401 8007220375 8007240686 8007250247* 8007020282	RES TOPREP NUREO 50-327 50-445	P M		8007100465 8007110027 8007110027 8007110027	50-400 50-400 50-324 50-324 50-261	8 0 0
	8009150417 8009160182 8009160275 8009260318 8009300013	50-445 50-445 50-445 50-445 50-445	н н н н		8009110354 8009110442 8009120228 8009120344 8009120371#	FOIA 50-324 50-261 50-325 50-325	g 8 8
iruce Norton durns & Rae Co	8007030689 8007030699 8007220213 8007030359 8007030364*	50-275 50-275 50-323 TOPREP TOPREP	G G G		8009120437 8009120437 8009120437 8009120437 8009120437	50-261 50-261 50-261 50-261 50-261	н н н н
C-E Operating Plants Owners Group	8007030403 8007150435± 8007170317± 8007170684 8007230581	50-397 50-320 50-320 NUREO TOPREP	A P P		8007120437 8007120437 8007120573 8007120573 8007120573	50-261 50-261 50-400 50-400 50-400	H G G
C-E Power Bystems	8007150028 8007170017* 8007170024* 8007240360 8007240520	70-1100 QA999 QA999 50-317 TOPREP	P		8009120593 8009150284 8009150289* 8009160255 8009160258*	50-400 50-261 50-261 50-261 50-261	Q S B R R
COS, Inc CONOCO, Inc (Continential Oil Co)	8007240527* 8007250422* 8007120336 8007150585 8007070178	TOPREP 70-34 NUREQ NUREQ 40-8743			8009140260 8009140260 8009140243* 8009160376 8009170186	50-324 50-324 50-324 50-324 50-324	R R P P
Cahili, Qordon & Reindel	8007050442 8007050446* 8007110632 8007110635* 8007020462*	XFORTLIC XFORTLIC XFORTLIC XFORTLIC 50-395			8007170184 8007170191* 8007170191* 8007170197* 8009180365	50-324 50-324 50-324 50-324 50-324	P P P
California Institute of Technology California, State of	8007020071* 8007030581 8007030438 8007030443* 8007030447*	50-204 50-275 PR PR PR	Р H		8009180450 8009180450 8009180450 8009180450 8009180570	50-400 50-400 50-400 50-400 50-324	0 0 0 8
	8009110019 8009110024 8009150404 8009170339 8009190863	50-275 PR 50-275 50-312 State Pr	0 0 P 09		8007170425 8007170427* 8007170467 8007170477* 8007230057	50-325 50-325 50-261 50-261 50-324	P S B 0
	8009220406 8009230616 8009250456* 8009020040 8009020049	50-275 50-275 50-361 50-224 50-224	0 A P F		8007230057 8007230047 8007230080 8007230080 8007230085	50-324 50-400 50-324 50-324 50-324	G G G

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	
	8007230085 8007230438 8007230438	50-324 50-324 50-324	G P P	Citizens Committee for Protection of the Environment	8009110044* 8009090363*	50-445 50-247	Ç Ç
	E009230439* E009230439*	50-324 50-324	P P	Citizens Energy Forum Citizens for Fair Utility Regulation	8009230013 8009100425 8009260005	30-280 50-445 50-445	0 G
	8009230459 8009230459 8009230488* 8009230624	50-324 50-324 50-219 50-325	S S S	Citizens for the Conservation of Natural	8007250008 8007040225	50-445 50-376	G G
	8007230635* 8007230670	50-325 50-325	s	Resources, Inc	6007040233 6007110010 8007110055	50-376 50-376 50-376	0 0 0
	8007230483* 8007230473 8007230473 8007230707	50-325 50-324 50-324 50-325	5 0 0 8	Cleveland Electric Illuminating Co	8007180564 8007260670 8007260681* 8007260684*	50-376 50-376 50-376 50-376 50-440	0 0 0
	8009230718 8009230719 8009230725 8009230727*	50-325 50-324 50-325 50-324	9 8 8 5	•	8007100112* 8007120277 8007160636 8007170133	50-440 50-440 50-440 50-440	9 0 K
	8009230735* 8009230736 8009230740* 8009230745* 8009240340*	50-325 50-325 50-325 50-325 50-324	8 8 8 9		8009190133 8009190138* 8009190141 8009190141	50-440 50-440 50-440 50-440 50-440	K K K K
	8009240348 8009240356* 8009240370 8009240370 8009250262	50-261 50-324 50-324 50-324 50-261	Q Q Q Q P		8009190144 8009190144 8009190149 8009190149	50-440 50-440 50-440 50-440 50-440	K K K K K
	8009250265 8009250265 8009250301 8009250304* 8009250351*	50-324 50-324 50-261 50-261 50-400	5 8 8 0		8009190156 8009190162 8009190162 8009190165 8009190165	50-440 50-440 50-440 50-440 50-440	K K K K
	8009250351* 8009250351* 8009250351* 8009260497 8009260509	50-400 50-400 50-400 50-400 50-400	Q Q Q Q H		8009190219 8009190219 8009190224 8009190224 8009190234	50-440 50-440 50-440 50-440 50-440	K K K K
	8009260635 8009260638* 8009290286 8009290288 8009290309*	50-324 50-324 50-325 50-324 50-324	6 8 8 8 8		8009190234 8009190240 8009190240 8009190244 8009190244	50-440 50-440 50-440 50-440	K K K K
	8009290311* 8009300357 8009300474 8009300479* 8009300489	50-325 NUREQ 50-324 50-325	8 8 9 9		8009190248 8009190248 8009190252 8009190252	50-440 50-440 50-440 50-440	K K K K
Carpenter Technology Corp	8009300509* 8009300559 8009300568* 8009300581 8009120574	50-325 50-325 50-325 50-400 XPORTLIC			8009190253* 8009190263* 8009190270 8009190270	50-440 50-440 50-440 50-440	X K K K
Central & South West Corp	8009170177 8009170235* 8009170235* 8009170239* 8009170349*	50-445 50-445 50-445 50-445	# # # #		8009190272 8009190272 8009190279 8009190279 8009190285	50-440 50-440 50-440 50-440 50-440	K K K K
Cerac. Inc Ghem-Nuclear Bystems, Inc Chickering & Gregory	6009170369* 8009090665 8009220172 8009260059 8009110396	50-445 XPORTLIC 71-9080 71-9097 50-361	o		8009190293 8009190293 8009190294 8009190294	50-440 50-440 50-440 50-440	К К К
Christa-Maria Cincinnati Gas & Electric Co	8009110397* 8009190083 8009110802 8009240450 8009030588	50-361 50-361 50-155 50-155 50-358	0 0 0 F		8009190303 8009190305 8009190305 8009190309	50-440 50-440 50-440 50-440 50-440 B0-440	* * * * * * * * * * * * * * * * * * * *
	8007030570* 8007050272 8007170422 8007170429 8007250227*	50-358 50-358 50-358 50-358 50-358	F 0 0 0		8007170307 8007170312 8007170314 8007170314 8007170314	50-440 50-440 50-440 50-440 50-440	K K K K
Citisuns Against Nuclear Dangers	8009260137 8009270460* 8009300016 8009300126* 8009180394	50-358 50-358 FOIA 50-397	Q Q		8009190318 8009190321 8009190321 8009190329	50-440 50-440 50-440 50-440 50-440	K K K
Citisens Association for Sound Energy	8009090579 8009090579 8009110034 8009110034 8009110044*	50-445 50-445 50-445 50-445 50-445	0 0 0		8009190329 8009190334 8009190334 8009190337	50-440 50-440 50-440 50-440	K K K

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	GATEO	
	8009190337 8009190342 8009190342 8009190371 8009190371	50~440 50~440 50~440 50~440 50~440	K K K K		8007030507 8007030516# 8007040632 8007050347 8007080338	50-237 50-237 50-237 50-237 50-254	8 6 9 P
	8009190404 8009190404 8009190406 8009190406 8009190407	50-440 50-440 50-440 50-440 50-440	К К К К		8007080341* 8007080355 8007080378 8007080407* 8007080412	50-254 50-295 50-265 50-265 50-265	8 8 8 8
	6009190407 6009190408 6009190408 6009190410 6009190410	50~440 50~440 50~440 50~440 50~440	K K K K		8007080417* 8007080422 8007080427* 8007070013 8007070013	50-265 50-254 50-254 50-237 50-237	6 8 8
	8009190411 8009190411 8009190413 8009190413 8009190431	50-440 50-440 50-440 50-440 50-440	Х К К А		8007070274 8007070274 8007070274 8007070278* 8007070278*	50-559 50-295 50-295 50-295 50-295	0 R R R
Cohn, D B	6009190431 8009190435* 8009190435* 8009030149 8009030152*	50-440 50-440 50-440 50-367 50-367	A A C C		E009090394 E009090394 E009090394 E009090537* E009100532	50-237 50-237 50-237 50-458 TOPREP	P P F
Colorado State Univ Colorado, State of	8009020200* 8009160488* 8009190717 8009260233* 8009190874	40-4492 CONTRAC RECOD 50-267 State P	T R		8009100548* 8009110217 8009110300 8009110376 8009110376	TOPREP 70-2409 50-295 50-10 50-10	P P P
Colt Industries, Inc , Fairbanks Morse Engine Div Combustion Engineering, Inc	8009190977* 8009040425 8009050308* 8009110325 8009110704	State P 50-352 50-361 50-335	70g 8 A P		8007110545 8007110545 8007110545 8007110545 8007110545	50-237 50-237 50-237 50-237 50-237	G G G
Commerce,Dept of, National Bureau of Standards	8007230546# 8007230550# 8007100504	70-1100 50-317 50-317 50-184	P F		6007110545 6007110545 6007110545 6007110545 8007110545	50-237 50-237 50-237 50-237 50-237	G G G Q
Commerce.Dept of National Oceanographic 8 Atmospheric Adminstration Committee to Bridge the Cap	8009290243 8009110847 8009120014* 8009040203	71-5740 WABTE M CONTRAC 50-142			8009110545 8009110545 8009110562 8009110562 8009110562	50-237 50-237 50-237 50-237 50-237	0 0 0
Commonwealth Edison Co	8009240446 8009020105 8009020105 8009020109	50-142 50-237 50-237 50-10 50-10	P P Q		8009110362 8009110737* 8009120253 8009120299 8009120302	50-237 50-254 50-254 50-295 50-295	0 0 R 8
	8007020107 8007020107 8007020107 8007020107 8007020107	50-10 50-10 50-10 50-10 50-10	0 0 0		8009120305 8009120320* 8009120324* 8009120331* 8009120391	50-295 50-295 50-295 50-295 50-254	8 8 8
	8007020276 8007020277* 8007020274 8007020381 8007020388*	50-304 50-304 NUREG 50-237 50-237	\$ S		8009120399* 8009120404 8009120446 8009120446	50-254 50-10 50-454 50-454	9 P F F
,	8009020390 8009020395 8009020396* 8009020401* 8009020447	50-254 50-295 50-254 50-295 50-295		8 8	3007120446 3007120453 3007120453 3007120453	50-454 50-454 50-10 50-10 50-10	F F F F
	8007020452 8007020455# 8007020457# 8007030437	50-295 50-295 50-295 50-295	9 8 8	8 8 6	3009150399 3009160216 3009160272 3009160272	71-9113 50-237 50-254 50-254 50-254	P R R R
	**************************************	50-295 50-295 50-295 50-295 50-295	P P R R	5 8 8	7007160276* 7007160273 8009160305* 8009160355* 8009160374	50-254 50-304 50-304 50-311 50-334	6 8 8
	800703044# 800703044B 800703044B 8007030453#	50-295 50-254 50-254 50-254	R R R R	6 8 8	007160408 007160426* 007160585 007160681		s A Q
	8007030454 8007030454 8007030456 8007030467*	50-10 50-10 50-10 50-10	R R R	8 8	007160681 007160681 007160681 007160681	50-237 50-237 50-237	0 0 0 0
	8007030447* 8007030447*	50-10 50-10	R R	8	009140481 009140481	50-237	ā

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8009160681 8009160681 8009160681 8009160681 8009160681	50-237 50-237 50-237 50-237 50-237	0 0 0 0 0		8009260213 8009260465 8009260511 8009260638* 8009270334	50-275 50-237 50-273 50-275 50-10	P A G P
	8009170230 8009170230 8009170230 8009170411 8009170411	50-237 50-237 50-237 50-10 50-10	0 Q Q Q		6009290335 6009290397 8009300200 8009300200 6009300200	50-10 50-373 50-10 50-10 50-10	P 0 0 0
	8009170411 8009170411 8009170411 8009170411 8009170411	50-10 50-10 50-10 50-10 50-10	Q Q Q Q		8007300200 8007300200 8007300200 8007300200 8007300200	50-10 50-10 50-10 50-10 50-10	0 0 0
	8009170421 8009170421 8009170421 8009170421 8009180261	50-237 50-237 50-237 50-237 70-2609	0 0 0		8009300200 8009300200 8009300200 8009300200 8009300200	\$0-10 \$0-10 \$0-10 \$0-10 \$0-10	0 0 0
	800918040A 800918046A 800918046A 800918046A	50-373 50-10 50-10 50-10 50-10	A Q Q Q		8009300267 8009300273* 8009300287 8009300287 8009300287	50-295 50-295 50-10 50-10 50-10	でなって
	8009180466 8009180466 8009180466 8009180466 8009180466	50-10 50-10 50-10 50-10 50-10	G G G		8004300287 8004300287 8004300287 8004300287 8004300287	50-10 50-10 50-10 50-10 50-10	>>>>
	8009180466 8009180466 8009180466 8009190007 8009190007	50-10 50-10 50-10 50-373 50-373	0 0 0 0		8009300287 8009300287 8009300287 8009300287 8009300287	50-10 50-10 50-10 50-10 50-10	****
	8009190007 8009190007 8009190007 8009190007 8009190403	50-373 50-373 50-373 50-373 50-295	Q Q Q Q P		8009300455 8009300468 8009300472 8009300473# 8009300478*	50-454 50-237 50-237 50-237 50-237	A 9 9
	8007170403 8007170448 8007170468 8007220268 8007220271#	50-295 50-295 50-295 50-265 50-265	P P P B B	Computer Data Systems, Inc Computer Systems Support Corp Comsip.Inc , Delphi Systems Div Congress (Joint & Rotating Committees, etc)	9009190191* 9009190190* 9009190255 9009240117*	CONTRACT CONTRACT PT21 FOIA	
	8009220274 8009220278* 8009220281 8009220287* 8009220293	50-304 50-304 50-295 50-295 50-10	8 8 8 6	Connecticut Yankaa Atomic Powar Co	8007020015 8007020016* 8007020231 8007030378 8007030641 8007030645*	50-213 50-213 50-213 50-213 50-213 50-213	G 0 P P P P
	8009220349 8009220352* 8009230463 8009230466* 8009230390	50-275 50-275 50-10 50-10 50-322	5 9 P P		8007040380 8007110474 8007120247 8007120257 8007180175	50-213 50-213 50-213 50-213 50-213	ROOPR
	8007230672 8007230674 8007230681 8007230684* 8007230687*	TOPREP 50-237 50-304 TOPREP 50-237	S S		8007180180* 8007180357 8007180357 8007230621 8007270351	50-213 50-213 50-213 50-213 50-213	R P P
	8009230704* 8009230713 8009230720* 8009230720* 8009230720*	50-304 50-10 50-10 50-10 50-10	S R R R		8009290384* 8009290368* 8009290362* 8009290367*	50-213 50-213 50-213 50-213 50-213	9 9 9
	8007240555 8007240555 8007240555 8007250272 8007250272	50-10 50-10 50-10 50-10 50-10	P P P ያ		8007270372* 8007270372* 8007270377* 8007270377* 8007270381*	50-213 50-213 50-213 50-213 50-213	P P P P
	8007250344# 8007250468 8007250468 8007250468 8007250468	50-295 50-373 50-373 50-373 50-373	Q Q Q		8009290381* 8009290384* 8009290384* 8009290387*	50-213 50-213 50-213 50-213 50-213	P P P
	8007250468 8007250468 8007250504 8007250504 8007250504	50-373 50-373 50-237 50-237 50-237	a a a	Connecticut, Btate of Conner, Moore & Corber	8009190103 8009260478 8009030272 8009230027 8009300016	PR 50-213 50-358 50-375 50-358	P 0 0
	8009260109 8009260109 8009260109 8009260109 8009260109	50-10 50-10 50-10 50-10 50-10	a a a a	Canoco Cost Development Co Cansolidated Edison Co of New York	8009300119* 8009150158 8009030382 8009030382	FOIA 40-8743 50-3 50-3	R R

AUTHOR AFFILIATION	ACCESSION NUMBER	SUDJEC CATEGO			AUTHOR AFFILIATION	ACCEBBION NUMBER	SUBJEC	
	8007030382 8007030384* 8007030386* 8007030386* 8007030458	50-3 50-3 50-3 50-3 50-247	R R R R			8009120462* 8009120533 8009150344* 8009160370 8009160642	50-255 REQQD 50-155 50-255 50-413	R Q R Q
	8009030559 8009030610 8009030610 8009030616 8009030618#	50-247 50-3 50-3 50-247 50-247	բ Տ Տ Ք			8009170065 8009170259 8009170259 8009180102 8009180292	FOIA 50-329 50-329 50-155 50-255	A A D
	8009080329 8009090242 8009090383 8009090383 8009090383	50-247 50-3 50-3 50-3 50-3	9 9 9 9			8009190098 8009190101* 8009190105* 8009190124* 8009190129*	50-155 50-155 50-155 50-155 50-155	8 8 8 8
	8009090423 8009090484 8009090506 8009120187 8009120353	50-3 50-247 50-247 50-3 50-247	0 P 0 S			8009190218 8009190221* 8009190420 8009190661 8009220216*	50-329 50-329 50-329 PRH 50-155	K G G
	8007120381* 8007160365 8007160367* 8007230432 8007230432	50-247 50-247 50-247 50-3 50-3	\$ 8 R R			8009220217* 8009220218* 8009220238 8009220238 8009220285	50-155 50-155 50-329 50-329 50-255	Q Q A A B
	8007230432 8007230433* 8007230433* 8007230433* 8007230451	50-3 50-3 50-3 50-3 50-247	R R R P			8009220289* 8009230110 8009230275 6009230436 8009230440	50-255 50-329 50-329 50-255 50-255	8 9 9
	8009230568 8009230571# 8009240452 8009240452 8009240452	50-247 50-247 50-3 50-3 50-3	R R R R			E009230443 E009230458 E009230512 E009230550 E009230550	50-155 50-255 50-255 50-329 50-329	J P R A
	8009250266 8009250266 8009300384 8009300481 8009300524	50-3 50-3 50-247 50-247 50-247	8 6 6			8009230559* 8009230559* 8009230562* 8009230612 8009230618*	50-329 50-329 50-329 50-255 50-255	Å Å 8
Consumers Power Co	8009300530* 8008080297 8008190605 8009020070 8009020077*	50-247 50-329 50-329 50-155 50-155	5 5 5 8 8			6007250268 6007250268 6007250278 8007250277* 6007250284	50-329 50-329 50-155 50-155 50-329	8 8 P 8
	8007020262 8007020266 8007020271* 8007020343* 8007030117*	50-255 50-155 50-155 50-155 50-255	0 8 8 0			6007250284 8007260002* 8007260127 8007260146 8007260266	50-329 50-329 50-155 50-155 50-369	6 0 0
	8009030430 8009030490 8009030544 8009030547* 8009030583	50-255 50-155 50-155 50-155 50-255	P R R S			8009260266 8009260273 8009260273 8009260488 8009260492*	50-369 50-369 50-369 50-255 50-255	0 0 8
	8007030594* 8007030624 8007030627* 8007030718 8007040275	50-255 50-255 50-255 50-327 50-329	S Q Q R			8009260496# 8009290360 8009290360 8009290364 8009290368	50-255 50-329 50-329 50-255 50-329	8 8 P A
	8007040423 8007040423 8007080406 8007080414* 8007080419	50-155 50-155 50-255 50-255 50-255	F 8 8 9			6009290348 8009290475# 8009300023 6009300023 8009300231	50-329 50-329 50-329 50-329 50-155	A Q Q P
	8009080426* 8009080432 8009080437* 8009090397 8009090458	50-255 50-255 50-255 50-327 50-155	8 8 8 8			8007300484 8007300487* 8007300472 8007300479* 8007300507	50-255 50-255 50-255 50-255 50-329	8 8 8 8
	8007070474# 8007070300 8007070500 8007070511# 8007070511#	50-155 50-329 50-329 50-329 50-329	8 A A A	i	Contra Costa Industrial X-Ray Co Control Data Corp Cooper Industrias, Inc., Cooper — Bessemer Co Div. Cooper Industries, Inc., Cooper Energy	8007300507 8007070073 8007020185 8007270378*	50-329 71-9033 FOIA 50-382 50-382	8 8
	8007070548 8007100521 8007100573 8007100574 8007110428	50-255 50-155 50-155 50-155 50-255	G P P F	Bervice	Services Div Cornell Univ	8007020355 8007230643 8007230647# 8007230652#	NUREO 50-157 50-157 50-157	P P P
	8009110730* 8009110820* 8009120384 8009120388* 8009120457	50-255 50-155 50-255 50-255 50-255	Q Q S B R		Cotter Corp	8007230657# 8007230668# 8007230668# 8007150557	50-157 50-157 50-157 40-8692	Р Р Р

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	
Coulse Region Energy Coalition	8007230001 8007230002* 8007230004* 8007260672 8007260677*	50-409 50-409 50-409 50-409 50-409	0 0 0		E007020044 B007020044 B007020047# B007020047# B007020047*	50-269 50-269 50-269 50-269 50-269	R R R R
Council on Environmental Guality Covington & Burling Crease, Inc	8009070798* 8009240350* 8009170142 8009300474 8009160198	50-347 50-275 50-389 50-250 NUREO	о н н		8007020137 8007020211 8007020371 8007020371 8007030183	50-488 50-389 50-389 50-389	0 A A Q
Conterland County, PA Date County, F1 Datealson Associates, Inc Dairyland Power Cooperative	8007070380 8007270180 8007240271 8007020041 8007030237	50-320 50-250 RES 50-407 50-407	H O C P		8007030445 8007030447* 8007030468 8007030474* 8007030507	50-269 50-269 50-270 50-270 50-287	8 8 8 P
	8007030243* 8007030454 8007030457* 8007070008 8007070010	50~409 50~409 50~409 50~409 50~409	P 8 0 0		8007030513* 8007030605 8007030605 8007030605 8007040383	50-267 50-269 50-269 50-269 50-369	P Q Q Q 8
	8007070336 8007070527 8007160250 8007160253* 8007220145	50-409 50-409 50-409 50-409 50-409	Q P R R P		8007040383 8007040640 8007050086 8007050087# 8007050545	50-369 50-269 50-369 50-369 50-369	9
	6007230648 8007230657* 8007230664* 8007240343 8007240350*	50~409 50~409 50~409 50~409 50~409	9 5 9 P		8007080312 8007080312 8007070577 8007070577 8007070577	50-413 50-413 50-249 50-249 50-249	8 9 R R
Dames & Hoore	8007260157 8007260630 8007260636* 8007300008 8007020077*	50-409 50-409 50-409 50-409 50-483	Q S S O A		8007070582* 8007070582* 8007070582* 8007100487 8007100487	50-269 50-269 50-269 50-269 50-269	R R R P
Cirtesuth College Outs Consultants, Inc Dawn Hining Co	8007120603 8007270171* 8007260680* 8007180130* 8007270477	40-B084 50-170 CONTRACT CONTRACT WASTE MO	Т Т		8007100497 8007100807* 8007100807* 8007100807* 8007110275	50-269 50-269 50-269 50-269 70-2623	g G
Diberoise & Liberman	8007270501* 8007030086 8007110048 8007110781 8007170141	WABTE MG 50-369 50-445 50-445 50-445	9T G G G		6007110345 8007110345 8007110423 8007110459 8007110858	50-369 50-369 50-413 50-269 50-269	A G G
	8007170141 8007170347* 8007230005 8007260010 8007260266	50-445 50-445 50-445 50-369 50-369	0 M Q 0 0		8007110458 8007120212 8007120262 8007120414 8007120418	50-269 50-488 50-370 50-269 50-270	0 0 0
	8009260266 8009260273 8009260273 8009290028 8009300009	50-369 50-369 50-369 50-488 50-395	0 0 0 0 0 0		8007120431* 6007120436* 6007120576 6007120587 6007120587	50-270 50-269 50-489 50-413 50-413	8 8 0
Defense, Dept. of. Defense Intelligence Agency Defense, Dept of. Defense Nuclear Agency	8007270168 8007030450 8007030452* 8007170175 8007170177*	50-170 50-170 50-170 50-170 50-170	ғ Р Р V		8007120578 8007120578 8007150367* 8007150383 8007150437	50-349 50-349 50-370 50-287 50-349	0 0 8 8
Del Kar Technical Associates Celavare, Etate of Cetroit Edison Go	8009290359 8009160231* 8009100446 8009030602	50-170 50-206 PR 50-341 50-341	P P A		8007150437 8007150548 8007160261 8007160477 8007160480*	50-349 50-349 50-249 50-249	44488
	8007090417 8007160417 8007180016 8007180029 8007240307#	50-341 50-341 50-341 50-341 50-341	Q B Q Q		8009160540* 8009160541* 8009160541* 8009160600 8009160603	50-269 50-269 50-269 50-369	Q Q A Q
Det - Gearch Astociates Doggett, S. A.	8009240509# 8009240513# 8009250446 8009110339 8009160527	50-341 50-341 50-341 FOIA 50-466	A A Q		8009170233 8009170371 8009180322 8009180322 8009180327*	50-269 50-413 50-369 50-369 50-369	Q A A A
Dougherty, J B Dow Chamical Co Bravo Corp Dolm Power Co	8007230013 8007220139 8007160486 8007020025 8007020027	50-280 TOPREP WABTE KG 50-269 50-369	0 P F		8009180327* 8009180376 8009180395 8009180395 8009190399	50-349 50-369 50-287 50-287 50- 369	AABBA
	8007020029 8007020033+ 8007020033+ 8007020044	50-367 50-367 50-367 50-267	F F R		6009190399 6009190399 8009190424 8009190424 6009190424	50-369 50-369 50-269 50-269 50-269	44777

AUTHOR AFFILIATION	ACCESSION NUMBER	EUDJEC CATEGO	DRY	AUTHOR AFFILIATION	ACCESSION NUMBER	EUBJECT	
	8009190462 8009190462 8009190462 8009190473#	50-269 50-269 50-269 50-269 50-269			8009240450 8009240456* 8009240458* 8009240461* 8009250251	50-334 50-334 50-334 50-334 50-334	8 8 8
	8009190473# 8009190506 8009190506 8009230496 8009230504#	50-269 50-369 50-369 50-270 50-270	R A A S S		8007270251 8007270257* 8007300357 8007300370 8007300412	50-334 50-334 50-334 NUREO 50-334	8 P 8
	8009230509 8009230517* 8009230724 8009240206* 8009240212*	50-270 50-270 50-269 50-369 50-369	s s p o q	E I du Pant de Namours & Go : Inc EDS Nuclear: Inc EG&O Idaho: Inc	8007120540 8007090088 8007030010 8007050377 8007050405	regod Reb Reb Reb Reb	Q
	8009240220* 8009240262* 8009240290* 8009240290* 8009240297*	50-369 50-370 50-413 50-413 50-413	G G G G	,	8009100412 8009100520 8009100530 8009120579 8009120639	RE8 RE8 RE8 50-243 50-315	p P
	8009240297* 8009240298* 8009240409 8009240448 8009240448	50-413 50-413 50-369 50-369 50-369	q q A V V		8007120666 8007180307 8007170768 8007240067 8007260075	RE8 -00-034 RE8 RE8 RE8	ρ
	6009240481 8009240489 8009240487 8009250191 8009250339	50-369 50-369 50-369 50-369 50-413	S A Q Q		8007240084 8007240077 8007240110 8007240520 8007240542	50-316 REB 50-263 50-315 REB	p P
	8009260010 8009260010 8009260450 8009260455* 8009290028	50-369 50-369 50-287 50-287 50-488	o o a a a o	EO&O, inc Earth Sciences Associates Eaton Corp Cutler-Hammer Products Div	8009260558 8009260568 8009020366 8009040256* 8009260018	RES 50-315 50-312 50-70 50-440	Р Р 9
	8007270303 8007270371 8007270371 8007300157 8007300428	50-369 50-369 50-369 50-369 50-269	A A G J	Eberline Instrument Corp Eckert, Bezmans, Cherin & Mellott Edison Electric Institute	8009190123* 8009110028 8009050434 8009220219 8009230644	40-2061 XPORTLIC PR NUREO PR	
	8007300428 8007300428 8007300434 8007300486 8007300486	50-269 50-269 50-369 50-269 50-269	J A P P	Edlow International Co	8009090459 8009190245 8009230799 8009290157 8009300668	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	
	8007300486 8007300543 8007300547 8007300626* 8007300426*	50-269 50-334 50-311 50-269 50-269	G S S P	Eichhorn,Eichhorn & Link	8009040281 8009080509 8009080511 8009110808 8009190039	50-367 50-367 50-367 50-367 50-367	0 0 0
Duquesne Light Co	8007300626* 8007030370 8007030375* 8007030250 8007050254*	50-269 50-334 50-334 50-334 50-334	Q A R S S	Electric Power Research Institute	8009230035 8009300025 8009300576 8009110256# 8009110433#	50-367 50-367 50-367 CONTRACT 50-338	0 0 0
	8007080307 8007070116 8007070248 8007070374 8007070405	50-334 50-334 50-412 50-334 50-334	G G S G P	Elfreth Alley Apothacary Energy Fuels Nuclear, Inc	8006240527 8009100666 8009170127 8009300237 8009300409	Docket 340-8681 40-8681 40-8681 40-8681	D
•	8009090412# 8009100389# 8009100409 8009120377 8009120386#	50-334 50-334 50-334 50-334 50-334	P O P S S	Energy Incorporated Energy, Dept of	8007240467 8007300236* 8007050705 8007050207* 8007050412*	NUREQ 50-155 71-9508 71-9508 FOIA	P
	8009150393 8009140309 8009140311* 8009140313* 8009140405	50-334 50-334 50-334 50-334 50-334	8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	•	8009070549 8009100074* 8009100590 8009150241* 8009190529	50-537 50-289 PR 50-320 PR	H H
	8007160411* 8007160444 8007160451* 8007160470 8007160472*	50-334 50-334 50-334 50-334 50-334	5 5 5 6 8		8009190762 8009220046 8009240563 8009300306* 8009300306*	WASTE MO WASTE MO PR 50-275 50-275	
	8009180188 8009180194* 8009190446 8009190500 8009230263	50-334 50-334 50-334 50-334 50-334	R R S P	Energy, Dept of, Clinch River Breeder Reactor Plant Engineering Decision Analysis Company,	8007020002 8007020003* 8007020014 8007070575 8007180477*	50-537 50-537 50-537 50-537 50-70	B A B P
	8007230267* 8007230454 8007230573 8007230601 8007230711	50-334 50-334 50-334 50-334 50-334	P P P P	Environmental Coalition on Nuclear Power	8007120348 8007120374* 8007120377*	PR PR PR	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	_	AVTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
Environmental Defense Fund Environmental Protection Agency	8009260666 8009300010 8009240070* 8009170144 8009190775*		0		8009140378 8009140378 8009140378 8009140439 8009170279	50-250 50-250 50-250 50-250 50-250	P P Q R
Eurapean Communities, Commission of	8009300218 8009110359 8009110364 8009110580 8009190258	40-2061 XPORTLIC XPORTLIC XPORTLIC XPORTLIC			E009170279 E009170279 E009170281* E009170281* E009170281*	50-250 50-250 50-250 50-250 50-250	R R R R
Essan Carp Essan Nuclear Co . Inc (subs of Exxon Carp)	8009260184 8009040473 8009040475* 8009040490	71-9022 70-1257 70-1257 50-335	.		8009170374 8009180444 8009190137 8009190206 8009190206	50-335 50-335 50-335 50-250 50-250	0 P P
	8009110278 8009110718 8009160523 8009180099* 8009240105 8009240117*	70-1257 70-1257 70-1257 94999 71-6581 71-4581			8009190209* 8009190209* 8009230304 8009240174 8009240412	50-250 50-250 50-335 50-387 50-250	P P Q Q
	6009260477 6009260462* 6009260467* 8009260493* 8009260498*	TOPREP TOPREP TOPREP TOPREP TOPREP			8007250207 8007270343 8007270343 8007300040 8007300127	50-250 50-250 50-250 50-367 50-250	9 6 9 9
Fideral American Partners	8009260504# 8009100654 8009100657# 8009110266 8009170234	TOPREP 40-4492 40-4492 40-4492 40-4492			8009300129 8009300152 8009300177 8009300177 8009300372	50-250 50-335 50-250 50-250 50-335	0 P O
Federal Emergency Management Agency Flatman.C A Flatschater, D 8	8007080397 8007160388 8007150075* 8007160234 8007220262	State Pro 50-375 (50-250 (50-275 (50-275 (; ;		8009300474 8009300482 8009300485* 8009300490 8009300494*	50-250 50-335 50-335 50-250 50-250	# 8 8 8
Florida Cities	8007240544 8007170162 8007170071 8007170071 8007220222*	50-275 (50-389) 50-335) 50-335) 50-389)) 1 1	Florida Power Corp	8009020197 8009030200 8009030206* 8009030230 8009030475	50-302 50-302 50-302 50-302 50-302	8 R R F S
Florids Power & Light Co	8007220223* 8007270624 8007270625* 8007020077* 8007020192	50-387 F 50-335 F 50-335 F 50-250 G 50-335 G	! -		8009030482* 8009030497 8009030503* 8009030600 8009030609*	50-302 50-302 50-302 50-302 50-302	5 6 8
	8007020175 8007020175 8007020304 8007020345	50-250 (50-250 (50-335 (50-335 (8007050265 8007050268* 8007070278 8007070442 8007100733	50-302 50-302 50-302 50-302 50-302	9 P 0
	8007020372* 8007030236 8007030300 8007030300 8007030633	50-250 £ 50-250 £ 50-250 £ 50-389 £			8007110337 8007110342* 8007150280 8007150282* 8007160637	50-302 50-302 50-302 50-302 50-250	6 8 9 0
	8007070257 0720707008 40070707008 *400707008	50-250 F 50-250 F 50-250 F 50-250 F			8009170288 8009170289# 8009180285 8009190786 8009220361	50-302 50-302 50-302 50-302 50-302	р Р О В
	8007070311* 8007100585 8007110166* 8007110673 8007110853	50-250 F 50-250 G 50-250 G 50-250 G) 		8007220353# 8007240184* 8007240628# 8007270270 8007270306*	50-302 50-302 50-302 50-302 50-302	8 8 8
	8009110853 8009120307 8009120312 8009120313 8009120315*	50-250 0 50-335 6 50-335 6 50-251 6		Florida Rural Legal Bervices, Inc Florida, Univ of, Gainesville Fluor Power Bervice, Inc	8007300143 8007300624 8007160387 8007170211* 8007300378	50-302 FOIA 50-83 MISC NUREO	Q P
	8009120316* 8009120318* 8009120350 8009120385* 8009120491*	50-335 8 50-335 5 50-250 8 50-250 8 50-250 0	:	Fox Industries Fox, Farr & Cunningham Frankhauser,D B Franklin Institute/Franklin Research Canter	8009300394 8009040278 8009030693 8009020148*	TOPREP 50-289 50-358 50-331	0 0 P
	8009120520#	50-250 0 50-250 0			8007020463* 8007020467*	50-10 50-10	P P
	8009120471 8009150251 8009150242 8009150288	50-250 0 50-335 P 50-389 A 50-335 S			8009020470# 8009020473# 8009020474# 8009040103*	50-10 50-10 50-15	P P P
	8007150270 # 8007160033 8007160041# 8007160200	50-335 8 50-389 M 50-389 M 50-335 F			8007040127* B007040315* B007040544* B007050456*	50-263 50-324 50-271 50-293	P P P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCEBSION NUMBER	BUBJEC CATEGO	RY
	8009050501* 8009150426* 8009170260*	50-29 50-317 50-333	P P	General Public Utilities - GPU Bervice Corp	8007230472 8007070608*	TOPREP 50-289	1
Friends of the Earth	8009170402* 8009180219* 8009100406	50-220 50-336 50-361	P P	,	8007110328 8007110330* 8007160357	50-320 50-320 50-320	P P
Gary. IN	8007110397* 8007030147 8007030152* 8007090427*	50-361 50-367 50-367 50-367	0000		8007160361* 8007170265 8007180370 8007240541 8007300550	50-320 50-320 50-287 50-320 50-287	P P P R
Casser Associates General Atomic Co (subs of Oulf Oil Co)	8007090433* 8007090435* 8007110222* 8007260242* 8007120677	50-367 50-367 CONTRACT CONTRACT 50-295	Γ	George B Bush & Co George Uhw Co .Inc Georgia Power Co	8007300350 8007070202 8007070213 8007240048 8007020180	50-287 XPORTLI XPORTLI XPORTLI 50-321	R C C
General Atomic Co (subs of Gulf Oil	8009220321# 8009300088	50-267 XPORTL I C	Q :	0201912 F0001 00	8007020180 8007020180 8007020287	50-321 50-321	Q Q
Corp) General Dynamics Corp ,Electric Boat Div General Electric Co	8009170136 8009020023 8009020412*	71-6717 NUREQ 50-296	р		8009020362 8009020367* 8009020369	50-366 50-366 50-366	8
	8009030557 8009030578 8009030639 8009040255 8009050325	TOPREP 70-1309 50-70 50-70 TOPREP	P		8009020374* 8009020393 8009020393 8009020400 8009020404	50-366 50-321 50-321 50-366 50-321	8 9 8
	8007050328* 8007050363 8007050365* 8007050454 8007050457	TOPREP TOPREP TOPREP 70-2786 70-1308			8007020405* 8007020414* 8007020417 8007020433* 8007020436	50-366 50-321 50-366 50-366 50-321	8 8 8 8
	8009090874 8009100032 8009100061* 8009110161* 8009110225	70-1201 XPORTLIC CONTRACT 70-1113 70-754			8007020439 8007020444* 8007020446* 8007020461 8007020469*	50-321 50-321 50-321 50-321 50-321	8 8 8
	8009110227 8009110273 8009110279 8009110436 8009110443*	70-754 XPORTLIC 70-754 TOPREP TOPREP			8007030415 8007030415 8007030419* 8007030419* 8007030442	50-321 50-321 50-321 50-321 50-366	R R R R
	8007110488 8007110763 8007120089 8007160172 8007160278	70-1308 70-2784 70-754 TOPREP XPORTLIC			8007030447* 8007030451 8007030461* 8007030484 8007030487	50-366 50-366 50-366 50-321 50-424	8 8 F 9
	8009160366 8009160420 8009160424 8009160436* 8009180474	TOPREP 50-201 TOPREP TOPREP 50-70	G P		8009030489 8009040458 8009040458 8009040435 8009040435	50-424 50-424 50-424 50-424 50-424	8 8 0
	8009180509 8009190751 8009230308 8009230431* 8009230475*	70-1007 70-754 TOPREP TOPREP TOPREP			8007040637 8007040637 8007050076 8007050291 8007070428	50-424 50-424 50-321 50-321 50-366	8 6 7
	8009240580 8009240703 8009250245 8009260051 8009260106	70-2786 71-5926 50-70 71-5998 71-5971	P		800707043B* 8007070443 8007070460* 8007070467 800707070480*	50-366 50-321 50-321 50-321 50-321	8 8 8
	8009260391 8009260466 8009260581 8009300227 8009300302*	71-9049 71 - 4400	P P		8007070486 8007070475# 8007100416 8007110671 8007110676	50-366 50-366 50-424 50-321 50-321	8 8 8
	8009300307* 8009300477 8009300483* 8009300585* 8009300586*	50-245 TOPREP TOPREP 70-1308 70-1308	P		8009110676 8009110828# 8009150162 8009150281 8009150283#	50-321 50-321 50-321 50-321 50-321	Q Q S S
General Electric Co., Nuclear Energy Products Div.	8009030505	50-333	P		8009150291 8009150294#	50-321 50-321	8
	8007050414 8007050417* 8007050417* 8007070866	71-9019 71-9019 71-9019 70-1113			8007150275 8007150278* 8007150331	50-321 50-346	8 8
	8009110830 8009150001 8009150601 8009190111	XPORTLIC 71-5980 70-1113 70-1113			8009150335# 8009150382 8009150384 8009150385# 8009150386#	50-364 50-321 50-321 50-321 50-321	8 8
General Electric Operating Plant Owners Group	8009230430	TOPREP			8009160285 8009160306* 8009160448 8009160448	50-366 50-366 50-321 50-321	8 6 F

Sale .

APTER LATION	ACCEBBION R TEHUN	SUBJECT CATEGORY		AUTHOR Affiliation	ACCESSION NUMBER	GUBJECT
	8007180177 8007180208# 8007180235# 8007180478 8007170423	50~321 F 50~321 F 50~366 F 50~366 F		Hake, Inc Haneywell. Inc House of Rep	8009120605 8009030697 8009030698* 8009020217* 8009020323*	XPORTLIC XPORTLIC XPORTLIC COMMISSION 50-320 H
	######################################	50-021 F 50-021 F 50-021 F	9 tr tr tr		8009080346 8009090370 8009110267 8009110418* 8009110491*	50-287 U 50-320 U 70-820 COMMISSION 50-320 U
	91E0E24008 6010E24008 6010E24008 6010E24008	50-424 (50-521 (50-321 (0 0 0 0 8		8009110520* 8009170268 8009170383 8009180560* 8009230442*	50-275 U 50-466 U 50-446 U 50-320 H 50-289 H
	8004240367 8009240367 8009240389 8009240389 8009270278	50-321 (50-424 (50-424 (a a o o	House of Rep , Foreign Affairs House of Rep , Interstate & Foreign Commerce	8009240485 8009260205 8009260652* 8009110288* 8009100108*	50-456 U 50-320 H 50-201 G 50-320 H COMMISSION
	0007290201# 0007300104 0007300104	50-321 (0 0	House of Rep , Merchant Marine & Figheries	8009150182	PŘ
	0007300110 0007300477 0007300502#	50-424 (50-321 (0 6	House of Rep , Science & Technology House of Rep , Ways and Means	8009120494* 8009020156* 8009110319* 8009110322*	COMMISSION 50-320 H 50-320 H 50-320 H
Quorgia, State of	0007300517 0007300526# 0007100077# 0007120075#		8 8 9	Howston Lighting & Power Co	8007020288 8007020270 8007020270	50-498 8 50-498 8 50-498 8 50-498 8
Quatechnical Ingineers, Inc Quity Oil Co . Petrotomics Co Div	000190057# 000000107 0009100049 0009100212# 0009100222#	CUNTRACT 40 - 6657 40 - 6657 40 - 6657 40 - 6657			8007030170+ 8007040271 8007040287 8007040377 8007040377	50-498 Q 50-466 Q 50-445 M 50-498 B 50-498 B
935bs & Hill, Inc. (subs. of Dravo Gorp.	000722030# 0007220344# 0007220340# 0007220340# 0007220348#	50-445 50-445 50-445	^ ^ ^		8007050364 8007050364 8007080201 8007080201 8007110367	50-498 0 50-498 A 50-498 A 50-498 B
	800722035/# 800722035/# 800722036# 800722036# 8007220360#	50-445 50-445 50-445	^ ^ ^		8007110367 8007110384 8007150254* 8007150557 8007150557	50-498 B 50-466 G 50-478 K 50-478 K 50-498 K
	* 08E0525608 * EBE0225608 * EBE0225608 * EBE0225608	50-445 50-445 50-445	A A A		8007150561* 8007150561* 8007160157 8007160157	50-478 K 50-445 M 50-445 M 50-445 M
	8009220387# 8009220387# 8009220392# 8009220392# 8009220393#	80-445 50-445 50-445	A A A		8007140140* 8007140160* 8007140201 8007180461 8007180467 8007180473	50-445 M 50-466 G 50-478 Q 50-478 Q 50-478 Q
Gilbert/Gommonwealth Gos.	0004140343 * 0004190357 * 0004180357 * 0004180350 *	QA797 QA797 QA797	ĸ		8007180475 8007180477 8007180477 8007180477 8007170147	50-456 G 50-478 S 50-478 B 50-478 B 50-478 B
Greater Southeast Community Hosp Washington, D. C.	8009230147# 8009100219#	70-1417 0A999			8009230402	50-498 8 50-498 8
Oulf & Hastern Industries: Inc Oulf Otates Ubilities Co.	0007050522* 0007070407 0007070502	50~45B 50~45B	Q A F		8007230603 8007230603 8007230617 8007230617	50-498 8 50-498 8 50-498 8
Gutman, Peter FRS, Dept. of. US Public Health Service	8009280412 8009290326# 8009300086 8009180143# 8009170130	50~458	Q Q Q		8007230658 8007230658 8007240439 8007250054 8007250054	50-498 8 50-498 8 50-498 8 50-498 K 50-498 K
FWH Associates, Inc Hanford Engineering Development	8008080302*	50-329 REB	F		8009260210# 8009300027	50~466 Q 50~466 Q
Laboratory Haziston Laboratories, Inc	8009090020 8009260284*		R		8007300161 8007300453 8007300467	50-498 B 50-498 B 50-466 Q
Health & Human Hervices, Dept of, Hill Christopher & Philips	9009030258 9009110019		0		8009300536 8009300545 8009300545	50-498 Q 50-498 Q 50-498 Q
Millian Hall and a second	8007180404 8007170627 8007230616	F01A 50-275	о Р	Hunton & Williams	8007300555 8007170174	50-498 Q 50-516 Q
Hithman Nuclear & Development Corp. (446s Hittman Corp.)	8007030478#	•	H	tiydro-Enginearing	8008080193# 8008130378#	40-8659 40-299 40-8502
HjalmfultiD G. Hodder, B. II	8004120042* 8004590985		o o	Hydrology Associates, Inc.	1740019008	ig yan tanihir bir me

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO		AUTHOR AFFILIATION	ACCEBBION NUMBER	SUBJECT	
YTERA Environmental Consultants, Inc RT Corp Ilinois Power Co	8007020347 8007240067# 8007020341 8007040471 8007080173	NUREQ CONTRAC 50-461 50-461	A A A	Illinois, Univ αf, Urbana-Champaign ! !	8007260021 8007120611 8007120614* 8007150456 8007150461*	40-2061 70-258 70-258 50-356 50-356	R
	8007080193 8007080197* 8007080202 8007080202 8007080209*	50-461 50-461 50-461 50-461 50-461	A C C C	Indiana & Michigan Electric Co	8007230777* 8007020232* 8007110310 8007110310	CONTRACT 50-315 50-315 50-315 50-315	T Q R R
,	8007080207* 8007080211* 8007080211* 8007080347 8007070254	50-461 50-461 50-461 50-461 50-461	с с н к		8009110348* 8009150323 8009150328* 8009160195 8009160273	50-315 50-315 50-315 50-315 50-315	8 8 0 R
	8007070254 8007070258# 8007070258# 8007070262 8007070262	50-461 50-461 50-461 50-461 50-461	K K K K	5 6	3009160277* 3009160280 3009160283* 3009170350 3009190817	50-315 50-316 50-316 50-315 50-316	R R R V
	8007070266 8007070266 8007070267 8007070267 8007070272	50-461 50-461 50-461 50-461	x x x		3007170522* 3007240347 3007240074 3007240074 3007240212	50-316 50-315 50-315 50-315 50-315	8 9 9
	8007070272 8007070276 8007070276 8007070277 8007070277	50-461 50-461 50-461 50-461 50-461	K K K	E Indiana & Michigan Power Co	3007270444* 3007300510 3007300517* 3007070501	50-315 50-315 50-315 50-315 50-315	9 8 8
	8007070283 8007070283 8007070284 8007070286 8007070287	50-461 50-461 50-461 50-461 50-461	К К К	Indiana Univ	009190503 009190509* 009250373* 009050492	50-315 50-315 50-315 FOIA GONTRACT	8 8 9
	782070708 782070708 782070708 782070708 782070708	50-461 50-461 50-461 50-461 50-461	Ж К К К	Interior, Dept of	3009040485 3009260468* 3009030314* 3009170139 3009190676*	NUREQ 50-237 50-387 40-8681 FOIA	P A
	8007070277 8007070297 8007070301 8007070301 8007070304	50-461 50-461 50-461 50-461 50-461	К К Ж К	Intermountain Testing Co International Business Services, Inc	3009160363* 3009300646 3009040115 3009300097* 3009120115*	50-275 NUREO PR CONTRACT CONTRACT	
	8007070304 8007070307 8007070307 8007070310 8007070310	50-461 50-461 50-461 50-461 50-461	K K K K	- - 	8009020170 8009020289 8009030466 8009030471* 8009040424	50-331 50-331 50-331 50-331 50-331	0 P B 0
	8007070313 8007070313 8007070317 8007070317 8007070321	50-461 50-461 50-461 50-461 50-461	K K K K	6 8	009090026 009120555 009170061 009170315 009170320*	50-331 50-331 50-331 50-331 50-331	G G B B
	8007070321 8007070323 8007070323 8007070808 8007100830*	50-461 50-461 50-461 50-461 50-461	К К О О	8	009170324 009170328* 1009170333 1009170348 1009170352*	50-331 50-331 50-331 50-331 50-331	8 8 8
	8009100833* 8009110431 8009180575 8009190513 8009220130	50-461 50-461 50-461 50-461 50-461	G G A A	9 9	009170355 1009170360* 1009170363 1009170367* 1009170409	50-331 50-331 50-331 50-331 50-331	8 8 8 9
lingis, State of	8007240457 8007250208# 8007250457 8007270337 8007020048	50-461 50-461 50-461 50-461 50-367	K G G S G	8 8	009170427 009180389 009190499 009190504* 009170533	50-331 50-331 50-331 50-331 50-331	G F R P
	8007020084 8007040200 8007040200 8007040208* 8007040208*	50-367 50-237 50-237 50-237 50-237	0 0 0	8 9 8	009190541* 009230286 009300493 009300501* 009120012*	50-331 50-331 50-331 50-331 CONTRACT	р В В
	8007040218# 8007040218# 8007050358 8007110783 8007150400	50-237 50-237 40-2061 50-367 50-367	0	8 8	007030718 007080256 007070233 007070446 007070471	50-329 FOIA 50-559 50-255 50-275	0 0 0
	8009160247 8009160281 8009160403 8009220173 8009220177	50-367 PR 70-1308 50-367 50-367	G G	9 8 8	009110369 009150339 009150344* 009160397 009170177	50-445 50-155 50-155 50-329 50-445	0 0 0 0 M

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
Island Closeup News Service	8009170349 # 8009220185 8009240002 # 8009300023 8009020505	50-445 50-155 50-329 50-329 FOIA	Н С С С		8009170232* 8009170232* 8009170239* 8009170364* 8009170364*	50-445 50-445 50-445 50-445 50-445	* * * * *
Itsak Walton League of America, Porter County Chapter	8007030703	50-367	O .		8009180460 8009180460	50-445 50-445	H
	8007030710 8007120372 8007120445* 8007230008	50-367 50-367 50-367 50-367	C C O	KMC. Inc	8009180460 8009300021 8009020257	50-445 50-375 TOPREP	M
J E Lonergan Co.	8009230382 8009230393 8009240011 8009180490*	50-347 50-347 50-347 QA997	0 0 0	Kaiser Engineers Kensas Oas & Electric Co	8009190779 8009150014 8009150381# 8009290218 8009300612#	40-4492 50-482 50-482 50-482 50-462	0 0 8 0
J. H. Kleinfelder & Associates	8007180495* 8009230161*	GA999 CONTRACT		Kentucky, State of Kerr-McGee Chemical Corp (qub; of	6009100395 6009040099#	50-358 40-2061	0
Japan Jarsey Cantral Power & Light Co	8007120062 8007170571 8007020087 8007020360	XPORTL10 XPDRTL10 50-289 50-219		Kerr-McGee Corp) Kerr-McGee Corp Kerr-McGee Nuclear Corp	8009150377* 8009150233 8009150375	40-8769 70-925 40-8768	
	8009020379 8009020385* 8009020392 8009020398* 8009020421	50-219 50-219 50-219 50-219 50-289	\$ \$ \$	Laudig, G Law Engineering Testing Co Lawrence Livermore Laboratory	8009180334 8009300456 8009280057 8009120137* 8009110500	71-82 40-8027 50-357 27-48 NULEO	G
	8007020428 8007030372 8007030431 8007030582 8007030340	50-287 50-289 50-289 50-289 50-219	I T T S		8009120338 8009120339 8009160498 8009180434 8009180446	NUREO NUREO RES NUREO NUREO	
	8007080332 8007070031 8007070181* 8007070235 8007070351	50-289 50-219 50-219 50-219 50-219	0 0 0 8	LeBosuf, Lamb, Leiby & MacRae	8009290062 8009040413 8009150371 8009180340 8009240502	NUREQ 50-244 F01A 50-220 50-341	
	8007070353 8007070354 8007070365* 8007070368 8007070371*	50-219 50-219 50-219 50-219 50-219	6 5 8 R	Literature Research Corp Long Island Lighting Co	8009120662* 8009020425 8009030433 8009030437 8009120123*	CONTRACT 50-322 50-322 50-322 50-322	, E
	8009090373* 8009090381* 8009110394 8009110405 8009120179	50-219 50-219 50-289 50-289 50-219	9 9 0 1	Los Alamos Eclentífic Laboratory	8009120254 8009120395 8009170194 8009020141 8009050214*	50-222 50-322 50-516 NUREO 71-9508	Q A Q
	8009150252 8009160371 8009160471 8009160474* 8009160510	50-289 50-289 50-219 50-219 50-219	T Q B S Q		8007050453 8007100036 8007110503 8007120572 8007120589*	71-9853 NUREC NUREC RES 50-320	P
	8007170272 8007170421 8007220283 8007230104 8007230434	50-289 50-219 50-219 50-219 50-289	ያ የ ዕ		8007150576 8007150597 8007160472 8007220220 8007300167	NUREO NUREO RES 50-275 50-3	F
	8009230445 8009230449 8009230481 8009230561 8009230564*	50-289 50-289 50-219 50-219 50-219	T G E R R	Louisiana Power & Light Co	8009170368 8009190153 8009190158 8009190491 8009230437	50-282 50-382 50-382 50-382 50-382	a a H ♠
	8009250270 8009260175 8009260440 8009260447* 8009290357	50-287 50-289 50-219 50-219 50-287	T 0 8 8 1		8007270374 8007270376* 8007300072 8007300100 8007300212	50-362 50-362 50-362 50-362 50-362	8 0 0
	8007270365 8009270369* 8009300261 8009300270 8009300404	50-219 50-219 50-219 50-219 50-219	P P P P	Louisiana, State of Lovelace Biomed & Environmental Research Institute	8007300338 8007300342 8007070537* 8007100053	50-362 50-362 50-458 NUREO	8 8
	B009300522 B009200528* B009300541 B009300544 B009300569*	50-219 50-219 50-219 50-219 50-219	8 8 8 8	Lowenstein, Newman, Reis, Azelrad & Toll	8009020073 8009040271 8009040281 8009050434 8009080509 8009080511	50-250 50-466 50-367 PR 50-367 50-367	0 90.00
John A Blume & Associates, Engineers (subs. URS Corp) John F Halman & Co , Inc Justice, Dapt of	8007020100* 8007120083* 8007040287 8007100261 8007160033	50-206 CONTRACT 50-445 50-445 50-387	P M M		8009090791 8009090795* 8009090826 8009110808 8009150253	50-367 60-367 PR 50-367 30-466	0 0
	8007160041* 8007160160* 8007160160*	50-387 50-445 50-445	M M M		8007150256* 8007150463 8007160033	50-466 50-367 50-389	Q H

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR AFFILIATION	ACCEBBION NUMBER	SUBJECT CATEOOR	
	8007160041 # 8007160148 8007160151 * 8007160201 8007170167	50-389 50-374 50-374 50-464 50-582	 0 0 0	Merrimack College Metropolitan Edison Co	8009240051* 8009020008 8009020013 8009020037 8009020075	70-710 50-289 50-289 50-320 50-320	9 9
	8009180259 8009180475 8009190039 8009230035 8009230691	50-367 50-466 50-367 50-367 50-466	0 0 0		8007020241 8007020273 8007020379 8007020387* 8007030118	50-320 50-289 50-320 50-320 50-320	888
	8009240565 8009260207 8009260210* 8009300027 8009300439	50~466 50~466 50~466 50~466 50~376	0 0 0		8009030349 8009030361* 8009030372 8009030464 8009030464	50-320 50-320 50-320 50-289 50-289	C C 0 8 B
	8009300462 8009300469 8009300476 8009300476 8009300576	50-376 50-466 50-250 50-250 50-367	6 6 11 0		8007030469* 8007030472 8007030473 8007030481 8007030487*	50-289 50-289 50-320 50-289 50-289	6 6 6
Luco,J E MHB Technical Associates Sadison Gas & Electric Co	8009090779 8009150424* 8009160284* 8009240546* 8009090358*	50-275 50-206 PR 50-275 50-305	T P G P		8007030527 8007040365 8007050245* 8007050246* 8007050247*	50-320 50-289 50-320 50-320 50-320	P 0 8 8 8
ine Yankes Atomic Power Co	8007080528 8007080541 8007070431 8007070468 8007070477*	50-309 50-309 50-309 50-309 50-309	G G Q R R		8009050249* 8009050374* 8009080240 8009080240 8009080349	50-320 50-320 50-287 50-287 50-289	8 P V P
	8009100425 8009120207 8009120275 8009160257 8009160259#	50-307 50-307 50-309 50-309 50-309	P G G R R		8007070502 8007070556 8007100431 8007110020 8007110316	50-320 50-320 50-287 50-287 50-289	H
	8009170343 8009170347* 8009230455 8009230584 8009230591*	50-309 50-309 50-309 50-309 50-309	P P R P P		8009110316 8009110318* 8009110333* 8009110340* 8009110344*	50-287 50-287 50-287 50-287 50-289	R R R
	8009260494 8009260503* 8009260637 8009260642* 8009300426	50-309 50-309 50-309 50-309 50-309	5 5 9 9 R		8009120341 8009120342* 8009120402 800912040&* 8009120450	50-289 50-289 50-320 50-320 50-320	8 8 8
Hainer State of Hapleton Intervenors Harrack D. Harsh & McCennan, Inc., M & M Nuclear	8007300430* 8007170345 8007050423 8007180418 8007020278	50-309 50-309 50-329 50-466 50-348	R F O J		8009120452* 8009120454 8009150432 8009150554 8009140329	50-320 50-320	8 P P P
Consultants, Inc Div	8009030374 8009090384 8009280460 8009090863	50-327 50-280 50-311 XPORTLIC			8009160367 8009160381 8009160382 8009160384 8009160395	50-320 50-320 50-320	P P P P
Corp) Massachusetts Institute of Technology	8009030565 8009030569* 8009080198 8009120514*	50-20 50-20 50-20 50-206	R R F		8009140594 8009170219 8009170291 8009170302 8009170314		H Q Q Q P
Massachusetts, State of Massachusetts, Univ of	8009230359* 8009300244* 8009300434 8009100421 8009100651*	CONTRACT CONTRACT NUREO 50-471 70-312	o o		8009170334 8009170377 8009180404 8009180408* 8009180415	50-320	8 8 8 6
Matheson Gas Products Mayer: Brown & Platt	8009110600 8009300670 8009090461 8009100325	XPORTLIC XPORTLIC 70-1308 70-1308			8009180426* 8009190490 8009220129 8009220288 8009220291*	50-320 50-320 50-320 50-287 50-287	8 P R
McDermott, Will & Emery	8007160374 8007300580 8007170188	70-1308 70-1308 50-445	M		6009220276 6009220277	50-320	P
HcGean Chemical Co., Inc McGinnis, Lochridge & Kilgora	8009300533 8009300542# 8009300112 8009170188 8009300533	50-498 50-498 40-8724 50-445 50-498	н н		8009240538* 8009250017 8009260301 8009260313	50-287 50-287 50-287	000
Hadinaelectric Cooperative, Inc.	8009300542* 8009170188 8009300533	50-498 50-445 50-498	н н н		8007260313 8007260320* 8007260388*	50-287 50-287 50-287	TTTTT
Memorial Bloam-Kettering Cancer Center New York, NY	8009300542# 8009110025#	50-49B CONTRACT	Н		B009260394# B009260396#	50-287 50-289	Ţ
Hemphis State Univ Mentor, KY	8009230771* 8009050333	CONTRACT 50-958			8009260400* 8009260407* 8009260411*		T T

AUTHOR AFFILIATION	ACCESSION NUMBER	EUBJE		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATECO	
	8009260412* 8009260414* 8009260417* 8009260421* 8009260431*	50-289 50-289 50-289 50-289 50-289	, T		8007160591 8007160591 8007230072 8007230072 8007230456	50-416 50-416 50-416 50-416 50-416	8 0 0 A
	8009260439* 8009260443* 8009300014 8009300020 8009300022	50-287 50-287 50-320 50-287 50-287	0		8009230471 8009230471 8009230556 8009230595 8009230595	50-416 50-416 50-416 50-416 50-416	955
Michigan Technological Univ Michigan, Otato of Michigan, Univ of	8007300387 8007300304 8007120033* 8007110350* 8007150225	50-320 50-289 CONTRA CONTRA REGOD	CT 8		8009230627 8009230627 8009230642* 8009240331* 8009240438	50-416 50-416 50-416 50-416 50-416	5 6 6 6 6
Mid-America Legal Foundation Miller Balls & O'Ne()	8009160446 8009220242+ 8009220395 8009090331 8009040196	NUREO 50-329 TOPREP 27-39 50-445	A M		8007240438 8007240480 8007240480 8007250417 8007250417	50-416 50-416 50-416 50-416 50-416	8 8 8 8
	8007300035 8007300035 8007300035 8007300488 6007300488	50-445 50-445 50-445 50-445 50-445	н н н	Mississippi, State of	8009260473 8009260473 8009300029* 8009300437 8009100003*	50-416 50-416 50-416 50-416 CUNTRACT	8 9 0 A
	8007300488 8007300488 8007300476* 8007300476* 8007300476*	50-445 50-445 50-445 50-445 50-445	м м м	Missouri, Univ. of: Columbia	8009030212 8009040406 8009040418 8009040419* 8009190594	50-184 50-186 50-186 50-184 71-5088	R 8 9
Hinerals Exploration Co (subs of Union Oil Co. of California)		50-445 40-8584		Missouri, Univ of Rolla	8007230585 8007070377 8007070403*	50-186 50-123 50-123	P P P
Minnesota Power & Light Co Minnesota, State of	8009040489 8009030726 8009030726	50-416 50-282 50-282	G G	Mitsubishi International Corp (subs of Mitsubishi Corp)	8007110602 8007270257	XPORTLIC XPORTLIC	
Mississippi Power & Light Co	8009030728* 8009030728* 8009300039 8006270284 8009020064	50-282 50-282 50-282 50-416 50-416	9 9 8	Mobile Bystems Monsanto Co Morgan, Lewis & Bockius	8009300121 * 8009300062 8009300064 * 8009020041 8009090336	CONTRACT XPORTLIC XPORTLIC 50-409 50-409	:
	8007020064 8007020218 8007020272	50-416 50-416 50-416	8 0 0	Mudge, Rose, Quthrie & Alexander Municipal Electric Utility Association, Alabama	8007050451 8007260662	70-1309 50-349	1
	8009020413 8009020413	50-416 50-416	A	Murray & Trettel, inc Murray & Trettel, inc Myer, Bowman, Stroup & Flack N M Newmark Consulting Engineering	8009030440* 8009300375 8009160495*	50-295 50-424 CONTRACT	Į,
	8007020418* 8007020418* 8007020423* 8007030504 8007030504	50-416 50-416 50-416 50-416 50-416	AAAH	Bervices NL Industries, Inc NUS Gorp Netional Asronautics & Space Admin	8007120220* 8007170332 8007170313 8007020431 8007300185*	40-2940 50-352 FOIA 50-30 40-8092	F W
	8007050352 8007050352 8007050354# 8007050354#	50-416 50-416 50-416 50-416	A A A	National Nuclear Corp National Security Agency National Hildlife Federation	8007070614 8007070617* 8007180327* 8007170376* 8007300004	XPORTLIC XPORTLIC CONTRACT 40-279 50-367	
	8007080247 8007080328 8007080328 8007080376	50-416 50-416 50-416 50-416	8 9	Natural Resources Defense Council Navy-Dept of	8009040258 8009050179 8009160044 8009300004 80093000445#	70-143 70-143 PR 50-367 71-4888	G
	8007100303 8007100303 800710035 800710037	50-416 50-416 50-416 50-416	999	Navy,Dept of, Forces Afloat Navy,Dept of, Naval Facilities Engineers	8009020522 8009020525# 8009080442	71-385 71-385 71-4860	
	8007100347 8007100436 8007100436	50-416 50-416 50-416	8 S	ng Command	8007150199 8007150187#	71-112 71-112	
	8009100486 8009100519 8009100558 8009100558	50-416 50-416 50-416 50-416	8 8	Nebraske Public Power District	8009190707 8009020098 8009020101 8009020102 8009030551	PR 50-298 50-298 50-298 50-298	0 0 F
	8009100566 8009100592 8009110681 8009110681 8009150301	50-416 50-416 50-416 50-416 50-416	880		8009050187 8009050190* 8009050199 8009050203* 8009050252	50-298 50-298 50-298 50-298 50-298	8 8 8 8 8
	8007150425 8007150425 8007150453	50-416 50-416 50-416	A A		8009050295* 8009050260 8009050264*	50-298 50-298 50-298	6 8 S
	8009150453 8009150489 8009150489 8009160387	50-416 50-416 50-416 50-416	K K B		8007050284 8007050287# 8007050324	50-298 50-298	8 8

AUHUR AFFILIATION	ACCESSION NUMBER	CATEGO	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO	DRY
	8007050331# 8007100031 8007100844# 8007140242 800714024#	50-278 50-278 50-278 50-278 50-278	S O O R R		8009090017 8009090636 8009100109 8009100113 8009110245	50-245 50-245 50-336 50-423 50-245	Q P Q
Nevada, State of	8009170287 8009190478 8009190483* 8009260282 8009190881	50-298 50-298 50-298 50-298 State P	9 9 8 8		8009120197 8009150247 8009180357 8009180445 8009190427	50-245 50-336 50-213 50-336 50-245	0 0 0 0 0 0
New England Coalition on Nuclear Pollution New Jersey, State of New Hexico. State of	8009160046 8009020089* 8009030162 8009050498* 8009190891	PR 50-289 50-219 50-320 State P	T T H		8007170434 8007170456 8007170459* 8007170460 8007170531*	50-245 50-245 50-245 50-336 50-336	P R R S
New York, State Univ of, Buffalo New York, State of	8009040376 8009160338 8009160340* 8009020500 8009040250	50-57 50-57 50-57 8tate P 50-54	P I		8009190537# 8009190543# 8009230749 8009240571 8009300239	50-336 50-336 50-245 50-245 50-245	6 6 6 8 8 8 8 8 8 8 8
	8009050361 8009050429 8009100077* 8009110692* 8009120019*	State P PR CONTRAC 50-201 CONTRAC	rog T	Northwest Utilities	8007300245# 8007300271 8007070642# 8007110482 8007160457	50-245 50-336 50-245 50-336 50-336	P P 0 8
	8007120547* 8007300525 8007300525 8007300525 8007300525	50-201 70-1432 50-201 70-1432 50-564	P Q		8009160461* 8009160464* 8009160469* 80091820330* 8009230345	50-334 50-336 50-334 50-423 50-334	8 8 8 R
New York, State Univ of, (Albany) Nawberry Township THI Steering Committee Newberry Township, York Haven, PA	8009300525 8009020481* 8009180436 8009180571 8009040278	50-564 70-2313 50-289 50-289 50-269	0		8009230347* 8009280649 8009280654* 8009290351 8009300179	50-336 50-336 50-336 50-213 50-336	R 8 8 P P
Niagara Mohawk Power Corp	8007020248 8007070264 8007070281 8007070668 8007070848*	50-410 50-220 50-220 50-220 50-410	A Q Q Q S		8009300183# 8009300239 8009300297 8009300311# 8009300403	50-336 50-245 50-245 50-245 50-423	P P P A
	8009120263 8009120408 8009120413* 8009120417* 8009150265	50-220 50-220 50-220 50-220 50-220	Q > > > B	Northern Indiana Public Service Co	8009300443 8009020005 8009020051 8009030434 8009040281	NUREQ 50-367 50-367 50-367 50-367	R R R
	8009150266* 8009150297 8009150299* 8009150551 8009160213	50-220 50-220 50-220 50-410 50-220	S R R A		8007080507 8007080511 8007090427 8007070487 8007070775*	50-367 50-367 50-367 50-367 50-367	S R R G
	8009160214* 8009160460 8009160467* 8009160508 8009160513	50-220 50-220 50-220 50-220 50-220	R S G		8007100165 8007110556 8007110567 8007110808 8007150474	50-367 50-367 50-367 50-367 50-367	G G G R
	8007180248 8007180278* 8007180344* 8007180348* 8007220158	50-220 50-220 50-220 50-220 50-220	5 6 P Q		8009190039 8009230035 8009230259 8009250297 8009300419	50-367 50-367 50-367 50-367 50-367	Q Q R A
	B009230098 B009250331 8007250332* 8009260403 8009300491	50-410 50-220 50-220 50-220 50-220	0 R R P B	Northern States Power Co	8009300421* 8009300446 8009300576 8008200282 8008200282	50-367 50-367 50-367 50-282 50-282	A R O F F
North Carolina State Univ	B009300495* B009300622 B009020352 B009020356* B009180523	50-220 50-220 50-297 50-297 71-4717	S Q R R		8008200284* 8008200284* 8008240337 8008240340* 8009020009	50-262 50-263 50-263 50-263	F F F F
Northcutt Ely Northeast Nuclear Energy Co. (subs of Northeast Utilities)	8009170341 8009020283 8009020283	50-445 50-245 50-245	O R R		8007020055 8007020060* 8007020072 8007020076* 8007030380	50-263 50-263 50-282 50-282 50-263	F F F 9
	8007020285* 8007020285* 8007020284 8007020377 8007020383*	50-336 50-336 50-245 50-245 50-245	8 9 P 8		8007030381 8007030401* 8007030524 8007050348 8007050355*	50-243 50-243 50-243 50-243 50-243	FBFRR
	8007030378 8007030532 8007050103 8007050105* 8007050175	50-213 50-213 50-336 50-336 50-336	P P P		8007080375 8007080401* 800709017 8007070282 8007070287*	50-306 50-306 50-282 50-263 50-263	8 8 0 R

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEOD	RΥ	AUTHOR AFFILIATION	ACCESSION NUMBER	EUBJECT CATEGOR	łY
	B007070297 B009090297 B009090302* B009090302* B009090356	50-282 50-282 50-282 50-282 50-282	R R R R S	Nuclear Packaging, Inc Nuclear Pharmacy, Inc	8009170378 8009170382* 8009050458 7906290556* 7912190023*	50-201 50-201 71-9116 PT9	R
	B009090375 B0090903BB# B009100429 B009100500 B009100500	50-243 50-282 50-282 50-282 50-282	P S C Q		7912190047* 7912190067* 8003030219* 8003050232* 8003250232	PT9 PT9 PT9 PT9 PT9	
	8007100505* 8007100505* 8007110477 8007110534 8007110537	50-282 50-263 50-263 50-263 50-282	a a a a		6003260087 8004110323 8005070553+ 6005300697* 6007270122*	Doctet 30 Doctet 30 PT9 PT9 FOIA	
	8009110539 8009150074 8009150076 8009150218 8009150218	50-282 50-282 50-282 50-282 50-282	Q Q Q Q	Nuclear Technology, Inc. (Nutech) Nucor Corp O'Connor & Hannan	8009290127* 8009290156* 8009020111* 8009260495* 8002190229	FOIA FOIA 50-237 40-8663 PT9	P
	B009160279 B0091602B2* B009170341 B009170341 B009170405	50-282 50-282 50-282 50-282 50-282	R R P P Q	O'Nell, Backue, Spielman Dak Ridge National Laboratory	8009290027 8009290176* 8009020036 8009020359 8009030534*	NUREG	o P
	8009170405 8009170413 8009170441 8009180007 8009180422	50-262 50-263 50-263 50-263 50-202	0 0 0 0 8		8007030671 8007030407 8007100508 8007100744 8007100753	NUREO RES REB NUREO NUREO	
	8009170475 8009170481 8009170481 8009170486 8009230620	50~263 50~262 50~262 50~263 50~263	F P P \$		8007100754 8007110478 8007110574 8007110634 8007110876	NUREQ RES RES RES	
	8009230430* 8009230432 8009230441* 8009230738 8009230741*	50-263 50-263 50-263 50-282 50-282	8 8 9		8009110889 8009120567 8009120561 8009120581 8009120733	RES RES RES RES	
	8007230743 8007230750* 8007250244 8007250411* 8007260626	50-282 50-282 50-282 50-263 50-263	\$ 8 P Q \$		8007150311 8007160202 8007160473 8007240253 8007260536	RES NUREO NUREO RES NUREO	
	8007240440* 8007300037 8007300234 8007300551 8007300551	50-263 50-282 50-263 50-282 50-282	8 0 R S S	Offshore Power Systems (subs of Hestinghouse Electric Corp) Ogle Patroleum, Inc	8009260550 8009100586 8009030385 8009030455 8009030476	RES 50-437 40-8745 40-8493 40-8745	
Northwestern Oklahoma State Univ	8009300558* B009300558* B009300573 B009300573 8009260414*	50-282 50-282 50-282 50-282 70-1167	\$ \$ \$ 6		8007050362 8007150552 8007160330 8007160331* 8007160333*	40-8745 40-8745 40-8745 40-8745 40-8745	
Northwestern Univ Nuclear Engineering Co , Inc , (subs. of Teledyne, Inc)	8007260419* 8009100463* 8009110827 8009090331	70-1167 50-275 40-4826 27-39	Н		8007160334* 8007160336* 8007160345* 8007160348* 8007160350*	40-8745 40-8745 40-8745 40-8745 40-8745	
Nuclear Fuel Services, Inc (subs of Oetty Dil Co)	8009120156* 8009260168 8009090465	27-48 71-6058 70-143 70-143			B009160354 * B009160356 = B009160357 * B0091603B3 B0091603B6	40-874 40-87 40-87 40-8 40-8	
	8007070507* 8007100706* 8007110371 8007110372 8007110373*	70-143 70-143 70-143 70-143 70-143	R		8009160462 8009190389 8009190392 8009220332 8009300202	40-E 40-E 40-B, 40-B7 40-B7	
•	8007110652* 8007120126* 8007120147 8007120421	50-201 50-201 70-143 70-143 70-143 50-201	R R	Ohio Historical Sociaty Ohio State Univ	8009300457 800919025&* 8009300184 8009300192 8009300197*	40-874 50-440 50-243 50-243 50-243	
	8007120404* 8007120404* 8007130027 8007130137* 8007240558	50-201 70-143 50-201 70-143	R U	Ohio, State of Oil.Chemical & Atomic Horters Intl Oklahoma Osteopathic Hosp Tulsa,Ot Oklahoma, Univ of	8009100444 8009190703 8009260405* 8009100577 8009260408*	PR RE00D 70-2560 50-112 40-8160	R
Nuclear Fuel Services, Inc., West Valley Reprocessing Plant	E009240631* E009300475 E009150132*	70-143 70-143 50-201	U	Omaha Public Power District	8009250432 8009020106 8009030479 8009030486*	50-112 50-285 50-285 50-285	R C R R

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE	DRY	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY
	8009090505 8009090519= 8009090525 8009090536= 8009090581	50-285	5 G G P	Pennsylvania State Univ Pennsylvania, State of Pfefferkorn & Cooley, P A	8007170756 8007030601 8007170263* 8007030432 8007030676	90-387 G 50-5 F 50-440 K 50-289 H 50-488 0
	8007150444 8007230347 8007230351# 8007230721 8007300532	50-285 50-265 50-265 50-265 50-285	P R R R	Pharmaco Nuclear, Inc Pharmatopes, Inc	8009250015 7912040156* 8001290281* 8005160029 7906010086*	50-488 0 PT7 PT9 Docket 30 PT9
Oregon, State of Osenn, E. W	8009300539* 8009300566 8009030703 8009030710 800923000B	50-285 50-344 50-367 50-367 50-367	5 G G G G	Philadelphia Electric Co	8001020073* 8001020083* 8003190525* 8009020245 8009020245	PT9 PT9 PT9 50-171 R 50-171 R
Ott Water Engineers, Inc PRC Information Services Corp	8009230382 8009230393 8009260011 8009300595* 8009290423	50-367 50-367 50-367 CONTRAC FOLA	G G Q		E007020245 B007020244* 8007020246* E007020246* B007030635	50-171 R 50-171 R 50-171 R 50-171 R 50-277 B
Pacific Oss & Electric Co	8007020107 8007020263 8007020265* 8007020268* 8007020267*	70~1738 50~275 50~275 50~275 50~275	A A A		8009080340 8007080340 8009080342* 8009080342*	50-277 R 50-277 R 50-277 R 50-277 R 50-277 Q
	8009020270* 8007020272* 8009020274* 8009020275* 8009020277*	50-275 50-275 50-275 50-275 50-275	A A A		8007080533 8007070015 8007070226* 8007100026* 8007100070	50-277 0 50-278 0 50-352 0 50-352 0 50-277 0
	6007030687 6007030467 6007030467 8007050082 8007050321	50-275 50-275 50-275 50-133 50-133	0000		8009100090 8009100121 8009110251 8009110251 8009120165	50-277 q 50-277 q 50-277 q 50-277 q 50-277 q
	8007030324* 8007080333 8007080334* 8007080335* 8007080336*	50-133 50-133 50-133 50-133 50-133	V R R R		8007120330 8007120367 8007150478 8007150502 8007150502	50-276 8 50-276 8 50-277 F 50-277 Q 50-277 Q
	8007070514 8007070514 8007070520* 8007070520* 8007070526*	50-275 50-275 50-275 50-275 50-275	K K K K		8009140294 8009140294 8009140296* 8009140427 8009140427	50-277 R 50-277 R 50-277 R 50-277 R 50-277 R
	8007070544 8007070544 8007110756 8007120347 8007120417*	50-275 50-275 71-9096 50-133 50-133	A A S		8009160431# 8009160431# 8009160435# 8009160435# 8009160439	50-277 R 50-277 R 50-277 R 50-277 R 50-278 8
	8007120447 8007120451* 8007180486 8007180473* 8007230551	50-133 50-133 50-275 50-275 50-133	R R A A R		8007160441 8007180304 8007180304 8007180316# 8007180316#	50-278 8 50-277 P 50-277 P 50-277 P 50-277 P
'actific Legal Foundation Parameter, Inc Pathfinder Mines Corp	8009250288 8009110012 8009040470* 8009030510 8009110402	50-275 PR CONTRACT 40-2259 40-2259			8009180335* 8009180335* 8009180439 8009180439 8009180442*	50-277 P 50-277 P 50-277 R 50-277 R 50-277 R
	8007110404* 8007110407* 8007160347 8007170373 8007260045	40-2259 40-2259 40-2259 40-2259 40-2259			8007180442* 8007170048* 8007170482 8007220376 8007230367	50-277 R 50-352 Q 50-278 S 50-277 Q 50-277 R
Pell, D M Pennsylvania Power & Light Co	8009120224 8009120232 8009030004 8009080364 8009090036	50-287 50-287 NUREO 50-387 50-387	0 0 A 0		8007230547 8007230576* 8007230576* 8007250274 8007260616	50-277 R 50-277 R 50-277 R 50-277 R 50-171 F 50-278 S
	8007070472 8007070616 8007070654# 8007110414# 8007110414#	50-387 50-387 50-387 50-387 50-387	5 6 5 6 6		8009240421 8009270378 8009290378 8009290380# 8009290380#	50-278 B 50-352 B 50-352 B 50-352 B 50-352 B
	8009120142 8009120142 8009120660# 8009130309 8009130470	50-387 50-387 50-387 REGOD 50-387	Q Q A	Pioneer Nuclear, Inc	8009290382* 8009290382* 8009300131 8009300367 8009260085	50-352 B 50-352 B 50-278 Q 50-277 P WABTE MOT
	8009140310 8009170290 8009190250* 8009190271* 8009190956	50-387 50-387 50-387 50-387 50-387	A Q Q Q	Pioneer Uravan, Inc Pittsburgh, Univ of Pittsburgh-Des Hoines Steel Co	8007180321 8007040412 8007120370 8007300276# 8007150177#	WABTE MOT 50-320 P RES CONTRACT GA999

AUTHOR Affiliation	ACCESSION NUMBER	SUBJECT CATEGOR	T NY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
Plateau Resources, Ltd Popular Bluff Mosp Popular Bluff,MD Porter-Gert: Consultants, Inc	8007150204* 8007260027 8007150230 8007300377 8007300377	0A979 40-8498 REGOD 50-289 50-289	R R		8009190936 8009220030 8009220379 8009230451 8009260442	50-286 50-286 50-286 50-247 50-286	44000
Portland General Electric Co	8007300401* 8007300401* 8007020037 8007030575 8007030577*	50-289 50-289 50-344 50-344 50-344	ћ R Р R	President of UB & Executive Offices Public Citizen Litigation Group	8007260446 8007150316+ 8007070627+ 8007070633+ 8007070635+	50-333 50-352 50-367 50-367 50-367	00014
	8007070410 8007100237	50-344 50-344	S 8	Public Interest Law Center of Philadelph	8007300113 8007050370	F01A 50-320	Р
	8009100242* 8009100449 8009100453*	50-344 50-344 50-344	R 5 8	ia Public Service Co of Colorado	8007020221 8007030540 8007030625	50-267 50-267 50-267	О Р Б
	8009100461* 8009100467* 8009100909 8009110011 8009110308	50-344 50-344 50-344 50-344 50-344	8 8 6 0 0		9007030640* 8007100841* 8007160286 8007160288* 8007160270	50-267 50-267 50-267 50-267 50-267	8 8 8 8
	8007150007 8007150057 8007150471 8007150475* 8007160385	50-344 50-344 50-344 50-344 50-344	0 9 8 P		8009160292 8009160314 8009160316* 8009160344 8009160364	50-267 50-267 50-267 50-267 50-267	5 5 5 5
	8007140420 8009170309 8009180379 8009180448 8009190501	50-344 50-344 50-344 50-344 50-344	С 6 6 7		6009170189* 6009220319 6009230597 6009230598 6009230404*	50-267 50-267 50-267 50-267 50-267	9 8
	8009190691 8009220363 8009240375 8009250337 8009250463	NUREO 50-344 50-344 50-344 71-9018	P Q Q		8007230407* 8007230408 8007230414* 8007230487 8007230723	50-267 50-267 50-267 50-267 50-267	8 8 8 8 8
Potomac Alliance	8007240504 8007240510# 8007300314# 8007300471 8007230013	50-344 50-344 50-344 50-344 50-280	8 \$ & B		8009240194 8009260227 8009260233* 8009260369 8009260372*	50-267 50-267 50-267 50-267 50-267	222
Power Authority of the State of New York	8005210647 8007020115 8007020252 8007020354 8007020359#	PR 50-333 50-286 50-333 50-333	G F 8		8009260374# 8009260378 8009260386# 8009300556 8009300563#	50-267 50-267 50-267 50-267 50-267	R R R S
	8007020374 8007020403# 8007020407 8007020422# 8007030405	50-333 50-333 50-333 50-333 50-333	8 6 6 9	Public Service Co of Indiana, Inc	8007020253* 8007030480 8007030480 8007030500 8007040427	50-546 50-546 50-546 50-546 50-546	8 8 8 6
	8007030414* 8007030418 8007030423* 8007040420 8007050273	50-333 50-333 50-333 50-286 50-286	8 8 8 P P		8007040427 8007070574 8007070574 8007070580*	50~546 50~546 50~546 50~546 50~546	8 H H 8
	8009080329 8009080325# 8009080537 8009090014 8009090303	50-286 50-286 50-286 50-333 50-333	R R Q R		8009100469 8009160400 8009160400 8009160419 8009160419	50-546 50-546 50-546 50-546 50-546	9 9 9
	8007070308* 8007070357 8007070351* 8007100117 8007100268	50-333 50-333 50-333 50-333 50-333	R 8 8 0 R		8007180346 8007180521 8007180533 8007240561 8007250447	50~546 50~546 50~546 50~546 50~546	G A B G
	8009100275* 8009110298* 8009120359 8009120362 8009120365*	50-333 50-333 50-333 50-333	R Q 8 P 8		8007250447 8007250482* 8007250482* 8007270208* 8007270208*	50-546 50-546 50-546 50-546 50-546	0 8 0 0
	8009120396 8009120396 8009120410 8009120415* 8009150254	50-284 50-286 50-333 50-333 50-284	1 8 8	Public Service Co of New Hampshire	8009290511 8009290513* 8009300094 8009300452 8009030553	50-546 50-546 50-546 50-646 50-443	A Q H G
	8009160445 8009160449* 8009160458 8009160476* 8009170325	50-333 50-333 50-333 50-333 30-284	8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	Public Bervice Electric & Gas Co. of New Jamsey	8007070417 8007110478 8007170074* 8008280311	50-443 50-443 50-443 50-311	8 0 F
	6007180384 6007170442	50-286 50-286	P R		8009020237 8009030583	50~311 50~311	P 5
	8009190451* 8009190489 8009190496*	50-284 50-333 50-333	R 8 8		8007030591# 8007030513	50-311 50-311	35.

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8007030520* 8007040352 8009040374* 8009040375* 8009040378*	50-3 1 50-3 1 50-3 1 50-3 1 50-3 1	5 F F		8009220280 8009230348 8009230348 8009230478 8009230694*	50-311 50-272 50-272 50-311 50-311	8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8
	8009040379* 8009040379* 8009040381* 8009040381* 8009040384*	50-311 50-311 50-311 50-311 50-311	۴ ۴		8009250260 8009290361 8009300503 8009300512 8009300513	50-272 50-272 50-272 50-272 50-311	P P P
	8007040385* 8007040386* 8007040372* 8007040374* 8007040376*	50-311 50-311 50-311 50-311	۲ ۲ ۲	Purdue Research Foundation	8009160151* 8009160151* 8009240130* 8009260247* 8009120590	50-374 50-374 CONTRACT CONTRACT RES	
	8007040378* 8007040379* 8007040402* 8007040403* 8007040405*	50-311 50-311 50-311 50-311 50-311	1 1 1 1 1	R J Reynolds Tobacco Co RMI Co , RMI Titanium	8009120578 8009150414* 8009300602 8009110214* 8009110492	50-327 CONTRACT 71-6144 XPORTLIC XPORTLIC	2
	8007040407* 8007040408* 8007040410* 8007040411* 8007050270	50~311 50~311 50~311 50~311 50~272	F F F R	Reliance Testing Laboratories.Inc Rensselaer Polytechnic Inst	8009110587* 8009030676 8009160209 8009020012 8009300207	XPORTLIC PR PRM 50-225 71-376	; F
	8007050274* 8007050332 8007080530 8007070230 8007070312	50-272 50-311 50-272 50-272 50-311	R P Q Q	Reuter-Stokes, Inc Rio Algom, Ltd	8007300210# 8007110270 8007110476 8007300520 8007020076#	71-396 XPORTLIC XPORTLIC 40-8084 50-206	
	8007070315 8007070320* 8007070437 8007070441* 8007070447	50-311 50-311 50-311 11E-00	R R S S S		8007020026 8007020086 8007020346 8007020351* 8007030485	50-244 50-244 50-244 50-244 50-244	P V 8 S F
	8009090455* 8009090542 8009090550* 8009090554 8009090558*	50-311 50-311 50-311 50-311 50-311	33 53 53 55 53 55 55 54		8007030474 8007030545 8007040414* 8007040415* 8007050274	50-244 50-244 50-244	Р Р Р
	8007070557 8007070578 8007070587 8007070589* 8007070591*	50-354 50-272 50-272 50-272 50-272	**************************************		8007050278* 8007090377 8007070382* 8007070513 8007070551	50-244 50-244 50-244	У Р Р Р
	8007070593 8007070595* 8007110323 8007110357 8007110472	50-272 50-272 50-272 50-311 50-354	5 5 0 0	i	8009110485 8009140317 8009140539 8009170303 8009170304*	50-244 50-244 50-244	Q F P P
	8009120218 8009120357 8009120372* 8009120375 8009120382*	50-354 50-272 50-272 50-272 50-272	\$ \$ \$ \$ \$ \$		8009170311 8009180245 8009180272* 8009190667 8009220324	50-244 50-244 PR	Q R R
	8009120424 8009120428* 8009150043* 8009150264 8009150267*	50-272 50-272 50-354 50-311 50-311	# # # # # # # # # # # # # # # # # # #	Rochaster Univ of Rockwell International Corp , Energy Systems Div	8009240192* 8009200345 8009160450 8009120620	50-244 NUREO 70-25	Q P
	8009160278 8009160300# 8009160351 8009160393 8009160401	50-272 50-272 50-311 50-311 50-272	R R P V P	Rocky Mountain Energy Co	8009150396 8008110042 8008110046* 8009080453 8009170237	71-5088 40-8721 40-8721 40-8697 40-8380	
	8007140401 8007140478 8007140482* 8007140450 8007180247	50-272 50-311 50-311 50-354 50-311	P S S S		8007260024 8007260153 8007260157* 8007250047 8007120536*	40-8380 40-8380 40-8380 50-471 70-343	Q
	8009180257# 8009180413 8009180455 8009180458 8009180465	50-311 50-311 50-311 50-311 50-311	R P P	SRI International Sacramento Municipal Utility District	8007100012# 8007030187 8007040400 8007050240 8007050241#	50-312 50-312	9 F P
	8009190192 8009190210* 8009190213 8009190396 8009190466	50-311 50-354 50-311 50-311 50-311	6 6 6 6		8007050337 8007050344* 8007080433 8007070784 8007070788*	50-312 50-312 50-312 50-312 50-312	R P Q
	8009190479 8009190515 8009190527 8009190534 8009220244	50-311 50-311 50-311 50-311 50-311	₽ ₽ ₽ ₽		8007070812 8007070813* 8007150247 8007150272*	50-312 50-312 50-312	Q Q S S

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	RY
	8007150540 8007160295 8007160297* 8007160388 8007160372*	50-312 50-312 50-312 50-312 50-312	P R R P		8009120583 8009150041 8009160046 8009220064 8009250452	FOIA 50-289 PR 70-820 FOIA	G.
	80091 60628 8009230677 8009240378 8009260472 8009260476*	50-312 50-312 50-312 50-312 50-312	0 R 0 S	Sierra Club	8009250467* 800925047[* 8009300417 8009300423* 8009300004	10PREP 10PREP 50-289 50-367	G G
San Antonio, TX San Diego Cas & Electric Co	8009290353 8009290354* 8009040289 8008270280* 8009030538*	50-312 50-312 50-445 50-361 50-204	Р М F R	Sigma Chemical Co (subs of Sigma-Aldri ch Corp) Small Business Administration	8009290485 8009290488 8009290581 8009300024 8009150178*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC CONTRACT	
	8009110399* 8009170169 8009170169 8009170171* 8009170171*	50-361 50-582 50-582 50-582 50-582	0000	Snall & Wilmor	8009300097* 8009300198* 8009300209* 8009030689 8009030699	CONTRACT CONTRACT CONTRACT 50-275 50-275	T T
San Luis Obispo Mothers for Peace Sandia Laboratories	8009190344* 8009190351* 8009160234 8009220262 8009020349	50-361 50-361 50-275 50-275 NUREG	K G O	South Carolina Electric & Gas Co	8009030714 8009020065 8009030460 8009030493 8009030621	50-528 50-395 50-395 50-395 50-395	0 H Q A S
	6009020341 6009040437 60090132 6009120502 6009190398	NUREO NUREO RES 50-3 NUREO	þ		8007100320 8007100427 8007110211 8009110717 8009120347	50-395 50-395 50-395 50-395 50-395	A A O A
Sandvik Special Metals Corp	8009190743 8009260092 8009260649 8009300160 8009090208*	NUREG NUREG NUREG NUREG XPORTL1			8009140434* 8009170294 8009180129 8009180511 8009230027	50-395 50-395 50-395 50-395 50-395	0 A G Q
Sargent & Lundy, Inc	8007090215# 8007030440* 8007180443 8007170474* 8007300465*	XPORTL I 50-275 NUREG 50-295 50-454	P A A		8009230282 8009230296 8009240552 8009240557* 8009250072	50-395 50-395 50-395 50-395 50-395	F A Q Q
Schiff, Hardin & Waite Schultz, N B Science Applications, Inc	8009170002* 8009030149 8009030152* 8009110379* 8009120597*	70-820 50-367 50-367 CONTRAC FOIA	Q Q		8009260516 8009260518* 8009290337 8009300002 8009300009	50-375 50-375 50-375 50-375 50-375	A A M G
Seattle Univ	8009160493 8009160515* 8009240312 8009250497* 8009040240	NUREG CONTRAC 70-1113 CONTRAC 50-137	T F	South Carolina Public Bervice Authority South Carolina, Btate of	8007300168 8007300570 8007180364 8007300007 8007020316	50-395 50-395 50-395 50-395 NUREG	A Q M G
Senate	8009020124* 8009020148* 8009020191* 8009020332* 8009120317*	50-320 50-320 50-219 50-320 50-327	H H H	South Carolina, Univ of South Texas Electric Cooperative	8007100072* 8007100076* 8007270142* 8007050418* 8007170188	27-47 27-47 CONTRACT 50-395 50-445	T A
Senate. Danking. Housing & Urban Affairs Sanate. Energy & Natural Resources Senate. Foreign Relations Committee Senata. Covernmental Affairs	8009240014* 8009150448* 8009100107* 8009110413* 8009020375*	FDIA COMMISS COMMISS COMMISS	SION SION SION	South Hest Nuclear Co Southern California Edison Co	8009300542+ 8009300542+ 8009150390 8008270278 8008270280+	50-478 50-478 71-9044 50-361 50-361	M F F
Shannon & Wilson, Inc Shaw, Pittman, Potts & Trowbridge	8009100093* 8009220277 8009030118 8009040365 80090907084	COMMISS NUREO 50-320 50-289 50-312	0 0 0		8009020006 8009020006 8009020007* 8009020010*	50-361 50-361 50-361 50-361 50-361	A A A A
	8009090768* 8009100429 8009100431 8009170219 8009170302	50-312 50-282 50-289 50-289 50-289	0000		8007020010* 8007020031 8007020078 8007020078	50-361 50-395 50-206 50-206 50-206	A 0 8 8
	8007250017 8007260301 8007260313 8007300011 8007300020	50-289 50-289 50-289 50-289 50-289	0 T Q		8007020083* 8007030387 8007030533 8007030538* 8007030634	50-206 50-206 50-206 50-206 50-206	8 F R R
Sheldon, Harmon & Weiss	8009300022 8009300410 8009300570 8009040258 8009040358	50-289 50-266 50-483 70-143 50-289	0 0 0	·	8007030637* 8007030644* 8007050286 8007050286 8007050302	50-206 50-206 50-206 50-206 50-361	i ŝ
	8007080444 8007080575* 8007110365 8007110547 8007110802	70-820 COMMISS 50-155 FOIA 50-155			8007050302 8007080322 8007080337 8007080343	50-351 50-206 50-395 50-206	

AUTHOR Affiliation	ACCESSION NUMBER	SUBJEC CATEGOI	IRY	AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO:	
~	8009090265 8009090268+ 8009090463 8009090470 8009090470	50-206 50-206 50-206 50-361 50-361	- R R P S S	State, Dept of	8009150423 8009300074 8009300650 8009300660 8009300664	XPORTLIC	C C
	800707 <i>0</i> 552 8007070811	50-204	P Q	State Dept of Bureau of Oceans & Internati Environ & Scientific Affairs	8007080279	XPORTL10	c
	8009110399+ 8009150011 8009150314	50-361 50-206 50-395 50-395	о о к	internati Environ & desenting Arrents	8909080547 8009100155 8009150428: 8009180296	OLITADAX OLITACAX IBBIMMDO OLITACAX	C (10)4
	8009140230 8009140521 8009140624 8009140626	50-206 50-206 50-361 50-206	P Q Q Q	Steerns-Roger, Inc Stone & Webster Engineering Carp Stone & Webster, Inc	8009270130 8009270136 80092700414* 8009090119*	XPORTLIC XPORTLIC 40-8681 50-334 GA979	
	8009170334 8009180421 8009180421 8009180429+	50-206 50-361 50-361 50-361	F A A	Sutin: Theyer & Browne Sweden Switzerland Systems, Sciences & Boftware YERA Corp	8003240038 8007240175 8007120407 8007020483 8007020085*	PT9 XPDRTLIC XPORTLIC NUREO 50-204	
	8009180429* 8009180433* 8009180433* 800919083 8009190338	50-361 50-361 50-361 50-361	A A Q K		8009100748* 8009100748* 8009180165* 8009180434 8009180446	70-754	
	8009190351* 8009190351*	50-361 50-361 50-361	K K K	Tech/Ops (Technical Operations, Inc.) Technassociates, Inc Technical Operatums,Inc	8007020513 8009140459 8009300198* 8009300209* 8009160204	71-9039 XPORYLIC CONTRACT CONTRACT PRM	
	8009190402 8009260508 8009260513* 8009290348	50-206 50-206 50-206 50-206	P 9 9 9	Technology Development of California, Inc Tetnetron: Inc Teledyne (socopes Tennessee Valley Authority	8007150178* 8007150147* 8007150373* 8008130476 8008150212	TOATTHOOT TOATTHOO E118-04 OVE-05	& 6
South on Antidonous III	8007300362 8007300377 8007300431 8007300448	50-206 50-206 50-361 50-206	Ф Р В Р		8008170458 8008170463 8007020046 8007020046 8007020056	50-370 50-328 50-370 50-370	8 8 9
Southern California, Univ of Southern States Energy Board	8007070556# 8007070664# 8007070672#	50-275 50-275	T T T T		8007020056 8007020069 8007020074# 8007020081	50-390 (50-296 (6 6 8
Southwest Research Institute	8009110297 8009110299* 8009110304*	90-293 (50-293 (F G Q Q		8007020074 8007020077* 8007020077* 8007020103*	50-390 H 50-390 H 50-390 H	K K K
Sauthwest Terms Electric Cooperative		CONTRACT	м		8007020104	10PREP 50-327 G	3
Southwestern Public Service Co Spiegel & HcDiarmid	8009300035 8009160299+ 8009020282 5	30-445 M 30-267 R 30-445 M	M R M		8007020133 8007020184 8007020214 8007020214 8007020214	50-259 0 50-259 0 50-327 0 50-327 0 50-327 0)))
	8009150417 3 8009160182 3 8009160275 5 8009170162 5	0-445 M 0-445 M 0-445 M 0-389 M	M 1 3 1		8007020214 8007020214 8007020214 8007020214	50-327 0 50-327 0 50-327 0 50-327 0	
	8009190091 5: 8009220221 5: 8009220222* 5: 8009220223* 5:	0-335 H 0-335 H 0-389 H 0-389 M	1 1 1		8007020214 8007020281 8007020406 8007020408* 8007020260*	50-327 0 50-327 8 50-274 P 50-294 P 50-390 0	!
St Francis Peoria.IL St Louis Unit	8009300188 70 8009120007* 00 8009230372* 00	0-445 M 0-2705 Ontract Ontract Ontract	(! !	8007030367 8007030373* 8007030397 8007030406 8007030406	50-327 g 50-327 g 50-327 R 50-259 p	! !
Standardized Nuclear Unit Power Plant System	8009300597* CC 8009030541 50)-206 P Intract)-482 A		£	007030404 9007030411# 9007030411#	50-259 p 50-259 p 50-259 p	
	8009170416 50 8009170442 50	-482 8 -482 0		9 8	0007030411# 0007030434 0007030434	50-257 P 50-327 P	
	8007170441 50 8007170441 50 8007170445* 50	-482 K -482 K -482 K		8 8 8	1007030438* 1007030488 1007030476* 1007030508 1007030514*	50-327 P 50-259 & 50-259 & 50-240 P	
Stanford Univ	B009190445# 50-	-482 K -482 K -482 A		8	007030517 007030523* 007030536 007030548	50-327 9 50-327 9 60-327 6 50-391 F	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	₹¥	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
	6007030558 6007030560 6007030566+ 6007030574 6007030574	50-259 50-327 50-259 50-390 50-390	ទ ន ស ស		8007070555 8007070555 8007070557 8007070540* 8007070540*	50-257 50-257 50-257 50-257 50-257	5 5 5 6
	8009030597 8009030604* 8009030631 8009030662 8009030664*	50-296 50-296 50-296 50-327 50-327	8 9 P P		8007070340 # B007070543 # 8007070543 # B007070543 #	50-259 50-259 50-259 50-259 50-259	р 1 1 1 1
	8009030&&&* 8009040401 8009040401 8009040430	50-327 50-390 50-390 50-390 50-390	ម ម ម ម		# 524504008 # 524504008 # 524504008 # 52450404008 # 5245040408	50-259 50-259 50-259 50-259 50-259	I I I I
	8007040436 8007040449 8007040484 8007040486 8007040487*	50-390 50-518 50-553 50-328 50-553	S S S		* E&E0P0P008 * E&E0P0P008 * E&E0P0P008 * E&E0P0P008 * E&E0P0P008	50-259 50-259 50-259 50-259 50-259	I I I I
	8007050257 8007080257 8007080257 8007080354 8007080356*	50-327 50-327 50-327 50-327 50-327	្ ឧ ឧ ទ ទ		80070705&3* 80070705&3* 80070705&3* 80070705&5* 8007070583*	50-259 50-259 50-259 50-259 50-327	I I I S 8
	8007080360 8007080367* 8007080373 8007080380* 8007080382	50-327 50-327 50-327 50-327 50-327	3 5 5 5 5 5		6007070588* 8007070570* 8007070802 8007070802 8007070802	50-327 50-327 50-327 50-327 50-327	8 0 0
	8007080371 * 8007070314 8007070328 * 8007070332 8007070341 *	50-327 50-294 50-294 50-296 50-296	8 8 6 6 6		8007070802 8007070802 8007070802 8007070802 8007070802	50-327 50-327 50-327 50-327 50-327	0 0 0 0
	8007070367 8007070367 8007070367 8007070370 8007070370	50-259 50-259 50-259 50-327 50-327	면 면 면 면 면		8009100236 8009100283 8009100283 8009100284 8009100293	50-328 50-370 50-370 50-328 50-370	8 8 8
	8007070414 8007070418* 8007070427 8007070427 8007070427	50-327 50-327 50-518 50-518 50-518	R R B B B		8009100293 8009100401 8009100401 8009100443 8009100443	50-370 50-438 50-438 50-390 50-390	8 8 8
	8007070434 8007070434 8007070434 8007070434 8007070440	50-518 50-518 50-518 50-518	8 8 8 8 8		8009100459 8009100472 8009100494 8009100494 8009100526	50-328 50-553 50-438 50-328 50-518	8 8 8 2
	8007070440 8007070440 8007070440 8007070445 8007070462#	50-518 50-518 50-518 50-260 50-260	8 8 8 8		8009100937 8009100537 8009100537 8009100537 8009100576	50-327 50-327 50-327 50-327 50-328	8 8 8
	8007070467 8007070481* 8007070470 8007070507* 8007070522	50-240 50-260 50-260 50-260 50-438	\$ 9 5 8		8009100574 8009110181# 8009110320 8009110352 8009110352	50-328 50-327 50-328 50-259 50-259	9 8 8
	8007070522 8007070524 8007070527 8007070530 8007070530	50-438 50-438 50-327 50-518 50-518	A G S S S S S S S S S S S S S S S S S S		8009110352 8009110353* 8009110353* 8009110353* 8009120245	50-257 50-259 50-259 50-239 50-296	R R R R
	8007070531 8007070543 8007070543 8007070543 8007070543	50-327 50-259 50-259 50-259 50-259	8 1 1 1		8009120249* 8009120261 8009120261 8009120293 8009120389	50-296 50-327 50-327 50-438 50-327	8 A A A
	EACOPO008 EACOPO0008 EACOPO0008 EACOPO0008 EACOPO0008	50-259 50-259 50-259 50-259 50-259	I I I I		E009120411 B009120412 B009120440* B009120443* B009120489	50-327 50-327 50-327 50-327 50-390	8 8 8 F
	8007070543 8007070543 8007070543 8007070543	50-259 50-259 50-259 50-259 50-259	I E E		8009120488 8009120479 8009120479 8009120479 8009120479	50-390 50-327 50-327 50-327 50-327	F Q Q Q
	8007070543 8007070543 8007070543 8007070547 8007070555	50-259 50-259 50-259 50-327 50-259	t 1 8 P		8009120679 8009120679 8009120679 8009120679 8009150460	50-327 50-327 50-327 50-327 50-438	0 0 0 A

8009150468* 50-438 A 8009190495* 50-23 8009150597 71-9074 8009190519* 50-23 8009160219 50-259 P 800919054* 50-23 8009160219 50-259 P 800919054* 50-23 8009160219 50-259 P 8009190540* 50-23 800916021* 50-259 P 8009190540* 50-23 800916021* 50-259 P 8009190540* 50-23 800916021* 50-259 P 8009190640* 50-23 800916021* 50-259 P 8009190640* 50-23 8009160221* 50-259 P 8009190640* 50-23 8009160225 50-390 S 8009220038 40-13 8009160325 50-328 S 8009220041* 40-13 8009160326 50-328 S 800922010 50-23 8009160328 50-328 S 8009230333 50-33 8009160333 50-338 S 8009230348 S0-33 8009160333 50-438 S 8009230348 S0-33	9997 799104 419977 077770 88PPS
BO07140321* 50-257 B009190403* 50-257 B009190403* 50-257 B009140321* 50-257 B009140321* 50-257 B009190759 70-27 B009140317 50-327 B009140325 50-327 S009140325 50-327 S009140325 50-328 S009220041* 40-15 B009140326 50-328 B009220210 50-27 S009140326 50-328 B009230333 50-32 S009140333 S	9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9
8009160326	9 P 9 P 7 F 0 8 7 P 7 P 5 S
8009160353 50-438 S 8009230524 50-33	7 8 7 P 7 P 0 S
B00916036B 50-564 \$ B009230549 50-32 B009160372 50-327 \$ B009230549 50-32 B009160372 50-327 \$ 8009230560 50-32) e
B009160375 50-327 8 8009230560 50-39 8009160377 50-438 8 8009230587 50-32 8009160377 50-438 8 8009230587* 50-32 8009160380* 50-327 8 8009230510 50-39 8009160390 50-327 8 8009230510 50-39	7 S
8009160398* 50-327 \$ 8009230611 50-327 8009160406 50-327 \$ 8009230669 50-29 8009160412* 50-327 \$ 8009230674 50-29 8009160416 50-296 \$ 8009230675** 50-29 8009160418 50-376 Q 8009230679** 50-29	6 8 6 8
8009160418 50-370 G 8009230704 50-28 8009160421 50-327 G 8009230714* 50-25 8009160422* 50-286 S 8009230714* 50-25 8009160423 50-390 G 8009230728* 50-28 8009160423 50-390 G 8009230730* 50-32	7 B
8007160425* 50-327 8 9007230734* 50-32 8007160432 50-260 8 8007240261 50-25 8007160437 50-438 8007240261 50-25 8007160440* 50-260 8 8007240261 50-25 8009160454 50-260 8 8007240267 50-51	? a ? a ? a
8007160463 50-327 S 8007240383 50-25 8007160466* 50-260 B 8007240383 50-25 8007160468* 50-327 S 8007240383 50-25 8007160467* 50-391 A 8007240387 50-31 8007160643 50-518 B 6007240372 50-51	7 Q 9 Q
8009160648 50-438 8 8009240425 50-51 8009160648 90-438 8 8009240427 50-51 8009170206 50-297 P 8009240427 50-31 8009170261 50-327 R 8009240427 30-81 8009170262* 50-327 R 8009240427 50-51	9
8009170274 50-257 R 8009240427 50-51 8009170274 50-259 R 8009240427 50-51 8009170274 50-259 R 8009240446 50-25 8009170277* 50-259 R 8009240446 50-25 8009170277 50-327 P 8009240446 50-25	9
8009170297 50-327 P 8009240454 50-321 8009180068 50-318 Q 8009240434 50-321 8009180068 50-518 Q 8009240434 50-321 8009180068 50-518 Q 8009240434 50-321 8009180068 50-259 Q 8009240434 50-321	0
8007180068 50-518 Q 8007240454 50-326 8007180048 50-518 Q 50-566 50-566 8007180048 50-518 Q 6007250073 50-266 8007180087 50-390 Q 6007250075 50-266 8007180087 50-390 Q 8007250075 50-436	a a
B009180087 50-259 0 8009250256 50-436 B009180087 50-259 0 8009250273 50-397 B009180087 50-390 0 8009250480 50-327 8009180087 50-397 0 8009290282 50-327 8009180087 50-397 Q 8009290280* 50-327	9 0 P
8007180087 50-259 Q 8007290324 50-390 8007180397 50-260 B 8007290324 50-390 8009180400 50-259 B 8009290327 50-390 8009180401 50-259 B 8009290327 50-390 8009180441 50-276 B 8009290327 50-320	8 8
8009190440 50-260 8 8009290333 50-327 8009190454 50-260 6 8009290344 50-37 8009190465 50-259 8009290344 50-37 8009190467 30-259 8 8009290345 50-255 8009190471 50-327 8 9009290346 50-436	8 8 8
BO09190476 50-327 P 8009290347* 50-289 B009190476 50-327 P 800929035 50-325 B009190488 50-259 P 8009290355 50-35 B009190498 50-259 P 8009290355 50-55 B009190495* 50-259 P 8009290375 50-518	\$ 8

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEG		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEODR	
	8009290375 8009290375 8009300067* 8009300067* 8009300067*	50-519 50-519 50-259 50-259 50-259	8 0 0		8009220334 8009220334 8009230005 8009230005 8009230301	50-445 50-445 50-445 50-445 50-445	AAGGB
	8009300147 8009300147 8009300147 8009300156* 8009300156*	50-259 50-259 50-259 50-259 50-259	P P P		8009230301 8009290571= 8009300055 8009300065 8009300065	50-445 50-445 50-445 50-445 50-445	9 0 0 0
	8009300154* 8009300195 8009300226 8009300277 8009300280*	50-259 50-327 50-327 40-1341 40-1341		Teras Utilities Services, Inc Teras, State of	8009300070 8009300076 8009300076 8009230623 8009090851*	50-445 50-445 50-445 50-445 COMMISSI	G G A NO
	8007300348 8007300348 8007300353 8007300353 8007300353	50-438 50-438 50-259 50-259 50-259	8 8 P P		8009070655* 8009090662* 8009160332 8009160543 8009170894	COMMISSI COMMISSI 50-478 WASTE MO State Pr	MD M T
	8007300375 8007300400 8007300400 8007300400 8007300400	50-329 50-259 50-259 50-259 50-259	5 P P P	Teras, Unvi of, El Paso Teras-Louisiana Electric Cooperative, Inc	8009120590 8009170232* 8009170232* 8009170364* 8009170364*	RES 50-445 50-445 50-445 50-445	м н н
	8009300411 8009300411 8009300427 8009300427 8009300429	50-438 50-438 50-438 50-438 50-276	S S S P	The Tribune Chronicle, Warren, CH Thompson, Nielson, KlaverKamp & James	8009230239* 8009230242* 8009230245* 8009230247* 8009050354	50-320 50-320 50-320 50-320 50-327	H H H O
	8009300445 8009300451 8009300467 8009300480 8009300480	50-518 50-327 50-328 50-438 50-438	9 9 9 8	Three Hile Island Alert Three Hile Island Public Interest Resource Center	8009020407 8009300629 8009300632= 8009030421	50-289 50-289 50-289 50-289	0 0 P
8009300521 * 8009300529 8009300544	50-259 50-259 50-259 50-296 50-260	s c s		8009020057 8009020061* 8009020333 8009020374* 8009020012	50-346 50-346 50-346 50-346 NUREQ	8 8 8	
Teres A& & Univ	8009300553* 8009300554* 8009300562 8009300567* 8009030350	50-294 50-260 50-259 50-259 50-128	S S S R		8009080317 8009080319* 8009100172 8009100504 8009120351 8009120354*	50-346 50-346 50-346 50-346 50-346 50-346	R R P O S
Texas Border Cooperatives Texas Enstruments, Inc	8009030353* 8009030568 8009030572* 8009300496* 8009020255	50-129 50-59 50-59 50-445 70-33	R R R M		8009120430 8009150047 8009150274 8009150277# 8009160391	50-346 50-346 50-346 50-346 50-346	F Q R R
	8009020259* 8009030435* 8009110702 8009120648 8009150078	70-33 50-367 70-33 70-33 70-33	R		8007160377* 8007220176 8007220277 8007220301* 8007220313*	50-346 50-346 50-346 50-346 50-346	8 0 P P
Texas Public Interest Research Group	8009160527 8009170149 8009170153* 8009170154* 8009170157*	50-466 50-466 50-466 50-466 50-466	0 0 0		8007230671 8007230680* 8007230682 8007230686* 8007230670	50-346 50-346 50-346 50-346 50-346	8 8 8
Terms Technologial College forms Utilities Generating Co	8009170223 8009170225* 8009030216* 800907030216 8009110048	50-466 50-466 CONTRACT 50-445 50-445	Ç V O		8007230472* 8007260077 8007270363 8007270370* 8007170248	50-346 50-346 50-346 50-346 50-440	8 9 8 8 K
	8009110048 8009110781 8009150012 8009150213 8009150215*	50-445 50-445 50-445 70-2932 70-2932	0	Transmuciear. Inc	8009020480 8009020486* 8009050469 8009110240	XPORTLIC XPORTLIC XPORTLIC 70-2478 XPORTLIC	
	8009160362 8009160362 8009170141 8009170141 8009170232*	50-445 50-445 50-445 50-445 50-445	A O G M		8007110497 8007110502+ 8007110529 8007110695 8007110700	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	
	8009170235* 8009170235* 8009170359 8009170359 8009170359	50-445 50-445 50-445 50-445	M M M		8009110743 8009150433* 8009150438* 8009180512 8009240218	XFORTLIC COMMISSI COMMISSI 70-2478 XFORTLIC	
	8009170369* 8009170369* 8009170420 8009180045 8009180457	50-445 50-445 50-445 50-445 50-445	M Q G		5009250224* 6009300078 8009300079 8009300084*	XFORTLIC XPORTLIC XPORTLIC XPORTLIC	:

AUTHOR AFFILIATION	ACCESSION NUMBER	SUDJEC CATEOO	RY	AUTHOR AFFILIATION	ACCEBBION NVMBER	SUBJE	ORY
U S Court of Appeals 9th Circuit Union 75 Minerals Exploration Co Union Carbide Corp	8009180431 8009110890 8008130375 8009120390 8009160549	50-312 40-8584 40-299 40-299 40-299	o		8007030571 × 8007030576 8007030586 × 8007030593 8007030604	50-339 50-339 50-339 50-339 50-338	8
Union Electric Co	8007020073 8007070544 8007100080* 8007230651 8007230662	50-483 50-483 50-483 50-483 50-483	K 8 8		8007030608* 8007030612 8007030614* 8007030615 8007030617*	50-339 50-338 50-338 50-339 50-339	5 5 5 8
	8009230662 8009230667# 8009230667# 8009300447 8009300570	50-483 50-483 50-483 NVREO 50-483	и к к		8007030423* 8007030427 8007030432* 8007030642 8007030647*	50-338 50-338 50-338 50-338 50-338	8 8 8
Union of Cancerned Scientists	8007040358 8007150041 8007230011 8007300420+ 8007300422+	50-287 50-287 50-289 50-269 50-289	0 T 0 0		8007030453 8007030458* 8007050054 8007050327 8007050327	50-338 50-338 50-281 50-338 50-338	S 9 0 R
United Engineers & Constructors, Inc (subs of Raytheon Co)	8007300423* 8007160645	50-287 50-443	9 9		8009050335* 8009050335*	50-338 50-338	R
United Nuclear Carp . UNC Recovery Systems Div	8009110221 8009110230	70-820 70-820			8007080351 8007080366# 8007080374	50-281 50-281 50-339	9 8 P
United Nuclear Corp ,Navai Products Div	8009110235 8009110232* 8009170005* 8009180527 8009240668	70-820 70-820 70-820 70-820 70-371			6009090274 8009090344 8009090344 8009090347* 8009090347*	50-280 50-338 50-338 50-338 50-338	F P P P
United Technologies Corp , Pratt & Whitney Aircraft Group	8009300537	40-791			8009090352* 8009090352*	50-338 50-338	P
Utility Workers Union of America Velan Valve Go Vermont Yankee Nuclear Power Corp	6009150243 6009250313* 6009020113 6009050316	RECOD GA999 50-271 50-271	Q 8		8007070499 8009090512# 8009090528	50-338 50-338 50-280 50-280	8 9 9
	8009050322* 8009080375 8009080381* 8009090478 8009090535	50-271 50-271 50-271 50-271 50-271	8 P P R		8009070538 8009090541 8009090584* 8009090586*	50-339 50-338 50-339 50-338	9 9 9
	8007100127 8007100127 8007110467 8007120401 8007120405#	50-271 50-271 50-271 50-271 50-271	R Q P P		8009100262* 8009110431 8009120031 8009120031	50-280 50-338 50-280 50-280	8 P 4
	8007160271 8007160301* 8007180451 8007180452*	50-271 50-271 50-271 50-271	R R P P		8009120031 8009120702 8009130257 8009150274 8009150278*	50-260 50-338 50-338 50-280 50-260	9 9
	8009230100 8009230107 8009240207 8009240221 8009260458	50-271 50-271 50-271 50-271 50-271	a a P P P		8009160324 8009160429 8009170321 8009170323* 8009180251	50-281 50-339 50-281 50-281 50-280	٦ ٩ ٩
it Admin Hosp Omaha.NE illage Voice Jirginia Electric & Power Co	8007260461 * 8007260280 8007150003 8007030184	50-271 50-131 FOIA 50-280	P F		8009180251 8009180412 8009180417* 8009190437 8009190437	50-280 50-339 50-339 50-280 50-280	P 8 8 R R
	8007030207* 8007020098 8007020090*	50-280 50-281 50-281 50-404	F 9 8		8009190444* 8009190525 8009190525 8009190525	50-280 50-280 50-280	R P P
	8007020236 8007020242 8007020344 8007020350*	50-404 50-280 50-280 50-280	Q Q S S		8009190553 8009190553 8009190559*	50-280 50-260 50-280 50-280	8 9 8
	8007020397 8007020397 8007020416 8007020416	50-404 50-404 50-404 50-404	Q Q Q Q		8007170566* 8007220134 8007220134	50-280 50-280 50-339	9 P P
	8007020437 8007020437 8007020441* 8007020441*	50-280 50-280 50-280 50-280	P P P		8009220241 8009220243 6009220248 8009220251	50-339 50-338 50-281 50-338	8 8
	8007030425 8007030425 8007030428* 8007030428*	50-338 50-338 50-338 50-338	P P P		8007220253 8007220258* 8007220240* 8007220240*	50-280 50-280 50-280 50-280	9 8 8
	8007030525 8007030535# 8007030555	50-280 50-280 50-338	8 8		8007220306* 8007220307* 8007220315*	50-338 50-281 50-339	8 8
	8007030561* 8007030567	50-338 50-33 9	8 8		8009220319* 8009220324* 8009220355	50-337 50-339 50-339	5 6 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR AFF ILIATION	ACCESSION NUMBER	Bubject Categor	
	8009220360# 8009220369 8009220373# 8009220398# 8009220402#	50-339 50-338 50-338 50-281 50-281	\$ 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		8009160622 8009170388 8009170393 8009170393 8009190677	50-460 50-397 50-460 50-460 HUREO	0 0 0
	8009230097 8009230287 8009230292 8009230320 8009230320	50-338 50-338 50-338 50-338	G P F F		6009230352 6009230696 8009240464 8009240465 8009200346	50-397 50-397 50-397 50-397 50-460	A 8 9
	8007230343 8007230356 8007230360# 8007230360# 8007230554	50-280 50-338 50-338 50-338 50-337	F R R S	Washington State Univ	8009300352 8009300379 8009300415 8009030528 8009030530+	50-397 50-397 50-397 50-27 50-27	A S R R
	B009230577* B009230589 B009230600* B009230605 B009230615*	50-337 50-339 50-339 50-338 50-338	\$ \$ \$ \$ \$	Hashington, State of Hest Teras Legal Services Western Cultural Resource Hanagement, Inc.,	8007300391 8007240260 8007070238 8007150045 8007150164*	50-27 State Pr 50-445 50-445 40-8743	P 0 0
	8009230622 8009230629 8009230636*	50-338 50-338 50-338	8 0 0 6	Western Nuclear, Inc (subs of Pheips Dodge Corp)	8009150550 8009180419	40-1162 40-1162	
	8007230445 8007230461* 8007230473* 8007240180	50-280 50-280 50-280 50-280	8 9 9	Westinghouse Electric Corp	8009260041 8009300141 8009020017# 8009020492	40-1162 40-1162 50-537 XPORTLIC	
	E009240399 E009240399 E009240399	50-280 50-280	a a		8007020477* 8007040180* 8007040407 8007080274	XPORTLIC 50-298 TOPREP 50-348	
	8009240399 8009240469 8009240470* 8009240471*	50-280 50-281 50-281 50-281	Q 8 8 8		8007080277* 8007100048 8007100076 8007100101* 8007100117*	50-348 XPORTLIC XPORTLIC XPORTLIC XPORTLIC	:
	8009240661* 8009240701* 8009250087 8009250087	50-281 50-260 50-404 50-404	0 0 0 0		8007100131* 8007100187 8007100193* 8007100493 8007110028	XPORTLIC 70-1143 70-1143 XPORTLIC XPORTLIC	:
	8009260278 8009290319 8009290319 8009290321*	50-260 50-338 50-338 50-338	P R R R		B007110135* B007110256* B007110264 B007110406	70-1151 CONTRACT XPORTLIC XPORTLIC	.
	8007270321 * 8007270347 8007300116 8007300116 8007300116	50~338 50~338 50~280 50~280	R P Q Q Q		8009170295 8009170295 8009170298* 8009170301*	XPORTL1C 50-244 50-244 50-244 50-244	е Р Р
	8007300116 8007300247 8007300255 8007300478 8007300504*	50~280 50~338 50~338 50~281 50~281	0 P 0 8 5		8009170314* 8009170314* 8009180341 8009190365*	50-244 50-244 TOPREP 50-206	P P
Virginia Tech Virginia, State of	8009300508* 8009300459 8007030202* 8009090333* 8009090343*	50-281 50-124 50-280 50-339 50-339	9 F F U		8009190374# 8009190378# 8009220275 8009230685 8009230783	50-206 50-206 NUREO TOPREP XPORTLIC	
Virginia, Univ. of Vollen, R J	8009250263* 8009030703 8009030710 8009120372	CONTRACT 50-367 50-367 50-367	0 0 0	Westinghouse Electric Carp , Nuclear Energy Systems	8007250257 8007080279* 8007190453*	50-22 50-348 TOPREP	ů ľ
	8009120445* 800923000B 8009230382 8009230393	50-367 50-367 50-367 50-367	0 0 0	Westinghouse Electric Corp , PWR Systems Biv. Westen Deophysical Corp	8009190108 8009190457 8009190240 8009190240	70-1151 TOPREP 50-440 50-440	K K
Hashington Public Power Supply System	8007250011 8007020043 8007030342* 8007030521 8007080321	50-367 50-397 50-508 50-397 50-397	0 K 9 A A	Wharton & Pogalies White, M P Consulting Engineer	8007170244 8007170244 8007100406 8007110377 > 8007150242	50-440 50-440 50-361 50-361 50-70	K 0 0 D
	800707023 8007070317* 8007070322* 8007070476 8007070680	50-397 50-397 50-397 50-397 50-397 50-508	G K A K Q	Hhiting Corp Widoff, Reager, Selkowit: & Adler	8007150148 8007020407 8007240535 8007240536* 8007240538*	50-324 50-289 50-289 50-289 50-289	\$ · · · ·
	8007100177 8007110422* 8007120360 8007120363* 8007120568	50-460 TOPREP TOPREP 50-397	a	William F Kirk William Poweil Go Winthrop, Stimson, Putnam & Roberts Wisconsin Electric Fower Go	8009300627 8009170366 8009150062 8009230699 8009020497	50-289 50-201 50-358 50-412 50-266	i i p
	8009140422 8009140422	50-397 50-460	K G		8009030542	50-244	F



AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO	PRC	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEQUE	
	8009090539	50-266	R	Wisconsin's Environmental Decade	8009030498	50-266	P
	8007090539	50-266	R	Mtacodain a Citatiohmanas necana	8007080348	50-266	ő
	8009090545*	50-266	R			00 -00	
	8009090545*	50-266	R	Wisconsin, State of	8007020050	50-266	U
	8009110557	50-266	Q	HIZCONSINI GVENT OF	8009110411	50-246	H
					8009240490	50-266	ΰ
	6009190302	50-266	R	Wisconsin, Univ of Madison	8009040397	50-154	Š
	6007160304*	50-266	R	Woliver, J D	E740C07008	50-358	ŏ
	8009160442	50-266	P	W			-
P	8009180158	50-266	G	Woodward-Clyde Consultants, Inc	8009190272	50-440	K.
	8009180158	50-266	a	***************************************	8007240455#	50∽3	Ŕ
				Worcester Polytechnic Inst	8007020018	50-134	ř
	6009230460	50-266	P	Worsham, Forsuthe & Sampels	8007170359	50-445	н
	6004530777	50-266	P	Myoming Mineral Corp	8008110036	40-8502	••
	8007250249	50-266	P	ingomizing transplant corp			
	8009250249	50-256	Р		8008110038*	40-8502	
	80072502534	50-266	р		8008120614	40-0502	
					B009120620*	40-8502	
	8009250253*	50-266	P		8008150957*	40-8502	
	8009260215	50-266	F		8008120630*	40-8502	
	8009290177	50-266	F		p000120000+	10-0502	
	8009290177	50-266	F		800B120431*	40-B502	
	8007270341	50-266	P		8007150023	40-8502	
	0		•		8007170240	40-8502	
	B009290341	50-266	Р		8009300191	40-8502	
	8009290342#	50-266	P	Wyaming Outdoor Council	8007020508	40-8745	
	B009290342*	50-266	Þ	Månuttiå ogtodot, contrett	6007020308	40-6/43	
	8009300305	50-256	à	Wyoming, State of	60090Z0490	40-8502	
	8009300461	50-266	P	whowilld, grace or	8007020552	40-8745	
	0001000-101	22 EDC	•		8007020332 8007100288	40-8102	
	6009300461	50-266	Р		8009150212*	40-8745	
Wisconsin Power & Light Co	8007090358*	50-305	ė		6007150512#		
Wisconsin Public Service Carp	8009030504	50-305	Ř		8007130333	40-8745	
warden i addite dij filos ducp	8007030512*	50-305	Ř		0000440544	10 0745	
	B009090273	50-305	Ř		8009160546 8009170134	40-8745	
	400.0102.0	600	,,			40-8745	
	8007090277#	50-305	R	Yankee Atomic Electric Co	8007170423 8007020021	40-8492	
	8009090355	50-305	ë	AMUKAN Mcowic clectic co		50-29	P
	8009090358*	50-305	þ		164050908	20-56	P
	8007110378	50-305	p				_
	8007110378	50~305	P		8009080522	50-29	Q.
	8007110381#	30-303	r		8009080526	50-29	a
	8007150444=	50-305	a		8009100542	50-29	P
	E009240495	30-305	S		6007110327	50-29	8
			8		8009110334*	50-24	8
	8009240501=	50-305	8				
	800924050B*	50-305			8009140289	50-29	R
	1400926008	50-305	Q		8009140303*	50-27	R
	0000010001	EA 205			8009180351	50-29	R
	8009260081	50-305	Q F		8007180355*	50-29	R
	8009290173	50-305			EBE0814008	50-27	P
	8009300425	50-305	R				

REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCESSION NUMBER	BUBJECT CATEGORY	OTHER REPORT NUMBER
01-0910-1087 69-1106001-00 77-03 79-4 60-059	8009090088 8009260366* 8009090636* 8009050418* 8008080302*		IEB-79-01B IESUANCES SP
80-1120838-00 8007030010 8007030200 8007050399	8009100176* 8009020366 8009030010 8009050200 8009050399		648 E00-EA-5204 EEC-LOFT-5199 8052794 UBNRC-P394
8009050405 8009030409 8009090132 8009090707 B009100412	8009050405 8009050407 8009090132 8009090770 8009100412	RES RES RES RES	E00-TFBP-5193 ORNL/MRBT-5
8009100308 8009100320 8009100330 8009110416 8009110419	8007100508 8009100520 8009100530 8009110416 8009110419	REB REB RES REB REB	ORNL/FTR-868 EGO-TFBP-5171 EEG-CDAP-5214
8009110421 8009110483 8009110498 8009110574 8009110634	8009110421 8009110483 8009110498 8009110574 8009110634	RES RES RES RES RES	ORNL/HASRD-90 ORNL/FTR-892 ORNL/HASRD-89
8009110876 8009110888 8009120547 8009120571 8009120572	8007110876 8007110885 8007120567 8007120571 8007120572	RES RES RES RES RES	GRNL/HASRD-88 GRNL/CSD/1NF/80 WX-8-3775
8009120579 8009120581 8009120590 8009120637 8009120646	8007120577 8007120581 8007120590 8007120637 8007120666	RES RES 50-315 P	EGG-EA-5186 GRNL/FTR-897 NRC-04-76-323 EGG-EA-5220 LO-MR-007
B009120733 B009150311 B009150543 B009140472 B009140478	8009120733 8009150311 8009150343 8009160492 8009160498	REB REB REB	ORNL/ED/EAS-80 WX-8-3784 89-80-08-02
9009180309 8009190401 8009190768 8009240253 8009240291	8009180309 8009190401 8009190768 8009240253 8009240291	RES RES	E00-EA-5214 BNL-NURE0-20199 E00-CDAP-5166 ORNL/ED/E18-134
3007260067 3007260075 3007260084 3007260077 3007260110	8009260069 8009260075 8009260084 8009260099 8009260110	RES 50-316 P	UBNRC-P394 RE-A-80-055 E00-EA-5227 E00-TFBP-5221
3009240520 3009240530 8009240530	8007260520 8007260542 8007260550 8007260558 8007260568	RES RES	E00-EA-5228 EE0-GAAP-5191 ORNL/HASRD-74 E00-TFBP-5222 E00-EA-5220

REPORT	ACCESSIGN	SUBJECT	OTHER REPORT
NUMBER	NUMBER	CATEGORY	NUMBER
84-1103585-00 84-117679-000 86-1120838-00	8009260340* 8009260380* 8009290373*	50-289 T 50-289 T 50-329 A	ISSUANCES SP ISSUANCES SP
B&RUE-COM4-1-NP R2 BAW-10043	8007030364* 8009260402*	TOPREP	ISSUANCES SP
ES ACO101-WAS	8009240329 *	50~289 T	168UANCES BP
PC-01-WAS	8009030519 *	50~287 P	
00085-0390W-JNS	8009220395	TOPREP	
CE-1-A R14	8009100548*	TOPREP	
CE-1-A R14A	8009230684*	TOPREP	
CE-78-14	8007070472*	50-275 T	
CE-79-02	8007070664*	50-275 T	
CEB-78-14 R1	8007150468*	50-438 A	
CEN-135(8)-NP	8007050308*	50-361 A	
CEN-137(8)	8007230646*	50-317 P	
CEN-138(D)	8009230650*	50-317 P	64 801 0013
CENPD-254-NP-A	8009240527*	TOPREP	
COM-0708-03	8009020111*	50-237 P	
CRERP-ARD-0204	8009020017*	50-537 A	04 001 0015
CURL-2 81	8009230452*	50-157 P	
EA 80-01 EDAC 117-259 03	B009260468* B009180477*	50-237 P 50-70 P 50-155 P	
FD-CPW-002 R1 QA-C15847 CEAP-23163-2	8009300235* 8009220321* 8009160436*		1700 UC-78
NEDD-10327 NEDD-20776 R5 NEDD-24085-1 R1 NEDD-24757 NEDD-24798	8009300483* 8009300586* 8009300307* 8009050328* 8009230431*	TOPREP 70-1308 50-245 P TOPREP TOPREP	BONEDZB1 BONEDOŠA BONEDZB2
NEDD-24811	8007230475*	TOPREP	EDNEDO57
NUREO 0020 V4 N08	8007270038	NUREO	
NUREO-0011 DRFT 52	8007110343*	50-327 P	
NUREO-0011 DRFT 53	8007110355*	50-327 P	
NUREO-0011 52	8007080423*	50-327 E	
NUREO-0011 83	8009240258*	50-327 E	
NUREO-0053 812	8009110505	50-339 E	
NUREO-0134 ADD 2	8009150523	50-338 D	
NUREO-0436 NO1 51	8009110639	NUREO	
NUREO-0540 V2 NO5	8009020373	NUREO	
NUREO-0540 V2 NO6 NUREO-0606 V2 NO3 NUREO-0553 NUREO-0664 R1 APP A NUREO-0664 R1 APP B	8009120333 8009300308 8009100407 8009160661* 8009160663*	NUREO NUREO NUREO 50-339 P	
NURE9-0678	8009100158	NUREO	
NURE9-0679	8009120337	NUREO	
NURE9-0685	8009300303	NUREO	
NURE9-0702	8009020504*	40-299	
NURE9-0715	8009120626	50-247 P	
NUREG/CR-0893	8007120528 8007160202 8007100750 8007100750 8007160481	NUREO NUREO NUREO NUREO NUREO	ORNL/NUREO/CE BNL-NUREO-509 UCRL-52707 PNL-3046

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
NUREO/CR-1038 NUREO/CR-1045	8009120338 8009160450	NUREQ NUREQ	UCRL-52723
NUREO/CR-1113 NUREO/CR-1120 V3	8009240605 8009120339	NUREO NUREO	UCLA-ENG-7953
NUREO/CR-1185	8009100036	NUREQ	LA-7199-MS ADDI
NUREG/CR-1282	8009300140	NUREC NUREO	8AND79-2300 PNL-3158
NUREO/CR-1278 NUREO/CR-1302	800916045 <i>6</i> 8009150597	NUREO	PNL-3278
NUREO/CR-1302	8009160198	NUREG	TN-314
NUREG/CR-1340	8009020483	NUREG	856-R-80-4217
NUREQ/CR-1347	8007100744	NUREO	ORNL/NUREG-82 PNL-3040-4
NUREO/CR-1349	8009100403	NUREO	UCLA 12-1235
NUREG/CR-1358	8009190405	NUREO	SAND80-0644
NUREQ/CR-1377	8009020349	NUREO NUREO	BNL-NUREQ-51177
NUREO/CR-1402	6007110321		
NUREQ/CR-1404	8009100947	NUREO	BNL-NUREO-51179
MUREO/CR-1410 V1	8009120502		SAND80-0617/1
NUREO/CR-1411 V2	6009300169		LA-8306-MB
NUREO/CR-1428	6004570988	NUREO	PNL-3411
NUREO/CR-1448	8009020361	NUREO	BANDE0-1004
NUREQ/CR-1450	8009100954	NUREO	E-MT/QBRUN/JNRG
NUREG/C#-145B	8009100053	NUREO	LF-71
NUREG/CR-1471	8009150594	NUREO	LA-URBO-45-15
NUREG/CR-1482	8009020358	NUREO	E-MT/OBRUN/JUNO
NUREQ/CR-1404	8007070020	NUREG	HEDL-THE 80-24
NUREQ/CR-1485 V1 NO1	8009290062	NUREO	UCRL-52715-80-1
NUREQ/CR -1 487	6009040437	NUREO	
NUREG/CR-1492	8009190398	NUREG	SAND80-1117
NUREG/CR-1509	8009190743	NUREO	9ANDEO-1304/10F
NUREG/CR-1516	8009110503	NUREO	LA-8279-PR
NVREG/CR-1521	8009100953	NUREC	GRNL/NUREG/TM-3
NUREO/CR-1527	8009170782	NUREO	0011 4110ma 70
NUREQ/CR-1529	8009260536	NUREO	ORNL/NUREG-72
NUREQ/CR-1539 NUREQ/CR-1547	8009160493	NUREO NUREO	ORNL/SUB-7615/1 PNL-3314
	8009100413		
NUREG/CR-1541	8009260669	NUREO	SAND80-1495
NUREO/CR-1563	8009030671	NUREO	DRNL/NUREO/THI-
NUREQ/CR-1579	6007260072	NUREO	SAND 80-1618
NUREO/CR-1582 V2	8009180446	NUREO	
NUREO/CR-1582 V3	8007180434	NUREO	
NUREO/CR-1583	8009080402		ANL/EB-97
NUREO/CR-1592	8009020479		ANL-80-40
NUREQ/CR-1593	6009160446	NUREO	
"UREQ/CR-1602	B009020355	NUREO	
JREO/CR-1607	8009020161	NUREO	LA-8449-M8
JREG/CR-16GB	E0091505B5	NUREO	CGB/NR85FOAD
JREG/CR-1409	8009120336	NUREO	CQ5/NR85U060

REPORT NUMBER	ACCESSION NUMBER	EUBJECT GATEODRY	OTHER REPORT NUMBER
NUREG/CR-1625	6009100043	NUREO	BHI-2058
NUREG/CR-1631	8007100043	NUREO	RU1 -5026
NUREO/CR-1634	8009150599	NUREO	LA-8475-MB
NUREG/CR-1657	8009300164	NUREO	BM1-2062
NUREG/CR-1662 V1	8009020493	50-320 P	
NUREO/CR-1677 VI	8009240686	NUREO	BNL-NUREO-51247
ORNL/TM-7448	8009030534*	50-320 P	
RH-80-4-ED2	8009220041*	40-1341	10CFR 040 45
RH-80-5-8F-3	8009110353*	50-259 R	
RH-80-4-501	8007090418*	90-327 R	
EDTAT-80-05-03	8009170314*	50-244 P	
EDTAR-80-05-05	8009170296*	50-244 P	
80-80-08-RATGE	8009170301*	50-244 P	
SE-SP-58(80)	800919037B*	50-206 P	
SE-SP-58(80) ERR	8009190365*	50-206 P	
SECY-75-338	8009230141*	FOIA	
SECY-75-518	8009190320*	FOIA	
SECY-75-638	8009230274*	FOIA	
SECY-74-286	8009190366*	FOIA	
SECY-76-286A	8007170394*	FOIA	
8ECY-77-288	8007170514*	FOIA	
8ECY-77-433	8009190532*	FOIA	
SECY-78-216A	8009150418*	NOTEBIMMOS	
SECY-78-371	8009190550*	FOIA	
SECY-79-362	B0091905B7*	FOIA	
SECY-79-430	8009090799	SECY	3370
SECY-79-478	8009050131*	FOIA	
SECY-80-139A	6009180277*	10CFR	
SECY-80-253	8007040461	SECY	
BECY-80-293	8009090083	COMMISSION	
GECY-80-295A	8007070783	50-320 P	
SECY-80-342	8007030252	SECY	
8ECY-80-349	8009040459	SECY	
5ECY-80-364	8009250280*	10CFR	
SECY-80-393	8009240569	8ECY	
BECY-80-408	8009290405	SECY	
EECY-80-414	6009290032*	10CFR	
8ECY-A-80-138	8009290452	50-344 G	
TVA-TR75-1A R4	8007020103*	TOPREP	
WCAP-9765	8009190453*	TOPREP	
WCAP-9768	8009080297*	90-349 P	
WPP88-GA-004 R4	B007120363*	TOPREP	
XN-52-02 R1	8007260117*	71-6581	17119
XN-NF-79-59(NP)	8009260482*	TOPREP	
XN-NF-79-71 (NP) R1	8009260487#	TOPREP	
XN-NF-80-19(NP) V1	8009260493*	TOPREP	
XN-NF-80-17(NP) V2A	8009260498*	TOPREP	
XM-NF-80-19(NP) V2B	B009240504*	TOPREP	
Y1009J01A03	8009020412#	50-296 P	
Y1003J01A03	B007020412*	50-245 P	
1 1 000001 1101	DOGTOCOLORS	OU-ETU F	

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

ACCESSION NUMBER

ACCEBBION	NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE IBBUED	BUBJECT CATEGOR	
7904120082 7906010086 7906010088	7904120080 7906010084 7906010084	79/04/05 79/03/23 79/03/23	PT9 PT9 PT9	
7906010055 7906010091 7906290556	7906010084 7906290524	79/03/23 79/03/18	PT9 PT 9	
7911090077 7912040156 7912190023	7911090069 7912040149 7912190014	79/10/25 79/11/21 79/10/03	PT9 PT 9 PT 9	
7912190047 7912190054	7912190014 7912190014	79/10/03 79/10/03	PT9 PT9	
7912190067 7912190073 7912190080	7912190014 7912190014 7912190014	79/10/03 79/10/03 79/10/03	PT ም PT ማ P Tም	
B001020079 B00102007B	8001020069 8001020069	79/12/10 79/12/10	PT 9	
8001020083 8001020105 8001020108	8001020069 8001020069 8001020069	79/12/10 79/12/10 79/12/10	P T♥ P T♥ P T ♥	
B001270281 B003050217	8001290275 8003050215	80/01/18	PT 9 PT 9	
8003050224 8003050226 8003050232	8003050215 8003050215	80/01/21 80/01/21 80/01/21	PT 9 PT 9 PT 9	
8003190525 8003190529	8003190517 8003190517	80/02/06	PT9 PT9	
8003190537 8005090553 8005300695	8003190517 8005090552 8005300691	80/02/06 80/02/28 80/04/21	PT9 PT9 PT9	
8005300497 8004120884 8007030202	8005300691 8006120881 8007030184	80/04/21 80/05/07 80/06/30	PT9 PT9 50-280	F
8007030202 8007030207 8007290625 8008080193	8007030184 8007290624 8008080187	80/06/30 80/07/23 80/07/30	50~280 50~335 40~6659	F
B008090302	8008080277 8008110036	80/07/31	50-329 40-8502	F
8008110044 8008120620 8008120626	8008110042 8008120614 8008120614	80/07/14 80/07/23 80/07/23	40-8721 40-8502 40-8502	
B008120430	B008120614	80/07/23	40-8502 40-8502	
8008130378 8008200284 8008210618	8008130375 8008200282 8008210616	80/08/05 80/08/15 80/08/13	40-279 50-282 50-327	F
B008260340 B008270280	8008240337 8008270278	90/09/18	50-263 50-361	F
8008280114 8008280126 8008280495	8008280104 8008280104 8008280488	90/07/25 90/07/25 90/08/12	50-400 50-400 50-254	9
8007020003	8007020002	80/08/29	50-537	B

M4470410	· HOHAER			
	PRINCIPAL	DATE	SUBJEC	τ .
ENCLOSURE	DOCUMENT	ISBUED	CATEOD	
~				
8009020007	8009020006	80/08/22	50-351	A
8007020010	8009020004	80/08/22	50-361	A
8007020016	8009020015	80/08/22	50-213	ä
8009020017	8009020014	80/08/22	50-537	Ā
8007020033	8009020029	80/0B/25	50-369	F
8009020035	8009020034	80/08/20	50-317	R
8009020047	8007020044	80/08/25	50-249	R
8009020040	8009020055	80/08/25	50-263	F
8007020061	B009020057	80/08/26	50-346	8
B009020068	B003050095	80/08/22	50-348	8
8007020074	B009020059	80/08/56	50-296	P
8009020074	B009020072	60/08/52	50-282	F
9009020077	8007020070	80/08/25	50-155	а
8009020079	8009020073	80/08/27	50~250	٠
8009020080	8009020075	80/08/22	50-320	Ρ
80070200B3	000902007B	90/08/21	50-206	8
8007020085	6003020082	40/08/51	50-206	P
8009020089	8009020087	80/08/26	50~289	Ŧ
8009020090	8009020068	80/08/25	50-281	8
8009020091	8007020082	80/08/21	50-206	P
8009020096	8004020085	60/06/51	50~206	₽
8009020097	8007020094	80/08/59	50-370	ĸ
8009020099	8007020093	80/08/25	50 −483	Ą
8007020100	8004050085	80/08/21	50-206	₽
8004050103	8007020081	80/08/26	TOPREP	
				_
8007020111	8009020105	80/08/22	50-237	P
8009020112	8009020108	80/08/12	50-445	H
1009020124	8009020118	80/08/13	50-320	H
B009020148	8009020144	80/08/08	50-331	Р.
0009020156	8009020151	80/08/04	50-320	H
0000000110	ADDRESS C.	00.100.101	** **	41
8007020168 8007020171	8009020166	80/08/04 40/80/08	50-320 50-320	H
8007020171	8009020166 8009020172	11/80/08	50-320	Ĥ
8009020179	8007020172	80/08/05	50-329	Ä
			50-327	Ĥ
8009020191	8009020187	80/08/07	30-217	ra
8009020200	8009020193	80/09/11	40-4492	
8007020200	8009020202	80/09/08	COMMISSI	MO
8007020204	8009020202	80/08/08	COMMISSI	
8009020207	8009020202	80/08/08	COMMISSI	
8007020210	8009020202	80/08/08	COMMISSI	
000.0404.0	MAD GEMEAT	00, 00, 00	0011112001	
8007020212	8009020202	80/08/08	COMMISSI	ION
8007020214	B009020209	80/08/08	50-280	a
8009020217	8009020202	80/00/0B	COMMISSI	
8007020220	8009020209	80/08/0B	50-280	Ğ.
8009020225	8009020222	80/08/08	50-259	ā
	-341554-44			_
B009020232	8009020227	80/08/08	50-315	Œ
8009020237	8009020235	80/07/16	70-984	
8007020240	8009020233	80/07/16	50-397	G.
8009020246	8009020245	80/08/24	50-171	R
8007020251	8009020244	80/07/22	50-344	Q.

ACCESSION NUMBER			ACCERBION NUMBER
PRINCIPAL ENCLOSURE DOCUMENT	DATE	SUBJECT	PRINCIPAL DATE SUBJECT
	189UED	CATEODRY	ENCLOSURE DOCUMENT 188UED CATEGORY
8007020253 8007020249	80/08/07	50-546 8	8009020532 8009020528 80/08/15 50-528 8
8007020259 8007020255	80/08/25	70-33	8009020544 8009020544 80/08/15 PR
8007020261 8007020254	80/07/11	70-734	8009030040 8009030032 80/07/17 50-370 0
8007020265 8007020265	80/08/27	50-275 A	8009030054 8009030048 80/08/19 50-334 P
8007020267 8007020258	80/07/10	50-361 Q	8009030055 8009030052 80/08/15 NUREQ
8007020268 8007020263	80/09/27	50-275 A	8007030058 8007030048 80/08/19 50-336 P
8007020267 8007020263	80/09/27	50-275 A	80070300042 8007030048 80/08/19 50-336 P
8007020270 8007020263	80/08/27	50-275 A	8007030067 8007030041 80/08/15 REGOD
8007020271 8007020266	80/08/26	50-155 S	8007030079 8007030074 80/06/17 10CFR
8007020272 8007020266	80/08/27	50-275 A	8007030085 8007030080 80/08/17 CONTRACT
8007020274 8007020263	80/09/27	50-275 A	8009030098 8009030093 80/06/18 10CFR 8009030105 8009030105 80/09030105 80/06/17 10CFR 8009030117 8009030115 80/08/19 50-255 Q 8009030133 8009030126 80/08/18 50-295 Q 8009030140 8009030138 80/07/17 50-375 Q
8007020275 8007020263	80/09/27	50-275 A	
8007020277 8007020263	80/06/27	50-275 A	
8007020277 8007020276	80/08/15	50-304 S	
8007020285 8007020284	90/08/25	50-336 S	
8007020304 8007020277 8007020309 8009020305 8007020312 8009020303 8007020314 8007020310 8007020317 8007020315	80/08/14 80/08/11 80/08/06 80/08/14 80/08/11	50-289 H 50-289 8 50-327 0 50-320 H	8009030142 8009030134 80/08/29 50-409 0 8009030147 8009030134 80/08/29 50-409 0 8009030150 8009030134 80/08/29 50-409 0 8009030152 8009030149 80/08/29 50-367 0 8009030170 8009030139 80/08/14 50-498 0
8009020323 8009020320 8009020332 8009020328 8009020337 8009020303 8009020338 8009020336 8009020340 8009020340	80/08/12 80/08/13 80/08/15 80/08/15	50-320 H 50-320 H 50-327 Q 50-317 P 50-155 P	8009030184 8009030178 80/08/04 8tate Prog 8009030188 8009030183 80/08/15 50-349 0 8009030194 8009030187 80/08/16 50-320 H 8009030199 8009030183 80/08/15 50-349 0 8009030206 8009030200 80/08/27 50-302 R
8007020350 8007020344	80/08/27	50-280 8	8007030216 8007030208 80/08/13 CUNTRACT
8007020351 8007020345	80/08/25	50-244 5	8007030243 8007030239 80/08/06 50-407 P
8007020354 8007020352	80/08/27	50-277 R	8007030255 8007030252 80/07/23 8ECY
8007020357 8007020354	80/08/29	50-333 8	8007030260 8007030257 80/08/04 50-370 Q
8007020367 8007020362	80/08/29	50-366 8	8007030264 8007030257 80/08/04 50-370 Q
8009020372 8009020345	80/08/25	50-335 8	8009030270 8009030287 80/08/04 50-390 0
8009020374 8009020349	80/08/26	50-366 8	8009030274 8009030287 80/08/04 50-390 0
8009020375 8009020348	80/08/13	COMMIBSION	8009030281 8009030287 80/08/04 50-390 0
8009020376 8009020333	80/08/22	50-346 8	8009030314 8009030289 80/06/11 50-397 A
8009020333 8009020377	80/08/22	50-245 8	8009030326 8009030323 80/07/16 50-305 0
80070203B5 8007020377	80/08/24	50-217 8	8009030342 800903033B 80/07/09 50-508 8
80070203B6 80070203B2	80/08/27	50-273 8	8009030353 8009030350 80/08/28 50-128 R
80070203B7 8007020378	80/08/20	50-320 8	8009030361 8009030349 80/08/25 50-320 8
80070203B8 80070203B1	80/08/18	50-237 8	8009030364 8009030359 80/08/27 TOPREP
8007020391 80070203B0	80/08/26	50-324 8	8009030373 8009030347 80/08/27 50-327 8
800702039A 8009020370	80/08/06	50-254 8	8007030375 8007030348 80/08/11 50-320 H
800702039B 8009020392	80/08/26	50-219 8	8007030386 8007030382 80/08/27 50-3 R
8007020401 8009020395	90/08/14	50-295 8	8007030379 8007030370 80/08/27 50-334 R
8007020403 8009020394	80/08/29	50-333 8	8007030401 8007030400 80/08/28 50-263 8
8007020405 8009020400	80/08/26	50-366 8	8007030411 8007030406 80/08/19 50-259 P
800702040B 8007020405	80/08/27	50-276 P	8009030414 8009030405 80/08/27 50-333 8
8007020412 8007020405	90/08/27	50-276 P	8009030417 8009030410 80/08/27 50-328 8
8007020414 8007020404	80/08/29	50-321 8	8009030419 8009030415 80/08/30 50-321 R
8007020416 8007020403	80/08/29	50-416 A	8009030429 8009030418 80/08/28 50-333 8
8007020422 8007020407	80/08/29	50-333 8	8009030425 8009030422 80/08/27 50-368 8
8009020423 8009020413	90/08/29	50-416 A	8007030428 8007030426 80/08/28 50-338 P 8007030427 8007030427 80/08/26 50-348 8 8007030433 8007030434 80/08/22 50-327 R 8007030438 8007030436 80/08/27 50-327 P 8007030440 8007030437 80/08/27 50-327 P
8009020427 8009020413	90/08/29	50-416 A	
8009020430 8009020413	80/08/29	50-416 A	
8009020433 8009020419	80/08/29	50-366 B	
8009020434 8009020413	80/08/29	50-416 A	
8009020438 8009020413	80/08/29	50-416 A	8009030444 8009030441 80/08/07 50-295 R
8009020441 8009020437	80/08/28	50-280 P	8009030446 8009030443 80/08/29 50-99 P
8009020444 8009020439	80/08/26	50-321 8	8009030447 8009030442 80/08/26 50-366 8
8009020445 8009020436	80/08/26	50-321 8	8009030449 8009030445 80/08/29 50-269 8
8009020445 8009020447	80/08/04	50-275 8	8009030452 8009030450 80/09/01 50-170 P
8009020457 8009020452 8009020458 8009020449 8009020462 8009020459 8009020463 8009020456 8009020467 8009020456	80/08/15 80/08/26 80/08/29 80/08/12 80/08/12	50-295 8 50-368 8 50-395 H 50-10 P	8009030453 B009030448 B0/0B/13 50-254 R 8009030457 B009030454 B0/0B/27 50-409 8 B009030461 B009030451 B0/0B/25 50-366 B B009030463 B009030459 B0/0B/27 50-261 B B009030465 B009030462 B0/0B/27 40-8452
8009020448 8009020459 8009020449 8009020441 8009020470 8009020454 8009020472 8009020455	80/08/29 80/08/12 80/08/12 80/08/11	50-395 M 50-321 B 50-10 P 50-289 H 50-10 P	8009030467 8009030486 80/08/20 50-10 R 8009030469 8009030464 80/08/08 50-289 V 8009030471 8009030466 80/08/29 50-331 8 8009030474 8009030468 80/08/29 50-270 8 8009030478 8009030472 80/08/21 50-289 P
8007020474 8009020454	80/08/12	50-10 P	8009030482 8009030475 80/08/29 50-302 8
8007020477 8009020454	80/07/14	50-348 Q	8009030483 8009030477 80/08/29 50-293 8
8007020481 8009020475	80/08/18	70-2319	8009030488 8009030479 80/08/29 50-285 R
8007020486 8009020478	80/08/20	XPDRTLIC	8009030489 8009030481 80/08/28 50-285 P
8009020494 8009020487	90/08/15	50-320 H	8009030495 8009030491 80/08/28 50-348 R
8009020499 8009020492	80/08/14	XPORTLIC	B009030494 B009030488 B0/0B/28 50-239 S 8009030501 B009030498 B0/0B/26 50-266 P 8009030603 B009030497 B0/0B/27 50-302 B 8009030513 B009030506 B0/0B/29 50-302 B 8009030513 B009030507 B0/0B/25 50-287 P
8009020504 8009020498	80/08/20	40-297	
8009020515 8009020502	80/08/15	50-320 K	
8009020525 8009020522	80/08/12	71-385	
8009020531 8009020529	80/08/15	RECOB	

ACCESSION	NUMBER				ACCESSIO				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 186UED	SUBJECT		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 168UEO	CATEOD	
8007030514 8007030516 8007030517 8007030522 8007030523	8007030508 8007030507 8007030507 8007030520 8007030517	80/08/29 80/08/14 80/08/25 80/08/29 80/08/27	50-260 50-237 50-287 50-317 50-327	P 8 P 8	8009040387 8009040389 8009040387 8009040391	8009040384 8008280311 8009040384 8009040384 8009040384	80/09/02 80/08/22 80/09/02 80/09/02 80/09/02	50-364 50-311 50-364 50-364 50-364	A F A A
8007030530 8007030534 8007030535 8007030538 8007030546	8007030528 8007030529 8007030525 8007030533 8007030537	80/08/25 80/08/22 80/08/28 80/08/27 80/08/27	50-27 50-320 50-280 50-206 50-348	R P B R B	8009040392 8009040393 8009040394 8009040394 8009040395	8008280311 8007040386 8008280311 8007040386 8008280311	80/08/22 80/09/02 80/09/02 80/09/22	50-311 50-364 50-311 50-364 50-311	F A F A
8007030547 8007030547 8007030561 8007030563 8007030566	8007030544 8007030543 8007030555 8007030556 8007030558	80/08/27 80/08/29 80/08/27 80/08/25 80/08/30	50-155 50-318 50-338 50-528 50-259	R 8 8 6 6	8009040398 8009040399 8009040402 8009040403 8009040403	8008280311 8008280311 8008280311 8008280311	80/08/55 80/08/55 80/08/55 80/08/55 80/08/55	50-311 50-311 50-311 50-311 50-311	4444
8007030569 8007030571 8007030572 8007030579 8007030586	8007030965 8007030967 8007030568 8007030575 8007030576	80/08/27 80/08/27 80/08/27 80/08/28 80/08/27	50-20 50-339 50-59 50-344 50-339	R S R R	8007040407 8007040408 8007040411 8007040411 8007040414	8008280311 8008280311 8008280311 8008280311 8009040413	80/08/22 80/08/22 80/08/22 80/08/22 80/09/03	50-311 50-311 50-311 50-311 50-244	F F F P
8007030570 8007030571 8007030574 8007030577 8007030604	8007030588 8007030585 8007030583 8007030574 8007030597	80/08/29 80/08/28 80/08/27 80/08/29 80/08/29	50-358 50-311 50-255 50-273 50-276	F 8 8 8 8	8007040415 8007040417 8007040443 8007040450 8007040450	8007040413 8007040418 8007040434 8007040434 8007040468	80/09/03 80/08/29 80/08/22 80/08/22 80/07/02	50-244 50-186 50-369 50-369 CONTRACT	P S A A
8007030607 8007030608 8007030607 8007030614 8007030617	8007030603 8007030593 8007030600 8007030606 8007030611	80/08/27 80/08/27 80/08/29 80/08/27 80/08/29	50-293 50-339 50-332 50-338 50-293	88888	8007040474 8007040475 8007040485 8007040487 8007040507	8007040472 8007040473 8007040472 8007040484 8007040506	80/08/15 80/06/05 80/08/15 80/08/22 80/08/19	50-397 70-1257 50-397 50-553 50-267	G G A P
8007030418 8007030619 8007030420 8007030423 8007030427	8007030616 8007030615 8007030613 8007030612 8007030624	60/08/20 80/08/27 80/08/28 80/08/29 60/08/27	50-247 50-339 50-311 50-338 50-255	P 8 8 0	8009040513 8009040544 8009050087 8009050105 8009050126	9007040506 9007040532 9007050086 9007050103 8007050123	80/08/19 80/08/08 80/09/03 80/08/29 80/08/05	50-267 50-271 50-349 50-336 FOIA	P O P
8007030628 8007030632 8007030637 8007030640 8007030643	8007030622 8007030629 8007030634 8007030628 8007030638	80/08/28 80/08/27 80/08/27 80/08/27 80/08/12	50-368 50-338 50-206 50-267 PR	8 8 8	8007050131 8007050174 8007050176 8007050184 8007050190	8007050123 8007050168 8007050173 8007050180 8007050187	80/08/05 80/08/14 80/08/12 80/08/97 80/08/20	FOIA 70-143 70-1151 70-143 50-298	s
8007030644 8007030646 8007030647 8007030647 8007030650	8007030634 8007030641 8007030638 8007030642 8007030648	80/08/27 80/08/27 80/08/12 80/08/27 80/08/19	50-206 50-213 PR 50-338 ACRS	P P 8	8007050196 8007050201 8007050203 8007050204 8007050207	8007050172 8007050172 8007050177 8007050172 8007050205	80/08/18 80/08/18 80/08/22 80/08/16 80/08/05	50-339 50-339 50-298 50-339 71-9508	P P B
8007030658 8007030664 8007030666 8007030667 8007030680	8007030453 8007030462 8007030462 8007030467 8007030678	80/09/02 80/09/02 80/09/02 80/08/15 80/08/11	50-33B 50-327 50-327 NUREQ 50-287	8 P P	8009050211 8009050214 8009050215 8009050217 8009050219	8009050208 8009050205 8009050208 8009050210 8009050210	80/07/17 80/08/05 80/07/17 80/08/14 80/08/14	50-255 71-9509 50-255 50-278 50-278	Q Q P P
8007030483 8007030671 8007030478 8007030478 8007030728	8007030681 8007030688 8007030688 8007030677 8007030726	80/08/11 80/08/07 80/08/07 80/07/29 80/08/28	50-287 50-263 50-263 XPDRTLIC 50-282	H F O	8007050221 8007050241 8007050245 8007050246 8007050247	8009050210 8009050240 8009050243 8009050243 8009050243	80/08/14 80/08/11 80/09/02 80/09/02 80/09/02	50-278 50-312 50-320 50-320 50-320	P B B B
8007040049 8007040068 8007040083 8007040079 8007040103	8007040037 8007040055 8007040077 8007040087 8009040088	80/08/12 80/07/16 80/08/14 80/07/17 80/08/12	50~313 27-39 50-277 40-2061 50~155	Gt F P	8007050247 8007050254 8007050255 8007050264 8007050268	8009050243 8009050250 8009050252 8009050260 8009050265	80/09/02 80/08/18 80/08/11 80/09/02	50-320 50-334 50-298 50-302	8 8 8 8
8007040104 8007040107 8007040127 8007040180 8007040208	8007040087 8007040087 8007040125 8007040176 8007040200	80/07/17 80/07/17 80/08/08 80/08/11 80/08/27	40-2061 40-2061 50-263 50-296 50-237	P P O	8007050278 8007050281 8007050287 8007050287 8007050300	8007050274 8007050275 8007050284 8007050270 8007050277	80/08/22 80/08/22 80/08/21 80/08/29 80/09/02	50-244 50-289 50-298 50-272 50-488	V P B R Q
8009040218 8009040251 8009040256 8009040269 8009040274	8007040200 8007040246 8007040255 8007040262 8007040262	80/08/27 80/09/02 80/08/29 80/08/29 80/08/29	50-237 50-364 50-70 50-155 50-155	G A P G	6007050303 600705030B 6007050322 6007050324 8007050328	8007050297 8007050302 8007050318 8007050321 8007050325	80/09/02 80/09/03 80/09/02 80/09/20 80/08/25	50-488 50-341 50-271 50-133 TOPREP	O A B V
8009040305 8009040315 8009040330 8009040374 8009040375	8007040277 8007040307 8007040317 8008280311 8008280311	80/08/08 80/08/08 80/07/14 80/08/22 80/08/22	50-266 50-324 50-327 50-311 50-311	P 0 F F	8009050331 8009030335 8009050335 8009050355 8009050335	8009050326 8009050329 8009050339 8009050348 8009050352	80/08/12 80/09/02 80/08/15 80/08/29 80/08/29	50-278 50-338 50-312 50-263 50-414	S R R R
8007040378 8007040379 8007040381 8007040384 8007040385	8008280311 8008280311 8008280311	80/08/22 80/08/22 80/08/22 80/08/22	50-318 50-318 50-318 50-318 50-318	4444	8007050345 8007050376 8007050391 8007050402 8007050412	8009050363 8009050367 8009050386 8009050383 8009050383	60/07/31 60/08/08 60/08/14 80/08/07 80/08/07	TOPREP 50-320 50-320 FOIA FOIA	P H

ACCESSION NUMBER

PRINCIPAL

					ACCESS	ION NUMBER			
ENCLOSURE				OURY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBL	EGT GORY
800905041: 800905041: 800905041: 800905042:	7 800905041 B 800905038 9 800905041 1 800905041 6 800905042	4 80/08/2 3 80/08/0 4 80/08/2 5 80/07/2 4 80/08/1	71-90 7 50-39 1 71-90 5 50-36 5 50-26	19 5 A 19 4 G 6 H	800708087: 800709002: 8007070046 8007070058 8007070065	6 8009090022 8009090041 8009090041 8009090041	80/07/31 80/08/20 80/08/01 80/08/01	COMET	H 91
8009050431 8009050432 8009050444 8009050445	5 800905042 1 800905042 5 800905044 5 800905044	2 80/08/2 2 80/08/2 2 80/08/0 5 80/08/1	2 50-280 2 50-280 8 XPORTL 1 FOIA	0 Q	8007070066 8007070119 8007070181 8007070181 8007070184	8007070116 8007070145 8007070165 8007070165	80/08/14 80/07/28 80/07/28	50-21 50-21 50-21	4 Q 9 Q
8007050458 8007050468 8007050464 8007050467 8007050470	8009050446 8009050466 8009050466 B009050466	5 80/08/1: 5 80/07/2: 5 80/07/1/ 0 80/07/2:	F01A 5 50-315 5 50-267 5 50-315	е О Р	8009090159 8009090208 8009090215 8009090216	8007070202 8007070202	90/08/12 80/08/12 80/07/15	50-214 XPDRTI XPDRTI 50-264 50-35	LIC F H
8009050471 8009050477 8009050486 8009050498 8009050501	8007050465 8007050465 8007050476 8007050477	80/07/14 2 80/07/16 5 80/08/14 7 80/08/14	50-267 50-410 50-320 50-29	G H F	8007070229 8007070232 <i>90070702</i> 4 8007070250 8007070258	8009090222 8009090222 8009090237 8009090234	80/08/05 80/07/31 80/07/31 80/07/31	50-353 50-353 50-289 50-289 50-461	2 0
8009030504 8009030507 8009050307 8009050310 8009050516	8007050500 8007050500 8007050505 8007050505	0 80/08/11 0 60/09/11 0/80/08 10/80/08	50-155 50-155 50-281 50-281		8007090257 <i>80090070267</i> 8009090268 8009090287 8009090287	8009090253 8009090261 8009090265 8009090273 8009090282	80/07/21 80/09/01 80/09/04 80/09/05 80/09/05	50-553 50-293 50-204 50-305 50-263	R
8007050517 8007050522 8007050531 8007050533 8007050534	8009050517 8009050528 8009050525 8009050528	80/08/05 80/08/08 80/07/[6 80/08/08	50-498 50-295	P Q P Q	8007070278 8009070302 8009070306 9007070308 8007070311	8007070294 8007070297 8007070270 8007070303 8007070270	80/09/05 80/08/28 80/09/03 80/09/05 80/09/03	50-295 50-262 50-233 50-233 50-230	R H R
800903053B 8009050547 8009050550 8009080045 8009080053	8009050528 8009050545 8009050545 8009080036 8009080036	80\08\13 80\08\15 80\08\12 80\08\13	50-275 50-347 50-349 PR PR	Q Q	8007070319 8009070320 8009070328 8009070333	8007070680 8007070315 8007070680 8007070314 8007070330	60/08/08 80/08/29 80/08/08 80/09/04 80/08/08	50-397 50-311 50-397 50-296 50-339	K R K B
8009080197 8009080209 8009080211 8009080233 8009080238	8007080231 8007080202 8007080203 8007080231	80/08/29 80/08/29 80/08/29 80/08/08 80/08/08	50-461 50-461 50-461 50-332 50-332	A C C G	8007070341 8007070342 8007070343 8007070347 8007070348	8007070332 8007070337 8007070338 8007070344 8007070337	80/09/05 80/08/12 80/08/11 80/08/28 80/08/12	50-296 50-247 50-339 50-338 FOIA	8 0 0 P
8009080261 8009080270 8009080299 8009080319 8009080325	8009080251 8009080266 8009080294 8009080317 8009080323	80/08/05 80/09/18 80/07/25 80/08/21 80/08/29	FOIA 50-333 50-346 50-346 50-286	G P R	8007070347 8007070352 8007070358 8007070361 8007070363	6007070346 6007070344 6007070355 6007070357 8007070337	80/08/08 80/08/28 80/09/04 80/09/03 80/08/12	50-339 50-338 50-305 50-333 50-247	Р Р Р
8007680324 8007080334 8007080335 8007080336 8007080341	6004080338 8004080333 8004080333 8004080333	80/09/08 80/09/04 80/09/04 80/09/04 80/09/02	50-206 50 133 50-133 50-133 50-254	P R R R	8009090365 9009090371 8009090373 8009090376 8009090381	8007070351 8007070368 8007070383 8007070367 8007070354	80/08/28 80/09/02 80/09/02 80/09/05 80/08/14	719-08 912-08 912-08 912-08	9 R 9 8
8007080342 8007080352 8007080354 8007080366 8007080367	80090B0340 8009080350 8009080354 E009080351 8009080360	80/08/29 80/09/02 80/09/02 80/09/02 80/08/29	50-277 50-317 50-327 50-281 50-327	R F S 8	8007070382 8007070385 8007070388 8007070378 8007070401	6007070377 8007070378 8007070354 8007070372 8007070387	80/09/04 80/09/03 80/09/05 80/09/08 80/08/26	50-244 50-368 50-282 50-528 50-293	P 8 6 C 8
8007080380 8007080381 8007080391 8007080401 8007080407	8007080373 8007080375 8007080382 8007080375 8007080378	80/08/29 80/08/28 80/09/02 80/09/02	50-327 50-27] 50-327 50-306 50-265	8 9 8 8	8007070403 8007070412 8007070418 8007070426 8007070423	8007070397 8007070405 8007070414 8007070422 8007070428	80/09/03 80/09/04 80/08/29 80/09/02 80/08/29	50-123 50-334 50-327 50-293 50-313	P P R S
8009080414 8009080417 8009080423 8009080426 8009080427	8007080406 8007080412 8007080417 8007080418 8007080422	80/09/02 80/06/13 80/09/04 80/09/02 80/08/19	50-255 50-265 50-327 50-255 50-254	8 8 8	8007090433 8007070438 8007070441 800970445 8007070456	8007070430 8007070428 8007070437 8007070447	80/07/02 80/07/04 80/07/04 80/08/28 80/09/04	50-293 50-366 50-311 50-311 50-321	6 8 8
8009080438 800 9 080445 8009080457	8009080454	80/09/02 80/08/28 80/08/15 80/08/19 80/08/06		8 P	8009090462 8009090474 8009090477 8009090480 8009090481	8007070445 8007070458 8007070468 8007070467 8007070467	80/09/04 80/09/05 80/08/29 80/09/02 80/08/29	50-260 50-155 50-307 50-321 50-260	8 8 8 8
8009080475 8009080478	8009080472 8009080474	80/07/09 80/08/20 80/08/11	0A999 40-3453 50-164 <i>40-3453</i> 40-3453	Pi		8007070471 8007070482 8007070486 8007070504	80/09/03 80/09/05 80/09/04 80/08/29	50-295 50-313 50-364 70-143 50-315	P
			50-278 50-278	0 0 0	809909511 8009090512 8009090517	8009090490 8009090500 8009090499 8009090505	80/09/05 80/09/05 80/09/03 80/09/05	50-240 50-329 50-338 50-285 50-275	8 8 8 8 K

ACCESSION NUMBER

ACCESSIO	M NUMBER				ACCESSIO	N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJECT CATEGOR	Y	ENGLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJECT CATEOOR	
8007070526 8007070536 8007070537 8007070540 8007070543	8007070514 8007070525 8007070532 8007070535 8007070537	80/09/03 80/08/27 80/08/29 80/09/04 80/08/29	50-275 50-285 50-458 50-271 50-266	KBFRR	#009100116 #009100119 #009100120 #009100122 #009100122	009100111 00910004 009100111 00100111 00100111	60/08/22 60/08/14 60/07/07 80/08/22 60/08/22	COMMISSI XPORTLIC 50-440 COMMISSI COMMISSI	Q ON
8007070350 8007070358 8007070360 8007070363 8007070363	8007070542 8007070554 8007070555 8007070543 8007070557	80/08/28 80/08/28 80/09/03 80/09/04 80/09/04	50-311 50-311 50-259 50-259 50-259	8 P I S	8007100126 8007100128 8007100131 8007100134 8007100140	8009100118 8009100111 8009100132 8009100132	80/07/09 80/08/22 80/08/14 80/07/21 80/07/21	50-440 CEMHISSI XPORTLIC 50-255 50-255	
8007070568 8007070580 8007070582 8007090583 8007090584	8007090562 8007090574 8009090577 8009090527 8009090538	80/09/03 80/09/02 80/09/03 80/09/03 80/09/05	50-313 50-546 50-269 50-327 50-339	8 # 8 8	8009100145 8009100148 8009100149 8009100151 8009100155	8009100130 8009100143 8009100130 8009100145 8009100154	80/05/23 80/07/23 80/05/23 80/08/23 80/07/24	50-389 50-10 50-389 50-320 50-331	0 0 0 P
8007070586 8007070588 8007070587 8007070570 8007070571	8007070341 8009070331 8007070378 8007070347 8007070587	80/09/05 80/09/03 80/09/02 80/08/28 80/09/04	50-338 50-327 50-272 50-327 50-272	888888	181001900B 171001900B 171001900B 171001900B 171001900B	8007100154 8007100172 8007100188 8007100187 8007100188	80/07/24 80/09/08 80/06/18 80/06/12 80/06/18	50-331 50-346 40-6659 70-1143 40-6659	G P
8007070575 8007070604 8007070607 8007070608 8007070611	8007070573 8007070592 8007070601 8007070602 8007070592	80/08/28 80/07/30 80/07/30 80/08/26 80/07/30	50-272 50-320 COMMIBBIO 50-289 50-320	9 1 1 9	8007100205 8007100212 8007100217 8007100219 8007100222	8009100188 8009100188 8009100188 8009100208 8009100188	80/06/18 80/06/18 80/06/18 80/08/22 80/06/18	40-6659 40-6659 40-6659 GAYP9 40-6659	
8009090619 6009090624 8009090627 8009090633	8009090614 8009090624 8009090621 8009090614 8009090621	80/07/31 80/08/28 80/08/25 80/07/31 80/08/25	XPORTL1C	0	8009100223 8009100227 8009100231 8009100235 8009100238	8009100208 8009100208 8009100208 8009100232 8009100232	80/09/22 80/09/22 80/08/22 80/08/14 80/08/14	QA999 QA999 QA999 70-1257 70-1257	
B007070634 B007070635 B007070642 B007070648 B007070651	8007070614 8007070621 8007070636 8007070644 8007070637	80/07/31 80/08/25 80/09/04 80/07/21 80/08/14	50-245	e P Q N	8009100242 8009100250 8009100258 8009100262 8009100273	8009100239 8009100241 8009100241 8009100252 8009100269	90/07/02 80/08/22 80/08/22 80/07/05 80/07/31	50-344 50-400 50-400 50-280 50-445	R G G S
8007070654 8007070655 8007070656 8007070662 8007070664	8007070630 8007070637 8007070632 8007070639 8007070632	80/08/01 80/08/14 80/09/05 80/08/14 80/09/05	COMM18910 50-275 COMM18910	T	8009100275 8009100279 8009100297 8009100300 8009100307	8009100248 8009100269 8009100290 8009100237 8009100237	80/08/26 80/07/31 80/08/20 80/08/22 80/08/22	50-333 50-445 70-1113 50-364 50-364	R Q Q
8009090672 8009090769 8009090775 8009090786 8009090788	800707052 8007070768 8007070773 8007070785 8007070784	80/09/05 80/08/29 80/08/27 80/08/08 80/09/05	WASTE MOT 50-286 50-280	T F O	8009100389 8009100392 8009100395 8009100399 8009100409	8007100384 8007100384 8007100384 8007100384 8007100405	60/08/11 60/08/11 60/08/11 60/08/11 60/08/22	50-334 50-334 50-334 50-334 CONTRACT	G G G
8009090775 800909070813 8009090848 8009100003	8007070791 8007070791 8007070812 8007070844 8007100002	80/09/05 80/09/05 80/07/16 80/08/20 80/08/22	50-367 50-312	9	8009100483 8009100461 8009100463 8009100463 8009100505	8009100449 8009100449 8009100449 8009100500	80/07/05 80/07/05 80/08/27 80/07/05 80/07/03	50-344 50-344 50-275 50-344 50-282	6 8 H 5 0
8009100012 8009100024 8009100025 8009100026 8009100028	8009100010 6009100021 8009100022 8009100022	80/08/08 80/08/03 80/08/03 80/08/03 80/08/03	50-352 (T 0 0	8007100548 8007100617 8007100638 8007100638 8007100641	8007100532 8007100607 8007100632 8007100631 8007100631	80/09/05 80/09/04 80/06/20 80/08/28 80/08/28	TOPREP 50-334 M18C 50-247 50-247	P P
8009100030 8009100038 8009100041 8009100044 8009100052	8007100022 8007100037 8007100035 8007100034 8007100047	80/08/03 80/07/09 80/08/11 80/07/08 80/06/19	50-273 (CONTRACT 50-217 (3 3 3	8007100645 8007100646 8007100647 8007100657 8007100652	8009100631 8009100642 8009100634 8009100634 8009100642	80/08/28 80/08/13 80/08/14 80/08/14 80/08/13	50-247 70-371 70-312 70-312 70-371	P
8009100055 8009100057 8009100059 8009100061 8009100072	8009100033 8009100033 8009100047 8009100054 8009100067	80/07/16 80/07/16 90/06/19 80/08/18 80/06/30	50-267 (50-267 (50-482 (CONTRACT 27-47	3	8007100653 8007100657 8007100675 8007100677 8009100745	8007100650 8007100654 8007100673 8007100674 8007100741	80/08/28 80/08/28 80/07/31 80/07/07 80/08/18	50-182 40-4452 50-280 50-298 70-754	P Q
8009100074 8009100076 8009100077 8009100078 8009100080	8007100068 8007100067 8007100071 8007100073 8007100070	80/08/14 80/06/30 80/05/01 E0/08/20 80/08/19	50-289 } 27-47 CONTRACT 50-352 U 50-483 E		800910074B 8009100795 8009100807 8009100811 8009100813	8009100741 8009100790 8009100801 8009100801 8009100801	80/08/18 80/08/24 80/08/24 80/08/24	70-754 70-27 50-269 50-269 50-269	0 0 0
8009100091 8009100093 8009100097 8009100101 8009100102	8009100085 8009100086 8009100094 8009100098 8009100098	80/08/23 80/08/20 80/08/19 80/08/14 80/08/20	50-87 (COMMISSION State Prog XPORTLIC COMMISSION	1	8007100816 8007100830 8007100833 8007100841 8007100844	8009100801 8009100824 8009100826 8009100836 8009100842	80/08/26 80/08/28 80/08/28 80/08/25 80/08/13	50-269 50-461 50-461 50-267 50-278	0 0 0
8007100107 8007100108 8007100110 8007100112 8007100114	8009100098 8009100098 8009100104 8009100105 8009100111	80/08/20 80/08/20 80/08/19 80/08/15 80/08/22	COMMISSION COMMISSION 50-316 F 50-440 C COMMISSION	3	B007100853 B007100861 B007100870 B007100877 B007100884	8009100847 8009100857 8009100865 8009100874 8009100881	80/07/18 80/07/25 80/07/25 80/07/23 80/07/21	50-247 50-277 50-412 50-273 50-352	0 0 0

ACCESSION NUMBER

					ACCESSION	NONDEN			
ACCESSION		DATE	EUBJECT		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 1990ED	BUDJECT CATEGORY	
ENCLOSURE	DOCUMENT BOOG 100889	188UED 80/07/21	JU JU.	!	8009110379 8009110381	8009110375 8009110378	80/07/31 80/09/08	CONTRACT	- P
8007100893 8009100899 8009100906 8009100910 8009100914	8009100895 8009100902 8009100902 8009100902	80/07/21 80/08/14 80/08/14 80/08/14	50-289 70-143 70-143 70-143		8009110393 8009110399 8009110404	8009110391 8009110396 8009110402	80/09/03 80/09/03 80/08/29	40-2259	0
6007100720	8009100917	80/08/07 80/08/08	ACRS CONTRACT		8009110407 8009110410	8009110402 8009110409	80/08/29 80/08/25 80/08/13	40-2259 CONTRACT	
8009110002 8009110003 8009110004 8009110005	8009110001 8009110001 8009110001	80\08\08 80\08\08 80\08\08	CONTRACT CONTRACT CONTRACT		8009110413 8009110414 8009110418	8009110408 8009110401 8009110417	80/08/01 80/07/29	COMMISSIO	B
8009110025	B009110022	80/07/28 80/08/14	CONTRACT 50-348	•	8009110422 8009110424	B009110415 B009110415	80/08/20 80/08/20 80/08/13	50-460	a a a
8007110031 8007110033 8007110035 8007110044	8009110030 8009110030 8009110030 8009110034	80/08/14 80/08/14 80/09/03	50~349 50-349		8009110425 8009110426 8009110427	8009110423 8009110415 8009110423	80/08/20 80/08/13	30-460 50-413	Q
B009110050	8009110047 8009110056	80/07/25 80/08/26			8007110427 8007110433	8007110415 8007110431 8007110436	80/08/20 80/09/08 80/08/26		P
8009110061 8009110066 8009110135 8009110139	8009110056 8009110122 8009110122	80/08/26 80/08/27 80/08/27	50-397 70-1151 70-1151		8009110443 8009110491 8009110502	8009110495 8009110497	80/08/25 80/08/25	50-320 XPORTLIC	U
8009110142 8009110150	8009110122 8009110125	80/08/27 80/08/27	70-1151 70-1113		8007110516 8007110518 8007110520	8007110512 8007110507 8007110514	80/08/19 80/07/30 80/08/21	50-219	P G U
8009110153 8009110154 8009110161	8009110126 8009110126 8009110125	80/08/27 80/08/27 80/08/27	70-1113 70-1113 70-1113		8007110533 8007110581	8009110527 8009110575	80/09/08 80/07/29	FOIA 50-255	P
B009110166 B009110169	8009110121 8009110121	80/08/27 80/09/27	50-250		8007110583 8007110584	8009110552 8009110579 8009110492	80/08/28 80/08/18 80/08/25		F
8009110173 8009110177 8009110181	8009110121 8009110111 8009110118	80/08/27 80/07/29 80/08/27	50-518		8009110587 8009110589 8009110594	8009110575 8009110575	80/07/27 80/07/29	50-255	P
9009110198 8009110191	900911011B 800911011B	80/09/27 80/08/27			8009110596 8009110597	8009110592 8009110595	80/08/25 80/08/24	XPORTLIC 71-109	
8009110199 8009110202 8009110208	8009110107 8009110102 8009110099	80/07/29 80/07/29 80/07/29	50-395		8009110618 8009110627 8009110635	8009110613 8009110620 8009110632	00/06/30 00/07/22 00/08/08	6A999 50-282 XPORTLIC	Œ
8009110214 8009110222	8009110489 8009110215	80/09/03 80/07/28	XPORTL 1C		8009110652 8009110656	8009110648 8009110655	80/08/04 80/07/25	50-358	R
8009110246 6009110249 8009110252	8009110227 8009110223 8009110221	80/07/15 80/06/26 80/06/25	70-754 70-820 70-820		8009110661 8009110675 8009110692	8009110655 8009110665 8009110684	80/07/25 80/08/15 80/07/10	50-454	Q Q
8009110256 8009110269	8009110253 8009110263	80/08/19 80/08/19	CONTRACT 70-135		8007110730 8007110737	8009110727 8009110732	80/08/20 80/08/20	50-284	đ Q
8009110272 8009110274 8009110276	8009110262 8009110262 8009110263	80/08/19 80/08/05 80/08/05	70-135 70-135 70-135		8009110759 8009110769 8009110774	8007110750 8007110764 8007110770	80/07/31 80/08/23	71-9009 50-544 40-299	a
8009110281 8009110285	8009110262 8009110259	80/08/05 80/08/22	70-135 50-271	•	8009110777 8009110820	8009110773 8009110817	80/08/20	50-155	P Q
8009110287 8009110288 8009110298	8009110259 8009110260 8009110259	80/08/22 80/08/24 80/08/22	50-271 50-320		8009110828 8009110831 8009110835	8009110924 8009110927 8009110927	80/08/25 80/06/25 80/06/25	50-32 (40-4826 40-4826	a
8009110295 8009110298	8007110286 8007110257	80/09/04 80/08/07		1	6007110857 6007120007	8009110856 8009120004	80/09/04 80/09/03	50-502 CONTRACT	A
8009110299 8009110301 8009110302	8009110297 8009110257 8009110286	80/08/07 80/08/07 80/09/04			8009120012 8009120014 8009120019	8009120010 8009120013 8009120017	80/08/27 80/08/15 80/08/01	CONTRACT CONTRACT CONTRACT	
8009110303 8009110304	8009110257 8009110297	80/08/07 80/08/07			E009120033 8009120037	8007120023 8007120028	80/08/28 80/08/18	CONTRACT	
8009110306 8009110313 8009110318	8009110257 8009110307 8009110316	80/08/07 80/07/10 80/09/05	50-454		8007120048 8007120052 8007120061	8007120037 8007120045 8007120037	80/07/23 80/08/08 80/07/23	50-348	P Q P
6009110319 8009110322	E009110314 E009110314	80/08/26 80/08/26			800912006B 8009120071	8009120039 8009120045	80/07/25 80/08/08		p Q
8009110324 8009110330 8009110333	8009110307 8009110328 8009110316	80/07/10 80/09/09 80/09/05	50-320		8009120075 8009120083 8009120115	8009120068 8009120070 8009120104	80/09/03 80/07/21 80/08/18	CONTRACT CONTRACT CONTRACT	
8009110334 8009110338	8009110329 8009110331	80/09/09 80/08/25	50-29 CONTRACT	3	8009120123 8009120126	8007120120 8007120124	80/08/01 80/08/20	50-322 70-143	8
8009110340 8009110341 8009110342	8009110316 8009110332 8009110337	80/09/05 80/09/20 80/09/08	50-289 50-327		8007120130 8007120133 8007120137	8009120124 8009120124 8009120125	80/08/20 80/08/20 80/08/20	70-143 70-143 27-49	
8009110343 8009110344	8009110332 8009110316	80/08/20 80/09/05			8009120141 8009120144	8007120135 8007120125	80/07/21 80/08/20	50~416 27~48	q
8009110347 8009110348 8009110350	8007110335 8007110326 8007110346	80/09/04 80/09/05 80/08/22	FOIA	· }	8007120156 8007120210 8007120220	8007120125 8007120175 8007120201	80/03/20 80/07/08 80/07/31	27-48	œ
8009110351 8009110353	8009110335 8009110352	80/09/04 80/08/29	F01A 50-259	!	B009120222	8009120201 8009120201	80/07/31 80/07/31	40~2740 40~2740	
8009110355 8009110358 8009110360	8009110349 8009110349 8009110349	80/09/03 80/09/03 80/09/03	50-327 50-327		8007120224 8007120227 8007120225	8009120147 8009120147 8009120150	80/08/18 80/08/18 80/07/11	70-143 70-143 70-371	

ACCE8910					ACCESSIO	N NUMBER		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 1980ED	GUDJEC1 CATEGOS	łY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJECT CATEGORY
8007120240 8007120247	8009120143 8009120245	80/07/22 80/09/05	50-416 50-296	Q	8009120604	8009120601	80/06/05	50-201 R
8007120271 8007120271	E007120262 E007120272	80/08/27 80/08/05	50-370 50-528	a 0	8007120614 8007120616 8007120622	8009120611 8009120609 8009120609	80/06/03 80/09/02	70-25B 50-460 B
8007120309	6009120304	80/08/12	50-460	Q	8004150951	8009120624	80/08/57	SO-460 G XPDRTLIC
8007120315 8007120316	8009120313 8009120312 8009120301	80/09/02 80/09/02 80/09/08	50-251 50-335 50-327	8	8009120531 8009120548	8009120609 8009120645	80/09/02	50-440 G 50-289 P
8007120317 8007120318 8007120320	8009120307 8009120305	80\03\03 80\03\03	50-327 50-335 50-275	8	8009120450 8009120453	8009120445 8009120445	80/09/02 80/09/02	50-287 P
8009120324	8009120302	80/08/29	50-275	8	8009120457 8009120460	8009120454 8009120451	80/07/10 80/09/04	0A779 50-387 A
8009120331	8009120299 8009120334	80/07/09	50~275 GA999	8	6009120862 6009150004	B009120459 B009150002	80/08/27	50-387 A CONTRACT FOIA
8009120342 8009120348	8009120341 8009120344	80/07/09 80/07/08	50-289 50-317	8 5	8007150005 8007150018	B009150002 B009150016	80/08/25 80/08/25	FOIA 50-438 A
8009120356 8009120363	8009120351	80/09/10 80/09/02	50-346 TOPREP	S	80091 50021 80091 50024	8009150017	80/07/11	04999
8009120365 8009120371	8009120359	80/07/09	50-333 50-325	8 8	8009150025 8009150026	8007150022 8007150022 8007150020	80/07/24 80/07/24 80/08/18	50-373 0 50-373 0 COMMISSION
8009120372	8009120357	80/09/04	50-272	8	B009150030	8009150020	80/09/18	COMMISSION
8007120374 8007120378	6007120368 6007120354	80/09/10	PR 50-317	s	8004120035 8004120035	8009150020 8009150020	80/08/18 81/80/08	COMMISSION
8009120379 8009120381 8009120382	8007120368 8007120353 8007120375	80/09/10 80/09/05 80/09/04	PR 50~247 50~272	8 8	8009150039 8009150043	8009150020 8009150037	80/08/18	50-354 B
8007120385	8007120350	80/09/02	50-250	5	8009130044 8009150047	8009150020 8009150020	80/08/18	50-271 U COMMISSION
8009120384 8009120388	8007120377 8007120384	80/09/04 80/09/08	50-334 50-255	8	8009150050 8009150051	8009150045 8009150045	80/08/29	50-445 Q 50-445 Q
B009120399 B009120405	8009120391 8009120401	80/08/25 80/09/05	50-254 50-271	թ	8009150052 8009150054	8009130020 8009130020	80/09/1B	COMMISSION COMMISSION
8009120406 8140217008	8009120402 8009120408	90/09/08 90/09/05	50-320 50-220	8	8009150055 8009150056	8009150045	80/08/29	50-445 0
8009120415 8009120417	8007120410 8007120410	80/09/08 80/09/08	50~333 50~220	8	5009150057 5009150050	8009150020 8009150045 8009150045	80/08/18 80/08/29	COMMISSION 50-445 0 50-445 0
2007120419	8009120349	80/09/08	50-133	ġ	8009120041	E005120050	80/08/18	COMMISSION
8009120428 8009120431	8009120424 8009120418	80/09/04 80/09/04	50~272 50~270	8	8009150063 8009150064	£009150045 £009150020	80/08/18	50-445 Q Commission
8007120436 8007120440	8009120414 8009120412	80/09/05 80/09/04	50-249 50-327	8	900116009 800016009	8009150045 8009150045	60/08/29 60/08/29	50-445 Q 50-445 Q
B009120443 B009120445	8009120411	80/09/04	50-327 50-347	B 0	8009150069 8009150071	800715002¢ 8007150045	80/08/18 80/08/29	COMMISSION 50-445 O
8009120451 8009120452	8009120449 8009120450	80/09/08	50-320 50-320	8	8009130074 8009150075	8009150020 8009150045	80/08/18 80/08/29	50-293 U 50-445 Q
8009120455 8009120462	8009120447 8009120457	80/09/05 80/09/05	50-317 50-255	8 R	8009150077 8009150079	8009150045 8009150070	80/08/29 80/07/21	50-445 0 50-269 P
8007120466	8009120459 8009120459	80/09/04 80/09/04	50-326 50-326	a G	8009150080 8009150081	8007150045 8007150020	80/08/27 80/08/18	50-445 0 50-273 U
6009120470 6009120471 6009120472	8009120459 8009120459	80/09/04 80/09/07	50-326 50-327	ā	20001150083 200115008	8007150020 8007150020	80/08/18 80/08/18	50-445 0 50-293 U
8009120474	8007120459	80/09/04	20-356	ã	80091500B7	8009150045	80/08/29	50-445 0
8009120476 8009120478	8009120459 8009120459	80/09/04 80/09/04	20-359 20-359	a	B004120088 8004120088	8009150082 8009150084	B0/07/14 B0/08/15	50-245 Q 50-250 Q
8009120479 8009120480	8009120475 8009120477	80/08/12 80/08/12	50-341 COMMISSI COMMISSI		800713007 <i>0</i> 6007130071 6007130073	E007150020 B007150045 B007150045	80/08/18 80/08/29	COMMISSION 50-445 0
8007120483	8009120477 8009120477	80/08/22	COMMISSI		8007150074	8007150045	80/08/29 80/08/18	50-445 O 50-201 U
8009120485	B009120477 B009120477	80/08/22	I BEIMMOD	QN	9007150075 9007150076	8007150084 8007150045	80/08/15	50-250 Q 50-445 Q
8009120490 8009120491	8009120487 8009120486	80/08/14 80/08/25	50-312 50-250	G G	8009150097 8009150098	8009150092 8009150020	80/07/17 80/08/18	50-410 0 50-201 U
8009120494	8009120477	80/08/22	COMMISSI 50-250	ON G	8007150100 8007150102	6009150045 6009150045	80/08/29	50-445 0
6009120495 6009120497 6009120499	8009120486 8009120486 8009120486	80/08/25 80/08/25 80/08/25	50-250 50-250	Q G	8007180105 8007180107	8009150045 8009150020	60/08/27 80/08/29 60/08/18	50-445 Q 50-445 Q 50-201 U
8007120500	8007120474	80/08/12	50-528	ā	8004130103	8007150104	80/08/22	50-311 P
8009120509 8009120514	8009120505 8009120505	80/08/01 80/04/01	50~155 50-206	P	8009150112 8009150112	8007150104 8007150020	80/08/22 80/08/18	50-311 P 50-201 U
8009120520 8009120526	8009120515 8009120515	80/08/25 80/08/25	50-250 50-250 50-250	0 0	8009150113 8009180114 8009180114	8009150045 8009150104	80/08/29 80/08/22	50-445 0 50-31: P
6009120531 8009120535	8007120515 8007120515	80/08/25 80/08/25	50-250	a	8007150115 8007150116	8009150104 8009150045	80/07/25 B0/08/29	50-302 Q 50-445 Q
8007120535 8007120535 8007120537	8007120525	90/08/14 80/08/25	70-343 50-250	a	8007150118 8007150120	8007150020 8009150045	80/08/18 80/08/29	50-201 U 50-445 0
8009120542 8009120548	8009120525 8009120525	80/08/14 80/08/14	70-343 70-343		8004120155 8004120151	8009150020 8009150045	80/08/18 80/08/29	50-201 U 50-445 0
8009120549	8009120545	80/07/10	50-201 40-1341	P	8009150123	8009150117	80/08/29	40-8743
9009120565 9009120586 9009120589	8009120562 8009120582 8009120582	80/08/27 80/08/28 80/08/28	FQIA 50-320	Р	8009150124 8009150125 8009150127	8009150119 8009150045 8009150020	80/07/14 80/08/29 80/08/18	50-219 G 50-445 G 50-201 U
8007120597	8007120571	80/09/02	FOIA		8007150129	9009150045	80/08/29	50-445 0

ACCE6810	N NUMBER					CCESSION				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 168UED	CATEQO			OSURE	PRINCIPAL DOCUMENT	DATE 1880ED	SUBJECT CATEODRY	,
8009150132 8009150133 8009150136 8009150137 8009150138	8009150020 8009150045 8009150045 8009150130 8009150020	80/08/18 80/08/29 80/08/29 80/07/18 80/08/18	50-201 50-445 50-445 50-271 50-201	20000	1900B 1900B 1900B	150355 150356 150357 150358 150361	8009150351 8009150350 8009150340 8009150347 8009150350	90/08/25 80/08/19 80/07/28 80/07/25 80/08/19	50-317 50-458 70-135	H P Q P
8009150139 8009150143 8009150149 8009150161 8009150164	8009150020 8009150140 8009150146 8009150159 8009150158	80/08/18 80/06/30 80/07/21 80/07/24 80/08/14	50-201 CONTRAC CONTRAC 50-322 40-8743		90091 90091 90091	150342 150343 150347 150349 150370	8009150338 8009150337 8009150337 8009150336 8009150332	80/08/19 80/07/23 80/07/23 80/08/22 80/07/23	50-445 50-445 50-370	0000
8009150165 8009150173 8009150177 8009150178 8009150193	8009150163 8009150171 8009150172 8009150176 8009150181	80/07/28 80/07/15 80/07/28 80/08/22 80/08/29	40-3392 0A999 50-546 CONTRAC 70-258	a r	80091 80091 80091	150372 150373 150374 150375 150377	8009150366 8009150364 8009150366 8009150329 8009150366	80/08/22 80/08/11 80/08/22 80/07/24 80/08/22	40-8113 50-370 50-324	Q Q Q
6009150184 8009150189 6009150190 8009150196 8009150197	8009150180 8009150188 8009150187 8009150193 8009150194	80/07/24 80/09/15 80/07/25 80/08/05 80/07/18	50-277 71-112 50-354 50-482 50-329	Q 8 Q	80091 80091 80091	150378 150379 150380 150381 150385	8009150326 8009150376 8009150364 8009150334 8009150382	80/06/17 80/08/22 80/08/11 80/08/20 80/09/09	50-397 40-8113 50-482	G G G B
8009150199 8009150200 8009150203 8009150204 8009150207	8009150195 8009150195 8009150194 8009150195 8009150195	80/08/22 80/08/22 80/07/18 80/08/22 80/08/22	0A999 0A999 50~329 0A999 0A999	Q	80091 80091 80091	150386 150387 150398 150406 150412	8009150384 8009150364 8009150395 8009150403 8009150408	80/09/09 80/08/11 80/08/22 80/07/24 80/08/06	50-321 40-8113 70-143 70-135 70-1308	8
8009150210 8009150212 8009150215 8009150217 8009150223	8009150195 8009150209 8009150213 8009150195 8009150221	80/08/22 80/08/29 80/07/10 80/08/22 80/08/19	0A999 40-8745 70-2932 0A999 0A999		90091 90091 90091	150414 150416 150418 150422 150423	8009150409 8009150413 8009150410 8009150410 8009150410	80/08/25 80/07/30 80/08/22 80/08/22 80/08/22	CONTRACT 50-320 COMMISSID COMMISSID COMMISSID	N
8009150224 8009150226 8009150227 8009150228 8009150229	8004120551 8004120551 8004120551 8004120551	80/08/18 80/08/18 80/08/18 80/08/18 80/08/18	0A777 QA779 QA799 QA797 QA797		800 91 800 91 80091		8009150420 8009150415 8009150410 8009150427 8009150410	80/08/27 80/08/15 80/08/22 80/08/25 80/08/22	50-317 COMMISSIO	P
8009150231 8009150234 8009150241 8009150244 8009150246	8009150221 8009150221 8009150240 8009150219 8009150219	80/08/18 80/08/19 80/07/31 80/08/29 80/08/29	QA979 GA979 50-320 50-334 50-334	H P P	1700B 1700B 1700B	150442 150445	8009150432 8009150410 8009150410 8009150441 8009150440	80/09/08 80/08/22 80/08/22 80/08/22	COMMISSIO	Н
8009150248 8009150256 8009150260 8009150261 8009150263	6007150217 8007150257 8007150257 8007150258 8007150257	80/08/29 80/09/10 80/09/12 80/09/09 80/09/12	50-334 50-464 50-348 50-368 50-348	P K S K	1900B 1900B 1900B	150461 150464 15046B	8009150410 8009150454 8009150462 8009150460 8009150471	80/08/22 80/09/05 80/08/21 80/09/09 80/08/28	50-305 50-438	N R Q A B
8009150265 8009150267 8009150271 8009150272 8009150275	8009150265 8009150264 8009150268 8009150269 8009150273	80/09/08 80/09/09 80/09/09 80/09/09	50-220 50-311 50-368 50-312 50-348	8 8 8	90091 90091 80091	150561 150577 150600	8009150504 8009150559 8009150575 8009150594 8009150594	80/07/28 80/07/15 80/08/21 80/08/07 80/08/07	50-498 40-8768 50-546	G K G
8009150277 8009150278 8009150279 8009150282 8009150283	8009150274 8009150274 8009150270 8009150280 8009150281	80/07/09 80/09/08 80/09/01 80/09/11 80/09/09	50-346 50-260 50-293 50-302 50-321	R 8 P 8 8	80071 80071 80071	150603 60041 60131	8009130601 8009130601 8009160033 8009160148 8009160137	90/09/29 80/09/12 80/09/11 80/09/11	50-376	H O H
8007150285 8007150289 8007150290 8007150292 8007150294	8009150284 8009150286 8009150288 8009150287 8009150291	80/09/01 80/09/10 80/09/03 80/08/29 80/09/09	50-293 50-261 50-335 50-368 50-321	8 8 8	80091 80091 80091	60214 60221 60223	8009160179 8009160213 8009160219 8009160220 8009160225	80/07/08 80/08/29 80/09/09 80/07/26 80/07/21	50-259 6 50-244	R F O
8009150298 8009150298 8009150299 8009150304 8009150306	8009150293 8009150295 8009150297 8009150300 8009150303	80/07/08 80/07/05 80/07/08 80/08/05 80/08/22	50-348 50-321 50-220 50-438 50-286	8 R Q	80071 80071 80071	60241 60242 60246	8009160230 8009160235 8009160240 8009160244 8009160248	80/09/05 80/08/13 80/07/24 80/07/24 80/08/27	70~754 50~220 50~334	P
8009150308 8009150312 8009150315 8009150318 8009150325	8009150303 8009150307 8009150314 8009150316 8009150321	80/08/22 80/09/11 80/09/12 80/08/25 80/08/25	50-286 50-395 50-395 50-352 50-289	Ф К Н	80091 80091 80091	60256 60258 60259	8007160250 8007160251 8007160255 8007160257 8007160260	80/09/08 80/09/08 80/09/10 80/09/11 80/09/09	50-313 1 50-261 1 50-309 1	R R R R
80091 50327 80091 50328 80091 50335 80091 50336 80091 50344	8007150324 8007150323 8007150331 8007150330 8007150337	80/08/22 80/09/10 80/09/09 80/08/22 80/09/10	50-289 50-315 50-344 50-269 50-155	H 8 8 H 0	8007) 80071 80071	60270 60271 60276	8007160262 8007160268 8007160267 8007160272 8007160273	80/09/04 80/09/11 80/09/11 80/09/02 80/09/12	50-298 F 50-348 F 50-293 F 50-254 F	R R R R
8009150345 8009150346 8009150348 8009150352 8009150353	8009150342 8009150343 8009150342 8009150340 8009150340	80/07/28 80/08/22 80/07/28 80/07/28 80/07/28	50-458 50-458	9 4 0 0	12008 12008 12008	60282 60283 60284 60288	8009160279 8009160280 8009160281 8009160286 8009160294	80/09/08 80/09/12 80/09/05 80/09/09 80/09/10	50-282 F 50-314 F PR	R R

	ON NUMBER				ACCERS	ION NUMBER			
ENGLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	GATEGO			PRINCIPAL	DATE	SUBJEC	
6009160297				Ŕ	EXCLOSURE		ISSUED	CATEGO	
8007160299 8007160300		B0/09/10	50-272	R	800716034 800716035	EEE09160933	80/09/04 80/09/04	50-249 50-249	Q.
8009160301 8009160303	8009160291 8009160299	80/09/08	50-271	R	800716055 800716061	8009160610	80/09/04 80/07/28	50-269 50-305	Q: Q:
8009160304	8009160302	80/07/09		R	800914041		80/07/28	50-305	G
8009140305 4000140308	8009160293 8009160285	80/09/05	50-304	8	800914042: 600914042:	8009140419	60/08/13 60/08/13	50-277 50-277	G.
8009160308 8009160311	8009160307 8009160309	80/09/11 80/09/09	50-349	8	8009160625 8009160634	8009160631	80/09/13 80/09/04	50~277 50-395	G G
8009160313	8009160309	80/07/09		6	200016008		80/09/04	50~395	a
810041700B 810041700B	8009160314 8009160315	80/09/09	50-267	P 8	8007160638 8007160640	1E4041900B	80/09/04 80/09/04	50-375 50-375	G.
8009160322 8009160323	8009160321 8009160320	80/09/05 80/09/08	50-142	₽	8009160647 8009160657	8009160696	80/08/18 80/08/18	681MM03 9EE-08	₽
E009160327	8009160325	80/09/04		8	8007140455		80/08/21	50-339	P
8009160331 8009160333	8009160330 8009160330	80/09/05 80/09/05	40-8745		8009160661 8009160663	8009160656	80/08/21 80/08/21	50-339 50-339	P
8009160334 8009160336	8007160330 8007160330	80/09/05 80/09/05	40-8745		8009170000 8009170005	8007170001	80/08/14 80/08/14	70-820 70-820	
8007160340	8009160338		40-8745		8009170011		80/08/26	50-289	Н
8007160345 8007160347	8009160330 8009160343	80/07/11	50-57 40-8745	1	8009170054 8009170070	8007170043	80/09/02 80/09/02	FOIA FOIA	
800716034B	8007160330	80/09/12 80/09/05	30-369 40-8745	0	8009170088 8009170089	8009170082 8009170082	80/08/27 80/08/27	50-282	P
8009160352	8009140330	80/09/05	40-8745		B009170092		60/08/27	50-282	P
8009160354	8009160343 8009160330	80/09/12 80/09/05	50-369 40-8745	٥	8009170129 8009170131	8007170126 8007170126	80/09/15 80/09/15	70-2909 70-2909	
8009160355 8009160356	8009160381 8009160330	80/09/08 80/09/05	50-311 40-8745	P	8009170133 8009170147	8007170126 8007170145	80/09/15 80/09/05	70-2909 50-302	a
8009160357	0000110000	80/09/05	40-8745		8009170152		80/09/05	50-302	G
8009160361 8009160363	8009160359 8009160360	80/09/12 80/09/12	50-320 50-275	6 6	8007170153 8007170154	8009170[49 8009170149	80/09/09 80/09/09	50-466 50-466	0
8009160369 8009160379	8009160365 8009160373	80/09/10 80/09/11	50-247 50-528	8	8009170157 8009170158	8009170149 8009170156	80/09/09 80/07/21	50-466 Qaqqq	٥
8009160380	8009160378	80/09/04	50-327	8	6007170159	8009170155	80/07/21	GA999	
8009160392 8009160398	8007160388 8007160370	80/07/08 80/07/10	50-312 50-312	P 8	8007170163 8009170171	8009170161 8009170169	80/80/08 11/70/08	50-328 50-592	Q
8007160399 8007160402	8009160391 8009160396	80/09/09 80/09/12	50~346 50~293	8	8009170172 8009170176	8009170168 8009170173	60/07/31 60/08/29	50-392 50-313	a a
6009160410	B009160404	80/09/11	50-273	а	8009170181	8009170178	80/08/26	MISC	
8009160411 8009160412	8009160405 8009160406	80/09/11 80/09/11	50-334 50-327	8 8	8009170183 8009170189	8009170180 8009170185	80/08/29 80/09/02	50-382 50-267	G G
8007160422 8007160425	8009160416 8009160421	80/09/08 80/09/08	50-276 50-327	8 8	8007170191 8009170197	8009170184 8009170186	E0/09/05 E0/09/05	50-324 50-324	P P
8009140426	8009160408	80/09/09	50-275	8	8007170221	8009170217	80/07/28	50-45&	ù
8009140431 8009140432	0009160427 8009160429	80/09/10 80/09/11		R P	9009170225 8009170232	8009170223 8009170229	80/09/12 80/09/1	50-466 50-441	o H
B009160435 B009160436	8009160427 8009160424	80/07/10 80/09/11	50-277 TOPREP	R	8009170235 8009170239	8009170229 8009170229	80/09/14 80/09/14	50-445 50-445	H
8009160440	8009140432	B0/97/0B	50-240	8	8009170244	8009170243	80/08/28	50-312	₽
8007140449 8007160451	8009160445 8009160444	80/09/11 80/09/09		6 8	800917025& 8009170260	8009170254 8009170255	80/09/15 80/09/08	50-287 50-333	G P
E007160455 E007160461	8009160447 8009160457	80/09/11 80/09/08		8	8009170262 8009170263	6009170241 8009170257	80/00/55	50-327 50-289	R H
6009160464	8009160457	80/09/08	50~936	8	8009170257	8009170264	80/08/14	50-309	P
B007160466 B007160467	8009160454 8009160460	80/09/08 80/09/05		8 8	8009170269 8009170270	8009170266 8009170264	80/08/11 80/08/14	50-320 50-309	H P
8009160468 8009160469	8009160463 8009160457	80/07/11 80/07/08		8 8	8009170273 8009170275	8009170264 8009170272	80/08/14 80/08/11	50-309 50-320	P H
8009160472	8007160470	80/09/10	50-334	8	8007170277	8009170274	80/09/17	50-259	R
8009160474 8009160476	8009160471 8009160459	80/09/10 80/09/11		8 8	8009170281 8009170284	8007170279 8007170283	80/09/06 80/08/27	50-250 50-320	H
B009160479 B009160480	E007160475 E007160477	80/08/19 80/09/10	WASTE NOT	3	8009170285 8009170289	8007170285 8007170288	80/08/14 80/09/15	50-320 50-302	₽ P
8009160492	8009160478	80/09/11	50-311 8	3	8009170293	8007170292	80/09/10	50-289	P
8009160483 8009160487	8009160452 8009160473	80/07/07 80/08/22	50-293 8 50-280 6		8009170296 8009170301	8009170295 8009170298	80/07/18 80/07/18	50-244 50-244	P
8009140499 8009140490	8009160485 8009160473	80/08/22	CONTRACT 50-280	•	8009170306 8009170314	8009170303 8009170312	80/09/09 80/07/18	50-244 50-244	P
8009160495	8009160491	80/07/29	CONTRACT		8009170317	8009170316	80/09/08	50-320	P
8007140497 8007140502	B009160473	80/08/20	50-280 0 50-269 P		8009170320 8009170323	8009170315 8009170321	80/09/10 80/09/16	50-331 50-281	S P
8007160506 8007160507	8007160501 8007160501	80/08/20 80/08/20	50-269 P	1	8009170328 8009170347	8009170324 8009170343	80/09/10 80/09/11	50-331 50-309	S P
8009150512	8009140509	80/07/31	50-358 0		8007170347	8009170346	80/09/15	50-287	T -
8009160514 8009160515	8009160509 8009160511	B0/07/31 80/07/21	50-358 G		8009170351 8009170352	8009170346 8009170348	80/09/15 80/09/10	50-287 50-331	T S
8009160535 8009160537	8009140533 8009140533	80/09/04 80/09/04	50-269 0 50-269 0		8009170354 8009170354	8009170346 8009170353	80/09/15 80/09/11	50-269 50-364	T A
B007160540	8009160533	80/09/04	50-269 0		8007170358	8009170346	80/09/15	20-584	T

ACCESS16	N NUMBER				ACCE8910	ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 16SUED	EUBJEC CATECO		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188VED	SUBJECT CATEOO	
8009170360 8009170364 8009170365 8009170367	8009170355 8009170359 8009170362 8009170363 8009170359	80/09/10 80/09/12 80/08/14 80/09/10 80/09/12	50-331 50-445 50-320 50-331 50-445	8 H B	8009180459 8009180445 8009180472 8009180476 8009180476	8009180450 8009180448 8009180470 8009180470 8009180474	80/09/02 80/04/21 80/08/08 80/08/08 80/09/16	50-400 50-3 50-313 50-313 50-70	0 H 0 0
8009170376 8009170382 8009170385 8009170387 8009170402	8009170373 8009170378 8009170380 8009170384 8009170389	80/08/27 80/07/18 80/07/16 80/07/16 80/08/08	40-299 50-201 50-498 50-492 50-220	R 0 0	609180480 6009180481 6009180490 8009180491 8009180493	8009180385 8009180470 8009180484 8009180487 8009180486	80/09/11 80/08/08 80/08/05 80/08/05 80/09/16	50-369 50-313 6A999 70-33 50-275	H Q A
8009170414 8009170417 8009180005 8009180021 8009180033	8009170410 8009170410 8009180001 8009180012 8009180027	90/08/18 80/08/18 80/07/18 80/08/07 80/08/08	50-458 50-458 50-334 50-275 40-2259	0	8009180495 8009180497 8009180500 8009180502 8009180504	8009180484 8009180487 8009180484 8009180484 8009180301	80/08/26 80/08/03 80/08/26 80/08/26 80/09/08	QA999 70-33 0A999 QA999 50-237	þ
8009180047 8009180054 8009180061 8009180064 8009180070	8009180040 8009180040 8009180043 8009180036 8009180056	80/08/27 80/08/27 80/08/07 80/08/28 80/08/28	50-373 50-373 50-461 9A999 0A999	0 0 0	8009180506 8009180516 8009180526 8009180536 8009180536	8009180484 8009180501 8009180501 8009180529 8009180538	80/08/26 80/09/08 80/09/08 80/07/07 80/08/29	0A999 50-237 50-237 0A999 50-280	P P
8009180074 8009180077 8009180081 8009180085 8009180093	8007180072 8007180056 8007180072 8007180056 8007180087	80/08/13 80/08/28 80/08/28 80/08/28	40-8452 GA999 40-8452 GA999 40-8584		8009180352 8009180365 8009180365 8009180366 8009190017	8009180538 8009180548 8009180548 8009180562 8009190014	80/08/29 80/08/19 80/08/19 80/07/03 80/08/28	50-280 50-320 50-320 0A999 QA999	P H K
8007180079 8009180100 8009180104 8009180109 8009180113	8009180092 8009180095 8009180092 8009180092 8009180107	80/08/26 80/08/26 80/08/26 80/08/26	GA999 50-445 GA999 OA999 50~261	Q P	8007170020 8007170024 8007170027 8007170027 8007170031	8009190014 8009190014 8009190014 8009190014 8009190014	80/08/28 80/08/28 80/08/28 80/08/28 80/08/28	GA999 GA999 GA999 GA999 OA999	
8007180118 8007180117 8007180122 8007180150 8007180162	8009180107 8009180092 8009180107 8009180143 8009180148	80/08/29 80/08/26 80/08/29 80/08/28 80/08/03	50-261 0A999 50-261 CDNTRACT 50-280	P P 0	8009190048 8009190049 8009190053 8009190054 8009190056	8007170044 8007170044 8007170044 8007170044 8007170051	80/08/14 80/08/14 80/08/14 80/08/14 80/08/21	50-352 50-352 50-352 50-352 CDNTRACT	0 0
8007180145 8007180177 8007180180 8007180185 8007180171	8009180159 8009180169 8009180175 8009180169 8009180167	80/07/04 80/07/02 80/07/10 80/07/02 80/07/08	CONTRACT GA999 50-213 GA999 CONTRACT	R	8009190076 8009190079 8009190079 8009190091 8009190094	8009190073 8009190073 8009190073 8009190073 8009190089	80/08/13 80/08/13 80/08/13 80/08/13 80/08/14	50-293 50-293 50-293 50-293 50-443	G G G
8009180194 8009180196 8009180203 8009180208 8009180217	8009160188 8009180183 8009180199 8009180199	80/09/15 80/08/05 80/08/08 80/09/10 80/09/03	50-334 70-135 40-1162 50-321 CONTRACT	R	8009190100 6009190101 8009190104 8009190105 8009190106	8007170087 8007170078 8007170087 8007170078 8007170087	80/08/14 80/09/12 80/08/14 80/09/12 80/08/14	50-443 50-155 50-443 50-155 50-443	0 8 0 8
E009180219 8009180221 8009180232 8009180235 6009180237	8007180213 800718021i 8007180226 8007180498 8007180226	80/08/15 80/08/05 80/09/02 80/09/10 80/09/02	50-336 50-546 50-366 50-366 50-546	F Q Q R Q	8007170121 8007170123 8007170124 8007170128 8007170127	8007170118 8007170116 8007170078 8007170078	80/09/12 80/09/12 80/08/20 80/08/20	40-2061 40-2061 50-155 XPORTLIC 50-155	9
8007180240 8007180242 8007180257 8007180272 8007180277	8009180231 8009180226 8009180249 8009180265 8009180269	80/08/07 80/09/02 80/09/10 80/08/29 80/09/04	50-329 50-546 50-311 50-244 10CFR	0 R R	8007170138 8007170140 8007170143 8009170148 8009170131	8009190133 8009190134 8009190134 8009190145 8009190134	80/09/12 80/08/28 80/08/28 80/09/04 80/08/28	50-440 50-247 50-247 50-346 50-247	K P P P
8009180278 8009180280 8009180284 8009180291 8009180298	8009180268 8009180266 8009180269 8009180269 8009180269	80/09/10 80/07/28 80/09/04 80/09/04 80/09/04	50-220 50-373 10CFR 10CFR 10CFR	8 0	8009170169 8009190171 8009190179 8009190179 8009190182	8009190159 8009190166 8009190159 8009190175 8009190175	60/08/22 80/02/14 80/08/22 80/08/28 80/08/28	50-528 50-254 50-528 50-285 50-285	0 0 0 P P
8009180314 8009180327 8009180329 8009180335 8009180344	6007180304 8007180322 8007180320 8007180304 8007180340	80/09/15 80/09/16 80/09/04 80/09/15 80/09/17	50-277 50-369 CONTRACT 50-277 50-220	P A P	8009190183 8009190185 8009190190 8009190199 8009190205	8009190159 8009190175 8009190168 8009190195 8009190197	80/09/22 80/09/28 80/09/28 80/07/17 80/08/29	50-528 50-285 CONTRACT 50-170 MISC	Q P V
8009180348 8009180355 8009180408 8009180409 8009180417	8009180340 8009180351 8009180404 8009180395 8009180412	80/09/17 80/08/29 80/09/09 80/09/12 80/09/12		P R 8 8	8009190209 8009190210 8009190211 8009190214 8009190216	8009190206 8009190203 8009190197 8009190203 8009190203	80/09/12 80/08/05 80/08/05 80/08/05	50-354 MISC 50-354	Р Q Q
8009180426 8009180427 8009180429 8009180433 8009180442	8009180419 8009180424 8009180421 8009180421 8009180439	80/09/05 80/09/11 80/09/10 80/09/10 80/09/12	50-368 50-361 50-361	8 P A A	8007170221 8007170223 8007170241 8007170242 8007170230	8009190218 8009190203 8009190231 8009190235 6009190247	80/09/16 80/09/06 80/07/15 80/09/02 80/08/01	50-354 50-367 50-369	K Q Q A
8009180447 8009180449 8009180452 8009180453 8009180454	8007180440 8007180440 8007180451 8007180440 8007180450	80/09/03 80/09/03 80/09/12 80/09/03 80/09/02	40-2041	P Q	8009190254 8009190256 8009190257 8009190259 8009190260	E009190247 8009190252 E009190247 E009190247 E009190255	80/08/01 80/09/12 80/08/01 80/08/01 80/08/29	50-440 50-397 50-397	а К а е

	IN NUMBER				ACCESSI	ON NUMBER			
EXCLOSURE	PRINCIPAL DOCUMENT	DATE DEVED	EUBJE CATEG		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGO	
6007170263	8007170252	60/09/12	50-440	K	6007170548		80/09/04	FOIA	
8009190266 8009190271	8007170261 8007170264	80/06/23	ACR8 50-387	G	8007170581 8007170583		80/08/29 80/09/03	50-346 50-348	Ċ Cr
8009190275 8009190277	8009190267 8009190264	80/08/29 80/08/11	50-250 50-387	0	8007170584 8007170587		80/07/05 80/07/04	50-285 FOIA	Œ
8009190282 8009190288	8009190264 8009190264	11\B0\08	50-387	g	8009190588		E0/09/03	50-348	œ
6009190289	8007170283	80/08/11 80/08/29	50-387 50-272	0	8009190593 8009190596		80/09/03	50-348 50-334	G P
8009190302 8009190304	8007170277 8007170275	80/08/29 80/08/29	50-335 50-282	0	8009190502 8009190507	8007170587 8007170587	80/08/27 80/08/27	50-334 50-334	P P
8009190310 8009190311	8009190308 8009190308	80/08/29 80/08/29	50-313 50-344	G G	8009190609		80/09/03 80/09/21	50-348 50-259	0
8009190320	8007170277	80/09/04	FOIA		8007170612 8007170612	8007170277	80/09/04	FOIA	a
9007170324 8 0 07170326	8009190316 8009190299	60/08/29 60/09/04	50-312 F01A	C	8009190617 8009190624	6009190603 6009190299	80/08/21 80/09/04	50-259 FOIA	a
8009190328 8009190340	8009190322 8009190333	80/08/29 80/08/13	50-336 50-362	0	00919069 4080919009	8009190299 8009190614	80/09/04 80/09/02	50-219 FOIA	0
8009190343	8009190336	80/08/29	50-265	•	BD0919063B	E009190614	80/09/02	FOIA	_
8007170344 8007170351	8009190338 8009190338	80/09/12 80/09/12	50-361 50-361	K	8009190639 8009190642	8007170637 8007170614	80/09/12 80/09/02	50-133 FOIA	P
8009190357 8009190358	8009190352 8009190299	90/08/29	50-266	٥	8009190643 8009190646	8009190603 8009190603	80/08/21 80/08/21	50-257 50-259	G O
8009190365	18009190361	80/09/04 80/08/29	FOIA 50-206	P	8007190647	8007190614	E0/09/02	FOIA	_
8007170366 8007170367	8009190299 8009190362	80/09/04 80/08/29	FOIA 50-277	٠	8009170651 8009190653	8007170603 8007170614	80/08/21 80/09/02	50-259 FOIA	ū
8009190370 8009190374	8009190299 8009190361	80/09/04	FOIA		8007170657 8007170668	8007170614 8007170614	80/09/02 80/09/02	FOIA FOIA	
8009190377	8009190299	80/09/04 80/09/04	50-206 FOIA	P	8009190676	8009190514	80/09/02	FOIA	
8009190378 8009190380	8007170361 8007170375	80/08/29 80/08/29	50-206 50-302	P	B009190682 B009190688	B009190614 B009190614	80/09/02 80/09/02	FOIA FOIA	
8007170383	8007170297	80/09/04	FOIA		8009190695	8007170514	80/09/02	FOIA	
48E0919008 09E0919008	8007170277 8007170277	80/09/04 80/09/04	FOIA FOIA		6007190701 800 7 190713	8009190614 8009190702	60/09/02 60/08/29	FOIA CONTRACT	_
8009190394 8009190397	8009190299 8009190299	B0/09/04 B0/09/04	FOIA FOIA		8009190738 8009190775	8007170727 8007170771	60/08/29 60/09/03	CONTRACT 10CFR	•
8009190400	8007170299	80/09/04	FOIA		8009190817	8009190794	80/08/15 80/08/27	50-3 State Pr	Р
8007170428 8007170427	8009190423 8009190425	80/09/15 80/09/15	50-321 50-325	P	8009190877 8009220011	8009190874 8009220009	80/08/29	50-247	٠
8009190432 8009190435	8009190423 8009190431	80/09/15 80/09/12	50-321 50-440	P	8009220014 8009220017	8009220013 8009220015	80/08/29 80/08/29	50-220 50-249	0
6009190444	8009190437	80/09/15	50-280	R	8007220019 8007220037	8007220018 8007220033	80/08/29 80/08/13	50-259 50-339	Q H
9009190445 8009190451	8009190441 8009190442	80/09/17 80/09/15	50-482 50-286	K R	8009220041	B00455003B	80/09/13	40-1341	
8009190453 8009190454	8009190449 8009190440	90/09/15 80/09/12	TOPREP	8	8004550041 8004550081	8009220078 8009220088	80/08/13 80/08/29	50-352 50-275	0 H
8009190459	8009190456	80/09/08	50-245	R	\$7002227008 \$7002277008	8009220093	80/08/29 80/08/29	50-334 50-263	0
8009190464 80091 9 0470	8007170277 8007170277	20/09704 80/09/04	FO1A FOIA		8007220107	B009220104	80/08/29	50-333	G
8009190473 8009190474	8009190462 8009190468	80/09/15 80/09/05	50-269 50-295	R P	8007220117 8007220117	8009220109 8009220115	80/08/29 80/08/29	50-331 50-271	0
9009190477	8009190469	80/09/15	50-241	8	8009220128 8009220128	8009220120 8009220125	80/08/29 80/08/15	50-324 MISC	G
8009190480 8009190483	8009190299 8009190478	80/09/04 80/08/27	FOIA 50-298	P	8007220184	8009220182	80/06/26	50-335	Q.
8009190484 8009190494	8009190299 8009190491	80/09/04 80/09/16	FOIA 50-382	н	8007220170 8007220200	8009220188 8009220198	80/07/25 80/07/25	50-289 50-289	H
8009190495	8009190488	80/09/17	50-259	P	8007220207 8007220207	8007220203 8007220201	80/07/25 80/07/25	50-287 50-289	H H
8009190496 8009190498	8009170489 8009190299	80/09/12 80/09/04	50~333 F01A	8	8009220211	8009220202	80/07/25	50-289	H
8007170504 8007170507	8009190499 8009190299	80/09/12 80/09/04	50-331 FDIA	R	8009220216 8009220217	6007220165 6007220165	80/09/17 80/09/17	50-155 50-155	Q
8009190509	8009190503	60/09/12	50-315	s	8007220218 8007220222	8009220185 8009220221	90/09/17 90/09/10	50-155 50-389	0 M
8009190511 8009190514	8009190471 8009190299	80/09/11 80/09/04	50-327 FOIA	s	6007220223	8009220221	80/09/10	50-389	H
8007170519 8007170520	8009190467 8009190299	80/09/12 80/09/04	50-259 FOIA	s	8009220242 6009220247	8009220238 8009220238	80/07/15 80/07/15	50-329 50-329	A
8009190522	8007170317	80/09/12 80/09/12	50-316 50-259	S	8009220252 8009220258	8009220250 8009220253	80/09/12 80/09/12	50-293 50-280	y 8
8009190524 8009190526	8007170465 8007170277	80/09/04	FOIA		8009220240	8009220253	80/09/12	50-280 50-280	3
B009190531 B009190532	8007170460 8007170277	80/09/08 80/09/04	50-336 F01A	ខ	8007220283 8007220271	8009220253 8009220269	80/09/12 80/09/11	20-592	8
B009190537	8009190460	80/07/08 80/07/04	50-336 FOIA	s	8009220278 8009220287	8009220274 8009220281	80/09/11 80/09/12	50-304 50-295	8 8
B009190339 B009190541	8007170277 8007170533	90/09/10	50-331	P	8009220289	8007220285	80/09/16	\$0~255	В
8009190543 8009190546	8009190460 8009190299	80/09/08 80/09/04	50-336 FQIA	8	8007220271 8007220301	800722028B 8007220277	80/09/15 80/09/16	30-289 30-346	R P
8007170547	8009190540	80/09/12 80/09/04	50-327 FQIA	8	8009220305 8009220309	8009220251 8009220248	80/09/12	\$0-338 \$0-281	5 8
B009190550 B 0091 90557	8007170277 8007170277	E0/09/04	FOLA	_	8009220313 8009220313	8007220277 8007220241	80/09/16 80/09/16	\$0-345 \$0-339	P
8009190559 8009190566	8009190553 8009190553	E0/09/15 B0/ 0 9/15	50-280 50-280	8 8	8007220317	8007220237	80/09/16	30-337 30-339	8

PRINCIPAL DATE SUBJECT ENCLOSURE DOCUMENT ISSUED CATEGORY ENCLOSURE DOCUMENT ISSUED ENCOMES ENCOPED STATE SUBJECT ENCLOSURE DOCUMENT ISSUED ENCOPED STATE SUBJECT ENCOPED STATE SUBJEC	SUBJECT CATEGORY 50-336 R
800922034	40-33t B
S009220344 S009220334 S0/09/12 S0-445 A S009230394 S009230385 S0/09/09 S009220384 S0/09/12 S0-445 A S009230399 S009230385 S0/09/09 S009220385 S0/09/15 S009220385 S0/09/16 S0	50-295 R 50-295 R CONTRACT 50-338 R CONTRACT
B009220365 B009220341 B0/09/15 S0-302 R B009230439 B009230439 B0/09/16	50-295 P 50-295 P 50-295 P 50-368 R TOPREP
8009220385 8009220334 80/09/12 50-445 A 8009230504 8009230496 80/09/18 8009230387 8009230334 80/09/12 50-445 A 8009230317 8009230507 80/09/18	50-3 R 50-324 P 50-289 H 50-10 P TOPREP
8009220392 8009220334 80/09/12 50-445 A 8009230527 8009230520 80/09/18 8009220393 6009220334 80/09/12 50-445 A 8009230536 8009230536 80/09/15	50-219 8 50-270 8 50-270 8 50-319 8 50-317 8
6009220398 6009220248 80/09/12 50-281 B 8009230546 8009230542 80/09/16 6009220402 800922048 80/09/12 50-281 B 8009230559 8009230550 8009230550 8009230550 8009230550 8009230550 8009230550 8009230550 8009230550 8009230550 8009230550 8009230550 8009230550 8009230550 8009230550 8009230550 8009230561 80/09/16 80092300001 8009230001 80/09/10 50-409 0 8009230571 8009230561 80/09/15	50-317 B 50-329 A 50-329 A 50-219 R 50-247 R
800723001B 8007230016 80/07/07 50-142 0 8007230576 8007230579 8007230579 800723057 800723057 800723057 800723057 800723057 800723057 800723057 800723057 800723057 800723057 800723057 800723057 800723057 800723057 800723057 800723057 800723058 80/07/17 8007230117 8007230127 8007230127 800723057 800723057 800723057 800723057 800723058 80/09/18	50-277 R 50-339 B 50-309 P 50-317 B 50-327 B
8007230130 8007230124 80/08/27 50-261 0 8007230600 8007230589 80/09/16 8007230132 8007230121 80/08/27 50-280 0 8007230604 8007230604 8007230578 80/09/15 8007230134 8007230139 80/08/27 50-305 0 8007230607 8007230607 8007230607 8007230608 80/09/15 8007230139 8007050471 80078108 8007230614 8007230605 8007230605 80/09/16 8007230141 8007050471 80078108 80078108 80078108 80078108	50-339 8 50-267 8 50-267 8 50-267 8 50-338 6
8009230145 8009230147 8009230147 8009230147 8009230147 8009230143 8009230142 8009230143 8009230	50-255 8 50-243 8 50-325 8 50-338 8 50-317 P
8007230156 8007050471 800/818 FDIA 6007230641 8007230642 8007230642 8007230642 8007230642 8007230642 8007230642 8007230642 8007230642 8007230642 8007230642 8007230642 8007230643 8007230644 8007230644 8007230644 8007230644 8007230644 8007230644 8007230644 8007230644 8007230644 8007230644 8007230644 8007230644 8007230644 8007230644 8007230644 8007230643 8007915 8007230643 8007230643 8007915 8007230644 8007230644 8007230644 8007230643 8007915 8007230643 8007230643 80079230644 8007230643 8007230644 8007230643 8007230644	30-263 8 50-416 9 50-317 P 50-157 P 50-317 P
8007230176 8009050491 800918 FOIA 8009230432 8009230432 8009230433 8009230443 8009230443 8009230448 8009230448 8009230448 8009230448 8009230448 8009230448 8009230448 8009230443	50-157 P 50-409 E 50-157 P 50-250 8 50-409 B
8009230201 8007050491 800/09/18 FGIA 8009230667 8009230662 8009230662 8009230662 8009230662 8009230668 8009230668 8009230668 8009230668 8009230668 8009230669 8009230668 8009230669 <td>50-483 K 50-157 P 50-280 8 50-296 8</td>	50-483 K 50-157 P 50-280 8 50-296 8
8009230213 8009050491 80/08/19 FD1A 8009230680 8009230680 8009230671 80/09/19 8009230218 8009050491 80/08/19 FD1A 8009230683 8009230683 8009230670 80/09/16 8009230219 8009230212 80/08/12 50-275 Q 8009230684 8009230684 8009230672 80/09/16 8009230222 8009230216 80/08/12 50-320 H 8009230666 8009230682 800923068 8009230672 80/09/16 8009230224 8009250491 80/08/16 FDIA 8009230678 8009230672 8009230676	50-346 8 50-325 8 TOPREP 50-346 8 50-237 8
8009230229 8009050491 800/08/18 FOIA 8009230692 8009230690 80/09/18 8009230232 8009050491 80/08/18 FOIA 8009230694 8009230690 80/09/18 8009230234 8009050491 80/08/18 FOIA 8009230695 8009230689 80/09/29 8009230239 8009050491 80/08/18 FOIA 8009230700 8009230697 80/09/18 8009230700 8009230697 80/09/15 8009230239 80/08/18 8009230239 80/08/18 8009230700 8009230681 80/09/15	50-346 8 50-311 8 50-317 8 50-313 R 50-304 8
8009230242 8009230233 80/08/15 50-320 H 8009230712 8009230705 80/09/16 8009230247 8009230233 80/08/15 50-320 H 8009230714 8009230716 8009230715 8009230247 8009230247 8009230247 8009230247 8009230247 8009230715 8009230715 8009230715 8009230716	50-368 8 50-259 8 50-313 8 50-325 8 50-10 R
8009230260 8009030491 80/08/18 F0IA 8009230727 8009230719 80/09/17 8009230268 8009030491 80/08/18 F0IA 8009230728 8009230726 8009230728 8009230728 8009230728 8009230728 8009230729 8009230728 8009230729 8009230	50-324 S 50-259 B 50-348 S 50-327 B 50-328 S
8009230274 8009030491 80/08/18 FQIA 8009230737 8009230730 8009230732 8009230289 8009030491 80/08/18 FQIA 8009230730 80092	50-348 8 50-293 8 50-325 8 50-282 8 50-325 8

ACCEBBION NUMBER					ACCEBSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	GUBJEC1 CATEGOR	
8007230748 8007230750 8007230755 8007230751 8007230764	8009230744 8009230743 8009230751 8009230754 8009230760	80/09/16 80/09/19 80/08/27 80/08/27 80/08/14	50~349 50~282 CONTRACT 71~9001 50~320	8 8 8	8009240331 8009240339 8009240340 8009240350 8009240356	8009240318 8009240334 8009240329 8009240343 8009240329	80/08/28 80/08/15 80/09/03 80/09/16 80/09/03	50-416 70-33 50-324 50-409 50-324	Q Q P Q
8009230771 8009230777 8009230787 8009240014 8009240016	8009230768 8009230774 8009230785 8009240012 8009240012	80/08/27 80/08/29 80/08/29 80/08/21 80/08/21	CONTRACT CONTRACT 71-17 FOLA FOLA		8009240363 8009240368 8009240316 80092403167 8009240319	8009240329 8009240329 8009240329 8009240380 8009240380	60/09/03 60/90/03 60/90/03 60/90/03	50-324 50-324 50-324 50-518 50-518	0 0 0 0
E009240018 E009240021 E009240024 E009240026 E009240028	8007240012 8009240012 8009240012 8009240012 8009240023	80/09/21 80/08/21 80/08/21 80/09/03	FOIA FOIA FOIA FOIA CONTRACT		8009240406 8009240421 8009240455 8009240456 8009240456	8009240380 8009240380 8009240452 8009240450 8009240450	80/09/02 80/09/02 80/09/15 80/09/17 80/09/17	50-518 50-518 50-3 50-334 50-334	G: Q: R: B: S:
6007240038 6007240041 6007240047 6007240051 6007240054	8009240034 8009240012 8009240012 8009240044 8009240012	80/09/09 80/08/21 80/08/21 80/08/11 80/08/21	CONTRACT FOIA FOIA 70-710 FOIA	•	8009240461 8009240463 8009240468 8009240470 8009240471	8009240450 8009240462 8009240467 8009240469 8009240469	80/09/17 80/09/19 80/09/19 80/09/19	50-334 50-293 50-293 50-281 50-281	8 8 8
8009240055 8009240057 8009240059 8009240060 8009240063	8009240044 8009240052 8009240012 8009240044 8009240012	80/08/11 80/08/28 80/08/21 80/08/11 80/08/21	70-710 50-206 FOIA 70-710 FOIA	P	8009240473 8009240504 8009240504 9009240507 8009240508	8009240469 8009240495 8009240496 8009240502 8009240495	80/09/19 80/09/19 80/09/17 80/09/22 80/09/19	50-281 50-305 50-368 50-341 50-305	5 5 A 5
8009240067 8009240070 8009240071 8009240075 8009240079	8009240065 8009240012 8009240066 8009240012 8009240073	80/08/12 80/08/21 80/08/05 80/08/21 80/08/21	CONTRACT A LOT SCEC-08 FOIA TOARTHOO	a	8009240509 8009240513 8009240527 8009240532 8009240533	8009240502 8009240502 8009240520 8009240531 8009240407	80/09/22 80/09/22 80/08/04 80/09/22 80/07/11	50-341 50-341 TOPREP 50-289 50-147	A O O
B0092400B2 B0092400B4 B0092400B6 B0092400B9 B009240092	8007240012 8007240078 8007240012 8007240078 8007240012	80/08/21 80/08/29 80/08/21 80/08/29 80/08/21	FOIA 50-315 FOIA 50-315 FOIA	P P	8009240536 8009240536 8009240546 8009240550 8009240557	8007240535 8007240535 8007240544 8007240544 8007240532	80/09/19 80/09/19 80/09/19 80/09/19 80/09/17	50~289 50~289 50~275 50~275 50~395	0000
8007240077 8007240108 8007240113 8007240117 8007240121	8009240078 8009240012 8009240012 8009240012 8009240109	80/08/29 80/08/21 80/08/21 80/08/21 80/07/31	50-315 FOIA FOIA FOIA 50-320	P H	8009240564 8009240609 8009240603 8009240617 8009240628	8009240560 8009240583 8009240597 8009240606 8009240606	80/08/29 80/09/02 80/08/29 80/09/11 80/09/11	50~327 50~566 50~321 50~302 50~302	P Q P P
8009240125 8009240130 8009240132 8009240134 8009240145	8007240012 8007240123 8007240127 8007240106 8007240106	80/08/21 80/09/08 80/09/02 80/08/29 80/08/29	50-263 CONTRACT 71-4786 50-313 50-313	8 8	8009240431 8009240434 8009240437 8009240440 8009240446	8009240624 8009240606 8009240624 8009240624 8009240624	80/09/08 80/09/11 80/09/08 80/09/08 60/09/08	70-143 50-302 70-143 70-143 70-143	P
B007240151 B00724015B B007240177 B007240184 B007240187	8009240141 8009240106 8009240106 8009240176 8009240176	80/09/10 80/08/29 80/08/29 80/08/28 80/08/28	F01A 50-313 50-313 50-302 50-302	8 8 0	8007240661 8007240667 8009240673 8007240648 8007240701	8009240652 8009240652 8009240652 8009240652 8009240693	80/09/08 60/09/08 80/09/08 80/09/08	50-281 50-281 50-281 50-281 50-280	Q Q Q
8009240190 8009240192 8009240198 8009240196 8009240200	8009240176 8009240186 8009240176 8009240186 8009240186	80/08/28 80/08/19 80/08/28 80/08/19 80/08/19	50-302 50-244 50-302 50-244 50-244	G G G	8009240706 800924070 9009240713 8009240729 8009250066	8007240693 8009240693 8009240693 8007240721 8007250062	80/09/08 80/09/08 80/09/08 80/08/16 80/08/29	50-280 50-280 50-280 40-299 70-1151	Q Q Q
8007240205 8007240204 8007240212 8007240220 8007240228	8009240186 8009240201 8009240201 8009240201 8009240201	80/08/19 80/08/29 80/08/29 80/08/29 80/08/29	50-244 50-369 50-369 50-369 50-369	0 0 0 0	8009250112 8009250113 8009250130 8009250133 8009250137	8007250107 8007250107 8007250126 8007250126 8007250126	80/09/04 80/08/04 80/09/12 80/09/12 80/09/12	50-546 50-546 50-368 50-368 50-368	Q P P
E007240232 E007240241 E007240246 E007240255 E007240252	8009240201 8009240201 8009240239 8009240239 8009240236	80/08/29 80/08/29 80/08/12 80/08/12 80/08/29	50-369 50-369 50-282 50-282 50-370	Q G F G	8009250196 800925020 8009250208 8009250227 8009250247		80/08/27 80/08/27 80/08/30 80/08/30 80/09/03	50-369 50-369 50-461 50-358 50-327	0 0 0 8
B007240268 B007240266 B007240270 B007240276 B007240284	8009240259 8009240256 8009240256 8009240256 8009240273	80/07/23 80/08/29 80/08/29 80/08/29 80/08/04	50-317 50-370 50-370 50-370 50-324	0 0 0 0	8009250253 8009250265 8009250279 8009250280 8009250302	8009250258 8009250278 8009250276 8009250299	80/09/19 80/09/01 80/09/12 80/09/04 80/07/11	50-266 CONTRAC 50-135 10CFR 50-387	e a
8007240270 8007240274 8007240277 8007240278 8007240202	8007240282 8007240282 8007240292 8007240282 8007240282	80/09/02 80/09/02 80/09/02 80/09/02	50-413 50-413 50-413 50-413 50-413	0 0 0	B009250304 B009250325 B009250325 B009250326 B009250327	8009250307 8009250307 8009250307 8009250307	80/09/19 80/08/21 80/08/21 80/08/21 80/08/21	50-261 GA999 GA999 GA999 GA999	5
8009240306 8009240307 8009240313 8009240314 8009240320	8007240282 8007240272 8007240282 8007240272 8007240272	80/09/02 80/09/02 80/09/02 80/09/02 80/09/02	50-413 50-413 50-413 50-413 50-413	0 0 0 0	8009230333 80092350333 8009230334 8009230341 8009230343	8009250334 8009250339	80/09/17 80/07/01 80/07/01 80/09/09 80/09/07	50-220 70-820 70-820 50-413 50-413	R G

TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER					ACCES910				
PRINCIPAL ENGLOSURE DOCUMENT	DATE JESUED	SUBJECT			ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	CATEGO	
8009250344 8009250338 8009250349 8009250346 8009250351 8009250346 8009250352 8009250346 8009250359 8009250356	80/08/20 80/07/18 80/09/09 80/07/18 80/08/05	50-295 50-461 50-400 50-461 50-201	0 0 0 0		8009260412 8009260413 8009260414 8009260415 8009260416	8009260313 8009260410 8009260313 8009260410 8009260389	80/09/15 80/08/18 80/09/15 80/08/16 79/08/10	50-289 50-329 50-289 50-329 70-1167	T G T
8009250340 8009250357 8009250343 800925034 8009250373 8009250345 8009250393 8009250390 8009250395 8009250390		50-280 50-201 50-315 50-458 50-458	0 0 0 0		8009260417 8009260419 8009260420 8009260421 8009260431	8009260313 8009260389 8009260418 8009260313 8009260313	80/09/15 79/08/10 80/07/10 80/09/15 80/09/15	50-289 70-1167 50-409 50-289 50-289	T Q T T
8009250398 8009250390 8009250405 8009250402 8009250411 8009250408 8009250422 8009250419 8009250439 8009250431	80/08/08 80/09/09 80/09/09	50-458 50-498 50-263 70-36 70-143	0 0 0		8007260437 8007260443 8007260447 8007260455 8007260456	8009240313 8009240313 8009240440 8009240450 8009260453	80/09/15 80/09/15 80/09/18 80/09/22 80/09/16	50-289 50-289 50-219 50-287 50-369	T T 8 9
8009250453 8009250448 8009250456 8009250451 800925047 8009250462 8009250470 8009250464 8009250471 8009250462	80/09/13 80/08/25 80/09/11	FOIA 50-361 TOPREP 70-1151 TOPREP	A	i 1	8009260461 8009260468 8009260475 8009260476 8009260482	8009240455 8009240445 8009240470 8009240472 8009240477	80/09/19 80/09/23 80/09/19 80/09/12 80/09/19	50-271 50-237 50-293 50-312 TOPREP	P 8 8
8009250476 8009250472 8009250428 8009250472 8009250482 8009250479 8009250497 8009250493 8009250498 8009250493	80/09/10 80/09/08 80/08/15	70-1257 70-1257 50-546 CONFRACT 71-108	S	1	8009240484 8009240485 8009240487 8009240492 8009240493	8009240481 8009240480 8009240477 8009240488 8009240477	80/09/19 80/09/22 80/09/19 80/09/23 80/09/19	50-293 50-293 TOPREP 50-255 TOPREP	8
8009250502 8009250300 8009260002 8009260001 8009260004 8009260003 8009260005 8009260003 8009260005 8009260009	80/09/23 80/09/23	71-192 50-329 50-289 50-289 50-389	0 0	1	B007260475 B007260476 B007260478 B007260503 B007260504	8009260363 8009260488 8009260477 8009260494 8009260477	79/08/10 80/09/23 80/09/19 80/09/22 80/09/19	40-8443 50-255 TOPREP 50-309 TOPREP	8 8
8007260013 8007260007 8007260063 8007260058 8007260117 8007260105 8007260157 8007260153 8007260173 8007260168	80/08/27 80/08/15 80/08/12	50-389 50-341 71-6581 40-8380 71-6058	о н	6 8	8009260510 8009260513 8009260518 8009260532 9009260540	8009240304 8009240308 8009240314 8009240328 8009240335	80/08/27 80/09/16 80/09/24 80/08/29 80/08/29	50~344 50~206 50~395 50~317 50~366	5 8 A 0 0
8009240174 8009240168 8009240181 8009240164 8009240195 8009240164 8009240172 8009240165 800924020 8009240207	80/07/10 80/07/10 80/07/10	71-6098 50-334 50-334 50-334 50-466	P P Q	8 E	3009260341 3009260343 3009260397 3009260601 3009260607	8009260537 8009260537 8009260592 8009260596 8009260602	80/09/12 80/09/29 80/08/29 80/08/29	50~284 50~284 50~289 50~298 50~309	P P O O O
8009260233 8009260227 8009260238 8009260232 8009260242 8009260229	80/08/27 5 80/09/04 6 80/07/28 6	XPORTLIC 50-267 CONTRACT CONTRACT	R	E E	8009260613 8009260624 8009260634 8009260636 8009260638	8009240409 8009240415 8009240428 8009240430 8009240435	80/08/29 80/08/29 80/08/21 80/09/19 80/09/19	50-315 50-338 50-315 50-409 50-324	9 9
8009240258 8009240254 8009240271 8009240263 9 8009240284 8009240282	80/09/16 ! 80/08/14 ! 80/09/10 !	50-461 50-327 50-282 50-298 50-498	a E a R T	6 8	8009250540 8009260542 8009260545 8009250552 8009250554	8009260626 8009260637 8009260641 8009260641 8009260649	80/09/22 80/09/19 80/09/16 80/09/16 80/09/12	50-243 50-309 50-201 50-201 50-334	8008
8009260329 8009260313 8009260313 8009260313	80/09/15 : 80/09/15 : 80/09/15 :	50-316 50-269 50-289 50-269 50-296	Q T T T	8 8 8	007260658 0007260661 0007260665 0007260667 0007260677	8009260656 8009260659 8009260659 8009260664 8009260672	80/09/10 80/08/20 80/08/20 80/08/29 80/09/15	50-275 50-346 50-346 50-267 50-409	G G G
8009240336 8009260324 (8009260340 8009260313 (8009260341 8009260324 (60/09/09 5 80/09/15 5 80/09/09 5	50-287 50-276 50-287 50-296 50-289	T P T P T	8	009260680 009260681 009260684 009290004 009290003	8009240476 8009260670 8009240670 8009290002 8009290002	80/08/29 80/09/17 80/09/17 80/09/09 80/09/09	CONTRACT 50-376 50-376 50-266 50-266	0000
8009260358 8009260346 8 8009260359 8009260313 8 8009260364 8009260346 8	80/09/08 5 90/09/15 5 80/09/08 5	50-346 50-287 50-346	P P T T	9 6	009290013 009290015 009290018 009290020 009290023	8007270011 8007270011 8007270017 8007270017 8007270021	80/08/11 80/08/11 80/08/19 80/07/10 80/07/16	50-266 50-266 50-266 50-346 50-327	9 9 9 9 7
8009240374 8009260349 8 8009240380 8009250313 8 8009240386 8009240378 8	80/09/18 5 80/09/15 5 80/09/18 5	10-267 10-289 10-267	R R R T	8 8	009290026 009290030 009290031 009290032 009290037	8009270021 8009270021 8009270025 8009270025	80/09/16 80/09/16 80/09/08 80/09/16 80/09/08	50-327 50-327 FOIA 10CFR FOIA	T T
8009260396 8009260313 8 8009260397 8009260395 8 8009260400 8009260313 8	30/09/15 5 30/08/18 5 30/09/15 5	0-289 0-10 0-289	T T G T	8: 8:	009290057	8009290025 8009290025 8009290025 8009290054 8009290025	80/09/08 80/09/08 80/09/08 80/09/10 80/09/08	FOIA FOIA FOIA 50-275 FOIA	Н
8007260405 8007260372 7 8007260407 8007260313 8 8007260408 8007260390 7	79/08/10 76 80/09/13 5 79/08/10 46	0-2560 0-289 0-8180	o T T	8: 8:	009290048 009290073 009290079	8009290025 8009290025 8009290025 8009290025	80/07/08 80/09/08 80/09/08 80/09/08	FOIA FOIA FOIA FOIA FOIA	

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ENCLOSURE DOCUMENT ISSUED CATEGORY ENCLOSURE DOCUMENT ISSUED ENCOPPORT BOOPSTOOPS BOOPSTO	SUBJECT CATEGORY
B009290087 B009290025 B0/09/08 FDIA B009290454 B009290454 B009290454 B009290455 B009290454 B009290455 B009290454 B009290455 B009290454 B009290455 B009290454 B009290455	50-373 Q 50-329 Q 50-327 P 50-327 P WASTE H9T 50-546 A 50-440 Q 50-416 Q 50-416 Q 50-416 Q 50-416 Q 50-416 Q 50-416 Q 50-416 Q 50-346 P 50-346 P 50-346 P 50-346 P 50-346 P 50-346 P 50-346 P 50-346 P 50-346 P 50-326 Q XPORTLIC
BOO9290102 BOO9290028 BO/09/08 FOIA BOO9290213 BOO929022 BOO92902 BOO92	50-546 A 50-445 Q 50-416 Q 50-416 Q 50-155 Q 50-156 Q 50-156 Q 50-157 Q 50-346 P 50-347 Q 50-259 Q
BO09290114 BO09290125 BO/09/08 FDIA BO09300024 BO09300026 BO/09/11 BO09290118 BO09290125 BO/09/08 FDIA BO09290125 BO0929025 BO/09/08 FDIA BO09290125 BO09290125 BO0929025 BO/09/08 FDIA BO09290125 BO0929025 BO/09/08 FDIA BO09290125 BO09290025 BO0929002	50-416 0 50-155 0 50-416 0 50-346 P 50-346 P 50-342 P 50-261 9 XPORTLIC
8009370127 8009390025 80/09/08 F01A 8009300034 8009300047 8009300047 8009300048 8009300048 8009300048 8009300048 8009300048 8009300048 8009300048 8009300048 8009300048 8009300048 8009300048 8009300048 8009300061 8009300061 8009300062	50-312 0 50-346 P 50-261 0 XFORTLIC 50-259 Q 50-259 Q
	50-259 @
8009290152 8009290025 80/09/08 FDIA 8009290067 800920060 80/09/01 8009290158 8009290025 80/09/08 FDIA 8009290037 8009200060 80/09/11 8009290198 8009290025 80/09/08 FDIA 8009300073 8009300067 80/09/11 8009290162 8009290160 80/09/16 50-255 Q 8009300073 8009300060 80/09/11 8009290163 8009290025 80/09/08 FDIA 8009300080 8009300077 80/09/11	50-261 Q 50-259 Q 50-317 P
8009270164 8009270160 80/09/16 50-255 9 8009300081 8009300080 80/09/11 8009270166 8009290025 80/09/08 FGIA 8009300081 8009300077 80/09/06 8009290171 8009290168 80/09/26 50-170 F 8009300025 80/09/0007 80/09/10 8009290175 800929028 80/09/08 FDIA 8009300025 80/09300084 80/09300087 80/09/10	50-259 Q 50-317 P XFORTLIC 50-317 P 50-382 Q
8009290193 8009290188 80/08/17 50-454 Q 8009300097 8009300093 80/09/03 8009290208 8009290202 80/09/15 50-844 Q 8009300101 8009300019 80/09/11 8009290248 80/09/15 50-317 R 8009300102 8009300098 80/09/08/18 8009290257 800930013 80/09/15 8009300105 8009300105 80/09/16 800929028 800929026 80/09/2028 80/09/2024 50-327 P 8009300119 8009300109 80/09/11	CONTRACT 50-275 F 50-478 G 50-387 A FOIA
8009240281 8009270278 80/09/18 50-366 8 8009300121 8009300118 80/09/02 8009240306 8009240270 80/09/24 50-302 8 8009300125 8009300122 80/09/17 8009240301 8009240284 80/09/17 50-324 8 8009300120 8009300127 8009300127 80/09/11 8009270312 8009270310 800927031 80/09/03 80/09/03 80/09/30 80/09/11	CONTRACT 71-5980 FOIA 71-9037 FOIA
B009290313 B009290203 B0/09/24 50-293 B B009300137 8009300135 80/09/17 B009290314 B009290310 B0/09/03 6A979 B009300148 8009300145 8009300145 8009300145 80090145 80090145 80090145 80090145 80090145 80090145 80090145 80090145 80090145 80090145 80090145 80090145 80090145 80090145 80090145 80090165 800900145 80090145 80090164 80090145 80090164	71-7034 50-313 P 50-313 P 50-313 P 50-259 P
8009270318 8009270310 80/09/03 6A979 8009300163 8009300159 80/09/15 8009270321 8009270317 80/09/15	50-289 H 50-336 P 40-8092 50-243 R CONTRACT
8009290326 8009290325 80/07/10 50-458 Q 8009300207 8009300205 80/09/07 8009290342 8009290341 80/09/22 50-266 P 8009300210 8009300207 80/09/07 8009290344 8009290345 80/09/12 50-257 B 8009300224 8009300217 8009300217 8009290354 8009290354 80/09/16 50-213 P 8009300224 8009300230 80/09/15 8009290356 8009290353 80/09/22 50-312 P 8009300235 8009300230 80/09/15	CONTRACT 71-396 50-255 0 50-255 0 50-277 F
BD0929035B B009290351 B009716 50-213 P B009300236 B009300231 B009300231 B009300231 B009300231 B009300233	50-155 P 50-346 G 50-346 G 50-245 P 50-244 O
8009290372 8009290391 80/09/16 50-213 F 8009300258 8009300253 80/08/29 8009290373 8009290380 90/09/12 50-329 A 8009300249 8009300259 8009300259 80/09/12 8009290377 8009290351 80/09/16 50-213 F 8009300273 8009300253 8009300254 8009300267 8009290380 8009290373 8009300273 8009300273 8009300273 8009300271 <td< td=""><td>50-204</td></td<>	50-204
B009290332 B009290378 B009290	50-267 Q 40-1341 50-267 Q 40-297 50-297 P
8009270398 8009290394 8009290394 8009290394 8009290394 8009290394 8009290394 8009290394 8009290394 8009290394 8009290394 8009290425 8009290	50-297 P 50-245 P 50-275 H 50-245 P 50-245 P
B009290444 B009290440 B009105 50-315 G B009300314 B009300312 B009300312 B009710312	50-344 Q 50-344 Q 50-344 Q 50-257 H 50-344 Q

CROSS REFERENCE OF ENCLOSURES TO PRINICPAL DOCUMENTS

ENCLOSURE	PRINCIPAL DOCUMENT	DATE DATE	SUBJECT CATECORY		
8009300325	8007300316	80/09/19	50-259		
8009300327	8009300316	B0/09/19	50-259	н	
8009300340	8009300334	80/09/12	50-282	P	
10400EPOCE	PPEOOEPOGB	BQ/09/19	50-289	R	
8009300405	B009300402	80/09/29	50-528	K	
8009300414	8009300409	80/09/25	40~8681		
8009300420	8009300417	80/09/25	50-289	Ð	
8009300421	8009300419	80/09/26	50-367	A	
8009300422	8009300417	80/09/25	50-289	0	
6007300423	8009300417	80/09/25	30-289	G	
9009300430	8009300424	80/09/25	50-309	R	
8009300450	8009300441	80/09/22	50-317	5	
8009300460	8009300454	B0/09/26	81E-08	8	
8009300465	8009300455	80/09/24	SD-454	À	
8007300470	8009300464	80/09/26	50-317	8	
8009300473	800930046B	80/09/19	50-237	5	
600 9300 478	8009300472	80/09/25	50-237	8	
8009300479	8007300474	80/09/24	50-324	8	
8009300483 8009300485	8009300477 8009300482	80/09/23	TOPREP	_	
8007300485	8007300482	80/04/12	50-335	8	
8009300487	8009300484	80/09/25	50-255	8	
BD09300494	8009300490	80/09/12	50-250	8	
8009300495	8009300491	80/09/18	50-220	8	
8009300496	8009200488	80/09/24	50-445	M	
8009300499	8009300492	80/09/26	50-255	S	
8009300501	8009300493	80/09/23	20-331	8	
B009300502	8009300497	80/04/53	20-351	8	
8009300504	8009300498	80/09/25	50-281	3	
8009300505	8009300500	80/09/23	50-273	R	
80093 0 0508	6009300498	80/09/25	50~281	8	
8009300509	8009300489	80/09/23	50-325	8	
8009300515	B009300511	80/09/26	50-346	8	
8009300517	8009300510	80/09/24	50-315	8	
B00930051B	8009300512	80/09/24	50-272	P	
8009300521	8007300516	80/09/26	50~259	s	

ACCESS!	ON NUMBER				
ENCLOSURE	PRINCIPAL BOCUMENT	DATE DATE	SUBJECT CATEGORY		
8009300526	6009300519	80/09/23	50-366	~~~	
8009300527	8007300517 E2800EP008	80/09/23	50-366	8	
8009300528	8007300523	80/09/25	50-219	8	
8009300530	8007300524	80/09/22	50-217	8	
6007300535	8007300524	80/09/24	50-293	8	
0007300000	0001300331	60/07/24	30-473	•	
6009300539	8009300532	B0/09/17	50-285	В	
8009300542	8009300533	80/09/25	50-498	М	
8009300546	8009300538	80/09/18	845-05	В	
8009300553	8009300544	80/09/26	50-296	8	
8009300554	8009300548	B0/09/26	50-240	9	
8009300558	8009300551	80/09/25	50-282	8	
8009300563	8007300556	80/07/24	50-267	8	
6007300567	8009300562	80/09/22	50~259	9	
8007300548	B009300559	80/09/24	50~325	8	
8009300569	8009300564	80/09/25	50-219	8	
0007000007	400100004	00/01/23	30-217	8	
17500E700B	8009300565	80/09/19	50-367	G	
B009300577	8009300572	80/09/24	50-348	8	
8009300585	2009300580	80/09/24	70-1309		
8007300586	8009300580	80/09/24	70-1308		
8007300588	8009300584	80/09/12	50-273	G	
8009300595	8009300593	80/09/04	CONTRACT		
B009300597	8009300592	80/07/09	CONTRACT		
8007300578	6009300591	80/07/19	50-271	a	
8009300611	8007300606	80/09/02	70-1377	•	
B007300612	8007300608	80/09/15	50-482	a	
	,000000	00,0,,10	00-402	u	
B009300614	8009300603	80/09/19	50-249	Q	
8009300619	8009300403	80/09/19	50-249	G	
8007300826	8009300616	80/09/16	20~574	G	
OE&00E900B	9190055008	61\P0\0B	50-269	G	
1E400E7008	6180059008	80/09/16	50~269	G	
E009300632	6009300629	80/04/55	50-289	0	
8009300640	8009300616	80/09/16	50-249	ă	
8009300453	8009300651	80/08/29	50-29	ö	
		vur = r		v	

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

- 1. Application for construction permit.
- 2. General Information submitted with construction permit application.
- 3. Amendments and changes to items 1 and 2.
- 4. NRC questions, requests for additional information, and applicant responses.
- 5. Correspondence and documents relating to unresolved design and construction issues.
- 6. Meeting announcements and summaries of meeting discussions on issues of item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Construction Permit, amendments, and correspondence relating to the construction permit.
- 10. Scheduling of license application submission or review.
- 11. Environmental review information.
- 12. Application for operating license.
- 13. General Information submitted with operating license application.
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 17. Reports of site visits.
- 18. Backup technical documents (e.g., topical reports) submitted in support of the application.

B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

- 1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
- 2. Amendments and changes to the PSAR.

- 3. Transmittal and acknowledgement letters.
- 4. Certificates of service to the PSAR.

C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

- 1. Environmental Report (ER) submitted by the utility.
- 2. Amendments and supplements to the ER.
- 3. Transmittal and acknowledgement letters.
- 4. Information on scheduling of submittal or review of ER.
- 5. NRC questions, requests for additional information, and applicant responses.
- 6. Federal register notices citing the availability of items 1 and 2.
- 7. Correspondence relating to the review of ER.
- 8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

- 1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
- 2. Supplements to the DES and FES.
- 3. Correspondence relating to the DES and FES.
- 4. Comments from other federal, state and local government agencies.
- 5. Transmittal and acknowledgement letters.
- 6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
- 7. Backup technical documents submitted in connection with above.
- 8. Federal register notice citing availability of items 1 and 2.
- 9. Site visits to obtain information for DES or FES.
- Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

- 1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).
- 2. Supplements to SER.
- 3. Correspondence relating to SER.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests.
- 7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
- 8. Transmittal and acknowledgement letters.

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

- 1. Fire Hazard Protection Plan and surveys.
- 2. Plant evacuation correspondence.
- 3. Safeguards Contingency Plans.
- 4. Review of Health Physics Program.
- 5. Correspondence relating to aforementioned plans.
- 6. Supplements, changes and revisions to plans.

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2. Federal register notices regarding hearings.
- 3. Requests to make appearances at hearings.
- 4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
- 5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
- 6. Correspondence to and from intervenors.
- 7. Board orders and decisions.
- 8. Petitions for Commission action.
- 9. Legal filings and Commission orders and decisions resulting from item 8.

H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license Items that have no substantive technical content or meaning for the status of the license or application are included.

- 1. Change of address notifications.
- 2. Changes in structure of organization.
- 3. Changes in service lists.
- 4. NRC requests to applicant for additional copies of documents.
- 5. Correspondence from the public requesting information about the facility and NRC responses.
- 6. Correspondence on strictly administrative matters.
- 7. Letters of support, concern or opposition to the facility.
- 8. Correspondence regarding the Local Public Document Rooms (LPDRs).
- 9. Professional qualification statements not pertaining to the hearing process.

I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

J. INSURANCE AND INDEMNITY INFORMATION

- 1. Indemnity agreements and amendments.
- 2. Endorsements insurance policies.
- 3. Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

- 1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
- 2. Amendments and changes to the FSAR.
- 3. Federal register notices citing availability of items 1 and 2.
- 4. Transmittal and acknowledgement letters.
- 5. Certificates of service to the FSAR.

L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

- 1. Limited Work Authorizations (LWA) and amendments.
- 2. Correspondence pertaining to work performed under LWA's.

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- 1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review".
- 2. Correspondence where the primary topic of discussion is antitrust matters.
- 3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- 1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
- 2. Correspondence from ACRS.
- 3. Announcement of ACRS meetings.
- 4. Transmittal and acknowledgement letters.
- 5. ACRS reports.
- 6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
- 7. Minutes at ACRS Subcommittee Meetings.

P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

- 1. Operating license, amendments, proposed amendments, changes and related correspondence.
- 2. Technical specifications and changes.

- 3. Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
- 4. Federal register notices citing availability of items 1 and 2.
- 5 Correspondence regarding the Final Safety Analysis Report (FSAR).
- All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
- 7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
- 8. Information on the Standard Review Plan (STP).
- 9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10 Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11. Owner's group meeting announcements and reports.
- 12. Quality assurance information.
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool.
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits.
- Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE
- 1. Inspection reports.
- IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- Responses by applicant to IE correspondence.
- Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN's).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature.

- 1. Monthly, semiannual, or annual operating reports (other than financial).
- 2. Periodic environmental monitoring, effluent testing, or similar reports.
- 3. Periodic personnel exposure reports.
- 4. Operational Logbooks:

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets.

5. Correspondence or other documents relating to the above listed items.

S. REPORTABLE OCCURRENCES, PNO'S, PNS'S AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

- 1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
- 2. Potential or possible reportable deficiency reports and related correspondence.
- 3. Personnel exposure reports.
- 4. Construction deficiency reports submitted under 10 CFR 50.55e.
- 5. Preliminary Notification of Occurrence (PNO's) and Preliminary Notification of Safeguards Events (PN's).
- 6. Environmental Technical Specifications violation reports and Environmental Event reports.
- 7. Part 21 Reports of defects and noncompliance.
- 8. Correspondence or other documents relating to Items 1-7.

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
- 2. Testimony and statements submitted to ASLB and ASLAB.
- 3. Commission meeting transcripts.
- 4. NRC staff briefings to the Commission.
- 5. Statements and written testimony submitted at Commission meeting or hearings.
- 6. Transcripts of utility briefs to NRC staff.
- 7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.

- 3. Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
- 7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
- 8. Information on the Standard Review Plan (STP).
- 9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11. Owner's group meeting announcements and reports.
- 12. Quality assurance information.
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool.
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits.

Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1. Inspection reports.
- 2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- 7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN's).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature.

- 1. Monthly, semiannual, or annual operating reports (other than financial).
- 2. Periodic environmental monitoring, effluent testing, or similar reports.
- 3. Periodic personnel exposure reports.
- 4. Operational Logbooks:

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets.

5. Correspondence or other documents relating to the above listed items.

S. REPORTABLE OCCURRENCES, PNO'S, PNS'S AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

- 1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
- 2. Potential or possible reportable deficiency reports and related correspondence.
- 3. Personnel exposure reports.
- 4. Construction deficiency reports submitted under 10 CFR 50.55e.
- Preliminary Notification of Occurrence (PNO's) and Preliminary Notification of Safeguards Events (PN's).
- 6. Environmental Technical Specifications violation reports and Environmental Event reports.
- 7. Part 21 Reports of defects and noncompliance.
- 8. Correspondence or other documents relating to items 1-7.

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
- Testimony and statements submitted to ASLB and ASLAB.
- 3. Commission meeting transcripts.
- 4. NRC staff briefings to the Commission.
- 5. Statements and written testimony submitted at Commission meeting or hearings.
- Transcripts of utility briefs to NRC staff.
- 7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.

- 3. Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
- 7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
- 8. Information on the Standard Review Plan (STP).
- 9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11. Owner's group meeting announcements and reports.
- 12. Quality assurance information.
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool.
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits.
- Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE
- 1. Inspection reports.
- 2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- 7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN's).
- Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE R.

This category includes periodic reports of a routine nature.

- Monthly, semiannual, or annual operating reports (other than financial). 1.
- 2. Periodic environmental monitoring, effluent testing, or similar reports.
- 3. Periodic personnel exposure reports.
- 4. Operational Logbooks:

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets.

Correspondence or other documents relating to the above listed items. 5.

REPORTABLE OCCURRENCES, PNO'S, PNS'S AND RELATED CORRESPONDENCE S.

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

- Ali 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up İ. correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences),
- Potential or possible reportable deficiency reports and related correspondence. 2.
- 3. Personnel exposure reports.
- Construction deficiency reports submitted under 10 CFR 50.55e. 4.
- Preliminary Notification of Occurrence (PNO's) and Preliminary Notification of Safeguards 5. Events (PN's).
- Environmental Technical Specifications violation reports and Environmental Event reports. б.
- Part 21 Reports of defects and noncompliance. 7.
- Correspondence or other documents relating to stems 1-7. 8.

TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS Т.

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board 1. (ASLAB) transcripts.
- Testimony and statements submitted to ASLB and ASLAB. 2.
- Commission meeting transcripts. 3.
- NRC staff briefings to the Commission. 4.
- Statements and written testimony submitted at Commission meeting or hearings. 5.

8. Corrections to above items.

U. CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H.

- 1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches.
- 2. Preparatory and backup documents for item 1.
- 3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters.

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1. Operator licenses or administrative information bearing on licensing of operators.
- 2. NRC examination results.
- 3. Power plant examination summary sheet.

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

- 1. Application for authority to voluntarily surrender license.
- 2. Application to dismantle the facility and dispose of component parts.
- Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
- 4. Documents relating to disposal of radioactive material and decontamination of the site,
- 5. Other correspondence relating to above items.
- 6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

APPENDIX B

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR - Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

- 1. Sunshine Act Federal Register notices.
- 2. Full, written explanation of closed meetings.
- 3. Certification of General Counsel on closed meetings.
- 4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings,
- 5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
- 6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
- 7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

ACRS - Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

- 1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
- 2. ACRS meeting announcements; description of meeting agendas.
- 3. ACRS-generated reports, memoranda and correspondence that are publicly available.
- 4. ACRS consultant reports, comments and related correspondence.
- 5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.

- 2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners
- 3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

- 1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
- 2. Solicitations (RFP or IFB) issued by the NRC.
- 3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
- 4. Contractual documents and contract modifications, if any,

DISCLOSURE - Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

FOIA - Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include

- 1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year—numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
- 2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS - Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

- 1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
- 2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.

- 3. Meeting notifications and minutes.
- 4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

I&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

- 1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
- 2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- 3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
- 4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

MISC - Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

NUREG - NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

- 1. These reports are normally final work products and are characterized by the following criteria:
 - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
 - b. They present the results of Commission licensing and policy decisions.
 - c. They present the results of technical research conducted for the Commission.
- Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
- 3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

ORG - Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development; and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are.

- 1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
- 2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air
- 3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

- 1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
- 2. Text of the Proposed Rule (PR).
- 3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
- 4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

- 1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.

- 3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
- 4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ - Projects-Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

- A. Application/Construction Stage
 - 1. Application submitted by the utility.
 - 2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
 - 3. Applicant's Quality Assurance Manual.
 - 4. Early site review information.
 - 5. Backup technical documents submitted in support of the application.
 - 6. Early site visits.
- B. Utility PSAR and Amendments
 - 1. PSARs submitted by the utility.
 - 2. Amendments and changes to the PSAR.
 - 3. Transmittal letters.
 - 4. Letters acknowledging receipt of the PSAR.
- G. Adjudicatory Correspondence
 - 1. Motions, briefs, orders, et al. pertaining to pre-hearing conferences, if any.
- M. Antitrust Correspondence
 - 1. Submittals and related material pertaining to the antitrust review.

Q. Inspection Reports

- 1. Inspection reports of the applicant's quality assurance program.
- 2. Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited.

2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

- 1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- 2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited.
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

- NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
- 2. Notices of deviations.
- Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD - Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC

staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

- 1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports; for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
- 3. Pre-test prediction reports.
- 4. "Ouick look" reports.
- 5. Informal experimental data reports and post-irradiation examination analyses.
- Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by contractors.
- 8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
- Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
- 10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

Q. Inspection Reports

- 1. Inspection reports of the applicant's quality assurance program.
- 2. Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited.

2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

- 1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- 2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited.
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

- 1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
- 2. Notices of deviations.
- 3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD - Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC

staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

- 1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports; for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
- 3. Pre-test prediction reports.
- 4. "Quick look" reports.
- 5. Informal experimental data reports and post-irradiation examination analyses.
- 6. Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by contractors.
- 8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
- 9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
- 10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

- 1. Agendas for quarterly review group meetings.
- Summary minutes of review group meetings representing views expressed, including dissenting views.
- 3. Research plans and predicted results of major experiments; presentations by research contractors.
- 4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5. Internal memoranda relating to topics under discussion.

RM - Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

- 1. Designations of the presiding officer and any special directions for the conduct of the hearing.
- 2. Notifications of hearing board meetings.
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding.
- 6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY - Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- 1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- 2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG — State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

State and local governments in planning responses to radiological emergencies; and (3) a wide range of haison and cooperative activities regarding such functions as licensing and siting. It includes:

- 1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
 - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
 - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
- 2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.
- 3. State Legislative Reports.
- 4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

- 1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
- 2. Revisions, modifications and amendments to topical reports.
- 3. Correspondence between NRC and vendors pertaining to the review of submittals.
- 4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT - Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

- 1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
- 2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

- 3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
- 4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

XPORTLIC - Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are.

- 1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- 2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
- 3. Commission letters requesting Executive Branch views.
- 4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
- 5. Correspondence from foreign governments, international organizations, and members of the public.
- 6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
- 7. Filings pursuant to hearing requests or intervention petitions, if any.
- 8. Hearing records and decisions.
- 9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
- 10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

RC FORM 335	US NUCLEAR REGULATORY COMMISSION BIBLIOGRAPHIC DATA SHEET		ľ		(Assigned by DDC) Vol 2, No 9		
TITLE AND SUBTI	TLE (Add Volume No., if appropriate)	·			70, 2, 110 5		
Title List of Documents Made Publicly Available				2 (Leave blank)			
September 1-30, 1980			3 1	3 RECIPIENT'S ACCESSION NO			
AUTHOR(S)				ATE REPORT CO	OMPLETED		
			j	October	YEAR 1980		
PERFORMING OF	GANIZATION NAME AND MAILING ADDRESS (Include Zip Co		DATE REPORT IS			
Division of Technical Information and Document Control U.S. Nuclear Regulatory Commission				MONTH December 1980			
Washington,	Washington, D.C. 20555			Leave blank)			
			8 /	8 (Leave blank)			
. SPONSORING O	RGANIZATION NAME AND MAILING ADDRESS (Include Zip Co	ode)	BBO E OT TACK			
Division of	Technical Information and Docum	ent Contr	rol l'	10 PROJECT/TASK/WORK UNIT NO			
	U.S. Nuclear Regulatory Commission Washington, D.C. 20555			11 CONTRACT NO			
TYPE OF REPOR	RT	PERI	OD COVERED (I	oclusive dates!			
Monthly		1	00 00 12 1110 111	dalos,			
Ct Indicates			1				
. SUPPLEMENTAR	KY NOTES		114	(Leave plank)			
info incl plan mate regu merl Cent docu cont	document is a monthly publication received and generated by udes (1) docketed material assocts and other uses of radioactive rial received and generated by N latory agency. The docketed infly issued through the U.S. Department under the title Power Reactor ment replaces PRDI, which will not ains the following indexes: Person, and Report Number Index.	y the US iated wit material RC pertin ormation ment of E Docket I o longer	NRC. This h civilian s and (2) rent to its includes in formation be prepared	information nuclear pownondocketed role as a formation formation formation formation formation This doc	or- rmation is ument		
KEY WORDS AN	D DOCUMENT ANALYSIS	17a DE	ESCRIPTORS				
AVAILABILITY		ļ	9 SECURITY CL Unclassi		21 NO OF PAGES		
Unlimited		2	o secunity cu Unclassi	fied "" page"	\$		

--- - 7731